

AGENDA



LOCAL TRAFFIC COMMITTEE MEETING

MONDAY 15 NOVEMBER 2021

10.00AM

Function of the Local Traffic Committee

Background

Roads and Maritime Services (RMS) is legislated as the Authority responsible for the control of traffic on all NSW Roads. The RMS has delegated certain aspects of the control of traffic on local roads to councils. To exercise this delegation, councils must establish a local traffic committee and obtain the advice of the RMS and Police. The Inner West Council Local Traffic Committee has been constituted by Council as a result of the delegation granted by the RMS pursuant to Section 50 of the Transport Administration Act 1988.

Role of the Committee

The Local Traffic Committee is primarily a technical review and advisory committee which considers the technical merits of proposals and ensures that current technical guidelines are considered. It provides recommendations to Council on traffic and parking control matters and on the provision of traffic control facilities and prescribed traffic control devices for which Council has delegated authority. These matters are dealt with under **Part A** of the agenda and require Council to consider exercising its delegation.

In addition to its formal role as the Local Traffic Committee, the Committee may also be requested to provide informal traffic engineering advice on traffic matters not requiring Council to exercise its delegated function at that point in time, for example, advice to Council's Development Assessment Section on traffic generating developments. These matters are dealt with under **Part C** of the agenda and are for information or advice only and do not require Council to exercise its delegation.

Committee Delegations

The Local Traffic Committee has no decision-making powers. The Council must refer all traffic related matters to the Local Traffic Committee prior to exercising its delegated functions. Matters related to State Roads or functions that have not been delegated to Council must be referred directly to the RMS or relevant organisation.

The Committee provides recommendations to Council. Should Council wish to act contrary to the advice of the Committee or if that advice is not supported unanimously by the Committee members, then the Police or RMS have an opportunity to appeal to the Regional Traffic Committee.

Committee Membership & Voting

Formal voting membership comprises the following:

- one representative of Council as nominated by Council;
- one representative of the NSW Police from each Local Area Command (LAC) within the LGA, being Newtown, Marrickville, Leichhardt and Ashfield LAC's.
- one representative from the RMS; and
- State Members of Parliament (MP) for the electorates of Summer Hill, Newtown, Heffron, Canterbury, Strathfield and Balmain or their nominees.

Where the Council area is represented by more than one MP or covered by more than one Police LAC, representatives are only permitted to vote on matters which effect their electorate or LAC.

Informal (non-voting) advisors from within Council or external authorities may also attend Committee meetings to provide expert advice.

Committee Chair

Council's representative will chair the meetings.

Public Participation

Members of the public or other stakeholders may address the Committee on agenda items to be considered by the Committee. The format and number of presentations is at the discretion of the Chairperson and is generally limited to 3 minutes per speaker. Committee debate on agenda items is not open to the public.

AGENDA

1	Apologies	
2	Disclosures of Interest	
3	Confirmation of Minutes	Page
	Minutes of 18 October 2021 Local Traffic Committee Meeting	5
4	Matters Arising from Council's Resolution of Minutes	
5	Part A – Items Where Council May Exercise Its Delegated Functions	

Traffic Matters

ITEM		Page
LTC1121(1) Item 1	Gladstone Lane, Newtown - Proposed Signage and Linemarking associated with Public Domain Works Damun - Stanmore Ward/ Newtown Electorate/ Inner West PAC	19
LTC1121(1) Item 2	Bland Street, Ashfield – Proposed new raised pedestrian crossing - Design Plan 10174 (Djarrawunang-Ashfield Ward/Summer Hill Electorate/Burwood PAC)	22
LTC1121(1) Item 3	Bland Street, Haberfield - Proposed Raised Pedestrian Crossing (Gulgadya-Leichhardt Ward/Summer Hill Electorate/Burwood PAC)	25
LTC1121(1) Item 4	Waratah Street, Haberfield - Proposed Raised Pedestrian Crossing (Gulgadya-Leichhardt Ward/Summer Hill Electorate/Burwood PAC)	27
LTC1121(1) Item 5	Victoria Road, Marrickville at the Rail overbridge between Charlotte Avenue and Meeks Street – temporary full road closure - 2-week period - Christmas Shutdown for the Southwest Metro Upgrade Project - Sydney Metro City & Southwest (Midjuburi-Marrickville Ward / Summer Hill Electorate / Inner West PAC)	29
LTC1121(1) Item 6	Albermarle Street at the Rail Overbridge south of Challis Avenue, Marrickville – Temporary Full Road Closure - 2 week period - Christmas Shutdown for the Southwest Metro Upgrade Project - Sydney Metro City & Southwest (MIDJUBURI-Marrickville Ward / Summer Hill Electorate / Inner West PAC)	53

Parking Matters

Nil at the time of printing.

Late Items

Nil at time of printing.

6 Part B - Items for Information Only

Nil at the time of printing.

7 Part C - Items for General Advice

ITEM	Page
LTC1121(1) Item 7 Pedestrian Access and Mobility Plan Study (All wards/All Electorate/ All PACS)	79

8 General Business

9 Close of Meeting

**Minutes of Local Traffic Committee Meeting
Held remotely on 18 October 2021**

Meeting commenced at 10.04AM

ACKNOWLEDGEMENT OF COUNTRY BY CHAIRPERSON

I acknowledge the Gadigal and Wangal people of the Eora nation on whose country we are meeting today, and their elders past and present.

COMMITTEE REPRESENTATIVES PRESENT

Cr Victor Macri	Councillor – Midjuburi-Marrickville Ward (Chair)
Bill Holliday	Representative for Jamie Parker MP, Member for Balmain
Aislinn Stein-Magee	Representative for Jo Haylen MP, Member for Summer Hill
Cathy Peters	Representative for Jenny Leong MP, Member for Newtown
Solon Ghosh	Transport for NSW (TfNSW)

NON VOTING MEMBERS IN ATTENDANCE

Cr Marghanita da Cruz	Councillor – Gulgadya-Leichhardt Ward (Alternative Chair)
Colin Jones	Inner West Bicycle Coalition (IWBC)
Manod Wickramasinghe	IWC's Traffic and Transport Planning Manager
George Tsaprounis	IWC's Coordinator Traffic Engineering Services (South)
Sunny Jo	IWC's Coordinator Traffic Engineering Services (North)
Joe di Cesare	IWC's Design Services Coordinator
Mohammed Haque	IWC's Civil Engineer
Pierre Ayoub	IWC's Civil Engineer
Christina Ip	IWC's Business Administration Officer

VISITORS

Nil.

APOLOGIES:

Adrian Prichard	Transit Systems – Inner West Bus Services
SC Anthony Kenny	NSW Police – Inner West Police Area Command
Maryanne Duggan	Representative for Jodi MacKay MP, Member for Strathfield

DISCLOSURES OF INTERESTS:

Nil.

CONFIRMATION OF MINUTES

The minutes of the Local Traffic Committee meeting held on 20 September 2021 were confirmed with the following amendment to Item 6 and Item 9:

LTC0921(1) Item 6 Parking in Nelson Lane, Annandale

Cr da Cruz asked why a consultation into parking in Nelson Lane, Annandale was undertaken in response to the resident of 269 Nelson Street requesting 'No Parking' opposite their garage which faces Nelson Lane. Council Officers stated that the intention was to investigate access issues for the whole of Nelson Lane and implement any

changes at the same time. A mixed response was received from the consultation. Council Officers will investigate expediting 'No Parking' restrictions for residents who have supported it.

Cr da Cruz requested that officers also investigate the parking signage in Nelson Lane, adjacent to the pumping station, at the entrance from Rose Street, Annandale.

LTC0921(1) Item 9 Pedestrian safety on Canal Road and Charles Street, Lilyfield

The representative for the Member for Balmain raised a request that was made at a previous LTC meeting regarding pedestrian safety on Canal Road and Charles Street, Lilyfield. The representative requested a speed hump on the eastbound approach or a pedestrian crossing on Charles Street where pedestrians cross between the tram ramp and the path to the Leichhardt North light rail station. Alternatively, the tram ramp could be moved north to improve visibility of pedestrians or Canal Road could be converted into a Shared Zone. Cr da Cruz also requested that the tram ramp where Canal Road and Charles Street meet is investigated to improve pedestrian access. Council Officers will investigate these matters.

MATTERS ARISING FROM COUNCIL'S RESOLUTION OF MINUTES

The Local Traffic Committee recommendations of its meeting on 20 September 2021 were adopted at Council's meeting on 12 October 2021 with the following amendments:

- a) That the Mayor write to Transport for NSW to raise concerns with the WestConnex widening the road at the intersection of Victoria Road and Toelle Street, Rozelle. (General Business item 4); and
- b) That given that a broad range of community concerns remain with Item 2 Balmain East Parking Study that it be deferred further for these to be resolved.

EMAIL CONFIRMATION OF OFFICER'S RECOMMENDATION

The representative for NSW Police – Inner West supported the Officer's recommendations for the items in their PAC.

The representative for Transit Systems supported all the Officer's recommendations.

LTC1021(1) Item 1 Unwins Bridge Road at Gannon Street, Tempe - Proposed line marking treatment at roundabout (Midjumburi - Marrickville Ward/ Summer Hill Electorate/ Inner West PAC)

SUMMARY

Council has received concerns raised by residents within the area regarding safety relating to the intersection roundabout of Unwins Bridge Road, Gannon Street and Griffith Street, Tempe. It has come to Council's attention that on several occasions, motorists entering the roundabout, possibly at speed, have lost control of their vehicle, especially during wet weather.

Officer's Recommendation

THAT the proposed treatment at the intersection of Unwins Bridge Road, Gannon Street and Griffith Street, including reinstatement of roundabout signage, edge line marking, remarking of faded BB lines at all approaches/ departures of intersecting roads (as per Diagram 1 of

this report) and installation of bollards along the kerbside frontage of Property No. 155 & 157 Unwins Bridge Road, Tempe (as per Diagram 2 of this report) be APPROVED.

DISCUSSION

The IWBC representative requested pram ramps at the intersection to make it safer to cross at the roundabout. Council Officers will investigate the feasibility of pram ramps and advised that there are marked crossings near the roundabout on Gannon Street and Unwins Bridge Road that are safer crossing points than crossing at the roundabout.

Cr da Cruz raised concerns with conflict when vehicles leave the parking lane on Griffith Street and potentially form two lanes of traffic on approach to the roundabout. It was noted that proposed line marking on Unwins Bridge Road will narrow the carriageway to one lane. Cr da Cruz requested that line marking on Griffith Street be reviewed and pedestrian refuges be considered on approach to the roundabout.

The TfNSW representative requested that the line marking and placement of the 'Keep Left' sign on the same pole as the roundabout sign be reviewed as the 'Keep Left' sign is typically on a separate pole and positioned on approach to the refuge islands. Council Officers stated that due to the narrow refuge islands, the 'Keep Left' signs would likely be knocked over by trucks and cars if they were placed on the approach of the islands; however, Council Officers will undertake a review.

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT :

1. the proposed treatment at the intersection of Unwins Bridge Road, Gannon Street and Griffith Street, including reinstatement of roundabout signage, edge line marking, remarking of faded BB lines at all approaches/ departures of intersecting roads (as per Diagram 1 of this report) and installation of bollards along the kerbside frontage of Property No. 155 & 157 Unwins Bridge Road, Tempe (as per Diagram 2 of this report) be APPROVED.
2. Council Officers investigate improvement to the existing crossing facilities and further linemarking improvements and report back to the Local Traffic Committee members.

For motion: Unanimous

**LTC1021(1) Item 2 Traffic Management Plan for the 2021 New Year's Eve Event
(Baludarri-Balmain Ward/ Balmain Electorate/ Leichhardt PAC)**

SUMMARY

As instructed by the Police, access to the Balmain peninsula is closed to vehicular traffic every New Year's Eve. This report outlines the traffic management associated with the event.

Officer's Recommendation

THAT:

1. The Traffic Management Plan (Attachment 1) detailing the traffic arrangements for the 2021 New Year's Eve be supported;

2. The Traffic Management Plan (Attachment 1) be forwarded to Council's Parks and Streetscapes Coordinator, Transport Management Centre and the Major Events & Incidents Group (NSW Police);
3. A temporary 'No Stopping' zone be installed on the eastern side of Montague Street between Darling Street and Beattie Street, Balmain;
4. That the following temporary modifications to bus stops be approved:
 - a. On the northern side of Darling Street:
 - i. Install temporary 'Bus Zones' between Mort Street and Ford Street
 - ii. Extend the 'Bus Zone' between Ford Street and McDonald Street
 - iii. Extend the 'Bus Zone' between McDonald Street and Curtis Road, outside Nos.217-223 Darling Street
 - b. On the southern side of Darling Street:
 - i. Install a temporary 'Bus Zone' between Booth Street and Beattie Street, outside No. 244-270 Darling Street.
 - c. On the eastern side of Grove Street between Wharf Road and Bay Street, Birchgrove.
5. The Transit Systems representative be requested to place adequate notices on buses regarding the establishment of an alcohol free zone in the Balmain East area (details to be provided by Council);
6. The taxi/hire car access to the Peninsula be restricted from 7:00pm;
7. Taxis/hire cars carrying mobility impaired or infirmed residents be permitted access at all hours into the Peninsula; and
8. The NSW Taxi Council be advised of the Committee's recommendation.

DISCUSSION

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT:

1. **The Traffic Management Plan (Attachment 1) detailing the traffic arrangements for the 2021 New Year's Eve be supported;**
2. **The Traffic Management Plan (Attachment 1) be forwarded to Council's Parks and Streetscapes Coordinator, Transport Management Centre and the Major Events & Incidents Group (NSW Police);**
3. **A temporary 'No Stopping' zone be installed on the eastern side of Montague Street between Darling Street and Beattie Street, Balmain;**
4. **That the following temporary modifications to bus stops be approved:**
 - a. **On the northern side of Darling Street:**
 - i. **Install temporary 'Bus Zones' between Mort Street and Ford Street**
 - ii. **Extend the 'Bus Zone' between Ford Street and McDonald Street**
 - iii. **Extend the 'Bus Zone' between McDonald Street and Curtis Road, outside Nos.217-223 Darling Street**
 - b. **On the southern side of Darling Street:**
 - i. **Install a temporary 'Bus Zone' between Booth Street and Beattie Street, outside No. 244-270 Darling Street.**

- c. On the eastern side of Grove Street between Wharf Road and Bay Street, Birchgrove.
5. The Transit Systems representative be requested to place adequate notices on buses regarding the establishment of an alcohol free zone in the Balmain East area (details to be provided by Council);
6. The taxi/hire car access to the Peninsula be restricted from 7:00pm;
7. Taxis/hire cars carrying mobility impaired or infirmed residents be permitted access at all hours into the Peninsula; and
8. The NSW Taxi Council be advised of the Committee's recommendation.

For motion: Unanimous

LTC1021(1) Item 3 Intersection of Hardy Street/ Church Street and Princess Street, (at suburb boundaries) Canterbury/Ashbury/Hurlstone Park - Proposed roundabout - Design Plan CBC No. 01470 (Djarrawunang-Ashfield Ward/ Canterbury Electorate/ Ashfield PAC)

SUMMARY

Canterbury Bankstown Council in conjunction with Inner West Council has finalised a plan to propose a roundabout at the intersection of Hardy Street/Church Street and Princess Street, Canterbury/Ashbury/Hurlstone Park. The intersection is bounded by both Councils. The proposed roundabout would replace the current crossroad treatment at the intersection to improve safety for all road users.

Officer's Recommendation

THAT the detailed design plan for a proposed roundabout at the intersection Hardy Street/Church Street and Princess Street, Canterbury/Ashbury/Hurlstone Park, with the removal of a slip lane and associated signs and line markings (as per Plan CBC No.01470) be APPROVED.

DISCUSSION

It was noted that this matter was adopted by the Canterbury-Bankstown Council's LTC last week.

The IWBC has proposed that Hardy Street become a designated route under the Inner West Bicycle Plan and the IWBC representative requested that bike logos be installed on the road. Council Officers will consider the request as part of the Inner West Bicycle Plan.

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT the detailed design plan for a proposed roundabout at the intersection Hardy Street/Church Street and Princess Street, Canterbury/Ashbury/Hurlstone Park, with the removal of a slip lane and associated signs and line markings (as per Plan CBC No.01470) be APPROVED.

For motion: Unanimous

LTC1021(1) Item 4 Addison Road, Marrickville – Proposed new pedestrian refuge - Design Plan 10117 (Midjuburi-Marrickville Ward / Newtown and Summer Hill Electorate / Inner West PAC)

SUMMARY

Council has finalised a design plan for the proposed construction of a new pedestrian refuge on Addison Road, Marrickville near Denby Street. Council received funding from the TfNSW Blackspot Program and the proposed works will improve pedestrian safety and motorist safety and addresses concerns about pedestrian safety and driver behaviour in the area. It is recommended that the proposed detailed design plan be approved.

Officer's Recommendation

THAT the detailed design plan for the proposed new pedestrian refuge on Addison Road, Marrickville near Denby Street and associated signs and line markings (as per Plan No.10117) be APPROVED.

DISCUSSION

Cr Macri tabled concerns from Addison Road residents regarding the impact to parking from the proposal. Council Officers proposed that a Resident Parking Scheme could address concerns with loss of parking.

The representative for the Member for Summer Hill stated that some of the affected residents live in the Summer Hill electorate and they have raised concerns with the loss of parking and the relocation of the bus stop.

Cr Macri commented that there have been a number of accidents in Addison Road and development has changed traffic in the street. Cr Macri requested that a 40km/h zone be implemented in Addison Road to improve safety. The representative for the Member for Newtown supported a 40km/h zone. The IWBC representative requested mechanical protections for pedestrians crossing Addison Road and traffic calming devices in addition to a 40km/h zone.

In response to a resident's concern with the relocation of the bus stop to the front of their residence, Cr da Cruz stated that bus stops are smoke-free zones and asked that the resident be advised of this.

The TfNSW representative advised that the width of the kerb ramp should match the width of the pedestrian refuge. Council Officers will review this.

The Committee members agreed to defer the matter to allow consultation on the provision of resident parking in Addison Road and to address other issues raised in the meeting.

COMMITTEE RECOMMENDATION

THAT the detailed design plan for the proposed new pedestrian refuge on Addison Road, Marrickville near Denby Street and associated signs and line markings (as per Plan No.10117) be deferred to allow consultation on the provision of resident parking and to address other issues raised in the meeting.

For motion: Unanimous

LTC1021(1) Item 5 Dudley Street, Dulwich Hill; Illawarra Road, Marrickville; and (Lower) Railway Parade, Sydenham - Bus replacements during major rail shutdown 26 December 2021 to 9 January 2022 - Temporary parking changes during T3 Line upgrade for Sydney Metro (Midjumburi -Marrickville Ward / Summer Hill Electorate / Inner West PAC)

SUMMARY

Council has been notified by Transport for NSW (TfNSW) that Sydney Metro works will involve a major rail shutdown of the Sydenham to Bankstown rail line (T3) between Sunday 26 December 2021 to Sunday 9 January 2022 (inclusive). During the shutdown buses will replace train services along the T3 line and to accommodate the increased bus movements and necessary holding areas some short-term parking changes are required at a number of locations.

Specifically, TfNSW is requesting approval for the temporary conversion of multiple parking spaces at the following locations: Dudley Street, Dulwich Hill; Illawarra Road, Marrickville; and Railway Parade (lower section), Sydenham. It is recommended that no objections be raised, and Council approves the temporary short-term parking changes at the identified locations during the rail shutdowns. TfNSW will reinstate all existing parking arrangements and signage by/on Monday 10 January 2022.

Officer's Recommendation

THAT this report be received and noted and the following temporary short-term parking changes from Sunday 26 December 2021 to Sunday 9 January 2022 be approved and implemented by TfNSW:

Dudley Street - Dulwich Hill Station Precinct (5 parking spaces)

1. The short-term conversion of 7m (1 parking space) 'Loading Zone 8:30 am – 6 pm Mon – Fri & 8:30 am – 12:30 pm Sat' on the northwestern side of Dudley Street (between Wardell Road and School Parade) to a 'Bus Zone' be APPROVED in order to provide an additional bus bay with adequate draw-in length;
2. The short-term conversion of 18m (3 parking spaces) 'P30 min 8:30 am – 6 pm Mon – Fri & 8:30 am – 12:30 pm Sat' on the northern side of Dudley Street (between Wardell Road and School Parade) to a 'Bus Zone' be APPROVED in order to provide an additional bus bay with adequate draw-in length; and
3. The short-term conversion of 7m (1 parking space) 'Works Zone 7 am – 5:30 pm Mon – Sat' on the southeastern side of Dudley Street (between School Parade and Wardell Road) to a 'Bus Zone'; be APPROVED in order to provide an additional bus bay with adequate draw-in length.

Illawarra Road - Marrickville Station Precinct (1 parking space)

4. The short-term conversion of 7m (1 parking space) '1P 8:30 am – 6 pm' on the northern side of Illawarra Road (between Warburton Street and Greenbank Street) to a 'Bus Zone Mon-Fri only'; be APPROVED in order to provide an additional bus bay with adequate draw-in length.

Lower Railway Parade - Sydenham Station Precinct (62 parking spaces)

5. The short-term conversion of 69m (11 parking spaces) 'unrestricted parking' on the southeast kerb of Railway Parade (between Gleeson Avenue and Marrickville Road) to a 'Bus Zone' be APPROVED in order to provide additional layover bus bays with

adequate draw-in length;

6. The short-term conversion of 118m (40 parking spaces) 'unrestricted parking' on the northwest kerb of Railway Parade (Lower) (between Sydenham Road and Marrickville Road) to a 'Bus Zone'; be APPROVED in order to provide additional layover bus bays with adequate draw-in length;
7. The short-term conversion of 32m (11 angle parking spaces) '4P 8:30 am – 6 pm Mon - Fri' on the northwest kerb of Railway Parade (Lower) (between Gleeson Avenue and Marrickville Road) to a 'Bus Zone'; be APPROVED in order to provide additional layover bus bays with adequate draw-in length; and
8. The applicant and Council Rangers be advised in terms of this report.

DISCUSSION

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT this report be received and noted and the following temporary short-term parking changes from Sunday 26 December 2021 to Sunday 9 January 2022 be approved and implemented by TfNSW:

Dudley Street - Dulwich Hill Station Precinct (5 parking spaces)

1. The short-term conversion of 7m (1 parking space) 'Loading Zone 8:30 am – 6 pm Mon – Fri & 8:30 am – 12:30 pm Sat' on the northwestern side of Dudley Street (between Wardell Road and School Parade) to a 'Bus Zone' be APPROVED in order to provide an additional bus bay with adequate draw-in length;
2. The short-term conversion of 18m (3 parking spaces) 'P30 min 8:30 am – 6 pm Mon – Fri & 8:30 am – 12:30 pm Sat' on the northern side of Dudley Street (between Wardell Road and School Parade) to a 'Bus Zone' be APPROVED in order to provide an additional bus bay with adequate draw-in length; and
3. The short-term conversion of 7m (1 parking space) 'Works Zone 7 am – 5:30 pm Mon – Sat' on the southeastern side of Dudley Street (between School Parade and Wardell Road) to a 'Bus Zone'; be APPROVED in order to provide an additional bus bay with adequate draw-in length.

Illawarra Road - Marrickville Station Precinct (1 parking space)

4. The short-term conversion of 7m (1 parking space) '1P 8:30 am – 6 pm' on the northern side of Illawarra Road (between Warburton Street and Greenbank Street) to a 'Bus Zone Mon-Fri only'; be APPROVED in order to provide an additional bus bay with adequate draw-in length.

Lower Railway Parade - Sydenham Station Precinct (62 parking spaces)

5. The short-term conversion of 69m (11 parking spaces) 'unrestricted parking' on the southeast kerb of Railway Parade (between Gleeson Avenue and Marrickville Road) to a 'Bus Zone' be APPROVED in order to provide additional layover bus bays with adequate draw-in length;
6. The short-term conversion of 118m (40 parking spaces) 'unrestricted parking' on the northwest kerb of Railway Parade (Lower) (between Sydenham Road and Marrickville Road) to a 'Bus Zone'; be APPROVED in order to provide

additional layover bus bays with adequate draw-in length;

- 7. The short-term conversion of 32m (11 angle parking spaces) '4P 8:30 am – 6 pm Mon - Fri' on the northwest kerb of Railway Parade (Lower) (between Gleeson Avenue and Marrickville Road) to a 'Bus Zone'; be APPROVED in order to provide additional layover bus bays with adequate draw-in length; and**
- 8. The applicant and Council Rangers be advised in terms of this report.**

For motion: Unanimous

LTC1021(1) Item 6 Lords Road and Flood Street, Leichhardt - Proposed raised pedestrian crossings (Gulgadya-Leichhardt Ward/Balmain Electorate/Leichhardt PAC)

SUMMARY

Council is planning to improve pedestrian safety in Lords Road and Flood Street, Leichhardt by converting the two (2) existing at-grade pedestrian crossings into raised pedestrian crossings at these locations. The proposed works aim to improve pedestrian safety by narrowing the width of road that needs to be crossed and addresses concerns about driver behaviour by slowing traffic as they enter the streets.

Officer's Recommendation

THAT the attached detailed design plan (Design Plan No.10179) for the proposed upgrade of the existing two (2) pedestrian crossings into raised pedestrian crossings at Lords Road and Flood Street, Leichhardt be approved.

DISCUSSION

Cr da Cruz requested for a pedestrian crossing on the northern side of the roundabout on Flood Street, or a pedestrian refuge upgrade if a crossing is not possible. This is to reduce the number of roads pedestrians need to cross to access shops and bus stops. Council Officers will investigate the request separately.

The TfNSW representative requested that the speed hump warning signs be removed from the signage as they are not standard for a raised zebra crossing. The representative also asked that Council Officers ensure that the proposed lighting meets the technical specifications.

The IWBC representative stated that the bike logos on Lord Street proposed to be replaced should not be there at all as the road is narrow and the bike lane is in the 'door zone' of parked cars. Council Officers advised that this will be reviewed in the Council's upcoming Bike Plan, including suggestion to mark bike logos in the centre of the carriageway to move cyclists away from parked cars.

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT the attached detailed design plan (Design Plan No.10179) for the proposed upgrade of the existing two (2) pedestrian crossings into raised pedestrian crossings at Lords Road and Flood Street, Leichhardt be approved.

For motion: Unanimous

**LTC1021(1) Item 7 Probert Street, Walenore Avenue & Holt Street, Newtown -
Dedicated car share parking restrictions (Damun - Stanmore
Ward/ Newtown Electorate/ Inner West PAC)**

SUMMARY

A request has been received from a GoGet Car Share representative for the installation of three (3) on-street dedicated 'Car Share' parking spaces for existing floating car share vehicles around Newtown.

Officer's Recommendation

THAT the following 'No Parking Authorised Car Share Vehicles Excepted' restrictions be approved:

1. A 5.5m restriction in the first parking space on the western side of Probert Street, Newtown, immediately north of Lennox Street;
2. A 5.5m restriction in the first parking space on the western side of Walenore Avenue, Newtown, immediately south of driveway servicing Property No. 32-60 Alice Street, Newtown; and
3. A 5.5m restriction in the first parking space on the southern side of Holt Street, Newtown, immediately west of King Street.

DISCUSSION

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT the following 'No Parking Authorised Car Share Vehicles Excepted' restrictions be approved:

1. A 5.5m restriction in the first parking space on the western side of Probert Street, Newtown, immediately north of Lennox Street;
2. A 5.5m restriction in the first parking space on the western side of Walenore Avenue, Newtown, immediately south of driveway servicing Property No. 32-60 Alice Street, Newtown; and
3. A 5.5m restriction in the first parking space on the southern side of Holt Street, Newtown, immediately west of King Street.

For motion: Unanimous

**LTC1021(1) Item 8 James Street, Leichhardt - Proposed extension to time
restriction in existing Resident Parking Scheme (Gulgadya-
Leichhardt Ward/Balmain Electorate/Leichhardt PAC)**

SUMMARY

Council has received correspondence from a number of residents of James Street, Leichhardt, requesting the extension to the time restriction in the existing Residential Parking Scheme (RPS) streets to deter daytime long stay parking.

Currently James Street between William Street and Allen Street has a '2P 6pm-10pm Permit Holders Excepted Area L1' restriction.

This report provides the result of the resident parking scheme investigation in James Street, Leichhardt.

Officer's Recommendation

THAT the proposed changes to the existing Resident Parking Scheme in James Street, Leichhardt not be supported at the present time due to low level of support from the community.

DISCUSSION

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT the proposed changes to the existing Resident Parking Scheme in James Street, Leichhardt not be supported at the present time due to low level of support from the community.

For motion: Unanimous

LTC1021(1) Item 9 Lilyfield Road, Lilyfield - Proposed removal of existing Bus Zone (Gulgadya-Leichhardt Ward/Balmain Electorate/Leichhardt PAC)

SUMMARY

Council has received a request to remove a redundant existing 'Bus Zone' on the northern side of Lilyfield Road, Lilyfield (in front of 147 Lilyfield Road) to reinstate unrestricted parking at this location.

Officer's Recommendation

THAT the existing 20m 'Bus Zone' zone on the northern side of Lilyfield Road, Lilyfield (in front of 147 Lilyfield Road) be removed and reinstated with unrestricted parking. No Stopping (L) sign east of Perry Lane be retained.

DISCUSSION

The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT the existing 20m 'Bus Zone' zone on the northern side of Lilyfield Road, Lilyfield (in front of 147 Lilyfield Road) be removed and reinstated with unrestricted parking. No Stopping (L) sign east of Perry Lane be retained.

For motion: Unanimous

LTC1021(1) Item 10 Nowranie Lane, Summer Hill- Proposed extension of 'No Stopping' and installation of 'No Parking' Zone (Djarrawunang-Ashfield Ward/Summer Hill Electorate/Ashfield PAC)

SUMMARY

Council has received complaints regarding vehicles parking in Nowranie Lane obstructing driveway access and vehicle movement near to the intersection of Smith Lane, Summer Hill.

To alleviate this issue, it is proposed that the western corner side of Nowranie Lane, south of Smith Lane, have its existing 'No Stopping' restrictions extended from 5 metres to 10 metres and introduce 'No Parking' to a distance of approximately 16 metres south thereof.

Officer's Recommendation

THAT the western corner side of Nowranie Street, south of Smith Lane, Summer Hill be signposted with an extended distance of 'No Stopping' (from 5 metres) to 10 metres commencing from Smith Lane followed by 'No Parking' approximately 16 metres south thereof.

DISCUSSION

Members clarified the length of the zone and the need for the zone. The Committee members agreed with the Officer's recommendation.

COMMITTEE RECOMMENDATION

THAT the western corner side of Nowranie Street, south of Smith Lane, Summer Hill be signposted with an extended distance of 'No Stopping' (from 5 metres) to 10 metres commencing from Smith Lane followed by 'No Parking' approximately 16 metres south thereof.

For motion: Unanimous

General Business

LTC1021(1) Item 11 Request for resident parking in Grove Street, Birchgrove

The Mayor and Cr Stamolis have received representations from residents requesting a Resident Parking Scheme in Grove Street, Birchgrove. Council Officers will investigate the request.

LTC1021(1) Item 12 Improvements to the Terry Street, Glassop Street and Elliot Street intersection in Balmain

Cr Macri has received representations from a resident regarding safety improvements to the intersection of Terry Street, Glassop Street and Elliot Street. Council Officers advised that in addition to the line marking improvements implemented at the intersection, Council consulted on a proposed roundabout at the intersection as part of the Rozelle North LATM study. The roundabout was supported by residents and a final draft LATM report with the proposed roundabout will be presented to the LTC in a future meeting.

LTC1021(1) Item 13 Accidents in Marion Street, Leichhardt intersections

Cr da Cruz raised concerns with the recent accidents on Marion Street, Flood Street and Parramatta Road, Leichhardt, and asked if Council received reports on these accidents to help improve road safety for pedestrians and cyclists. Cr da Cruz also asked whether the Marion Street and Flood Street were designated truck routes.

Council Officers advised that Council receives reports from the Centre for Road Safety if there is a fatality on a local road and the site of the incident is reviewed to determine if improvements can be made to prevent future incidents. If the incident occurred at traffic

signals or on a State road, TfNSW will undertake the review. Council Officers stated that Marion Street is a regional road, as such it is expected to carry higher truck volumes than local roads. The TfNSW representative advised that approved truck routes can be found on the TfNSW website.

Cr da Cruz requested that the Marion Street and Flood Street intersection be a designated high pedestrian area as it is a busy shopping district and supported continued investigations to improve the intersection following the pedestrian fatality.

LTC1021(1) Item 14 Anti-social driving on Lilyfield Road, Lilyfield and the cycleway

Cr da Cruz stated that residents are petitioning to stop anti-social driving on Lilyfield Road which is currently a cycle route. Cr da Cruz asked for a progress update on the cycleway improvements on Lilyfield Road. Council Officers will follow up on the plans to modify the cycleway to improve interactions with the Rozelle parklands and provide an update.

LTC1021(1) Item 15 Intersection of City West Link and Waratah Street, Haberfield

The IWBC representative requested a review of the intersection of the City West Link and Waratah Street to prevent vehicles from hitting the pedestrian refuge. The representative also requested that improvements be made to the pedestrian crossing signals on the City West Link at Waratah Street to prevent confusion where pedestrians are crossing the western section of the road on the red pedestrian phase when the green pedestrian phase is only active for the eastern section of the road. TfNSW will investigate these issues.

LTC1021(1) Item 16 Pedestrian refuges on Darley Road, at Lyall Street and Allen Street, Leichhardt

Cr da Cruz asked for an update to TfNSW's investigation into pedestrian refuges on Darley Road, at Lyall Street and Allen Street. The TfNSW representative advised that works are underway to redesign the refuge splitter island on the northern side of the Darley Road and Allen Street roundabout. Cr da Cruz commented that Lyall Street is used by cyclists and pram users, and pedestrian refuges or speed humps are needed to slow vehicles down.

LTC1021(1) Item 17 Request for improvements to pedestrian crossing facilities near Marketplace Leichhardt

The representative for the Member for Balmain requested that refuge islands and countdown timers be installed at the signalised pedestrian crossings adjacent to Marketplace Leichhardt to facilitate safer access to the shopping centre.

LTC1021(1) Item 18 Traffic accident data

The representative for the Member for Balmain asked where blackspot and traffic accident data comes from. The representative was advised that NSW Police provide accident reports to TfNSW and the data is then provided to Council. The Centre for Road Safety collates the accident statistics and publishes them online. Council is notified of road fatalities within a few days and the Centre for Road Safety updates published statistics of fatalities within two months. Other crash data can take longer to be published.

LTC1021(1) Item 19 Cycleway in Livingstone Road, Marrickville

Cr Macri stated that residents have raised concerns with the cycleway treatment on Livingstone Road which has narrowed the carriageway such that buses can no longer pass each other. Concerns were raised that there is no splay at the corner of Hastings Street and Livingstone Road which has made turning left into Hastings Street more dangerous. Concerns with flooding in the street were also raised. These concerns will be passed onto Council's Civil Design team for investigation.

LTC1021(1) Item 20 Sydney Park Junction plan

Concerns have been raised with the Office of Jenny Leong regarding the proposed banning of right turns into May Street from Princes Highway as part of the Sydney Park Junction plan. The representative from the Office asked whether Council has made a submission on the project. Cr Macri advised that these concerns were raised with Council and residents were encouraged to provide submissions to Council's Senior Transport Planner who is handling Council's submission on the plan.

LTC1021(1) Item 21 Pedestrian safety on Canal Road and Charles Street, Lilyfield

The representative for the Member for Balmain reiterated his request for a pedestrian crossing or speed cushions on the eastern approach to Charles Street, Lilyfield. Council Officers advised that investigations are ongoing.

Meeting closed at 11.25am.

Item No: LTC1121(1) Item 1

Subject: GLADSTONE LANE, NEWTOWN - PROPOSED SIGNAGE AND
LINEMARKING ASSOCIATED WITH PUBLIC DOMAIN WORKS

**DAMUN - STANMORE WARD/ NEWTOWN ELECTORATE/ INNER WEST
PAC**

Prepared By: Scipio Tam - Engineer – Traffic and Parking Services

Authorised By: Manod Wickramasinghe - Traffic and Transport Planning Manager

SUMMARY

As part of the development for Property No. 2-2A Gladstone Street, Newtown, the applicant has requested Council's Local Traffic Committee approval for the proposed Public Domain Works as per applicant's Condition of Approval. Public Domain works including formalising vehicular parking on the western side of Gladstone Lane and introducing parking restrictions on the eastern side of Gladstone Lane, as well as introducing Give Way restrictions.

RECOMMENDATION

THAT the following restrictions be approved as shown on Attachment 1:

1. Three (3) line marked car spaces signposted as '90 degree Angle Parking Rear to kerb' on the western side of Gladstone Lane, Newtown;
2. Two (2) line marked 'Motorcycle Parking Only' spaces on the western side of Gladstone Lane, Newtown;
3. 'No Parking' restrictions on the eastern side of Gladstone Lane, immediately north of the intersection with Wilford Street; and
4. 'Give Way' signage and line marking for vehicles exiting Gladstone Lane onto Wilford Street.

BACKGROUND

As part of the development for Property No. 2-2A Gladstone Street, Newtown, as per applicant's Condition of Approval, Public Domain works including traffic and parking restrictions along the eastern and western sides of Gladstone Lane are required.

OTHER STAFF COMMENTS

As part of the Public Domain works along Gladstone Lane, Newtown, the applicant is to provide:

- 90 degree 'Rear to kerb' restriction signage with three (3) line marked car spaces on the western side;
- 'Motorcycle Parking Only' restriction signage with two (2) line marked vehicle bays on the western side;
- 'No Parking' restrictions on the eastern side, immediately north of the intersection with Wilford Street; and
- 'Give Way' signage and line marking for vehicles exiting Gladstone Lane onto Wilford Street.

The applicant has submitted a signage and line marking plan along with vehicular swept path plans to ensure unincumbered ingress and egress of vehicles from parking bays.

Please see attached plan for more details.

PUBLIC CONSULTATION

Public consultation was undertaken by applicant. A letter outlining the proposal was mailed out by the applicant to properties in close proximity to the proposal area. These include:

- 2-44 Wilford Street, Newtown;
- All associated townhouses in 2B Gladstone Street, Newtown;
- 2C Gladstone Street, Newtown;
- 76 Wilford Street, Newtown; and
- 83-99 Enmore Road, Newtown.

No responses were received.

ATTACHMENTS

1. [2-2A Gladstone Street, Newtown - Public Domain Works - Signage and Line Marking Plan](#)



Item No: LTC1121(1) Item 2

Subject: **BLAND STREET, ASHFIELD – PROPOSED NEW RAISED PEDESTRIAN CROSSING - DESIGN PLAN 10174 (DJARRAWUNANG-ASHFIELD WARD/SUMMER HILL ELECTORATE/BURWOOD PAC)**

Prepared By: Boris Muha - Engineer – Traffic and Parking Services

Authorised By: Manod Wickramasinghe - Traffic and Transport Planning Manager

SUMMARY

Council has finalised design plans to construct a new raised pedestrian (zebra) crossing in lieu of the existing at-road level crossing in Bland Street north of Elizabeth Street, Ashfield. The proposed works will improve pedestrian and motorist safety and addresses various concerns about pedestrian safety and driver behaviour in the area.

RECOMMENDATION

THAT the detailed design plan for a new raised pedestrian (zebra) crossing (with associated signs and line marking) in lieu of the existing at-road level crossing in Bland Street north of Elizabeth Street, (as per Plan No.10174) be APPROVED.

BACKGROUND & OTHER STAFF COMMENTS

Bland Street is a 2-way road measuring approximately 7.6m in width from kerb to kerb. It is a local collector road, linking traffic between Elizabeth Street and Parramatta Road, and carrying around 3500 vehicle per day with 85 percentile speeds within the 50km/h speed limit. Parking is permitted on the eastern side with 'No Stopping' throughout on the western side in the section of Bland Street between Elizabeth Street and Charlotte Street.

The existing at- road level crossing is located on Bland Street, approximately 90m north of Elizabeth Street. It is used by students at adjacent schools being Bethlehem College Girls High, De La Salle College Boys High and St Vincent's Catholic Primary School. Vehicles park close to the existing crossing impairing on sight view and traffic movement through the crossing.

In order to improve safety at the existing crossing, the following works are proposed and are illustrated on the attached plan (**Attachment 1**).

Bland Street, Ashfield (Plan No. 10174):

- Constructing new Raised Pedestrian Crossing.
- Resetting some of the sandstone kerb to new levels
- Constructing "gutter bridges" with heel safe grating to provide safe access over existing kerb and guttering to the new raised pedestrian crossing;
- Constructing new concrete footpath leads on both sides of the proposed pedestrian crossing;
- Resurfacing some of the existing road pavement with new asphalt on either end of the raised crossing
- Installing associated pavement line marking and signage as required;
- Implementing new 'No Stopping' zones and signage;
- Providing new flood lighting by installing two (2) new flood lights and power poles

Parking Changes

It is proposed under road safety to adjust existing “No Stopping” zones and signage to ensure current TfNSW minimum standards are met for crossings and that Australian Road rules apply in that vehicles do not park within 3 metres of double barrier centreline. This will result in the loss of three (3) on-street parking spaces on the east side of Bland Street.

FINANCIAL IMPLICATIONS


The estimate cost of the works is \$88,000 and is funded from an Australian Government stimulus program for works to be conducted for the 2021-2022 financial period.

PUBLIC CONSULTATION

Consultation was conducted between the 14 October 2021 to 2 November 2021. A total of 11 letters along with a copy of the design plan was sent to properties around the crossing, capturing the local church institutions, Bethlehem College and St Vincent’s Primary School. Although not directly affected, a notification letter was sent to De La Salle College for its information on the proposal. No responses were received at the time of compiling this report.

ATTACHMENTS

1. [Download](#) Bland Street, Ashfield - Raised Pedestrian Crossing - Design Plan



Item No: LTC1121(1) Item 3

Subject: **BLAND STREET, HABERFIELD - PROPOSED RAISED PEDESTRIAN CROSSING (GULGADYA-LEICHHARDT WARD/SUMMER HILL ELECTORATE/BURWOOD PAC)**

Prepared By: Vinoth Srinivasan - Engineer - Traffic and Parking Services

Authorised By: Manod Wickramasinghe - Traffic and Transport Planning Manager

SUMMARY

Council is planning to upgrade an existing pedestrian crossing in Bland Street, Haberfield near Denman Avenue by constructing a raised pedestrian crossing. The proposed works will improve pedestrian and motorist safety near Haberfield Public School.

RECOMMENDATION

THAT the attached detailed design plan (Design Plan No.10181) for the proposed installation of a new raised pedestrian (zebra) crossing at Bland Street, Haberfield near Denman Avenue be approved.

BACKGROUND & OTHER STAFF COMMENTS

The detailed design plan shown in **Attachment 1** outlines the proposed works on Bland Street, Haberfield near Denman Avenue and includes the following treatments:

- Installation of new raised pedestrian (zebra) crossing;
- Installation of associated pavement line marking and signage as required;
- Construction of new concrete footpath on both sides of the proposed pedestrian crossing;
- Implementation of new 'No Stopping' zones and signage, without impacting the existing car parking spaces;

The proposal will not result in any loss of on-street parking spaces. However, some adjustments to the 'No Stopping' signage on the south side of Bland Street is proposed to ensure vehicles do not park over the existing kerb ramp.

FINANCIAL IMPLICATIONS


Funding of \$40,000 has been allocated to this project for construction in the 2021/2022 Capital Works Program.

PUBLIC CONSULTATION

A letter outlining the proposal was mailed out to 6 properties in Bland Street and Denman Avenue, Haberfield. No responses were received regarding to the proposal.

ATTACHMENTS

1. [Detailed Design Plan - Bland Street, Haberfield - Proposed raised pedestrian crossing.](#)



Item No: LTC1121(1) Item 4

Subject: WARATAH STREET, HABERFIELD - PROPOSED RAISED PEDESTRIAN CROSSING (GULGADYA-LEICHHARDT WARD/SUMMER HILL ELECTORATE/BURWOOD PAC)

Prepared By: Vinoth Srinivasan - Engineer - Traffic and Parking Services

Authorised By: Manod Wickramasinghe - Traffic and Transport Planning Manager

SUMMARY

Council is planning to upgrade an existing pedestrian crossing in Waratah Street, Haberfield near Empire Street by constructing a new raised pedestrian crossing. The proposed works will improve pedestrian motorist safety near Dobroyd Point Public School.

RECOMMENDATION

THAT the attached detail design plan (Design Plan No.10182) for the proposed installation of a new raised pedestrian (zebra) crossing at Waratah Street, Haberfield near Empire Street be approved.

BACKGROUND & OTHER STAFF COMMENTS

The detailed design plan shown in **Attachment 1** outlines the proposed works on Waratah Street, Haberfield near Empire Street and includes the following treatments:

- Installing new raised pedestrian crossing;
- Constructing new landscaped kerb blister islands;
- Constructing "gutter bridges" with heel safe grating to provide safe access over existing kerb and guttering to the new raised pedestrian crossing;
- Constructing new concrete footpath leads on both sides of the proposed pedestrian crossing;
- Installing associated pavement line marking and signage as required;
- Adjusting existing 'No Stopping' zones and signage to meet current standards, thus creating one (1) additional on-street car parking space;
- Providing new flood lighting by installing two (2) new flood lights and power poles.

It is proposed to construct kerb extensions to minimise pedestrian crossing distances and to meet the current technical directions for 'No Stopping' zones. The proposed arrangement will optimise the on-street kerbspace available for parking and will result in the increase of one (1) space on the south side of Waratah Street.

FINANCIAL IMPLICATIONS


Funding of \$80,000 has been allocated to this project for construction in the 2021/2022 Capital Works Program.

PUBLIC CONSULTATION

A letter outlining the proposal was mailed out to seven (7) properties in Empire Street and Waratah Street, Haberfield. No responses were received to the proposal.

ATTACHMENTS

1. [Detailed Design Plan - Waratah Street, Haberfield - Proposed raised pedestrian crossing](#)



Item No: LTC1121(1) Item 5

Subject: VICTORIA ROAD, MARRICKVILLE AT THE RAIL OVERBRIDGE BETWEEN CHARLOTTE AVENUE AND MEEKS STREET – TEMPORARY FULL ROAD CLOSURE - 2-WEEK PERIOD - CHRISTMAS SHUTDOWN FOR THE SOUTHWEST METRO UPGRADE PROJECT - SYDNEY METRO CITY & SOUTHWEST (MIDJUBURI-MARRICKVILLE WARD / SUMMER HILL ELECTORATE / INNER WEST PAC)

Prepared By: Jennifer Adams - Engineer – Traffic and Parking Services

Authorised By: Manod Wickramasinghe - Traffic and Transport Planning Manager

SUMMARY

An application (ENRC/2021/0039) has been received from Sydney Metro City & Southwest for the temporary full road closure of Victoria Road, Marrickville at the Rail overbridge between Charlotte Avenue and Meeks Street, for a 2-week period scheduled for 0200 hours Sunday 26 December 2021 to 0500 hours Monday 10 January 2022 (contingency up to Monday 31 January 2022 0500 hours) in order to facilitate the Christmas Shutdown Rail Possession activities at the Victoria Road Bridge location. The road will be temporarily closed to all vehicular traffic, including emergency vehicles. It is recommended that the proposed temporary full road closures be approved, subject to the conditions outlined in this report.

RECOMMENDATION

THAT the proposed temporary full road closure of Victoria Road, Marrickville at the Rail overbridge between Charlotte Avenue and Meeks Street, for a 2-week period scheduled for 0200 hours Sunday 26 December 2021 to 0500 hours Monday 10 January 2022 (contingency up to Monday 31 January 2022 0500 hours) be approved, in order to facilitate the Christmas Shutdown Rail Possession activities at the Victoria Road Bridge location subject to, but not limited to, the following conditions:

1. A Road Occupancy License be obtained by the applicant from the Transport Management Centre;
2. All affected residents and businesses, including the NSW Police Local Area Commander, Fire & Rescue NSW and the NSW Ambulance Services be notified in writing, by the applicant, of the proposed temporary road closure at least 7 days in advance of the closure with the applicant making reasonable provision for stakeholders; and
3. The occupation of the road carriageway must not occur until the road has been physically closed.

BACKGROUND

Sydney Metro City & Southwest works involve the upgrading to metro rail standards the more than 125-year-old Bankstown Line between Sydenham and Bankstown. The joint venture John Holland Pty Ltd and Laing O'Rourke Australia Construction Pty Ltd, has been appointed to undertake the works which includes:

- Upgrading 15 bridges that cross over or under the railway, including installation of safety screens;

- Civil construction including work on retaining walls, culverts and track drainage;
- Fencing along the rail corridor and the segregation of the existing freight line from the new driverless railway tracks;
- Rail systems work including new track crossovers, upgrading and refurbishing overhead wiring and work to support signalling and communication equipment; and
- Utility modifications.


Sydney Metro works will also involve a major rail shutdown of the Sydenham to Bankstown rail line (T3) between Sunday 26 December 2021 to Sunday 9 January 2022 (inclusive). This temporary full road closure is to facilitate the Christmas Shutdown Rail Possession activities at the Victoria Road Bridge location and covers the 14-day period Sunday 26th December 2021 02:00am to Monday 10th January 2022 05:00am.

Between 26 December 2021 and 10 January 2022 upgrade works to Victoria Road Bridge will continue and include piling and installation of safety barrier. To safely accommodate these activities, there will be a road closure along Victoria Road between Meeks Road and Charlotte Avenue, including the below features.

- Road closure on Victoria Road, Marrickville (rail underbridge section) between Meeks Road and Charlotte Avenue. Please see following map.
- Vehicle diversions will be in place. From the southern side of Victoria Road diversions will be via Carrington Road, Schwebel Street, Illawarra Road and onto Marrickville Road. From the northern side of Victoria Road diversions will be from Calvert Street, Gladstone Street and onto Marrickville Road.
- Pedestrian access will be maintained during the road closure.
- Traffic control and directional signage will be in place for the safety of workers and the community.
- There may be an increase in traffic movements around the local area.
- Motorists may experience minor delays.

Equipment used across all of the above work will include excavators, vacuum trucks, motorised saws, concrete trucks, sucker trucks, delivery vehicles, borehole drillers, rollers, generators, whacker packers, dump trucks, telehandlers, drilling rigs, lifting machinery, elevated work platforms, mounted trucks, bobcats, concrete pumps, cranes, cable pulling equipment, road sweeper, compactors, lighting towers, forklifts, water carts, road sweepers, vibrating plates, and hand and power tools.

Access to buildings and driveways will be maintained at all times. Some of this work may be noisy, however Sydney Metro will take every possible step to minimise noise such as switching off equipment when not in use and installing non-tonal reversing beepers on vehicles.



It is noted that Albermarle Street underpass will simultaneously also be closed between 26th December to 4th January 2022 with a counterflow in place between 5th and 10th January 2022 when Wardell Road will operate with one lane open. Livingstone Road will operate with one lane in each direction during the Christmas shutdown period.

- Victoria Road Full Road Closure
 - o Duration 26/12/21 to 10/1/22 (24hr closure)
 - o Detour route on Illawarra Road
 - o Pedestrians can be managed through the worksite
- Livingstone Road 2 of 4 Lane Closure – One lane both ways to remain open
 - o Duration 26/12/21 to 10/1/22 (24hr closure)
 - o Detour route no longer required
- Albermarle Street Full Road Closure & Contraflow
 - o Full road closure duration 26/12/21 to 4/1/22 (24hr closure)
 - o Contraflow setup duration 5/1/22 to 10/1/22 (24hr closure) – changed to facilitate the single lane closure on Wardell Road
 - o Detour route on Wardell Road during full road closure

Albermarle Street, between Challis Avenue and Kays Avenue East, carries around 1,600 vehicles per day. At the railway overbridge the width of the road is approximately 5.7 metres in width. It is noted that the full road closure will divert traffic to either Wardell Road in the west or Livingstone Road in the west.

The Traffic Management Plan for the Christmas Shutdown Full Closure of Victoria Road for the Southwest Metro Upgrade Project is provided in **Attachment 1**.

Traffic movements will be managed in accordance with the TCP in **Attachment 2**. Traffic controllers will be on duty to assist both pedestrians and vehicle movements.

FINANCIAL IMPLICATIONS

Under Council's Fees & Charges, the applicant is to pay a fee for the temporary full road closure. This fee includes advertising the proposal in accordance with the Roads Act 1993.

PUBLIC CONSULTATION

The applicant is to notify all affected residents and businesses in writing at least 7 days prior to the commencement of works.

Community notification by Sydney Metro (SSJ) will include:

- Residents within a 200m radius of the works will be door knocked 7 days prior to any works commencing.
- Notification will be distributed 7 days prior to work commencing to the suburb and surrounding suburbs along the rail corridor.
- A door knock of local businesses with the potential to be impacted will be carried out 14 days before work commences.

The proposed road closure has been advertised on Council's website in accordance with the Roads Act 1993.

CONCLUSION

It is recommended that the proposed temporary full road closure be approved, subject to but not limited to the conditions outlined in this report.

ATTACHMENTS

1. [Download](#) Traffic Management Plan
2. [Download](#) Traffic Control Plan



Sydney Metro City & Southwest

Traffic Management Plan for Christmas Shutdown Full Closure of Victoria Road for the Southwest Metro Upgrade Project

John Holland Laing O'Rourke Joint Venture
100a Marrickville Road
Marrickville NSW 2204

Printed copies of this document are uncontrolled



Sydney Metro City & Southwest: Victoria Road Traffic Management Plan

About this release

Document Number: SMCSWSSJ-JHL-WEC-TF-PLN-000055

Title: Traffic Management Plan

Author: Matthew Hearne, Bitzios Consulting

Rev A	12 October 2021	First Release	A. Finlay
Issue	Date	Revision Description	Authorised by

Management Review

See Section 9 for details

Planned Review Date	Scope	Review By	Review Record Ref no. Date
07 October 2022		Project Manager and Interface Manager	
07 October 2023			
07 October 2024			

Endorsement of TMP

Project Manager

Date

/ /

Interface Manager

Date

12 /10 /2021

Table of Contents

Management Review	2
Endorsement of TMP	2
1. Overview	6
Scope of this Plan	6
John Holland Laing O'Rourke Joint Venture's Authority:	6
JHLOR JV's Objectives	6
2. Management of the TMP	6
3. Implementation	7
4. Traffic Guidance Schemes	7
4.1 For Services requiring a Non-Standard TGS:	Error! Bookmark not defined.
5. Responsibilities	8
Project Manager	8
JHLOR JV's Interface Manager	8
JHLOR JV's Site Supervisor	9
Traffic Management Sub-contractor	10
6. Traffic Controllers	10
7. Plant and Equipment	10
8. Time Management	11
9. Out-of-Working Hours Contacts	11
10. Reviewing this Traffic Management Plan	11
11. Proposed Traffic Management	12
A. Description or detailed plan of proposed measures.	12
B. Identification and assessment of impact of proposed measures.	12
C. Measures to ameliorate the impact of re-assigned traffic.	12
D. Assessment of public transport services affected.	12
E. Details of provision made for emergency vehicles, heavy vehicles, cyclists and pedestrians.	12
F. Assessment of effect on existing and future developments with transport implications in the vicinity of proposed measures.	14
G. Assessment of effect of proposed measures on traffic movements in adjoining Council areas.	14



Sydney Metro City & Southwest: Victoria Road Traffic Management Plan

H. Public consultation process.....	14
Appendix A - Traffic Controllers' Tickets	15
Appendix B - Not Used	16
Appendix C - Hold points.....	16
Appendix D - JHLOR JV Traffic Guidance Schemes for Routine Work under the Albermarle Street Closure	17
Appendix E - to L – Not used.....	18
Appendix M - Definitions.....	18
Last page.....	18

Sydney Metro City & Southwest: Traffic Management Plan



JOHN
HOLLAND

[THIS PAGE DELIBERATELY BLANK]



1. Overview

Scope of this Plan

The scope includes the provision for the safe movement of vehicular and pedestrian traffic, the protection of workers from passing traffic, the provision for access to properties located within the limits of the Victoria Road closure, the design, construction, maintenance and removal of any necessary temporary roadways and detours, the provision of traffic controllers, the installation of temporary signs, road markings, lighting and safety barriers.

It also covers maintenance of the existing road corridor, including the existing road and road shoulder that may be used for the temporary diversion of traffic, over the duration of the Victoria Road closure.

John Holland Laing O'Rourke Joint Venture's Authority:

John Holland Laing O'Rourke Joint Venture (JHLOR JV) is authorised by the Roads Regulation 2008 to appoint traffic controllers and direct traffic and is registered under the TfNSW's Registration Scheme Category G.

JHLOR JV's Objectives

JHLOR JV's objectives with respect to the Traffic Management Plan ("TMP") are to:

- Ensure the safety of its employees, contractors, the general public, TfNSW and Council personnel, pedestrians, cyclists and traffic,
- Keep traffic delays to a minimum,
- Maintain satisfactory property access,
- Minimise disruption to businesses,
- For works near speed cameras, traffic lights & traffic counters etc:
 - Inform the TfNSW Representative and
 - Not damage the equipment,
 - Make suitable arrangements where required.
- When required, obtain approvals and licenses such as Road Occupancy, Direction to Restrict (DTR for Speed Limit Sign Authorisation) and Traffic Signals,
- Minimise disturbance to the environment,
- Design temporary roadways and detours in accordance with TfNSW Traffic Control at Work Sites Manual and
- Meet the requirements of TfNSW G10 Traffic management, TfNSW G11M Road Occupancy Provisions and the TfNSW Traffic Control at Work Sites Manual.

2. Management of the TMP

JHLOR JV has warranted that it will provide people, materials, resources and systems to properly perform the Services including related traffic management.

Council and the TfNSW require the people to be competent, experienced and qualified to carry out the Services.

The Southwest Metro Upgrade Project key personnel for traffic management are shown in the table below.

Name	Position	Phone Number
Tony Waters	Project Leader	0417 593 979
Andrew Constantin	Interface Manager	0418 650 493
Luke Curley	Site Supervisor	0419 816 166
Andie Pitsiatari	Community Place Manager	0429 378 336
D&D (staff name to be confirmed)	Traffic Controller (Blue Card)	TBC
D&D (staff name to be confirmed)	Implement TGSs (Yellow Card)	TBC
D&D (staff name to be confirmed)	Prepare a Work Zone Traffic Management Plan	TBC

3. Implementation

Traffic Management for sites will be in accordance with the TfNSW Traffic Control at Work Sites Manual as modified to site conditions.

Before the Routine Services or any Ordered Work begins the Project Manager will carry out Risk Assessment (see Risk Management Plan) and develop treatments and Plans to eliminate or mitigate hazards.

4. Traffic Guidance Schemes

JHLOR JV will implement approved Traffic Control measures for any Services which disrupt free traffic movement. These measures will include Traffic Guidance Schemes ("TGS") and Vehicle Movement Plans as required and will encompass vehicle movement and pedestrian movement for both construction resources and the general public. Any property accesses affected by the construction activities will also be identified on the TGSs.

For all planned and scheduled works under the contract JHLOR JV will prepare Traffic Guidance Schemes as follows:

Traffic Guidance Schemes are to be designed in accordance with the Traffic Control at Work Sites Manual Version 6.0.



5. Responsibilities

The principle responsibilities and authorities of JHLOR JV staff with respect to traffic management are:

Project Manager

The Project Manager is responsible for ensuring traffic management:

- Is properly planned, organised, directed and controlled,
- Is properly resourced with people, equipment, facilities and systems and
- Meets the requirements of the contract including TfNSW Specifications G10 and G11,
- Complies with all other legislation and
- Is achieving its objectives

The Project Manager's responsibilities remain with him / her, however, the Project Manager has delegated as follows:

JHLOR JV's Interface Manager

The Interface Manager has delegated authority from, and responsibility to, the Project Manager for:

- The selection of any Traffic Control subcontractors,
- Ensuring that processes and control systems needed are established, implemented and maintained,
- Liaison with regulatory agencies regarding requirements for approvals, licences, permits and authorities,
- Arranging and approving training,
- Ensuring that the requirements of all the plans are properly implemented,
- Annually reviewing the continuing suitability, adequacy, and effectiveness, of all the plans and
- Community Relations including addressing complaints.

JHLOR JV's Site Supervisor

JHLOR JV's Site Supervisor has delegated authority from, and responsibility to, JHLOR JV's Project Manager for:

- Determination of traffic control at the work sites.
When selecting a standard TGS or designing a Non-Standard TGS, he / she will ensure the following are considered:
 - The signing-off TGSs by a person who has qualified in the TfNSW "Prepare a Work Zone Traffic Management Plan" course and is experienced in the design and implementation of traffic management plans,
 - Traffic Controllers,
 - Diversions, side tracks and/or detours as required,
 - Temporary warning signs,
 - Signs and devices,
 - Adequate delineation for night/wet conditions,
 - Special lighting when required,
 - Access ways to be kept clear for emergency vehicles and over-dimensional vehicles,
 - Temporary speed zones as required (and approved),
 - Vehicle Movement Plans (including specified locations for on-site parking, and consideration of pedestrian movement for workers, the public including children and disabled persons, bicycles, buses and light rail where applicable).
 - Set up diversions when required in consultation with Police when necessary,
 - Possible impact on main arterial roads,
 - Traffic impact for work near traffic lights,
 - Temporary delineation, barriers and signs until permanent measures are completed. All temporary measures will be maintained in an effective condition while in use and removed when permanent devices are complete including the removal of temporary raised pavement markers and temporary linemarking.
 - Position cones and early warning signs when required,
 - Sign sizes that are appropriate for the conditions,
 - Portable traffic signs if required,
 - Flashing traffic signs if required,
 - Place signs with regard to: Sight distance, motorists approaching at high speed, queue lengths, visibility, shade and light glare,
 - Ensuring only undamaged or non-defective signs are used and
 - Ensuring consideration of the needs of:
 - Pedestrians (including those who are disabled),
 - Cyclists,
 - Business and property owners and
 - School crossings and bus routes.
- Ensuring the TGS is approved,
- Preparing and submitting Hold Point FoTfNSW, Road Occupancy License applications and & *Directions to Restrict* applications 10 working days before the Services are due to begin,
- Allocation of all resources required for the implementation of all the plans,
- Ensuring that control measures are maintained and that work-in-progress is inspected,



- Identifying training needs and arranging for employees and subcontractors to attend the training,
- Ensuring subcontractors/suppliers have suitable qualifications and experience and
- Carrying out and recording weekly inspections and verifications to demonstrate compliance of the Services.

Traffic Management Sub-contractor

The Traffic Management Sub-contractor has:

- Qualified in the "Prepare a Work Zone Traffic Management Plan" course [NOTE: It is a Contract requirements that whoever selects and modifies TGSs has this ticket]

and has delegated authority from, and responsibility to, the Site Supervisor for:

- Implementing the Traffic Management Plan and the Traffic Guidance Scheme on site,
- Maintaining the TGS,
- Assessing and monitoring subcontractor's capabilities and performance in respect of site activities,
- Ensuring the safe passage of traffic at all times,
- Ensuring everyone on site is inducted and wears the appropriate approved clothing and
- Driving through the site to inspect the traffic control layout, recording any deficiencies and the action taken to rectify them.

6. Traffic Controllers

JHLOR JV will ensure any subcontractor undertaking traffic control is registered under the TfNSW's Registration Scheme Category G "Traffic Control".

All traffic controllers used by JHLOR JV have completed TfNSW accredited Traffic Controller training.

A list of their names, ticket numbers and ticket expiry dates is at Appendix A.

Traffic Controllers will carry their tickets with them.

Traffic Controllers will wear high-visibility outer garments complying with TfNSW OH&S Policy 4.0 Personal Protective Equipment and bearing the words "Authorised Traffic Controller" and the TfNSW logo (logo patch supplied by the TfNSW).

7. Plant and Equipment

All vehicles used in traffic control operations will be equipped with the appropriate vehicle mounted warning devices in accordance with the TfNSW Traffic Control at Work Sites Manual.

During daytime, plant and equipment working in a position adjacent to traffic and having a projection beyond the normal width of the item, for example, a grader blade, will have a fluorescent red flag attached to the outer end of the projection. During poor light conditions or at night, an additional traffic controller with an illuminated red wand will direct traffic around such plant and equipment.

During night time, where traffic is permitted to use the whole or portion of the existing road, all plant items and similar obstructions will be removed from the normal path of vehicles, to provide a lateral clearance of at least 6 m where practicable, with a minimum clearance of 1.2 m.

Plant and equipment, within 6 m of the normal path of vehicles, will be lit by not less than two yellow steady lamps suspended vertically from the point of the obstruction nearest to a traffic lane, and one yellow steady lamp at each end of the obstruction on the side furthest away from the traffic lane.

8. Time Management

The JHLOR JV aims to meet its time related obligations. Among them are:

- Notifying emergency services and relevant sections of the community and transport industry of work which results in significant traffic disruption. Provide to the TfNSW a draft of an appropriate advertisement 3 weeks before the proposed placement of the advertisement. See TfNSW M1 Clause 4.3.2.
- Notifying residents and businesses affected by disruption to property access or by night works in built-up areas. A letter will:
 - be "letter-box-dropped" at least three Business Days before the proposed date and
 - detail the dates and times of the proposed access restrictions and contact details. See TfNSW M1 Clause 4.3.4.
- Performing work and Services only in the times permitted.
- Lodging early as possible (at worst no less than 10 Business Days before the work) a road occupancy application. See TfNSW G10 (2.2). Noting, however, the exemptions for emergencies and hazards set down at TfNSW G10 (4.2).
- Promptly advising the TMC of delays to traffic which are, or are anticipated to be, longer than 15 minutes.

9. Out-of-Working Hours Contacts

See contact details in Section 2.

10. Reviewing this Traffic Management Plan

JHLOR JV will review the Traffic Management Plan to ensure it is appropriate and is being implemented effectively. Changes may arise from a change of scope, TfNSW or Council audits, TfNSW or Council comments or from opportunities for improvement. The Plan will then be updated to reflect any changes which have occurred. The revised document and the input which led to the revisions will be reviewed by JHLOR JV's Project Manager, approved by him/her and then forwarded to the TfNSW or Council Representative for his/her record.

The planned target dates (or frequencies) at which the TMP will be subject to formal review and the personnel who will participate in the review are identified in the table at *Management Review* at the beginning of this plan. Council's Contract Manager will maintain records of any review.



11. Proposed Traffic Management

A. Description or detailed plan of proposed measures.

Refer to the attached TGS for detail of the proposed closure and diversion route for vehicles. See below for the diversion route for emergency vehicles, heavy vehicles, cyclists and pedestrians.

The traffic closure is to facilitate the Christmas Shutdown Rail Possession activities at the Victoria Road Bridge location. We plan to close all lanes on Victoria Road from the following:

- Sunday 26th December 2021 02:00am to Monday 10th January 2022 05:00am

B. Identification and assessment of impact of proposed measures.

The signposted diversion route is 2.9km long and is about 8 minutes driving time according to Google Maps. However, the actual distance and time would be less for most traffic depending on their origin and destination connecting to the diversion route.

Due to the 4m bridge clearance on Victoria Road, it is expected that there would be low heavy vehicle movements to the bridges.

C. Measures to ameliorate the impact of re-assigned traffic.

Given that the intersection of Wardell Road and Illawarra Road is a SCATS-enabled intersection, it is likely that the system would detect the extra vehicles using that turn and would allocate extra time each phase to optimise performance and minimise delays.

No additional measures are proposed other than the signposting of the alternative route to provide clear guidance to drivers.

D. Assessment of public transport services affected.

No public transport routes use the bridge on Victoria Road.

E. Details of provision made for emergency vehicles, heavy vehicles, cyclists and pedestrians.

The alternative route for emergency vehicles when Victoria Road is closed is via Carrington Road, Warren Road, Illawarra Road, and Marrickville Road as shown on the TGS and in Figure 11.1.

Heavy vehicles will also follow the signposted diversion route shown on the TGS and in Figure 11.1. Some longer heavy vehicles may need to use an alternative route due to a tight left turn from Illawarra Road to Warren Road.

The suggested alternative route for pedestrians is via Charlotte Avenue, Riverdale Avenue, Leofrene Avenue, Schwebel Street, Illawarra Road, and Calvert Street, as shown in Figure 11.1. The route is 1.6km. The existing street lighting along the alternative route for pedestrians is observed to be similar to other pedestrian areas in the vicinity, so is assumed to be adequate for use of the route at night. Note a detailed condition assessment has not been undertaken.

An existing Shared Path that runs along the southern side of the railway line is currently closed for construction activities and so cannot be used as a pedestrian detour option.

The project team will install lighting along the route where necessary to ensure good lighting conditions for pedestrians along the route during night hours.

VMS sign boards are to be installed on approaches to the bridge advising of the proposed closure at least 1 week before the closure date. These will state

- VICTORIA RD
- BRIDGE CLOSED
- DD DEC – DD JAN

The bottom row will be the start and end dates of the detour.

Traffic controllers are required at each end of the Victoria Road closure during construction hours to assist vehicles and pedestrians with the detour directions.

The alternative route for pedestrians (including cyclists) and emergency services vehicles is shown in Figure 11.1.



Source: Nearmap

Figure 11.1 Alternative Route for Pedestrians and Emergency Services



F. Assessment of effect on existing and future developments with transport implications in the vicinity of proposed measures.

As the works are temporary there is no ongoing effect on development. However, notification requirements are noted in Section 8.

G. Assessment of effect of proposed measures on traffic movements in adjoining Council areas.

The work and the diversion route is fully contained within Inner West Council area and will not affect adjoining Councils' road network.

H. Public consultation process.

As the works are temporary there is no need to consult with the public directly affected by the proposed measures. However, notification requirements are noted in Section 8.

Appendix A - Traffic Controllers' Tickets

Surname	First Name	Council or Contractor Name	Certificate Number	Expiry Date



Appendix B - Not Used

Appendix C - Hold points

Reference TfNSW Doc [Clause no]	Type TfNSW or JHLOR JV Hold	Process Held	Submission Details
M1 (4.3.2)	TfNSW Hold	Services which significantly disrupt traffic	Appropriate advertisement 3 weeks before
M1 (4.3.3)	JHLOR JV Hold	Services which significantly disrupt access	Letter box drop 3 Business Days before
TfNSW G10 (2.2)	TfNSW Hold	Road Occupancy	ROL Application 10 Business Days before
This Traffic Management Plan Clause:			
1	TfNSW Hold	Work near Speed Cameras, Traffic Counters etc.	Inform the TfNSW Representative
3	JHLOR JV Hold	Any Ordered Work	Risk Assessment and Treatment and Plans
4	JHLOR JV Hold	Ordered Work which disrupts traffic	Non standard relating to the work TGS
6	JHLOR JV Hold	Traffic Controller's engagement as such	Subcontractor registered under Scheme G traffic Controller has current ticket

Appendix D - JHLOR JV Traffic Guidance Schemes for Routine Work under the Victoria Road Closure

TGS Number	Location	Description of Control
Sheet 1	Victoria Road, Marrickville - Entire Road Closure, detour for pedestrians and vehicles.	Implement detour via Illawarra Road.





Appendix E - to L – Not used

Appendix M - Definitions

JHLOR JV has adopted the Definitions set out in Clause 1.3 of TfNSW Specification G10 Traffic Management.

Last page



Item No: LTC1121(1) Item 6

Subject: ALBERMARLE STREET AT THE RAIL OVERBRIDGE SOUTH OF CHALLIS AVENUE, MARRICKVILLE – TEMPORARY FULL ROAD CLOSURE - 2 WEEK PERIOD - CHRISTMAS SHUTDOWN FOR THE SOUTHWEST METRO UPGRADE PROJECT - SYDNEY METRO CITY & SOUTHWEST (MIDJUBURI-MARRICKVILLE WARD / SUMMER HILL ELECTORATE / INNER WEST PAC)

Prepared By: Jennifer Adams - Engineer – Traffic and Parking Services

Authorised By: Manod Wickramasinghe - Traffic and Transport Planning Manager

SUMMARY

An application (ENRC/2021/0046) has been received from Sydney Metro City & Southwest for the temporary full road closure of the rail over bridge on Albermarle Street just south of Challis Avenue, Marrickville for a 2-week period scheduled for 0200 hours Sunday 26 December 2021 to 0500 hours Monday 10 January 2022 (contingency up to Monday 31 January 2022) in order to facilitate the Christmas Shutdown Rail Possession activities at the Albermarle Street Bridge location. A contra flow system will operate in the last week of the closure between 5 and 10 January 2022 to facilitate a single lane closure on Wardell Road. The road will be temporarily closed to all vehicular traffic, including emergency vehicles and local residents. It is recommended that the proposed temporary full road closures be approved, subject to the conditions outlined in this report.

RECOMMENDATION

THAT the proposed temporary full road closure of Albermarle Street (between Challis Avenue and Kays Avenue East), Marrickville for a 2-week period scheduled for 0200 hours Sunday 26 December 2021 to 0500 hours Monday 10 January 2022 (contingency up to Monday 31 January 2022 0500 hours) be approved, in order to facilitate the Christmas Shutdown Rail Possession activities on the Rail Overbridge subject to, but not limited to, the following conditions:

1. A Road Occupancy License be obtained by the applicant from the Transport Management Centre;
2. All affected residents and businesses, including the NSW Police Local Area Commander, Fire & Rescue NSW and the NSW Ambulance Services be notified in writing, by the applicant, of the proposed temporary road closure at least 7 days in advance of the closure with the applicant making reasonable provision for stakeholders; and
3. The occupation of the road carriageway must not occur until the road has been physically closed.

BACKGROUND

Sydney Metro City & Southwest works involve the upgrading to metro rail standards the more than 125-year-old Bankstown Line between Sydenham and Bankstown. The joint venture John Holland Pty Ltd and Laing O'Rourke Australia Construction Pty Ltd, has been appointed to undertake the works which includes:

- Upgrading 15 bridges that cross over or under the railway, including installation of safety screens;
- Civil construction including work on retaining walls, culverts and track drainage;
- Fencing along the rail corridor and the segregation of the existing freight line from the new driverless railway tracks;
- Rail systems work including new track crossovers, upgrading and refurbishing overhead wiring and work to support signalling and communication equipment; and
- Utility modifications.

The T3 Line between Sydenham and Bankstown will be closed from 26 December 2021 to 10 January 2022 for upgrade works. In December 2021 and January 2022, work will continue along the rail corridor and at Dulwich Hill Station (weather and site conditions permitting). Access to the rail corridor will be via existing rail corridor/pedestrian access gates.


Between 26 December 2021 and 10 January 2022 there will be upgrade work taking place in the rail corridor. To accommodate these activities, there will be a temporary road closure along Albermarle Street Bridge, Dulwich Hill.

Due to the nature of some activities and for the safety of workers, work will occur during a number of rail shutdown weekends when trains are not running on the following dates:

- 2am Sunday 26 December 2021 to 2am Monday 10 January 2022

The temporary road closure on Albermarle Street Bridge between Albermarle Street and Challis Avenue, Marrickville will include the below features:

- Pedestrian footpath closure along Albermarle Street Bridge.
- Traffic and pedestrian diversions together with traffic control and directional signage will be in place for the safety of workers and the community.
- There may be an increase in traffic movements around the local area.
- Motorists may experience minor delays



Equipment used across all of the above work will include excavators, vacuum trucks, motorised saws, concrete trucks, sucker trucks, delivery vehicles, borehole drillers, rollers, generators, whacker packers, dump trucks, telehandlers, drilling rigs, lifting machinery, elevated work platforms, mounted trucks, bobcats, concrete pumps, cranes, cable pulling

equipment, compactors, lighting towers, forklifts, water carts, road sweepers, vibrating plates, and hand and power tools.

Access to buildings and driveways will be maintained at all times. Some of this work may be noisy, however we will take every possible step to minimise noise such as switching off equipment when not in use and installing non-tonal reversing beepers on vehicles.



It is noted that Victoria Road underpass will simultaneously also be closed between 26th December to 4th January 2022. Livingstone Road will operate with one lane in each direction during the Christmas shutdown period.

- Albermarle Street Full Road Closure & Contraflow
 - o Full road closure duration 26/12/21 to 4/1/22 (24hr closure)
 - o Contraflow setup duration 5/1/22 to 10/1/22 (24hr closure) – changed to facilitate the single lane closure on Wardell Road
 - o Detour route on Wardell Road during full road closure
- Victoria Road Full Road Closure

- Duration 26/12/21 to 10/1/22 (24hr closure)
- Detour route on Illawarra Road
- Pedestrians can be managed through the worksite
- Livingstone Road 2 of 4 Lane Closure – One lane both ways to remain open
 - Duration 26/12/21 to 10/1/22 (24hr closure)
 - Detour route no longer required

Albermarle Street, between Challis Avenue and Kays Avenue East, carries around 1,600 vehicles per day. At the railway overbridge the width of the road is approximately 5.7 metres in width. It is noted that the full road closure will divert traffic to either Wardell Road to the north or Livingstone Road to the south. The Traffic Management Plan is included as **Attachment 1**. The Traffic Control Plan submitted by the applicant is shown in **Attachment 2**.

FINANCIAL IMPLICATIONS

Under Council's Fees & Charges, the applicant is to pay a fee for the temporary full road closure. This fee includes advertising the proposal in accordance with the Roads Act 1993.

PUBLIC CONSULTATION

The applicant is to notify all affected residents and businesses in writing at least 7 days prior to the commencement of works.

Community notification by Sydney Metro (SSJ) will include:

- Residents within a 200m radius of the works will be door knocked 7 days prior to any works commencing.
- Notification will be distributed 7 days prior to work commencing to the suburb and surrounding suburbs along the rail corridor.
- A door knock of local businesses with the potential to be impacted will be carried out 14 days before work commences.

The proposed road closure has been advertised on Council's website in accordance with the Roads Act 1993.

CONCLUSION

It is recommended that the proposed temporary full road closure be approved, subject to but not limited to the conditions outlined in this report.

ATTACHMENTS

1. [Traffic Management Plan](#)
2. [Traffic Control Plan](#)



Sydney Metro City & Southwest

Traffic Management Plan for Christmas Shutdown Full Closure of Albermarle Street for the Southwest Metro Corridors Works

John Holland Laing O'Rourke Joint Venture
100a Marrickville Road
Marrickville NSW 2204

Printed copies of this document are uncontrolled



Sydney Metro City & Southwest: Traffic Management Plan

About this release

Document Number: SMCSWSSJ-JHL-WEC-TF-PLN-000054

Title: Traffic Management Plan

Author: Tom Wheatley, Bitzios Consulting

Rev B	22 Oct 2021	Updated for Christmas Shutdown	
Rev A	21 Sep 2021	First release	Shaun Paul Power
Issue	Date	Revision Description	Authorised by

Management Review

See Section 9 for details

Planned Review Date	Scope	Review By	Review Record Ref no. Date
21 Sep 2021		Project Manager and Interface Manager	
21 Sep 2022			
21 Sep 2023			

Endorsement of TMP

Project Manager

Date

/ /

Interface Manager

Date

22 / 10 / 2021

Table of Contents

Management Review	2
Endorsement of TMP	2
1. Overview	6
Scope of this Plan	6
John Holland Laing O'Rourke Joint Venture's Authority:	6
JHLOR JV's Objectives	6
2. Management of the TMP	6
3. Implementation	7
4. Traffic Guidance Schemes	7
5. Responsibilities	8
Project Manager	8
JHLOR JV's Interface Manager	8
JHLOR JV's Site Supervisor	9
Traffic Management Sub-contractor	10
6. Traffic Controllers	10
7. Plant and Equipment	10
8. Time Management	11
9. Out-of-Working Hours Contacts	11
10. Reviewing this Traffic Management Plan	11
11. Proposed Traffic Management	12
A. Description or detailed plan of proposed measures.	12
B. Identification and assessment of impact of proposed measures.	12
C. Measures to ameliorate the impact of re-assigned traffic.	12
D. Assessment of public transport services affected.	12
E. Details of provision made for emergency vehicles, heavy vehicles, cyclists and pedestrians.	12
F. Assessment of effect on existing and future developments with transport implications in the vicinity of proposed measures.	14
G. Assessment of effect of proposed measures on traffic movements in adjoining Council areas.	14
H. Public consultation process	14
Appendix A - Traffic Controllers' Tickets	15



Sydney Metro City & Southwest: Traffic Management Plan

Appendix B -	Not Used	16
Appendix C -	Hold points	16
Appendix D -	JHLOR JV Traffic Control Plans for Routine Work under the Albermarle Street Closure	17
Appendix E -	Comments Register	18
Appendix F – to L –	Not used	19
Appendix M -	Definitions	19
Last page.....		19

Sydney Metro City & Southwest: Traffic Management Plan



Item 6

[THIS PAGE DELIBERATELY BLANK]

Attachment 1



1. Overview

Scope of this Plan

The scope includes the provision for the safe movement of vehicular and pedestrian traffic, the protection of workers from passing traffic, the provision for access to properties located within the limits of the Albermarle Street closure, the design, construction, maintenance and removal of any necessary temporary roadways and detours, the provision of traffic controllers, the installation of temporary signs, road markings, lighting and safety barriers.

It also covers maintenance of the existing road corridor, including the existing road and road shoulder that may be used for the temporary diversion of traffic, over the duration of the Albermarle Street closure.

John Holland Laing O'Rourke Joint Venture's Authority:

Holland Laing O'Rourke Joint Venture (JHLOR JV) is authorised by the Roads Regulation 2008 to appoint traffic controllers and direct traffic and is registered under the RMS's Registration Scheme Category G.

JHLOR JV's Objectives

objectives with respect to the Traffic Management Plan ("TMP") are to:

- Ensure the safety of its employees, contractors, the general public, RMS and Council personnel, pedestrians, cyclists and traffic,
- Keep traffic delays to a minimum,
- Maintain satisfactory property access,
- Minimise disruption to businesses,
- For works near speed cameras, traffic lights & traffic counters etc:
 - Inform the RMS Representative and
 - Not damage the equipment,
 - Make suitable arrangements where required.
- When required, obtain approvals and licenses such as Road Occupancy, Direction to Restrict (DTR for Speed Limit Sign Authorisation) and Traffic Signals,
- Minimise disturbance to the environment,
- Design temporary roadways and detours in accordance with RMS Traffic Control at Work Sites Manual and
- Meet the requirements of RMS G10 Traffic management, RMS G11M Road Occupancy Provisions and the RMS Traffic Control at Work Sites Manual.

2. Management of the TMP

JHLOR JV has warranted that it will provide people, materials, resources and systems to properly perform the Services including related traffic management.

Council and the RMS require the people to be competent, experienced and qualified to carry out the Services.

The Southwest Metro Upgrade Project key personnel for traffic management are shown in the table below.

Name	Position	Phone Number
Tony Waters	Project Leader	0417 593 979
Andrew Constantin	Interface Manager	0418 650 493
Luke Curley	Site Supervisor	0419 816 166
Andie Pitsiatari	Community Place Manager	0429 378 336
Traffic Group Australia (staff name to be confirmed)	Traffic Controller (Blue Card)	TBC
Traffic Group Australia (staff name to be confirmed)	Implement TCPs (Yellow Card)	TBC
Traffic Group Australia (staff name to be confirmed)	Prepare a Work Zone Traffic Management Plan	TBC

3. Implementation

Traffic Management for sites will be in accordance with the RMS Traffic Control at Work Sites Manual as modified to site conditions.

Before the Routine Services or any Ordered Work begins the Project Manager will carry out Risk Assessment (see Risk Management Plan) and develop treatments and Plans to eliminate or mitigate hazards.

4. Traffic Guidance Schemes

JHLOR JV will implement approved Traffic Control measures for any Services which disrupt free traffic movement. These measures will include Traffic Guidance Schemes ("TGS") and Vehicle Movement Plans as required and will encompass vehicle movement and pedestrian movement for both construction resources and the general public. Any property accesses affected by the construction activities will also be identified on the TCPs.

For all planned and scheduled works under the contract JHLOR JV will prepare Traffic Guidance Schemes as follows:

Traffic Guidance Schemes are to be designed in accordance with the Traffic Control at Work Sites Manual Version 6.0.



5. Responsibilities

The principle responsibilities and authorities of JHLOR JV staff with respect to traffic management are:

Project Manager

The Project Manager is responsible for ensuring traffic management:

- Is properly planned, organised, directed and controlled,
- Is properly resourced with people, equipment, facilities and systems and
- Meets the requirements of the contract including RMS Specifications G10 and G11,
- Complies with all other legislation and
- Is achieving its objectives

The Project Manager's responsibilities remain with him / her, however, the Project Manager has delegated as follows:

JHLOR JV's Interface Manager

The Interface Manager has delegated authority from, and responsibility to, the Project Manager for:

- The selection of any Traffic Control subcontractors,
- Ensuring that processes and control systems needed are established, implemented and maintained,
- Liaison with regulatory agencies regarding requirements for approvals, licences, permits and authorities,
- Arranging and approving training,
- Ensuring that the requirements of all the plans are properly implemented,
- Annually reviewing the continuing suitability, adequacy, and effectiveness, of all the plans and
- Community Relations including addressing complaints.

JHLOR JV's Site Supervisor

JHLOR JV's Site Supervisor has delegated authority from, and responsibility to, JHLOR JV's Project Manager for:

- Determination of traffic control at the work sites.
When selecting a standard TCP or designing a Non-Standard TCP, he / she will ensure the following are considered:
 - The signing-off of Non-Standard TCPs by a person who has qualified in the RMS "Design and Audit Traffic Control Plans" course (i.e. holds a current "Orange" ticket) and is experienced in the design and implementation of traffic management plans,
 - Traffic Controllers,
 - Diversions, side tracks and/or detours as required,
 - Temporary warning signs,
 - Signs and devices,
 - Adequate delineation for night/wet conditions,
 - Special lighting when required,
 - Access ways to be kept clear for emergency vehicles and over-dimensional vehicles,
 - Temporary speed zones as required (and approved),
 - Vehicle Movement Plans (including specified locations for on-site parking, and consideration of pedestrian movement for workers, the public including children and disabled persons, bicycles, buses and light rail where applicable).
 - Set up diversions when required in consultation with Police when necessary,
 - Possible impact on main arterial roads,
 - Traffic impact for work near traffic lights,
 - Temporary delineation, barriers and signs until permanent measures are completed. All temporary measures will be maintained in an effective condition while in use and removed when permanent devices are complete including the removal of temporary raised pavement markers and temporary linemarking.
 - Position cones and early warning signs when required,
 - Sign sizes that are appropriate for the conditions,
 - Portable traffic signs if required,
 - Flashing traffic signs if required,
 - Place signs with regard to: Sight distance, motorists approaching at high speed, queue lengths, visibility, shade and light glare,
 - Ensuring only undamaged or non-defective signs are used and
 - Ensuring consideration of the needs of:
 - Pedestrians (including those who are disabled),
 - Cyclists,
 - Business and property owners and
 - School crossings and bus routes.
- Ensuring the TCP is approved,
- Preparing and submitting Hold Point Forms, Road Occupancy License applications and & *Directions to Restrict* applications 10 working days before the Services are due to begin,
- Allocation of all resources required for the implementation of all the plans,



Sydney Metro City & Southwest: Traffic Management Plan

- Ensuring that control measures are maintained and that work-in-progress is inspected,
- Identifying training needs and arranging for employees and subcontractors to attend the training,
- Ensuring subcontractors/suppliers have suitable qualifications and experience and
- Carrying out and recording weekly inspections and verifications to demonstrate compliance of the Services.

Traffic Management Sub-contractor

The Traffic Management Sub-contractor has:

- Qualified in the "Prepare a Work Zone Traffic Management Plan" course [NOTE: It is a Contract requirements that whoever selects and modifies TCPs has this ticket]

and has delegated authority from, and responsibility to, the Site Supervisor for:

- Implementing the Traffic Management Plan and the Traffic Control Plan on site,
- Maintaining the TCP,
- Assessing and monitoring subcontractor's capabilities and performance in respect of site activities,
- Ensuring the safe passage of traffic at all times,
- Ensuring everyone on site is inducted and wears the appropriate approved clothing and
- Driving through the site to inspect the traffic control layout, recording any deficiencies and the action taken to rectify them.

6. Traffic Controllers

JHLOR JV will ensure any subcontractor undertaking traffic control is registered under the RMS's Registration Scheme Category G "Traffic Control".

All traffic controllers used by JHLOR JV have completed MS accredited Traffic Controller training.

Traffic Controllers will carry their tickets with them.

Traffic Controllers will wear high-visibility outer garments complying with RMS OH&S Policy [4.0 Personal Protective Equipment](#) and bearing the words "Authorised Traffic Controller" and the RMS logo (logo patch supplied by the RMS).

7. Plant and Equipment

All vehicles used in traffic control operations will be equipped with the appropriate vehicle mounted warning devices in accordance with the RMS Traffic Control at Work Sites Manual.

During daytime, plant and equipment working in a position adjacent to traffic and having a projection beyond the normal width of the item, for example, a grader blade, will have a fluorescent red flag attached to the outer end of the projection. During poor light conditions or at night, an additional traffic controller with an illuminated red wand will direct traffic around such plant and equipment.

During night time, where traffic is permitted to use the whole or portion of the existing road, all plant items and similar obstructions will be removed from the normal path of vehicles, to provide a lateral clearance of at least 6 m where practicable, with a minimum clearance of 1.2 m.

Plant and equipment, within 6 m of the normal path of vehicles, will be lit by not less than two yellow steady lamps suspended vertically from the point of the obstruction nearest to a traffic lane, and one yellow steady lamp at each end of the obstruction on the side furthest away from the traffic lane.

8. Time Management

The JHLOR JV aims to meet its time related obligations. Among them are:

- Notifying emergency services and relevant sections of the community and transport industry of work which results in significant traffic disruption. Provide to the RMS a draft of an appropriate advertisement 3 weeks before the proposed placement of the advertisement. See RMS M1 Clause 4.3.2.
- Notifying residents and businesses affected by disruption to property access or by night works in built-up areas. A letter will:
 - be "letter-box-dropped" at least three Business Days before the proposed date and
 - detail the dates and times of the proposed access restrictions and contact details. See RMS M1 Clause 4.3.4.
- Performing work and Services only in the times permitted.
- Lodging early as possible (at worst no less than 10 Business Days before the work) a road occupancy application. See RMS G10 (2.2). Noting, however, the exemptions for emergencies and hazards set down at RMS G10 (4.2).
- Promptly advising the TMC of delays to traffic which are, or are anticipated to be, longer than 15 minutes.

9. Out-of-Working Hours Contacts

See contact details in Section 2.

10. Reviewing this Traffic Management Plan

JHLOR JV will review the Traffic Management Plan to ensure it is appropriate and is being implemented effectively. Changes may arise from a change of scope, RMS or Council audits, RMS or Council comments or from opportunities for improvement.

The Plan will then be updated to reflect any changes which have occurred.

The revised document and the input which led to the revisions will be reviewed by JHLOR JV's Project Manager, approved by him/her and then forwarded to the RMS or Council Representative for his/her record.

The planned target dates (or frequencies) at which the TMP will be subject to formal review and the personnel who will participate in the review are identified in the table at *Management Review* at the beginning of this plan. Council's Contract Manager will maintain records of any review.



11. Proposed Traffic Management

A. Description or detailed plan of proposed measures.

Refer to the attached TGS for detail of the proposed closure and diversion route for vehicles. See below for the diversion route for emergency vehicles, heavy vehicles, cyclists and pedestrians.

The traffic closure is to facilitate the Christmas Shutdown Rail Possession activities at the Albermarle St Bridge location. We plan to close all lanes on Albermarle St from the following:

- Sunday 26th December 2021 02:00am to Monday 10th January 2022 05:00am

B. Identification and assessment of impact of proposed measures.

Traffic counts show that at the peak usage of Albermarle Street, 134 vehicles in the AM and 111 vehicles in the PM use the bridge. These numbers indicate use by local traffic rather than rat-running or commuters from outside the local area. Therefore, it is expected that the closure will only affect local trips.

The traffic counts also show 7% of the traffic is heavy vehicles.

The signposted diversion route is 1.9km long and is about 5 minutes driving time according to Google Maps. However, the actual distance and time would be less for most traffic depending on their origin and destination connecting to the diversion route.

C. Measures to ameliorate the impact of re-assigned traffic.

A traffic impact assessment was undertaken for the reassignment of diverted traffic from Albermarle Street onto the alternative route. The findings indicated that the detour route should have sufficient capacity to handle the temporary closures all day and night.

Given that the intersection of Wardell Road and Ewart Street is a SCATS-enabled intersection, it is likely that the system would detect the extra vehicles using that turn and would allocate extra time each phase to optimise performance and minimise delays.

No additional measures are proposed other than the signposting of the alternative route to provide clear guidance to drivers.

The State arterial road network will not experience any increase in traffic due to the diversion. Wardell Road is a Regional Road.

D. Assessment of public transport services affected.

No public transport routes use the bridge on Albermarle Street.

E. Details of provision made for emergency vehicles, heavy vehicles, cyclists and pedestrians.

The alternative route for emergency vehicles when Albermarle Street is closed is via Livingstone Road, Beauchamp Street, Ewart Street, Wardell Road, and Challis Avenue, as shown on the TGS and in Figure 11.1.

Heavy vehicles will also follow the signposted diversion route shown on the TCP and in Figure 11.1.

The suggested alternative route for pedestrians is via the shared path to Kays Avenue East, School Parade, Dudley Street, Wardell Road, and Challis Avenue, as shown in Figure 11.1. The route is 1km.

VMS sign boards are to be installed on approaches to the bridge advising of the proposed closure at least 1 week before the closure date. These will state:

- ALBERMARLE ST
- BRIDGE CLOSED
- DD DEC – DD JAN

The bottom row will be the start and end dates of the detour.

Traffic controllers are required at each end of the Albermarle Street closure during construction hours.

The alternative route for pedestrians (including cyclists) and emergency services vehicles is shown in Figure 11.1.



Source: Nearmap

Figure 11.1 Alternative Route for Pedestrians and Emergency Services



Sydney Metro City & Southwest: Traffic Management Plan

F. Assessment of effect on existing and future developments with transport implications in the vicinity of proposed measures.

As the works are temporary there is no ongoing effect on development. However, notification requirements are noted in Section 8.

G. Assessment of effect of proposed measures on traffic movements in adjoining Council areas.

The work and the diversion route is fully contained within Inner West Council area and will not affect adjoining Councils' road network.

H. Public consultation process.

As the works are temporary there is no need to consult with the public directly affected by the proposed measures. However, notification requirements are noted in Section 8.

Appendix A - Traffic Controllers' Tickets

Surname	First Name	Council or Contractor Name	Certificate Number	Expiry Date




Appendix B - Not Used

Appendix C - Hold points

Reference RMS Doc [Clause no]	Type RMS or JHLOR JV Hold	Process Held	Submission Details
M1 (4.3.2)	RMS Hold	Services which significantly disrupt traffic	Appropriate advertisement 3 weeks before
M1 (4.3.3)	JHLOR JV Hold	Services which significantly disrupt access	Letter box drop 3 Business Days before
RMS G10 (2.2)	RMS Hold	Road Occupancy	ROL Application 10 Business Days before
This Traffic Management Plan Clause:			
1	RMS Hold	Work near Speed Cameras, Traffic Counters etc.	Inform the RMS Representative
3	JHLOR JV Hold	Any Ordered Work	Risk Assessment and Treatment and Plans
4	JHLOR JV Hold	Ordered Work which disrupts traffic	Non-standard relating to the work TCP
6	JHLOR JV Hold	Traffic Controller's engagement as such	Subcontractor registered under Scheme G traffic Controller has current ticket

Appendix D - JHLOR JV Traffic Control Plans for Routine Work under the Albermarle Street Closure

TCP Number	Location	Description of Control
SMCSWSSJ-JHL-WEC-TF-PLN-000054	Albermarle St, Marrickville - Entire Road Closure	Implement detour via Livingstone Road, Beauchamp Street, Ewart Street, Wardell Road.





Sydney Metro City & Southwest: Traffic Management Plan

Appendix E - Comments Register


DOCUMENT NO.	TITLE	VER	STATUS	NO.	DATE	COMPANY	RAISED BY	REVIEW DOC. NO.*	DOCUMENT REF*	DEED REF*	COMMENTS / RESPONSE	COMMENT CATEGORY*	CLOSED OUT
SMCSWSSJ-JHL-WEC-TF-PLN-005794	Southwest Metro Corridor Works - Albermarle Street Closure - Traffic Management Plan	A.01	RVW	01	28/09/2021	TFN	LWILBY				No Comments		N
					22/10/2021	JHLOR JV	ACONSTANTIN				Noted.		N
				02	28/09/2021	SMD	KHIND				No Comments		N
					22/10/2021	JHLOR JV	ACONSTANTIN				Noted.		N
				03	6/10/2021	RMS	CMELLA	Rev A	General	NA	Approval for local road closure must be obtained from local council through regular traffic committee process.	Observation	N
					22/10/2021	JHLOR JV	ACONSTANTIN	Rev A	General	NA	Noted. Local council permits will be obtained.	Observation	N
				04	8/10/2021	SCO	SBROWN				No Comments		Y
					22/10/2021	JHLOR JV	ACONSTANTIN				Noted.		Y
				05	8/10/2021	SCO	JCOLES				No Comments		Y
					22/10/2021	JHLOR JV	ACONSTANTIN				Noted.		Y

Appendix F – to L – Not used

Appendix M - Definitions

JHLOR JV has adopted the Definitions set out in Clause 1.3 of RMS Specification G10 Traffic Management.

Last page



Item No: LTC1121(1) Item 7

Subject: PEDESTRIAN ACCESS AND MOBILITY PLAN STUDY (ALL WARDS/ALL ELECTORATE/ ALL PACS)

Prepared By: Felicia Lau - Engineer - Traffic and Parking Services

Authorised By: Manod Wickramasinghe - Traffic and Transport Planning Manager

SUMMARY

A Pedestrian Access and Mobility Plan (PAMP) is a comprehensive strategic action plan used to develop pedestrian policies and build pedestrian facilities.

The draft PAMP study was put to Public Exhibition for 28 days in May and June 2021. Community feedback was collated and assessed to develop the final PAMP Action Plan as outlined in Attachment 1.

The final PAMP identifies maintenance and capital works to a value of approximately \$18 million of which \$8 million are high priority items. These works are recommended to be incorporated into Council's Operational Program and Capital Works Program as well as grant funding applications. It is envisaged that the PAMP will be reviewed and updated approximately every 5 years in order to identify arising issues and rebalance priorities.

RECOMMENDATION

THAT:

1. The final Pedestrian Access and Mobility Plan (PAMP) report be adopted; and
2. The PAMP action plan detailing maintenance and capital works be supported to be included in Council's operational program and Capital Works Program, noting some implementation may subject to further Local Traffic Committee and Council approval of detailed designs.

BACKGROUND & OTHER STAFF COMMENTS

The most recent PAMP was commissioned by former Ashfield Council in 2015/16, whilst the Leichhardt PAMP was updated in 2014 and the Marrickville PAMP was updated in 2009. Since amalgamation, there have been a number of changes to land use, policy and infrastructure which triggered a need to develop an Inner West PAMP. The development of an Inner West PAMP for the entire LGA was one of recommendations in the action plan in Council's adopted Integrated Transport Strategy.

A PAMP is a comprehensive strategic report that builds an updated and prioritised Action Plan for pedestrian facilities with a focus on encouraging and increasing localised pedestrian activity. This has been developed in accordance with Transport for NSW's guide 'How to Prepare a Pedestrian Access and Mobility Plan'.

The collected data and site inspections have led to the development of the PAMP Action Plan. The main aims of the Action Plan are to provide a programme for the implementation of pedestrian facilities that can be readily identified, budgeted and prioritised so that the existing facilities may be maintained or upgraded and new facilities can be constructed.

The Action Plan has been staged implementation of high, medium and low priorities to be undertaken over a period of ten years. The works include proposals such as pedestrian crossings, signposting and linemarking, resealing, footpath upgrades/widening, kerb ramps, accessible ramps, speed cushions, pedestrian refuges, lighting upgrades, rough surface upgrades, tree trimming and pedestrian fencing.

The estimated total cost to implement the PAMP project over a period of 10 years is approximately \$18 million. A detailed list of all works necessary and budget is presented in the Appendix E of the final report.

FINANCIAL IMPLICATIONS

The final PAMP Action Plan details maintenance and capital works to a value of approximately \$18 million of which \$8 million are high priority items. It has been recommended that works are programmed over 10 years, although this timeframe will vary depending upon funding levels allocated by:

- Council's Operational Program and Capital Works Program, some implementation is subject to further Local Traffic Committee support and adoption by Council.
- State or Federal Government grant applications.
- Potential implementation of relevant Section 7.11 and 7.12 development contributions plans in proposed uplift areas.

PUBLIC CONSULTATION

Public Exhibition of the PAMP commenced on 26 May 2021, this included high priority recommendations being displayed on an interactive map through Council's website. Feedback was provided via an online form or through direct channels, such as emails.

The PAMP project page was viewed 319 times with 25 providing direct feedback. Overall, there were over 170 individual downloads across 4 documents, 23 video views and 104 map views. Additional six responses provided via email, resulting in a total 31 responses during the public exhibition period.

The feedback related to pedestrian infrastructure has been collated and included in the final PAMP report and include:

- Raising existing at-grade marked pedestrian crossings within high pedestrian traffic areas.
- Investigation study to convert Prospect Street, Leichhardt to shared zone.
- Masterplan study to investigate better pedestrian connectivity along Johnston's Creek.

REVIEW PROCESS

It is envisaged that the PAMP will be reviewed and updated approximately every 5 years in order to identify arising issues and rebalance priorities. Between these plans, specific pedestrian investigations will continue during Local Area Traffic Management studies and ad-hoc investigations.

CONCLUSION

The proposed PAMP Action Plan in Appendix E outlines the recommended maintenance and capital works, categorizing into high, medium and low priority. It is recommended that these works be supported and included in Council's Operational Program and Capital Works Program.

ATTACHMENTS

1. [PAMP Study Final Report](#)
2. [Appendix A - Engagement Outcome Report](#)
3. [Appendix B - PAMP Audit Routes](#)
4. [Appendix C - PAMP Route Hierarchy](#)
5. [Appendix D - Audit Findings](#)
6. [Appendix E - PAMP Action Plan](#)



Inner West Pedestrian Access and Mobility Plan

Final Report

Inner West Council

06 August 2021

Item 7



Attachment 1

Gold Coast

Suite 26, 58 Riverwalk Avenue
Robina QLD 4226
P: (07) 5562 5377

Brisbane

Level 2, 428 Upper Edward Street
Spring Hill QLD 4000
P: (07) 3831 4442

Sydney

Studio 203, 3 Gladstone Street
Newtown NSW 2042
P: (02) 9557 6202

W: www.bitziosconsulting.com.au

E: admin@bitziosconsulting.com.au

Copyright in the information and data in this document is the property of Bitzios Consulting. This document and its information and data is for the use of the authorised recipient and this document may not be used, copied or reproduced in whole or in part for any purpose other than for which it was supplied by Bitzios Consulting. Bitzios Consulting makes no representation, undertakes no duty and accepts no responsibility to any third party who may use or rely upon this document or its information and data.

Document Issue History

Report File Name	Prepared	Reviewed	Issued	Date	Issued to
P4909.001R Inner West PAMP - Draft	M. Hearne, K. Wu, G. Yin	S. Brooke	G. Yin	26/03/2021	Felicia Lau (Inner West Council) Via email: felicia.lau@innerwest.nsw.gov.au
P4909.002R Inner West PAMP - Draft	G. Yin	S. Brooke	G. Yin	08/04/2021	Felicia Lau (Inner West Council) Via Google DropBox: felicia.lau@innerwest.nsw.gov.au
P4909.003R Inner West PAMP	G. Yin	S. Brooke	G. Yin	06/08/2021	Felicia Lau (Inner West Council) Via Google DropBox: felicia.lau@innerwest.nsw.gov.au



Inner West Pedestrian Access and Mobility Plan: Final Report
Project: P4909 Version: 003



EXECUTIVE SUMMARY

The Inner West is one of Sydney's most populated LGAs and has the second highest population density. As such, there is great benefit to shift people away from private vehicles and onto active transport options. Regardless of travel modes, walking typically makes up the start or end of any trip.

Bitzios Consulting was commissioned by Inner West Council to undertake and develop the Inner West PAMP to provide an updated and consolidated PAMP that covers the entire LGA. The PAMP intends to provide Council with a long-term strategy for the development and improvement of pedestrian routes and facilities with a focus on encouraging and increasing localised pedestrian activity.

The PAMP was developed in accordance with Transport for NSW's Guide 'How to Prepare a Pedestrian Access and Mobility Plan'.

The overarching objectives of the PAMP included:

- *To facilitate improvements in the level of pedestrian access and priority, particularly in areas of pedestrian concentration*
- *To reduce pedestrians access severance and enhance safe and convenient crossing opportunities*
- *To identify and resolve pedestrian crash clusters*
- *To ensure that pedestrian facilities remain appropriate and relevant to the surrounding land use and pedestrian user groups.*

An initial engagement program was conducted to gain an insight on pedestrian and access issues currently faced by Inner West residents and visitors. The engagement process was primarily conducted online using an interactive map on the *Your Say* website and yielded responses from nearly 300 users. Most of who lived within the Inner West.

The demographic of the Inner West is primarily made up of parents and home-owners (aged 35 to 49) and the young workforce (aged 25-34) both of which are higher than the Greater Sydney average.

Journey to work statistics also show most residents work in adjoining LGAs (including City of Sydney) which places further importance on walking as a primary travel mode. Around 5% of residents currently walk to work.

The PAMP focusses on key areas and strategic links throughout the LGA and includes all 26 suburb areas. A review of pedestrian attractors and generators show a strong distribution across the study area, including schools, parks and community facilities.

Historic crash data shows a concentration of pedestrian related crashes within town centres and along main road corridors, totalling 324 crashes over the past five years.

Routes were selected as part of the investigation based on previously developed PAMPs (Ashfield, Leichardt and Marrickville) and various strategic documentation. These routes were then subject to a detailed site investigation and audit looking into pedestrian issues relating to missing pathways, narrow pathways, crossing deficiencies, obstructions, connectivity issues and pedestrian safety issues.

A recommended works program has been developed to assign a priority to each correcting action associated with identified issues. The action plan will inform future works program and assist Council in programming future works to improve the pedestrian network.

Based on these recommended actions, the project was estimated to cost approximately **\$18.1 million**, with an additional **\$3.6 million** as a project contingency.



CONTENTS

	Page
EXECUTIVE SUMMARY	III
1. INTRODUCTION	7
1.1 Background	7
1.2 PAMP Methodology	7
2. PAMP OBJECTIVES	10
2.1 Overview	10
2.2 Connectivity and Missing Links	10
2.3 Pedestrian Safety in Key Areas	10
2.4 Complementing Other Projects and Procedures	11
3. COMMUNITY AND STAKEHOLDER ENGAGEMENT	12
3.1 Engagement Process	12
3.2 Interactive Mapping	12
3.3 Email Submissions	13
3.4 Community Group Sessions	13
3.5 Use of Community Engagement Findings in PAMP	14
4. INNER WEST CHARACTERISTICS	15
4.1 Overview	15
4.2 Population	16
4.2.1 Overview	16
4.2.2 Current demographics	17
4.3 Employment in the Inner West	18
4.4 Journey to Work data	18
4.5 Transport Characteristics	20
4.5.1 Travel characteristics	20
4.5.2 Public Transport	20
4.6 Future Growth and Development Areas	22
4.6.1 Parramatta Road Corridor	22
4.6.2 Sydney Metro Corridors	23
4.7 Links to Neighbouring Areas	23
5. PAMP FOCUS AREAS	25
5.1 Overview	25
5.2 Pedestrian Attractors and Generators	25
6. RESEARCH AND REVIEW	27
6.1 Overview	27
6.2 State Government Plans	27
6.2.1 Eastern City District Plan	27
6.3 Local Plans and Strategies	27
6.3.1 Community Strategic Plan	27
6.3.2 Inner West Integrated Transport Plan (ITS)	28
6.3.3 Inclusion Action Plan	28
6.4 Local Plans and Projects	29
6.4.1 Greenway – Cooks River to Iron Cove	29
6.4.2 Parramatta Road Urban Transformation Strategy	29

6.4.3	Iron Cove Creek / Dobroyd Canal Cycle and Pedestrian Path	30
6.4.4	Inner West @ 40	30
6.5	Previous PAMPs	30
6.5.1	Marrickville PAMP (2009)	30
6.5.2	Leichhardt PAMP (2014)	31
6.5.3	Ashfield PAMP (2016)	31
6.6	Planned Infrastructure and Major Developments	31
6.6.1	Sydney Metro	31
6.6.2	WestConnex	31
7.	PEDESTRIAN CRASH DATA REVIEW	32
7.1	Overview	32
7.2	Crash Summary by Suburb	33
7.3	Crashes by Street	35
7.4	Crash Severity	35
7.5	Crash Type	36
7.6	Crash Clusters	38
7.7	Crash Data Analysis Summary	38
8.	DEVELOPMENT OF PRIORITISED PEDESTRIAN NETWORK	40
8.1	Overview	40
8.2	Route Selection	40
8.3	Route Hierarchy	42
8.3.1	Route Segments	42
8.3.2	Scoring Criteria	42
8.3.3	Segment Ranking / Priority	43
9.	PEDESTRIAN ROUTE AUDITS	45
9.1	Methodology	45
9.2	Audit Findings	48
9.3	Audit Limitations	50
10.	RECOMMENDED WORKS PROGRAM	52
10.1	Works Prioritisation	52
10.1.1	Prioritisation criteria	52
10.1.2	Scoring system	52
10.2	Implementation Costs	54
10.3	Other Costs	57
10.3.1	Other Pedestrian Routes	57
10.3.2	Ongoing Maintenance	57
10.3.3	Major Infrastructure and Projects	58
10.4	Implementation of Treatments and Further Investigations	58
11.	IMPLEMENTATION AND FUNDING	59
11.1	Potential funding sources	59
11.1.1	Transport for NSW	59
11.1.2	Development Contribution Plans	59
11.2	Monitoring and Evaluation	59
12.	CONCLUSIONS AND RECOMMENDATIONS	60
12.1	Conclusions	60

Tables

Table 4.1:	Key Bus Services
Table 7.1:	Pedestrian Crashes by Suburb
Table 7.2:	Highest Number of Pedestrian Involved Crashes by Street
Table 7.3:	Crash Severity
Table 7.4:	Pedestrian Involved Crash Types
Table 7.5:	Crash Type Severity
Table 7.6:	Intersection Crash Clusters – Pedestrian Involved Crashes
Table 8.1:	PAMP Route Criteria and Scoring
Table 8.2:	Segment Ranking
Table 9.1:	Audit Issues Examples
Table 9.2:	Audit Issues by Type
Table 9.3:	Locations Not Audited
Table 10.1:	Treatment Priority Scoring Criteria
Table 10.2:	Project Costs
Table 10.3:	Cost by Priority
Table 10.4:	Cost by Road Type

Figures

Figure 1.1:	PAMP Development Methodology
Figure 1.2:	PAMP Study Area – Inner West LGA
Figure 3.1:	Inner West Council – Your Say Website and Interactive Map
Figure 4.1	Inner West LGA and Surrounds
Figure 4.2	Population Density of the Inner West LGA
Figure 4.3	Age Profile of Inner West in Comparison with Greater Sydney
Figure 4.4	Employment Industry Profile of Inner West
Figure 4.5	Resident Employment Location
Figure 4.6	Travel Mode Share of Inner West Residents
Figure 4.7	Public Transport within the Inner West
Figure 4.8:	Pedestrian Corridor Connections to Neighbouring Areas
Figure 5.1	Pedestrian Attractors and Generators within Inner West LGA
Figure 7.1	Total Number of Pedestrian Crashes for Inner West LGA
Figure 7.2	Inner West LGA Crash Map - Pedestrian Involved Crashes
Figure 8.1	Inner West PAMP Routes
Figure 8.2:	Route Segment Rankings
Figure 9.1:	Pedestrian Route Deficiencies
Figure 10.1:	Priority Issues and Works

Appendices

Appendix A:	Engagement Outcomes Report
Appendix B:	Audit Routes
Appendix C:	Route Hierarchy
Appendix D:	Audit Findings
Appendix E:	Detailed Works Program

1. INTRODUCTION

1.1 Background

Active modes of transport are the most basic and equitable forms of transport available. Most individual trips, regardless of the type of transport used, begin and / or finish with a walk section, making walking a major element of all travel. Of the top 20 most populated LGAs in Sydney, the Inner West has the second highest population density. Areas such as these often see higher degrees of benefit to shift people away from private vehicles and onto active transport options. This would be especially beneficial in the Inner West, where old, narrow streets have limited options for improvement.

The most recent PAMP was commissioned by former Ashfield Council in 2015/16, whilst the former Leichhardt PAMP was updated in 2014 and former Marrickville PAMP updated in 2009. Since the amalgamation of Ashfield, Leichhardt and Marrickville Councils in 2016, there have been a number of changes to land use, policy and infrastructure which has triggered the need to develop an updated and consistent PAMP for the entire Inner West LGA.

Bitzios Consulting was commissioned by Inner West Council (Council) to develop the updated PAMP, with the intention of providing Council a long-term strategy for the development and improvement of pedestrian routes and facilities with a focus on encouraging and increasing localised pedestrian activity within the Inner West LGA. This can be achieved by improving the safety, convenience, connectivity, and accessibility of pedestrian routes across the network.

This report presents the findings of the study and contains the following:

- An assessment of the existing situation, activity centres and pedestrian routes
- Identification of deficiencies in the existing pedestrian network
- An audit of identified pedestrian routes
- A list of recommendations to detail and priorities as future projects for Council to implement.

1.2 PAMP Methodology

The purpose of this PAMP is to guide the future provision and management of pedestrian access and mobility facilities within the Inner West. To achieve this, the PAMP was developed in accordance with the TfNSW Guide *'How to Prepare a Pedestrian Access and Mobility Plan'*. This guide identifies three stages in the PAMP process, shown in Figure 1.1.

- Stage 1: Defining Objectives
- Stage 2: Preparation and community consultation
- Stage 3: Implementation.





Figure 1.1: PAMP Development Methodology

This PAMP study covers the entire Inner West LGA, shown in Figure 1.2, with focus on key areas and emphasis on routes identified in previous Council PAMPs and other Inner West Council strategic documents. In consultation with Council, a defined PAMP area for this study was developed, which is further discussed and presented in Section 8.



Source: Community.id

Figure 1.2: PAMP Study Area – Inner West LGA

2. PAMP OBJECTIVES

2.1 Overview

The aim of this PAMP is to provide a strategy that improves pedestrian safety and promotes walking throughout the Inner West LGA. The PAMP objectives as outlined in the NSW TfNSW Guide 'How to Prepare a Pedestrian Access and Mobility Plan', have been incorporated in this PAMP as follows:

- To facilitate improvements in the level of pedestrian access and priority, particularly in areas of pedestrian concentration
- To reduce pedestrians access severance and enhance safe and convenient crossing opportunities
- To identify and resolve pedestrian crash clusters
- To ensure that pedestrian facilities remain appropriate and relevant to the surrounding land use and pedestrian user groups.

These overarching objectives will drive the purpose and implementation of this PAMP.

2.2 Connectivity and Missing Links

In addition, the Inner West PAMP specifically aims to:

- Provide a network of safe, inclusive, connected and convenient pedestrian routes which will encourage the shift from car dependency to walking.
- Enhance the pedestrian network to allow all pedestrians to enjoy safe, convenient and coherent independent mobility.

A key focus of the PAMP is to identify and complete key pedestrian connections in the wider pedestrian network. Improving connectivity would also include the provision of usable and safe crossing facilities such as kerb ramps or pedestrian refuges connecting two footpaths across a section of road, or provision of pedestrian priority facilities such as pedestrian crossings, signalised crossings or shared zones.

2.3 Pedestrian Safety in Key Areas

The PAMP also aims to increase pedestrian safety, particularly in key centres, town centres and areas of high pedestrian concentration. Where possible, and supported by detailed investigation, the PAMP supports the use of treatments to increase pedestrian safety, such as:

- Upgrading of existing at-grade pedestrian crossings to raised pedestrian (wombat) crossings to slow vehicle speeds and increase visibility of pedestrians, particularly:
 - Within town centres
 - Near schools and education facilities
 - Near public transport hubs (such as train stations)
- Progressively and where funding permits, implement Continuous Footpath Treatments (CFTs) across side streets within town centres
- Implementation of 40km/h High Pedestrian Activity Areas (HPAAs) in town centres and villages
- Introduction Shared Zones along local streets in mixed development areas.

2.4 Complementing Other Projects and Procedures

Where possible, the Inner West PAMP also aims to complement and support other related projects and procedures to improve the pedestrian network and experience across the LGA. This includes (but is not limited to):

- Key pedestrian projects identified within the Inner West Integrated Transport Strategy
 - Inner West @ 40 – reducing the speed limit to 40km/h in local areas
 - The Greenway and The Green Grid
 - Planning and Building the Inner West Pedestrian Network
- Council's *Report an Issue / Request a Service* online portal
- Future streetscape, public domain projects or masterplans.

Related key projects within the ITS are further detailed in Section 6.

3. COMMUNITY AND STAKEHOLDER ENGAGEMENT

3.1 Engagement Process

An initial engagement program was conducted by Council to gather resident feedback on existing pedestrian issues across the Inner West. The engagement period was conducted between 23 November and 22 December 2020. Three community engagement methods were used:

- Online – via an interactive map on Your Say Inner West
- Online – via individual email submissions
- Community group sessions

Local democracy groups and community groups were invited to participate in the community group sessions. The Vietnamese Seniors Group and Arabic Seniors Group accepted the invitation and in-language sessions were conducted with these two groups via interpreters.

A detailed review of the input from the engagement is discussed in the Engagement Outcomes Report, included in **Appendix A**.

3.2 Interactive Mapping

An online interactive map via the *Your Say* website allowed users to place a pin under different categories to provide location-based comments of pedestrian issues, shown Figure 3.1.

A summary of the findings from this engagement method is as follows:

- A total of 836 responses were submitted from 295 participants
- 98% of responses were provided by Inner West residents
- The majority (52%) of participants are within the 35-49 year age group
- The majority of participants reside in Annandale (14%), Leichhardt (11%), Marrickville (11%), and Stanmore (10%)
- Footpaths within the Inner West are used for a variety of purposes, in which there is no dominant purpose
- Using footpaths for travelling to/from shops is the most common (19%), and travelling to/from school is the least common (9%)
- A relatively similar proportion of participants use footpaths to commute to work (13%) and for leisure, health and fitness purposes (13%)
- The most common categories of submissions were related to safety concerns (62%) and accessibility concerns (15%)
- Notably, the top three reported submissions were related to vehicle behaviours, footpath connectivity and obstructions, and crossing deficiencies, comprising of approximately 70% of all submissions
- The greatest number of responses submitted were recorded in the suburbs of Marrickville (14%), Newtown (11%), Ashfield (10%), and Annandale (9%).




Figure 3.1: Inner West Council – Your Say Website and Interactive Map

3.3 Email Submissions

An email campaign allowed users to submit individual responses if they did not wish to use the online interactive map. A summary of findings from this engagement method is as follows:

- A total of 14 individual responses were received from individuals and groups of residents of the Inner West, including the local State MP for Summer Hill, Jo Haylen, supporting the pedestrian study
- The common themes across all responses were related to footpath facilities and pedestrian safety.

3.4 Community Group Sessions

Local democracy groups and community groups were invited to participate in the community group sessions. The Vietnamese Seniors Group and Arabic Seniors Group accepted the invitation and in-language sessions were conducted with these two groups via interpreters.

A summary of findings from this engagement method is as follows:

- A total of 3 community groups were engaged including a Vietnamese mother's group, Vietnamese senior's group, and Arabic senior's group
- A total of 31 issues were provided by 30 participants involved
- The most commonly raised concerns were related to the following:
 - Poor pedestrian facilities on Petersham Road (29%)
 - Cars parking on footpaths (10%)
 - Accessibility difficulties with uneven footpaths due to tree roots (10%).

3.5 Use of Community Engagement Findings in PAMP

Overall, a total of 881 submissions were received from 339 participants involved in the initial engagement process.

The data received provided important insights on the behaviours, challenges and issues for pedestrians in the Inner West and identified locations of key concerns related to pedestrian accessibility, connectivity, and safety. The locations of these related issues were identified and considered in the PAMP study.


4. INNER WEST CHARACTERISTICS

4.1 Overview

The Inner West is located in NSW, within the inner Sydney city area. It is located adjacent to the Sydney CBD area and is bounded by City of Sydney LGA to the east, Bayside LGA to the south, Canterbury-Bankstown LGA and Burwood LGA to the west, and Canada Bay LGA and the Parramatta River to the north.

The Inner West has a total area of approximately 35 km², and is predominantly comprised of residential areas, but also has substantial commercial, industrial and marina areas.

A map of the Inner West LGA and surrounds is shown in Figure 4.1.



Source: NationalMap


Figure 4.1 Inner West LGA and Surrounds

4.2 Population

4.2.1 Overview

Inner West has an estimated population (2021) of around 204,400 people, according to Australian Bureau of Statistics (ABS) Census Data and is forecast to reach 247,881 people by the year 2041, representing a 21.7% increase over the 20 years from 2021.

The Inner West is one of Sydney's most populated LGAs and has the second highest population density. Figure 4.2 illustrates the population density by area within the Inner West LGA.



Source: Inner West Social Atlas

Figure 4.2 Population Density of the Inner West LGA


The population is dispersed across the LGA with the highest density areas located in Newtown, Ashfield, Dulwich Hill, and Balmain, with densities between 70 to 100 persons per hectare.

4.2.2 Current demographics

Pedestrian planning considers a number of pedestrian facility user groups based on age and assumed mobility levels. To develop this PAMP, key pedestrian demographic groups were derived from TfNSW's Guide *How to Prepare a Pedestrian Access and Mobility Plan*, as follows:

- Infants (ages 0 - 4)
- Pre-school (ages 5 - 8)
- Primary (ages 9 - 11)
- Secondary (ages 12 - 17)
- Young adults (ages 18 - 25)
- Adults (ages 26 - 59)
 - Adults (a) from 26 - 39 years old
 - Adults (b) from 40 - 59 years old
- Elderly (ages 60+)
 - Elderly (a) from 60 - 69 years old
 - Adults (b) from 70+ years of age.

The age profile for the Inner West LGA is presented in Figure 4.3 in comparison with the Greater Sydney according to the 2016 census data.



Source: Australian Bureau of Statistics 2016

Figure 4.3 Age Profile of Inner West in Comparison with Greater Sydney


The predominant service age groups within the Inner West LGA are parents (aged 35 to 49) and the young workforce (aged 25 to 34). Comparatively, there is a higher proportion of these age groups compared to Greater Sydney.

In comparison, the proportion of school children (aged 5 to 17) are much lower. The community profile indicates a middle-aged population and an emerging younger and elderly population. This presents the current challenge to provide safer pedestrian facilities and crossings for school children, and slower travelling or immobile pedestrians.

Typically, the parents demographic group requires good footpath and kerb ramp connectivity to properly navigate with a pram or walk young children who may be less experienced and vulnerable.

4.3 Employment in the Inner West

Employment numbers in the Inner West LGA have increased approximately 6.9% from 2011 to 2016. This increase in employment may be the result of the emerging young workforce and current middle-aged population. A summary of the employment industry profile within the Inner West LGA is shown in Figure 4.4.



Source: Australian Bureau of Statistics 2016

Figure 4.4 Employment Industry Profile of Inner West

The key employment industries within the Inner West are the professional, scientific, and technical services, health care and social assistance, and education and training. The greatest changes to employment sectors from 2011 to 2016 were a reduction to manufacturing and wholesale trade, and an increase to professional, scientific and technical services, and construction.

The employment profile further reiterates the current demographics of the middle-aged and emerging young population.

4.4 Journey to Work data


ABS Journey to Work (JTW) data was used to gain an understanding of work locations and typical modal shares for trips to work by the residents of the LGA.

Key JTW statistics include:

- Approximately 43% of employed residents travel to the City of Sydney for work, followed by the Inner West (20%) and North Sydney (4%)
- 'Outbound' commute trips outside the Inner West make up 77% of residents within the area
- Approximately 31% of workers within the Inner West are residents of the area, followed by residents from Canterbury-Bankstown (12%) and City of Sydney (6%) LGA's
- 'Inbound' commute trips to the Inner West make up 69% of workers within the area
- The data shows that there is a higher proportion of 'outbound' journeys to work outside of the Inner West, with a relatively similar proportion of 'inbound' commute trips and a low level of 'local' journeys


- The predominant mode of transport for Inner West residents is by private car, as a driver or passenger (39% combined)
- 37% of workers travel by public transport including:
 - Train (25%)
 - Bus (11%)
 - Ferry (1%).
- Approximately 5% of people walk to work.

Figure 4.5 shows the place of employment for residents within the Inner West and Figure 4.6 shows the travel modes for Inner West residents commuting to work.



Source: Australian Bureau of Statistics 2016

Figure 4.5 Resident Employment Location



Source: Australian Bureau of Statistics 2016

Figure 4.6 Travel Mode Share of Inner West Residents

The data shows that the total number of people using public and active transport are similar to the number of people using private cars. Pedestrian activity forms part of every journey, either at the start or end of each travel mode, as people will move from their mode of transport to their destinations (i.e. school, sporting fields, work, etc.). This incidental activity highlights the importance of the active transport network.

4.5 Transport Characteristics

4.5.1 Travel characteristics

The Inner West LGA is well serviced by public transport with multiple forms available including bus, heavy rail, light rail, and ferry services. These services provide connectivity within the Inner West, to Greater Sydney, and the Greater Western Sydney region. There are three rail corridors providing east-west connectivity in the central region, and the southern extents of the Inner West. The Light Rail extends the connectivity within the Inner West through the north-south direction and towards the city. The northern region of the Inner West is primarily serviced by bus and ferry services.

The Inner West is also well connected through an extensive network of footpaths throughout a significant portion of the area to town centres, public transport, parks, and various attractors.

4.5.2 Public Transport


Figure 4.7 shows the various public transport routes, stops and stations servicing the Inner West LGA.

Bus

There are over 25 bus routes servicing the Inner West. Table 4.1 is a summary of the key bus routes within the Inner West.

Table 4.1: Key Bus Services

Bus Service	Destination 1	Destination 2
M30	Spit Junction	Sydenham
M10	Leichhardt	Randwick
308	Marrickville	City
348	Wolli Creek	Bondi Junction
352, 355	Marrickville	Bondi Junction
412, 413	Campsie	City
418	Bondi Junction	Burwood
422	Kogarah	City
423, L23, 426	Kingsgrove and Dulwich Hill	City
425	Tempe	Dulwich Hill
428, L28	Canterbury	City
444, 445	Balmain East Wharf	Campsie
461	Burwood	City
480, 483	Strathfield	City
438, L38	Abbotsford	City
439, L39	Mortlake	City



Source: Council GIS Data

Figure 4.7 Public Transport within the Inner West

Train

There are four train lines servicing 10 train stations within the Inner West. These are:

- **T3 Bankstown Line** – Dulwich Hill, Marrickville, Sydenham, St Peters. Services to the City or to Liverpool/Lidcombe via Bankstown.
- **T4 Eastern Suburbs & Illawarra Line** – Sydenham, Tempe. Services to Bondi Junction via the City, or to Mortdale/Waterfall/Cronulla.
- **T2 Inner West & South Line** – Newtown, Stanmore, Petersham, Lewisham. All-stations services to the City or to Homebush.
- **T2 Airport Line** (weekday peak only) – Sydenham. Express services to the City (morning peak) and to Campbelltown (afternoon peak).

Light Rail

The L1 Dulwich Hill Line connects Dulwich Hill and Central via Leichardt and Pyrmont. Light Rail stations serviced by this route are:

- | | |
|-----------------|---------------------|
| ▪ Dulwich Hill | ▪ Taverners Hill |
| ▪ Dulwich Grove | ▪ Marion, Hawthorne |
| ▪ Arlington | ▪ Leichardt North |
| ▪ Waratah Mills | ▪ Lilyfield |
| ▪ Lewisham West | ▪ Rozelle Bay |

Ferry

There are three wharfs within the Inner West towards the northern region of Balmain which are serviced by two Sydney Ferries services, including:

- **F3 Parramatta River Service** – Birchgrove Wharf (at Louisa Road), and Balmain Wharf (at Thames Street)
- **F4 Darling Harbour Service** – Balmain East Wharf (at Darling Street).

These services provide connectivity to and from Parramatta River, Pyrmont Bay, and Circular Quay.

4.6 Future Growth and Development Areas

4.6.1 Parramatta Road Corridor

The Parramatta Road Corridor within the Inner West includes three of the eight recognised precincts under the Parramatta Road Urban Transformation Strategy (PRUTS), including:


- Taverners Hill (near Lewisham)
- Leichardt
- Camperdown
- Part of Kings Bay (City of Canada Bay)

The Parramatta Road Corridor Urban Transformation Strategy (PRCUTS) sets out the NSW Government's 30 year plan for the Corridor and identifies the future land use, development decisions and long-term infrastructure.

Through changes to planning controls and rezoning of existing land uses, housing and population density is expected to increase in these areas, including the development of high-density residential buildings and improved public transport services.

4.6.2 Sydney Metro Corridors

4.6.2.1 Sydney Metro – Southwest



The Sydenham to Bankstown Urban Renewal Corridor Strategy aims to create more housing, jobs and infrastructure around the eleven train stations on the Sydenham to Bankstown line and make this area a high-frequency metro train service under the Sydney Metro Southwest project.

Under the Plan, the construction of the Sydney Metro Southwest is anticipated to increase the number of dwellings and employment opportunities along the corridor, particularly within the Sydenham, Marrickville and Dulwich Hill areas.

The plan is expected to generate:


- Sydenham Station Precinct: 500 additional dwellings and 711 jobs
- Marrickville Station Precinct: 6,000 additional dwellings and 555 jobs
- Dulwich Hill Station Precinct: 2,000 additional dwellings and 275 jobs.

4.6.2.2 Sydney Metro - West

While no stations along Sydney Metro West are proposed to in the Inner West, the locality of the nearest stations is likely to see an increase in pedestrian activity.

The Metro presents itself as more appealing public transport option, reducing dependency on private vehicle travel, and increase pedestrian activity due to passenger walk up to the stations.

The station proposed for Five Dock will see Inner West residents in the Haberfield and Ashfield areas walking to and from the station. The station proposed for White Bay will see an increase in pedestrian activity related to the station and the White Bays Precinct development.



4.7 Links to Neighbouring Areas

Being centrally located between other LGAs, the Inner West pedestrian network is well connected to neighbouring areas and beyond. This includes a number of corridors and routes:

Main Roads

- | | | |
|-------------------|---------------------------|----------------------|
| ▪ Parramatta Road | ▪ Broadway | ▪ Canterbury Road |
| ▪ Liverpool Road | ▪ King Street / City Road | ▪ Georges River Road |
| ▪ Princes Highway | ▪ Ramsay Street | ▪ Bridge Road |


Bridges

- | | | |
|-------------------|------------------|-----------------|
| ▪ Princes Highway | ▪ Wardell Road | ▪ Canal Road |
| ▪ Victoria Road | ▪ Illawarra Road | ▪ Campbell Road |
| ▪ Anzac Bridge | ▪ Bayview Avenue | |

Parks and Off-Road Paths

- Bay Run
- Jubilee Park / Bicentennial Park
- Sydney Park
- Cooks River Foreshore

Key routes and connections to neighbouring LGAs are shown in Figure 4.8.



Adapted from National Map

Figure 4.8: Pedestrian Corridor Connections to Neighbouring Areas

5. PAMP FOCUS AREAS

5.1 Overview

The Inner West is comprised of 26 suburb areas, including:

- | | |
|------------------------------|-----------------------|
| ▪ Annandale | ▪ Leichhardt |
| ▪ Ashbury (Partially) | ▪ Lewisham |
| ▪ Ashfield | ▪ Lilyfield |
| ▪ Balmain | ▪ Marrickville |
| ▪ Balmain East | ▪ Mascot (Partially). |
| ▪ Birchgrove | ▪ Newtown |
| ▪ Camperdown | ▪ Petersham |
| ▪ Croydon (Partially) | ▪ Rozelle |
| ▪ Croydon Park (Partially) | ▪ St Peters |
| ▪ Dulwich Hill | ▪ Stanmore |
| ▪ Enmore | ▪ Summer Hill |
| ▪ Haberfield | ▪ Sydenham |
| ▪ Hurlstone Park (Partially) | ▪ Tempe |


The Inner West is primarily comprised of low to medium density residential, retail and commercial within suburb core centres, and industrial towards the south-eastern extents. There are also a high number of parks and educational areas within the Inner West.

5.2 Pedestrian Attractors and Generators

When developing a PAMP, certain land-uses are considered key pedestrian attractors and generators of trips. Typically, these include:

- Shopping centres and main streets
- Educational facilities
- Hospitals and medical centres
- Aged care facilities
- Childcare centres, pre-schools, out of school hours care facilities
- Community halls and facilities, neighbourhood centres, youth centres
- Parks and recreational facilities
- Public transport facilities.

It is also typical for suburbs to have a core town centre which usually includes groups of these attractors and generators which are focus areas due to high pedestrian activity. The key pedestrian attractors and generators within the Inner West is presented in Figure 5.1. Public transport routes and stations and key areas of the Inner West are illustrated in Figure 4.7.



Source: Adapted from Google Maps

Figure 5.1 Pedestrian Attractors and Generators within Inner West LGA

6. RESEARCH AND REVIEW

6.1 Overview

The purpose of this chapter is to align this PAMP with other related plans, as required in TfNSW PAMP Guidelines. These include State Government plans, Regional plans, local planning documents and other relevant plans. A summary of relevant strategies is provided in this section.

6.2 State Government Plans

6.2.1 Eastern City District Plan


The Eastern City District Plan provides a 20-year plan to manage growth and achieve the 40 year vision, while enhancing Greater Sydney's liveability, productivity and sustainability into the future. This will see the Eastern City District become more innovative and globally competitive, carving out a greater portion of knowledge-intensive jobs from the Asia Pacific Region. The vision will improve the district's lifestyle and environmental assets.

The plan informs local strategic planning statements and local environmental plans, the assessment of planning proposals as well as community strategic plans and policies. It aims to achieve the objectives of the overarching Metropolis of Three Cities region plan, built on a vision of three cities where most residents live within 30 minutes of their jobs, education and health facilities, services

It provides direction on

- Infrastructure
- Liveability
- Productivity
- Sustainability

Inner West LGA lies within the Eastern City District.




6.3 Local Plans and Strategies

6.3.1 Community Strategic Plan

The Community Strategic Plan (CSP) identifies the community's vision for the future, long-term goals, strategies to get there and how to measure progress towards that vision. The Plan:

- Informs the strategic decision-making that will shape our future community and environment
- Protects and enhances the community's values and everything that makes Inner West unique
- Paves the way for the future by anticipating change and the impacts of that change on the community, economy and environment
- Achieves inclusivity, sustainability, accountability and innovation in service delivery



The development of Our Inner West 2036 involved thousands of people who participated through a series of engagement activities in 2016 and 2017.

This reflects the values of the Inner West community, underpins community expectations of how Council will interact with its residents and is the foundation for all decision-making, actions taken and management of resources.

6.3.2 Inner West Integrated Transport Plan (ITS)




Going Places: an Integrated Transport Strategy for Inner West, aims to address these transport challenges and provide strategies and actions that move towards a transport future focusing on active and sustainable modes of transport, and land-use planning approaches to support these modes of transport.

The Strategy proposes a vision for transport in the future focused on active and sustainable transport modes. It considers important values for the future network and develops a set of principles. The strategy establishes a hierarchy that prioritises people and sustainable modes of transport over private and polluting vehicles.

The ITS outlines a number of strategic pedestrian routes throughout the LGA, linking key centres and identifying potential active transport corridors. These routes have formed the skeleton of the pedestrian network across the LGA under this PAMP.

6.3.3 Inclusion Action Plan

The Inner West Council Inclusion Action Plan (for People with a Disability) outlines Council's commitment to respecting the rights and improving opportunities for people with a disability of all ages, to participate fully in community life.



The key objectives of the IAP 2017-21 are to:

- Assist Council to realise a vision of the Inner West for people experiencing or living with a disability
- Create an accessible and inclusive community that provides the same range of opportunities to all
- Promote and uphold the human rights of people with a disability
- Facilitate the exercise of those rights
- Promote the independence and social and economic inclusion of people with disability
- Assist Council to meet its obligations under the Disability Inclusion Act, 2014 (NSW) and thereby the UNCRPD • Articulate all the above into strategies and actions that will inform Council practice and be delivered through Council's Integrated Planning and Reporting Framework (IPRF)

6.4 Local Plans and Projects

6.4.1 Greenway – Cooks River to Iron Cove



The GreenWay is a 5.8km environmental and active travel corridor linking the Cooks River at Earlwood with the Parramatta River at Iron Cove. The GreenWay mostly follows the route of the Inner West Light Rail and Hawthorne Canal and features bike paths and foreshore walks, cultural and historical sites, cafes, bush care sites and a range of parks, playgrounds and sporting facilities.

The GreenWay Master Plan was adopted by Inner West Council in August 2018 and guides the delivery of landscaping and infrastructure within the corridor over the next 15 years. It establishes the GreenWay as an integrated ecological and active transport corridor that facilitates a range of recreation opportunities and incorporates local places for culture and art.


Sections of the greenway have been constructed, predominantly along Hawthorne Canal between Leichhardt and Haberfield. The section following the Inner West Light Rail corridor is yet to be developed. The connections to and from the Greenway to the surrounding pedestrian network is included in this PAMP.

6.4.2 Parramatta Road Urban Transformation Strategy

The Parramatta Road corridor has been earmarked as an urban renewal corridor that will be the focus for increased housing, economic activity and social infrastructure.

The corridor will be transformed over the next 30 years through implementation of the Parramatta Road Urban Transformation Strategy, developed by urban Growth NSW, specifically providing:

- A long-term vision for the transformation of the Parramatta Road Corridor
- An integrated plan that includes land use and development intensity, public transport and walking and cycling initiatives, green space and links, and key infrastructure focused in eight growth Precincts
- Guiding principles for land use, transport, development and public domain, which will apply to all land within the Corridor
- Precinct Plans and associated building envelopes for each Precinct, providing more detailed principles and targets for growth and development, and actions for implementation.



The Strategy outlines a number of precincts adjacent to Parramatta Road as part of the revitalisation of the corridor with the aim of creating place making opportunities. These precincts include:

- Taverners Hill Precinct – around Taverners Hill Light Rail Station, Leichhardt
- Leichhardt Precinct – around Norton Street, Leichhardt
- Camperdown Precinct – around Pyrmont Bridge Road, Gordon Street, Camperdown
- Part of Kings Bay Precinct

Priority pedestrian routes have also been identified in relation to each precinct and have been considered as part of this PAMP.

6.4.3 Iron Cove Creek / Dobroyd Canal Cycle and Pedestrian Path



Iron Cove Creek (also known as Dobroyd Canal) is an open stormwater channel running between Iron Cove and Croydon. Iron Cove Creek is part of the Sydney Green Grid and the Inner West Blue-Green Grid, a long-term network of green spaces connecting parks, transport services and locations where people live and work. North of Parramatta Road the canal travels through surrounding park areas and south of Parramatta Road the canal is surrounded by residential and industrial development with road bridges at Ramsay Street and Parramatta Rd at Five Dock.

The Iron Cove Creek corridor will ultimately become an ecological and active transport link connecting the Bay Run, Parramatta Road and the new Ashfield Aquatic Centre. State Government funding has been sought by Inner West Council under the Metropolitan GreenSpace Program for development of a feasibility and masterplan to provide a landscaping walking and cycling link and connections to the corridor are included in this PAMP.

6.4.4 Inner West @ 40

Reducing speed limits have been shown to improve pedestrian safety by reducing the likelihood of serious injury and fatality. A reduction from 50km/h (default urban speed) to 40km/h reduces the likelihood of a fatality by approximately 50%. As such the introduction of a lower speed limit on local streets has been identified as a key project to be undertaken in the Inner West to significantly improve pedestrian and cyclist safety.

Typically, reduced 40km/h speed limits have been applied to high pedestrian activity areas and school zones. Expanding the use of 40km/h speed limits will not only increase the safety of pedestrians and cyclists, but also to improve the local street environment by reducing noise pollution.

Existing 40km/h local areas in the Balmain peninsula has created a safer environment for vulnerable road users and better street environment.

This initiative will complement the improvements to pedestrian facilities and safety under this PAMP (and vice versa) and will be undertaken as a separate project.



6.5 Previous PAMPs

The previous Council's which now make up the Inner West have previously developed PAMPs for their respective LGA. This includes:

- Marrickville Council PAMP – 2009
- Leichardt PAMP - 2014
- Ashfield PAMP – 2016.

6.5.1 Marrickville PAMP (2009)

The Marrickville PAMP was prepared by Arup Planning in 2009. The study included the entire former Marrickville LGA, including the suburbs of Petersham, Lewisham, Stanmore, Newtown, Enmore, Dulwich Hill, Marrickville, St Peters, Sydenham and Tempe.

The PAMP identified several deficiencies with the pedestrian network and presented a recommended action plan with estimated works totalling \$870,000 over 10 years.

6.5.2 Leichhardt PAMP (2014)

The Leichhardt PAMP was prepared by Urban Arc in 2014. The study included the entire former Leichhardt LGA, including the suburbs of Leichhardt, Annandale, Lilyfield, Rozelle, Balmain, Balmain East, and Birchgrove.

The Leichhardt PAMP focussed on key commercial areas in Leichhardt, Rozelle and Balmain, and included an action Plan with estimated works totalling \$946,580.

6.5.3 Ashfield PAMP (2016)

The Ashfield PAMP was prepared by Calibre Consulting in 2016. The study included the entire former Ashfield LGA, including the suburbs of Ashfield, Haberfield, Summer Hill, and parts of Croydon, Croydon Park, Ashbury, and Hurlstone Park.

The Ashfield PAMP included the main commercial centres and villages and routes along main corridors and local street surrounding these centres. The developed PAMP action plan identified 199 recommendations with no estimation of total cost.

6.6 Planned Infrastructure and Major Developments

6.6.1 Sydney Metro

The expansion of the Sydney Metro network will see two new Metro lines running east west from Sydney CBD, including:

- Sydney Metro Southwest – Sydney CBD to Bankstown via Sydenham
- Sydney Metro West – Sydney CBD to Parramatta CBD

The metro will provide a number of new public transport options for Inner West residents, creating a further need to develop a pedestrian network capable of servicing the increased demand as users walk to and from stations.



Relevant stations with the Inner West LGA include:

Sydney Metro Southwest

- Sydenham
- Marrickville
- Dulwich Hill

Sydney Metro West

- White Bay
- Five Dock (Canada Bay LGA)

6.6.2 WestConnex



Current WestConnex construction within the Inner West includes Rozelle interchange, with project sites primarily located near Anzac Bridge and Iron Cove Bridge.

The Rozelle Interchange, which is expected for completion in 2023 connects the M4-M5 Link to the Anzac Bridge, Iron Cove Bridge, and the future Western Harbour Tunnel via the Iron Cove Link. The Rozelle Interchange is being built almost entirely underground, freeing up space for a new 10-hectare regional park on the surface and active transport links through the area.

7. PEDESTRIAN CRASH DATA REVIEW

7.1 Overview

The NSW Speed Zoning Guidelines recommend a minimum of three years of crash data for a statistical crash analysis. For this assessment, crash data recorded within the Inner West LGA between January 2015 and October 2019 was sourced from Council, representing a five-year period. The crash assessment focused on identifying any trends and crash clusters within the LGA for pedestrian involved crashes.

During the five-year period, there was a total of 2,813 crashes recorded. Pedestrian related crashes comprised of 11.5% of all crashes with a total of 324 crashes. When broken down by year, the number of pedestrian crashes varied between 52 to 84 crashes, as shown in Figure 7.1.




Figure 7.1 Total Number of Pedestrian Crashes for Inner West LGA

The overall trend over the 5-year period is a decreasing number of pedestrian crashes. Pedestrian crashes resulting in fatalities varied between one or two crashes per year.

Figure 7.2 shows all recorded pedestrian involved crashes within the Inner West LGA.




Figure 7.2 Inner West LGA Crash Map - Pedestrian Involved Crashes

7.2 Crash Summary by Suburb

Table 7.1 summarises the total number of crashes and the pedestrians involved per suburb.

Table 7.1: Pedestrian Crashes by Suburb

Suburb	Total Crashes	Pedestrian Crashes	Pedestrian Crashes in Suburb (%)	Total Pedestrians (%)
Annandale	108	9	8.3%	2.8%
Ashfield	332	48	14.5%	14.8%
Balmain	49	5	10.2%	1.5%
Balmain East	3	1	33.3%	0.3%
Birchgrove	6	1	16.7%	0.3%
Camperdown	32	1	3.1%	0.3%
Croydon	50	3	6.0%	0.9%
Croydon Park	19	1	5.3%	0.3%
Dulwich Hill	134	23	17.2%	7.1%
Enmore	72	8	11.1%	2.5%
Erskineville	5	0	0.0%	0.0%
Haberfield	154	11	7.1%	3.4%
Hurlstone Park	19	2	10.5%	0.6%
Leichhardt	208	22	10.6%	6.8%
Lewisham	79	3	3.8%	0.9%
Lilyfield	121	5	4.1%	1.5%
Marrickville	401	70	17.5%	21.6%
Mascot	10	1	10.0%	0.3%
Newtown	145	27	18.6%	8.3%
Petersham	189	16	8.5%	4.9%
Rozelle	198	19	9.6%	5.9%
St Peters	120	10	8.3%	3.1%
Stanmore	117	13	11.1%	4.0%
Summer Hill	69	8	11.6%	2.5%
Sydenham	52	6	11.5%	1.9%
Tempe	121	11	9.1%	3.4%
Total	2813	324	11.5%	100%

Ashfield, Dulwich Hill, Marrickville, and Newtown each have the largest composition of pedestrian involved crashes, over 14% of total crashes in the suburb. Ashfield and Marrickville both make up 36.4% of the total number of pedestrian crashes in the LGA.

7.3 Crashes by Street

The highest number of pedestrian related crashes were ranked by streets, as summarised in Table 7.2.

Table 7.2: Highest Number of Pedestrian Involved Crashes by Street

Rank	Street	Total Pedestrian Crashes	(%)
1	Princes Highway	21	6%
2	Enmore Road	16	5%
3	Parramatta Road	16	5%
4	Liverpool Road	16	5%
5	Marrickville Road	16	5%
6	Victoria Road	13	4%
7	Illawarra Road	12	4%
8	New Canterbury Road	12	4%
9	Darling Street	9	3%
10	Marion Street	9	3%
11	Frederick Street	7	2%
12	Addison Road	6	2%
13	Elizabeth Street	6	2%
14	Stanmore Road	6	2%
15	Unwins Bridge Road	6	2%
16-116	Other	153	47%
Total		324	100%

The top 15 roads comprise of over half of all crashes (53%) involving pedestrians. The highest number of pedestrian related crashes occurred on Princes Highway, Enmore Road, Great Western Highway, Hume Highway and Marrickville Road.

7.4 Crash Severity

Table 7.3 summarises the crash severity of all vehicle and pedestrian crashes.

Table 7.3: Crash Severity

Crash Type	Fatal	(%)	Injury	(%)	Non-casualty	(%)	Total
Vehicle	6	0.2%	1701	68.3%	782	31.4%	2489
Pedestrian	7	2.2%	317	97.8%	0	0.0%	324
Total	13	0.5%	2018	71.7%	782	27.8%	2813

All pedestrian involved crashes resulted in an injury or a fatality. Details on the severity of pedestrian crashes are as follows:

- 7 (2%) pedestrian crashes resulted in a fatality
- 317 (98%) pedestrian crashes resulted in an injury.

7.5 Crash Type

The pedestrian involved crashes were classified into TfNSW Road User Movement (RUM) codes which indicate the type of crash involved, as shown in Table 7.4.

The majority of pedestrian related crashes involve the RUM codes 0 and 2, contributing to 75% of all pedestrian related crashes. These correspond to pedestrians being hit crossing a road. This data could indicate a recurring issue of poor visibility, high vehicle speeds, low pedestrian awareness, poor pedestrian facilities, or identify common pedestrian behaviours.

Table 7.5 summarises the crash severity of all pedestrian related crash types.

Table 7.4: Pedestrian Involved Crash Types

Crash Type	RUM Code	Description	Number of Crashes	(%)
Pedestrians (on foot or in toy / pram)	0	Near side	140	43%
	1	Emerging	26	8%
	2	Far side	104	32%
	3	Playing, working, lying, standing on carriageway	22	7%
	5	Facing traffic	1	0%
	6	On footpath / median	8	2%
	7	Driveway	11	3%
	9	Other, pedestrian	2	1%
Vehicles from opposing direction	21	Right through	1	0%
	30	Rear end	3	1%
Manoeuvring	41	U-turn into fixed object / parked vehicle	1	0%
	46	Reversing into fixed object / parked vehicle	1	0%
	49	Other manoeuvring	2	1%
Off path, on straight	73	Right off carriageway into object / parked vehicle	1	0%
Off path, on curve or turning	87	Off carriageway left on left bend into object / parked vehicle	1	0%
Total			324	100%

Table 7.5: Crash Type Severity

RUM Code	Fatal	Injury	Non-casualty	Total
0	4	136	0	140
1	0	26	0	26
2	2	102	0	104
3	0	22	0	22
5	0	1	0	1
6	0	8	0	8
7	1	10	0	11
9	0	2	0	2
21	0	1	0	1
30	0	3	0	3
41	0	1	0	1
46	0	1	0	1
49	0	2	0	2
73	0	1	0	1
87	0	1	0	1
Total	7	317	0	324

RUM Codes 0, 2, and 7, resulted in at least one fatality, highlighting the severity of these crash types within the Inner West LGA. Over half (57%) of pedestrian fatalities were a result of a RUM Code 0 crash.

7.6 Crash Clusters

A review of the crash locations show that pedestrian crash clusters occurred within the Marrickville and Ashfield areas, notably along Marrickville Road, Illawarra Road, and Hume Highway / Liverpool Road. These locations correspond to major roads within the LGA, and the high number of pedestrian crashes are likely attributed to the high traffic and pedestrian volumes in these environments.

Table 7.6 show the intersections which have recurring number of pedestrian crashes (more than two).

The recurring RUM Code classifications at these intersections are 0 and 2. The data may indicate that these intersections have recurring issues and require further inspection.

7.7 Crash Data Analysis Summary

Based on the crash data, the highest number of pedestrian related crashes occur in the suburbs of Ashfield, Dulwich Hill, Marrickville, and Newtown, comprising of over half (51.8%) of the total pedestrian related crashes.

The highest number of pedestrian related crashes occurred on, Princes Highway, Enmore Road, Great Western Highway, Hume Highway, and Marrickville Road, comprising of over a quarter (26%) of the total pedestrian crashes. These are large major roads and do not necessarily indicate poor facility. A review of the crash locations show that crash clusters primarily occur within the Marrickville and Ashfield areas, notably along Marrickville Road, Illawarra Road, and Hume Highway / Liverpool Road.

Table 7.6: Intersection Crash Clusters – Pedestrian Involved Crashes

Intersection	RUM Codes	Crashes
Marrickville Road / Buckley Street	0, 2	5
Edgware Road / Alice Street / Llewellyn Street	0, 2	4
New Canterbury Road / Marrickville Road	0, 2	4
Darling Street / Waterloo Street	0	3
Dulwich Station / Wardell Road / Dudley Street	0, 2	3
Elizabeth Street / Wood Street	0	3
Enmore Road / Station Street	0, 1	3
Enmore Road outside No. 17 (Oporto / Post Office)	2, 7	3
Frederick Street / John Street	0, 2	3
Hume Highway / Liverpool Road / Holden Street	0	3
Hume Highway / Liverpool Road / Murrell Street	0, 2	3
Johnston Street / Booth Street	2, 7	3
King Street / Erskineville Road	0, 2	3
Liverpool Road / Knox Street	2	3
Marion Street / Flood Street	0, 2	3
Marrickville Road / Livingstone Road	0, 2	3
Marrickville Road / Victoria Road	0, 1	3
Parramatta Road / Cannon Street	2	3
Trafalgar Street / Audley Street	2, 9	3
Unwins Bridge Road / Gleeson Avenue	0	3
Total		64

The highest number of crashes at a particular intersection occurs at the following 3 intersections:

- Marrickville Road / Buckley Street
- Edgware Road / Alice Street / Llewellyn Street
- New Canterbury Road / Marrickville Road.

The data indicates that these intersections are likely to have safety issues and requires inspection.

The primary crash type (75%) involved the RUM Code 0 and 2 of all pedestrian related crashes, which corresponds with pedestrians being hit while crossing the road. RUM Codes 0, 2, and 7 resulted in at least 1 pedestrian fatality, with over half (57%) associated with a RUM Code 0 crash. This may indicate a recurring issue of poor visibility, high vehicle speeds, low pedestrian awareness, poor pedestrian facilities, or identify common pedestrian behaviours, highlighting the significance of providing further traffic measures or improved pedestrian facilities within the Inner West LGA.

8. DEVELOPMENT OF PRIORITISED PEDESTRIAN NETWORK

8.1 Overview

The primary purpose of the PAMP is to identify the highest priority pedestrian routes, to then define what is needed to upgrade or augment infrastructure along these routes, and to prioritise the proposed new infrastructure.

On this basis, PAMP routes and proposed new infrastructure along these defined routes have been identified in this chapter. This includes 'new links', 'new crossing points' and 'link / crossing upgrades / improvements'.

8.2 Route Selection

The defined PAMP routes provide a network of primary pedestrian links within the Inner West. Connecting routes to form networks is important to encourage their wider use for trip origins and destinations. That is, these connected networks have cumulative benefits for the community. These PAMP routes have also been nominated because they connect key attractors and generators. The PAMP routes were selected based on the following considerations:

- Routes identified in previous PAMPs and strategic documentation
- Proximity to key centres and pedestrian attractors / generators, such as village centres and railway stations
- Links through suburbs and between key centres and major routes
- Initial community engagement information and feedback (i.e. continuous, safe and connected or highly demanded routes)
- Road hierarchy
- Location of pedestrian crashes.

The network of the PAMP priority routes for Inner West was developed in consultation with Council and is presented in Figure 6.1 and **Appendix B**.




Figure 8.1 Inner West PAMP Routes

8.3 Route Hierarchy

8.3.1 Route Segments

To assist with the process of prioritising any new or missing links and to determine which upgrades need to occur first, each PAMP route was split into smaller sections for scoring purposes. These route segments were created based on:

- Roads: when possible, a segment is entirely contained in a single road.
- Length of segment: to evenly split the length along the PAMP route, or to split the route at logical locations.

These PAMP route segments were created with the objective to develop an equitable basis for scoring to help establish an even distribution of scoring.

8.3.2 Scoring Criteria

The PAMP routes were assigned a hierarchy: primary, secondary, or tertiary. A higher order level was given to routes servicing multiple high trip attractors and generators such as town centres and key pedestrian links such as train stations, public transport, schools and parks. A higher order level was also assigned to links that were identified within previous strategic documents and key roads. Emphasis was also given to areas of frequent crash history.

The scoring criteria for prioritising the PAMP routes is summarised in Table 8.1.

Table 8.1: PAMP Route Criteria and Scoring

Category	Criteria	Performance Conditions	Score
Land Use	Number of Attractors / generators within 200m	More than 30	12
		More than 20	7
		More than 10	3
		More than 0	1
	Land Use Type	Key Centres and Town Centres (shopping, commercial areas)	15
		Railway Stations (incl light rail stations)	15
		Bus Stops	10
		Education facilities (primary and high schools)	15
Road Hierarchy	Road Classification	Recreation (parks, pools, sports facilities)	10
		State Road	10
		Regional Road	5
Safety	Identified pedestrian crashes	Local Road	0
		More than 5	12
		More than 1	6
Strategic Route	Defined strategic pedestrian routes within the ITS	No crashes	0
		Strategic Route	10
		Non-Strategic Route	0

8.3.3 Segment Ranking / Priority

Based on the scoring system presented in Table 8.1, the following criteria in Table 8.2 was applied to determine the rank of each route segment. A map of resulting route segment rankings is shown in Figure 8.2 and **Appendix C**.

Table 8.2: Segment Ranking

Priority	Scoring Criteria
Primary	42 - 101
Secondary	15 - 41
Tertiary	0 -14




Figure 8.2: Route Segment Rankings

9. PEDESTRIAN ROUTE AUDITS

9.1 Methodology

Existing facility audits were undertaken during the period between 1 December 2020 to 15 March 2021, spanning over three months. These audits were undertaken to:


- Identify gaps, missing links and footpaths in the existing network
- Identify issues, accessibility or crossing deficiencies and maintenance needs
- Investigate locations areas identified by community feedback high pedestrian or crash history
- Identify locations for opportunities for safety improvements or further investigation.




Audits were undertaken on all the identified PAMP routes, in which issues or deficiencies were identified based on Criteria 5C outlined in *Austrroads Guide to Road Design Part 6A: Pedestrian and Cyclist Paths (AGRD Part 6A)* which are:




- **Connectivity:** is the route connected to the rest of the network?
- **Comfort:** is the route well maintained, smooth and unobstructed? Is the route attractive and free from excessive traffic noise?
- **Convenience:** are there adequate crossing opportunities? Are key destinations within walking distance of one another?
- **Conviviality:** how pleasant is the walking environment?
- **Conspicuousness:** are the walking route clearly lit and easy to follow?

The audit considered footpaths, kerb ramps, crossing points, and other pedestrian facilities, however, was limited to 'high level' issues that would fundamentally impact the use of the paths or access to the paths. Some examples of issues found during the audits and potential treatments are provided in Table 9.1.

Table 9.1: Audit Issues Examples

Description	Picture
<p>Missing Footpath:</p> <ul style="list-style-type: none"> ▪ Pathways which end abruptly ▪ Clear pedestrian desire line ▪ Missing paved footpath at key locations. <p>Treatment</p> <ul style="list-style-type: none"> ▪ Install new footpath <p>Example: Missing paved footpath along strong pedestrian desire line</p>	

Description	Picture
<p>Narrow Footpaths:</p> <ul style="list-style-type: none"> Existing footpaths which appear to provide insufficient width for pedestrians of all abilities. <p>Treatment</p> <ul style="list-style-type: none"> Widen footpath Investigate and install Shared Zone Realign kerb and provide footpath <p>Example: Narrow footpath</p>	
<p>Crossing Deficiencies:</p> <ul style="list-style-type: none"> Insufficient or unsafe crossing points Missing pedestrian crossing facilities, including kerb ramps or refuge island Poorly orientated / aligned kerb ramps and crossing infrastructure <p>Treatment</p> <ul style="list-style-type: none"> Reconstruct kerb ramps to correct alignment / orientation Reconstruct refuge island Reduce crossing distance by installing kerb extension / refuge island <p>Example: Poorly aligned kerb ramp – leads pedestrians onto roadway</p>	
<p>Obstructions:</p> <ul style="list-style-type: none"> Any obstructions preventing or causing difficulty in pedestrian access, connectivity, or crossing, such as: <ul style="list-style-type: none"> Power poles Trees Electricity boxes Maintenance issues which could hinder or narrow pedestrian pathways such as overhanging vegetation. <p>Treatment</p> <ul style="list-style-type: none"> Relocate or remove obstruction Refer to ongoing Council maintenance team (vegetation issues) <p>Example: Power pole narrows available footpath</p>	

Description	Picture
<p>Access:</p> <ul style="list-style-type: none"> Inaccessibility or difficulty in traversing through locations for pedestrians of all abilities, such as footpaths with only stairs and no ramps <p>Treatment</p> <ul style="list-style-type: none"> Install accessible ramp Provide alternative path Reconstruct footpath <p>Example: Stair access only</p>	
<p>Connectivity:</p> <p>Areas where the pathway does not provide continued ease of movement from one point to another.</p> <p>Treatment</p> <ul style="list-style-type: none"> Re-align kerb and provide footpath Provide alternative route <p>Example: footpath disconnected due to sudden change in level (wall)</p>	
<p>Infrastructure Condition:</p> <ul style="list-style-type: none"> Damaged or poor construction of infrastructure such as footpaths/surfaces and accessibility indicators Pedestrian related signage which are extremely faded or obstructed by graffiti or damage. <p>Treatment</p> <ul style="list-style-type: none"> Re-construct footpath pavement or concrete panel Repair utility pit <p>Example: Uneven footpath surface</p>	

The identified deficiencies are shown in Figure 9.1. Detailed maps are provided in **Appendix D**.



Figure 9.1: Pedestrian Route Deficiencies

9.3 Audit Limitations

During the auditing process, some areas were not able to be audited due to construction activities or strategic routes identified which are not yet developed (such as within the light rail corridor). While these areas were not audited, it is extremely likely that these routes would be developed to modern standards and guidelines which would provide suitable pathways and should be reviewed in future following the end of construction activities.

Table 9.3 outlines the locations which were not audited due to these limitations.

Table 9.3: Locations Not Audited

Suburb	Location	Limitation
Annandale	Bignell Lane between Mallet Street and Gordon Street	Undeveloped strategic route
Annandale	White Creek Park	Undeveloped strategic route
Annandale	Links across City West Link to Gordon Street and Lilyfield Road	Undeveloped strategic route
Annandale	Railway Parade between Bayview Crescent and The Crescent	Construction – Rozelle Interchange works
Annandale	The Crescent / Johnston Street Intersection	Construction – Rozelle Interchange works
Ashfield	Alt Street near Charlotte Street	Construction
Ashfield	Parramatta Road near Alt Street	Construction - WestConnex
Camperdown	Parramatta Road near Mallet Street	Construction - WestConnex
Dulwich Hill	Hercules Street / Consett Street Intersection	Construction
Dulwich Hill	Hercules Street between Consett Street and bridge over Light Rail	Construction
Dulwich Hill	Old Canterbury Road near Hampstead Road	Construction
Dulwich Hill	Old Canterbury Road near Constitution Road	Construction
Dulwich Hill	Weston Street near Channel Street	Construction
Haberfield	Parramatta Road near Wattle Street	Construction - WestConnex
Leichardt	Flood Street near Lords Street	Construction
Leichardt	Derbyshire Road near Balmain Road	Construction
Lewisham	McGill Street	Construction
Marrickville	Smidmore Street between Edinburgh Road and Edgeware Road	Construction – Marrickville Metro Shopping Centre
Marrickville	Murray Street between Smidmore Street and Edinburgh Road	Construction – Marrickville Metro Shopping Centre
Marrickville	Edinburgh Road / Murray Street Intersection	Construction – Sydney Metro
Marrickville	Sydney Steel Road	Construction – Sydney Metro
Petersham	Petersham Station	Construction – Station upgrades
Petersham	Trafalgar Street between Audley Street and Shaw Street	Construction – Station upgrades
Rozelle	Gordon Street / Butt Street Intersection	Construction - WestConnex
Rozelle	Byrnes Street / Bay Run Intersection near King George Park	Construction

Suburb	Location	Limitation
Rozelle	Bay Run / Byrnes Street near Victoria Road	Construction - WestConnex
Rozelle	Victoria Road between Moodie Street to Iron Cove Bridge	Construction - WestConnex
Rozelle	Lilyfield Road / Victoria Road	Construction - WestConnex
Rozelle	Lilyfield Road southern side opposite Easton Park	Construction - WestConnex
Stanmore	Gordon Crescent at Douglas Street	Cycleway construction
Summer Hill	Carlton Crescent near Darrell Jackson Gardens	Construction
Summer Hill	Old Canterbury Road near James Street	Construction
Sydenham	Railway Parade between Gleeson Avenue and Sydenham Road	Construction – Sydney Metro

10. RECOMMENDED WORKS PROGRAM

10.1 Works Prioritisation

A priority level has been assigned to each identified issue and recommended action, taking into consideration its contribution to pedestrian safety, ease of accessibility, the route hierarchy and the amenity of the surrounding environment.

10.1.1 Prioritisation criteria

The treatment priority criteria were primarily based on the route segment rank and issue category as summarised below

- **Segment Rank – Primary, Secondary or Tertiary**
 - Ranked route segments indicates the importance of the sections of route based on expected use and surrounding attractors and generators.
 - Primary ranked segments would be mostly representative of key pedestrian areas such as town / village centres, near public transport hubs / stations and strategic corridors (outlined in Section 8.3)
 - Issues within primary ranked route segments are given a higher priority
- **Issue Category**
 - Prioritises treatment based on the type of issue category
 - Issues related to missing paths, crossing deficiencies, access and safety issues are prioritised higher to better improve the pedestrian network or correct current deficiencies presenting safety risks to pedestrians
 - Issues related to infrastructure condition and obstruction are prioritised lower as these are mainly related to existing pedestrian facilities

10.1.2 Scoring system

A scoring system was developed to assign a priority to each issue identified, outlined below in Table 10.1.

Table 10.1: Treatment Priority Scoring Criteria

Criteria	Category	Conditions	Score
1	Route Segment Rank	Primary	10
		Secondary	5
		Tertiary	0
2	Issue Category	Safety Issue	10
		Crossing deficiency	10
		Missing footpath	10
		Access	10
		Narrow Footpath	5
		Infrastructure condition	5
		Obstruction	0
		Connectivity	0
Priority Assignment			
High		15 to 20	
Medium		11 to 15	
Low		0 to 10	

Based on the above criteria and scoring system, the recommended works program has been prioritised with high priority works to be undertaken first, followed by medium and low.

Figure 10.1 presents the assigned priority for each of the issues and associated action within the study area, also provided in **Appendix E**.



Figure 10.1: Priority Issues and Works

10.2 Implementation Costs

A detailed list of recommended works and costings has been sorted by priority and provided in Appendix D.

The estimated cost required to implement these treatments is summarised in Table 10.2.

Table 10.2: Project Costs

Item No.	Type	Quantity	Unit Cost	Total Cost
1	adjust flood light orientation	3	\$1,000	\$3,000
2	consult with City of Canada Bay	1	\$-	\$0
3	consult with City of Canterbury-Bankstown	10	\$-	\$0
4	consult with City of Sydney	5	\$-	\$0
5	consult with City of Sydney and TfNSW	1	\$-	\$0
6	consult with Concordia Club (landowner)	1	\$-	\$0
7	consult with Marrickville Metro	1	\$-	\$0
8	consult with TfNSW	17	\$-	\$0
9	further investigation required - bins	1	\$-	\$0
10	further investigation required - crossfall	5	\$-	\$0
11	further investigation required - crossing point	1	\$5,000	\$5,000
12	further investigation required - footpath	3	\$5,000	\$15,000
13	further investigation required - kerb ramp	1	\$5,000	\$5,000
14	further investigation required - path widening	1	\$-	\$0
15	further investigation required - pedestrian crossing	24	\$10,000	\$240,000
16	further investigation required - pedestrian crossing, consult with City of Canterbury-Bankstown	1	\$-	\$0
17	further investigation required - pedestrian link (major infrastructure)	1	\$50,000	\$50,000
18	further investigation required - pedestrian refuge or crossing (signal)	3	\$15,000	\$45,000
19	further investigation required - raised pedestrian crossing	4	\$15,000	\$60,000
20	further investigation required - refuge	2	\$10,000	\$20,000
21	further investigation required - safety assessment	1	\$5,000	\$5,000
22	further investigation required - signals	2	\$20,000	\$40,000
23	further investigation required - stairs	1	\$-	\$0
24	further investigation required - traffic calming	2	\$-	\$0
25	install accessible ramp	19	\$10,000	\$190,000
26	install contrasting threshold	2	\$5,000	\$10,000
27	install keep clear pavement marking	1	\$2,500	\$2,500
28	install kerb blisters/ build outs	5	\$10,000	\$50,000
29	install kerb extension	11	\$10,000	\$110,000
30	install kerb extension - pair	22	\$20,000	\$440,000

Item No.	Type	Quantity	Unit Cost	Total Cost
31	install kerb extension / refuge island	7	\$10,000	\$70,000
32	install kerb extensions	1	\$10,000	\$10,000
33	install landscaping barriers	1	\$750	\$750
34	install new corner refuge island	2	\$10,000	\$20,000
35	install new footpath	4292m	\$200	\$858,400
36	install new kerb ramp	845	\$2,500	\$2,112,500
37	install new kerb ramp - pair	859	\$5,000	\$4,295,000
38	install new kerb ramp - pair, and Tactile Ground Surface Indicators	1	\$6,300	\$6,300
39	install new kerb ramp - pair, new refuge island	6	\$7,000	\$42,000
40	install new kerb ramp and reconstruct refuge island	1	\$5,000	\$5,000
41	install new lighting	12	\$10,000	\$120,000
42	install new pavement surface	3	\$300	\$900
43	install new pedestrian refuge	1	\$15,000	\$15,000
44	install new pit cover	1	\$250	\$250
45	install new refuge island	26	\$15,000	\$390,000
46	install new shared path signage	2	\$350	\$700
47	install new shared zone signage and delineation	1	\$500	\$500
48	install new signpost	1	\$250	\$250
49	install new speed cushions	1	\$3,000	\$3,000
50	install new Tactile Ground Surface Indicators	207	\$650	\$134,550
51	install new Tactile Ground Surface Indicators - pair	127	\$1,300	\$165,100
52	install new utility cover	4	\$2,000	\$8,000
53	install new wheel stops	28	\$1,500	\$42,000
54	install no stopping sign and signpost	3	\$300	\$900
55	install pavement warning message	9	\$150	\$1,350
56	install pedestrian crossing signage	1	\$200	\$200
57	install pedestrian fencing	1	\$750	\$750
58	install raised continuous footpath and tgsi	1	\$30,000	\$30,000
59	install raised continuous footpath treatment	91	\$30,000	\$2,730,000
60	install raised pedestrian crossing	51	\$50,000	\$2,550,000
61	install shared path signage	1	\$300	\$300
62	install splitter/refuge island	2	\$10,000	\$20,000
63	install warning line marking and signage	1	\$1,500	\$1,500
64	investigate High Pedestrian Activity Area implementation	18	\$20,000	\$360,000
65	investigate shared zone implementation	20	\$15,000	\$300,000
66	modify splitter island	1	\$10,000	\$10,000
67	no action	183	\$-	\$0

Item No.	Type	Quantity	Unit Cost	Total Cost
68	notify business owner	3	\$-	\$0
69	notify business/property owner	637	\$-	\$0
70	notify property owner	4	\$-	\$0
71	provide warning signage	1	\$500	\$500
72	re-align crossing and refuge island	1	\$6,000	\$6,000
73	re-align kerb and footpath	2	\$7,500	\$15,000
74	re-construct fence	1	\$150	\$150
75	re-construct footpath pavement	442m	\$200	\$88,400
76	reconstruct kerb blister	1	\$1,500	\$1,500
77	re-construct pedestrian fencing	1	\$5,000	\$5,000
78	re-construct refuge island	40	\$15,000	\$600,000
79	refer to maintenance	394	\$-	\$0
80	relocate bollard	2	\$2,500	\$5,000
81	relocate bus stop pole	1	\$400	\$400
82	relocate crossing - signals	1	\$20,000	\$20,000
83	relocate light post	5	\$10,000	\$50,000
84	relocate no stopping sign	1	\$1,500	\$1,500
85	relocate no stopping signage	1	\$300	\$300
86	relocate or remove bench	2	\$400	\$800
87	relocate or remove bike locker	1	\$400	\$400
88	relocate or remove bike rack	1	\$250	\$250
89	relocate or remove bollard	5	\$2,500	\$12,500
90	relocate or remove bus shelter	5	\$5,000	\$25,000
91	relocate or remove bus shelter and signposts	1	\$5,500	\$5,500
92	relocate signpost	38	\$300	\$11,400
93	repaint bollards	1	\$150	\$150
94	repair barrier	1	\$750	\$750
95	repair bollard	3	\$2,500	\$7,500
96	repair linemarking	1	\$500	\$500
97	repair pavement marking	1	\$200	\$200
98	repair pavement panel	82	\$200	\$16,400
99	repair pit cover	1	\$2,000	\$2,000
100	requires further investigation - long crossing	1	\$5,000	\$5,000
101	review and implement shared zone	2	\$40,000	\$80,000
102	review and relocate double pole signpost	13	\$500	\$6,500
103	review and replace shared path signage	1	\$500	\$500
104	review footpath trading	1	\$-	\$0
105	review when land use changes	1	\$-	\$0

Item No.	Type	Quantity	Unit Cost	Total Cost
106	top up tree pit	1	\$150	\$150
107	Undertake masterplan study	1	\$200,000	\$200,000
108	widen footpath	6427m	\$200	\$1,285,400
109	widen path and relocate fencing	51m	\$400	\$20,400
Estimated Project Sum				\$18,070,750
Contingency		1	20% Of Project Estimated Sum	\$3,614,150
Estimated Project Sum with Contingency				\$21,684,900

Project costings have been sorted by priority and summarised in Table 10.3. It is noted these costs do not include the development and implementation of traffic management plans or the contingency percentage.

Table 10.3: Cost by Priority

Priority	Quantity	Cost
High	847	\$7,922,300
Medium	1520	\$6,918,050
Low	2083	\$3,230,400
Total	4450	\$18,070,750

Project costings have been sorted by road type and summarised in Table 10.4.

Table 10.4: Cost by Road Type

Road Classification	Quantity	Cost
State	504	\$1,307,200
Regional	632	\$2,177,000
Local	3314	\$14,586,550
Total	4450	\$18,070,750

10.3 Other Costs

10.3.1 Other Pedestrian Routes

While a detailed audit of the PAMP routes was undertaken, a number of issues may exist along other streets within the PAMP study area which were not designated as a priority PAMP route. As such, the cost of addressing these pedestrian and access issues is not included as part of the above cost estimate.

10.3.2 Ongoing Maintenance

Actions deferred to ongoing maintenance across the LGA primarily include actions related to vegetation obstructions (such as overhanging vegetation) and drainage (where drainage is identified as an issue) have not been included as part of the PAMP and is assumed to be under the responsibility of the relevant department and budget within Council.

In addition, costs presented as part of this PAMP include the installation or implementation of treatments and do not include ongoing maintenance costs.

10.3.3 Major Infrastructure and Projects

A number of issues were identified relating to State owned infrastructure or under a major project. This included:

- Accessibility issues at train stations, wharves, and pedestrian bridges over a State road
- Proposed or strategic routes through major infrastructure sites (such as Rozelle interchange)

These items have been assumed to be under the scope of each project or responsibility of transport for NSW and have been excluded from the action associated costs.

10.4 Implementation of Treatments and Further Investigations

The PAMP study has identified the implementation of new shared zones, pedestrian crossings, continuous footpath treatments or High Pedestrian Activity Areas (HPAA) to provide a pedestrian facility at certain locations. The following actions are required under the implementation of each treatment:

Shared Zones

- Undertaking a shared zone warrant assessment following TfNSW guidelines (including traffic surveys)
- Design of shared zone
- Approvals and installation of relevant signage and line marking (and other infrastructure)

Pedestrian Crossings

- Undertaking a pedestrian crossing warrant assessment and investigation following TfNSW guidelines (including traffic and pedestrian surveys) at new crossing locations
- Design of pedestrian crossing and review of local drainage arrangements (where a raised pedestrian crossing is being installed)
- Approvals and installation of relevant signage, line marking and physical infrastructure

Continuous Footpath Treatments

- Undertaking an assessment and investigation following TfNSW guidelines (including traffic volume surveys)
- Design of continuous footpath treatment and review of local drainage arrangements

High Pedestrian Activity Areas (HPAA)

- Undertaking a HPAA assessment following TfNSW guidelines (including traffic surveys)
- Design of HPAA scheme (including signage, line marking and traffic calming)
- Approvals and installation of infrastructure

It should be noted that while a typical expected cost for each of these treatments have been included in the works program, the actual costs associated with these procedures can vary greatly and will be subject to detailed investigation and design.

11. IMPLEMENTATION AND FUNDING

11.1 Potential funding sources

11.1.1 Transport for NSW

TfNSW will generally fund works on state-controlled roads and can be used as a potential source of funding to implement the PAMP action plan.

Actions identified within or across Regional Road and Local Road corridors may be included as part of funding applications to TfNSW. A summary of costs by road type is presented in Table 10.4.

11.1.2 Development Contribution Plans

The Environmental Planning and Assessment Act 1979 makes allowance for a consent authority to extract money for the provision of public amenity or public services. Should a development increase pedestrian activity or demand then it would be reasonable for Council to seek contribution toward improvements to pedestrian facilities in the area or adjacent to these developments, to provide a link between the development and local pedestrian network or facilities.

Considering the amount of development occurring within the Inner West LGA, obtaining funding from S.7.11 S.7.12 contributions would be a feasible funding source. As such, Council may consider including some of the works as part of their development contribution plans.

11.2 Monitoring and Evaluation

The PAMP is intended to be implemented over the 10-year horizon of this Plan. Funding and budget for recommendations should be identified and set in the budget, and higher priority works be given precedent.

It is typical to have a monitoring program for the PAMP. This would involve:

- Recording of all proposed pedestrian works in a database
- Analysis of crash statistics
- Collection of pedestrian count information
- Periodic updating of the PAMP every five years.

12. CONCLUSIONS AND RECOMMENDATIONS

12.1 Conclusions

The Inner West PAMP presents the investigation and development of an action plan to improve pedestrian connectivity and safety to encourage more walking across the Inner West LGA.

Issues affecting pedestrians were discussed with Inner West Council in addition to undertaking an initial engagement program to gain an insight of issues and pedestrian concerns faced by Inner West residents and visitors.

Major pedestrian infrastructure deficiencies were identified along key routes through the LGA, and included the lack of quality crossing provisions and connectivity between parts of the pedestrian network. Other issues included obstructions from street furniture, street posts and vegetation. Opportunities to improve pedestrian safety were also identified, such as implementing raised pedestrian crossings and potential reduction in speed limits in High Pedestrian Activity Areas.

Priority PAMP routes were defined, and a comprehensive field audit was undertaken to catalogue issues with footpaths, kerb ramps, crossing points, accessibility issues and pedestrian safety. A number of recommended works are proposed with indicative costs given for each upgrade required. These recommended actions have been prioritised to inform the future works program to be undertaken by Council.

The total cost of the implementation of the identified improvements is approximately **\$18,070,750** with an additional **\$3,614,150** as a 20% project contingency. Most costs arise from the reconstruction of kerb ramps, improvements to pedestrian safety, installation of new footpaths, and widening of existing footpaths.

If fully implemented, the proposed works will support pedestrian safety and amenity across the inner West and encourage residents and employees to undertake walking trips for shopping, work and leisure purposes. It is recommended that these works be implemented as funding becomes available from Council and Transport for NSW. Consideration could also be given to include some items in Council's Development Contribution Plans.

Engagement outcomes report Improve pedestrian safety and accessibility



Contents

Summary	3
Background	5
Stage 1 – community insights	5
Stage 2 – Public Exhibition	16

Summary

As part of the development of the new Inner West Pedestrian Access and Mobility Plan (PAMP), the community could provide feedback during a two stage engagement program. Stage one gathered insights of existing pedestrian issues across the Inner West government area. These insights were combined with other information to prepare a draft report and recommendations. Stage two was public exhibition which sought feedback on more than 4000 recommendations in the draft PAMP.

The first stage of engagement ran for 29 days from 23 November 2020 – 22 December 2020. The community could provide feedback online via an interactive map on Your Say Inner West, COVID-safe workshops, or by direct email. Participants could drop a pin/s on a location and provide details of pedestrian safety issues.

Overall, 339 people participated in stage one. There were over 800 pins added to the interactive map covering all the available categories. The majority of responses (98%) were provided by Inner West residents with more than half (52%) provided by users in the 35-49 year age group. The greatest number of responses were recorded in the suburbs of Marrickville, Newtown, Ashfield, and Annandale.

A total of 14 email submissions from individual senders were also received, providing comments on some specific locations within the LGA (namely Newtown, Enmore, Rozelle, Balmain, and Croydon) and comments / suggestions across the LGA, such as footpath improvements and reduction of speed limits in local areas.

Covid-safe interpreted conversations were held with three community groups via a local NGO with support from interpreters. This included a Vietnamese mothers group, a Vietnamese seniors group and an Arabic seniors groups. A total of 30 people participated and provided feedback in these sessions. Other community organisations were approached but did not respond to the offer for in-language consultation.

The most common themes raised were related to safety concerns (62%) and accessibility concerns (15%). Notably, the top three reported issues were related to vehicle/driver behaviours, footpath connectivity and obstructions, and poor quality or unsafe crossing locations which comprised approximately 70% of all submissions.

Page 3 of 26

Stage two (public exhibition) sought feedback on the draft Pedestrian Access and Mobility Plan which included over 4000 recommendations. Public exhibition ran from 26 May-23 June 2021. High and medium priority recommendations were displayed on an interactive map and feedback could be provided via a feedback form or direct channels. Tailored summaries were provided to groups involved in stage one. The summary included content specific to the issues they had raised and how they related to the final recommendations.

Overall, 31 different people provided responses to the public exhibition. The project page was viewed by 319 people with 25 providing direct feedback. Overall, there were over 170 individual downloads across 4 documents, 23 video views and 104 map views. A total of 6 email responses were also received.

Key themes that arose from public exhibition included:

- The overall direction of the PAMP and action plan was lacking
- Reduction of traffic volumes and speeds will greatly improve pedestrian amenity and safety (including reducing speed limits to 40km/h or 30km/h)
- Bicycle conflicts with pedestrians was not widely explored or investigated
- Further enforcement of illegal parking, bicycles on footpaths and kerbside trading is needed to improve pedestrian environment
- More crossings and shares zones are required in the Inner West
- Mixed opinions on the implementation of Shared Zones as a pedestrian treatment
- Improved maintenance of crossings and upgrades to raised crossings required
- General design of kerb ramps to consider wheelchair users and retaining heritage kerbing where possible
- Queries whether past customer complaints have been included and how future complaints will work with the plan
- Groups of treatments by location or area should be upgraded and prioritised instead of by treatment priority

A number of items and themes relating to specific locations, areas and issues were also raised.

Background

A PAMP guides how Councils enhance pedestrian networks, allowing everyone to enjoy safe, convenient, and independent mobility. The works identified as part of the PAMP also attempts to encourage the shift from car dependency to walking, where possible. Our commitment to this is explained in the Integrated Transport Strategy (2017).

As part of the investigation process of the PAMP, initial community engagement was conducted to gather local insight and identify issues relevant to people within the Inner West. The engagement outcomes was then be combined with site audits and field studies to create a picture of the current Inner West pedestrian network and experience.

Feedback gathered was combined with expert knowledge to identify priority areas for upgrades in the next five to ten years. Improvement or upgrade works may include:

- Providing kerb ramps (such as for prams, wheelchairs, walking frames, etc)
- Safer crossings points (such as pedestrian crossings and refuge islands
- Footpath connectivity and continuity between popular destinations

Stage 1 – Community Insights

Engagement Methods

The initial engagement was conducted using the following methods:

- Online via an interactive map on Your Say Inner West
- Online via individual email responses
- COVID-safe conversations via interpreters with Vietnamese community and Arabic seniors.

The online interactive map allowed users to place a pin under a number of categories to provide information of locations and detailed comments.

Prompts with each pin included:

- Comment
- Is there anything else you'd like to share about this location? Be as specific as possible.
- Age
- What suburb do you live in?
- Why do you use paths?*
- If other, please specify here.

* It is noted that users were able to input multiple reasons as choices for this question.

Categories of pins included:

- **Safety concern** – locations where pedestrian safety is a concern or where pedestrians are at risk
- **Accessibility concern** – locations where pedestrian access is a concern, particularly wheelchair or mobility aid users
- **Works well** – locations or facilities that have had a positive impact on pedestrian access or safety
- **Path required** – locations or sections of road where a footpath should be provided
- **Ideas** – opportunity to provide resident input on potential upgrades or modifications to benefit pedestrian access
- **Amenities** – opportunity to provide resident input on potential upgrades or modifications to benefit pedestrian amenity (such as trees and providing shade etc.)

The engagement period was conducted between 23 November and 22 December 2020, spanning a total of 29 days.

Promotion

The opportunity to participate was promoted using the following methods:

- Council's corporate website
- Your Say Inner West home page
- Vinyl footpath stickers located across town centres in the Inner West – providing a QR code to Your Say Inner West and map
- Email contact with community groups
- Direct email to local democracy groups
- Council's social media
- Direct email to Your Say Inner West subscribers and Multicultural network
- Distribution via Local Democracy Group conveners

Engagement Outcomes

Who did we hear from?


Overall 339 people participated in the engagement. A breakdown of these number of participants are as follows:

- Online engagement – 295 people
- Individual emails – 14 people
- Vietnamese Mothers Group – 8 people
- Arabic Seniors Group – 7 people
- Vietnamese Seniors Group – 15 people

Where do they live?


A very large majority of responders reside within Inner West LGA (approx. 98%), of which most resided in the suburbs of Annandale, Leichardt, Marrickville, and Stanmore. The remaining 2% of responders reside outside of the Inner West LGA. A detailed breakdown of the received data for responders by residential suburb is shown graph below.

Responders by Residential Suburb



What age groups did we hear from?

A majority of responders are within the 25-34 and 35-49 year age groups (16% and 52% respectively). A detailed breakdown of the received data for responders by age group is shown in the graph below.




Why do they use paths?

Responses indicated that walking is well used for a variety of purposes. The number of all uses were relatively similar with walking to/from school being the least. The data shows that people commuting to/from work and leisure, health and fitness activities are examples of common reasons for using paths within the Inner West (both comprising of 13%). The most common use for paths are to/from shops which comprised of 19% of all uses.

A detailed breakdown of the received data for responses to the query “why do you use paths?” is shown in the graph below.

Why do you use paths?



What did they say?

Online Engagement – Your Say Inner West Interactive map


The interactive map received 836 pins marking locations with pedestrian issues. These pins were provided by 295 different responders.

Response by Category

Most responses/pins on the map identified 'pedestrian safety' issues (approx. 62%) followed by 'access concerns' (approx. 15%). Notably, approximately 70% of all responses were associated with common themes related to vehicle behaviours, footpath connectivity and obstructions, and crossing deficiencies.

A detailed breakdown of the received data for responses by category is shown in the graph below.


Responses by Category



Response by Suburb

Most responses/pins on the map were provided in the suburbs of Marrickville (14%), Newtown (11%), Ashfield (10%), Annandale (9%) and Leichardt (8%).

A detailed breakdown of the received data for responses by category is shown in graph below.



Comments received from organisations/groups/stakeholders

Council's Multicultural Officer offered COVID-safe in-language sessions via community leaders. One organisation responded and times were arranged with three community groups.

Commonly raised concerns from responders included:

- Poor pedestrian facilities on Petersham Road (29%)
- Cars parking on footpaths (10%)
- Accessibility difficulties with uneven footpaths due to tree roots (10%).

Other comments received during these conversations include:

- Vehicle traffic and kerbside parking creates hazards for pedestrians attempting to crossroads or use footpaths, with vehicles parked on the footpath in some areas in Marrickville
- Limited kerb ramps and narrow footpaths present in Petersham area and are difficult to navigate with a pram or mobility aide
- Concerns over security and safety in relation to robberies and other crimes
- Poor condition of footpaths and uneven surfaces in many places (including paths damaged by tree roots) making walking difficult
- Limited rest stops or street furniture to be used as a rest stops for seniors
- Limited or no public restrooms or family rooms near Marrickville Station or town centre
- Limited PWD parking at Marrickville Town Hall
- Desire to connect public spaces with other seniors services or groups (such as mens shed)
- Desire for community led social activities at the Library
- Dog waste left of footpaths in Tempe.

Other Responses from individuals

A total of 14 email responses were received from individuals and groups of residents of the Inner West during the engagement period, including the local State MP for Summer Hill Jo Haylen supporting the pedestrian study.

Each individual email represented a unique issue, however, the common themes across the responses were related to footpath facilities and pedestrian safety.

A summary of the received email submissions and their feedback include:

- Condition of footpaths within the Inner West vary greatly, with some paths damaged or poorly constructed, presenting hazards for wheelchair users or mobility impaired users. Some specific submissions included paths in Tempe, Croydon, and Balmain
- All footpaths in the Balmain area should be reviewed as part of the study
- In older suburbs with narrow streets and footpaths, pedestrians are forced to use the roadway. The use of local streets by pedestrians should be considered in conjunction with lowering local speed limits to 30km/h or 40km/h
- Reduction of speed limits to 30 or 40km/h should be considered for local streets in Newtown and Enmore
- High traffic speeds and traffic volumes on local streets present safety issues for residents and pedestrians travelling along and using these roadways.
- Footpath trading (such as restaurant dining) in busy areas present challenges to footpath users, including parents accompanying younger bicycle riders
- Pedestrian issues are present at and near the intersection of Terry Street and Wellington Street in Rozelle, including challenges to crossing the road, high vehicle speeds and poor opportunities to cross
- A number of challenges to pedestrians and pedestrian safety are present at the Toothill Street, Old Canterbury Road, Summer Hill Street and McGill Street intersections due to geometry, vehicles speeds and volumes and non-compliance of parking and turn restrictions
- Increased use of powered bicycles and bicycle traffic on footpaths create a safety risk of other pedestrians, particularly on busy corridors.

Stage 2 – Public Exhibition

Overview

Stage two (public exhibition) sought feedback on the draft Pedestrian Access and Mobility Plan which included over 4000 recommendations. Public exhibition ran from 26 May–23 June 2021. High priority recommendations were displayed on an interactive map and feedback could be provided via a feedback form or direct channels, such as email.

Engagement methods

The community could provide feedback via the following methods:

- Your Say Inner West project page consisted of an information-only map with high priority works and a feedback form to provide comments
- A summary of the proposals specific feedback to the targeted groups

Promotion

The opportunity to participate was promoted using the following methods:

- Council's corporate website
- Your Say Inner West home page
- Vinyl footpath stickers located across town centres in the Inner West – providing a QR code to Your Say Inner West and map
- Email contact with community groups
- Direct email to Local Democracy Groups
- Council's social media
- Direct email to Your Say Inner West subscribers, past participants, and Multicultural network
- Direct email to community group convenors, including tailored summaries with content specific to the issues they had raised previously and how they were related to the final recommendations.

Engagement Outcomes


Who did we hear from?

The project page was viewed by 319 people with 25 providing direct feedback. Overall, there were over 170 individual downloads across 4 documents, 23 video views and 104 map views. 6 email responses were also received. A total of 31 people and organisations responded to the public exhibition.

Where do they live / are based?

Of the 31 responders, all but two indicated to reside or be based within the Inner West as a resident or organisation. This included 27 Inner West Residents, 1 resident from neighbouring City of Sydney, 2 Organisations based in the Inner West and 1 not providing details.


A detailed breakdown of the received data for responders by residential suburb is shown graph below.



What age groups did we hear from?

Responders were well distributed across the age brackets, with the highest number of responders within the 35-49 years old bracket (7) or *preferred not to say* (7). Age brackets were not applicable to organisations. A detailed breakdown of responders by age group is shown in the graph below.

Responders by Age Bracket



What did they say?

Of the 31 responses received, a wide range of topics and themes were presented, including different locations, issues, and suggestions. Feedback also varied in detail and covered both general topics and specific locations or issues.

Key general topics and themes included:

- The PAMP lacks action, direction, and aspirations, focussing on existing issues
- Reducing traffic volumes, rat running and speed limits on local streets to better provide for pedestrians and local access (including more traffic calming, and changing speed limits to 40km/h or 30km/h)
- Lack of action or investigation on bicycles using footpaths and conflicts with pedestrians

- Further enforcement required of illegal parking, bicycle riding and kerbside trading to improve use of footpaths by pedestrians
- Provide more crossings and/or shared zones (where necessary) to improve pedestrian priority and amenity throughout the Inner West
- Mixed opinions about implementation of shared zones and impact on pedestrian safety
- Improved maintenance of pedestrian crossings, and upgrade to raised crossings at problematic locations
- General design of kerb ramps such that they are more wheelchair and pram friendly
- Queries whether past customer complaints have been included and how future complaints will be integrated with the plan, particularly issues not on priority routes
- Groups of treatments by location or area should be upgraded and prioritised instead of by treatment priority
- Preference to retain sandstone kerbing and heritage items where possible

Key site or area specific responses included the following (by suburb) topics or items:

- Annandale
 - o Poor crossing opportunities on Booth Street and suggestions on providing an underpass and better connections along Johnstons Creek
 - o Driver behaviour in some small local streets poses a safety risk to pedestrians crossing
- Ashfield
 - o Routes to and from the aquatic centre should be prioritised
 - o Damaged barriers along the Frederick Street rail underpass degrades quality of footpath and route
 - o Further treatments required near the Knox Street / Norton Street intersection
- Camperdown
 - o More traffic calming needed to match bordering City of Sydney areas and provide consistent speed environment
 - o Pedestrian crossing on Salisbury Road near St Marys St has poor sight lines, exhibits many near misses and vehicles approaching at speed

- Croydon
 - o Provide a second access to train station platform at Paisley Lane
 - o Include the newly proposed Iron Cove Creek / Dobroyd Parade path in action plan
- Haberfield
 - o More pedestrian crossings over main roads, particularly over Ramsay Steet
- Leichardt
 - o Shared zone required on Prospect Street to provide better access for students and pedestrians accessing nearby schools
- Lewisham
 - o Pedestrian routes to and from Lewisham West is poor, particularly the route to Lewisham Station
 - o Facilities and routes should be upgraded, including additional crossing points to accommodate local population growth and desire lines
- Lilyfield
 - o The well-used laneway near Orange Grove Primary School requires upgrade to better provide for pedestrians
- Marrickville
 - o Industrial area around Sydenham does not consider or include many pedestrian attractors or generators
 - o Missing kerb ramps in South Marrickville area
 - o Poor crossing opportunities along Addison Road between Victoria Road and Illawarra Road
 - o Path and access upgrades needed near Cooks River path and on Bayview Avenue bridge
 - o The crossing at Fitzroy St / Sydenham Road requires upgrade to wombat crossing or signals
 - o High traffic volumes and speeds at Cook Street / Victoria Road makes crossing unsafe
- Newtown
 - o Major bottle necks are present along footpaths and intersection near the train station
 - o Many streets and footpath are poorly lit forcing pedestrians onto the road

- Rozelle
 - New kerb ramps required along Victoria Road near Ellen Street and Evan Street due to grade and width
- Summer Hill
 - Further treatments are required at some locations, including new kerb ramps
 - Some recommended kerb ramp improvements are not required on local streets.
 - Suggestion to block Lackey Street to vehicle traffic altogether to improve pedestrian amenity.

Officer comments in response to public exhibition

General Themes

Staff have provided responses to main themes raised during public exhibition, provided in the table below.

General Theme / Topic	Response
The PAMP lacks action, direction, and aspirations, focussing on existing issues	As the pedestrian network within the Inner West is well developed, the PAMP aims to upgrade existing facilities to improve the pedestrian experience.
Reducing traffic volumes, rat running and speed limits on local streets to better provide for pedestrians and local access (including more traffic calming, and changing speed limits to 40km/h or 30km/h)	The PAMP recommendations primarily focusses on pedestrian facilities. The plan aims to work concurrently with other Council traffic safety programs, including local traffic management and the 'Inner West goes 40' project.
Lack of action or investigation on bicycles using footpaths and conflicts with pedestrians	Minimal recommendations have been made to provide shared paths in key areas and not introduce further pedestrian bicycle-pedestrian conflicts. Younger bicycle riders are allowed to use footpaths under NSW road rules.

Further enforcement required of illegal parking, bicycle riding and kerbside trading to improve use of footpaths by pedestrians	Enforcement of these items will continue and are referred to Council compliance officers
Provide more crossings and/or shared zones (where necessary) to improve pedestrian priority and amenity throughout the Inner West	The action plan proposes the upgrade of many marked pedestrian crossings across the Inner West and new Shared Zones (where appropriate) to provide pedestrian access on some local streets.
Mixed opinions about implementation of shared zones and impact on pedestrian safety	Shared zones follow state design guidelines to ensure a safe and convenient road environment for all users, including pedestrians. In some locations, a shared zone is the most appropriate and effective treatment.
Improved maintenance of pedestrian crossings, and upgrade to raised crossings at problematic locations	The action plan proposes the upgrade of many marked pedestrian crossings across the Inner West, including conversion to raised crossings in key areas
General design of kerb ramps such that they are more wheelchair and pram friendly	Grades and designs of kerb ramps must typically be treated on a case-by case basis, but follow general design principles set out by Council, including grades.
Queries whether past customer complaints have been included and how future complaints will be integrated with the plan, particularly issues not on priority routes	Initial engagement data and common customer complaints were considered in the investigation process. Council will continue to receive customer feedback.
Groups of treatments by location or area should be upgraded and prioritised instead of by treatment priority	Treatment priority as part of the action plan is indicative based on the type of treatment and issue it is addressing. It may be more efficient to undertake a group of upgrades or treatments and will be determined as the action plan is carried out.

Preference to retain sandstone kerbing and heritage items where possible	Council's preference is to retain or reinstate sandstone or heritage kerbing where it currently exists. This will be reviewed on a case-by-case basis.
--	--

Location Specific Items

Responses to location specific topics and items are provided in the table below:

Suburb	Item	Response
Annandale	Poor crossing opportunities on Booth Street and suggestions on providing an underpass and better connections along Johnstons Creek	<ul style="list-style-type: none"> - Some new crossing points were proposed and include in final action plan. These crossings will require consultation with City of Sydney - Investigations were included as part of the Johnstons Creek Shared path
	Driver and corner cutting behaviour in some small local streets poses a safety risk to pedestrians crossing	Road width at these locations may not allow for a pedestrian refuge. Kerb extensions have been proposed as an alternative
Ashfield	Routes to and from the aquatic centre should be prioritised	Key routes surrounding the aquatic centre were scored based on surrounding land uses, including the aquatic centre, resulting in a secondary ranking within the route hierarchy, positively contributing to treatment priority scoring in the area
	Damaged barriers along the Frederick Street rail underpass degrades quality of footpath and route	Damaged barriers and width of footpath were identified and included in the action plan. Path widening to be further investigated
	Further treatments required near the Knox Street / Norton Street intersection	Intersection and treatments were reviewed and updated. Raised crossing included as recommended treatment

Ashfield	More traffic calming needed to match bordering City of Sydney areas and provide consistent speed environment	Council is currently looking to undertake the 'inner West goes 40' project to reduce local street speeds to 40km/h, similar to neighbouring areas in City of Sydney
	Pedestrian crossing on Salisbury Road near St Marys St has poor sight lines, exhibits many near misses and vehicles approaching at speed	Crossing included to be converted to a raised crossing
Croydon	Provide a second access to train station platform at Paisley Lane	Train station access will be referred to Transport for NSW for consideration
	Include the newly proposed Iron Cove Creek / Dobroyd Parade path in action plan	The Iron Cove Creek / Dobroyd Parade path has been included in the action plan
Haberfield	More pedestrian crossings over main roads, particularly over Ramsay Steet	A number of improvements are being planned for Ramsay Street as part of the Haberfield Village High Pedestrian Activity Area, included upgraded pedestrian refuges
Leichardt	Shared zone required on Prospect Street to provide better access for students and pedestrians accessing nearby school	Shared zone along prospect Street has been included in the action plan
Lewisham	Pedestrian routes to and from Lewisham West is poor, particularly the route to Lewisham Station	- additional crossing to be investigated (as below)
	Facilities and routes should be upgraded, including additional crossing points on Old Canterbury Rad to accommodate local population growth and desire lines	- Crossing point at Henry Street and Hudson Street has been included in the action plan for investigation - Shared zone along McGill Street and following pedestrian desire line has been included in the action plan

Lilyfield	The well-used laneway near Orange Grove Primary School requires upgrade to better provide for pedestrians	The subject laneway was not included as an PAMP audit route. Any issues are to be referred to Council maintenance
Marrickville	Industrial area around Sydenham does not consider or include many pedestrian attractors or generators	Key pedestrian attractor and generators were considered in the investigation, such as Sydenham Train Station, bus stops and Marrickville Metro shopping centre.
	Missing kerb ramps in South Marrickville area	Kerb ramps near school route and near attractor generators near Steel Park included in action plan
	Poor crossing opportunities along Addison Road between Victoria Road and Illawarra Road	Pedestrian refuge included in action plan near Perry Street and bus stops
	Path and access upgrades needed near Cooks River path and on Bayview Avenue bridge	<ul style="list-style-type: none"> – Bridge and path upgrade along Bayview Avenue to be referred to Canterbury-Bankstown and Transport for NSW for further investigation – Access upgrades near Cooks River Path to be referred to car park and landowners
	The crossing at Fitzroy St / Sydenham Road requires upgrade to wombat crossing or signals	Crossing and intersection upgrades included as part of action plan
	High traffic volumes and speeds at Cook Street / Victoria Road makes crossing unsafe	Kerb extensions and modifications of intersection included in action plan to reduce traffic speeds and reduce crossing distance for pedestrians


Newtown	Major bottle necks are present along footpaths and intersection near the train station and bus stops	Footpath widening along Enmore Road may be limited due to primary movement corridor and constraints due to bridge, added to action plan for further investigation New kerb ramps outside Newtown Train Station added to action plan and to be further consulted with TfNSW and City of Sydney
	Many streets and footpath are poorly lit forcing pedestrians onto the road	
Rozelle	New kerb ramps required along Victoria Road near Ellen Street and Evan Street due to grade and width	Kerb ramps added to action plan
Summer Hill	Further treatments are required at some locations, including new kerb ramps	Kerb ramps around Sloane Street added to action plan
	Some recommended kerb ramp improvements are not required on local streets.	Specific kerb ramps were reviewed and removed from action plan
	Suggestion to block Lackey Street to vehicle traffic altogether to improve pedestrian amenity	While this suggestion would ultimately provide for pedestrians in Summer Hill village, this will cause issues with vehicle access in the area, including deliveries and service vehicles. Re-routing of traffic may also cause issues on other local streets used as detours



Appendix B: Audit Routes

Item 7

Attachment 3






Appendix C: Route Hierarchy

Item 7

Attachment 4





Appendix D: Audit Findings

Item 7

Attachment 5





Appendix E: Detailed Works Program

Item 7


Attachment 6












Gold Coast
Suite 26, 58 Riverwalk Avenue
Robina QLD 4226
P: (07) 5562-5377
W: www.bitziosconsulting.com.au

Brisbane
Level 2, 428 Upper Edward Street
Spring Hill QLD 4000
P: (07) 3831-4442
E: admin@bitziosconsulting.com.au


Sydney
Studio 203, 3 Gladstone Street
Newtown NSW 2042
P: (02) 9557-6202


Title:
Inner West PAMP
Treatment Priority
Balmain, Birchgrove,
Rozelle, Lilyfield


Project Number: P4909
Date: 06/08/2021
Issue: 2





<p>Gold Coast Suite 26, 58 Riverwalk Avenue Robina QLD 4226 P: (07) 5562-5377 W: www.bitziosconsulting.com.au</p>	<p>Brisbane Level 2, 428 Upper Edward Street Spring Hill QLD 4000 P: (07) 3831-4442 E: admin@bitziosconsulting.com.au</p>	<p>Sydney Studio 203, 3 Gladstone Street Newtown NSW 2042 P: (02) 9557-6202</p>	<p>Title: Inner West PAMP Treatment Priority Leichardt, Haberfield Annandale, Camperdown</p>	<p>Project Number: P4909 Date: 05/08/2021 Issue: 1</p>
--	--	--	---	---



	Gold Coast	Brisbane	Sydney	Title: Inner West PAMP Treatment Priority Dulwich Hill, Lewisham, Petersham Stanmore, Newtown, Camperdown	Project Number: P4909
	Suite 26, 58 Riverwalk Avenue Robina QLD 4226 P: (07) 5562-5377 W: www.bitziosconsulting.com.au	Level 2, 428 Upper Edward Street Spring Hill QLD 4000 P: (07) 3831-4442 E: admin@bitziosconsulting.com.au	Studio 203, 3 Gladstone Street Newtown NSW 2042 P: (02) 9557-6202	Date: 05/08/2021	
					Issue: 2



	Gold Coast Suite 26, 58 Riverwalk Avenue Robina QLD 4226 P: (07) 5562-5377 W: www.bitziosconsulting.com.au	Brisbane Level 2, 428 Upper Edward Street Spring Hill QLD 4000 P: (07) 3831-4442 E: admin@bitziosconsulting.com.au	Sydney Studio 203, 3 Gladstone Street Newtown NSW 2042 P: (02) 9557-6202	Title: Inner West PAMP Treatment Priority Marrickville, Tempe St Peters, Newtown	Project Number: P4909 Date: 05/08/2021 Issue: 2
---	---	---	--	---	---



**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
AC10	Darling Street	Balmalm	Local Road	access	stairs only access to park	-33.85823	151.183699	1		install accessible ramp	BA28	Primary	HIGH	\$ 10,000
AC11	Jane Street	Balmalm	Local Road	access	stairs only access	-33.85836	151.184402	1		no action	BA44	Primary	HIGH	\$ -
AC20	Railway Terrace	Lewisham	State Road	access	stairs only access to station underpass	-33.89354	151.147642	1		consult with TNSW	W24	Primary	HIGH	\$ -
AC21	Thomas Street	Lewisham	Local Road	access	stairs only access to station underpass	-33.89358	151.147694	1		consult with TNSW	W30	Primary	HIGH	\$ -
AC31	Traralgar Street	Petersham	Regional Road	access	stairs only access to station underpass	-33.894495	151.154246	1		consult with TNSW	PE62	Primary	HIGH	\$ -
AC38	Starmore Road	Starmore	State Road	access	stairs only access	-33.89477	151.163590	1		consult with TNSW	SM35	Primary	HIGH	\$ -
AC39	Traralgar Street	Starmore	Regional Road	access	stairs only access to station underpass	-33.89432	151.164375	1		consult with TNSW	SM34	Primary	HIGH	\$ -
AC40	Carlton Crescent	Summer Hill	Regional Road	access	steep crossfall	-33.890665	151.138762	1		further investigation required - crossfall	SH3	Primary	HIGH	\$ -
CD1007	Flood Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.88569	151.149749	1		install new kerb ramp	LH89	Primary	HIGH	\$ 2,500
CD1018	Foster Lane	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88531	151.147697	1		install new Tactile Ground Surface Indicators	LH68	Primary	HIGH	\$ 650
CD1021	Lords Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886078	151.14756	1		install new kerb ramp	LH153	Primary	HIGH	\$ 2,500
CD1032	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883673	151.158939	1		install new kerb ramp - pair	LH102	Primary	HIGH	\$ 5,000
CD1033	Renwick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.883871	151.156101	1		install new kerb ramp	LH101	Primary	HIGH	\$ 2,500
CD1034	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88399	151.153892	1		install new kerb ramp	LH100	Primary	HIGH	\$ 2,500
CD104	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.880862	151.169319	1		install new kerb ramp	AN26	Primary	HIGH	\$ 2,500
CD1041	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88413	151.14997	1		install new kerb ramp	LH95	Primary	HIGH	\$ 2,500
CD1042	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88413	151.149756	1		install new kerb ramp - pair	LH95	Primary	HIGH	\$ 5,000
CD1043	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884145	151.147654	1		install new kerb ramp	LH94	Primary	HIGH	\$ 2,500
CD1044	Marion Street	Leichhardt	Regional Road	crossing deficiency	narrow kerb ramp	-33.884211	151.147573	1		install new kerb ramp	LH72	Primary	HIGH	\$ 2,500
CD1047	Moore Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.879308	151.164158	1		install new kerb ramp	LH108	Primary	HIGH	\$ 2,500
CD1052	Catherine Lane	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.87916	151.163623	1		install new kerb ramp - pair	LH107	Primary	HIGH	\$ 5,000
CD1058	Norton Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883856	151.157086	1		install new kerb ramp - pair	LH128	Primary	HIGH	\$ 5,000
CD1059	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883771	151.157157	1		install new kerb ramp - pair	LH103	Primary	HIGH	\$ 5,000
CD1060	Norton Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883712	151.157086	1		install new kerb ramp - pair	LH119	Primary	HIGH	\$ 5,000
CD1061	Marion Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.883749	151.157016	1		install new kerb ramp - pair	LH101	Primary	HIGH	\$ 5,000
CD1062	Norton Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.883857	151.157030	1		install new kerb ramp	LH128	Primary	HIGH	\$ 2,500
CD1063	Norton Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.880304	151.156889	1		install new Tactile Ground Surface Indicators	LH121	Primary	HIGH	\$ 650
CD1064	Norton Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.880308	151.156716	1		install new Tactile Ground Surface Indicators	LH122	Primary	HIGH	\$ 650
CD1067	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88786	151.161367	1		install new kerb ramp	LH145	Primary	HIGH	\$ 2,500
CD1068	Tebbutt Street	Leichhardt	State Road	crossing deficiency	misaligned kerb ramp	-33.88983	151.145681	1		install new kerb ramp	LH132	Primary	HIGH	\$ 2,500
CD1069	Paramatta Road	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88945	151.14611	1		install new kerb ramp - pair	LH158	Primary	HIGH	\$ 5,000	
CD1070	Petersham Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888162	151.157724	1		install new kerb ramp - pair	LH142	Primary	HIGH	\$ 5,000
CD1072	Hay Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.887746	151.16008	1		install new kerb ramp - pair	LH143	Primary	HIGH	\$ 5,000
CD1073	Balmalm Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887762	151.159286	1		install new kerb ramp - pair	LH18	Primary	HIGH	\$ 5,000
CD1074	Paramatta Road	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88777	151.159607	1		install new kerb ramp - pair	LH142	Primary	HIGH	\$ 5,000
CD1075	Norton Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888066	151.157645	1		install new kerb ramp - pair	LH115	Primary	HIGH	\$ 5,000
CD1076	Paramatta Road	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888163	151.157514	1		install new kerb ramp - pair	LH141	Primary	HIGH	\$ 5,000
CD1077	Renwick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888112	151.156816	1		install new kerb ramp - pair	LH141	Primary	HIGH	\$ 5,000
CD1078	Rofe Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888601	151.15552	1		install new kerb ramp - pair	LH139	Primary	HIGH	\$ 5,000
CD1079	Elswick Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.888991	151.153145	1		install new kerb ramp - pair	LH138	Primary	HIGH	\$ 5,000
CD1080	National Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889579	151.162990	1		install new kerb ramp - pair	LH136	Primary	HIGH	\$ 5,000
CD1083	Upward Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889577	151.147479	1		install new kerb ramp - pair	LH133	Primary	HIGH	\$ 5,000
CD1084	Tebbutt Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889912	151.146872	1		install new kerb ramp - pair	LH133	Primary	HIGH	\$ 5,000
CD1089	Renwick Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.887972	151.156707	1		install new kerb ramp - pair	LH141	Primary	HIGH	\$ 5,000
CD1099	Keyworth Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886867	151.147436	1		install new kerb ramp	LH153	Primary	HIGH	\$ 2,500
CD110	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.878113	151.170580	1		re-construct refuge island	AN8	Primary	HIGH	\$ 15,000
CD111	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879453	151.169885	1		install new kerb ramp	AN9	Primary	HIGH	\$ 2,500
CD114	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877203	151.159957	1		install new kerb ramp - pair	LH13	Primary	HIGH	\$ 5,000
CD115	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878663	151.170208	1		install new Tactile Ground Surface Indicators	AN8	Primary	HIGH	\$ 650
CD113	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.878116	151.170595	1		re-construct refuge island	AN8	Primary	HIGH	\$ 15,000
CD114	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878116	151.170589	1		install new kerb ramp - pair	AN8	Primary	HIGH	\$ 5,000
CD1142	Moore Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.878239	151.159638	1		install new kerb ramp	LH13	Primary	HIGH	\$ 2,500
CD1144	Annandale Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.879103	151.159489	1		install new kerb ramp	LH12	Primary	HIGH	\$ 2,500
CD1145	Balmalm Road	Leichhardt	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.879732	151.159290	1		install new Tactile Ground Surface Indicators - pair	LH11	Primary	HIGH	\$ 1,300
CD1146	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881096	151.145263	1		install new kerb ramp	LH10	Primary	HIGH	\$ 2,500
CD1147	Hill Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.879797	151.159179	1		install new kerb ramp - pair	LH17	Primary	HIGH	\$ 5,000
CD1148	Balmalm Road	Leichhardt	Regional Road	crossing deficiency	driveway as kerb ramp	-33.881722	151.158878	1		further investigation required - kerb ramp	LH21	Primary	HIGH	\$ 5,000
CD1149	Balmalm Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.882683	151.158965	1		install new kerb ramp	LH21	Primary	HIGH	\$ 2,500
CD1150	Balmalm Road	Leichhardt	Regional Road	crossing deficiency	missing kerb ramp	-33.882684	151.158914	1		install new kerb ramp	LH21	Primary	HIGH	\$ 2,500
CD1151	Wetherhill Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882736	151.158909	1		install new kerb ramp	LH17	Primary	HIGH	\$ 2,500
CD1152	Wetherhill Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.882683	151.158984	1		install new kerb ramp	LH21	Primary	HIGH	\$ 2,500
CD1153	Balmalm Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88378	151.159008	1		install new kerb ramp - pair	LH9	Primary	HIGH	\$ 5,000
CD1154	McDonald Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.885079	151.159123	1		install new kerb ramp	LH20	Primary	HIGH	\$ 2,500
CD1155	McDonald Street	Leichhardt	Local Road	crossing deficiency	steep kerb ramp	-33.885067	151.159139	1		install new kerb ramp - pair	LH20	Primary	HIGH	\$ 5,000
CD1157	Dol Lane	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.887436	151.159195	1		install new kerb ramp	LH18	Primary	HIGH	\$ 2,500
CD1158	Dol Lane	Leichhardt	Local Road	crossing deficiency	driveway as kerb ramp	-33.887452	151.159173	1		no action	LH18	Primary	HIGH	\$ 2,500
CD1159	Balmalm Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887031	151.159216	1		install new kerb ramp - pair	LH18	Primary	HIGH	\$ 5,000
CD1165	Hudson Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89402	151.143995	1		install new kerb ramp	LW5	Primary	HIGH	\$ 2,500
CD1166	Hudson Street	Lewisham	Local Road	crossing deficiency	missing kerb ramp	-33.894026	151.143926	1		install new kerb ramp	LW5	Primary	HIGH	\$ 2,500
CD1167	Hudson Street	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893715	151.143903	1		install new Tactile Ground Surface Indicators	LW12	Primary	HIGH	\$ 650
CD1168	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.896848	151.14936	1		install new kerb ramp	LW11	Primary	HIGH	\$ 2,500
CD1174	Hunter Street	Lewisham	Local Road	crossing deficiency	missing kerb ramp	-33.894468	151.148709	1		install new kerb ramp	LW7	Primary	HIGH	\$ 2,500
CD1175	New Canterbury Road	Lewisham	State Road	crossing deficiency	misaligned kerb ramp	-33.897933	151.147029	1		install new kerb ramp	LW14	Primary	HIGH	\$ 2,500
CD1176	New Canterbury Road	Lewisham	State Road	crossing deficiency	misaligned kerb ramp	-33.89696	151.149287	1		install new kerb ramp	LW11	Primary	HIGH	\$ 2,500
CD1177	Wardell Road	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896923	151.149333	1		install new kerb ramp - pair	LW38	Primary	HIGH	\$ 5,000
CD1180	New Canterbury Road	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896847	151.149351	1		install new kerb ramp	LW11	Primary	HIGH	\$ 2,500
CD1179	Morton Avenue	Lewisham	Regional Road	crossing deficiency	misaligned refuge island	-33.896933	151.149209	1		re-construct refuge island	LW38	Primary	HIGH	\$ 15,000
CD1178	Wardell Road	Lewisham	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.896966	151.149296	1		install new Tactile Ground Surface Indicators	LW38	Primary	HIGH	\$ 650
CD1183	Hudson Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894163	151.145168	1		install new kerb ramp - pair	LW19	Primary	HIGH	\$ 5,000
CD1184	Tootill Street	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.894894	151.146036	1		install new kerb ramp	LW19	Primary	HIGH	\$ 2,500
CD1185	Old Canterbury Road	Lewisham	Local Road	crossing deficiency	missing kerb ramp	-33.895418	151.145439	1		install new kerb ramp	LW38	Primary	HIGH	\$ 5,000
CD1190	Old Canterbury Road	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895998	151.146479	1		install new kerb ramp - pair	LH132	Primary	HIGH	\$ 5,000
CD1191	Camington Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897158	151.147484	1		install new kerb ramp - pair	LH133	Primary	HIGH	\$ 5,000
CD1193	Railway Terrace	Lewisham	State Road	crossing deficiency	narrow pedestrian waiting area	-33.894031	151.149796	1		consult with TNSW	LW23	Primary	HIGH	\$ 5,000
CD1195	Thomas Street	Lewisham	Local Road	crossing deficiency	missing crossing point	-33.891675	151.147995	1		install new kerb ramp - pair	LW33	Primary	HIGH	\$ 5,000
CD1197	Tootill Street	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.895554	151.145063	1		install new kerb ramp	LW36	Primary	HIGH	\$ 2,500
CD1198	Tootill Street	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.895527	151.145114	1		install new kerb ramp	LW36	Primary	HIGH	\$ 2,500
CD1203	Tootill Street	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.897585	15							

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1217	Nestor Lane	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890352	151.148867	1		install new kerb ramp	LN31	Primary	HIGH	\$ 2,500
CD1218	Thomas Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890473	151.148928	1		install new kerb ramp - pair	LN31	Primary	HIGH	\$ 5,000
CD1220	Cecily Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886778	151.165703	1		install new kerb ramp	LF3	Primary	HIGH	\$ 2,500
CD1221	Balmann Road	Lewisham	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.886495	151.16569	1		install new Tactile Ground Surface Indicators	LF3	Primary	HIGH	\$ 650
CD1222	Balmann Road	Lewisham	Local Road	crossing deficiency	missing kerb ramp	-33.886429	151.16595	1		install new kerb ramp	LF3	Primary	HIGH	\$ 2,500
CD1223	Park Drive	Lewisham	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.886642	151.16571	1		install new Tactile Ground Surface Indicators	LF3	Primary	HIGH	\$ 650
CD1224	Balmann Road	Lewisham	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.887525	151.164648	1		install new Tactile Ground Surface Indicators	LF3	Primary	HIGH	\$ 650
CD1225	Alberto Street	Lewisham	Local Road	crossing deficiency	long crossing	-33.887596	151.164929	1		install kerb extension	LF5	Primary	HIGH	\$ 10,000
CD1231	Balmann Road	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871553	151.159717	1		install new kerb ramp - pair	LF6	Primary	HIGH	\$ 5,000
CD1232	Wharf Road	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.874482	151.159591	1		install new kerb ramp	LF8	Primary	HIGH	\$ 2,500
CD1233	NSW Ambulance Centre	Lewisham	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.871272	151.160505	1		install new Tactile Ground Surface Indicators	LF6	Primary	HIGH	\$ 650
CD1238	Edward Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872662	151.160034	1		install new kerb ramp	LF10	Primary	HIGH	\$ 2,500
CD1240	Pont Street	Lewisham	Local Road	crossing deficiency	raised kerb ramp lip	-33.871968	151.159995	1		install new kerb ramp	LF10	Primary	HIGH	\$ 2,500
CD1241	Balmann Road	Lewisham	Regional Road	crossing deficiency	missing crossing point	-33.872477	151.159942	1		install new kerb ramp - pair	LF10	Primary	HIGH	\$ 5,000
CD1247	City West Link Bridge	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.874937	151.156111	1		install new kerb ramp	LN114	Primary	HIGH	\$ 2,500
CD1248	Norton Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.874933	151.156117	1		install new kerb ramp	LN114	Primary	HIGH	\$ 2,500
CD1249	City West Link Bridge	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.874903	151.156171	1		install new kerb ramp	LN114	Primary	HIGH	\$ 2,500
CD1252	James Street	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.875036	151.155283	1		install new kerb ramp	LN114	Primary	HIGH	\$ 2,500
CD129	Nelson Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.88233	151.173585	1		install new kerb ramp - pair	AN65	Primary	HIGH	\$ 5,000
CD130	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.880939	151.169351	1		re-construct refuge island	AN25	Primary	HIGH	\$ 15,000
CD1315	Norton Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875189	151.155955	1		install new kerb ramp	LN114	Primary	HIGH	\$ 2,500
CD1316	Norton Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875128	151.15596	1		install new kerb ramp	LN114	Primary	HIGH	\$ 2,500
CD1317	Emmerick Street	Lewisham	Local Road	crossing deficiency	long crossing	-33.872096	151.157377	1		install kerb extension - pair	LF8	Primary	HIGH	\$ 20,000
CD1325	Piper Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876487	151.164897	1		install new kerb ramp - pair	LF40	Primary	HIGH	\$ 5,000
CD1355	Addison Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.90221	151.163512	1		install new kerb ramp	MV8	Primary	HIGH	\$ 2,500
CD1373	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.913721	151.158851	1		install new Tactile Ground Surface Indicators - pair	MV226	Primary	HIGH	\$ 1,300
CD14	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.880203	151.173778	1		install new kerb ramp	AN65	Primary	HIGH	\$ 2,500
CD1400	Dudley Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.911448	151.142222	1		install new kerb ramp	MV46	Primary	HIGH	\$ 2,500
CD1403	Edgeware Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tpsi	-33.905559	151.173464	1		install new Tactile Ground Surface Indicators	MV47	Primary	HIGH	\$ 650
CD1404	Edinburgh Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905669	151.167114	1		install new kerb ramp	MV13	Primary	HIGH	\$ 2,500
CD1407	Lewellyn Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903409	151.163844	1		install new kerb ramp - pair	MV5	Primary	HIGH	\$ 5,000
CD1408	Enmore Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.903192	151.169892	1		install new kerb ramp	MV62	Primary	HIGH	\$ 2,500
CD1409	Cowper Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.902992	151.16888	1		install new kerb ramp	MV62	Primary	HIGH	\$ 2,500
CD141	Bridge Road	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887546	151.171471	1		install new kerb ramp - pair	AN81	Primary	HIGH	\$ 5,000
CD1410	Scotter Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.902513	151.169388	1		install new kerb ramp	MV13	Primary	HIGH	\$ 2,500
CD1413	Enmore Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.905667	151.167394	1		install new kerb ramp	MV13	Primary	HIGH	\$ 2,500
CD1416	Ewart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912116	151.140145	1		install new kerb ramp - pair	MV65	Primary	HIGH	\$ 5,000
CD1417	Ewart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912824	151.140813	1		install new kerb ramp - pair	MV65	Primary	HIGH	\$ 5,000
CD1422	Ewart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.912887	151.141059	1		install new Tactile Ground Surface Indicators - pair	MV67	Primary	HIGH	\$ 1,300
CD1423	Ewart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912382	151.140564	1		install new kerb ramp - pair	MV66	Primary	HIGH	\$ 5,000
CD1424	Wardell Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912055	151.140174	1		install new kerb ramp - pair	MV28	Primary	HIGH	\$ 5,000
CD1449	Ilwara Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.910171	151.156635	1		install new Tactile Ground Surface Indicators - pair	MV6	Primary	HIGH	\$ 1,300
CD1451	Schwebel Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914357	151.152771	1		install new kerb ramp	MV189	Primary	HIGH	\$ 2,500
CD1457	Wharf Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.921478	151.14337	1		install new kerb ramp - pair	MV103	Primary	HIGH	\$ 5,000
CD1458	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.921368	151.143327	1		install new kerb ramp	MV103	Primary	HIGH	\$ 2,500
CD1459	Wharf Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.921641	151.143403	1		install new Tactile Ground Surface Indicators - pair	MV103	Primary	HIGH	\$ 1,300
CD146	Chester Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884328	151.17328	1		install new kerb ramp - pair	AN31	Primary	HIGH	\$ 5,000
CD1462	Carly Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.917233	151.148749	1		install new kerb ramp - pair	MV66	Primary	HIGH	\$ 5,000
CD1463	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912477	151.145094	1		install new kerb ramp - pair	MV6	Primary	HIGH	\$ 5,000
CD1464	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912446	151.154119	1		install new kerb ramp - pair	MV6	Primary	HIGH	\$ 5,000
CD1465	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.911826	151.154946	1		install new kerb ramp	MV6	Primary	HIGH	\$ 2,500
CD1467	Ilwara Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.910868	151.156113	1		install new Tactile Ground Surface Indicators - pair	MV8	Primary	HIGH	\$ 1,300
CD1468	Byrnes Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912864	151.153798	1		install new kerb ramp - pair	MV91	Primary	HIGH	\$ 5,000
CD1469	Byrnes Street	Marrickville	Local Road	crossing deficiency	uneven crossing surface	-33.912999	151.153824	1		install new pavement surface	MV91	Primary	HIGH	\$ 300
CD147	Chester Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.88427	151.173274	1		install new Tactile Ground Surface Indicators - pair	AN31	Primary	HIGH	\$ 1,300
CD1470	Ilwara Road	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.911641	151.152629	1		install new kerb ramp - pair	MV6	Primary	HIGH	\$ 5,000
CD1472	Livingstone Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.901474	151.153484	1		install new kerb ramp	PE27	Primary	HIGH	\$ 2,500
CD1473	Livingstone Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.901483	151.153491	1		install new kerb ramp	PE27	Primary	HIGH	\$ 2,500
CD1478	Livingstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.90866	151.152513	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1479	Livingstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.908791	151.152467	1		install new kerb ramp - pair	MV138	Primary	HIGH	\$ 5,000
CD1480	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.908449	151.152436	1		install new Tactile Ground Surface Indicators - pair	MV107	Primary	HIGH	\$ 1,300
CD1486	Livingstone Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.901646	151.153367	1		install new kerb ramp	MV108	Primary	HIGH	\$ 2,500
CD1487	Fraser Street	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.90154	151.153318	1		install new kerb ramp	MV108	Primary	HIGH	\$ 2,500
CD1491	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.91076	151.149772	1		install new Tactile Ground Surface Indicators - pair	MV121	Primary	HIGH	\$ 1,300
CD1501	Livingstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.910797	151.149835	1		install new kerb ramp	MV121	Primary	HIGH	\$ 2,500
CD1502	Livingstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.910335	151.150428	1		install new kerb ramp	MV120	Primary	HIGH	\$ 2,500
CD1504	Livingstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.910443	151.150542	1		install new kerb ramp	MV120	Primary	HIGH	\$ 2,500
CD1511	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.908781	151.152458	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1512	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.908675	151.152381	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1516	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.908678	151.152499	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1517	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.914417	151.163315	1		install new Tactile Ground Surface Indicators - pair	MV130	Primary	HIGH	\$ 1,300
CD1518	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.913516	151.162154	1		install new kerb ramp	MV129	Primary	HIGH	\$ 2,500
CD1519	Sydney Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909449	151.151923	1		install new kerb ramp - pair	MV129	Primary	HIGH	\$ 5,000
CD1527	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.909709	151.154418	1		install new kerb ramp - pair	MV137	Primary	HIGH	\$ 5,000
CD1528	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.909574	151.154322	1		install new kerb ramp	MV139	Primary	HIGH	\$ 2,500
CD1529	Pelcher Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.909572	151.154225	1		install new Tactile Ground Surface Indicators	MV139	Primary	HIGH	\$ 650
CD1530	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.908946	151.152955	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1531	Marrickville Road	Marrickville	Regional Road	crossing deficiency	major driveway crossing missing tpsi - pair	-33.908958	151.153242	1		install new Tactile Ground Surface Indicators	MV138	Primary	HIGH	\$ 650
CD1532	Pelcher Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909566	151.154329	1		install new kerb ramp - pair	MV139	Primary	HIGH	\$ 5,000
CD1533	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.909735	151.154445	1		install new kerb ramp	MV137	Primary	HIGH	\$ 2,500
CD1534	Malcolm Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tpsi - pair	-33.909764	151.154582	1		install new Tactile Ground Surface Indicators - pair	MV137	Primary	HIGH	\$ 1,300
CD1544	Marrickville Road	Marrickville	Regional Road	crossing deficiency	narrow refuge island	-33.912126	151.160239	1		install new corner refuge island	MV220	Primary	HIGH	\$ 10,000
CD1545	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.912263	151.160294	1		install new kerb ramp	MV220	Primary	HIGH	\$ 2,500
CD1546	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned refuge island	-33.913403	151.16199	1		re-construct refuge island	MV129	Primary	HIGH	\$ 15,000
CD1547	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.913823	151.162616	1		install new kerb ramp - pair	MV129	Primary	HIGH	\$ 5,000
CD1548	Rayway Parade	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.915071	151.164587	1		install new kerb ramp - pair	MV131	Primary	HIGH	\$ 5,000
CD1549	Marrickville Road	Marrickville	Regional Road	crossing										

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1612	Station Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914237	151.152881	1		install new kerb ramp - pair	MV189	Primary	HIGH	\$ 5,000
CD1615	Victoria Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.909896	151.162437	1		install new kerb ramp	MV200	Primary	HIGH	\$ 2,500
CD1616	Victoria Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.907768	151.162202	1		install new kerb ramp	MV219	Primary	HIGH	\$ 2,500
CD1626	Sydenham Road	Marrickville	State Road	crossing deficiency	at grade crossing missing tgi	-33.905286	151.157094	1		install new Tactile Ground Surface Indicators	MV197	Primary	HIGH	\$ 650
CD1627	Northote Street	Marrickville	Local Road	crossing deficiency	long crossing point	-33.905736	151.167333	1		install kerb extension - pair	MV187	Primary	HIGH	\$ 20,000
CD1628	Neville Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.904046	151.165928	1		install new Tactile Ground Surface Indicators	MV180	Primary	HIGH	\$ 650
CD1629	Sydenham Road	Marrickville	State Road	crossing deficiency	at grade crossing missing tgi	-33.903404	151.165937	1		install new Tactile Ground Surface Indicators	MV180	Primary	HIGH	\$ 650
CD1630	Park Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.903355	151.165642	1		install new Tactile Ground Surface Indicators - pair	MV180	Primary	HIGH	\$ 1,300
CD1631	Petersham Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.903365	151.155103	1		install new Tactile Ground Surface Indicators	MV180	Primary	HIGH	\$ 650
CD1632	Bereton Avenue	Marrickville	Local Road	crossing deficiency	long crossing point	-33.902453	151.154247	1		install kerb extension - pair	MV189	Primary	HIGH	\$ 20,000
CD1633	Bereton Avenue	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.902363	151.154106	1		install new kerb ramp	MV199	Primary	HIGH	\$ 2,500
CD1637	Sydenham Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913383	151.166823	1		install new Tactile Ground Surface Indicators - pair	MV165	Primary	HIGH	\$ 1,300
CD1638	Sydenham Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.912702	151.166051	1		install new kerb ramp - pair	MV203	Primary	HIGH	\$ 5,000
CD1639	Buckley Street	Marrickville	State Road	crossing deficiency	unsafe crossing point	-33.912523	151.165675	1		further investigation required - pedestrian crossing	MV203	Primary	HIGH	\$ 10,000
CD1644	Weeks Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.910348	151.163087	1		install new kerb ramp - pair	MV200	Primary	HIGH	\$ 5,000
CD1660	Empire Lane	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905695	151.173199	1		install new Tactile Ground Surface Indicators	MV47	Primary	HIGH	\$ 650
CD1664	Sydenham Road	Marrickville	State Road	crossing deficiency	poor kerb ramp alignment	-33.90976	151.162221	1		install new kerb ramp	MV200	Primary	HIGH	\$ 2,500
CD1665	Sydenham Road	Marrickville	State Road	crossing deficiency	missing kerb ramp	-33.909751	151.162137	1		install new kerb ramp	MV219	Primary	HIGH	\$ 2,500
CD1666	Victoria Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913068	151.169302	1		install new Tactile Ground Surface Indicators - pair	MV225	Primary	HIGH	\$ 1,300
CD1667	Victoria Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912609	151.169786	1		install new kerb ramp - pair	MV225	Primary	HIGH	\$ 5,000
CD1668	Victoria Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.912606	151.169884	1		install new Tactile Ground Surface Indicators - pair	MV225	Primary	HIGH	\$ 1,300
CD1660	Victoria Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91432	151.158344	1		install new kerb ramp - pair	MV227	Primary	HIGH	\$ 5,000
CD1662	Warburton Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914195	151.162302	1		install new kerb ramp - pair	MV230	Primary	HIGH	\$ 5,000
CD1663	Warburton Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.913899	151.151787	1		install new Tactile Ground Surface Indicators	MV230	Primary	HIGH	\$ 650
CD1665	Warburton Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913943	151.152227	1		install new Tactile Ground Surface Indicators - pair	MV230	Primary	HIGH	\$ 1,300
CD1675	Duxley Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.911263	151.141324	1		install new kerb ramp	MV46	Primary	HIGH	\$ 2,500
CD1679	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918452	151.165094	1		install new kerb ramp - pair	MV42	Primary	HIGH	\$ 5,000
CD1680	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915627	151.150296	1		install new kerb ramp - pair	MV65	Primary	HIGH	\$ 5,000
CD1681	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.916337	151.151041	1		install new Tactile Ground Surface Indicators - pair	MV246	Primary	HIGH	\$ 1,300
CD1687	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915965	151.173933	1		install new kerb ramp - pair	MV246	Primary	HIGH	\$ 5,000
CD1688	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915934	151.150314	1		install new kerb ramp - pair	MV246	Primary	HIGH	\$ 5,000
CD1692	Enmore road	Newtown	State Road	crossing deficiency	narrow kerb ramp - pair	-33.89767	151.178392	1		install new kerb ramp - pair	NE33	Primary	HIGH	\$ 5,000
CD1693	King Street	Newtown	State Road	crossing deficiency	narrow kerb ramp - pair	-33.897873	151.178511	1		consult with City of Sydney and TNSW	NE47	Primary	HIGH	\$ -
CD1712	Alice Street	Newtown	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.894867	151.173315	1		install new kerb ramp	NE23	Primary	HIGH	\$ 2,500
CD1713	Australia Street	Newtown	Local Road	crossing deficiency	missing kerb ramp - pair	-33.897184	151.178517	1		install new kerb ramp - pair	NE12	Primary	HIGH	\$ 5,000
CD1714	Australia Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896019	151.178057	1		install new kerb ramp	NE13	Primary	HIGH	\$ 2,500
CD1715	Belford Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.897515	151.178004	1		install new kerb ramp	NE15	Primary	HIGH	\$ 2,500
CD1722	Smidmore Street	Newtown	Local Road	crossing deficiency	steep kerb ramp	-33.907496	151.174508	1		install new kerb ramp - pair	NE29	Primary	HIGH	\$ 5,000
CD1723	Edgeware Road	Newtown	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.904875	151.173284	1		install new kerb ramp	NE23	Primary	HIGH	\$ 2,500
CD1724	Edgeware Road	Newtown	Regional Road	crossing deficiency	steep kerb ramp	-33.905084	151.173292	1		install new kerb ramp - pair	NE24	Primary	HIGH	\$ 5,000
CD1725	Enmore Road	Newtown	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898467	151.176463	1		install new kerb ramp - pair	NE35	Primary	HIGH	\$ 5,000
CD1726	Station Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898554	151.176408	1		install new kerb ramp - pair	NE38	Primary	HIGH	\$ 5,000
CD1727	Enmore Road	Newtown	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898527	151.176501	1		install new kerb ramp - pair	NE38	Primary	HIGH	\$ 5,000
CD1730	Phillip Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.898794	151.173933	1		install new kerb ramp	NE37	Primary	HIGH	\$ 2,500
CD1731	Enmore Road	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.897768	151.178399	1		install new kerb ramp	NE39	Primary	HIGH	\$ 2,500
CD1733	Holt Street	Newtown	Local Road	crossing deficiency	missing kerb ramp - pair	-33.900155	151.177624	1		install new kerb ramp - pair	NE38	Primary	HIGH	\$ 5,000
CD1735	King Street	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.902783	151.179362	1		install new kerb ramp	NE52	Primary	HIGH	\$ 2,500
CD1736	King Street	Newtown	State Road	crossing deficiency	misaligned kerb ramp	-33.898532	151.177837	1		install new kerb ramp	NE48	Primary	HIGH	\$ 2,500
CD1737	King Street	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.906863	151.180328	1		install new kerb ramp	NE49	Primary	HIGH	\$ 2,500
CD1738	King Street	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.905915	151.181008	1		install new kerb ramp	NE47	Primary	HIGH	\$ 2,500
CD1739	Darley Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90593	151.180978	1		install new kerb ramp	NE56	Primary	HIGH	\$ 2,500
CD1740	Wells Street	Newtown	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905177	151.180691	1		install new kerb ramp - pair	NE58	Primary	HIGH	\$ 5,000
CD1741	Holmwood Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903892	151.179951	1		install new kerb ramp	NE54	Primary	HIGH	\$ 2,500
CD1742	King Street	Newtown	State Road	crossing deficiency	missing crossing point	-33.902984	151.179507	1		consult with City of Sydney	NE53	Primary	HIGH	\$ -
CD1747	Lord Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907569	151.177678	1		install new kerb ramp	NE28	Primary	HIGH	\$ 2,500
CD1748	Lord Street	Newtown	Local Road	crossing deficiency	at grade crossing missing tgi	-33.906855	151.180778	1		install new Tactile Ground Surface Indicators	NE22	Primary	HIGH	\$ 650
CD1749	Lord Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.906782	151.180811	1		install new kerb ramp	NE22	Primary	HIGH	\$ 2,500
CD175	Rose Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876314	151.172976	1		install new kerb ramp - pair	AN46	Primary	HIGH	\$ 5,000
CD176	Rose Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.876346	151.172989	1		install new Tactile Ground Surface Indicators	AN45	Primary	HIGH	\$ 650
CD1765	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894672	151.154162	1		install new kerb ramp	PE46	Primary	HIGH	\$ 2,500
CD1766	Audley Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895301	151.154311	1		install new kerb ramp	PE46	Primary	HIGH	\$ 2,500
CD177	Piper Street North	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878378	151.172188	1		install new kerb ramp	AN48	Primary	HIGH	\$ 2,500
CD1772	Crystal Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88405	151.157288	1		install new kerb ramp	PE6	Primary	HIGH	\$ 2,500
CD1778	Elswick Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88925	151.158528	1		install new kerb ramp	PE17	Primary	HIGH	\$ 2,500
CD1779	Queen Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888306	151.15893	1		install new kerb ramp	PE12	Primary	HIGH	\$ 2,500
CD178	Piper Street South	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.878763	151.172017	1		install new kerb ramp	AN45	Primary	HIGH	\$ 2,500
CD1780	Margaret Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890777	151.158727	1		install new kerb ramp	PE17	Primary	HIGH	\$ 2,500
CD1781	Corunna Road	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890675	151.158576	1		install new kerb ramp	PE16	Primary	HIGH	\$ 2,500
CD1786	McRae Street	Petersham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.900593	151.155334	1		install new Tactile Ground Surface Indicators	PE27	Primary	HIGH	\$ 650
CD1787	Johnston Street	Annandale	State Road	crossing deficiency	narrow kerb ramp	-33.878025	151.172291	1		install new kerb ramp	AN45	Primary	HIGH	\$ 2,500
CD1790	Morgan Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.898847	151.153443	1		install new kerb ramp	PE25	Primary	HIGH	\$ 2,500
CD1791	McRae Street	Petersham	Local Road	crossing deficiency	long crossing point	-33.90062	151.153533	1		install kerb extension / refuge island	PE27	Primary	HIGH	\$ 10,000
CD1792	West Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898869	151.153384	1		install new kerb ramp - pair	PE38	Primary	HIGH	\$ 5,000
CD1793	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896191	151.154171	1		install new kerb ramp	PE38	Primary	HIGH	\$ 2,500
CD1794	Audley Street	Petersham	Local Road	crossing deficiency	narrow kerb ramp	-33.896182	151.154188	1		install new kerb ramp	PE38	Primary	HIGH	\$ 2,500
CD1795	New Canterbury Road	Petersham	State Road	crossing deficiency	narrow kerb ramp	-33.896209	151.154183	1		install new kerb ramp	PE31	Primary	HIGH	\$ 2,500
CD1796	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896214	151.154193	1		install new kerb ramp	PE31	Primary	HIGH	\$ 2,500
CD1797	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896546	151.152492	1		install new kerb ramp - pair	PE33	Primary	HIGH	\$ 5,000
CD1798	Gordon Street	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896582	151.152424	1		install new kerb ramp	PE34	Primary	HIGH	\$ 2,500
CD1799	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896593	151.152438	1		install new kerb ramp - pair	PE34	Primary	HIGH	\$ 2,500
CD1800	New Canterbury Road	Petersham	State Road	crossing deficiency	missing kerb ramp	-33.897007	151.151497	1		install new kerb ramp	PE28	Primary	HIGH	\$ 2,500
CD1801	Livingstone Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896617	151.152519	1		install new kerb ramp - pair	PE23	Primary	HIGH	\$ 5,000
CD1802	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896586	151.152572	1		install new kerb ramp	PE23	Primary	HIGH	\$ 2,500
CD1803	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896254	151.154162	1		install new kerb ramp - pair	AN20	Primary	HIGH	\$ 5,000
CD181	Johnston Street	Annandale	State Road	crossing deficiency	poor kerb ramp alignment	-33.881396	151.17028	1		install new kerb ramp	AN20	Primary	HIGH	\$ 2,500
CD1813	Palace Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.892797	151.154338	1		install new kerb ramp	PE43	Primary	HIGH	\$ 2,500
CD1814	Palace Street	Petersham	Local Road	crossing deficiency	missing kerb ramp	-33.892894	151.154338	1		install new kerb ramp	PE43	Primary	HIGH	\$ 2,500

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1829	Panramatta Road	Petersham	State Road	crossing deficiency	bollard narrow crossing	-33.888486	151.156691	1		relocate bollard	LH141	Primary	HIGH	\$ 2,500
CD1840	New Canterbury Road	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895657	151.156775	1		install new kerb ramp	PE28	Primary	HIGH	\$ 2,500
CD1842	Marshall Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896702	151.160209	1		install new kerb ramp - pair	PE35	Primary	HIGH	\$ 5,000
CD1843	Marshall Lane	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895225	151.160592	1		install new kerb ramp	PE55	Primary	HIGH	\$ 2,500
CD1844	Terminus Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893548	151.1543	1		install new kerb ramp - pair	PE59	Primary	HIGH	\$ 5,000
CD1845	Terminus Street	Petersham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893596	151.157152	1		install new Tactile Ground Surface Indicators	PE58	Primary	HIGH	\$ 5,000
CD1849	Trafalgar Street	Petersham	Regional Road	crossing deficiency	missing crossing point	-33.894883	151.151447	1		install new kerb ramp - pair	PE22	Primary	HIGH	\$ 5,000
CD1850	Trafalgar Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894894	151.152744	1		install new kerb ramp - pair	PE63	Primary	HIGH	\$ 5,000
CD1851	Trafalgar Street	Petersham	Regional Road	crossing deficiency	poor crossing alignment	-33.894612	151.154081	1		re-align crossing and refuge island	PE62	Primary	HIGH	\$ 6,000
CD1855	West Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.893722	151.150451	1		install new kerb ramp	PE65	Primary	HIGH	\$ 2,500
CD1856	West Street	Petersham	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.892397	151.149872	1		install new Tactile Ground Surface Indicators	LW42	Primary	HIGH	\$ 650
CD1857	West Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.893281	151.150413	1		install new kerb ramp	PE66	Primary	HIGH	\$ 2,500
CD1861	Ellen Street	Rozelle	Local Road	crossing deficiency	narrow kerb ramp	-33.864073	151.171397	1		install new kerb ramp	RO76	Primary	HIGH	\$ 2,500
CD1863	Darling Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.863095	151.170142	1		install new kerb ramp	RO24	Primary	HIGH	\$ 2,500
CD1864	Darling Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.863122	151.170439	1		install new Tactile Ground Surface Indicators	RO24	Primary	HIGH	\$ 650
CD1865	Darling Street	Rozelle	Regional Road	crossing deficiency	misaligned kerb ramp	-33.861614	151.17138	1		install new kerb ramp	RO22	Primary	HIGH	\$ 2,500
CD1866	Darling Street	Rozelle	Regional Road	crossing deficiency	missing crossing point	-33.862055	151.171763	1		install new kerb ramp - pair	RO21	Primary	HIGH	\$ 5,000
CD1867	Norman Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859975	151.171782	1		install new kerb ramp	RO21	Primary	HIGH	\$ 2,500
CD1868	Darling Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.858868	151.172067	1		install new Tactile Ground Surface Indicators	RO19	Primary	HIGH	\$ 650
CD1870	Nelson Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.861812	151.171307	1		install new kerb ramp	RO23	Primary	HIGH	\$ 2,500
CD1871	Nelson Street	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgi	-33.861814	151.170807	1		install new Tactile Ground Surface Indicators	RO24	Primary	HIGH	\$ 650
CD1872	Victoria Road	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.863807	151.170271	1		install new kerb ramp	RO24	Primary	HIGH	\$ 2,500
CD1873	Waterloo Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.864519	151.1699	1		install new kerb ramp	RO26	Primary	HIGH	\$ 2,500
CD1874	Darling Street	Rozelle	State Road	crossing deficiency	at grade crossing missing tgi	-33.865368	151.167519	1		install new Tactile Ground Surface Indicators	RO27	Primary	HIGH	\$ 650
CD1875	Darling Street	Rozelle	State Road	crossing deficiency	at grade crossing missing tgi	-33.865599	151.167182	1		install new Tactile Ground Surface Indicators	RO27	Primary	HIGH	\$ 650
CD1889	Hercules Street	Ashfield	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.888783	151.124952	1		install new kerb ramp - pair	AF21	Primary	HIGH	\$ 5,000
CD1919	Nelson Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884205	151.172820	1		install new kerb ramp - pair	AN7	Primary	HIGH	\$ 5,000
CD1919	Liverpool Road	Ashfield	State Road	crossing deficiency	narrow kerb ramp - pair	-33.888653	151.124486	1		install new kerb ramp - pair	AF103	Primary	HIGH	\$ 5,000
CD1919	Liverpool Road	Ashfield	State Road	crossing deficiency	narrow kerb ramp - pair	-33.888787	151.124863	1		relocate crossing - signals	AF104	Primary	HIGH	\$ 20,000
CD1961	Victoria Road	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.863712	151.170109	1		install new kerb ramp	RO24	Primary	HIGH	\$ 2,500
CD1963	Victoria Road	Rozelle	State Road	crossing deficiency	at grade crossing missing tgi	-33.863849	151.169503	1		install new Tactile Ground Surface Indicators	RO26	Primary	HIGH	\$ 650
CD1964	Wellington Street	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.862799	151.168724	1		install new kerb ramp - pair	RO80	Primary	HIGH	\$ 5,000
CD1965	Victoria Road	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.862898	151.168732	1		install new kerb ramp	RO80	Primary	HIGH	\$ 2,500
CD1967	Victoria Road	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.866004	151.172879	1		install new kerb ramp	RO72	Primary	HIGH	\$ 2,500
CD1961	Mackenzie Street	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865586	151.172893	1		install new kerb ramp - pair	RO72	Primary	HIGH	\$ 5,000
CD1962	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865219	151.172293	1		install new kerb ramp - pair	RO72	Primary	HIGH	\$ 5,000
CD1963	Ellen Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.864843	151.171605	1		install new kerb ramp - pair	RO76	Primary	HIGH	\$ 5,000
CD1964	Prosper Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.864578	151.171276	1		install new kerb ramp - pair	RO76	Primary	HIGH	\$ 5,000
CD1965	Whitcombe Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.864773	151.171073	1		install new kerb ramp	RO76	Primary	HIGH	\$ 2,500
CD1969	Wise Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.860495	151.170842	1		install new kerb ramp	RO67	Primary	HIGH	\$ 2,500
CD1970	Wise Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.860564	151.171016	1		install new kerb ramp - pair	RO67	Primary	HIGH	\$ 5,000
CD1972	Cambell Street	St Peters	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.912505	151.179202	1		install new kerb ramp	SP16	Primary	HIGH	\$ 2,500
CD1976	Edith Street	St Peters	Local Road	crossing deficiency	missing kerb ramp	-33.914608	151.175473	1		install new kerb ramp	SP21	Primary	HIGH	\$ 2,500
CD1977	Goodsell Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907901	151.181247	1		install new kerb ramp - pair	SP11	Primary	HIGH	\$ 5,000
CD1978	King Street	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907969	151.181397	1		consult with City of Sydney	SP10	Primary	HIGH	\$ 5,000
CD1979	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment	-33.912891	151.179219	1		install new kerb ramp	SP16	Primary	HIGH	\$ 2,500
CD1980	Grove Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.916225	151.173136	1		install new kerb ramp - pair	SP24	Primary	HIGH	\$ 5,000
CD1982	Short Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.910967	151.180107	1		install new kerb ramp	SP9	Primary	HIGH	\$ 2,500
CD1963	May Street	St Peters	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.908881	151.181007	1		install new kerb ramp - pair	SP12	Primary	HIGH	\$ 5,000
CD1984	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912853	151.179254	1		install new kerb ramp - pair	SP16	Primary	HIGH	\$ 5,000
CD1995	Victoria Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913249	151.178906	1		install new kerb ramp - pair	SP17	Primary	HIGH	\$ 5,000
CD1986	Bishop Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913755	151.17835	1		install new kerb ramp - pair	SP18	Primary	HIGH	\$ 5,000
CD1997	Edith Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.914957	151.175744	1		install new kerb ramp - pair	SP21	Primary	HIGH	\$ 5,000
CD1998	Silver Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.914811	151.178419	1		install new kerb ramp - pair	SP20	Primary	HIGH	\$ 5,000
CD1999	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914751	151.177405	1		install new kerb ramp - pair	SP19	Primary	HIGH	\$ 5,000
CD200	Nelson Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884121	151.176267	1		install new Tactile Ground Surface Indicators	AN21	Primary	HIGH	\$ 650
CD2000	Victoria Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913279	151.17844	1		install new kerb ramp - pair	SP17	Primary	HIGH	\$ 5,000
CD2001	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912485	151.179035	1		install new kerb ramp - pair	SP16	Primary	HIGH	\$ 5,000
CD2002	Princes Highway	St Peters	State Road	crossing deficiency	missing kerb ramp	-33.908808	151.181189	1		install new kerb ramp	SP12	Primary	HIGH	\$ 2,500
CD2003	Princes Highway	St Peters	State Road	crossing deficiency	misaligned refuge island	-33.908812	151.181207	1		consult with City of Sydney	SP12	Primary	HIGH	\$ 2,500
CD2013	Douglas Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894079	151.164246	1		install new kerb ramp	SM34	Primary	HIGH	\$ 2,500
CD2014	Douglas Street	Stammore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.894068	151.164151	1		install new kerb ramp	SM34	Primary	HIGH	\$ 2,500
CD2016	Bruce Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893551	151.161842	1		install new kerb ramp - pair	SM12	Primary	HIGH	\$ 5,000
CD2017	Bruce Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893427	151.161524	1		install new kerb ramp	SM12	Primary	HIGH	\$ 2,500
CD2018	Bruce Lane East	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.8936	151.162057	1		install new kerb ramp	SM12	Primary	HIGH	\$ 2,500
CD2019	Gordon Crescent	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.89423	151.162039	1		install new kerb ramp	SM12	Primary	HIGH	\$ 2,500
CD2022	Holt Street	Stammore	Local Road	crossing deficiency	at grade crossing missing tgi	-33.896307	151.163672	1		install new Tactile Ground Surface Indicators	SM35	Primary	HIGH	\$ 650
CD2023	Holt Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896008	151.163839	1		install new kerb ramp	SM35	Primary	HIGH	\$ 2,500
CD2024	Holt Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.895829	151.163787	1		install new kerb ramp	SM35	Primary	HIGH	\$ 2,500
CD2025	Holt Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895868	151.163787	1		install new kerb ramp	SM35	Primary	HIGH	\$ 2,500
CD2039	Panarama Road	Stammore	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888095	151.161447	1		install new kerb ramp - pair	LH145	Primary	HIGH	\$ 5,000
CD2040	Canon Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888329	151.162998	1		install new kerb ramp - pair	AN73	Primary	HIGH	\$ 5,000
CD2043	Perivola Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.892981	151.164141	1		install new kerb ramp	SM42	Primary	HIGH	\$ 2,500
CD2044	Perivola Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893529	151.164249	1		install new kerb ramp	SM33	Primary	HIGH	\$ 2,500
CD2045	Perivola Road	Stammore	Local Road	crossing deficiency	misaligned refuge island	-33.890778	151.165047	1		re-construct refuge island	SM30	Primary	HIGH	\$ 15,000
CD2046	Perivola Road	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.890632	151.165033	1		install new kerb ramp	SM29	Primary	HIGH	\$ 2,500
CD2047	Perivola Road	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.890538	151.165144	1		install new kerb ramp	SM29	Primary	HIGH	\$ 2,500
CD2049	Perivola Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893323	151.164446	1		install new kerb ramp	SM48	Primary	HIGH	\$ 2,500
CD2055	Railway Avenue	Stammore	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893737	151.166522	1		install new Tactile Ground Surface Indicators	SM36	Primary	HIGH	\$ 650
CD2056	Railway Avenue	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.893604	151.165597	1		install new kerb ramp	SM36	Primary	HIGH	\$ 2,500
CD2057	Sallybury Road	Stammore	Regional Road	crossing deficiency	misaligned kerb ramp	-33.892694	151.165874	1		install new kerb ramp	SM42	Primary	HIGH	\$ 2,500
CD2058	Myrtle Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89258	151.16515	1		install new kerb ramp	SM42	Primary	HIGH	\$ 2,500
CD2060	Myrtle Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.892474	151.165318	1		install new kerb ramp	SM47	Primary	HIGH	\$ 2,500
CD2060	Myrtle Lane	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.892088	151.167277	1		install new kerb ramp	SM46	Primary	HIGH	\$ 2,500
CD2061	Sallybury Road	Stammore	Regional Road	crossing deficiency	misaligned kerb ramp	-33.891757	151.168003	1		install new kerb ramp	SM46	Primary	HIGH	\$ 2,500
CD2064	Sallybury Road	Stammore	Regional Road	crossing deficiency	narrow refuge island	-33.891809	151.168042	1		install new refuge island	SM46	Primary	HIGH	\$ 15,000
CD2067	Stammore Road	Stammore	Local Road	crossing deficiency	deep kerb ramp	-33.896481	151.163203	1		install new kerb ramp - pair	SM43	Primary	HIGH	\$ 5,000
CD2068	Middleton Street	Stammore	Local Road	cross										

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD21	Parramatta Road	Annandale	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.8868	151.176498	1		install new kerb ramp - pair	CA23	Primary	HIGH	\$ 5,000
CD2101	Liverpool Road	Summer Hill	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88753	151.136898	1		install new kerb ramp - pair	SH47	Primary	HIGH	\$ 5,000
CD2105	Norton Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.881419	151.132335	1		install new kerb ramp - pair	AF118	Primary	HIGH	\$ 5,000
CD2110	Junction Lane	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.895861	151.138048	1		install new Tactile Ground Surface Indicators - pair	SH56	Primary	HIGH	\$ 1,300
CD2111	Old Canterbury Road	Summer Hill	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895668	151.138512	1		install new kerb ramp - pair	SH56	Primary	HIGH	\$ 5,000
CD2115	Edward Street	Summer Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.895599	151.141741	1		install new kerb ramp	DH100	Primary	HIGH	\$ 2,500
CD2116	Edward Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp	-33.8954	151.141673	1		install new kerb ramp	DH100	Primary	HIGH	\$ 2,500
CD2117	Old Canterbury Road	Summer Hill	State Road	crossing deficiency	missing crossing point	-33.895442	151.141705	1		further investigation required - refuge	DH100	Primary	HIGH	\$ 10,000
CD2118	Edward Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895401	151.141637	1		install new kerb ramp - pair	DH100	Primary	HIGH	\$ 5,000
CD212	Alt Street	Ashfield	Local Road	crossing deficiency	narrow refuge island	-33.885511	151.123035	1		install new refuge island	AF54	Primary	HIGH	\$ 15,000
CD2120	Sloane Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887665	151.141684	1		install new kerb ramp - pair	SH77	Primary	HIGH	\$ 5,000
CD2121	Dover Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889506	151.144304	1		install new kerb ramp - pair	HA65	Primary	HIGH	\$ 5,000
CD2130	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900763	151.132035	1		install new kerb ramp - pair	AF128	Primary	HIGH	\$ 5,000
CD2131	Sloane Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890626	151.139224	1		install new kerb ramp - pair	SH78	Primary	HIGH	\$ 5,000
CD2132	Sloane Street	Summer Hill	Local Road	crossing deficiency	long crossing	-33.88956	151.139503	1		install kerb blisters/ build outs	SH78	Primary	HIGH	\$ 10,000
CD2134	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891658	151.137215	1		install new kerb ramp - pair	SH84	Primary	HIGH	\$ 5,000
CD2135	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894441	151.134049	1		install new kerb ramp	SH85	Primary	HIGH	\$ 2,500
CD2151	Smith Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.8917	151.137074	1		install new Tactile Ground Surface Indicators - pair	SH84	Primary	HIGH	\$ 1,300
CD2152	Smith Street	Summer Hill	Local Road	crossing deficiency	missing crossing point	-33.891783	151.138114	1		install new kerb ramp - pair	SH49	Primary	HIGH	\$ 5,000
CD2153	Unwins Bridge Road	Sydenham	Regional Road	crossing deficiency	missing kerb ramp	-33.916462	151.166629	1		install new kerb ramp	SV7	Primary	HIGH	\$ 2,500
CD2165	Burrows Avenue	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915332	151.166163	1		install new kerb ramp - pair	SV5	Primary	HIGH	\$ 5,000
CD2167	Burrows Avenue	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915293	151.166124	1		install new kerb ramp - pair	SV5	Primary	HIGH	\$ 5,000
CD2168	Gleasons Avenue	Sydenham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915176	151.166105	1		install new kerb ramp - pair	SV5	Primary	HIGH	\$ 5,000
CD2164	Reels Lane	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.916362	151.170215	1		install new kerb ramp - pair	SP28	Primary	HIGH	\$ 5,000
CD2168	Rowe Lane	Sydenham	Local Road	crossing deficiency	steep kerb ramp	-33.916798	151.166665	1		install new kerb ramp - pair	SV7	Primary	HIGH	\$ 5,000
CD2169	Unwins Bridge Road	Sydenham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.916422	151.166363	1		install new kerb ramp	SV13	Primary	HIGH	\$ 2,500
CD2170	Cook Street	Tempe	Local Road	crossing deficiency	missing kerb ramp	-33.926554	151.156189	1		install new kerb ramp	TE34	Primary	HIGH	\$ 2,500
CD2171	Cook Street	Tempe	Local Road	crossing deficiency	missing kerb ramp - pair	-33.926535	151.156194	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2178	Union Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.923411	151.162336	1		install new kerb ramp	TE12	Primary	HIGH	\$ 2,500
CD2179	Wentworth Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924775	151.160733	1		install new kerb ramp	TE6	Primary	HIGH	\$ 2,500
CD218	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891628	151.123047	1		install new kerb ramp - pair	AF53	Primary	HIGH	\$ 2,500
CD2180	Wentworth Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924864	151.160776	1		install new kerb ramp	TE6	Primary	HIGH	\$ 2,500
CD2181	Fanning Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924497	151.161301	1		install new kerb ramp	TE13	Primary	HIGH	\$ 2,500
CD2189	Brooklyn Street	Tempe	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.922749	151.163038	1		install new kerb ramp - pair	TE5	Primary	HIGH	\$ 5,000
CD219	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891767	151.123038	1		install new kerb ramp - pair	AF53	Primary	HIGH	\$ 5,000
CD2191	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment	-33.923549	151.162357	1		install new kerb ramp	TE12	Primary	HIGH	\$ 2,500
CD2192	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment	-33.924214	151.161524	1		install new kerb ramp	TE13	Primary	HIGH	\$ 2,500
CD2193	Barden Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.923994	151.161711	1		install new kerb ramp	TE13	Primary	HIGH	\$ 2,500
CD2194	Smith Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.923424	151.162467	1		install new kerb ramp - pair	TE5	Primary	HIGH	\$ 5,000
CD2197	Bay Street	Tempe	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.926789	151.158887	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2198	Holbeck Avenue	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.92656	151.156771	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2199	Bay Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.926516	151.158605	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2208	View Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.926619	151.158123	1		install new kerb ramp	TE34	Primary	HIGH	\$ 2,500
CD228	Brown Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.887628	151.126022	1		further investigation required - refuge	AF22	Primary	HIGH	\$ 10,000
CD228	Cavill Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887074	151.121993	1		install new kerb ramp	AF33	Primary	HIGH	\$ 2,500
CD229	Cavill Avenue	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.887023	151.121949	1		install new kerb ramp - pair	AF33	Primary	HIGH	\$ 5,000
CD230	Cavill Avenue	Ashfield	Local Road	crossing deficiency	at grade crossing missing tpsl	-33.887113	151.12196	1		install new Tactile Ground Surface Indicators	AF33	Primary	HIGH	\$ 650
CD231	Charlotte Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88502	151.12697	1		install new kerb ramp - pair	AF35	Primary	HIGH	\$ 5,000
CD251	Granger Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88707	151.126729	1		install new kerb ramp - pair	AF52	Primary	HIGH	\$ 5,000
CD252	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.886706	151.125812	1		install new kerb ramp	AF59	Primary	HIGH	\$ 5,000
CD253	Charlotte Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88668	151.12596	1		install new kerb ramp	AF39	Primary	HIGH	\$ 2,500
CD254	Bland Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.886198	151.12486	1		install new kerb ramp	AF17	Primary	HIGH	\$ 2,500
CD255	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886319	151.124889	1		install new kerb ramp - pair	AF59	Primary	HIGH	\$ 5,000
CD256	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.886205	151.124785	1		install new kerb ramp - pair	AF60	Primary	HIGH	\$ 5,000
CD257	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	crossing within roundabout	-33.885462	151.125171	1		install new kerb ramp - pair	AF10	Primary	HIGH	\$ 5,000
CD258	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.885207	151.12317	1		install new kerb ramp - pair	AF53	Primary	HIGH	\$ 5,000
CD259	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.885424	151.122952	1		install new kerb ramp - pair	AF54	Primary	HIGH	\$ 5,000
CD261	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88632	151.12481	1		install new kerb ramp - pair	AF16	Primary	HIGH	\$ 5,000
CD262	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886223	151.124914	1		install new kerb ramp	AF17	Primary	HIGH	\$ 2,500
CD263	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing refuge island	-33.885458	151.123144	1		install new refuge island	AF53	Primary	HIGH	\$ 15,000
CD264	Alt Street	Ashfield	Local Road	crossing deficiency	missing refuge island	-33.885385	151.12313	1		install new refuge island	AF10	Primary	HIGH	\$ 15,000
CD265	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing refuge island	-33.885368	151.122983	1		install new refuge island	AF54	Primary	HIGH	\$ 15,000
CD267	Beatrice Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887249	151.11943	1		install new kerb ramp	AF67	Primary	HIGH	\$ 5,000
CD268	Frederick Street	Ashfield	State Road	crossing deficiency	missing kerb ramp - pair	-33.88573	151.119161	1		install new kerb ramp - pair, new refuge island	AF77	Primary	HIGH	\$ 7,000
CD269	Henry Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tpsl	-33.877949	151.127512	1		install new Tactile Ground Surface Indicators	AF69	Primary	HIGH	\$ 650
CD271	Frederick Street	Ashfield	State Road	crossing deficiency	at grade crossing missing tpsl	-33.878623	151.12544	1		install new Tactile Ground Surface Indicators	AF69	Primary	HIGH	\$ 650
CD272	John Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.879862	151.123535	1		install new kerb ramp	AF70	Primary	HIGH	\$ 5,000
CD273	Hedger Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880581	151.122653	1		install new kerb ramp - pair	AF72	Primary	HIGH	\$ 5,000
CD274	Mackay Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.883177	151.120843	1		install new kerb ramp - pair	AF66	Primary	HIGH	\$ 5,000
CD275	Pound Lane	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88362	151.120517	1		install new kerb ramp - pair	AF64	Primary	HIGH	\$ 5,000
CD276	Pound Lane	Ashfield	Local Road	crossing deficiency	shallow kerb ramp - pair	-33.883603	151.120469	1		install new Tactile Ground Surface Indicators	AF66	Primary	HIGH	\$ 650
CD28	Gordon Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887243	151.174443	1		install new kerb ramp - pair	AN85	Primary	HIGH	\$ 5,000
CD281	Eccles Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883449	151.120722	1		install new kerb ramp - pair	AF66	Primary	HIGH	\$ 5,000
CD285	Henry Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.877993	151.127559	1		install new kerb ramp - pair	AF69	Primary	HIGH	\$ 5,000
CD286	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877571	151.128553	1		install new kerb ramp - pair	AF69	Primary	HIGH	\$ 5,000
CD289	Malheson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887403	151.173284	1		install new kerb ramp - pair	AN83	Primary	HIGH	\$ 5,000
CD291	Henry Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877533	151.127523	1		install new kerb ramp	AF14	Primary	HIGH	\$ 2,500
CD295	Norton Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89001	151.117135	1		install new kerb ramp - pair	AF114	Primary	HIGH	\$ 5,000
CD296	Milton Road	Ashfield	State Road	crossing deficiency	improve pedestrian access by providing additional crossing	-33.89009	151.117204	1		consult with TfNSW	AF114	Primary	HIGH	\$ 2,500
CD297	Milton Road	Ashfield	State Road	crossing deficiency	missing kerb ramp	-33.88966	151.117283	1		install new kerb ramp	AF114	Primary	HIGH	\$ 5,000
CD298	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889975	151.117287	1		install new kerb ramp - pair	AF114	Primary	HIGH	\$ 5,000
CD299	Somerville Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890549	151.11725	1		install new kerb ramp - pair	AF114	Primary	HIGH	\$ 5,000
CD300	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887533	151.171287	1		install new kerb ramp - pair	AN81	Primary	HIGH	\$ 5,000
CD306	Holten Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890453	151.125463	1		install new kerb ramp - pair	AF85	Primary	HIGH	\$ 5,000
CD309	Holten Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891772	151.125416	1		install new kerb ramp - pair	AF85	Primary	HIGH	\$ 5,000
CD310	Holten Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891037	151.125394	1		install new kerb ramp	AF85	Primary	HIGH	\$ 2,500
CD311	Holten Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891162	151.125416	1		install new kerb ramp - pair	AF85	Primary	HIGH	\$ 5,000
CD315	Hugh Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-3								

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
C0321	Liverpool Road	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.884606	151.134267	-	-	install new kerb ramp	AF05	Primary	HIGH	2,500
C0324	Gower Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887388	151.13699	-	-	install new kerb ramp	AF07	Primary	HIGH	2,500
C0325	Gower Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.887243	151.136762	-	-	install new kerb ramp	AF92	Primary	HIGH	2,500
C0326	Tidewater Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888655	151.137244	-	-	install new kerb ramp - pair	AF92	Primary	HIGH	5,000
C0328	Liverpool Road	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.890239	151.129126	-	-	install new kerb ramp	AF100	Primary	HIGH	2,500
C0329	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879477	151.125252	-	-	install new kerb ramp - pair	AF93	Primary	HIGH	5,000
C0330	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889776	151.123363	-	-	install new kerb ramp - pair	AF105	Primary	HIGH	5,000
C0331	State Street	Ashfield	State Road	crossing deficiency	narrow kerb ramp	-33.888477	151.117453	-	-	install new kerb ramp	AF01	Primary	HIGH	2,500
C0332	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890293	151.126312	-	-	install new kerb ramp - pair	AF100	Primary	HIGH	5,000
C0333	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890432	151.126239	-	-	install new kerb ramp - pair	AF150	Primary	HIGH	5,000
C0334	Liverpool Road	Ashfield	State Road	crossing deficiency	missing kerb ramp	-33.890233	151.126735	-	-	install new kerb ramp	AF100	Primary	HIGH	2,500
C0335	Commonwealth Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891191	151.130129	-	-	install new kerb ramp - pair	AF09	Primary	HIGH	5,000
C0336	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898868	151.13068	-	-	install new kerb ramp - pair	AF98	Primary	HIGH	5,000
C0339	Carlton Crescent	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895958	151.131638	-	-	install new kerb ramp - pair	AF97	Primary	HIGH	5,000
C0340	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890336	151.128161	-	-	install new kerb ramp - pair	AF150	Primary	HIGH	5,000
C0341	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890315	151.129126	-	-	install new kerb ramp - pair	AF150	Primary	HIGH	5,000
C0356	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891326	151.126006	-	-	install new kerb ramp - pair	AF123	Primary	HIGH	5,000
C0357	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891217	151.127785	-	-	install new kerb ramp - pair	AF122	Primary	HIGH	5,000
C0358	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891201	151.127465	-	-	install new kerb ramp - pair	AF122	Primary	HIGH	5,000
C0359	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89088	151.126454	-	-	install new kerb ramp - pair	AF121	Primary	HIGH	5,000
C0360	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890549	151.125529	-	-	install new kerb ramp - pair	AF121	Primary	HIGH	5,000
C0361	Abbeckett Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889624	151.123768	-	-	install new kerb ramp	AF120	Primary	HIGH	2,500
C0362	Abbeckett Avenue	Ashfield	Local Road	crossing deficiency	long crossing	-33.889632	151.123635	-	-	install kerb extension - pair	AF120	Primary	HIGH	20,000
C0363	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889355	151.122597	-	-	install new kerb ramp - pair	AF119	Primary	HIGH	5,000
C0364	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.889387	151.122789	-	-	install new kerb ramp	AF119	Primary	HIGH	2,500
C0365	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890461	151.125458	-	-	install new kerb ramp - pair	AF117	Primary	HIGH	5,000
C0366	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890457	151.125573	-	-	install new kerb ramp - pair	AF121	Primary	HIGH	5,000
C0367	Norton Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891505	151.131116	-	-	install new kerb ramp - pair	AF125	Primary	HIGH	5,000
C0368	Norton Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891404	151.130186	-	-	install new kerb ramp	AF125	Primary	HIGH	2,500
C0369	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891371	151.130186	-	-	install new kerb ramp - pair	AF124	Primary	HIGH	5,000
C0370	Franks Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903895	151.129081	-	-	install new kerb ramp - pair	AF130	Primary	HIGH	5,000
C0373	Orrington Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88667	151.128623	-	-	install new kerb ramp - pair	AF133	Primary	HIGH	5,000
C0387	Querr Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89121	151.128029	-	-	install new kerb ramp - pair	AF130	Primary	HIGH	5,000
C0390	Station Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.887407	151.126423	-	-	install new kerb ramp - pair	AF138	Primary	HIGH	5,000
C0395	The Esplanade	Ashfield	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.887542	151.124052	-	-	install new Traffic Ground Surface Indicators	AF32	Primary	HIGH	60,000
C0400	Tidewater Street	Ashfield	Local Road	crossing deficiency	long crossing	-33.886687	151.137366	-	-	install kerb extension - pair	AF92	Primary	HIGH	25,000
C0401	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892038	151.127688	-	-	install new kerb ramp - pair	AF169	Primary	HIGH	5,000
C0438	Brinborough Road	Balmain	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.853435	151.177544	-	-	install new Traffic Ground Surface Indicators	BA46	Primary	HIGH	650
C0439	Booth Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.858247	151.16221	-	-	install new Traffic Ground Surface Indicators	BA13	Primary	HIGH	650
C0442	Booth Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860449	151.161911	-	-	install new kerb ramp	BA16	Primary	HIGH	2,500
C0443	Curtis Road	Balmain	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.858959	151.163920	-	-	install new kerb ramp - pair	BA16	Primary	HIGH	5,000
C0444	Curtis Road	Balmain	Local Road	crossing deficiency	missing crossing point	-33.857193	151.163256	-	-	install new kerb ramp - pair	BA20	Primary	HIGH	2,500
C0455	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.857011	151.163293	-	-	install new kerb ramp - pair	BA20	Primary	HIGH	5,000
C0456	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858186	151.172063	-	-	install new kerb ramp	BA20	Primary	HIGH	2,500
C0462	Lawson Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.857433	151.172465	-	-	install new kerb ramp	BA37	Primary	HIGH	5,000
C0463	High Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858236	151.172192	-	-	install new kerb ramp	RO19	Primary	HIGH	5,000
C0464	Darling Street	Balmain	Local Road	crossing deficiency	long crossing point	-33.858145	151.164967	-	-	install new refuge island	BA27	Primary	HIGH	15,000
C0465	Darling Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858181	151.164957	-	-	install new kerb ramp - pair	BA27	Primary	HIGH	5,000
C0466	Darling Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858105	151.166146	-	-	install new kerb ramp - pair	BA26	Primary	HIGH	5,000
C0467	Darling Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858167	151.167043	-	-	install new kerb ramp	BA26	Primary	HIGH	2,500
C0468	Darling Street	Balmain	Local Road	crossing deficiency	steep kerb ramp	-33.858204	151.168228	-	-	install new kerb ramp	BA26	Primary	HIGH	5,000
C0469	Darling Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858294	151.165526	-	-	install new kerb ramp - pair	BA26	Primary	HIGH	5,000
C0470	Darling Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857952	151.162786	-	-	install new kerb ramp	BA28	Primary	HIGH	5,000
C0471	Lawson Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857467	151.172421	-	-	install new kerb ramp	BA37	Primary	HIGH	2,500
C0472	Lawson Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858046	151.163255	-	-	install new kerb ramp	BA39	Primary	HIGH	2,500
C0473	Eaton Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.85838	151.183757	-	-	install new kerb ramp	BA40	Primary	HIGH	2,500
C0474	Eaton Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.85871	151.183763	-	-	install new Traffic Ground Surface Indicators - pair	BA40	Primary	HIGH	1,300
C0475	Eaton Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.858989	151.183868	-	-	install new kerb ramp	BA40	Primary	HIGH	2,500
C0476	Eaton Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.858985	151.183796	-	-	install new kerb ramp	BA40	Primary	HIGH	5,000
C0484	Jane Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.858788	151.184383	-	-	install new Traffic Ground Surface Indicators - pair	BA44	Primary	HIGH	1,300
C0495	Jane Street	Balmain	Local Road	crossing deficiency	missing kerb ramp - pair	-33.858786	151.184452	-	-	install new kerb ramp - pair	BA44	Primary	HIGH	5,000
C0496	Jane Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.858783	151.184428	-	-	install new kerb ramp	BA44	Primary	HIGH	2,500
C0497	Macquarie Terrace	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.853896	151.176066	-	-	install new kerb ramp - pair	BA46	Primary	HIGH	5,000
C0498	Macquarie Terrace	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.854036	151.176235	-	-	install new kerb ramp - pair	BA46	Primary	HIGH	5,000
C0507	Reynolds Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.861004	151.176643	-	-	install new kerb ramp	BA80	Primary	HIGH	2,500
C0508	Reynolds Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.861277	151.176761	-	-	install new kerb ramp	BA80	Primary	HIGH	2,500
C0509	Reynolds Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.861252	151.176693	-	-	install new kerb ramp	BA51	Primary	HIGH	5,000
C0525	Robert Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.861326	151.177112	-	-	install new kerb ramp	BA80	Primary	HIGH	2,500
C0526	Robert Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854543	151.176569	-	-	install new kerb ramp	BA86	Primary	HIGH	2,500
C0535	Wortley Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861451	151.177142	-	-	install new kerb ramp - pair	BA80	Primary	HIGH	5,000
C0547	Darling Street	Balmain East	Local Road	crossing deficiency	steep kerb ramp	-33.857762	151.190509	-	-	install new kerb ramp - pair	BE9	Primary	HIGH	5,000
C0548	Darling Street	Balmain East	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857321	151.190599	-	-	install new kerb ramp	BE2	Primary	HIGH	2,500
C0549	Darling Street	Balmain East	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857214	151.194196	-	-	install new kerb ramp	BE2	Primary	HIGH	2,500
C0550	Darling Street	Balmain East	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.857127	151.195332	-	-	install new kerb ramp - pair	BE1	Primary	HIGH	5,000
C0582	Tooths Place	Camdenpool	Local Road	crossing deficiency	misaligned kerb ramp	-33.898865	151.176241	-	-	install new kerb ramp	CA12	Primary	HIGH	2,500
C0583	Camdenpool Lane	Camdenpool	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89742	151.176875	-	-	install new kerb ramp	CA11	Primary	HIGH	2,500
C0584	Cardigan Street	Camdenpool	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89753	151.172953	-	-	install new kerb ramp - pair	CA83	Primary	HIGH	5,000
C0585	Parramatta Road	Camdenpool	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88748	151.173544	-	-	install new kerb ramp - pair	CA83	Primary	HIGH	5,000
C061	View Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.737995	151.174698	-	-	install new kerb ramp	AN98	Primary	HIGH	2,500
C0618	Highway Street	Croydon	Local Road	crossing deficiency	long crossing	-33.81919	151.151919	-	-	install kerb extension - pair	CR24	Primary	HIGH	20,000
C0619	Highway Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887487	151.114517	-	-	install new kerb ramp - pair	CR24	Primary	HIGH	5,000
C062	The Crescent	Annandale	State Road	crossing deficiency	potential mid block crossing point - kerb extensions	-33.674616	151.174668	-	-	consult with TNSW	AN98	Primary	HIGH	5,000
C0620	Walsh Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88783	151.115299	-	-	install new kerb ramp - pair	CR25	Primary	HIGH	5,000
C0621	Welshby Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888066	151.11547	-	-	install new kerb ramp	CR25	Primary	HIGH	2,500
C0622	Holborn Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887256	151.113883	-	-	install new kerb ramp	CR23	Primary	HIGH	2,500
C0623	Greenalls Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886928	151.112326	-	-	install new kerb ramp	CR23	Primary	HIGH	2,500
C063	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.811659	151.172193	-	-	install new kerb ramp	AN98	Primary	HIGH	5,000
C0646	Seaview Street	Dulwich Hill	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.90261	151.144686	-	-	further investigation required - pedestrian crossing	DH94	Primary	HIGH	10,000
C0670	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.902472	151.138825	-	-	install new kerb ramp	DH10	Primary	HIGH	5,000
C0674	Dulwich Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901945	151.14026	-	-	install new kerb ramp - pair	DH25	Primary	HIGH	5,000
C0675	Dulwich Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902355	151.142379	-	-	install new kerb ramp - pair	DH25	Primary	HIGH	5,000
C0679	Ewart Street	Dulwich Hill</												

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD684	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910302	151.138251	1		install new kerb ramp - pair	DH31	Primary	HIGH	\$ 5,000
CD699	Hill Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901598	151.140437	1		install new kerb ramp	DH22	Primary	HIGH	\$ 2,500
CD705	Lewisham Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tps - pair	-33.901548	151.140577	1		install new Tactile Ground Surface Indicators - pair	DH22	Primary	HIGH	\$ 1,300
CD706	MacArthur Parade	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.905445	151.144416	1		install new kerb ramp	DH79	Primary	HIGH	\$ 2,500
CD709	Dunham Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tps - pair	-33.904508	151.143419	1		install new Tactile Ground Surface Indicators - pair	DH78	Primary	HIGH	\$ 1,300
CD710	Seaview Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tps - pair	-33.904196	151.143373	1		install new Tactile Ground Surface Indicators - pair	DH78	Primary	HIGH	\$ 1,300
CD713	Yule Street	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.901632	151.144709	1		re-construct refuge island	DH84	Primary	HIGH	\$ 15,000
CD714	Marionville Road	Dulwich Hill	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.903403	151.142462	1		install new kerb ramp - pair	DH76	Primary	HIGH	\$ 5,000
CD715	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment	-33.903326	151.142496	1		install new kerb ramp	DH97	Primary	HIGH	\$ 2,500
CD716	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment	-33.903364	151.142372	1		install new kerb ramp	DH76	Primary	HIGH	\$ 2,500
CD717	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp construction	-33.90336	151.142329	1		install new kerb ramp	DH97	Primary	HIGH	\$ 2,500
CD718	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.903822	151.141053	1		install new kerb ramp - pair	DH98	Primary	HIGH	\$ 5,000
CD719	Beach Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903825	151.141054	1		install new kerb ramp	DH98	Primary	HIGH	\$ 2,500
CD720	Beach Road	Dulwich Hill	Local Road	crossing deficiency	narrow kerb ramp	-33.903971	151.140959	1		install new kerb ramp	DH98	Primary	HIGH	\$ 2,500
CD721	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.903953	151.140904	1		install new kerb ramp	DH98	Primary	HIGH	\$ 2,500
CD723	Myra Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905858	151.135932	1		install new kerb ramp	DH86	Primary	HIGH	\$ 2,500
CD724	Carnet Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.905868	151.134424	1		install new kerb ramp	DH87	Primary	HIGH	\$ 2,500
CD725	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.905213	151.133320	1		consult with City of Canterbury-Bankstown	DH89	Primary	HIGH	\$ -
CD726	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	missing kerb ramp - pair	-33.905172	151.133277	1		consult with City of Canterbury-Bankstown	DH89	Primary	HIGH	\$ -
CD729	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	missing kerb ramp	-33.905169	151.133352	1		install new kerb ramp	DH89	Primary	HIGH	\$ 2,500
CD730	Union Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905712	151.133366	1		install new kerb ramp	DH87	Primary	HIGH	\$ 2,500
CD731	Denison Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905034	151.137707	1		install new kerb ramp	DH84	Primary	HIGH	\$ 2,500
CD732	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.90302	151.140856	1		install new kerb ramp - pair	DH88	Primary	HIGH	\$ 5,000
CD733	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.903811	151.140842	1		install new kerb ramp	DH88	Primary	HIGH	\$ 2,500
CD734	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	steep kerb ramp	-33.903817	151.140856	1		install new kerb ramp - pair	DH88	Primary	HIGH	\$ 5,000
CD735	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.903803	151.141045	1		install new kerb ramp	DH88	Primary	HIGH	\$ 2,500
CD736	Dulwich Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903205	151.142379	1		install new kerb ramp	DH86	Primary	HIGH	\$ 2,500
CD737	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment	-33.903256	151.142454	1		install new kerb ramp	DH86	Primary	HIGH	\$ 2,500
CD738	Lewisham Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902944	151.143025	1		install new kerb ramp - pair	DH86	Primary	HIGH	\$ 5,000
CD739	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	narrow kerb ramp - pair	-33.902882	151.143809	1		install new kerb ramp - pair	DH86	Primary	HIGH	\$ 5,000
CD740	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903774	151.142337	1		install new kerb ramp - pair	DH86	Primary	HIGH	\$ 5,000
CD741	Flemington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89809	151.137949	1		install new kerb ramp - pair	SH56	Primary	HIGH	\$ 5,000
CD750	Hugh Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901371	151.131607	1		install new kerb ramp - pair	AF126	Primary	HIGH	\$ 5,000
CD751	Elizabeth Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902416	151.130674	1		install new kerb ramp - pair	AF128	Primary	HIGH	\$ 5,000
CD752	Cobar Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90356	151.132719	1		install new kerb ramp - pair	DH125	Primary	HIGH	\$ 5,000
CD753	Cobar Street	Dulwich Hill	Local Road	crossing deficiency	long crossing point	-33.903679	151.129653	1		install kerb extension / refuge island	AF129	Primary	HIGH	\$ 10,000
CD754	Old Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904672	151.128993	1		install new kerb ramp - pair	DH82	Primary	HIGH	\$ 5,000
CD774	Wardell Road	Dulwich Hill	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.911027	151.141173	1		install new kerb ramp - pair	DH83	Primary	HIGH	\$ 5,000
CD775	Kelth Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.910229	151.141904	1		install new kerb ramp - pair	DH125	Primary	HIGH	\$ 5,000
CD776	Margaret Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.908917	151.143231	1		install new kerb ramp - pair	DH126	Primary	HIGH	\$ 5,000
CD778	Kaye Avenue West	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.909742	151.142489	1		install new kerb ramp	DH126	Primary	HIGH	\$ 2,500
CD779	Willa Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.910246	151.142053	1		install new kerb ramp	DH125	Primary	HIGH	\$ 2,500
CD796	Lynch Avenue	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.902132	151.171895	1		install new kerb ramp	EN3	Primary	HIGH	\$ 2,500
CD798	Stannmore Road	Enmore	State Road	crossing deficiency	misaligned kerb ramp	-33.899521	151.170816	1		install new kerb ramp	EN13	Primary	HIGH	\$ 2,500
CD797	Enmore Road	Enmore	State Road	crossing deficiency	poor kerb ramp alignment	-33.899565	151.170777	1		install new kerb ramp	EN3	Primary	HIGH	\$ 2,500
CD798	Juliet Street	Enmore	Local Road	crossing deficiency	missing kerb ramp	-33.900927	151.170224	1		install new kerb ramp	MV63	Primary	HIGH	\$ 2,500
CD799	Francis Street	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900073	151.17072	1		install new kerb ramp	EN8	Primary	HIGH	\$ 2,500
CD8	Albion Lane	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887416	151.16794	1		install new kerb ramp - pair	AN55	Primary	HIGH	\$ 5,000
CD800	Edgeware Road	Enmore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.896971	151.170682	1		install new kerb ramp	EN6	Primary	HIGH	\$ 2,500
CD801	Enmore Road	Enmore	State Road	crossing deficiency	poor kerb ramp alignment	-33.896457	151.171042	1		install new kerb ramp	EN6	Primary	HIGH	\$ 5,000
CD802	Enmore Road	Enmore	State Road	crossing deficiency	misaligned kerb ramp	-33.899154	151.172057	1		install new kerb ramp	EN7	Primary	HIGH	\$ 2,500
CD803	Enmore Road	Enmore	State Road	crossing deficiency	misaligned kerb ramp	-33.898940	151.172823	1		install new kerb ramp	EN7	Primary	HIGH	\$ 2,500
CD804	Edgeware Road	Enmore	Regional Road	crossing deficiency	at grade crossing missing tps	-33.899461	151.171077	1		install new Tactile Ground Surface Indicators	EN6	Primary	HIGH	\$ 650
CD812	Stannmore Road	Enmore	State Road	crossing deficiency	poor kerb ramp alignment	-33.898889	151.169599	1		install new kerb ramp	EN13	Primary	HIGH	\$ 2,500
CD814	Tupper Street	Enmore	Local Road	crossing deficiency	misaligned kerb ramp	-33.889765	151.168652	1		install new kerb ramp	EN14	Primary	HIGH	\$ 2,500
CD816	Marion Street	Haberfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.884195	151.143674	1		further investigation required - pedestrian crossing	H460	Primary	HIGH	\$ 10,000
CD818	Ramsay Street	Haberfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.878846	151.135906	1		further investigation required - pedestrian crossing	H463	Primary	HIGH	\$ 10,000
CD837	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880468	151.138758	1		install new kerb ramp - pair	H460	Primary	HIGH	\$ 5,000
CD838	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880364	151.138885	1		install new kerb ramp - pair	H434	Primary	HIGH	\$ 5,000
CD839	Dalhousie Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tps - pair	-33.879891	151.139171	1		install new Tactile Ground Surface Indicators - pair	H434	Primary	HIGH	\$ 1,300
CD840	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877708	151.140738	1		install new kerb ramp	H432	Primary	HIGH	\$ 2,500
CD844	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878791	151.140024	1		install new kerb ramp - pair	H432	Primary	HIGH	\$ 5,000
CD845	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880494	151.138689	1		install new kerb ramp - pair	H463	Primary	HIGH	\$ 5,000
CD846	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880622	151.138851	1		install new kerb ramp - pair	H463	Primary	HIGH	\$ 5,000
CD847	Dalhousie Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tps - pair	-33.880955	151.138589	1		install new Tactile Ground Surface Indicators - pair	H435	Primary	HIGH	\$ 1,300
CD860	Hampton Parade	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.889165	151.144486	1		install kerb extension	H465	Primary	HIGH	\$ 10,000
CD862	Howthorne Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884191	151.143972	1		install new kerb ramp - pair	H461	Primary	HIGH	\$ 5,000
CD863	Marion Street	Haberfield	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884468	151.142134	1		install new kerb ramp	H460	Primary	HIGH	\$ 2,500
CD864	Howthorne Parade	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.88408	151.144179	1		install new kerb ramp	H461	Primary	HIGH	\$ 2,500
CD874	Wattle Street	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877026	151.129653	1		install new kerb ramp - pair	H461	Primary	HIGH	\$ 5,000
CD875	Wattle Street	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877192	151.130019	1		install new kerb ramp - pair	H466	Primary	HIGH	\$ 5,000
CD876	Walker Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.87808	151.130638	1		install new kerb ramp - pair	H467	Primary	HIGH	\$ 5,000
CD880	Ramsay Street	Haberfield	Regional Road	crossing deficiency	missing crossing point	-33.881373	151.138685	1		install new kerb ramp	H467	Primary	HIGH	\$ 5,000
CD881	Kingston Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.881492	151.13988	1		install new kerb ramp	H485	Primary	HIGH	\$ 5,000
CD884	Yasmar Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878588	151.137239	1		install new kerb ramp - pair	H489	Primary	HIGH	\$ 5,000
CD886	Walker Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876151	151.135262	1		install new kerb ramp - pair	H483	Primary	HIGH	\$ 5,000
CD891	Al Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876841	151.135991	1		install new kerb ramp - pair	H483	Primary	HIGH	\$ 5,000
CD892	Empire Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878525	151.137351	1		install new kerb ramp - pair	H489	Primary	HIGH	\$ 5,000
CD893	Ramsay Street	Haberfield	Regional Road	crossing deficiency	opportunity to raise pedestrian crossing within town centre	-33.878495	151.137248	1		further investigation required - raised pedestrian crossing	H489	Primary	HIGH	\$ 15,000
CD894	Ramsay Street	Haberfield	Regional Road	crossing deficiency	at grade crossing missing tps - pair	-33.878554	151.138383	1		install new Tactile Ground Surface Indicators - pair	AN73	Primary	HIGH	\$ 1,300
CD901	White Creek Lane	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88195	151.162767	1		install new kerb ramp - pair	AN73	Primary	HIGH	\$ 1,300
CD926	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904854	151.128671	1		consult with City of Canterbury-Bankstown	DH82	Primary	HIGH	\$ -
CD935	Waralan Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.881258	151.15995	1		install new kerb ramp	DH107	Primary	HIGH	\$ 2,500
CD940	Moore Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.876231	151.164093	1		install new kerb ramp	DH107	Primary	HIGH	\$ 2,500
CD950	Catherine Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.879234	151.164113	1		install new kerb ramp	DH107	Primary	HIGH	\$ 2,500
CD951	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp construction	-33.87919	151.164293	1		install new kerb ramp	DH108	Primary	HIGH	\$ 2,500
CD955	Limes Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875164	151.165325	1		install new kerb ramp	DH114	Primary	HIGH	\$ 2,500
CD971	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.881097	151.158005	1		install new kerb ramp - pair	LH44	Primary	HIGH	\$ 5,0

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
MP22	Hudson Street	Lewisham	Local Road	missing footpath	missing footpath	-33.893976	151.143764	34	install new footpath	LW5	Primary	HIGH	\$ 6,800	
MP23	McGill Street	Lewisham	Local Road	missing footpath	missing footpath	-33.89426	151.143891	114	investigate shared zone implementation	LW5	Primary	HIGH	\$ 15,000	
MP27	Ever Line	Marrickville	Local Road	missing footpath	missing footpath	-33.910179	151.139553	140	install new footpath	PH31	Primary	HIGH	\$ 24,800	
MP41	Victoria Road	Marrickville	State Road	missing footpath	missing footpath	-33.914528	151.158279	54	install new footpath	MV227	Primary	HIGH	\$ 10,800	
MP7	Johnsons Creek	Annandale	Local Road	missing footpath	major pedestrian link missing	-33.885979	151.173072	376	further investigation required - pedestrian link (major infrastructure)	AN31	Primary	HIGH	\$ 50,000	
SA102	Alan Street	Leichhardt	Regional Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.880351	151.15874	1	install raised continuous footpath treatment	UH122	Primary	HIGH	\$ 30,000	
SA103	Balmori Road	Leichhardt	Regional Road	safety issue	opportunity to raise pedestrian crossing near school	-33.882073	151.158871	1	install raised pedestrian crossing	UH21	Primary	HIGH	\$ 50,000	
SA104	Norton Street	Leichhardt	Regional Road	safety issue	potential HPAA	-33.883798	151.157073	1	investigate High Pedestrian Activity Area implementation	UH128	Primary	HIGH	\$ 20,000	
SA105	Remwick Lane	Leichhardt	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.88736	151.157512	1	install raised continuous footpath treatment	UH131	Primary	HIGH	\$ 30,000	
SA110	Balmori Road	Leichhardt	Regional Road	safety issue	steep crossfall	-33.878979	151.159511	1	re-construct footpath pavement	UH12	Primary	HIGH	\$ 200	
SA111	Balmori Road	Leichhardt	Regional Road	safety issue	steep crossfall	-33.879236	151.159445	1	further investigation required - crossfall	UH12	Primary	HIGH	\$ 200	
SA112	Balmori Road	Leichhardt	Regional Road	safety issue	footlights approached incorrectly	-33.882059	151.15887	1	adjust flood light orientation	UH21	Primary	HIGH	\$ 1,000	
SA113	Balmori Road	Leichhardt	Regional Road	safety issue	vehicles approach crossing at speed	-33.882059	151.158873	1	install raised pedestrian crossing	UH21	Primary	HIGH	\$ 50,000	
SA114	Deysville Road	Leichhardt	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.879642	151.158578	1	install raised pedestrian crossing	UH41	Secondary	HIGH	\$ 50,000	
SA115	Flood Street	Leichhardt	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.885805	151.148643	1	install raised pedestrian crossing	UH59	Secondary	HIGH	\$ 60,000	
SA116	Lords Road	Leichhardt	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.885707	151.149733	1	install raised pedestrian crossing	UH89	Primary	HIGH	\$ 50,000	
SA12	Trafalgar Street	Annandale	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.886017	151.170286	1	install raised pedestrian crossing	AN101	Secondary	HIGH	\$ 50,000	
SA121	Hobb Street	Lewisham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.89413	151.14716	1	install raised continuous footpath treatment	LW25	Primary	HIGH	\$ 30,000	
SA122	Hunter Street	Lewisham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.89382	151.148402	1	install raised continuous footpath treatment	LW7	Primary	HIGH	\$ 30,000	
SA123	Jubilee Lane	Lewisham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.893811	151.147396	1	install raised continuous footpath treatment	LW25	Primary	HIGH	\$ 30,000	
SA125	Thomas Street	Lewisham	Local Road	safety issue	missing lighting	-33.893268	151.148191	1	install new lighting	LW34	Primary	HIGH	\$ 10,000	
SA126	Thomas Street	Lewisham	Local Road	safety issue	missing lighting	-33.893341	151.148383	1	install new lighting	LW34	Primary	HIGH	\$ 10,000	
SA127	Todd Street	Lewisham	Regional Road	safety issue	opportunity to raise pedestrian crossing near school	-33.895634	151.145199	1	install raised pedestrian crossing	LW36	Primary	HIGH	\$ 50,000	
SA128	Victoria Street	Lewisham	Local Road	safety issue	potential HPAA	-33.893722	151.147588	1	investigate High Pedestrian Activity Area implementation	LW24	Primary	HIGH	\$ 20,000	
SA13	Trafalgar Street	Annandale	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.884198	151.171128	1	install raised pedestrian crossing	AN109	Secondary	HIGH	\$ 50,000	
SA130	Perry Street	Lylfild	State Road	safety issue	opportunity to raise pedestrian crossing near school	-33.872037	151.157407	1	install raised pedestrian crossing	LF88	Primary	HIGH	\$ 50,000	
SA131	Arthur Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.914175	151.153168	1	install raised continuous footpath treatment	MV92	Primary	HIGH	\$ 30,000	
SA132	Blumen Lane	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.914482	151.15235	1	install raised continuous footpath treatment	MV93	Primary	HIGH	\$ 30,000	
SA133	Buckley Street	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing near public transport station	-33.914591	151.163849	1	install raised pedestrian crossing	MV131	Primary	HIGH	\$ 60,000	
SA135	Carrington Road	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.920061	151.145446	1	install raised pedestrian crossing	MV24	Secondary	HIGH	\$ 50,000	
SA136	Church Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.915294	151.151073	1	install raised continuous footpath treatment	MV94	Primary	HIGH	\$ 30,000	
SA138	Greenbank Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.914991	151.151923	1	install raised continuous footpath treatment	MV94	Primary	HIGH	\$ 30,000	
SA139	Grove Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.915178	151.151824	1	install raised continuous footpath treatment	MV94	Primary	HIGH	\$ 30,000	
SA14	Booth Street	Annandale	Regional Road	safety issue	potential HPAA	-33.881823	151.171774	1	investigate High Pedestrian Activity Area implementation	AN20	Primary	HIGH	\$ 20,000	
SA140	Illawarra Road	Marrickville	Regional Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.915018	151.15185	1	install raised pedestrian crossing	MV94	Primary	HIGH	\$ 50,000	
SA141	Illawarra Road	Marrickville	Regional Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.914423	151.152654	1	install raised pedestrian crossing	MV93	Primary	HIGH	\$ 50,000	
SA142	Illawarra Road	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.905623	151.162258	1	install raised pedestrian crossing	MV31	Secondary	HIGH	\$ 50,000	
SA148	Toddy Lane	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.913832	151.154929	1	install raised continuous footpath treatment	MV92	Primary	HIGH	\$ 30,000	
SA149	Warburton Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.914294	151.15263	1	install raised continuous footpath treatment	MV230	Primary	HIGH	\$ 30,000	
SA153	Illawarra Road	Marrickville	Regional Road	safety issue	steep crossfall	-33.913098	151.152911	1	re-construct footpath pavement	MV92	Primary	HIGH	\$ 200	
SA154	Illawarra Road	Marrickville	Regional Road	safety issue	corner obscures pedestrians	-33.911863	151.154599	1	install pavement warning message	MV90	Primary	HIGH	\$ 150	
SA155	Illawarra Road	Marrickville	Regional Road	safety issue	corner obscures pedestrians	-33.911838	151.154595	1	install pavement warning message	MV90	Primary	HIGH	\$ 150	
SA156	Illawarra Road	Marrickville	Regional Road	safety issue	vehicles approach crossing at speed	-33.911635	151.155297	1	install raised pedestrian crossing	MV90	Primary	HIGH	\$ 60,000	
SA157	Illawarra Road	Marrickville	Regional Road	safety issue	missing pedestrian crossing signage	-33.911252	151.155622	1	install pedestrian crossing signage	MV89	Primary	HIGH	\$ 200	
SA158	Illawarra Road	Marrickville	Regional Road	safety issue	potential HPAA	-33.910868	151.155913	1	investigate High Pedestrian Activity Area implementation	MV89	Primary	HIGH	\$ 20,000	
SA159	Marrickville Road	Marrickville	State Road	safety issue	missing lighting	-33.914814	151.164091	1	install new lighting	MV131	Primary	HIGH	\$ 10,000	
SA16	Chester Street	Annandale	Local Road	safety issue	steep crossfall	-33.884132	151.172892	1	further investigation required - crossfall	AN31	Primary	HIGH	\$ -	
SA169	Sydenham Road	Marrickville	Local Road	safety issue	substation obstructs pedestrian sight lines	-33.912566	151.165876	1	no action	MV203	Primary	HIGH	\$ -	
SA17	Chester Street	Annandale	Local Road	safety issue	steep crossfall	-33.884136	151.172917	1	further investigation required - crossfall	AN31	Primary	HIGH	\$ -	
SA171	Wardell Road	Marrickville	Regional Road	safety issue	poor visibility of pedestrians from workshop, no warning of vehicular crossover	-33.911863	151.142093	1	install pavement warning message	MV238	Primary	HIGH	\$ 150	
SA172	Schubert Street	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.914308	151.152821	1	install raised pedestrian crossing	MV189	Primary	HIGH	\$ 50,000	
SA173	Bailey Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.908491	151.176874	1	install raised continuous footpath treatment	NE34	Primary	HIGH	\$ 30,000	
SA174	Camden Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.901915	151.178566	1	install raised continuous footpath treatment	NE51	Primary	HIGH	\$ 30,000	
SA175	Enmore Road	Newtown	State Road	safety issue	narrow footpath	-33.897736	151.178252	1	further investigation required - path widening	NE33	Primary	HIGH	\$ 30,000	
SA176	Goodson Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896268	151.177757	1	install raised continuous footpath treatment	NE48	Primary	HIGH	\$ 30,000	
SA177	Holt Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.90011	151.178269	1	install raised continuous footpath treatment	NE38	Primary	HIGH	\$ 30,000	
SA178	Lennox Street	Newtown	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.895616	151.179576	1	install raised pedestrian crossing	NE40	Secondary	HIGH	\$ 60,000	
SA179	Marian Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.898978	151.172854	1	install raised continuous footpath treatment	EN7	Primary	HIGH	\$ 30,000	
SA18	Colma Street	Annandale	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.884366	151.171073	1	install raised pedestrian crossing	AN32	Secondary	HIGH	\$ 50,000	
SA180	Reilly Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.898777	151.175237	1	install raised continuous footpath treatment	NE36	Primary	HIGH	\$ 30,000	
SA181	Wells Street	Newtown	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.906471	151.178441	1	install raised pedestrian crossing	NE62	Secondary	HIGH	\$ 50,000	
SA182	Edgeware Road	Newtown	Regional Road	safety issue	shared path signage conflict	-33.907574	151.174553	1	install shared path signage	NE21	Primary	HIGH	\$ 300	
SA184	Enmore Road	Newtown	State Road	safety issue	poor visibility of pedestrians from workshop, no warning of vehicular crossover	-33.898554	151.173613	1	no action	NE37	Primary	HIGH	\$ -	
SA185	Enmore Road	Newtown	State Road	safety issue	pedestrian waiting area too small - narrowed by café seating	-33.897602	151.178472	1	review footpath trading	NE33	Primary	HIGH	\$ -	
SA186	Eliza Street	Newtown	Local Road	safety issue	cars do not give way to pedestrians	-33.897214	151.179099	1	install new shared zone signage and delineation	NE12	Primary	HIGH	\$ 500	
SA189	Laura Street	Newtown	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.905532	151.175676	1	install raised pedestrian crossing	NE35	Secondary	HIGH	\$ 30,000	
SA19	Johnston Street	Annandale	State Road	safety issue	poor visibility of waiting pedestrians and crossing	-33.878017	151.172223	1	install kerb extension - pair	AN48	Primary	HIGH	\$ 200	
SA190	Albert Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896164	151.158013	1	install raised continuous footpath treatment	PE57	Primary	HIGH	\$ 30,000	
SA191	Audley Lane	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.898271	151.153598	1	install raised continuous footpath treatment	PE32	Primary	HIGH	\$ 30,000	
SA192	Balmington Lane	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.898271	151.153598	1	install raised continuous footpath treatment	PE32	Primary	HIGH	\$ 30,000	
SA193	Church Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.895793	151.157631	1	install raised continuous footpath treatment	PE54	Primary	HIGH	\$ 30,000	
SA194	Ducros Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.897065	151.151587	1	install raised continuous footpath treatment	PE28	Primary	HIGH	\$ 30,000	
SA195	Fisher Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.895616	151.154189	1	install raised continuous footpath treatment	PE34	Primary	HIGH	\$ 30,000	
SA196	Hunter Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.897118	151.150675	1	install raised continuous footpath treatment	PE35	Primary	HIGH	\$ 30,000	
SA197	Maria Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896909	151.152122	1	install raised continuous footpath treatment	PE34	Primary	HIGH	\$ 30,000	
SA198	Marshall Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896743	151.150687	1	install raised continuous footpath treatment	PE36	Primary	HIGH	\$ 30,000	
SA199	Railway Terrace	Petersham	State Road	safety issue	review pedestrian and cyclist safety	-33.894032	151.148859	1	further investigation required - safety assessment	AN31	Primary	HIGH	\$ 5,000	
SA2	Chester Street	Annandale	Local Road	safety issue	vehicle encroach on pedestrian areas	-33.884154	151.172842	1	install kerb extensions built out	AN31	Primary	HIGH	\$ 10,000	
SA20	Nelson Street	Annandale	Local Road	safety issue	steep crossfall	-33.893398	151.17322	1	re-construct footpath pavement	AN72	Primary	HIGH	\$ 200	
SA200	Regent Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.894887	151.155439	1	install raised continuous footpath treatment	PE48	Primary	HIGH	\$ 50,000	
SA201	West Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.894887	151.155439	1	install raised continuous footpath treatment	PE48	Primary	HIGH	\$ 50,000	
SA202	West Street	Petersham	Regional Road	safety issue	opportunity to raise pedestrian crossing near school	-33.892415	151.148839	1	install raised pedestrian crossing	LW42	Primary	HIGH	\$ 60,000	
SA203	Audley Street	Petersham	Local Road	safety issue	potential HPAA	-33.895938	151.154144	1	investigate High Pedestrian Activity Area implementation	PE38	Primary	HIGH	\$ 20,000	
SA204	Regent Street	Petersham	Local Road	safety issue	vehicles obscure pedestrians	-33.895915	151.155439	1	install no stopping sign and signpost	PE38	Primary	HIGH	\$ 300	
SA205	Stannmore Road	Petersham	State Road	safety issue	poor drainage - severe ponding	-33.895611	151.155994	1	refer to maintenance	PE54	Primary	HIGH	\$ -	
SA208	Evans Street	Rozelle	Local Road	safety issue	crossover at the driveway is dangerous with vehicles approaching at speed	-33.865332	151.171842	1	install contrasting threshold	RO76	Primary	HIGH	\$ 5,000	
SA209	Hartock Lane	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.862387	151.169827	1	install raised continuous footpath treatment	RO28	Primary	HIGH	\$ 30,000	
SA211	Malinda Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.865959	151.16681	1	install raised continuous footpath treatment	LF3	Primary	HIGH	\$ 30,000	
SA212	Merton Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.862348	151.171054	1	install raised continuous footpath treatment	RO23	Primary	HIGH	\$ 30,000	
SA213	Merton Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.862293	151.170991	1	install raised continuous footpath treatment	RO18	Primary	HIGH	\$ 30,000</	

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
SA219	Wise Street	Rozelle	Local Road	Safety Issue	opportunity to raise pedestrian crossing within town centre	-33.80727	151.171632	1		install raised pedestrian crossing	R067	Primary	HIGH	\$ 60,000
SA221	Princess Street	Ashbury	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.90574	151.123614	1		consult with City of Canterbury-Bankstown	HP2	Secondary	HIGH	\$ 20,000
SA221	Darling Street	Rozelle	State Road	Safety Issue	potential HPAA	-33.86402	151.169837	1		investigate High Pedestrian Activity Area implementation	R026	Primary	HIGH	\$ 20,000
SA225	Cavendish Street	Stammore	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.89595	151.163889	1		install raised pedestrian crossing	SM35	Primary	HIGH	\$ 50,000
SA226	Holt Street	Stammore	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.89539	151.163846	1		install raised pedestrian crossing	SM35	Primary	HIGH	\$ 50,000
SA227	Myrie Street	Stammore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.89235	151.164540	1		install raised continuous footpath treatment	SM31	Primary	HIGH	\$ 30,000
SA228	Myrie Street	Stammore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.89241	151.164724	1		install raised continuous footpath treatment	SM31	Primary	HIGH	\$ 30,000
SA229	Perivall Lane East	Stammore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.893176	151.164894	1		install raised continuous footpath treatment	SM48	Primary	HIGH	\$ 30,000
SA231	Cavill Avenue	Ashfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.887412	151.121736	1		install raised continuous footpath treatment	AF106	Primary	HIGH	\$ 30,000
SA230	Perivall Lane West	Stammore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.89347	151.163575	1		install raised continuous footpath treatment	SM13	Primary	HIGH	\$ 30,000
SA231	Temple Street	Stammore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.893234	151.164252	1		install raised continuous footpath treatment	SM32	Primary	HIGH	\$ 30,000
SA233	Perivall Road	Stammore	Local Road	Safety Issue	potential HPAA	-33.892551	151.164569	1		investigate High Pedestrian Activity Area implementation	SM32	Primary	HIGH	\$ 20,000
SA236	Aubrey Street	Stammore	Local Road	Safety Issue	missing lighting	-33.895371	151.165138	1		install new lighting	SM50	Primary	HIGH	\$ 10,000
SA237	Holt Street	Stammore	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.894053	151.164314	1		install new lighting	SM26	Primary	HIGH	\$ 50,000
SA238	Holt Street	Stammore	Local Road	Safety Issue	potential HPAA	-33.895192	151.164221	1		investigate High Pedestrian Activity Area implementation	SM26	Primary	HIGH	\$ 20,000
SA239	Liberty Street	Stammore	Regional Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.89733	151.170394	1		install raised pedestrian crossing	EN12	Secondary	HIGH	\$ 50,000
SA24	Fort Lo	Ashfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.887762	151.126138	1		install raised continuous footpath treatment	AF32	Primary	HIGH	\$ 30,000
SA240	Hardie Avenue	Summer Hill	Local Road	Safety Issue	opportunity to raise pedestrian crossing within town centre	-33.89094	151.137299	1		install raised pedestrian crossing	SH34	Primary	HIGH	\$ 50,000
SA241	Hardie Avenue	Summer Hill	Local Road	Safety Issue	opportunity to raise pedestrian crossing within town centre	-33.891634	151.137252	1		install raised pedestrian crossing	SH34	Primary	HIGH	\$ 50,000
SA242	Hardie Avenue	Summer Hill	Local Road	Safety Issue	potential HPAA	-33.890812	151.137451	1		investigate High Pedestrian Activity Area implementation	SH33	Primary	HIGH	\$ 20,000
SA243	Lacey Street	Summer Hill	Local Road	Safety Issue	potential HPAA	-33.891166	151.138286	1		investigate High Pedestrian Activity Area implementation	SH48	Primary	HIGH	\$ 20,000
SA244	Monroe Street	Summer Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.891714	151.136911	1		install raised continuous footpath treatment	SH84	Primary	HIGH	\$ 30,000
SA245	Morris Street	Summer Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.891681	151.137884	1		install raised continuous footpath treatment	SH85	Primary	HIGH	\$ 30,000
SA246	Spaine Street	Summer Hill	Local Road	Safety Issue	opportunity to raise pedestrian crossing within town centre	-33.89001	151.139159	1		install raised pedestrian crossing	SH78	Primary	HIGH	\$ 50,000
SA247	Carlton Crescent	Summer Hill	Regional Road	Safety Issue	steep crossfall	-33.890708	151.138985	1		further investigation required - crossfall	SH3	Primary	HIGH	\$ 50,000
SA250	Henson Street	Summer Hill	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.89219	151.134579	1		install raised pedestrian crossing	SH36	Secondary	HIGH	\$ 50,000
SA251	Junction Road	Summer Hill	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.895265	151.135801	1		install raised pedestrian crossing	SH43	Secondary	HIGH	\$ 50,000
SA253	Lacey Street	Summer Hill	Local Road	Safety Issue	traction issues when wet	-33.891692	151.138101	1		no action	SH49	Primary	HIGH	\$ 50,000
SA257	Rayfield Road	Sydenham	Local Road	Safety Issue	opportunity to raise pedestrian crossing within town centre	-33.916315	151.166296	1		install raised pedestrian crossing	SV6	Primary	HIGH	\$ 50,000
SA258	Rayfield Road	Sydenham	State Road	Safety Issue	potential HPAA	-33.914702	151.165932	1		investigate High Pedestrian Activity Area implementation	SV6	Primary	HIGH	\$ 20,000
SA259	Wright Street	Summer Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.915703	151.168176	1		install raised continuous footpath treatment	SV9	Primary	HIGH	\$ 30,000
SA26	Lapin Avenue	Ashfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.888198	151.120111	1		install raised continuous footpath treatment	AF109	Primary	HIGH	\$ 30,000
SA27	Miller Avenue	Ashfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.887673	151.122173	1		install raised continuous footpath treatment	AF106	Primary	HIGH	\$ 30,000
SA28	Murel Street	Ashfield	Local Road	Safety Issue	opportunity to provide raised pedestrian crossing	-33.889451	151.127634	1		further investigation required - raised pedestrian crossing	AF101	Primary	HIGH	\$ 15,000
SA29	Murel Street	Ashfield	Local Road	Safety Issue	opportunity to provide traffic calming treatment	-33.889463	151.127652	1		further investigation required - traffic calming	AF101	Primary	HIGH	\$ 30,000
SA3	Johnson Lane	Annandale	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.881763	151.171433	1		install raised continuous footpath treatment	AN20	Primary	HIGH	\$ 30,000
SA30	Murel Street	Ashfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.889941	151.127448	1		install raised continuous footpath treatment	AF101	Primary	HIGH	\$ 30,000
SA31	Norton Street	Regional Road	Safety Issue	opportunity to provide traffic calming treatment	-33.889078	151.128217	1		further investigation required - traffic calming	AF122	Primary	HIGH	\$ 30,000	
SA32	Orchard Crescent	Ashfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.888375	151.128672	1		install raised continuous footpath treatment	AF31	Primary	HIGH	\$ 30,000
SA34	Alt Street	Ashfield	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.883612	151.124288	1		install raised pedestrian crossing	AF7	Secondary	HIGH	\$ 50,000
SA35	Blair Street	Ashfield	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.885538	151.125397	1		install raised pedestrian crossing	AF18	Secondary	HIGH	\$ 50,000
SA36	Brown Street	Ashfield	Local Road	Safety Issue	potential HPAA	-33.886356	151.128144	1		investigate High Pedestrian Activity Area implementation	AF30	Primary	HIGH	\$ 20,000
SA38	Elizabeth Street	Ashfield	Regional Road	Safety Issue	potential HPAA	-33.88691	151.12628	1		investigate High Pedestrian Activity Area implementation	AF58	Primary	HIGH	\$ 20,000
SA39	Frederick Street	Ashfield	State Road	Safety Issue	poor drainage	-33.885242	151.119688	1		refer to maintenance	AF76	Primary	HIGH	\$ 20,000
SA4	Susan Street	Annandale	Local Road	Safety Issue	vehicle encroach on pedestrian areas	-33.884388	151.173324	1		install kerb bollards build outs	AN31	Primary	HIGH	\$ 10,000
SA41	Prospect Road	Ashfield	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.899418	151.132148	1		install raised pedestrian crossing	SH74	Secondary	HIGH	\$ 50,000
SA44	Church Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.85687	151.179648	1		install raised continuous footpath treatment	BA31	Primary	HIGH	\$ 30,000
SA45	Church Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.856764	151.179714	1		install raised continuous footpath treatment	BA31	Primary	HIGH	\$ 30,000
SA46	College Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857065	151.180219	1		install raised continuous footpath treatment	BA30	Primary	HIGH	\$ 30,000
SA47	Darling Street	Balmoral	Local Road	Safety Issue	potential HPAA	-33.856479	151.177998	1		investigate High Pedestrian Activity Area implementation	BA32	Primary	HIGH	\$ 20,000
SA48	Ford Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857665	151.18202	1		install raised continuous footpath treatment	BA29	Primary	HIGH	\$ 30,000
SA49	Hargrove Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.858178	151.174846	1		install raised continuous footpath treatment	BA34	Primary	HIGH	\$ 30,000
SA50	Jacques Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.856118	151.176719	1		install raised continuous footpath treatment	BA33	Primary	HIGH	\$ 30,000
SA52	McDonald Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857821	151.182749	1		install raised continuous footpath treatment	BA28	Primary	HIGH	\$ 30,000
SA53	Mort Street	Balmoral	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857342	151.180692	1		install raised continuous footpath treatment	BA30	Primary	HIGH	\$ 30,000
SA58	Darling Street	Balmoral East	Local Road	Safety Issue	potential HPAA	-33.857476	151.182186	1		investigate High Pedestrian Activity Area implementation	BE5	Primary	HIGH	\$ 20,000
SA59	Darling Street	Balmoral East	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857705	151.19198	1		install raised continuous footpath treatment	BE3	Primary	HIGH	\$ 30,000
SA60	Duke Street	Balmoral East	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857476	151.19231	1		install raised continuous footpath treatment	BE3	Primary	HIGH	\$ 30,000
SA61	Johnston Street	Balmoral East	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857499	151.193697	1		install raised continuous footpath treatment	BE2	Primary	HIGH	\$ 30,000
SA62	Union Street	Balmoral East	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.857617	151.192615	1		install raised continuous footpath treatment	BE5	Primary	HIGH	\$ 30,000
SA65	Elizabeth Street	Croydon	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.882742	151.117276	1		install raised pedestrian crossing	CR21	Secondary	HIGH	\$ 50,000
SA66	Teakle Street	Croydon	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.893708	151.133628	1		install raised pedestrian crossing	SH68	Secondary	HIGH	\$ 50,000
SA67	Beach Road	Dulwich Hill	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.904613	151.141382	1		install raised pedestrian crossing	OH6	Primary	HIGH	\$ 50,000
SA69	Denison Road	Dulwich Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.904398	151.139258	1		install raised continuous footpath treatment	OH83	Primary	HIGH	\$ 30,000
SA7	View Street	Annandale	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.88161	151.171503	1		install raised continuous footpath treatment	AN20	Primary	HIGH	\$ 30,000
SA70	Farlow Lane	Dulwich Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.904613	151.141382	1		install raised continuous footpath treatment	OH75	Primary	HIGH	\$ 30,000
SA71	Herbert Street	Dulwich Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.902479	151.144496	1		install raised continuous footpath treatment	OH94	Primary	HIGH	\$ 30,000
SA72	Kingstone Street	Dulwich Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.904395	151.139596	1		install raised continuous footpath treatment	OH99	Primary	HIGH	\$ 30,000
SA73	Lewisham Street	Dulwich Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.902534	151.143172	1		install raised continuous footpath treatment	OH96	Primary	HIGH	\$ 30,000
SA74	New Canterbury Road	Dulwich Hill	State Road	Safety Issue	potential HPAA	-33.903436	151.142054	1		investigate High Pedestrian Activity Area implementation	OH94	Primary	HIGH	\$ 20,000
SA75	Old Canterbury Road	Dulwich Hill	State Road	Safety Issue	opportunity to upgrade to signalised crossing	-33.900913	151.132005	1		further investigation required - signals	AF126	Primary	HIGH	\$ 20,000
SA76	Piggott Street	Dulwich Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.902495	151.144004	1		install raised continuous footpath treatment	OH95	Primary	HIGH	\$ 30,000
SA77	Warrell Road	Dulwich Hill	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.911233	151.142175	1		install raised continuous footpath treatment	OH96	Primary	HIGH	\$ 30,000
SA8	Wells Street	Annandale	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.882279	151.172798	1		install raised continuous footpath treatment	AN26	Primary	HIGH	\$ 30,000
SA81	Cambridge Street	Enmore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.89133	151.171484	1		install raised continuous footpath treatment	EN6	Primary	HIGH	\$ 30,000
SA82	Enmore Lane	Enmore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.896699	151.171232	1		install raised continuous footpath treatment	EN1	Primary	HIGH	\$ 30,000
SA83	Fetheringham Street	Enmore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.896564	151.170741	1		install raised continuous footpath treatment	EN13	Primary	HIGH	\$ 30,000
SA84	London Street	Enmore	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.898943	151.172149	1		install raised continuous footpath treatment	EN7	Primary	HIGH	\$ 30,000
SA85	Stammore Road	Enmore	State Road	Safety Issue	potential HPAA	-33.89943	151.170771	1		investigate High Pedestrian Activity Area implementation	EN13	Primary	HIGH	\$ 20,000
SA88	Dickson Street	Haberfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.879863	151.139437	1		install raised continuous footpath treatment	SH34	Primary	HIGH	\$ 30,000
SA89	Gillies Avenue	Haberfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.879491	151.137841	1		install raised continuous footpath treatment	SH88	Primary	HIGH	\$ 30,000
SA9	Annandale Street	Annandale	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.877992	151.17063	1		install raised pedestrian crossing	AN7	Secondary	HIGH	\$ 50,000
SA90	Ramsay Street	Haberfield	Regional Road	Safety Issue	potential HPAA	-33.884496	151.138852	1		investigate High Pedestrian Activity Area implementation	HA03	Primary	HIGH	\$ 20,000
SA91	Ransom Street	Haberfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.879491	151.138172	1		install raised continuous footpath treatment	HA03	Primary	HIGH	\$ 30,000
SA92	Wincombe Avenue	Haberfield	Local Road	Safety Issue	opportunity to provide raised continuous footpath within town centre	-33.881342	151.138081	1		install raised continuous footpath treatment	HA36	Primary	HIGH	\$ 30,000
SA95	Dalhouse Street	Haberfield	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.878865	151.14	1		install raised pedestrian crossing	HA32	Primary	HIGH	\$ 50,000
SA96	Warant Street	Haberfield	Local Road	Safety Issue	opportunity to raise pedestrian crossing near school	-33.874858	151.140382	1		install raised pedestrian crossing	HA107	Secondary	HIGH	\$ 50,000

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
AC1	Booth Street	Annandale	Regional Road	access	stairs only access to crossing	-33.88058	151.168129	1		further investigation required - stairs	AN21	Secondary	MED	\$ -
AC13	Grove Street	Birchgrove	Local Road	access	stairs only access	-33.850183	151.183234	1		install accessible ramp	B11	Secondary	MED	\$ 10,000
AC14	Louisa Road	Birchgrove	Local Road	access	stairs only access to wharf	-33.846725	151.16213	1		consult with TNSW	B17	Secondary	MED	\$ -
AC15	Palisley Road	Croydon	Local Road	access	alternative access to station platform	-33.83957	151.116144	1		consult with TNSW	CR16	Secondary	MED	\$ -
AC16	Constitution Road	Dulwich Hill	Local Road	access	stairs only access	-33.902486	151.138001	1		no action	DH20	Secondary	MED	\$ -
AC17	Davis Street	Dulwich Hill	Local Road	access	stairs only access	-33.898337	151.140341	1		no action	DH116	Secondary	MED	\$ -
AC18	Boumang Street	Haberfield	Local Road	access	stairs only access to park	-33.871425	151.144465	1		install accessible ramp	H423	Secondary	MED	\$ 10,000
AC19	White Creek	Leichhardt	Local Road	access	no ramp between different height footpaths	-33.886716	151.163344	1		install new kerb ramp	LH157	Secondary	MED	\$ 2,500
AC2	Nelson Street	Annandale	Local Road	access	stairs only access	-33.879484	151.174831	1		install accessible ramp	AN68	Secondary	MED	\$ 10,000
AC22	Lilyfield Road	Lilyfield	Regional Road	access	stairs only access	-33.872221	151.167898	1		install accessible ramp	LF74	Secondary	MED	\$ 10,000
AC24	Lilyfield Road	Lilyfield	Regional Road	access	stairs only access	-33.872252	151.167966	1		install accessible ramp	LF74	Secondary	MED	\$ 10,000
AC26	Enmore Road	Marrickville	Regional Road	access	no access to push button	-33.904041	151.168294	1		consult with TNSW	MV11	Secondary	MED	\$ 10,000
AC27	Illawarra Road	Marrickville	Regional Road	access	stairs only access	-33.918432	151.146907	1		install accessible ramp	MV100	Secondary	MED	\$ 10,000
AC30	Bedford Street	Newtown	Local Road	access	stairs only access to underpass	-33.896186	151.173503	1		install accessible ramp	NE17	Secondary	MED	\$ 10,000
AC32	Anzac Bridge	Rozelle	State Road	access	stairs only access	-33.867943	151.18197	1		no action	RO8	Secondary	MED	\$ -
AC33	Anzac Bridge	Rozelle	State Road	access	stairs only access	-33.868141	151.181188	1		no action	RO7	Secondary	MED	\$ -
AC34	Evans Street	Rozelle	Local Road	access	stairs only access	-33.867355	151.169111	1		install accessible ramp	RC35	Secondary	MED	\$ 10,000
AC35	Victoria Road	Rozelle	State Road	access	stairs only access	-33.860693	151.164353	1		consult with TNSW	RC84	Secondary	MED	\$ -
AC36	Maney Street	Rozelle	Local Road	access	stairs only access	-33.866115	151.173661	1		install new kerb ramp - pair	RO73	Secondary	MED	\$ 5,000
AC37	Graham Street	Rozelle	Local Road	access	stairs only access	-33.866456	151.174471	1		install accessible ramp	RO74	Secondary	MED	\$ 10,000
AC4	Prichard Street	Annandale	Local Road	access	stairs only access	-33.874159	151.170476	1		install accessible ramp	AN122	Secondary	MED	\$ 10,000
AC41	View Street	Tempe	Local Road	access	stairs only access	-33.925798	151.156101	1		install accessible ramp	TE33	Secondary	MED	\$ 10,000
AC5	Rose Street	Annandale	Local Road	access	stairs only access	-33.877603	151.176526	1		install accessible ramp	AN95	Secondary	MED	\$ 10,000
AC8	Trafalgar Street	Annandale	Local Road	access	stairs only access	-33.876952	151.174355	1		install accessible ramp	AN103	Secondary	MED	\$ 10,000
AC8	Young Street	Annandale	Local Road	access	stairs only access to crossing	-33.88067	151.168203	1		install kerb extension	AN21	Secondary	MED	\$ 10,000
CD1	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873888	151.172547	1		install new kerb ramp	AN3	Secondary	MED	\$ 2,500
CD10	Lehrman Street	Annandale	State Road	crossing deficiency	misaligned kerb ramp	-33.885777	151.168995	1		install new kerb ramp	AN82	Secondary	MED	\$ 2,500
CD100	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.885116	151.168282	1		install new Tactile Ground Surface Indicators	AN14	Secondary	MED	\$ 650
CD1000	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886079	151.149736	1		install new kerb ramp - pair	UH59	Secondary	MED	\$ 5,000
CD1001	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886774	151.149464	1		install new kerb ramp	UH60	Secondary	MED	\$ 2,500
CD1002	Flood Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.886814	151.149188	1		install new kerb ramp	UH10	Secondary	MED	\$ 1,300
CD1006	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.886395	151.149857	1		install new Tactile Ground Surface Indicators	UH112	Secondary	MED	\$ 650
CD101	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882384	151.168704	1		install new kerb ramp - pair	AN12	Secondary	MED	\$ 5,000
CD1012	Flood Street	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.885577	151.149888	1		install new kerb ramp - pair	UH62	Secondary	MED	\$ 5,000
CD1013	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.883766	151.149693	1		install new Tactile Ground Surface Indicators - pair	UH10	Secondary	MED	\$ 1,300
CD1017	Foster Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment	-33.88593	151.147574	1		install new kerb ramp	UH8	Secondary	MED	\$ 2,500
CD1019	Lords Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88607	151.147532	1		install new kerb ramp	UH87	Secondary	MED	\$ 2,500
CD102	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.883184	151.168234	1		install new Tactile Ground Surface Indicators	AN14	Secondary	MED	\$ 650
CD1020	Foster Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment	-33.88593	151.147706	1		install new kerb ramp	UH8	Secondary	MED	\$ 2,500
CD1022	Foster Street	Leichhardt	State Road	crossing deficiency	misaligned kerb ramp	-33.88593	151.147731	1		install new kerb ramp	UH8	Secondary	MED	\$ 2,500
CD1023	Lords Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886043	151.14775	1		install new kerb ramp	UH8	Secondary	MED	\$ 2,500
CD1024	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.88336	151.161290	1		install new kerb ramp - pair	UH9	Secondary	MED	\$ 5,000
CD1025	Leichhardt Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp construction	-33.883182	151.161236	1		install new kerb ramp	UH3	Secondary	MED	\$ 2,500
CD1026	Lords Road	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.885962	151.148314	1		install new Tactile Ground Surface Indicators	UH88	Secondary	MED	\$ 650
CD1027	Lords Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88607	151.146937	1		install new kerb ramp	UH8	Secondary	MED	\$ 2,500
CD1028	Lords Road	Leichhardt	Local Road	crossing deficiency	long driveway crossing point	-33.885792	151.148453	1		no action	UH8	Secondary	MED	\$ -
CD1029	Lords Road	Leichhardt	Local Road	crossing deficiency	long driveway crossing point	-33.885801	151.148442	1		no action	UH8	Secondary	MED	\$ -
CD103	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88314	151.168216	1		install new kerb ramp	AN34	Secondary	MED	\$ 2,500
CD1030	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.88445	151.161074	1		install new kerb ramp	UH47	Secondary	MED	\$ 2,500
CD1031	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.88447	151.161133	1		install new kerb ramp	UH47	Secondary	MED	\$ 2,500
CD1035	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884088	151.162036	1		install new kerb ramp	UH8	Secondary	MED	\$ 2,500
CD1036	Elswick Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.884161	151.151189	1		install new kerb ramp - pair	UH45	Secondary	MED	\$ 5,000
CD1037	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.884032	151.151886	1		install new kerb ramp	UH97	Secondary	MED	\$ 2,500
CD1038	Marion Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.884079	151.151889	1		install new kerb ramp - pair	UH97	Secondary	MED	\$ 5,000
CD1039	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884187	151.151890	1		install new kerb ramp	UH97	Secondary	MED	\$ 2,500
CD1040	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884143	151.152026	1		install new kerb ramp	UH6	Secondary	MED	\$ 2,500
CD1045	Foster Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment	-33.88413	151.147534	1		install new kerb ramp	UH71	Secondary	MED	\$ 2,500
CD1046	Marion Street	Leichhardt	State Road	crossing deficiency	at grade crossing missing tgi	-33.884092	151.145378	1		install new Tactile Ground Surface Indicators	UH92	Secondary	MED	\$ 650
CD1048	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879311	151.164138	1		install new kerb ramp	UH4	Secondary	MED	\$ 2,500
CD1049	John Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879799	151.166228	1		install new kerb ramp	UH109	Secondary	MED	\$ 2,500
CD105	Booth Street	Annandale	Regional Road	crossing deficiency	narrow kerb ramp	-33.881	151.169297	1		install new kerb ramp	AN11	Secondary	MED	\$ 2,500
CD1050	Moore Street	Leichhardt	Regional Road	crossing deficiency	missing crossing point	-33.879754	151.166258	1		install new kerb ramp - pair	UH109	Secondary	MED	\$ 5,000
CD1051	Moore Street	Leichhardt	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.878739	151.166627	1		install new Tactile Ground Surface Indicators	UH10	Secondary	MED	\$ 650
CD1053	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.878769	151.161921	1		install new kerb ramp	UH104	Secondary	MED	\$ 2,500
CD1054	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.878784	151.161971	1		install new kerb ramp	UH105	Secondary	MED	\$ 2,500
CD1055	Annworth Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.878853	151.162426	1		install new kerb ramp	UH10	Secondary	MED	\$ 2,500
CD1056	White Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879777	151.169646	1		install new kerb ramp	UH110	Secondary	MED	\$ 2,500
CD1057	Annworth Street	Leichhardt	Local Road	crossing deficiency	steep kerb ramp	-33.878862	151.162513	1		install new kerb ramp - pair	UH105	Secondary	MED	\$ 5,000
CD106	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.880866	151.169307	1		install new kerb ramp	AN11	Secondary	MED	\$ 2,500
CD1065	Norton Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877222	151.156115	1		install new kerb ramp - pair	UH126	Secondary	MED	\$ 5,000
CD1066	Norton Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877151	151.156128	1		install new kerb ramp - pair	UH126	Secondary	MED	\$ 5,000
CD107	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88092	151.169327	1		install new kerb ramp	AN10	Secondary	MED	\$ 2,500
CD1071	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887853	151.161242	1		install new kerb ramp - pair	UH14	Secondary	MED	\$ 5,000
CD108	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.880449	151.169603	1		install new Tactile Ground Surface Indicators - pair	AN10	Secondary	MED	\$ 1,300
CD1082	George Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889558	151.148488	1		install new kerb ramp - pair	UH134	Secondary	MED	\$ 5,000
CD1085	Prospect Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.884458	151.160544	1		install new kerb ramp - pair	UH147	Secondary	MED	\$ 5,000
CD1086	Prospect Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.884457	151.160595	1		install new kerb ramp	UH147	Secondary	MED	\$ 2,500
CD1087	Prospect Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.884416	151.160492	1		install new kerb ramp	UH147	Secondary	MED	\$ 2,500
CD1088	Hay Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.884447	151.160498	1		install new kerb ramp	UH147	Secondary	MED	\$ 2,500
CD109	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.880069	151.168731	1		install new Tactile Ground Surface Indicators	AN22	Secondary	MED	\$ 650
CD1090	John Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882791	151.165404	1		install new kerb ramp - pair	UH150	Secondary	MED	\$ 5,000
CD1091	Emma Lane	Leichhardt	Regional Road	crossing deficiency	raised kerb ramp lip	-33.882864	151.164907	1		install new kerb ramp	UH151	Secondary	MED	\$ 2,500
CD1092	Styies Street	Leichhardt	Regional Road	crossing deficiency	raised kerb ramp lip	-33.882868	151.164953	1		install new kerb ramp	UH151	Secondary	MED	\$ 2,500
CD1093	Emma Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.882927	151.164416	1		install new kerb ramp - pair	UH148	Secondary	MED	\$ 5,000
CD1094	Thorby Avenue	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882977	151.164416	1		install new kerb ramp - pair	UH148	Secondary	MED	\$ 5,000
CD1095	Coleridge Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.883269	151.161884	1		install new kerb ramp	UH149	Secondary	MED	\$ 2,500
CD1096	Styies Street	Leichhardt	Regional Road	crossing deficiency	missing kerb ramp	-33.883176	151.162034	1		install new kerb ramp	UH149	Secondary	MED	\$ 2,500
CD1097	Coleridge Lane	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.883197	151.162313	1		install new kerb ramp - pair	UH149	Secondary	MED	\$ 5,000
CD1098	Styies Street	Leichhardt	Regional Road	crossing deficiency	narrow refuge island	-33.882698	151.16639	1		install new refuge island				

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1101	Keeworth Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887094	151.147313	1		install new kerb ramp - pair	UH154	Secondary	MED	\$	5,000
CD1102	Beason Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887924	151.147137	1		install new kerb ramp	UH154	Secondary	MED	\$	2,500
CD1103	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.884052	151.160338	1		install new Tactile Ground Surface Indicators - pair	UH161	Secondary	MED	\$	1,300
CD1104	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.88408	151.160207	1		install new Tactile Ground Surface Indicators - pair	UH161	Secondary	MED	\$	1,300
CD1105	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.885008	151.164792	1		install new Tactile Ground Surface Indicators - pair	UH162	Secondary	MED	\$	1,300
CD1106	White Creek	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.883842	151.165139	1		install new kerb ramp - pair	UH163	Secondary	MED	\$	5,000
CD1107	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.885071	151.164803	1		install new Tactile Ground Surface Indicators - pair	UH164	Secondary	MED	\$	1,300
CD1108	White Creek	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.886365	151.164099	1		install new kerb ramp	UH165	Secondary	MED	\$	2,500
CD1109	White Creek	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.886268	151.164173	1		install new kerb ramp	UH166	Secondary	MED	\$	2,500
CD1110	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.886292	151.164105	1		install new Tactile Ground Surface Indicators	UH167	Secondary	MED	\$	650
CD1111	White Creek	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.88667	151.163356	1		install new kerb ramp - pair	UH168	Secondary	MED	\$	5,000
CD1112	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.87734	151.156443	1		install new kerb ramp	UH169	Secondary	MED	\$	2,500
CD1113	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.877499	151.152042	1		install new kerb ramp	UH170	Secondary	MED	\$	2,500
CD1115	William Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877225	151.156285	1		install new Tactile Ground Surface Indicators	UH171	Secondary	MED	\$	650
CD1116	William Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877252	151.157563	1		install new Tactile Ground Surface Indicators	UH172	Secondary	MED	\$	650
CD1117	William Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.877261	151.157481	1		install new kerb ramp	UH173	Secondary	MED	\$	2,500
CD1118	William Street	Leichhardt	Local Road	crossing deficiency	misaligned refuge island	-33.877794	151.150239	1		re-construct refuge island	UH174	Secondary	MED	\$	15,000
CD1119	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877248	151.149287	1		install new kerb ramp - pair	UH175	Secondary	MED	\$	5,000
CD1120	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877603	151.150211	1		install new kerb ramp	UH176	Secondary	MED	\$	2,500
CD1121	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877531	151.150697	1		install new kerb ramp	UH177	Secondary	MED	\$	2,500
CD1122	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877761	151.151119	1		install new kerb ramp - pair	UH178	Secondary	MED	\$	5,000
CD1123	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877508	151.152522	1		install new kerb ramp - pair	UH179	Secondary	MED	\$	5,000
CD1124	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877422	151.154471	1		install new kerb ramp - pair	UH180	Secondary	MED	\$	5,000
CD1125	William Street	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.877463	151.154597	1		install new kerb ramp - pair	UH181	Secondary	MED	\$	5,000
CD1126	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877464	151.153579	1		install new kerb ramp	UH182	Secondary	MED	\$	2,500
CD1127	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877468	151.153111	1		install new kerb ramp	UH183	Secondary	MED	\$	2,500
CD1128	William Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.877255	151.153177	1		install new Tactile Ground Surface Indicators - pair	UH184	Secondary	MED	\$	1,300
CD1129	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.877063	151.155435	1		install new kerb ramp	UH185	Secondary	MED	\$	2,500
CD1130	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.87764	151.151718	1		install new kerb ramp - pair	UH186	Secondary	MED	\$	5,000
CD1131	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.8776	151.152178	1		install new kerb ramp - pair	UH187	Secondary	MED	\$	5,000
CD1132	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned refuge island	-33.880329	151.149891	1		re-construct refuge island	UH188	Secondary	MED	\$	15,000
CD1133	Allen Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.880432	151.148781	1		install new Tactile Ground Surface Indicators	UH189	Secondary	MED	\$	650
CD1134	Allen Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.880415	151.149948	1		install new kerb ramp	UH190	Secondary	MED	\$	2,500
CD1136	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.880203	151.153377	1		install new kerb ramp - pair	UH191	Secondary	MED	\$	5,000
CD1137	Allen Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.880068	151.154829	1		install new kerb ramp	UH192	Secondary	MED	\$	2,500
CD1138	Allen Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.880061	151.154864	1		install new kerb ramp	UH193	Secondary	MED	\$	5,000
CD1139	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.880102	151.155007	1		install new kerb ramp	UH194	Secondary	MED	\$	2,500
CD1140	Allen Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879943	151.155739	1		install new kerb ramp	UH195	Secondary	MED	\$	2,500
CD1143	Balmann Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.878192	151.155968	1		install new kerb ramp	UH196	Secondary	MED	\$	2,500
CD1115	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878108	151.17095	1		install new Tactile Ground Surface Indicators	UH197	Secondary	MED	\$	650
CD1196	Prospect Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894615	151.155195	1		install new kerb ramp - pair	UH198	Secondary	MED	\$	5,000
CD1116	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878108	151.170519	1		install new Tactile Ground Surface Indicators	UH199	Secondary	MED	\$	650
CD1160	Style Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.883185	151.162833	1		install new kerb ramp	UH200	Secondary	MED	\$	2,500
CD1161	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887213	151.161611	1		install new kerb ramp	UH201	Secondary	MED	\$	2,500
CD1162	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.887358	151.161688	1		install new Tactile Ground Surface Indicators	UH202	Secondary	MED	\$	650
CD1164	Carlington Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890489	151.147837	1		install new kerb ramp	UH203	Secondary	MED	\$	2,500
CD1169	Hunter Street	Lewisham	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.895509	151.149447	1		install new kerb ramp - pair	UH204	Secondary	MED	\$	5,000
CD1171	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879509	151.171659	1		install new kerb ramp	UH205	Secondary	MED	\$	2,500
CD1170	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895262	151.149439	1		install new kerb ramp	UH206	Secondary	MED	\$	2,500
CD1171	Hunter Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895244	151.149209	1		install new kerb ramp	UH207	Secondary	MED	\$	2,500
CD1172	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895096	151.149246	1		install new kerb ramp	UH208	Secondary	MED	\$	2,500
CD1173	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895193	151.149238	1		install new kerb ramp	UH209	Secondary	MED	\$	2,500
CD1118	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878617	151.171711	1		install new kerb ramp	UH210	Secondary	MED	\$	2,500
CD1181	Gould Avenue	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.898134	151.149195	1		install new Tactile Ground Surface Indicators	UH211	Secondary	MED	\$	650
CD1182	Henry Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894035	151.145379	1		install new kerb ramp	UH212	Secondary	MED	\$	2,500
CD1188	McGill Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895033	151.147973	1		install new kerb ramp	UH213	Secondary	MED	\$	2,500
CD1187	McGill Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89508	151.143879	1		install new kerb ramp	UH214	Secondary	MED	\$	2,500
CD1188	Old Canterbury Road	Lewisham	State Road	crossing deficiency	long crossing	-33.895069	151.144053	1		requires further investigation - long crossing	UH215	Secondary	MED	\$	5,000
CD1189	Old Canterbury Road	Lewisham	State Road	crossing deficiency	missing crossing point	-33.895188	151.142939	1		further investigation required - pedestrian refuge or crossing (signal)	UH216	Secondary	MED	\$	15,000
CD1119	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.878991	151.171658	1		re-construct refuge island	UH217	Secondary	MED	\$	15,000
CD1192	Parramatta Road	Lewisham	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.895953	151.148908	1		install new kerb ramp - pair	UH218	Secondary	MED	\$	5,000
CD1194	Smith Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893422	151.14337	1		install new kerb ramp	UH219	Secondary	MED	\$	2,500
CD1196	Thomas Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.891453	151.147992	1		install new kerb ramp - pair	UH220	Secondary	MED	\$	5,000
CD1199	Toothill Street	Lewisham	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.896345	151.145674	1		install new Tactile Ground Surface Indicators	UH221	Secondary	MED	\$	650
CD1212	Bignell Lane	Annandale	Local Road	crossing deficiency	poor kerb ramp construction	-33.886159	151.176304	1		install new kerb ramp	UH222	Secondary	MED	\$	2,500
CD120	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878318	151.172517	1		install new Tactile Ground Surface Indicators	UH223	Secondary	MED	\$	650
CD1200	Toothill Street	Lewisham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.896917	151.14628	1		install new kerb ramp	UH224	Secondary	MED	\$	2,500
CD1201	Toothill Street	Lewisham	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.896942	151.146453	1		install new kerb ramp - pair	UH225	Secondary	MED	\$	5,000
CD1202	Toothill Street	Lewisham	Regional Road	crossing deficiency	misaligned refuge island	-33.896918	151.146431	1		re-construct refuge island	UH226	Secondary	MED	\$	15,000
CD1205	Toothill Street	Lewisham	Regional Road	crossing deficiency	narrow kerb ramp	-33.897017	151.147052	1		install new kerb ramp	UH227	Secondary	MED	\$	2,500
CD1206	Toothill Street	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.894914	151.144468	1		install new kerb ramp	UH228	Secondary	MED	\$	5,000
CD1210	Old Canterbury Road	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893083	151.145792	1		install new kerb ramp - pair	UH229	Secondary	MED	\$	5,000
CD1211	Lonsport Street	Lewisham	Regional Road	crossing deficiency	narrow kerb ramp	-33.893053	151.145891	1		install new kerb ramp	UH230	Secondary	MED	\$	2,500
CD1212	Tralagar Street	Lewisham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.892525	151.144983	1		install new kerb ramp	UH231	Secondary	MED	\$	2,500
CD1219	Charlotte Street	Lewisham	Local Road	crossing deficiency	narrow kerb ramp	-33.878622	151.160481	1		install new kerb ramp	UH232	Secondary	MED	\$	2,500
CD122	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.873465	151.17257	1		install new Tactile Ground Surface Indicators	UH233	Secondary	MED	\$	650
CD1229	Carlington Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895236	151.152736	1		install new kerb ramp - pair	UH234	Secondary	MED	\$	5,000
CD1227	The Boulevard	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.869991	151.162201	1		install new kerb ramp - pair	UH235	Secondary	MED	\$	5,000
CD1228	The Boulevard	Lewisham	Local Road	crossing deficiency	long crossing point	-33.870013	151.162216	1		install kerb extension / refuge island	UH236	Secondary	MED	\$	10,000
CD1229	May Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872587	151.151382	1		install new kerb ramp - pair	UH237	Secondary	MED	\$	5,000
CD123	Annandale Street	Annandale	Local Road	crossing deficiency	missing crossing point	-33.872587	151.172545	1		install new kerb ramp	UH238	Secondary	MED	\$	5,000
CD1230	Helena Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871139	151.160992	1		install new kerb ramp - pair	UH239	Secondary	MED	\$	5,000
CD124	Glendene Drive	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.870851	151.161066	1		install new Tactile Ground Surface Indicators	UH240	Secondary	MED	\$	650
CD1235	Glendene Drive	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.870169	151.161625	1		install new Tactile Ground Surface Indicators	UH241	Secondary	MED	\$	650
CD1236	Balmann Road	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.873733	151.160391	1		install new kerb ramp	UH242				

P4909 Inner West PAMP Detailed Works Program All Treatments 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1246	Church Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870237	151.156706	1		install new kerb ramp - pair	UH249	Secondary	MED		\$ 5,000
CD125	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889006	151.166902	1		install new kerb ramp - pair	UH250	Secondary	MED		\$ 5,000
CD1260	James Street	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.875032	151.155116	1		install new kerb ramp - pair	UH251	Secondary	MED		\$ 2,500
CD1251	James Street	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.874741	151.155206	1		install new kerb ramp	UH252	Secondary	MED		\$ 2,500
CD1254	Frazer Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.870086	151.152039	1		install new kerb ramp - pair	UH253	Secondary	MED		\$ 5,000
CD1255	Glover Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.869573	151.166519	1		install new kerb ramp	UH254	Secondary	MED		\$ 2,500
CD1256	Glover Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.869137	151.166221	1		install new Tactile Ground Surface Indicators	UH255	Secondary	MED		\$ 650
CD1260	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872581	151.164457	1		install new kerb ramp - pair	UH256	Secondary	MED		\$ 5,000
CD1266	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.869597	151.163655	1		install new kerb ramp	UH257	Secondary	MED		\$ 2,500
CD1267	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.869554	151.163460	1		install new kerb ramp - pair	UH258	Secondary	MED		\$ 5,000
CD1268	Grove Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.869444	151.163364	1		install new kerb ramp - pair, and Tactile Ground Surface Indicators	UH259	Secondary	MED		\$ 6,300
CD1269	City West Link Bridge	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.874603	151.154996	1		install new kerb ramp	UH260	Secondary	MED		\$ 2,500
CD127	Annandale Street	Annandale	Local Road	crossing deficiency	driver confusion at unconventional crossing	-33.875853	151.171631	1		further investigation required - pedestrian crossing	UH261	Secondary	MED		\$ 10,000
CD1270	Foucart Lane	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.871631	151.169173	1		install new kerb ramp	UH262	Secondary	MED		\$ 2,500
CD1271	Cecily Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.871877	151.16884	1		install new kerb ramp	UH263	Secondary	MED		\$ 2,500
CD1272	Cecily Lane	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872049	151.168409	1		install new kerb ramp - pair	UH264	Secondary	MED		\$ 5,000
CD1273	Lamb Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872563	151.167217	1		install new kerb ramp - pair	UH265	Secondary	MED		\$ 5,000
CD1274	Lamb Lane	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872726	151.16665	1		install new kerb ramp	UH266	Secondary	MED		\$ 2,500
CD1275	Justin Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872779	151.166326	1		install new kerb ramp - pair	UH267	Secondary	MED		\$ 5,000
CD1276	Halboun Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873022	151.165352	1		install new kerb ramp - pair	UH268	Secondary	MED		\$ 5,000
CD1277	Grove Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.873266	151.164719	1		install new kerb ramp - pair	UH269	Secondary	MED		\$ 5,000
CD1278	Catherine Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873326	151.16443	1		install new kerb ramp - pair	UH270	Secondary	MED		\$ 5,000
CD1279	Lilyfield Road	Lilyfield	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.873596	151.165801	1		install new Tactile Ground Surface Indicators	UH271	Secondary	MED		\$ 650
CD128	Taylor Street	Annandale	Local Road	crossing deficiency	steep kerb ramp - pair	-33.88276	151.174586	1		install new kerb ramp	UH272	Secondary	MED		\$ 2,500
CD1280	Trevor Street	Lilyfield	Regional Road	crossing deficiency	misaligned kerb ramp	-33.87363	151.162639	1		install new kerb ramp	UH273	Secondary	MED		\$ 2,500
CD1281	Lilyfield Road	Lilyfield	Regional Road	crossing deficiency	missing kerb ramp	-33.873268	151.164257	1		install new kerb ramp	UH274	Secondary	MED		\$ 2,500
CD1282	Lilyfield Road	Lilyfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874368	151.160715	1		install new kerb ramp - pair	UH275	Secondary	MED		\$ 5,000
CD1283	Balmann Road	Lilyfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874159	151.160669	1		install new kerb ramp - pair	UH276	Secondary	MED		\$ 5,000
CD1284	Edward Street	Lilyfield	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.873954	151.161247	1		install new kerb ramp	UH277	Secondary	MED		\$ 2,500
CD1286	Henry Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.874095	151.157177	1		install new kerb ramp	UH278	Secondary	MED		\$ 2,500
CD1287	Norton Road	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873755	151.155843	1		install new kerb ramp - pair	UH279	Secondary	MED		\$ 5,000
CD1288	Norton Road	Lilyfield	Local Road	crossing deficiency	missing refuge island	-33.873748	151.155973	1		install new refuge island	UH280	Secondary	MED		\$ 15,000
CD1289	James Street	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.873586	151.15521	1		install new kerb ramp	UH281	Secondary	MED		\$ 2,500
CD1287	Steward Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873744	151.156417	1		install new kerb ramp	UH282	Secondary	MED		\$ 2,500
CD1289	Rayner Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874268	151.158929	1		install new kerb ramp - pair	UH283	Secondary	MED		\$ 5,000
CD1289	Lilyfield Road	Lilyfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.872254	151.167973	1		install new kerb ramp - pair	UH284	Secondary	MED		\$ 5,000
CD131	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889698	151.165503	1		install new kerb ramp	UH285	Secondary	MED		\$ 2,500
CD1330	Lilyfield Road	Lilyfield	Regional Road	crossing deficiency	missing crossing point - future park access	-33.872249	151.167827	1		install new kerb ramp - pair, new refuge island	UH286	Secondary	MED		\$ 7,000
CD131	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880436	151.167526	1		install new kerb ramp - pair	UH287	Secondary	MED		\$ 5,000
CD1311	James Street	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.873679	151.155236	1		install new kerb ramp	UH288	Secondary	MED		\$ 2,500
CD1314	Perry Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.872466	151.165553	1		install new kerb ramp - pair	UH289	Secondary	MED		\$ 5,000
CD1319	Steward Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.87402	151.156049	1		install new kerb ramp	UH290	Secondary	MED		\$ 2,500
CD132	Booth Street	Annandale	Regional Road	crossing deficiency	missing kerb ramp	-33.880609	151.168088	1		install new kerb ramp	UH291	Secondary	MED		\$ 2,500
CD1325	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.876647	151.165703	1		install new kerb ramp	UH292	Secondary	MED		\$ 2,500
CD133	Young Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.889553	151.168253	1		install new kerb ramp	UH293	Secondary	MED		\$ 2,500
CD1334	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875417	151.161043	1		install new kerb ramp - pair	UH294	Secondary	MED		\$ 5,000
CD1335	Addison Road	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.903008	151.165389	1		install new pedestrian refuge	UH295	Secondary	MED		\$ 15,000
CD1336	Addison Road	Marrickville	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.899699	151.157739	1		further investigation required - pedestrian crossing	UH296	Secondary	MED		\$ 10,000
CD1338	Canby Street	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.918003	151.151776	1		further investigation required - pedestrian crossing	UH297	Secondary	MED		\$ 10,000
CD1339	Cook Road	Marrickville	Local Road	crossing deficiency	long crossing	-33.905699	151.16609	1		install kerb blisters/built outs	UH298	Secondary	MED		\$ 10,000
CD134	Young Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.880701	151.168339	1		install new kerb ramp	UH299	Secondary	MED		\$ 2,500
CD1340	Hawthurst Road	Marrickville	Local Road	crossing deficiency	long crossing	-33.905714	151.15449	1		install kerb extensions	UH300	Secondary	MED		\$ 10,000
CD1341	Livingstone Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.903998	151.153226	1		further investigation required - pedestrian crossing	UH301	Secondary	MED		\$ 10,000
CD1342	Livingstone Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.912787	151.147235	1		further investigation required - pedestrian crossing	UH302	Secondary	MED		\$ 10,000
CD1343	Livingstone Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.912133	151.161624	1		further investigation required - pedestrian crossing	UH303	Secondary	MED		\$ 10,000
CD1344	Thompson Street	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.908065	151.151796	1		further investigation required - pedestrian crossing	UH304	Secondary	MED		\$ 10,000
CD1345	Thornley Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp - pair	-33.919773	151.146799	1		install new kerb ramp - pair	UH305	Secondary	MED		\$ 5,000
CD1346	Warren Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.915051	151.148765	1		further investigation required - pedestrian crossing	UH306	Secondary	MED		\$ 10,000
CD1347	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.899919	151.157784	1		install new kerb ramp	UH307	Secondary	MED		\$ 2,500
CD1348	Park Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.899996	151.157813	1		install new kerb ramp	UH308	Secondary	MED		\$ 2,500
CD1349	Neville Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.900342	151.15863	1		install new kerb ramp	UH309	Secondary	MED		\$ 2,500
CD135	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.880699	151.168321	1		install new kerb ramp	UH310	Secondary	MED		\$ 2,500
CD1360	Bright Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900443	151.159208	1		install new kerb ramp	UH311	Secondary	MED		\$ 2,500
CD1361	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.901101	151.160811	1		install new kerb ramp	UH312	Secondary	MED		\$ 2,500
CD1362	East Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901316	151.16135	1		install new kerb ramp - pair	UH313	Secondary	MED		\$ 5,000
CD1363	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.901343	151.162572	1		install new kerb ramp	UH314	Secondary	MED		\$ 5,000
CD1364	England Avenue	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.901728	151.162544	1		install new kerb ramp	UH315	Secondary	MED		\$ 2,500
CD1366	Shepard Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.902668	151.16447	1		install new kerb ramp	UH316	Secondary	MED		\$ 2,500
CD1367	Perry Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902463	151.165391	1		install new kerb ramp - pair	UH317	Secondary	MED		\$ 5,000
CD1368	Fotheringham Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.903636	151.167729	1		install new Tactile Ground Surface Indicators	UH318	Secondary	MED		\$ 650
CD1369	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.904049	151.168262	1		install new kerb ramp	UH319	Secondary	MED		\$ 2,500
CD136	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.880925	151.169148	1		install new kerb ramp	UH320	Secondary	MED		\$ 2,500
CD1360	Fotheringham Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.903843	151.167892	1		install new Tactile Ground Surface Indicators	UH321	Secondary	MED		\$ 650
CD1361	Addison Road	Marrickville	Regional Road	crossing deficiency	narrow refuge island	-33.904094	151.16834	1		install new refuge island	UH322	Secondary	MED		\$ 15,000
CD1366	Beauchamp Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.914643	151.143401	1		install new Tactile Ground Surface Indicators - pair	UH323	Secondary	MED		\$ 1,300
CD1367	Beauchamp Street	Marrickville	Local Road	crossing deficiency	overhanging vegetation narrows kerb ramp	-33.914	151.145104	1		refer to maintenance	UH324	Secondary	MED		\$ 1,300
CD1368	Beauchamp Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.914169	151.144704	1		install new Tactile Ground Surface Indicators - pair	UH325	Secondary	MED		\$ 1,300
CD1369	Beauchamp Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.913849	151.146222	1		install new kerb ramp - pair	UH326	Secondary	MED		\$ 5,000
CD137	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885377	151.176071	1		consult with City of Sydney	UH327	Secondary	MED		\$ 5,000
CD1370	Calvert Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912469	151.166596	1		install new kerb ramp - pair	UH328	Secondary	MED		\$ 5,000
CD1371	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.912746	151.167186	1		install new Tactile Ground Surface Indicators	UH329	Secondary	MED		\$ 650
CD1372	Calvert Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912831	151.167328	1		install new kerb ramp	UH330	Secondary	MED		\$ 2,500
CD1374	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.913497	151.168675	1		install new Tactile Ground Surface Indicators - pair	UH331	Secondary	MED		\$ 1,300
CD1375	Calvert Street	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.912943	151.167586	1		install new kerb ramp - pair	UH332	Secondary	MED		\$

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1362	Canterbury Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912008	151.155815	-	-	install new kerb ramp - pair	UH340	Secondary	MED	\$	5,000
CD1366	Carlington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920484	151.154511	-	-	install new kerb ramp - pair	UH341	Secondary	MED	\$	5,000
CD1367	Carlington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.920562	151.154468	-	-	install new kerb ramp	UH342	Secondary	MED	\$	2,500
CD1368	Carlington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.922265	151.154021	-	-	install new kerb ramp	UH343	Secondary	MED	\$	2,500
CD1369	Carlingford Parade	Marrickville	Local Road	crossing deficiency	poor kerb ramp construction	-33.933177	151.168132	-	-	install new kerb ramp	UH344	Secondary	MED	\$	2,500
CD1394	Chapel Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.9051	151.161694	-	-	install new Traffic Ground Surface Indicators	UH345	Secondary	MED	\$	650
CD1395	Chapel Street	Marrickville	Local Road	crossing deficiency	narrow kerb ramp	-33.905514	151.162409	-	-	install new kerb ramp	UH346	Secondary	MED	\$	2,500
CD1396	Chapel Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.905506	151.162163	-	-	install new kerb ramp	UH347	Secondary	MED	\$	2,500
CD1397	Chapel Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905528	151.162361	-	-	install new kerb ramp	UH348	Secondary	MED	\$	2,500
CD1398	Chapel Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905982	151.162946	-	-	install new kerb ramp - pair	UH349	Secondary	MED	\$	5,000
CD1399	Chapel Street	Marrickville	Local Road	crossing deficiency	raised kerb ramp tgi - pair	-33.905908	151.162996	-	-	install new kerb ramp	UH350	Secondary	MED	\$	5,000
CD1400	Both Street	Annandale	Regional Road	crossing deficiency	potential build-out to improve crossing and slow vehicles	-33.890576	151.168162	-	-	install kerb extension - pair	UH351	Secondary	MED	\$	20,000
CD1401	Duxley Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.911446	151.143019	-	-	install new kerb ramp	UH352	Secondary	MED	\$	2,500
CD1402	Llewellyn Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.905052	151.173209	-	-	install new kerb ramp	UH353	Secondary	MED	\$	2,500
CD1405	Edinburgh Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.90613	151.17258	-	-	install new Traffic Ground Surface Indicators	UH354	Secondary	MED	\$	2,500
CD1406	Edinburgh Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.909776	151.170625	-	-	install new kerb ramp	UH355	Secondary	MED	\$	2,500
CD1411	Enmore Road	Marrickville	Regional Road	crossing deficiency	narrow pedestrian walking area	-33.904014	151.168283	-	-	install new refuge island	UH356	Secondary	MED	\$	15,000
CD1412	Enmore Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.904189	151.168169	-	-	install new kerb ramp	UH357	Secondary	MED	\$	2,500
CD1414	EWart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.911966	151.139993	-	-	install new kerb ramp	UH358	Secondary	MED	\$	2,500
CD1415	EWart Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912068	151.139958	-	-	install new kerb ramp - pair	UH359	Secondary	MED	\$	5,000
CD1416	EWart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.914898	151.142749	-	-	install new Traffic Ground Surface Indicators	UH360	Secondary	MED	\$	650
CD1419	EWart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.9149	151.142626	-	-	install new Traffic Ground Surface Indicators	UH361	Secondary	MED	\$	650
CD1420	EWart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913973	151.142381	-	-	install new Traffic Ground Surface Indicators - pair	UH363	Secondary	MED	\$	1,300
CD1421	EWart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913564	151.141829	-	-	install new Traffic Ground Surface Indicators - pair	UH364	Secondary	MED	\$	1,300
CD1425	EWart Street	Marrickville	Local Road	crossing deficiency	narrow kerb ramp	-33.911955	151.14001	-	-	install new kerb ramp	UH365	Secondary	MED	\$	2,500
CD1433	Chester Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88561	151.174627	-	-	install new kerb ramp	UH366	Secondary	MED	\$	2,500
CD1432	Regional Road	Marrickville	Regional Road	crossing deficiency	steep kerb ramp	-33.90119	150.753	-	-	install new kerb ramp - pair	UH367	Secondary	MED	\$	2,500
CD1433	Wardell Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.90112	151.149171	-	-	install new kerb ramp - pair	UH368	Secondary	MED	\$	2,500
CD1434	Bishop Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.901035	151.150577	-	-	install new Traffic Ground Surface Indicators - pair	UH369	Secondary	MED	\$	1,300
CD1435	Mill Lane	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.901045	151.151117	-	-	install new kerb ramp - pair	UH370	Secondary	MED	\$	2,500
CD1436	Fraser Street	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.90129	151.153131	-	-	install new kerb ramp	UH371	Secondary	MED	\$	2,500
CD1437	Hawkhurst Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.905466	151.154725	-	-	install new kerb ramp - pair	UH372	Secondary	MED	\$	2,500
CD1438	Hawkhurst Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.905201	151.155626	-	-	install new Traffic Ground Surface Indicators - pair	UH373	Secondary	MED	\$	1,300
CD1439	Hawkhurst Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.904937	151.155769	-	-	install new Traffic Ground Surface Indicators - pair	UH374	Secondary	MED	\$	1,300
CD144	Chester Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885656	151.174627	-	-	install new kerb ramp - pair	UH375	Secondary	MED	\$	5,000
CD1440	Hawkhurst Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.904858	151.155887	-	-	install new Traffic Ground Surface Indicators - pair	UH376	Secondary	MED	\$	1,300
CD1441	Hawkhurst Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.90662	151.154795	-	-	install new kerb ramp - pair	UH377	Secondary	MED	\$	5,000
CD1442	Wydenham Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907617	151.159156	-	-	install new kerb ramp - pair	UH378	Secondary	MED	\$	5,000
CD1444	Illawarra Road	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.906239	151.160376	-	-	install new kerb ramp - pair	UH379	Secondary	MED	\$	5,000
CD1445	Illawarra Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.906141	151.160245	-	-	install new kerb ramp	UH380	Secondary	MED	\$	2,500
CD1446	Illawarra Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.905928	151.161261	-	-	install new Traffic Ground Surface Indicators	UH381	Secondary	MED	\$	5,000
CD1447	Illawarra Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.904518	151.161589	-	-	install new Traffic Ground Surface Indicators	UH382	Secondary	MED	\$	650
CD1448	Illawarra Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.904161	151.161493	-	-	install new Traffic Ground Surface Indicators	UH383	Secondary	MED	\$	650
CD145	Chester Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.885071	151.174468	-	-	install new kerb ramp	UH384	Secondary	MED	\$	2,500
CD1451	Illawarra Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.901465	151.157656	-	-	install new Traffic Ground Surface Indicators - pair	UH385	Secondary	MED	\$	1,300
CD1452	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.916528	151.157662	-	-	install new kerb ramp - pair	UH386	Secondary	MED	\$	5,000
CD1453	Hill Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918828	151.144687	-	-	install new kerb ramp - pair	UH387	Secondary	MED	\$	5,000
CD1454	Illawarra Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919109	151.145367	-	-	install new kerb ramp - pair	UH388	Secondary	MED	\$	5,000
CD1455	Wallace Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919799	151.14467	-	-	install new kerb ramp - pair	UH389	Secondary	MED	\$	5,000
CD1456	Illawarra Road	Marrickville	Regional Road	crossing deficiency	misaligned refuge island	-33.919716	151.144817	-	-	re-construct refuge island	UH390	Secondary	MED	\$	15,000
CD1460	Thornley Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919111	151.145596	-	-	install new kerb ramp - pair	UH391	Secondary	MED	\$	5,000
CD1461	Wane Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.918672	151.147683	-	-	install new kerb ramp - pair	UH392	Secondary	MED	\$	5,000
CD1466	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.910496	151.156326	-	-	install new kerb ramp - pair	UH393	Secondary	MED	\$	5,000
CD1474	Livstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.904991	151.153063	-	-	install new kerb ramp	UH394	Secondary	MED	\$	2,500
CD1475	Livstone Road	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.90507	151.153124	-	-	install new kerb ramp - pair	UH395	Secondary	MED	\$	5,000
CD1476	Livstone Road	Marrickville	Local Road	crossing deficiency	steep roadway crossing point	-33.906768	151.153026	-	-	no action	UH396	Secondary	MED	\$	5,000
CD1477	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.907662	151.152781	-	-	install new Traffic Ground Surface Indicators - pair	UH397	Secondary	MED	\$	1,300
CD148	Wane Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.89601	151.17111	-	-	install new Traffic Ground Surface Indicators	UH398	Secondary	MED	\$	650
CD1481	Livstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907173	151.152702	-	-	install new kerb ramp	UH399	Secondary	MED	\$	2,500
CD1482	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.906315	151.152936	-	-	install new Traffic Ground Surface Indicators - pair	UH400	Secondary	MED	\$	1,300
CD1483	Livstone Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.905148	151.153067	-	-	re-construct refuge island	UH401	Secondary	MED	\$	15,000
CD1484	Livstone Road	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.905601	151.153197	-	-	install new kerb ramp	UH402	Secondary	MED	\$	2,500
CD1485	Livstone Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.904819	151.153102	-	-	re-construct refuge island	UH403	Secondary	MED	\$	15,000
CD1488	Livstone Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.901237	151.153329	-	-	install new kerb ramp	UH404	Secondary	MED	\$	2,500
CD1489	Livstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913858	151.148363	-	-	install new kerb ramp - pair	UH405	Secondary	MED	\$	5,000
CD149	Colins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.89413	151.171282	-	-	install new Traffic Ground Surface Indicators - pair	UH406	Secondary	MED	\$	1,300
CD1490	Livstone Road	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.913723	151.146587	-	-	install new kerb ramp - pair	UH407	Secondary	MED	\$	5,000
CD1492	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911171	151.148871	-	-	install new Traffic Ground Surface Indicators - pair	UH408	Secondary	MED	\$	1,300
CD1493	Livstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.911449	151.148496	-	-	install new kerb ramp - pair	UH409	Secondary	MED	\$	5,000
CD1494	Livstone Road	Marrickville	Local Road	crossing deficiency	long crossing	-33.911434	151.148496	-	-	install kerb extension - pair	UH410	Secondary	MED	\$	20,000
CD1495	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.912101	151.147962	-	-	install new Traffic Ground Surface Indicators - pair	UH411	Secondary	MED	\$	1,300
CD1496	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.912783	151.147314	-	-	install new Traffic Ground Surface Indicators	UH412	Secondary	MED	\$	650
CD1497	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.912573	151.147554	-	-	install new Traffic Ground Surface Indicators	UH413	Secondary	MED	\$	650
CD1499	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.912029	151.148087	-	-	install new Traffic Ground Surface Indicators	UH414	Secondary	MED	\$	650
CD15	Neison Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88274	151.174693	-	-	install new kerb ramp	UH415	Secondary	MED	\$	2,500
CD1508	Wane Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897031	151.166366	-	-	install new kerb ramp - pair	UH416	Secondary	MED	\$	5,000
CD1500	Livstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912	151.148114	-	-	install new kerb ramp	UH417	Secondary	MED	\$	2,500
CD1503	Livstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909686	151.152205	-	-	install new kerb ramp - pair	UH418	Secondary	MED	\$	2,500
CD1505	Shelly Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.904743	151.172497	-	-	install new Traffic Ground Surface Indicators - pair	UH419	Secondary	MED	\$	1,300
CD1506	Lynch Lane	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.904668	151.172613	-	-	install new kerb ramp	UH420	Secondary	MED	\$	2,500
CD1507	O'Connor Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.904374	151.171508	-	-	install new Traffic Ground Surface Indicators - pair	UH421	Secondary	MED	\$	1,300
CD1508	Wane Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.89713	151.17179	-	-	install new kerb ramp	UH422	Secondary	MED	\$	2,500
CD1509	Juliet Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904349	151.171909	-	-	install new kerb ramp - pair	UH423	Secondary	MED	\$	5,000
CD151	Colins Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.893994	151.170422	-	-	install new kerb ramp	UH424	Secondary	MED	\$	2,500
CD1510	Llewellyn Street	Marrickville	Regional Road	crossing deficiency	misaligned refuge island	-33.904124	151.170905	-	-	re-construct refuge island	UH425	Secondary	MED	\$	15,000
CD1513	Harey Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.907134	151.147693	-	-	install new kerb ramp	UH426	Secondary	MED	\$	2,500
CD1514	Wardell Road</														

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1521	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.912331	151.159994	1		install new kerb ramp - pair	UH431	Secondary	MED	\$ 5,000
CD1522	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.911296	151.158077	1		install new kerb ramp	UH432	Secondary	MED	\$ 2,500
CD1523	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.911001	151.157625	1		install new kerb ramp	UH433	Secondary	MED	\$ 2,500
CD1524	Illawarra Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.910503	151.156588	1		install new kerb ramp - pair	UH434	Secondary	MED	\$ 5,000
CD1525	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.910509	151.156445	1		install new kerb ramp	UH435	Secondary	MED	\$ 2,500
CD1526	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910446	151.155426	1		install new Tactile Ground Surface Indicators - pair	UH436	Secondary	MED	\$ 1,300
CD153	Collins Street	Annandale	Local Road	crossing deficiency	driveway as kerb ramp	-33.884612	151.172815	1		no action	UH437	Secondary	MED	\$ -
CD1535	Depoties Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910171	151.155476	1		install new Tactile Ground Surface Indicators - pair	UH438	Secondary	MED	\$ 1,300
CD1536	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at shallow kerb ramp	-33.910534	151.156276	1		install new kerb ramp	UH439	Secondary	MED	\$ 2,500
CD1537	Silver Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911176	151.157155	1		install new Tactile Ground Surface Indicators - pair	UH440	Secondary	MED	\$ 1,300
CD1538	Garners Avenue	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910946	151.157265	1		install new Tactile Ground Surface Indicators - pair	UH441	Secondary	MED	\$ 1,300
CD1539	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.911279	151.158132	1		install new Tactile Ground Surface Indicators	UH442	Secondary	MED	\$ 650
CD154	Collins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884642	151.172484	1		install new Tactile Ground Surface Indicators	UH443	Secondary	MED	\$ 650
CD1540	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911286	151.156301	1		install new Tactile Ground Surface Indicators - pair	UH444	Secondary	MED	\$ 1,300
CD1541	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.912173	151.160052	1		install new kerb ramp	UH445	Secondary	MED	\$ 2,500
CD1542	Marrickville Road	Marrickville	Regional Road	crossing deficiency	narrow refuge island	-33.912187	151.160074	1		install new corner refuge island	UH446	Secondary	MED	\$ 10,000
CD1543	Victoria Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.912378	151.160167	1		install new kerb ramp	UH447	Secondary	MED	\$ 2,500
CD155	Collins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884653	151.172488	1		install new Tactile Ground Surface Indicators	UH448	Secondary	MED	\$ 650
CD1553	Victoria Road	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.912393	151.160118	1		install new kerb ramp	UH449	Secondary	MED	\$ 2,500
CD1555	Murray Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.906463	151.173099	1		install new Tactile Ground Surface Indicators	UH450	Secondary	MED	\$ 650
CD1556	Murray Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.906802	151.172899	1		install new Tactile Ground Surface Indicators	UH451	Secondary	MED	\$ 650
CD156	Collins Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.884662	151.17267	1		install new kerb ramp	UH452	Secondary	MED	\$ 2,500
CD1562	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.901772	151.16912	1		install new Tactile Ground Surface Indicators	UH453	Secondary	MED	\$ 650
CD1563	Newington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901029	151.168763	1		install new kerb ramp	UH454	Secondary	MED	\$ 2,500
CD157	Collins Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882505	151.166587	1		install new kerb ramp	UH455	Secondary	MED	\$ 2,500
CD1570	Newington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.899764	151.163626	1		install new kerb ramp	UH456	Secondary	MED	\$ 2,500
CD1571	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.898155	151.15924	1		install new Tactile Ground Surface Indicators	UH457	Secondary	MED	\$ 650
CD1572	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.886276	151.159071	1		install new Tactile Ground Surface Indicators - pair	UH458	Secondary	MED	\$ 1,300
CD1573	Premier Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.921285	151.153885	1		install new kerb ramp	UH459	Secondary	MED	\$ 2,500
CD1574	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.921018	151.153178	1		install new Tactile Ground Surface Indicators - pair	UH460	Secondary	MED	\$ 1,300
CD1575	Premier Street	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.921114	151.153211	1		install new kerb ramp - pair	UH461	Secondary	MED	\$ 1,300
CD1576	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.921051	151.151801	1		install new Tactile Ground Surface Indicators - pair	UH462	Secondary	MED	\$ 1,300
CD1577	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.919674	151.151554	1		install new Tactile Ground Surface Indicators - pair	UH463	Secondary	MED	\$ 1,300
CD1578	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.920161	151.151813	1		install new Tactile Ground Surface Indicators	UH464	Secondary	MED	\$ 650
CD1579	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.919587	151.150889	1		install new Tactile Ground Surface Indicators	UH465	Secondary	MED	\$ 650
CD158	Young Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.88276	151.167193	1		install new kerb ramp	UH466	Secondary	MED	\$ 2,500
CD1580	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.919902	151.151151	1		install new Tactile Ground Surface Indicators - pair	UH467	Secondary	MED	\$ 1,300
CD1581	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.919903	151.150552	1		install new Tactile Ground Surface Indicators - pair	UH468	Secondary	MED	\$ 1,300
CD1587	Premier Street	Marrickville	Local Road	crossing deficiency	narrow refuge island	-33.921003	151.153154	1		install new refuge island	UH469	Secondary	MED	\$ 15,000
CD1589	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.917837	151.151894	1		install new Tactile Ground Surface Indicators - pair	UH470	Secondary	MED	\$ 1,300
CD159	Collins Lane	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.882695	151.167712	1		install new Tactile Ground Surface Indicators	UH471	Secondary	MED	\$ 650
CD1590	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.918051	151.152221	1		install new Tactile Ground Surface Indicators - pair	UH472	Secondary	MED	\$ 1,300
CD1591	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.918002	151.152283	1		install new Tactile Ground Surface Indicators - pair	UH473	Secondary	MED	\$ 1,300
CD1596	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.917919	151.151761	1		install new Tactile Ground Surface Indicators - pair	UH474	Secondary	MED	\$ 1,300
CD1597	Renwick Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.916842	151.149597	1		install new kerb ramp - pair	UH475	Secondary	MED	\$ 5,000
CD1598	Richardson Crescent	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.922128	151.156436	1		install new kerb ramp - pair	UH476	Secondary	MED	\$ 5,000
CD160	Collins Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88304	151.168311	1		install new kerb ramp	UH477	Secondary	MED	\$ 2,500
CD1601	Richardson Crescent	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.923555	151.155986	1		install new kerb ramp	UH478	Secondary	MED	\$ 2,500
CD1602	Richardson Crescent	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.923516	151.156104	1		install new kerb ramp - pair	UH479	Secondary	MED	\$ 5,000
CD1611	Smidmore Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp - pair	-33.907764	151.171415	1		install new kerb ramp - pair	UH480	Secondary	MED	\$ 5,000
CD1613	Station Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914847	151.156203	1		install new kerb ramp - pair	UH481	Secondary	MED	\$ 5,000
CD1614	Sydenham Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.909566	151.162174	1		install new kerb ramp	UH482	Secondary	MED	\$ 2,500
CD1617	Fair Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.908804	151.160814	1		install new kerb ramp	UH483	Secondary	MED	\$ 2,500
CD1618	Frampson Avenue	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.909246	151.161319	1		install new kerb ramp - pair	UH484	Secondary	MED	\$ 5,000
CD1619	Edward Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.908413	151.160197	1		install new kerb ramp	UH485	Secondary	MED	\$ 2,500
CD162	Collins Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.882554	151.167439	1		install new kerb ramp	UH486	Secondary	MED	\$ 2,500
CD1620	Gorman Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.908181	151.159779	1		install new kerb ramp	UH487	Secondary	MED	\$ 2,500
CD1621	Illawarra Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907578	151.159214	1		install new kerb ramp	UH488	Secondary	MED	\$ 2,500
CD1625	Depoties Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.907124	151.158598	1		re-construct refuge island	UH489	Secondary	MED	\$ 15,000
CD163	Collins Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.882811	151.167121	1		install new kerb ramp	UH490	Secondary	MED	\$ 2,500
CD1634	Cadogan Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911421	151.164611	1		install new Tactile Ground Surface Indicators - pair	UH491	Secondary	MED	\$ 1,300
CD1635	Slane Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911337	151.165339	1		install new Tactile Ground Surface Indicators - pair	UH492	Secondary	MED	\$ 1,300
CD1636	Shirrow Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.912485	151.166024	1		install new Tactile Ground Surface Indicators	UH493	Secondary	MED	\$ 650
CD164	Young Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.882821	151.167196	1		re-construct refuge island	UH494	Secondary	MED	\$ 15,000
CD1640	Sydenham Road	Marrickville	State Road	crossing deficiency	at grade crossing missing tgi - pair	-33.912233	151.165552	1		install new Tactile Ground Surface Indicators - pair	UH495	Secondary	MED	\$ 1,300
CD1641	Sydenham Road	Marrickville	State Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911803	151.164937	1		install new Tactile Ground Surface Indicators - pair	UH496	Secondary	MED	\$ 1,300
CD1642	Sydney Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.911229	151.164271	1		install new kerb ramp	UH497	Secondary	MED	\$ 2,500
CD1643	Vincent Street	Marrickville	Local Road	crossing deficiency	raised kerb ramp lip	-33.910605	151.163438	1		install new kerb ramp	UH498	Secondary	MED	\$ 2,500
CD1645	Faversham Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910337	151.16342	1		install new Tactile Ground Surface Indicators - pair	UH499	Secondary	MED	\$ 1,300
CD1648	Sydney Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp construction	-33.910601	151.171464	1		install new kerb ramp	UH500	Secondary	MED	\$ 2,500
CD1649	Victoria Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment, does not follow desire line	-33.905452	151.169251	1		no action	UH501	Secondary	MED	\$ -
CD165	Collins Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.882789	151.167169	1		install new kerb ramp	UH502	Secondary	MED	\$ 2,500
CD1651	Lock Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.908511	151.166211	1		re-construct refuge island	UH503	Secondary	MED	\$ 15,000
CD1652	Smith Street	Marrickville	Local Road	crossing deficiency	long crossing point	-33.905848	151.165795	1		install new refuge island	UH504	Secondary	MED	\$ 15,000
CD1653	Chapel Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.908616	151.164431	1		install new kerb ramp - pair	UH505	Secondary	MED	\$ 5,000
CD1659	Victoria Road	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.914602	151.156428	1		install new kerb ramp - pair	UH506	Secondary	MED	\$ 5,000
CD166	Hutchinson Street	Marrickville	Regional Road	crossing deficiency	missing kerb ramp	-33.917605	151.168821	1		install new kerb ramp	UH507	Secondary	MED	\$ 2,500
CD1661	Victoria Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.912192	151.160089	1		install new Tactile Ground Surface Indicators	UH508	Secondary	MED	\$ 650
CD1664	Warburton Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.913776	151.151736	1		install new kerb ramp	UH509	Secondary	MED	\$ 2,500
CD167	Hutchinson Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.911699	151.169924	1		install new kerb ramp	UH510	Secondary	MED	\$ 2,500
CD1673	Pine Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.907576	151.144781	1		re-construct refuge island	UH511	Secondary	MED	\$ 15,000
CD1674	Wardell Road	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.908029	151.144207	1		install new kerb ramp - pair	UH512	Secondary	MED	\$ 5,000
CD1676	Riverside Crescent	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.913304	151.158644	1		re-construct refuge island	UH513	Secondary	MED	\$ 15,000
CD1677	Wardell Road	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.91142	151.137776	1		install new kerb ramp - pair	UH514	Secondary	MED	\$ 5,000
CD1678	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914796	151.148406	1		install new kerb ramp	UH515	Secondary	MED	\$ 2,500
CD168	Hutchinson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.875024	151.169932	1		install new kerb ramp	UH516	Secondary	MED	\$ 2,500
CD1682	Warren Road	Marrickville	Local Road	crossing deficiency										

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1691	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91419	151.147391	1		install new kerb ramp - pair	UH522	Secondary	MED		\$ 5,000
CD1694	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp - pair	-33.89517	151.174988	1		install new kerb ramp - pair	UH523	Secondary	MED		\$ 5,000
CD1695	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.89518	151.174988	1		install new kerb ramp	UH524	Secondary	MED		\$ 2,500
CD1696	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89593	151.174984	1		install new kerb ramp	UH525	Secondary	MED		\$ 2,500
CD1697	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.8959	151.17503	1		install new kerb ramp	UH526	Secondary	MED		\$ 2,500
CD1698	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp - pair	-33.89594	151.175733	1		install new kerb ramp - pair	UH527	Secondary	MED		\$ 5,000
CD1699	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89517	151.176303	1		install new kerb ramp	UH528	Secondary	MED		\$ 2,500
CD170	Hutchinson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.875305	151.170671	1		install new kerb ramp - pair	UH529	Secondary	MED		\$ 5,000
CD1700	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89566	151.176329	1		install new kerb ramp	UH530	Secondary	MED		\$ 2,500
CD1701	Albermarle Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.89555	151.176379	1		install new kerb ramp	UH531	Secondary	MED		\$ 2,500
CD1702	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895496	151.176366	1		install new kerb ramp	UH532	Secondary	MED		\$ 2,500
CD1703	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895319	151.176972	1		install new kerb ramp	UH533	Secondary	MED		\$ 2,500
CD1704	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895298	151.177025	1		install new kerb ramp	UH534	Secondary	MED		\$ 2,500
CD1705	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895367	151.176989	1		install new kerb ramp	UH535	Secondary	MED		\$ 2,500
CD1706	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895346	151.177048	1		install new kerb ramp	UH536	Secondary	MED		\$ 2,500
CD1707	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895297	151.177035	1		install new kerb ramp	UH537	Secondary	MED		\$ 2,500
CD1708	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895117	151.177662	1		install new kerb ramp	UH538	Secondary	MED		\$ 2,500
CD1709	Alice Street	Newtown	Regional Road	crossing deficiency	driveway as kerb ramp	-33.904092	151.175913	1		no action	UH539	Secondary	MED		\$
CD171	Hutchinson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.875367	151.170844	1		install new kerb ramp - pair	UH540	Secondary	MED		\$ 5,000
CD1710	Alice Street	Newtown	Regional Road	crossing deficiency	driveway as kerb ramp	-33.903064	151.175963	1		no action	UH541	Secondary	MED		\$
CD1711	Clara Street	Newtown	Local Road	crossing deficiency	at grade crossing missing tps	-33.904065	151.175822	1		install new Tactile Ground Surface Indicators	UH542	Secondary	MED		\$ 650
CD1716	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897555	151.177141	1		install new kerb ramp - pair	UH543	Secondary	MED		\$ 5,000
CD1717	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896881	151.174668	1		install new kerb ramp	UH544	Secondary	MED		\$ 2,500
CD1718	Bedford Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.896276	151.173784	1		install new kerb ramp - pair	UH545	Secondary	MED		\$ 5,000
CD1719	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896204	151.173576	1		install new kerb ramp - pair	UH546	Secondary	MED		\$ 5,000
CD1720	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895305	151.172	1		install new kerb ramp	UH547	Secondary	MED		\$ 2,500
CD1721	Edgeware Road	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907966	151.174811	1		install new kerb ramp	UH548	Secondary	MED		\$ 2,500
CD1729	Enmore Road	Newtown	State Road	crossing deficiency	misaligned kerb ramp	-33.898771	151.174031	1		install new kerb ramp	UH549	Secondary	MED		\$ 2,500
CD1729	Phillip Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.898719	151.173892	1		install new kerb ramp	UH550	Secondary	MED		\$ 2,500
CD173	Hutchinson Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.875346	151.170738	1		install new kerb ramp	UH551	Secondary	MED		\$ 2,500
CD1732	Station Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897244	151.176332	1		install new kerb ramp - pair	UH552	Secondary	MED		\$ 5,000
CD1734	Alice Street	Newtown	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.902894	151.173936	1		install new kerb ramp	UH553	Secondary	MED		\$ 2,500
CD174	Kentville Avenue	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873735	151.174157	1		install new kerb ramp	UH554	Secondary	MED		\$ 2,500
CD1743	Sandbrook Lane	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.894411	151.171971	1		install new kerb ramp	UH555	Secondary	MED		\$ 2,500
CD1744	Lennox Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895465	151.176222	1		install new kerb ramp	UH556	Secondary	MED		\$ 2,500
CD1745	Lennox Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895547	151.176734	1		install new kerb ramp	UH557	Secondary	MED		\$ 2,500
CD1746	Lennox Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895901	151.176485	1		install new kerb ramp	UH558	Secondary	MED		\$ 2,500
CD1750	Phillip Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.898433	151.173284	1		install new kerb ramp	UH559	Secondary	MED		\$ 2,500
CD1751	Phillip Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.897923	151.17355	1		install new kerb ramp	UH560	Secondary	MED		\$ 2,500
CD1752	Phillip Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.897894	151.173575	1		install new kerb ramp	UH561	Secondary	MED		\$ 2,500
CD1753	Phillip Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.897311	151.173267	1		install new kerb ramp - pair	UH562	Secondary	MED		\$ 5,000
CD1754	Phillip Street	Newtown	Local Road	crossing deficiency	damaged kerb ramp - pair	-33.898256	151.173769	1		install new kerb ramp - pair	UH563	Secondary	MED		\$ 5,000
CD1755	Station Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900219	151.177231	1		install new kerb ramp	UH564	Secondary	MED		\$ 2,500
CD1756	Walls Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.905265	151.180217	1		install new kerb ramp	UH565	Secondary	MED		\$ 2,500
CD1757	Walls Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.906109	151.177894	1		install new kerb ramp	UH566	Secondary	MED		\$ 2,500
CD1758	Walls Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.906202	151.177328	1		install new kerb ramp	UH567	Secondary	MED		\$ 2,500
CD1759	Walls Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.906476	151.176455	1		install new kerb ramp	UH568	Secondary	MED		\$ 2,500
CD1760	Palace Street	Petersham	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.892217	151.154283	1		further investigation required - pedestrian crossing	UH699	Secondary	MED		\$ 10,000
CD1761	Condon Avenue	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896987	151.155881	1		install new kerb ramp	UH670	Secondary	MED		\$ 2,500
CD1762	Audley Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.899477	151.154484	1		install new kerb ramp - pair	UH671	Secondary	MED		\$ 5,000
CD1763	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89948	151.154562	1		install new kerb ramp	UH672	Secondary	MED		\$ 2,500
CD1764	Shaw Street	Petersham	Regional Road	crossing deficiency	deep kerb ramp	-33.899523	151.155501	1		install new kerb ramp - pair	UH673	Secondary	MED		\$ 5,000
CD1767	Brighton Street	Petersham	Local Road	crossing deficiency	missing kerb ramp	-33.892211	151.154886	1		install new kerb ramp	UH674	Secondary	MED		\$ 2,500
CD1768	Brighton Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.892187	151.15614	1		install new kerb ramp	UH675	Secondary	MED		\$ 2,500
CD1770	Brighton Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.89307	151.156439	1		re-construct refuge island	UH676	Secondary	MED		\$ 15,000
CD1771	Brighton Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893236	151.150431	1		install new kerb ramp	UH677	Secondary	MED		\$ 2,500
CD1773	Crystal Street	Petersham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.894099	151.157447	1		install new kerb ramp	UH678	Secondary	MED		\$ 2,500
CD1774	Crystal Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.89326	151.157524	1		install new kerb ramp	UH679	Secondary	MED		\$ 2,500
CD1775	Douglas Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.892653	151.15748	1		install new kerb ramp	UH680	Secondary	MED		\$ 2,500
CD1776	Brighton Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89231	151.1579	1		install new kerb ramp	UH681	Secondary	MED		\$ 2,500
CD1777	Croydon Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891117	151.158341	1		install new kerb ramp	UH682	Secondary	MED		\$ 2,500
CD1782	Westbourne Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891903	151.15829	1		install new kerb ramp	UH683	Secondary	MED		\$ 2,500
CD1783	Fraser Street	Petersham	Regional Road	crossing deficiency	missing kerb ramp	-33.900453	151.149176	1		install new kerb ramp	UH684	Secondary	MED		\$ 2,500
CD1784	Jarvie Avenue	Petersham	Local Road	crossing deficiency	at grade crossing missing tps - pair	-33.900685	151.149583	1		install new Tactile Ground Surface Indicators - pair	UH685	Secondary	MED		\$ 1,300
CD1785	Fraser Street	Petersham	Regional Road	crossing deficiency	at grade crossing missing tps	-33.901185	151.153311	1		install new Tactile Ground Surface Indicators	UH686	Secondary	MED		\$ 650
CD1787	Livingstone Road	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.899507	151.153446	1		install new kerb ramp	UH687	Secondary	MED		\$ 2,500
CD1788	Addison Road	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.899416	151.153636	1		install new kerb ramp	UH688	Secondary	MED		\$ 2,500
CD1789	Rosford Avenue	Petersham	Local Road	crossing deficiency	at grade crossing missing tps - pair	-33.897479	151.153493	1		install new Tactile Ground Surface Indicators - pair	UH689	Secondary	MED		\$ 1,300
CD180	Piper Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878533	151.171963	1		install new kerb ramp - pair	UH690	Secondary	MED		\$ 5,000
CD1804	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.898501	151.178465	1		install new Tactile Ground Surface Indicators	UH691	Secondary	MED		\$ 650
CD1805	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.898421	151.180478	1		install new Tactile Ground Surface Indicators	UH692	Secondary	MED		\$ 650
CD1806	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.898306	151.159974	1		install new Tactile Ground Surface Indicators	UH693	Secondary	MED		\$ 650
CD1807	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.898166	151.159542	1		install new Tactile Ground Surface Indicators	UH694	Secondary	MED		\$ 650
CD1808	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.898016	151.159311	1		install new Tactile Ground Surface Indicators	UH695	Secondary	MED		\$ 650
CD1809	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.897997	151.158338	1		install new Tactile Ground Surface Indicators	UH696	Secondary	MED		\$ 650
CD1810	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.897958	151.158323	1		install new Tactile Ground Surface Indicators	UH697	Secondary	MED		\$ 650
CD1811	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.897856	151.158241	1		install new Tactile Ground Surface Indicators	UH698	Secondary	MED		\$ 650
CD1812	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tps	-33.897866	151.157472	1		install new Tactile Ground Surface Indicators	UH699	Secondary	MED		\$ 650
CD1817	Palace Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.892104	151.154319	1		install new kerb ramp	UH600	Secondary	MED		\$ 2,500
CD1818	Palace Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89186	151.154439	1		install new kerb ramp - pair	UH601	Secondary	MED		\$ 5,000
CD1820	Palace Street	Petersham	Local Road	crossing deficiency	missing crossing point	-33.891236	151.154323	1		install new kerb ramp - pair	UH602	Secondary	MED		\$ 2,500
CD1821	Palace Street	Petersham	Local Road	crossing deficiency	missing crossing point	-33.89213	151.154399	1		install new kerb ramp - pair	UH603	Secondary	MED		\$ 5,000
CD1824	West Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.898983	151.149128	1		install new kerb ramp	UH604	Secondary	MED		\$ 2,500
CD1825	Paramatta Road	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896933	151.149158	1		install new kerb ramp - pair	UH605	Secondary	MED		\$ 5,000
CD1826	Park Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896829	151.149494	1							

P4909 Inner West PAMP Detailed Works Program All Treatments 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1835	Railway Street	Petersham	Local Road	crossing deficiency	crossing within roundabout	-33.892246	151.156176	1		install new kerb ramp and reconstruct refuge island	LH613	Secondary	MED		\$ 5,000
CD1836	Chester Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896433	151.156633	1		install new kerb ramp	LH614	Secondary	MED		\$ 2,500
CD1837	Oxford Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.897576	151.155695	1		install new kerb ramp	LH615	Secondary	MED		\$ 2,500
CD1838	Chester Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896421	151.156527	1		install new kerb ramp	LH616	Secondary	MED		\$ 2,500
CD1839	Crystal Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.895605	151.156845	1		install new kerb ramp	LH617	Secondary	MED		\$ 2,500
CD184	Hardy Street	Ashbury	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896624	151.152342	1		install new kerb ramp	LH618	Secondary	MED		\$ 2,500
CD1841	Shaw Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895781	151.156894	1		install new kerb ramp - pair	LH619	Secondary	MED		\$ 5,000
CD1845	Terminus Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893447	151.155858	1		install new kerb ramp	LH620	Secondary	MED		\$ 2,500
CD1847	Terminus Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893415	151.15758	1		install new kerb ramp - pair	LH621	Secondary	MED		\$ 5,000
CD1848	Trafalgar Street	Petersham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.894031	151.151739	1		install new kerb ramp	LH622	Secondary	MED		\$ 2,500
CD1852	Wardell Road	Petersham	Regional Road	crossing deficiency	missing kerb ramp	-33.900952	151.149216	1		install new kerb ramp	LH623	Secondary	MED		\$ 2,500
CD1853	Wardell Road	Petersham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.90096	151.149125	1		install new kerb ramp	LH624	Secondary	MED		\$ 2,500
CD1854	Morgan Street	Petersham	Local Road	crossing deficiency	misaligned refuge island	-33.898719	151.149241	1		re-construct refuge island	LH625	Secondary	MED		\$ 15,000
CD1855	West Street	Petersham	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.89074	151.149006	1		install new Tactile Ground Surface Indicators	LH626	Secondary	MED		\$ 650
CD1859	Station Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890643	151.149052	1		install new kerb ramp	LH627	Secondary	MED		\$ 2,500
CD186	Carlton Crescent	Ashfield	Regional Road	crossing deficiency	missing crossing point	-33.892442	151.143766	1		modify splitter island	LH628	Secondary	MED		\$ 10,000
CD1860	York Crescent	Petersham	Local Road	crossing deficiency	missing kerb ramp	-33.893722	151.150509	1		install new kerb ramp	LH629	Secondary	MED		\$ 2,500
CD1862	Beattie Street	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgi	-33.860575	151.172306	1		install new Tactile Ground Surface Indicators	LH630	Secondary	MED		\$ 650
CD1869	Beattie Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860732	151.171926	1		install new kerb ramp	LH631	Secondary	MED		\$ 2,500
CD1876	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.868344	151.169217	1		install new kerb ramp - pair	LH632	Secondary	MED		\$ 5,000
CD1877	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868314	151.169182	1		install new kerb ramp	LH633	Secondary	MED		\$ 2,500
CD1887	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866197	151.168037	1		install new kerb ramp	LH634	Secondary	MED		\$ 2,500
CD1888	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865765	151.167858	1		install new kerb ramp - pair	LH635	Secondary	MED		\$ 5,000
CD1889	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865942	151.16788	1		install new kerb ramp - pair	LH636	Secondary	MED		\$ 5,000
CD1892	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866908	151.169566	1		install new kerb ramp	LH637	Secondary	MED		\$ 2,500
CD1893	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.867483	151.168794	1		install new kerb ramp - pair	LH638	Secondary	MED		\$ 5,000
CD1894	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.867107	151.169273	1		install new kerb ramp	LH639	Secondary	MED		\$ 2,500
CD1895	Gordon Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866435	151.17260	1		install new kerb ramp	LH640	Secondary	MED		\$ 2,500
CD1899	Alfred Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.867861	151.172611	1		install new kerb ramp	LH641	Secondary	MED		\$ 2,500
CD1900	Gordon Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.867723	151.172764	1		install new kerb ramp	LH642	Secondary	MED		\$ 2,500
CD1901	Gordon Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.867438	151.172728	1		install new Tactile Ground Surface Indicators	LH643	Secondary	MED		\$ 650
CD1902	Gordon Street	Rozelle	Regional Road	crossing deficiency	misaligned kerb ramp	-33.867075	151.172776	1		install new kerb ramp	LH644	Secondary	MED		\$ 2,500
CD1903	Quirk Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866994	151.172778	1		install new kerb ramp - pair	LH645	Secondary	MED		\$ 5,000
CD1904	Gordon Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.866642	151.172681	1		install new Tactile Ground Surface Indicators	LH646	Secondary	MED		\$ 650
CD1905	Prince Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866455	151.172673	1		install new kerb ramp	LH647	Secondary	MED		\$ 2,500
CD1906	Gordon Street	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgi	-33.866475	151.173002	1		install new Tactile Ground Surface Indicators	LH648	Secondary	MED		\$ 650
CD1907	Quirk Street	Rozelle	Local Road	crossing deficiency	misaligned kerb ramp	-33.866952	151.172909	1		install new kerb ramp	LH649	Secondary	MED		\$ 2,500
CD1908	Homes Street	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgi	-33.866716	151.172837	1		install new Tactile Ground Surface Indicators	LH650	Secondary	MED		\$ 650
CD1909	Gordon Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.868078	151.172876	1		install new Tactile Ground Surface Indicators	LH651	Secondary	MED		\$ 650
CD1910	Gordon Street	Rozelle	Regional Road	crossing deficiency	missing crossing point	-33.868523	151.172889	1		install new kerb ramp - pair	LH652	Secondary	MED		\$ 5,000
CD1912	Burt Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp - pair	-33.868676	151.172437	1		install new kerb ramp - pair	LH653	Secondary	MED		\$ 5,000
CD1913	Gordon Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.868544	151.172781	1		install new kerb ramp - pair	LH654	Secondary	MED		\$ 5,000
CD1914	Lifford Road	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.868771	151.172411	1		install new Tactile Ground Surface Indicators	LH655	Secondary	MED		\$ 650
CD1915	Lifford Road	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.869224	151.171724	1		install new Tactile Ground Surface Indicators	LH656	Secondary	MED		\$ 650
CD1916	Lifford Road	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.86845	151.171578	1		install new kerb ramp	LH657	Secondary	MED		\$ 2,500
CD1917	Lifford Road	Rozelle	Regional Road	crossing deficiency	missing crossing point	-33.868693	151.173029	1		install new kerb ramp - pair	LH658	Secondary	MED		\$ 5,000
CD1918	Foucart Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.871332	151.169552	1		install new kerb ramp	LH659	Secondary	MED		\$ 2,500
CD1919	Foucart Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.87142	151.169449	1		install new kerb ramp	LH660	Secondary	MED		\$ 2,500
CD1920	Foucart Lane	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgi	-33.871579	151.169207	1		install new Tactile Ground Surface Indicators	LH661	Secondary	MED		\$ 650
CD1921	Lifford Road	Rozelle	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.869686	151.170823	1		install new kerb ramp - pair	LH662	Secondary	MED		\$ 5,000
CD1922	Lifford Road	Rozelle	Regional Road	crossing deficiency	missing crossing point - future park access	-33.869595	151.171029	1		install new kerb ramp - pair, new refuge island	LH663	Secondary	MED		\$ 7,000
CD1923	Lifford Road	Rozelle	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.870848	151.17022	1		install new kerb ramp - pair	LH664	Secondary	MED		\$ 5,000
CD1924	Lifford Road	Rozelle	Regional Road	crossing deficiency	missing crossing point - future park access	-33.870985	151.170104	1		install new kerb ramp - pair, new refuge island	LH665	Secondary	MED		\$ 7,000
CD1929	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.863648	151.165329	1		install new kerb ramp - pair	LH666	Secondary	MED		\$ 5,000
CD193	Norton Street	Ashfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.891284	151.172931	1		further investigation required - pedestrian crossing	LH667	Secondary	MED		\$ 10,000
CD1930	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.864216	151.165269	1		install new kerb ramp	LH668	Secondary	MED		\$ 2,500
CD1931	Manning Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.865215	151.166302	1		install new kerb ramp	LH669	Secondary	MED		\$ 2,500
CD1932	Mullens Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.863946	151.176639	1		install new Tactile Ground Surface Indicators - pair	LH670	Secondary	MED		\$ 1,300
CD1933	Mullens Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.864031	151.176778	1		install new kerb ramp	LH671	Secondary	MED		\$ 2,500
CD1934	Mansfield Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.86416	151.176741	1		install new kerb ramp	LH672	Secondary	MED		\$ 2,500
CD1935	Mullens Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp - pair	-33.863082	151.176432	1		install new kerb ramp - pair	LH673	Secondary	MED		\$ 5,000
CD1938	Mullens Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.863404	151.176531	1		install new Tactile Ground Surface Indicators - pair	LH674	Secondary	MED		\$ 1,300
CD1939	Robert Street	Rozelle	Regional Road	crossing deficiency	narrow kerb ramp - pair	-33.866163	151.176516	1		install new kerb ramp - pair	LH675	Secondary	MED		\$ 5,000
CD194	Norton Street	Ashfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.891444	151.130048	1		further investigation required - pedestrian crossing	LH676	Secondary	MED		\$ 10,000
CD1940	Crescent Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866634	151.175495	1		install new kerb ramp - pair	LH677	Secondary	MED		\$ 5,000
CD1943	Terry Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861541	151.165483	1		install new kerb ramp - pair	LH678	Secondary	MED		\$ 5,000
CD1945	Terry Street	Rozelle	Local Road	crossing deficiency	narrow refuge island	-33.86069	151.169973	1		install new refuge island	LH679	Secondary	MED		\$ 15,000
CD1946	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.860664	151.169954	1		install new kerb ramp	LH680	Secondary	MED		\$ 2,500
CD1947	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp - pair	-33.860355	151.170337	1		install new kerb ramp - pair	LH681	Secondary	MED		\$ 5,000
CD1948	Terry Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858663	151.171122	1		install new kerb ramp	LH682	Secondary	MED		\$ 2,500
CD1949	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.85877	151.171152	1		install new kerb ramp	LH683	Secondary	MED		\$ 2,500
CD195	Queen Street	Ashfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.892005	151.126778	1		further investigation required - pedestrian crossing	LH684	Secondary	MED		\$ 10,000
CD1960	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp - pair	-33.860453	151.170348	1		install new kerb ramp - pair	LH685	Secondary	MED		\$ 5,000
CD1962	Robert Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.866745	151.175209	1		install new Tactile Ground Surface Indicators	LH686	Secondary	MED		\$ 650
CD1966	Crystal Lane	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.862043	151.167416	1		install new kerb ramp - pair	LH687	Secondary	MED		\$ 5,000
CD1968	Manley Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866143	151.173754	1		install new kerb ramp	LH688	Secondary	MED		\$ 2,500
CD1969	Harley Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865877	151.173553	1		install new kerb ramp - pair	LH689	Secondary	MED		\$ 5,000
CD1960	Robert Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.866664	151.175467	1		install new kerb ramp	LH690	Secondary	MED		\$ 2,500
CD1966	Loughlin Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866075	151.174188	1		install new kerb ramp - pair	LH691	Secondary	MED		\$ 5,000
CD1967	Lifford Road	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.868327	151.175071	1		install new kerb ramp	LH692	Secondary	MED		\$ 2,500
CD1968	Victoria Road	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.867011	151.175164	1		install new kerb ramp	LH693	Secondary	MED		\$ 5,000
CD1971	Campbell Street	St Peters	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.911797	151.177657	1		install new kerb ramp	LH694	Secondary	MED		\$ 2,500
CD1973	Church Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912782	151.176077	1		install new kerb ramp	LH695	Secondary	MED		\$ 2,500
CD1974	Church Street	St Peters	Local Road	crossing deficiency	missing crossing point	-33.913402	151.174549	1		install new kerb ramp - pair	LH696	Secondary	MED		\$ 5,000
CD1975	Church Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91218	151.176576	1		install new kerb ramp - pair	LH697	Secondary	MED		\$ 5,000
CD198															

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1987	Princes Highway	St Peters	State Road	crossing deficiency	missing crossing point	-33.915677	151.174383	1		install new kerb ramp - pair	UH704	Secondary	MED	\$	5,000
CD1988	Canal Road	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915624	151.174683	1		install new kerb ramp - pair	UH705	Secondary	MED	\$	5,000
CD1989	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915554	151.174815	1		install new kerb ramp - pair	UH706	Secondary	MED	\$	5,000
CD1990	Mary Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915454	151.174502	1		install new kerb ramp - pair	UH707	Secondary	MED	\$	5,000
CD1991	Alfred Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915771	151.173918	1		install new kerb ramp - pair	UH708	Secondary	MED	\$	5,000
CD2004	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.88697	151.166512	1		install new Tactile Ground Surface Indicators	UH709	Secondary	MED	\$	650
CD2005	St Peters Street	St Peters	Local Road	crossing deficiency	missing crossing point	-33.912864	151.176709	1		install new kerb ramp - pair	UH710	Secondary	MED	\$	5,000
CD2006	Sutherland Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914086	151.169965	1		install new kerb ramp	UH711	Secondary	MED	\$	2,500
CD2006	Grove Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.913505	151.170742	1		install new kerb ramp	UH712	Secondary	MED	\$	2,500
CD2008	Salisbury Lane	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.909055	151.170547	1		install new kerb ramp	UH713	Secondary	MED	\$	2,500
CD2015	Stanley Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893142	151.15942	1		install new kerb ramp	UH714	Secondary	MED	\$	2,500
CD2022	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879412	151.131048	1		install new kerb ramp - pair	UH715	Secondary	MED	\$	5,000
CD2020	Gordon Crescent	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894369	151.161218	1		install new kerb ramp - pair	UH716	Secondary	MED	\$	5,000
CD2021	Gordon Crescent	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893878	151.15933	1		install new kerb ramp	UH717	Secondary	MED	\$	2,500
CD2026	Harrow Road	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.896372	151.170787	1		install new kerb ramp	UH718	Secondary	MED	\$	2,500
CD2027	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp - pair	-33.897108	151.166888	1		install new kerb ramp - pair	UH719	Secondary	MED	\$	5,000
CD2028	Merchant Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.897108	151.166772	1		install new kerb ramp	UH720	Secondary	MED	\$	2,500
CD2029	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.896971	151.16683	1		install new kerb ramp	UH721	Secondary	MED	\$	2,500
CD2033	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.883402	151.124342	1		install new Tactile Ground Surface Indicators - pair	UH722	Secondary	MED	\$	1,300
CD2030	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.897048	151.166705	1		install new kerb ramp	UH723	Secondary	MED	\$	2,500
CD2031	Merchant Street	Stammore	Local Road	crossing deficiency	raised kerb ramp lip	-33.896977	151.167443	1		install new kerb ramp	UH724	Secondary	MED	\$	2,500
CD2032	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.897299	151.166573	1		install new kerb ramp	UH725	Secondary	MED	\$	2,500
CD2034	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.882725	151.124937	1		install new Tactile Ground Surface Indicators - pair	UH726	Secondary	MED	\$	1,300
CD2041	Parramatta Road	Stammore	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888169	151.165025	1		install new kerb ramp - pair	UH727	Secondary	MED	\$	5,000
CD2042	Bridge Road	Stammore	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887727	151.171561	1		install new kerb ramp - pair	UH728	Secondary	MED	\$	5,000
CD2056	Alt Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.882622	151.124953	1		install new kerb ramp - pair	UH729	Secondary	MED	\$	5,000
CD2054	Railway Avenue	Stammore	Local Road	crossing deficiency	misaligned refuge island	-33.883778	151.167464	1		re-construct refuge island	UH730	Secondary	MED	\$	15,000
CD2066	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.882321	151.124342	1		install new Tactile Ground Surface Indicators - pair	UH731	Secondary	MED	\$	1,300
CD2062	Durham Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891683	151.168495	1		install new kerb ramp	UH732	Secondary	MED	\$	2,500
CD2063	Salisbury Road	Stammore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.891245	151.170413	1		install new kerb ramp	UH733	Secondary	MED	\$	2,500
CD2065	Merchant Street	Stammore	Local Road	crossing deficiency	deep kerb ramp - pair	-33.897056	151.166427	1		install new kerb ramp	UH734	Secondary	MED	\$	2,500
CD2066	Stammore Road	Stammore	State Road	crossing deficiency	misaligned kerb ramp	-33.897611	151.16634	1		install new kerb ramp	UH735	Secondary	MED	\$	2,500
CD2071	Dryden Street	Summer Hill	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.893565	151.132904	1		further investigation required - pedestrian crossing	UH736	Secondary	MED	\$	10,000
CD2072	Smith Street	Summer Hill	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.892707	151.141805	1		further investigation required - pedestrian crossing	UH737	Secondary	MED	\$	10,000
CD2073	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897623	151.134166	1		install new kerb ramp - pair	UH738	Secondary	MED	\$	5,000
CD2077	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	raised kerb ramp lip - pair	-33.891733	151.142156	1		install new kerb ramp - pair	UH739	Secondary	MED	\$	5,000
CD2078	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	missing crossing point	-33.892465	151.14378	1		install new kerb ramp - pair	UH740	Secondary	MED	\$	5,000
CD2080	Pear Mill Way	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.892014	151.142347	1		install new Tactile Ground Surface Indicators	UH741	Secondary	MED	\$	650
CD2081	Frenchs Lane	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889746	151.144604	1		install new kerb ramp - pair	UH742	Secondary	MED	\$	5,000
CD2083	Grosvener Crescent	Summer Hill	Local Road	crossing deficiency	missing crossing point	-33.892461	151.144	1		install new kerb ramp - pair	UH743	Secondary	MED	\$	5,000
CD2085	Henson Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896361	151.134678	1		install new kerb ramp - pair	UH744	Secondary	MED	\$	5,000
CD2086	Herbert Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.896337	151.134492	1		install new kerb ramp - pair	UH745	Secondary	MED	\$	5,000
CD2087	Herbert Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896357	151.135689	1		install new kerb ramp - pair	UH746	Secondary	MED	\$	5,000
CD2089	James Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897295	151.134558	1		install new kerb ramp - pair	UH747	Secondary	MED	\$	5,000
CD2090	James Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897408	151.135881	1		install new kerb ramp - pair	UH748	Secondary	MED	\$	5,000
CD2092	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894977	151.132434	1		install new kerb ramp - pair	UH749	Secondary	MED	\$	5,000
CD2093	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895033	151.133492	1		install new kerb ramp - pair	UH750	Secondary	MED	\$	5,000
CD2094	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895189	151.135637	1		install new kerb ramp - pair	UH751	Secondary	MED	\$	5,000
CD2095	Junction Road	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.895278	151.136607	1		install new Tactile Ground Surface Indicators	UH752	Secondary	MED	\$	650
CD2096	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895299	151.136714	1		install new kerb ramp	UH753	Secondary	MED	\$	2,500
CD2097	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895355	151.137577	1		install new kerb ramp - pair	UH754	Secondary	MED	\$	5,000
CD2098	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895401	151.137187	1		install new kerb ramp	UH755	Secondary	MED	\$	2,500
CD2099	Junction Road	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.895391	151.137155	1		install new Tactile Ground Surface Indicators	UH756	Secondary	MED	\$	650
CD2100	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895341	151.136559	1		install new kerb ramp - pair	UH757	Secondary	MED	\$	5,000
CD2102	Oaklands Avenue	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888194	151.135129	1		install new kerb ramp - pair	UH758	Secondary	MED	\$	5,000
CD2103	Kennington Road	Summer Hill	Local Road	crossing deficiency	long crossing	-33.886392	151.137974	1		install kerb batters/built outs	UH759	Secondary	MED	\$	10,000
CD2104	Grosvener Crescent	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894919	151.132474	1		install new kerb ramp - pair	UH760	Secondary	MED	\$	5,000
CD2106	Nowanite Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892396	151.138896	1		install new kerb ramp - pair	UH761	Secondary	MED	\$	5,000
CD2107	Nowanite Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.894926	151.138734	1		install new Tactile Ground Surface Indicators - pair	UH762	Secondary	MED	\$	1,300
CD2108	Nowanite Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895477	151.138597	1		install new kerb ramp - pair	UH763	Secondary	MED	\$	5,000
CD2109	Nowanite Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89335	151.138692	1		install new kerb ramp - pair	UH764	Secondary	MED	\$	5,000
CD2119	Parramatta Road	Summer Hill	State Road	crossing deficiency	missing kerb ramp	-33.887664	151.141804	1		install new kerb ramp	UH765	Secondary	MED	\$	2,500
CD2122	Prospect Road	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.894463	151.132253	1		install new Tactile Ground Surface Indicators - pair	UH766	Secondary	MED	\$	1,300
CD2123	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88863	151.132295	1		install new kerb ramp - pair	UH767	Secondary	MED	\$	5,000
CD2124	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89353	151.132342	1		install new kerb ramp	UH768	Secondary	MED	\$	2,500
CD2125	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893463	151.132417	1		install new kerb ramp - pair	UH769	Secondary	MED	\$	5,000
CD2126	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898794	151.132216	1		install new kerb ramp - pair	UH770	Secondary	MED	\$	5,000
CD2128	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896284	151.132403	1		install new kerb ramp - pair	UH771	Secondary	MED	\$	5,000
CD2129	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897668	151.132207	1		install new kerb ramp - pair	UH772	Secondary	MED	\$	5,000
CD2133	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp	-33.891594	151.136115	1		install new kerb ramp	UH773	Secondary	MED	\$	2,500
CD2136	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.891819	151.138099	1		install new kerb ramp - pair	UH774	Secondary	MED	\$	5,000
CD2137	Smith Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.892043	151.138786	1		install new Tactile Ground Surface Indicators - pair	UH775	Secondary	MED	\$	1,300
CD2138	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892364	151.140438	1		install new kerb ramp - pair	UH776	Secondary	MED	\$	5,000
CD2139	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892514	151.141703	1		install new kerb ramp - pair	UH777	Secondary	MED	\$	5,000
CD2140	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.892496	151.143564	1		install new kerb ramp - pair	UH778	Secondary	MED	\$	5,000
CD2141	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892622	151.141712	1		install new kerb ramp - pair	UH779	Secondary	MED	\$	5,000
CD2142	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892562	151.140856	1		install new kerb ramp - pair	UH780	Secondary	MED	\$	5,000
CD2143	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892374	151.139908	1		install new kerb ramp - pair	UH781	Secondary	MED	\$	5,000
CD2144	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892089	151.138894	1		install new kerb ramp - pair	UH782	Secondary	MED	\$	5,000
CD2145	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.891823	151.134807	1		install new kerb ramp - pair	UH783	Secondary	MED	\$	5,000
CD2146	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.891707	151.133503	1		install new kerb ramp - pair	UH784	Secondary	MED	\$	5,000
CD2147	Smith Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.89171	151.13323	1		install new Tactile Ground Surface Indicators - pair	UH785	Secondary	MED	\$	1,300
CD2148	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89178	151.132522	1		install new kerb ramp - pair	UH786	Secondary	MED	\$	5,000
CD2149	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891656									

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD2163	George Street	Sydenham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.918021	151.170721	1		install new kerb ramp - pair	UH795	Secondary	MED	\$	5,000
CD2165	Rayway Road	Sydenham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919086	151.169292	1		install new kerb ramp - pair	UH796	Secondary	MED	\$	5,000
CD2166	Rayway Road	Sydenham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919184	151.169188	1		install new kerb ramp - pair	UH797	Secondary	MED	\$	5,000
CD2167	Belmore Street	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920195	151.16791	1		install new kerb ramp - pair	UH798	Secondary	MED	\$	5,000
CD2172	Gannon Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.924783	151.159867	1		install new kerb ramp - pair	UH799	Secondary	MED	\$	5,000
CD2173	Gannon Street	Tempe	Local Road	crossing deficiency	misaligned kerb ramp	-33.923643	151.167903	1		install new kerb ramp	UH800	Secondary	MED	\$	2,500
CD2174	Gannon Street	Tempe	Local Road	crossing deficiency	steep kerb ramp	-33.92325	151.167321	1		install new kerb ramp - pair	UH801	Secondary	MED	\$	5,000
CD2175	Griffiths Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924748	151.156844	1		install new kerb ramp	UH802	Secondary	MED	\$	2,500
CD2176	Griffiths Street	Tempe	Local Road	crossing deficiency	at grade crossing missing tgi	-33.924132	151.156971	1		install new Tactile Ground Surface Indicators	UH803	Secondary	MED	\$	650
CD2177	Gannon Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.925033	151.160336	1		install new kerb ramp	UH804	Secondary	MED	\$	2,500
CD2182	Samuel Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.92094	151.166501	1		install new kerb ramp	UH805	Secondary	MED	\$	2,500
CD2183	Terry Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.920473	151.167509	1		install new kerb ramp	UH806	Secondary	MED	\$	2,500
CD2184	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920502	151.16772	1		install new kerb ramp - pair	UH807	Secondary	MED	\$	5,000
CD2185	Terry Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920496	151.167503	1		install new kerb ramp - pair	UH808	Secondary	MED	\$	5,000
CD2186	Terry Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920534	151.16733	1		install new kerb ramp - pair	UH809	Secondary	MED	\$	5,000
CD2187	Lymerston Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.921107	151.165531	1		install new kerb ramp - pair	UH810	Secondary	MED	\$	5,000
CD2188	Foreman Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.922104	151.16389	1		install new kerb ramp - pair	UH811	Secondary	MED	\$	5,000
CD2190	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.923308	151.162371	1		install new kerb ramp - pair	UH812	Secondary	MED	\$	5,000
CD2195	Belmore Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920626	151.167628	1		install new kerb ramp - pair	UH813	Secondary	MED	\$	5,000
CD2196	Station Street West	Tempe	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.925648	151.159681	1		install new kerb ramp - pair	UH814	Secondary	MED	\$	5,000
CD2202	Pyrmont Bridge Road	Annandale	State Road	crossing deficiency	missing kerb ramp	-33.987268	151.172694	1		install new kerb ramp	UH815	Secondary	MED	\$	2,500
CD2200	Station Street West	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.925714	151.159408	1		install new kerb ramp - pair	UH816	Secondary	MED	\$	5,000
CD2201	Hart Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.925374	151.160182	1		install new kerb ramp - pair	UH817	Secondary	MED	\$	5,000
CD2202	Unwin Bridge Road	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.922365	151.157952	1		install new kerb ramp - pair	UH818	Secondary	MED	\$	5,000
CD2203	Richardson Crescent	Tempe	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.922288	151.158039	1		install new kerb ramp - pair	UH819	Secondary	MED	\$	5,000
CD2204	Unwin Street	Tempe	Local Road	crossing deficiency	at grade crossing missing tgi	-33.92163	151.160547	1		install new Tactile Ground Surface Indicators	UH820	Secondary	MED	\$	650
CD2205	Unwin Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.921685	151.160589	1		install new kerb ramp	UH821	Secondary	MED	\$	2,500
CD2206	Unwin Street	Tempe	Local Road	crossing deficiency	at grade crossing missing tgi	-33.921108	151.159689	1		install new Tactile Ground Surface Indicators	UH822	Secondary	MED	\$	650
CD2207	Unwin Bridge Road	Tempe	Regional Road	crossing deficiency	misaligned kerb ramp	-33.920345	151.160854	1		install new kerb ramp	UH823	Secondary	MED	\$	2,500
CD2227	Carlton Crescent	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898997	151.131654	1		install new kerb ramp - pair	UH824	Secondary	MED	\$	5,000
CD23	Pyrmont Bridge Road	Annandale	State Road	crossing deficiency	missing kerb ramp - pair	-33.987268	151.172694	1		install new kerb ramp - pair	UH825	Secondary	MED	\$	5,000
CD235	Church Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.879492	151.125967	1		install new Tactile Ground Surface Indicators - pair	UH826	Secondary	MED	\$	1,300
CD236	Classid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895787	151.13099	1		install new kerb ramp - pair	UH827	Secondary	MED	\$	5,000
CD24	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp construction	-33.884754	151.161848	1		install new kerb ramp	UH828	Secondary	MED	\$	2,500
CD241	Classid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895868	151.131129	1		install new kerb ramp - pair	UH829	Secondary	MED	\$	5,000
CD242	Classid Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.895844	151.130406	1		install new Tactile Ground Surface Indicators - pair	UH830	Secondary	MED	\$	1,300
CD243	Classid Street	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.895727	151.12976	1		install new kerb ramp	UH831	Secondary	MED	\$	2,500
CD244	Classid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895711	151.127487	1		install new kerb ramp - pair	UH832	Secondary	MED	\$	5,000
CD245	Classid Street	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.89563	151.127516	1		re-construct kerb ramp	UH833	Secondary	MED	\$	15,000
CD246	Classid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895601	151.127633	1		install new kerb ramp - pair	UH834	Secondary	MED	\$	5,000
CD247	Classid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895654	151.126633	1		install new kerb ramp - pair	UH835	Secondary	MED	\$	5,000
CD248	Classid Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.89578	151.126819	1		install new Tactile Ground Surface Indicators	UH836	Secondary	MED	\$	650
CD25	Johnston Street	Annandale	State Road	crossing deficiency	poor kerb ramp alignment	-33.887841	151.167895	1		install new kerb ramp	UH837	Secondary	MED	\$	2,500
CD256	Paramatta Road	Annandale	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88812	151.164827	1		install new kerb ramp - pair	UH838	Secondary	MED	\$	5,000
CD259	Bennell Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884841	151.121621	1		install new kerb ramp - pair	UH839	Secondary	MED	\$	5,000
CD266	Thomas Street	Ashfield	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.886595	151.118683	1		install new kerb ramp - pair	UH840	Secondary	MED	\$	5,000
CD27	Paramatta Road	Annandale	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886641	151.176389	1		install new kerb ramp - pair	UH841	Secondary	MED	\$	5,000
CD270	Church Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878889	151.125595	1		install new kerb ramp - pair	UH842	Secondary	MED	\$	5,000
CD277	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.88402	151.120245	1		install new kerb ramp	UH843	Secondary	MED	\$	2,500
CD278	Elizabeth Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884034	151.120171	1		install new kerb ramp - pair	UH844	Secondary	MED	\$	5,000
CD279	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88414	151.120352	1		install new kerb ramp - pair	UH845	Secondary	MED	\$	5,000
CD280	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.884266	151.12027	1		install new kerb ramp	UH846	Secondary	MED	\$	2,500
CD282	Albert Parade	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882168	151.121631	1		install new kerb ramp	UH847	Secondary	MED	\$	2,500
CD283	Church Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878994	151.12556	1		install new Tactile Ground Surface Indicators	UH848	Secondary	MED	\$	650
CD284	Church Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878977	151.125651	1		install new kerb ramp - pair	UH849	Secondary	MED	\$	5,000
CD287	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877506	151.126853	1		install new kerb ramp - pair	UH850	Secondary	MED	\$	5,000
CD288	Frederick Street	Ashfield	State Road	crossing deficiency	raised kerb ramp lip	-33.877432	151.12884	1		install new kerb ramp	UH851	Secondary	MED	\$	2,500
CD289	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877101	151.12965	1		install new kerb ramp - pair	UH852	Secondary	MED	\$	5,000
CD290	Henry Lane	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877055	151.129214	1		install new kerb ramp - pair	UH853	Secondary	MED	\$	5,000
CD292	Thomas Street	Ashfield	Local Road	crossing deficiency	narrow kerb ramp	-33.88659	151.11862	1		install new kerb ramp	UH854	Secondary	MED	\$	2,500
CD293	Albert Parade	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.882199	151.121631	1		install new kerb ramp - pair	UH855	Secondary	MED	\$	5,000
CD294	Georges River Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893236	151.116927	1		install new kerb ramp - pair	UH856	Secondary	MED	\$	5,000
CD3	Collins Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893822	151.169756	1		install new kerb ramp - pair	UH857	Secondary	MED	\$	5,000
CD300	Blackwood Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892924	151.117156	1		install new kerb ramp - pair	UH858	Secondary	MED	\$	5,000
CD301	Watson Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893406	151.116773	1		install new kerb ramp - pair	UH859	Secondary	MED	\$	5,000
CD305	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903847	151.12669	1		install new kerb ramp - pair	UH860	Secondary	MED	\$	2,500
CD31	Trafalgar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887693	151.169736	1		install new kerb ramp - pair	UH861	Secondary	MED	\$	5,000
CD312	Holden Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893709	151.125363	1		install new Tactile Ground Surface Indicators	UH862	Secondary	MED	\$	650
CD313	Holden Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.89455	151.12516	1		install new Tactile Ground Surface Indicators - pair	UH863	Secondary	MED	\$	1,300
CD314	Holden Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89413	151.125186	1		install new kerb ramp - pair	UH871	Secondary	MED	\$	5,000
CD32	Perivol Road	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888091	151.164942	1		install new kerb ramp - pair	UH865	Secondary	MED	\$	5,000
CD327	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886159	151.138667	1		install new kerb ramp - pair	UH866	Secondary	MED	\$	5,000
CD33	Piper Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.887716	151.126626	1		install new Tactile Ground Surface Indicators	UH867	Secondary	MED	\$	650
CD337	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.885399	151.132029	1		install new kerb ramp	UH868	Secondary	MED	\$	2,500
CD338	Liverpool Road	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.889337	151.1322	1		install new kerb ramp	UH869	Secondary	MED	\$	2,500
CD34	Piper Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.877438	151.138645	1		install new kerb ramp	UH870	Secondary	MED	\$	2,500
CD341	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88478	151.121167	1		install new kerb ramp - pair	UH871	Secondary	MED	\$	5,000
CD343	Markham Place	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88745	151.123253	1		install new kerb ramp	UH872	Secondary	MED	\$	5,000
CD344	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891611	151.117025	1		install new kerb ramp - pair	UH873	Secondary	MED	\$	5,000
CD345	Milton Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891433	151.11702	1		install new kerb ramp - pair	UH874	Secondary	MED	\$	5,000
CD346	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891595	151.11728	1		install new kerb ramp - pair	UH875	Secondary	MED	\$	5,000
CD347	Milton Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891627	151.117178	1		install new kerb ramp - pair	UH876	Secondary	MED	\$	5,000
CD348	Palace Lane	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.894531	151.116216	1		install new Tactile Ground Surface Indicators - pair	UH877	Secondary	MED	\$	1,300
CD349	Park Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891661	151.117417	1		install new kerb ramp	UH878	Secondary	MED	\$	2,500
CD35	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment -										

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD36	Piper Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877452	151.168691	1		install new Tactile Ground Surface Indicators	UH886	Secondary	MED	\$	650
CD371	Orpington Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884446	151.134738	1		install new kerb ramp - pair	UH887	Secondary	MED	\$	5,000
CD372	Orpington Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884439	151.132445	1		install new kerb ramp - pair	UH888	Secondary	MED	\$	5,000
CD374	Orpington Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88449	151.133126	1		install new kerb ramp - pair	UH889	Secondary	MED	\$	5,000
CD375	Orpington Street	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.884454	151.134666	1		install new kerb ramp	UH890	Secondary	MED	\$	2,500
CD376	Palace Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.894608	151.122279	1		install new kerb ramp	UH891	Secondary	MED	\$	2,500
CD377	Palace Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.894644	151.120729	1		install raised continuous footpath and tgi	UH892	Secondary	MED	\$	30,000
CD378	Paramatta Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.884616	151.13549	1		install new kerb ramp	UH893	Secondary	MED	\$	2,500
CD379	Paramatta Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.884616	151.13549	1		install new kerb ramp	UH894	Secondary	MED	\$	2,500
CD38	Piper Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877736	151.168715	1		install new Tactile Ground Surface Indicators	UH895	Secondary	MED	\$	650
CD380	Earle Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.876267	151.129117	1		install new kerb ramp	UH896	Secondary	MED	\$	2,500
CD381	Page Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875644	151.128572	1		install new kerb ramp - pair	UH897	Secondary	MED	\$	5,000
CD382	Paramatta Road	Ashfield	State Road	crossing deficiency	long driveway crossing point	-33.874466	151.128268	1		install new Tactile Ground Surface Indicators	UH898	Secondary	MED	\$	650
CD383	Paramatta Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886063	151.138642	1		install new kerb ramp - pair	UH899	Secondary	MED	\$	5,000
CD384	Premier Street	Ashfield	Local Road	crossing deficiency	long crossing	-33.894036	151.119392	1		install kerb extension - pair	UH900	Secondary	MED	\$	20,000
CD385	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893327	151.127898	1		install new kerb ramp	UH901	Secondary	MED	\$	2,500
CD386	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892037	151.127972	1		install new kerb ramp - pair	UH902	Secondary	MED	\$	5,000
CD388	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891924	151.127821	1		install new kerb ramp - pair	UH903	Secondary	MED	\$	5,000
CD389	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892834	151.12776	1		install new kerb ramp - pair	UH904	Secondary	MED	\$	5,000
CD39	Piper Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.87753	151.168767	1		install new kerb ramp - pair	UH905	Secondary	MED	\$	5,000
CD390	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893553	151.12789	1		install new kerb ramp - pair	UH906	Secondary	MED	\$	5,000
CD391	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894053	151.127545	1		install new kerb ramp - pair	UH907	Secondary	MED	\$	5,000
CD392	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895716	151.127635	1		install new kerb ramp - pair	UH908	Secondary	MED	\$	5,000
CD394	The Esplanade	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.887004	151.123388	1		install new kerb ramp	UH909	Secondary	MED	\$	2,500
CD396	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886529	151.118683	1		install new kerb ramp	UH910	Secondary	MED	\$	2,500
CD397	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886408	151.118019	1		install new kerb ramp - pair	UH911	Secondary	MED	\$	5,000
CD398	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887166	151.120380	1		install new kerb ramp - pair	UH912	Secondary	MED	\$	5,000
CD399	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887507	151.121335	1		install new kerb ramp - pair	UH913	Secondary	MED	\$	5,000
CD4	Collins Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.883608	151.169566	1		install new kerb ramp	UH914	Secondary	MED	\$	2,500
CD40	Pritchard Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.872122	151.173016	1		install new kerb ramp	UH915	Secondary	MED	\$	2,500
CD402	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892076	151.120846	1		install new kerb ramp - pair	UH916	Secondary	MED	\$	5,000
CD403	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891537	151.130115	1		install new kerb ramp	UH917	Secondary	MED	\$	2,500
CD404	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893239	151.130058	1		install new kerb ramp	UH918	Secondary	MED	\$	2,500
CD405	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895694	151.129926	1		install new kerb ramp - pair	UH919	Secondary	MED	\$	5,000
CD406	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895647	151.129761	1		install new kerb ramp - pair	UH920	Secondary	MED	\$	5,000
CD407	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.894725	151.12978	1		install new Tactile Ground Surface Indicators - pair	UH921	Secondary	MED	\$	1,300
CD408	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893345	151.129991	1		install new kerb ramp	UH922	Secondary	MED	\$	2,500
CD409	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.89591	151.129577	1		install new Tactile Ground Surface Indicators - pair	UH923	Secondary	MED	\$	1,300
CD41	Pritchard Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.873684	151.174284	1		install new kerb ramp	UH924	Secondary	MED	\$	2,500
CD410	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897776	151.129517	1		install new kerb ramp - pair	UH925	Secondary	MED	\$	5,000
CD411	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.897847	151.129622	1		install new kerb ramp - pair	UH926	Secondary	MED	\$	5,000
CD412	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.897558	151.129697	1		install new kerb ramp	UH927	Secondary	MED	\$	2,500
CD413	Victoria Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.899408	151.129473	1		install new kerb ramp	UH928	Secondary	MED	\$	2,500
CD414	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.899477	151.12943	1		install new kerb ramp	UH929	Secondary	MED	\$	2,500
CD415	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.898891	151.129585	1		install new kerb ramp - pair	UH930	Secondary	MED	\$	5,000
CD416	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.900689	151.129438	1		install new Tactile Ground Surface Indicators	UH931	Secondary	MED	\$	650
CD417	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.900807	151.129355	1		install new Tactile Ground Surface Indicators - pair	UH932	Secondary	MED	\$	1,300
CD418	Victoria Street	Ashfield	Local Road	crossing deficiency	raised kerb ramp lip	-33.900623	151.129328	1		install new kerb ramp	UH933	Secondary	MED	\$	2,500
CD419	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.901701	151.129439	1		install new kerb ramp - pair	UH934	Secondary	MED	\$	5,000
CD420	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.903343	151.129214	1		install new kerb ramp - pair	UH935	Secondary	MED	\$	5,000
CD421	Beattie Street	Balmoral	Local Road	crossing deficiency	missing kerb ramp - pair	-33.858665	151.177882	1		install new kerb ramp - pair	UH936	Secondary	MED	\$	5,000
CD422	Beattie Street	Balmoral	Local Road	crossing deficiency	missing kerb ramp - pair	-33.858753	151.177628	1		install new kerb ramp - pair	UH937	Secondary	MED	\$	5,000
CD423	Beattie Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857788	151.180893	1		install new kerb ramp	UH938	Secondary	MED	\$	2,500
CD427	Beattie Street	Balmoral	Local Road	crossing deficiency	at grade crossing missing tgi	-33.860229	151.173133	1		install new Tactile Ground Surface Indicators	UH939	Secondary	MED	\$	650
CD428	Beattie Street	Balmoral	Local Road	crossing deficiency	misaligned kerb ramp	-33.860402	151.172678	1		install new kerb ramp	UH940	Secondary	MED	\$	2,500
CD429	Beattie Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860355	151.173269	1		install new kerb ramp	UH941	Secondary	MED	\$	2,500
CD43	Pritchard Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.874991	151.169875	1		install new kerb ramp	UH942	Secondary	MED	\$	2,500
CD430	Beattie Street	Balmoral	Local Road	crossing deficiency	raised kerb ramp lip	-33.859334	151.174707	1		install new kerb ramp	UH943	Secondary	MED	\$	2,500
CD431	Beattie Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859263	151.174797	1		install new kerb ramp	UH944	Secondary	MED	\$	2,500
CD432	Birchgrove Road	Balmoral	Local Road	crossing deficiency	missing kerb ramp - pair	-33.855874	151.175781	1		install new kerb ramp - pair	UH945	Secondary	MED	\$	5,000
CD433	Birchgrove Road	Balmoral	Local Road	crossing deficiency	missing crossing point	-33.854146	151.176157	1		install new kerb ramp - pair	UH946	Secondary	MED	\$	5,000
CD434	Birchgrove Road	Balmoral	Local Road	crossing deficiency	missing crossing point	-33.854646	151.175135	1		install new kerb ramp - pair	UH947	Secondary	MED	\$	5,000
CD435	Birchgrove Road	Balmoral	Local Road	crossing deficiency	missing crossing point	-33.854532	151.175168	1		install new kerb ramp - pair	UH948	Secondary	MED	\$	5,000
CD436	Birchgrove Road	Balmoral	Local Road	crossing deficiency	misaligned kerb ramp	-33.853832	151.176783	1		install new kerb ramp	UH949	Secondary	MED	\$	2,500
CD437	Birchgrove Road	Balmoral	Local Road	crossing deficiency	at grade crossing missing tgi	-33.853253	151.17739	1		install new Tactile Ground Surface Indicators	UH950	Secondary	MED	\$	650
CD4	Pymont Bridge Road	Annandale	State Road	crossing deficiency	at grade crossing missing tgi	-33.886301	151.174784	1		install new Tactile Ground Surface Indicators	UH951	Secondary	MED	\$	650
CD440	Booth Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.86102	151.182127	1		install new kerb ramp	UH952	Secondary	MED	\$	2,500
CD441	Booth Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860346	151.181961	1		install new kerb ramp	UH953	Secondary	MED	\$	2,500
CD445	Curtis Road	Balmoral	Local Road	crossing deficiency	misaligned kerb ramp	-33.857084	151.163177	1		install new kerb ramp	UH954	Secondary	MED	\$	2,500
CD446	Curtis Road	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856909	151.162538	1		install new kerb ramp	UH955	Secondary	MED	\$	2,500
CD447	Curtis Road	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855941	151.161	1		install new kerb ramp	UH956	Secondary	MED	\$	2,500
CD448	Curtis Road	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855487	151.160642	1		install new kerb ramp	UH957	Secondary	MED	\$	2,500
CD449	Curtis Road	Balmoral	Local Road	crossing deficiency	raised kerb ramp lip	-33.854832	151.176923	1		install new kerb ramp	UH958	Secondary	MED	\$	2,500
CD45	Gordon Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.886593	151.174291	1		install new kerb ramp - pair	UH959	Secondary	MED	\$	5,000
CD450	Curtis Road	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854754	151.179224	1		install new kerb ramp	UH960	Secondary	MED	\$	2,500
CD451	Curtis Road	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855016	151.179919	1		install new kerb ramp	UH961	Secondary	MED	\$	2,500
CD452	Curtis Road	Balmoral	Local Road	crossing deficiency	missing kerb ramp	-33.852636	151.180692	1		install new kerb ramp	UH962	Secondary	MED	\$	2,500
CD453	Curtis Road	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855788	151.180987	1		install new kerb ramp	UH963	Secondary	MED	\$	2,500
CD454	Curtis Road	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855614	151.18216	1		install new kerb ramp	UH964	Secondary	MED	\$	2,500
CD457	Elliott Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856533	151.17296	1		install new kerb ramp	UH965	Secondary	MED	\$	2,500
CD458	Darling Street	Balmoral	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.856533	151.178018	1		install new kerb ramp - pair	UH966	Secondary	MED	\$	5,000
CD459	Rowntree Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854667	151.178058	1		install new kerb ramp	UH967	Secondary	MED	\$	2,500
CD46	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884669	151.167662	1		install new kerb ramp - pair	UH968	Secondary	MED	\$	5,000
CD460	Darling Street	Balmoral	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.856176	151.17296	1		install new Tactile Ground Surface Indicators	UH969	Secondary	MED	\$	650
CD461	Elliott Street	Balmoral	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.85667	151.172777	1		install new kerb ramp - pair	UH970	Secondary	MED	\$	

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD481	Glassop Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.854694	151.173664	1		install new kerb ramp	UH977	Secondary	MED	\$	2,500
CD482	Glassop Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.853986	151.175431	1		install new kerb ramp	UH978	Secondary	MED	\$	2,500
CD483	Glassop Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.854003	151.175476	1		install new kerb ramp - pair	UH979	Secondary	MED	\$	5,000
CD484	Glassop Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854104	151.176105	1		install new kerb ramp	UH980	Secondary	MED	\$	2,500
CD485	Glassop Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.854038	151.176149	1		install new kerb ramp	UH981	Secondary	MED	\$	2,500
CD486	Hyam Street	Balmain	Local Road	crossing deficiency	narrow refuge island	-33.862022	151.179699	1		re-construct refuge island	UH982	Secondary	MED	\$	15,000
CD488	Hyam Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861626	151.179708	1		install new kerb ramp - pair	UH983	Secondary	MED	\$	5,000
CD489	Chester Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859868	151.175128	1		install new kerb ramp	UH984	Secondary	MED	\$	2,500
CD492	Hyam Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.861679	151.180288	1		install new kerb ramp - pair	UH985	Secondary	MED	\$	5,000
CD493	Lene Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tsgl - pair	-33.859317	151.184494	1		install new Tactile Ground Surface Indicators - pair	UH986	Secondary	MED	\$	1,300
CD499	Little Llewellyn Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858326	151.177675	1		install new kerb ramp	UH987	Secondary	MED	\$	2,500
CD5	Johnston Street	Annandale	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.836337	151.169661	1		install new kerb ramp - pair	UH988	Secondary	MED	\$	5,000
CD59	Railway Parade	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.872041	151.172221	1		install new kerb ramp	UH989	Secondary	MED	\$	2,500
CD500	Montague Street	Balmain	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.85742	151.177695	1		install new kerb ramp - pair	UH990	Secondary	MED	\$	5,000
CD501	Llewellyn Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857447	151.177628	1		install new kerb ramp	UH991	Secondary	MED	\$	2,500
CD502	Llewellyn Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.85735	151.177725	1		install new kerb ramp - pair	UH992	Secondary	MED	\$	5,000
CD503	Little Beattie Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858477	151.177552	1		install new kerb ramp	UH993	Secondary	MED	\$	2,500
CD504	Little Beattie Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.858521	151.177543	1		install new kerb ramp	UH994	Secondary	MED	\$	2,500
CD505	Mulvena Street	Balmain	Regional Road	crossing deficiency	at grade crossing missing tsgl	-33.859019	151.177509	1		install new Tactile Ground Surface Indicators	UH995	Secondary	MED	\$	650
CD506	Ennis Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.859992	151.177334	1		install new kerb ramp - pair	UH996	Secondary	MED	\$	5,000
CD51	Railway Parade	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872041	151.172179	1		install new kerb ramp	UH997	Secondary	MED	\$	2,500
CD510	Mulvena Street	Balmain	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.862463	151.176427	1		install new kerb ramp - pair	UH998	Secondary	MED	\$	5,000
CD511	Henry Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.862057	151.1763	1		install new Tactile Ground Surface Indicators	UH999	Secondary	MED	\$	650
CD512	Stewards Street	Balmain	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.859656	151.177439	1		install new kerb ramp - pair	UH1000	Secondary	MED	\$	5,000
CD515	Palmer Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tsgl - pair	-33.859203	151.180602	1		install new Tactile Ground Surface Indicators - pair	UH1001	Secondary	MED	\$	1,300
CD516	Palmer Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859628	151.180607	1		install new kerb ramp	UH1002	Secondary	MED	\$	2,500
CD517	Palmer Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859794	151.180777	1		install new kerb ramp	UH1003	Secondary	MED	\$	2,500
CD518	Palmer Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858629	151.179859	1		install new kerb ramp	UH1004	Secondary	MED	\$	2,500
CD519	Palmer Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tsgl - pair	-33.858339	151.17994	1		install new Tactile Ground Surface Indicators - pair	UH1005	Secondary	MED	\$	1,300
CD52	Railway Parade	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872033	151.172093	1		install new kerb ramp	UH1006	Secondary	MED	\$	2,500
CD520	Palmer Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.858708	151.178107	1		install new kerb ramp - pair	UH1007	Secondary	MED	\$	5,000
CD522	Reynolds Street	Balmain	Local Road	crossing deficiency	narrow refuge island	-33.862196	151.179727	1		install new refuge island	UH1008	Secondary	MED	\$	15,000
CD523	Reynolds Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.862278	151.179699	1		install new kerb ramp	UH1009	Secondary	MED	\$	2,500
CD524	Robert Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.861409	151.177409	1		install new kerb ramp - pair	UH1010	Secondary	MED	\$	5,000
CD527	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858177	151.171165	1		install new kerb ramp	UH1011	Secondary	MED	\$	2,500
CD528	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.85758	151.171032	1		install new kerb ramp	UH1012	Secondary	MED	\$	2,500
CD529	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857264	151.171203	1		install new kerb ramp	UH1013	Secondary	MED	\$	2,500
CD3	Railway Parade	Annandale	Local Road	crossing deficiency	long crossing	-33.87702	151.180897	1		install kerb extension / refuge island	UH1014	Secondary	MED	\$	10,000
CD530	Terry Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.858642	151.17123	1		install new Tactile Ground Surface Indicators	UH1015	Secondary	MED	\$	650
CD531	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858626	151.1711	1		install new kerb ramp - pair	UH1016	Secondary	MED	\$	5,000
CD532	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859527	151.171217	1		install new kerb ramp	UH1017	Secondary	MED	\$	2,500
CD533	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858441	151.17123	1		install new kerb ramp - pair	UH1018	Secondary	MED	\$	5,000
CD534	Thames Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.85648	151.185236	1		install new kerb ramp	UH1019	Secondary	MED	\$	2,500
CD538	Worley Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861472	151.177496	1		install new kerb ramp - pair	UH1020	Secondary	MED	\$	5,000
CD537	Worley Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.861195	151.178053	1		install new kerb ramp	UH1021	Secondary	MED	\$	2,500
CD538	Worley Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.861171	151.178159	1		install new kerb ramp	UH1022	Secondary	MED	\$	2,500
CD539	Worley Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.861103	151.178239	1		install new kerb ramp	UH1023	Secondary	MED	\$	2,500
CD54	Rose Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.877058	151.176318	1		install new Tactile Ground Surface Indicators	UH1024	Secondary	MED	\$	650
CD540	Worley Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.859625	151.180566	1		install new kerb ramp	UH1025	Secondary	MED	\$	2,500
CD541	Worley Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.859697	151.18023	1		install new kerb ramp	UH1026	Secondary	MED	\$	2,500
CD545	Worley Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.86073	151.178616	1		install new kerb ramp - pair	UH1027	Secondary	MED	\$	5,000
CD546	Caring Street	Balmain East	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859834	151.180555	1		install new kerb ramp	UH1028	Secondary	MED	\$	2,500
CD55	Rose Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tsgl - pair	-33.877398	151.175914	1		install new Tactile Ground Surface Indicators - pair	UH1029	Secondary	MED	\$	1,300
CD551	Birchgrove Road	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852762	151.178803	1		install new kerb ramp	UH1030	Secondary	MED	\$	2,500
CD552	Birchgrove Road	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856833	151.179075	1		install new kerb ramp	UH1031	Secondary	MED	\$	2,500
CD553	Birchgrove Road	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852513	151.179058	1		install new kerb ramp	UH1032	Secondary	MED	\$	2,500
CD558	Louisa Road	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.846815	151.18544	1		install new kerb ramp	UH1033	Secondary	MED	\$	2,500
CD559	Louisa Road	Birchgrove	Local Road	crossing deficiency	missing kerb ramp - pair	-33.846834	151.185549	1		install new kerb ramp - pair	UH1034	Secondary	MED	\$	5,000
CD56	The Crescent	Annandale	State Road	crossing deficiency	misaligned refuge island	-33.876552	151.176037	1		consult with City of Sydney	UH1035	Secondary	MED	\$	2,500
CD560	Louisa Road	Birchgrove	Local Road	crossing deficiency	missing kerb ramp	-33.846793	151.185472	1		install new kerb ramp	UH1036	Secondary	MED	\$	2,500
CD564	Rowntree Street	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.852054	151.181435	1		install new kerb ramp - pair	UH1037	Secondary	MED	\$	5,000
CD565	Rowntree Street	Birchgrove	Local Road	crossing deficiency	missing kerb ramp	-33.852874	151.181415	1		install new kerb ramp	UH1038	Secondary	MED	\$	2,500
CD566	Rowntree Street	Birchgrove	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.852863	151.181291	1		install new kerb ramp - pair	UH1039	Secondary	MED	\$	5,000
CD567	Rowntree Street	Birchgrove	Local Road	crossing deficiency	missing crossing point	-33.853024	151.181135	1		install new kerb ramp - pair	UH1040	Secondary	MED	\$	5,000
CD569	Rowntree Street	Birchgrove	Local Road	crossing deficiency	missing crossing point	-33.854495	151.178877	1		install new kerb ramp - pair	UH1041	Secondary	MED	\$	5,000
CD57	Annandale Street	Annandale	Local Road	crossing deficiency	missing crossing point	-33.864551	151.187623	1		install new kerb ramp - pair	UH1042	Secondary	MED	\$	5,000
CD571	Australia Street	Camperdown	Local Road	crossing deficiency	misaligned kerb ramp	-33.893259	151.176873	1		install new kerb ramp	UH1043	Secondary	MED	\$	2,500
CD572	Australia Street	Camperdown	Local Road	crossing deficiency	misaligned kerb ramp	-33.893084	151.176762	1		install new kerb ramp	UH1044	Secondary	MED	\$	2,500
CD573	Australia Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89438	151.175753	1		install new kerb ramp	UH1045	Secondary	MED	\$	2,500
CD574	Australia Street	Camperdown	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.897114	151.174473	1		install new Tactile Ground Surface Indicators	UH1046	Secondary	MED	\$	650
CD575	Derby Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889933	151.174715	1		install new kerb ramp - pair	UH1047	Secondary	MED	\$	5,000
CD576	Derby Street	Camperdown	Local Road	crossing deficiency	missing kerb ramp	-33.889908	151.174582	1		install new kerb ramp	UH1048	Secondary	MED	\$	2,500
CD577	Australia Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887169	151.174346	1		install new kerb ramp - pair	UH1049	Secondary	MED	\$	5,000
CD58	William Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.876294	151.175539	1		install new kerb ramp	UH1050	Secondary	MED	\$	2,500
CD586	Salisbury Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.891852	151.17638	1		install new kerb ramp	UH1051	Secondary	MED	\$	2,500
CD587	Roberts Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891352	151.17787	1		install new kerb ramp - pair	UH1052	Secondary	MED	\$	5,000
CD588	Hopetown Street	Camperdown	Local Road	crossing deficiency	misaligned kerb ramp	-33.891653	151.177029	1		install new kerb ramp	UH1053	Secondary	MED	\$	2,500
CD589	Denison Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891879	151.175472	1		install new kerb ramp - pair	UH1054	Secondary	MED	\$	5,000
CD59	The Crescent	Annandale	State Road	crossing deficiency	missing kerb ramp	-33.876227	151.174983	1		install new kerb ramp	UH1055	Secondary	MED	\$	2,500
CD590	Denison Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891044	151.175489	1		install new kerb ramp - pair	UH1056	Secondary	MED	\$	5,000
CD591	Kingston Lane	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891658	151.175178	1		install new kerb ramp	UH1057	Secondary	MED	\$	2,500
CD592	Church Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875277	151.118565	1		install new kerb ramp	UH1058	Secondary	MED	\$	2,500
CD593	Church Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875917	151.125032	1		install new kerb ramp - pair	UH1059	Secondary	MED	\$	5,000
CD594	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874687	151.124141	1		install new kerb ramp - pair	UH1060	Secondary	MED	\$	5,000
CD595	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873979	151.125053	1		install new kerb ramp	UH106				

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD601	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878458	151.121446	1		install new kerb ramp	UH1068	Secondary	MED	\$	2,500
CD602	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878554	151.120895	1		install new kerb ramp - pair	UH1069	Secondary	MED	\$	5,000
CD603	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880177	151.120274	1		install new kerb ramp - pair	UH1070	Secondary	MED	\$	5,000
CD604	Croydon Road	Croydon	Local Road	crossing deficiency	raised kerb ramp lip - pair	-33.882828	151.118358	1		install new kerb ramp - pair	UH1071	Secondary	MED	\$	5,000
CD605	Croydon Road	Croydon	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.881397	151.119322	1		install new Tactile Ground Surface Indicators	UH1072	Secondary	MED	\$	650
CD606	Croydon Road	Croydon	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.88105	151.119590	1		install new Tactile Ground Surface Indicators	UH1073	Secondary	MED	\$	650
CD607	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878743	151.120455	1		install new kerb ramp - pair	UH1074	Secondary	MED	\$	5,000
CD608	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878624	151.121204	1		install new kerb ramp - pair	UH1075	Secondary	MED	\$	5,000
CD609	Edwin Street	Croydon	Local Road	crossing deficiency	missing kerb ramp - pair	-33.881545	151.118345	1		install new kerb ramp - pair	UH1076	Secondary	MED	\$	5,000
CD610	Edwin Street	Croydon	Local Road	crossing deficiency	missing kerb ramp	-33.881518	151.118159	1		install new kerb ramp	UH1077	Secondary	MED	\$	2,500
CD611	Edwin Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881531	151.118114	1		install new kerb ramp	UH1078	Secondary	MED	\$	2,500
CD612	Edwin Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881493	151.118119	1		install new kerb ramp	UH1079	Secondary	MED	\$	2,500
CD613	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883169	151.116271	1		install new kerb ramp - pair	UH1080	Secondary	MED	\$	5,000
CD614	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88313	151.116118	1		install new kerb ramp	UH1081	Secondary	MED	\$	2,500
CD615	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883001	151.117638	1		install new kerb ramp - pair	UH1082	Secondary	MED	\$	5,000
CD616	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882937	151.117617	1		install new kerb ramp	UH1083	Secondary	MED	\$	2,500
CD617	Edwin Street North	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882951	151.117310	1		install new kerb ramp - pair	UH1084	Secondary	MED	\$	5,000
CD624	Paramatta Road	Croydon	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874099	151.127280	1		install new kerb ramp - pair	UH1085	Secondary	MED	\$	5,000
CD625	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873145	151.126138	1		install new kerb ramp - pair	UH1086	Secondary	MED	\$	5,000
CD626	Scott Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871672	151.123587	1		install new kerb ramp - pair	UH1087	Secondary	MED	\$	5,000
CD627	Paramatta Road	Croydon	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873341	151.121954	1		consult with City of Canada Bay	UH1088	Secondary	MED	\$	5,000
CD628	Paramatta Road	Croydon	State Road	crossing deficiency	missing kerb ramp	-33.873779	151.126963	1		install new kerb ramp	UH1089	Secondary	MED	\$	2,500
CD629	Scott Street	Croydon	Local Road	crossing deficiency	misaligned refuge island	-33.871679	151.123506	1		install new kerb ramp - pair	UH1090	Secondary	MED	\$	5,000
CD630	Thomas Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886013	151.117194	1		install new kerb ramp	UH1091	Secondary	MED	\$	2,500
CD631	Thomas Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88559	151.116671	1		install new kerb ramp	UH1092	Secondary	MED	\$	2,500
CD632	Thomas Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885485	151.116167	1		install new kerb ramp - pair	UH1093	Secondary	MED	\$	5,000
CD633	Thomas Street	Croydon	Local Road	crossing deficiency	misaligned kerb ramp	-33.886453	151.115332	1		install new kerb ramp	UH1094	Secondary	MED	\$	2,500
CD634	Thomas Street	Croydon	Local Road	crossing deficiency	missing crossing point	-33.884063	151.116221	1		install new kerb ramp	UH1095	Secondary	MED	\$	5,000
CD635	Paitley Lane	Croydon	Local Road	crossing deficiency	missing kerb ramp	-33.884453	151.114657	1		install new kerb ramp	UH1096	Secondary	MED	\$	2,500
CD637	Crownwell Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893539	151.115448	1		install new kerb ramp - pair	UH1097	Secondary	MED	\$	5,000
CD638	Leopold Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893766	151.115485	1		install new kerb ramp - pair	UH1098	Secondary	MED	\$	5,000
CD639	Forbes Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893997	151.114423	1		install new kerb ramp - pair	UH1099	Secondary	MED	\$	5,000
CD64	Trafalgar Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.885906	151.170216	1		install new kerb ramp - pair	UH1100	Secondary	MED	\$	5,000
CD640	Georges River Drive	Croydon Park	State Road	crossing deficiency	misaligned kerb ramp	-33.894079	151.113756	1		install new kerb ramp	UH1101	Secondary	MED	\$	2,500
CD641	Hay Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894026	151.113116	1		install new kerb ramp - pair	UH1102	Secondary	MED	\$	5,000
CD642	Georges River Drive	Croydon Park	State Road	crossing deficiency	improve pedestrian access by providing additional crossing	-33.894013	151.113512	1		consult with TfNSW	UH1103	Secondary	MED	\$	-
CD643	Holborow Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893895	151.113611	1		install new kerb ramp - pair	UH1104	Secondary	MED	\$	5,000
CD645	Greenhill Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894254	151.112533	1		install new kerb ramp	UH1105	Secondary	MED	\$	2,500
CD646	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.900752	151.136071	1		install new kerb ramp	UH1106	Secondary	MED	\$	5,000
CD65	Trafalgar Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.886238	151.170991	1		install new Tactile Ground Surface Indicators - pair	UH1107	Secondary	MED	\$	1,300
CD654	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900681	151.132205	1		install new kerb ramp - pair	UH1108	Secondary	MED	\$	5,000
CD656	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.900747	151.136172	1		install new refuge island	UH1109	Secondary	MED	\$	15,000
CD657	Bedford Crescent	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.910735	151.141138	1		install new kerb ramp - pair	UH1110	Secondary	MED	\$	5,000
CD658	Bedford Crescent	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.91061	151.141409	1		install new Tactile Ground Surface Indicators - pair	UH1111	Secondary	MED	\$	1,300
CD659	Blackwood Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.908641	151.141088	1		install new kerb ramp - pair	UH1112	Secondary	MED	\$	5,000
CD66	Trafalgar Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.886646	151.169880	1		install new Tactile Ground Surface Indicators	UH1113	Secondary	MED	\$	650
CD660	Blackwood Lane	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.907346	151.1405	1		install new Tactile Ground Surface Indicators	UH1114	Secondary	MED	\$	650
CD664	Consett Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905711	151.138048	1		install new kerb ramp - pair	UH1115	Secondary	MED	\$	5,000
CD665	Consett Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.906089	151.138683	1		install new kerb ramp	UH1116	Secondary	MED	\$	2,500
CD666	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900977	151.136327	1		install new kerb ramp - pair	UH1117	Secondary	MED	\$	5,000
CD667	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90235	151.137629	1		install new kerb ramp - pair	UH1118	Secondary	MED	\$	5,000
CD668	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903744	151.14087	1		install new kerb ramp - pair	UH1119	Secondary	MED	\$	5,000
CD669	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903624	151.140794	1		install new kerb ramp - pair	UH1120	Secondary	MED	\$	5,000
CD67	Trafalgar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.884183	151.171209	1		install new kerb ramp	UH1121	Secondary	MED	\$	2,500
CD671	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90208	151.137705	1		install new kerb ramp - pair	UH1122	Secondary	MED	\$	5,000
CD672	Dawn Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.896433	151.140269	1		install new kerb ramp	UH1123	Secondary	MED	\$	2,500
CD673	Denison Road	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.90076	151.14118	1		install new Tactile Ground Surface Indicators - pair	UH1124	Secondary	MED	\$	1,300
CD676	Ewart Lane	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.910593	151.139034	1		install new Tactile Ground Surface Indicators	UH1125	Secondary	MED	\$	650
CD677	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909772	151.137742	1		install new kerb ramp - pair	UH1126	Secondary	MED	\$	5,000
CD678	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909936	151.134905	1		install new kerb ramp - pair	UH1127	Secondary	MED	\$	5,000
CD68	Annandale Street	Annandale	Local Road	crossing deficiency	missing crossing point	-33.884693	151.167594	1		install new kerb ramp - pair	UH1128	Secondary	MED	\$	5,000
CD683	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.911787	151.139962	1		install new kerb ramp - pair	UH1129	Secondary	MED	\$	5,000
CD686	Grove Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90231	151.138654	1		install new kerb ramp - pair	UH1130	Secondary	MED	\$	5,000
CD689	Grove Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902315	151.138679	1		install new kerb ramp - pair	UH1131	Secondary	MED	\$	5,000
CD69	Trafalgar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.887785	151.16986	1		install new kerb ramp	UH1132	Secondary	MED	\$	2,500
CD690	Grove Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901149	151.139715	1		install new kerb ramp - pair	UH1133	Secondary	MED	\$	5,000
CD691	Hampstead Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898064	151.137554	1		install new kerb ramp - pair	UH1134	Secondary	MED	\$	5,000
CD692	Hampstead Road	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.898787	151.138333	1		install new kerb ramp	UH1135	Secondary	MED	\$	2,500
CD693	Hampstead Road	Dulwich Hill	Local Road	crossing deficiency	long crossing point	-33.897143	151.136643	1		install kerb extension / refuge island	UH1136	Secondary	MED	\$	10,000
CD694	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.9007281	151.138625	1		install new Tactile Ground Surface Indicators - pair	UH1137	Secondary	MED	\$	1,300
CD696	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.90486	151.140219	1		install new Tactile Ground Surface Indicators - pair	UH1138	Secondary	MED	\$	1,300
CD697	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.904876	151.140428	1		install new Tactile Ground Surface Indicators	UH1139	Secondary	MED	\$	1,300
CD698	Hill Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.901468	151.140193	1		install new Tactile Ground Surface Indicators	UH1140	Secondary	MED	\$	650
CD7	Johnston Street	Annandale	State Road	crossing deficiency	narrow kerb ramp	-33.895516	151.168727	1		install new kerb ramp	UH1141	Secondary	MED	\$	2,500
CD70	Trafalgar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886783	151.169846	1		install new kerb ramp	UH1142	Secondary	MED	\$	2,500
CD700	Keith Lane	Dulwich Hill	Local Road	crossing deficiency	missing kerb ramp	-33.905992	151.140229	1		install new kerb ramp	UH1143	Secondary	MED	\$	2,500
CD701	Keith Lane	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.905877	151.138986	1		install new Tactile Ground Surface Indicators	UH1144	Secondary	MED	\$	650
CD702	Kinross Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906579	151.141114	1		install new kerb ramp - pair	UH1145	Secondary	MED	\$	5,000
CD703	Kinross Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.907195	151.141997	1		install new Tactile Ground Surface Indicators - pair	UH1146	Secondary	MED	\$	1,300
CD704	Kinross Street	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.907195	151.141973	1		re-construct refuge island	UH1147	Secondary	MED	\$	15,000
CD706	Marionville Road	Dulwich Hill	Regional Road	crossing deficiency	misaligned kerb ramp	-33.906833	151.145797	1		install new kerb ramp	UH1148	Secondary	MED	\$	2,500
CD707	Canbury Grove	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.906092	151.145159	1		install new kerb ramp	UH1149	Secondary	MED	\$	2,500
CD71	Trafalgar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886755	151.170025	1		install new kerb ramp - pair	UH1150	Secondary	MED	\$	5,000
CD711	Fraser Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.900765	151.144919	1		install new kerb ramp	UH1151	Secondary			

P4909 Inner West PAMP Detailed Works Program All Treatments 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD742	Rosedale Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896568	151.137297	1		install new kerb ramp - pair	UH1159	Secondary	MED	\$	5,000
CD743	Hampstead Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897116	151.136997	1		install new kerb ramp - pair	UH1160	Secondary	MED	\$	5,000
CD744	Mastroy Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897513	151.136803	1		install new kerb ramp - pair	UH1161	Secondary	MED	\$	5,000
CD745	Dixon Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898483	151.13343	1		install new kerb ramp - pair	UH1162	Secondary	MED	\$	5,000
CD749	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900723	151.132295	1		install new kerb ramp - pair	UH1163	Secondary	MED	\$	5,000
CD755	Tralagar Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.879011	151.173499	1		install new Tactile Ground Surface Indicators	UH1164	Secondary	MED	\$	650
CD756	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.900807	151.141180	1		install new Tactile Ground Surface Indicators - pair	UH1165	Secondary	MED	\$	1,300
CD757	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901677	151.142692	1		install new kerb ramp - pair	UH1167	Secondary	MED	\$	5,000
CD758	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901666	151.142753	1		install new kerb ramp - pair	UH1168	Secondary	MED	\$	5,000
CD759	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.900765	151.141123	1		install new Tactile Ground Surface Indicators - pair	UH1169	Secondary	MED	\$	1,300
CD76	Tralagar Street	Annandale	Local Road	crossing deficiency	missing crossing point	-33.878994	151.173511	1		install new kerb ramp - pair	UH1170	Secondary	MED	\$	5,000
CD760	Tennyson Street	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.911033	151.136997	1		install new kerb ramp - pair	UH1171	Secondary	MED	\$	5,000
CD762	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90943	151.13609	1		install new kerb ramp - pair	UH1172	Secondary	MED	\$	5,000
CD763	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.907188	151.137634	1		install new Tactile Ground Surface Indicators - pair	UH1173	Secondary	MED	\$	1,300
CD765	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp construction	-33.905711	151.137889	1		install new kerb ramp	UH1174	Secondary	MED	\$	2,500
CD766	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905065	151.136063	1		install new kerb ramp	UH1175	Secondary	MED	\$	2,500
CD767	Terry Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.899415	151.137879	1		install new kerb ramp - pair	UH1176	Secondary	MED	\$	5,000
CD768	Barnsbury Grove	Dulwich Hill	Local Road	crossing deficiency	steep kerb ramp	-33.906159	151.146317	1		install new kerb ramp - pair	UH1177	Secondary	MED	\$	5,000
CD769	Wardell Road	Dulwich Hill	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.903822	151.14864	1		install new kerb ramp	UH1178	Secondary	MED	\$	2,500
CD77	Tralagar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.878616	151.174413	1		install new kerb ramp - pair	UH1179	Secondary	MED	\$	5,000
CD770	Wardell Road	Dulwich Hill	Regional Road	crossing deficiency	misaligned refuge island	-33.903771	151.148693	1		re-construct refuge island	UH1180	Secondary	MED	\$	15,000
CD772	Beach Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907764	151.14433	1		install new kerb ramp - pair	UH1181	Secondary	MED	\$	5,000
CD773	Margaret Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.908002	151.143358	1		install new kerb ramp - pair	UH1182	Secondary	MED	\$	5,000
CD777	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.909036	151.143228	1		no action	UH1183	Secondary	MED	\$	5,000
CD78	Tralagar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.877222	151.174338	1		install new kerb ramp	UH1184	Secondary	MED	\$	2,500
CD780	Rosedale Crescent	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91114	151.138129	1		install new kerb ramp - pair	UH1185	Secondary	MED	\$	5,000
CD781	Pile Street	Dulwich Hill	Local Road	crossing deficiency	missing kerb ramp	-33.903333	151.148696	1		install new kerb ramp - pair	UH1186	Secondary	MED	\$	2,500
CD782	Wheaton Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898197	151.139206	1		install new kerb ramp - pair	UH1187	Secondary	MED	\$	5,000
CD783	Wheaton Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898363	151.139855	1		install new kerb ramp - pair	UH1188	Secondary	MED	\$	5,000
CD784	Wheaton Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.898363	151.141712	1		install new Tactile Ground Surface Indicators	UH1189	Secondary	MED	\$	650
CD785	Wheaton Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895535	151.141753	1		install new kerb ramp - pair	UH1190	Secondary	MED	\$	5,000
CD787	Williams Parade	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.902338	151.137903	1		re-construct refuge island	UH1191	Secondary	MED	\$	15,000
CD788	Windsor Road	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.898262	151.138344	1		install new kerb ramp - pair	UH1192	Secondary	MED	\$	5,000
CD789	Windsor Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898363	151.138919	1		install new kerb ramp - pair	UH1193	Secondary	MED	\$	5,000
CD79	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.884692	151.167525	1		install new Tactile Ground Surface Indicators	UH1194	Secondary	MED	\$	650
CD790	Windsor Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.898208	151.139189	1		install new kerb ramp	UH1195	Secondary	MED	\$	2,500
CD791	Windsor Road	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.89812	151.139208	1		install new kerb ramp - pair	UH1196	Secondary	MED	\$	5,000
CD792	Windsor Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898243	151.139042	1		install new kerb ramp - pair	UH1197	Secondary	MED	\$	5,000
CD793	Camden Street	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903062	151.172888	1		install new kerb ramp	UH1198	Secondary	MED	\$	2,500
CD794	Sarah Street	Enmore	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.902519	151.172237	1		install new Tactile Ground Surface Indicators	UH1199	Secondary	MED	\$	650
CD80	Tralagar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.876883	151.174469	1		install new kerb ramp - pair	UH1200	Secondary	MED	\$	5,000
CD805	Liberty Street	Enmore	Regional Road	crossing deficiency	misaligned kerb ramp	-33.896253	151.171009	1		install new kerb ramp	UH1201	Secondary	MED	\$	2,500
CD807	Caversham Street	Enmore	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.896488	151.170925	1		install new kerb ramp - pair	UH1202	Secondary	MED	\$	5,000
CD808	Caversham Street	Enmore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.896268	151.169765	1		install new kerb ramp	UH1203	Secondary	MED	\$	2,500
CD809	Liberty Street	Enmore	Regional Road	crossing deficiency	missing refuge island	-33.895593	151.17135	1		install new refuge island	UH1204	Secondary	MED	\$	15,000
CD809	Llewellyn Street	Enmore	Regional Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.904826	151.173084	1		install new Tactile Ground Surface Indicators	UH1205	Secondary	MED	\$	650
CD811	Phillip Street	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896634	151.173267	1		install new kerb ramp	UH1206	Secondary	MED	\$	2,500
CD813	Liberty Street	Enmore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.898865	151.169667	1		install new kerb ramp	UH1207	Secondary	MED	\$	2,500
CD815	Dalhousie Street	Haberfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.862353	151.137157	1		further investigation required - pedestrian crossing	UH1208	Secondary	MED	\$	10,000
CD817	Ramsay Street	Haberfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.862618	151.140562	1		further investigation required - pedestrian crossing	UH1209	Secondary	MED	\$	10,000
CD82	Tralagar Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.876858	151.174449	1		re-construct refuge island	UH1210	Secondary	MED	\$	15,000
CD820	All Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.879245	151.131218	1		install new kerb ramp - pair	UH1211	Secondary	MED	\$	5,000
CD822	All Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.876936	151.135888	1		install kerb extension - pair	UH1212	Secondary	MED	\$	20,000
CD824	All Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878466	151.131308	1		install new kerb ramp - pair	UH1213	Secondary	MED	\$	5,000
CD825	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88035	151.132199	1		install new kerb ramp - pair	UH1214	Secondary	MED	\$	5,000
CD826	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878733	151.134616	1		install new kerb ramp - pair	UH1215	Secondary	MED	\$	5,000
CD827	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878783	151.134648	1		install new kerb ramp - pair	UH1216	Secondary	MED	\$	5,000
CD828	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878689	151.134937	1		install new kerb ramp - pair	UH1217	Secondary	MED	\$	5,000
CD829	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880429	151.132164	1		install new kerb ramp - pair	UH1218	Secondary	MED	\$	5,000
CD830	Bland Street	Haberfield	Local Road	crossing deficiency	misaligned refuge island	-33.878777	151.134679	1		re-construct refuge island	UH1219	Secondary	MED	\$	15,000
CD831	Boomerang Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.870652	151.145187	1		install new kerb ramp	UH1220	Secondary	MED	\$	2,500
CD832	Boomerang Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.870609	151.145098	1		install new Tactile Ground Surface Indicators	UH1221	Secondary	MED	\$	650
CD833	Boomerang Street	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.872869	151.143609	1		install new kerb ramp - pair	UH1222	Secondary	MED	\$	5,000
CD834	Boomerang Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874688	151.142508	1		install new kerb ramp - pair	UH1223	Secondary	MED	\$	5,000
CD835	Boomerang Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871661	151.142991	1		install new kerb ramp - pair	UH1224	Secondary	MED	\$	2,500
CD836	Boomerang Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.872533	151.143099	1		install new kerb ramp - pair	UH1225	Secondary	MED	\$	5,000
CD84	White Creek	Annandale	Local Road	crossing deficiency	uneven pavement surface	-33.878485	151.16825	1		re-construct footpath pavement	UH1226	Secondary	MED	\$	200
CD841	Dalhousie Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.875754	151.142096	1		install new kerb ramp - pair	UH1227	Secondary	MED	\$	5,000
CD842	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875754	151.142096	1		install new kerb ramp - pair	UH1228	Secondary	MED	\$	5,000
CD843	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877349	151.141137	1		install new kerb ramp - pair	UH1229	Secondary	MED	\$	5,000
CD848	Dalhousie Street	Haberfield	Local Road	crossing deficiency	long driveway crossing point	-33.884254	151.136159	1		install new Tactile Ground Surface Indicators	UH1230	Secondary	MED	\$	650
CD849	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884647	151.136724	1		install new kerb ramp - pair	UH1231	Secondary	MED	\$	5,000
CD85	White Creek	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.883921	151.165206	1		install new kerb ramp - pair	UH1232	Secondary	MED	\$	5,000
CD850	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882105	151.137289	1		install new kerb ramp - pair	UH1233	Secondary	MED	\$	5,000
CD851	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880563	151.135942	1		install new kerb ramp - pair	UH1234	Secondary	MED	\$	5,000
CD852	Denman Avenue	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.878711	151.135313	1		install new kerb ramp - pair	UH1235	Secondary	MED	\$	5,000
CD853	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880847	151.135955	1		install new kerb ramp - pair	UH1236	Secondary	MED	\$	5,000
CD854	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.880605	151.135959	1		install new kerb ramp	UH1237	Secondary	MED	\$	2,500
CD855	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.881104	151.136469	1		install new kerb ramp - pair	UH1238	Secondary	MED	\$	5,000
CD856	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.884907	151.143935	1		install new kerb ramp	UH1239	Secondary	MED	\$	2,500
CD857	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.886367	151.144061	1		install new Tactile Ground Surface Indicators	UH1240	Secondary	MED	\$	650
CD858	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	missing kerb ramp	-33.887186	151.143786	1		install new kerb ramp	UH1241	Secondary	MED	\$	2,500
CD859	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887661	151.143819	1		install new kerb ramp	UH1242	Secondary	MED	\$	2,500
CD86	White Creek	Annandale	Local Road												

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD87	White Creek	Annandale	Local Road	crossing deficiency	missing crossing point	-33.887191	151.162936	1		install new kerb ramp - pair	UH1250	Secondary	MED	\$	5,000
CD870	Paramatta Road	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884557	151.135639	1		install new kerb ramp - pair	UH1251	Secondary	MED	\$	5,000
CD871	Paramatta Road	Haberfield	State Road	crossing deficiency	missing crossing point	-33.880379	151.13227	1		install new kerb ramp - pair	UH1252	Secondary	MED	\$	5,000
CD872	Dobroyd Parade	Haberfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.874427	151.127948	1		install new kerb ramp - pair	UH1253	Secondary	MED	\$	5,000
CD873	Wolsley Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875385	151.128735	1		install new kerb ramp - pair	UH1254	Secondary	MED	\$	5,000
CD877	Rogers Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88391	151.134605	1		install new kerb ramp - pair	UH1255	Secondary	MED	\$	5,000
CD878	Slane Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887467	151.141807	1		install new kerb ramp - pair	UH1256	Secondary	MED	\$	5,000
CD879	Paramatta Road	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887486	151.141723	1		install new kerb ramp - pair	UH1257	Secondary	MED	\$	5,000
CD88	White Creek	Annandale	Local Road	crossing deficiency	at grade crossing missing tssl	-33.887216	151.162943	1		install new Tactile Ground Surface Indicators	UH1258	Secondary	MED	\$	650
CD882	Connor Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.882154	151.140398	1		install new kerb ramp - pair	UH1259	Secondary	MED	\$	5,000
CD883	Connor Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882424	151.140348	1		install new kerb ramp - pair	UH1260	Secondary	MED	\$	5,000
CD885	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877766	151.135654	1		install new kerb ramp	UH1261	Secondary	MED	\$	2,500
CD886	Bland Street	Haberfield	Local Road	crossing deficiency	long crossing point	-33.877731	151.135656	1		install kerb extension - pair	UH1262	Secondary	MED	\$	20,000
CD887	Alt Street	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.876901	151.135659	1		install new kerb ramp	UH1263	Secondary	MED	\$	2,500
CD889	Ramsay Street	Haberfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875302	151.13467	1		install new kerb ramp - pair	UH1264	Secondary	MED	\$	5,000
CD89	White Creek	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.887734	151.162891	1		install new kerb ramp	UH1265	Secondary	MED	\$	2,500
CD900	Ramsay Street	Haberfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.87531	151.134603	1		install new kerb ramp - pair	UH1266	Secondary	MED	\$	5,000
CD905	Ramsay Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.884764	151.14227	1		install new kerb ramp	UH1267	Secondary	MED	\$	2,500
CD906	Ramsay Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885157	151.14271	1		install new kerb ramp - pair	UH1268	Secondary	MED	\$	5,000
CD909	Northcote Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874125	151.135689	1		install new kerb ramp	UH1269	Secondary	MED	\$	5,000
CD9	Johnston Street	Annandale	State Road	crossing deficiency	poor kerb ramp alignment	-33.883866	151.166861	1		install new kerb ramp	UH1270	Secondary	MED	\$	2,500
CD90	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tssl	-33.884711	151.167543	1		install new Tactile Ground Surface Indicators	UH1271	Secondary	MED	\$	650
CD900	Wolsley Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873301	151.132989	1		install new kerb ramp - pair	UH1272	Secondary	MED	\$	5,000
CD901	Ramsay Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.874712	151.133218	1		further investigation required - pedestrian refuge or crossing (signal)	UH1273	Secondary	MED	\$	15,000
CD902	Dobroyd Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873328	151.133192	1		install new kerb ramp - pair	UH1274	Secondary	MED	\$	5,000
CD903	Ramsay Street	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875011	151.134294	1		install new kerb ramp - pair	UH1275	Secondary	MED	\$	5,000
CD904	Ramsay Street	Haberfield	State Road	crossing deficiency	traffic post narrow kerb ramp	-33.874558	151.134273	1		consult with TfNSW	UH1276	Secondary	MED	\$	5,000
CD905	Slane Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886044	151.142449	1		install new kerb ramp - pair	UH1277	Secondary	MED	\$	5,000
CD906	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874494	151.139733	1		install new kerb ramp - pair	UH1278	Secondary	MED	\$	5,000
CD910	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874776	151.139969	1		install new kerb ramp - pair	UH1279	Secondary	MED	\$	5,000
CD911	Waratan Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tssl	-33.874458	151.140138	1		install new Tactile Ground Surface Indicators	UH1280	Secondary	MED	\$	650
CD912	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875231	151.141112	1		install new kerb ramp	UH1281	Secondary	MED	\$	2,500
CD913	Waratan Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.875259	151.141185	1		install kerb extension - pair	UH1282	Secondary	MED	\$	20,000
CD914	Waratan Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tssl	-33.875265	151.141233	1		install new Tactile Ground Surface Indicators	UH1283	Secondary	MED	\$	650
CD92	Widson Street	Annandale	Local Road	crossing deficiency	raised kerb ramp to	-33.878558	151.168177	1		install new kerb ramp	UH1284	Secondary	MED	\$	2,500
CD922	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906481	151.123516	1		install new kerb ramp - pair	UH1285	Secondary	MED	\$	5,000
CD923	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905919	151.12388	1		install new kerb ramp - pair	UH1286	Secondary	MED	\$	5,000
CD924	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905167	151.12432	1		install new kerb ramp - pair	UH1287	Secondary	MED	\$	5,000
CD925	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903876	151.125114	1		install new kerb ramp - pair	UH1288	Secondary	MED	\$	5,000
CD927	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906125	151.127203	1		consult with City of Canterbury-Bankstown	UH1289	Secondary	MED	\$	-
CD928	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906368	151.127146	1		consult with City of Canterbury-Bankstown	UH1290	Secondary	MED	\$	-
CD929	Princes Street	Hurlstone Park	Local Road	crossing deficiency	missing kerb ramp - pair	-33.90558	151.12689	1		consult with City of Canterbury-Bankstown	UH1291	Secondary	MED	\$	5,000
CD93	Widson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878923	151.168207	1		install new kerb ramp	UH1292	Secondary	MED	\$	2,500
CD930	Warkins Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906669	151.12662	1		install new kerb ramp - pair	UH1293	Secondary	MED	\$	5,000
CD931	Queen Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905448	151.127054	1		install new kerb ramp - pair	UH1294	Secondary	MED	\$	5,000
CD932	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90492	151.128402	1		consult with City of Canterbury-Bankstown	UH1295	Secondary	MED	\$	5,000
CD933	Griffiths Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904686	151.128443	1		install new kerb ramp - pair	UH1296	Secondary	MED	\$	5,000
CD934	Long Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.886186	151.14418	1		install new kerb ramp - pair	UH1297	Secondary	MED	\$	5,000
CD936	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886033	151.161891	1		install new kerb ramp	UH1298	Secondary	MED	\$	2,500
CD937	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tssl - pair	-33.886194	151.161818	1		install new Tactile Ground Surface Indicators - pair	UH1299	Secondary	MED	\$	1,300
CD938	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884513	151.162455	1		install new kerb ramp - pair	UH1300	Secondary	MED	\$	5,000
CD939	Styles Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.883161	151.162754	1		install new kerb ramp - pair	UH1301	Secondary	MED	\$	5,000
CD94	Young Street	Annandale	Local Road	crossing deficiency	driveway as kerb ramp	-33.87538	151.170671	1		no action	UH1302	Secondary	MED	\$	5,000
CD940	Catherine Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.883207	151.162799	1		install new kerb ramp - pair	UH1303	Secondary	MED	\$	5,000
CD941	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.883169	151.162851	1		install new kerb ramp	UH1304	Secondary	MED	\$	2,500
CD942	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88313	151.162787	1		install new kerb ramp - pair	UH1305	Secondary	MED	\$	5,000
CD943	Styles Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88314	151.162853	1		install new kerb ramp - pair	UH1306	Secondary	MED	\$	5,000
CD944	Catherine Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.883114	151.162828	1		install new kerb ramp	UH1307	Secondary	MED	\$	2,500
CD945	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tssl	-33.880721	151.163989	1		install new Tactile Ground Surface Indicators	UH1308	Secondary	MED	\$	650
CD946	Catherine Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.880794	151.163585	1		install new kerb ramp - pair	UH1309	Secondary	MED	\$	5,000
CD947	Catherine Street	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.880067	151.163817	1		install new kerb ramp - pair	UH1310	Secondary	MED	\$	5,000
CD948	Catherine Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.876284	151.164092	1		install new kerb ramp	UH1311	Secondary	MED	\$	2,500
CD95	Young Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876127	151.170253	1		install new kerb ramp - pair	UH1312	Secondary	MED	\$	5,000
CD952	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tssl - pair	-33.880657	151.163611	1		install new Tactile Ground Surface Indicators - pair	UH1313	Secondary	MED	\$	1,300
CD953	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tssl - pair	-33.880641	151.163527	1		install new Tactile Ground Surface Indicators - pair	UH1314	Secondary	MED	\$	1,300
CD954	Catherine Street	Leichhardt	Local Road	crossing deficiency	uneven crossing surface	-33.880337	151.163541	1		install new pavement surface	UH1315	Secondary	MED	\$	650
CD956	Francis Lane	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875454	151.154816	1		install new kerb ramp	UH1316	Secondary	MED	\$	2,500
CD957	Francis Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.875426	151.15439	1		install new kerb ramp	UH1317	Secondary	MED	\$	2,500
CD958	Darley Road	Leichhardt	State Road	crossing deficiency	at grade crossing missing tssl	-33.875493	151.153783	1		install new Tactile Ground Surface Indicators	UH1318	Secondary	MED	\$	650
CD959	Hubert Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875475	151.153899	1		install new kerb ramp - pair	UH1319	Secondary	MED	\$	5,000
CD96	Young Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876879	151.170066	1		install new kerb ramp - pair	UH1320	Secondary	MED	\$	5,000
CD960	Darley Road	Leichhardt	State Road	crossing deficiency	at grade crossing missing tssl	-33.875424	151.153789	1		install new Tactile Ground Surface Indicators	UH1321	Secondary	MED	\$	650
CD961	Elswick Lane North	Leichhardt	Local Road	crossing deficiency	narrow kerb	-33.875456	151.154825	1		install new kerb ramp	UH1322	Secondary	MED	\$	2,500
CD962	Elswick Street North	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tssl	-33.875705	151.151505	1		install new Tactile Ground Surface Indicators	UH1323	Secondary	MED	\$	650
CD963	Falls Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876175	151.15057	1		install new kerb ramp - pair	UH1324	Secondary	MED	\$	5,000
CD964	Fall Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.87652	151.150225	1		install new kerb ramp	UH1325	Secondary	MED	\$	2,500
CD965	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877146	151.148491	1		install new kerb ramp	UH1326	Secondary	MED	\$	2,500
CD966	William Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.877231	151.148316	1		install new kerb ramp	UH1327	Secondary	MED	\$	2,500
CD967	Athol Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp construction	-33.878339	151.148209	1		install new kerb ramp	UH1328	Secondary	MED	\$	2,500
CD968	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.877303	151.158188	1		install new kerb ramp - pair	UH1329	Secondary	MED	\$	5,000
CD969	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tssl - pair	-33.878224	151.158317	1		install new Tactile Ground Surface Indicators - pair	UH1330	Secondary	MED	\$	1,300
CD97	Young Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.876904	151.169904	1		install new kerb ramp	UH1331	Secondary	MED	\$	2,500
CD970	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878953	151.158446	1		install new kerb ramp	UH1332	Secondary	MED	\$	2,500
CD972	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tssl	-33.884791	151.152173	1		install new Tactile Ground Surface Indicators	UH1333	Secondary	MED	\$	650
CD974	Elswick Street	Leichhardt	Local												

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD985	Elswick Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.88562	151.15296	1		install new kerb ramp	UH1341	Secondary	MED	\$ 2,500
CD990	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88424	151.15117	1		install new kerb ramp - pair	UH1342	Secondary	MED	\$ 5,000
CD994	Elswick Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.87737	151.15163	1		install new kerb ramp	UH1343	Secondary	MED	\$ 2,500
CD995	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.87754	151.15174	1		install new kerb ramp	UH1344	Secondary	MED	\$ 2,500
CD996	Flood Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.87698	151.15197	1		install new kerb ramp	UH1345	Secondary	MED	\$ 2,500
CD997	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tps	-33.87633	151.15195	1		install new Traffic Ground Surface Indicators	UH1346	Secondary	MED	\$ 500
CD998	Flood Street	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.87781	151.15168	1		install new kerb ramp - pair	UH1347	Secondary	MED	\$ 5,000
CD999	Flood Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.88581	151.14869	1		no action	UH1348	Secondary	MED	\$ -
CI1	Booth Street	Annandale	Regional Road	infrastructure condition	uneven pavement surface	-33.88368	151.17505	1		re-construct footpath pavement	UH1349	Primary	MED	\$ 200
CI10	Knox Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.88264	151.12207	1		re-construct footpath pavement	UH1350	Primary	MED	\$ 200
CI106	Norton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.88971	151.12365	1		re-construct footpath pavement	UH1351	Primary	MED	\$ 200
CI107	Norton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.89121	151.12761	1		re-construct footpath pavement	UH1352	Primary	MED	\$ 200
CI108	Norton Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.89112	151.13031	1		re-construct footpath pavement	UH1353	Primary	MED	\$ 200
CI109	Old Canterbury Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.89406	151.12890	1		re-construct footpath pavement	UH1354	Primary	MED	\$ 200
CI117	Parramatta Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.87794	151.13021	1		re-construct footpath pavement	UH1355	Primary	MED	\$ 200
CI12	Booth Street	Annandale	Regional Road	infrastructure condition	uneven pavement surface	-33.88343	151.17546	1		re-construct footpath pavement	UH1356	Primary	MED	\$ 200
CI133	Lene Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.88625	151.18437	1		re-construct footpath pavement	UH1357	Primary	MED	\$ 200
CI140	Robert Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.88132	151.17724	1		re-construct footpath pavement	UH1358	Primary	MED	\$ 200
CI158	Denison Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90183	151.14032	1		re-construct footpath pavement	UH1359	Primary	MED	\$ 200
CI159	Dulwich Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90276	151.14197	1		re-construct footpath pavement	UH1360	Primary	MED	\$ 200
CI160	Dulwich Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90249	151.14171	1		re-construct footpath pavement	UH1361	Primary	MED	\$ 200
CI173	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.91055	151.13868	1		re-construct footpath pavement	UH1362	Primary	MED	\$ 200
CI192	New Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.90443	151.13916	1		re-construct footpath pavement	UH1363	Primary	MED	\$ 200
CI194	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.90027	151.13291	1		re-construct footpath pavement	UH1364	Primary	MED	\$ 200
CI195	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	raised pavement lip	-33.90048	151.13246	1		repair pavement panel	UH1365	Primary	MED	\$ 200
CI196	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.90275	151.13245	1		re-construct footpath pavement	UH1366	Primary	MED	\$ 200
CI197	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.90264	151.13381	1		re-construct footpath pavement	UH1367	Primary	MED	\$ 200
CI2	Parramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.88772	151.17357	1		re-construct footpath pavement	UH1368	Primary	MED	\$ 200
CI227	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90507	151.13795	1		re-construct footpath pavement	UH1369	Primary	MED	\$ 200
CI231	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.90282	151.14302	1		re-construct footpath pavement	UH1370	Primary	MED	\$ 200
CI232	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.90943	151.14286	1		re-construct footpath pavement	UH1371	Primary	MED	\$ 200
CI233	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.90989	151.14236	1		re-construct footpath pavement	UH1372	Primary	MED	\$ 200
CI234	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.91039	151.14174	1		re-construct footpath pavement	UH1373	Primary	MED	\$ 200
CI267	New Canterbury Road	Hurlstone Park	State Road	infrastructure condition	damaged refuge island	-33.90510	151.13228	1		consult with City of Canterbury-Bankstown	UH1374	Primary	MED	\$ -
CI270	Derbyshire Road	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.88637	151.15877	1		re-construct footpath pavement	UH1375	Primary	MED	\$ 200
CI271	Derbyshire Road	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.88093	151.15874	1		re-construct footpath pavement	UH1376	Primary	MED	\$ 200
CI276	Foster Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.88428	151.14758	1		re-construct footpath pavement	UH1377	Primary	MED	\$ 200
CI277	Lane Road	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.88516	151.14945	1		re-construct footpath pavement	UH1378	Primary	MED	\$ 200
CI278	Marion Street	Leichhardt	Regional Road	infrastructure condition	raised pavement lip	-33.88395	151.15549	1		repair pavement panel	UH1379	Primary	MED	\$ 200
CI280	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.88854	151.15408	1		re-construct footpath pavement	UH1380	Primary	MED	\$ 200
CI282	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.88958	151.14646	1		re-construct footpath pavement	UH1381	Primary	MED	\$ 200
CI283	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.88948	151.14629	1		re-construct footpath pavement	UH1382	Primary	MED	\$ 200
CI284	Renwick Lane	Leichhardt	Local Road	infrastructure condition	faded traffic control marking	-33.88769	151.15791	1		repair pavement marking	UH1383	Primary	MED	\$ 200
CI289	New Canterbury Road	Lewisham	State Road	infrastructure condition	damaged tps	-33.89809	151.14628	1		install new Traffic Ground Surface Indicators	UH1384	Primary	MED	\$ 650
CI29	Nelson Street	Annandale	Local Road	infrastructure condition	raised pavement lip	-33.88273	151.17348	1		repair pavement panel	UH1385	Primary	MED	\$ 200
CI290	Old Canterbury Road	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.89454	151.14489	1		re-construct footpath pavement	UH1386	Primary	MED	\$ 200
CI293	Railway Terrace	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.89431	151.14966	1		re-construct footpath pavement	UH1387	Primary	MED	\$ 200
CI294	Thomas Street	Lewisham	Local Road	infrastructure condition	uneven pavement surface	-33.89336	151.14389	1		re-construct footpath pavement	UH1388	Primary	MED	\$ 200
CI295	Orange Grove Plaza	Livfield	Local Road	infrastructure condition	refer to maintenance	-33.87404	151.16063	1		refer to maintenance	UH1389	Primary	MED	\$ -
CI3	Parramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.88726	151.17122	1		re-construct footpath pavement	UH1390	Primary	MED	\$ 200
CI30	Nelson Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.88216	151.17345	1		re-construct footpath pavement	UH1391	Primary	MED	\$ 200
CI31	Nelson Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.88368	151.17338	1		re-construct footpath pavement	UH1392	Primary	MED	\$ 200
CI319	Dudley Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91144	151.14246	1		re-construct footpath pavement	UH1393	Primary	MED	\$ 200
CI320	Dudley Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91157	151.14203	1		re-construct footpath pavement	UH1394	Primary	MED	\$ 200
CI321	Edgeware Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.90598	151.17344	1		re-construct footpath pavement	UH1395	Primary	MED	\$ 200
CI322	Ermore Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.90572	151.16756	1		re-construct footpath pavement	UH1396	Primary	MED	\$ 200
CI323	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91204	151.14038	1		re-construct footpath pavement	UH1397	Primary	MED	\$ 200
CI324	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91272	151.14076	1		re-construct footpath pavement	UH1398	Primary	MED	\$ 200
CI329	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91338	151.14148	1		re-construct footpath pavement	UH1399	Primary	MED	\$ 200
CI33	Queen Street	Ashfield	Local Road	infrastructure condition	repaint dragons teeth	-33.89103	151.12797	1		refer to maintenance	UH1400	Primary	MED	\$ -
CI345	Ilwara Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.91364	151.15306	1		re-construct footpath pavement	UH1401	Primary	MED	\$ 200
CI346	Ilwara Road	Marrickville	Regional Road	infrastructure condition	trip hazard - raised manhole cover	-33.91479	151.15283	1		repair pit cover	UH1402	Primary	MED	\$ 2,000
CI347	Ilwara Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.91452	151.15349	1		re-construct footpath pavement	UH1403	Primary	MED	\$ 200
CI360	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91076	151.14969	1		re-construct footpath pavement	UH1404	Primary	MED	\$ 200
CI361	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91069	151.15015	1		re-construct footpath pavement	UH1405	Primary	MED	\$ 200
CI363	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.90926	151.15184	1		re-construct footpath pavement	UH1406	Primary	MED	\$ 200
CI364	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.90898	151.15214	1		re-construct footpath pavement	UH1407	Primary	MED	\$ 200
CI365	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.90925	151.15167	1		re-construct footpath pavement	UH1408	Primary	MED	\$ 200
CI366	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91032	151.15077	1		re-construct footpath pavement	UH1409	Primary	MED	\$ 200
CI369	Marrickville Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.91387	151.16215	1		re-construct footpath pavement	UH1410	Primary	MED	\$ 200
CI370	Marrickville Road	Marrickville	Regional Road	infrastructure condition	sunk pits	-33.91363	151.16228	1		install new utility cover	UH1411	Primary	MED	\$ 2,000
CI380	Railway Parade	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91378	151.16674	1		re-construct footpath pavement	UH1412	Primary	MED	\$ 200
CI4	Parramatta Road	State Road	infrastructure condition	uneven pavement surface	uneven pavement surface	-33.88769	151.17338	1		re-construct footpath pavement	UH1413	Primary	MED	\$ 200
CI404	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.91284	151.16648	1		re-construct footpath pavement	UH1414	Primary	MED	\$ 200
CI405	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.91282	151.16649	1		re-construct footpath pavement	UH1415	Primary	MED	\$ 200
CI406	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.91301	151.16661	1		re-construct footpath pavement	UH1416	Primary	MED	\$ 200
CI407	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.91307	151.16676	1		re-construct footpath pavement	UH1417	Primary	MED	\$ 200
CI411	Sydenham Road	Marrickville	State Road	infrastructure condition	damaged pit cover	-33.90961	151.16231	1		install new pit cover	UH1418	Primary	MED	\$ 250
CI423	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.90574	151.17096	1		re-construct footpath pavement	UH1419	Primary	MED	\$ 200
CI425	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.90576	151.17112	1		re-construct footpath pavement	UH1420	Primary	MED	\$ 200
CI427	Victoria Road	Marrickville	Regional Road	infrastructure condition	sunk pit	-33.91163	151.16071	1		install new utility cover	UH1421	Primary	MED	\$ 2,000
CI428	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91331	151.15918	1		re-construct footpath pavement	UH1422	Primary	MED	\$ 200
CI429	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91329	151.15919	1		re-construct footpath pavement	UH1423	Primary	MED	\$ 200
CI430	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91264	151.15977	1		re-construct footpath pavement	UH1424	Primary	MED	\$ 200
CI431	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91312	151.15952	1		re-construct footpath pavement	UH1425	Primary	MED	\$ 200
CI432	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91526	151.14076	1		re-construct footpath pavement	UH1426	Primary	MED	\$ 200
CI433	Warren Road	Marrickville	Local Road	infrastructure condition	raised pavement lip	-33.91518	151.14915	1		repair pavement panel	UH1427	Primary	MED	\$ 200
CI454	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91256	151.15076	1		re-construct footpath pavement	UH1428	Primary	MED	\$ 200
CI461	Bedford Street	Newtown	Local Road	infrastructure condition	cyclist sign faded and covered with stickers	-33.89746	151.17808	1		refer to maintenance	UH1429	Primary	MED	\$ -
CI462	Edgeware Road	Newtown	Regional Road	infrastructure condition	uneven pavement surface	-33.90461	151.17313	1		re-construct footpath pavement	UH1430	Primary	MED	\$ 200
CI463	Simmons Street	Newtown	Local Road	infrastructure condition	faded traffic control marking									

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
IC464	Holt Street	Newtown	Local Road	infrastructure condition	uneven pavement surface	-33.90021	151.177432	1		re-construct footpath pavement	UH1432	Primary	MED	\$ 200
IC468	New Canterbury Road	Petersham	State Road	infrastructure condition	uneven pavement surface	-33.896717	151.152209	1		re-construct footpath pavement	UH1433	Primary	MED	\$ 200
IC471	Terminix Street	Petersham	Local Road	infrastructure condition	raised pavement tip	-33.89352	151.156534	1		repair pavement panel	UH1434	Primary	MED	\$ 200
IC472	Wardell Road	Petersham	Regional Road	infrastructure condition	uneven pavement surface	-33.897133	151.149416	1		re-construct footpath pavement	UH1435	Primary	MED	\$ 200
IC498	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.91613	151.173422	1		re-construct footpath pavement	UH1436	Primary	MED	\$ 200
IC499	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.91043	151.160192	1		re-construct footpath pavement	UH1437	Primary	MED	\$ 200
IC5	Paramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.888143	151.162580	1		re-construct footpath pavement	UH1438	Primary	MED	\$ 200
IC500	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.913677	151.178402	1		re-construct footpath pavement	UH1439	Primary	MED	\$ 200
IC501	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.91433	151.177469	1		re-construct footpath pavement	UH1440	Primary	MED	\$ 200
IC502	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.915133	151.176839	1		re-construct footpath pavement	UH1441	Primary	MED	\$ 200
IC504	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.91487	151.176133	1		re-construct footpath pavement	UH1442	Primary	MED	\$ 200
IC505	Audley Street	Stammore	Local Road	infrastructure condition	uneven pavement surface	-33.895143	151.161807	1		re-construct footpath pavement	UH1443	Primary	MED	\$ 200
IC520	Smith Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.891723	151.137041	1		re-construct footpath pavement	UH1444	Primary	MED	\$ 200
IC529	Railway Parade	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.914974	151.16525	1		re-construct footpath pavement	UH1445	Primary	MED	\$ 200
IC534	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.922804	151.163263	1		re-construct footpath pavement	UH1446	Primary	MED	\$ 200
IC536	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.920207	151.159502	1		re-construct footpath pavement	UH1447	Primary	MED	\$ 200
IC58	Alt Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884007	151.123521	1		re-construct footpath pavement	UH1448	Primary	MED	\$ 200
IC59	Alt Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.885251	151.123249	1		re-construct footpath pavement	UH1449	Primary	MED	\$ 200
IC60	Alt Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884614	151.123684	1		re-construct footpath pavement	UH1450	Primary	MED	\$ 200
IC65	Charlotte Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.886364	151.126096	1		re-construct footpath pavement	UH1451	Primary	MED	\$ 200
IC75	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.887487	151.127379	1		re-construct footpath pavement	UH1452	Primary	MED	\$ 200
IC76	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	raised pavement tip	-33.887763	151.127987	1		repair pavement panel	UH1453	Primary	MED	\$ 200
IC77	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.888124	151.128056	1		re-construct footpath pavement	UH1454	Primary	MED	\$ 200
IC80	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.885653	151.123207	1		re-construct footpath pavement	UH1455	Primary	MED	\$ 200
IC81	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.885764	151.123609	1		re-construct footpath pavement	UH1456	Primary	MED	\$ 200
IC82	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.878426	151.126481	1		re-construct footpath pavement	UH1457	Primary	MED	\$ 200
IC83	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.878665	151.126041	1		re-construct footpath pavement	UH1458	Primary	MED	\$ 200
IC84	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.878714	151.125248	1		re-construct footpath pavement	UH1459	Primary	MED	\$ 200
IC85	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.879505	151.124267	1		re-construct footpath pavement	UH1460	Primary	MED	\$ 200
IC86	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.879739	151.12382	1		re-construct footpath pavement	UH1461	Primary	MED	\$ 200
IC87	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.880883	151.123384	1		re-construct footpath pavement	UH1462	Primary	MED	\$ 200
IC88	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.880893	151.122364	1		re-construct footpath pavement	UH1463	Primary	MED	\$ 200
IC92	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.880541	151.12208	1		re-construct footpath pavement	UH1464	Primary	MED	\$ 200
IC94	Frederick Street	Ashfield	State Road	infrastructure condition	poor barrier condition	-33.885216	151.119696	1		repair barrier	UH1465	Primary	MED	\$ 750
IC96	Milton Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.889068	151.117413	1		re-construct footpath pavement	UH1466	Primary	MED	\$ 200
IC97	Milton Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.889708	151.117296	1		re-construct footpath pavement	UH1467	Primary	MED	\$ 200
IC98	Milton Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.890292	151.117268	1		re-construct footpath pavement	UH1468	Primary	MED	\$ 200
MP1	Railway Parade	Camperdown	Local Road	missing footpath	missing footpath	-33.872369	151.127521	75	install new footpath	UH1469	Secondary	MED	\$ 15,000	
MP12	Cardigan Lane	Camperdown	Local Road	missing footpath	missing footpath	-33.889898	151.127806	152	investigate shared zone implementation	UH1470	Secondary	MED	\$ 15,000	
MP13	Church Street	Croydon	Local Road	missing footpath	missing footpath	-33.875618	151.120223	170	install new footpath	UH1471	Secondary	MED	\$ 35,800	
MP16	Hercules Street	Dulwich Hill	Local Road	missing footpath	missing footpath	-33.89001	151.158479	75	install new footpath	UH1472	Secondary	MED	\$ 15,800	
MP18	Elswick Street	Leichhardt	Local Road	missing footpath	missing footpath	-33.87763	151.151887	82	install new footpath	UH1473	Secondary	MED	\$ 13,000	
MP19	Dailey Road	Leichhardt	State Road	missing footpath	missing footpath	-33.876759	151.149643	580	install new footpath	UH1474	Secondary	MED	\$ 117,800	
MP2	Pritchard Street	Annandale	Local Road	missing footpath	missing footpath	-33.872312	151.117296	60	install new footpath	UH1475	Secondary	MED	\$ 12,000	
MP20	Whites Creek Lane	Leichhardt	Local Road	missing footpath	missing footpath	-33.885839	151.144353	101	install new footpath	UH1476	Secondary	MED	\$ 20,200	
MP21	Whites Creek Lane	Leichhardt	Local Road	missing footpath	missing footpath	-33.882401	151.146209	57	install new footpath	UH1477	Secondary	MED	\$ 11,400	
MP25	Maiyauwi Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.872116	151.151727	91	install new footpath	UH1478	Secondary	MED	\$ 18,200	
MP26	Maiyauwi Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.872296	151.151095	44	install new footpath	UH1479	Secondary	MED	\$ 8,800	
MP27	Maiyauwi Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.871576	151.151894	112	install new footpath	UH1480	Secondary	MED	\$ 22,400	
MP28	Maiyauwi Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.869276	151.152044	186	install new footpath	UH1481	Secondary	MED	\$ 37,200	
MP3	Cohen Park	Annandale	Local Road	missing footpath	missing footpath	-33.875723	151.169162	198	install new footpath	UH1482	Secondary	MED	\$ 39,200	
MP31	Glover Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.867735	151.155751	347	install new footpath	UH1483	Secondary	MED	\$ 69,400	
MP32	Lilyfield Road	Lilyfield	Regional Road	missing footpath	missing footpath	-33.872812	151.166819	31	install new footpath	UH1484	Secondary	MED	\$ 6,200	
MP34	Camrington Road	Marrickville	Local Road	missing footpath	missing footpath	-33.92101	151.154255	86	install new footpath	UH1485	Secondary	MED	\$ 17,200	
MP36	Byrnes Street	Marrickville	Local Road	missing footpath	missing footpath	-33.913724	151.156453	92	install new footpath	UH1486	Secondary	MED	\$ 600	
MP39	Victoria Road	Marrickville	Local Road	missing footpath	missing footpath	-33.914457	151.157058	92	install new footpath	UH1487	Secondary	MED	\$ 18,400	
MP4	Hudson Street - Piper Street	Annandale	Local Road	missing footpath	missing footpath	-33.877031	151.168789	90	investigate shared zone implementation	UH1488	Secondary	MED	\$ 15,000	
MP40	Mexes Road	Marrickville	Local Road	missing footpath	missing footpath	-33.914755	151.158052	105	install new footpath	UH1489	Secondary	MED	\$ 21,000	
MP42	Edgeware Road	Marrickville	Regional Road	missing footpath	missing footpath	-33.908036	151.174698	18	install new footpath	UH1490	Secondary	MED	\$ 3,800	
MP43	Pearl Lane	Newtown	Local Road	missing footpath	missing footpath	-33.905116	151.177747	183	investigate shared zone implementation	UH1491	Secondary	MED	\$ 15,000	
MP44	Manning Street	Rozelle	Local Road	missing footpath	missing footpath	-33.863095	151.16485	273	install new footpath	UH1492	Secondary	MED	\$ 54,600	
MP47	Albion Lane	St Peters	Local Road	missing footpath	missing footpath	-33.913363	151.171591	155	investigate shared zone implementation	UH1493	Secondary	MED	\$ 15,000	
MP48	James Street	Summer Hill	Local Road	missing footpath	missing footpath	-33.897348	151.153723	8	install new footpath	UH1494	Secondary	MED	\$ 1,600	
MP49	Smith Street	Summer Hill	Local Road	missing footpath	missing footpath	-33.892684	151.14323	8	install new footpath	UH1495	Secondary	MED	\$ 1,600	
MP5	Gehrig Lane	Annandale	Local Road	missing footpath	missing footpath	-33.885652	151.174785	89	investigate shared zone implementation	UH1496	Secondary	MED	\$ 15,000	
MP6	Byrnes Lane	Annandale	Local Road	missing footpath	missing footpath	-33.886367	151.17613	151	investigate shared zone implementation	UH1497	Secondary	MED	\$ 15,000	
MP8	Victoria Street	Ashfield	Local Road	missing footpath	missing footpath	-33.903441	151.129241	32	install new footpath	UH1498	Secondary	MED	\$ 6,400	
MP9	Palace Street	Ashfield	Local Road	missing footpath	missing footpath	-33.894974	151.122167	169	install new footpath	UH1499	Secondary	MED	\$ 33,800	
NP1	Janet Street	Annandale	Local Road	narrow footpath	narrow footpath	-33.884362	151.17384	53	widen footpath	UH1500	Primary	MED	\$ 10,600	
NP10	Janet Street	Balmoral	Local Road	narrow footpath	narrow footpath	-33.89066	151.14339	161	widen footpath	UH1501	Primary	MED	\$ 33,400	
NP11	Janet Street	Balmoral	Local Road	narrow footpath	narrow footpath	-33.890991	151.14443	165	widen footpath	UH1502	Primary	MED	\$ 33,000	
NP14	Mulens Street	Balmoral	Regional Road	narrow footpath	narrow footpath	-33.861438	151.176628	14	widen footpath	UH1503	Primary	MED	\$ 2,800	
NP19	Detson Road	Leichhardt	Local Road	narrow footpath	narrow footpath	-33.892163	151.139939	218	widen footpath	UH1504	Primary	MED	\$ 4,400	
NP22	Paramatta Road	Haberfield	State Road	narrow footpath	narrow footpath	-33.88124	151.132727	210	widen footpath	UH1505	Primary	MED	\$ 42,000	
NP44	Wilford Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.898373	151.174777	67	investigate shared zone implementation	UH1506	Primary	MED	\$ 15,000	
NP45	Station Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.899738	151.171022	231	widen footpath	UH1507	Primary	MED	\$ 46,200	
NP46	Station Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.899916	151.170999	218	widen footpath	UH1508	Primary	MED	\$ 43,600	
NP48	Goddard Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.899341	151.17755	46	investigate shared zone implementation	UH1509	Primary	MED	\$ 15,000	
NP56	Princes Highway	St Peters	State Road	narrow footpath	narrow footpath	-33.914542	151.176996	17	widen footpath	UH1510	Primary	MED	\$ 3,400	
NP6	Cavill Avenue	Leichhardt	Local Road	narrow footpath	narrow footpath	-33.889712	151.122279	61	widen footpath	UH1511	Primary	MED	\$ 12,000	
NP7	Frederick Street	Ashfield	State Road	narrow footpath	narrow footpath in underpass due to fencing	-33.885379	151.119519	69	widen path and relocate fencing	UH1512	Primary	MED	\$ 10,000	
NP8	Frederick Street	Ashfield	State Road	narrow footpath	narrow footpath in underpass due to fencing	-33.885328	151.119435	26	widen path and relocate fencing	UH1513	Primary	MED	\$ 10,400	
NP9	Eaton Street	Balmoral	Local Road	narrow footpath	narrow footpath	-33.885362	151.163702	11	widen footpath	UH1514	Primary	MED	\$ 2,200	
SA1	Hutchinson Lane	Annandale	Local Road	safety issue	missing footpaths in laneway	-33.87576	151.166809	1	and implement shared zone	UH1515	Secondary	MED	\$ 40,000	
SA10	Taylor Street	Annandale	Local Road	safety issue	vegetation obscures pedestrians	-33.862991	151.174647	1	refer to maintenance	UH1516	Secondary	MED	\$ 0	
SA100	Lord Street	Leichhardt	Local Road	safety issue	fencing requires flare at end	-33.88244	151.144377	1	re-construct fence	UH1517	Secondary	MED	\$ 150	
SA101	Allen Street	Leichhardt	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.88244	151.144377	1	UH1518	Secondary	MED	\$ 30,000		
SA11	Trafford Street	Annandale	Local Road	safety issue	corner obstructs pedestrian	-33.877258	151.174322	1	install pavement warning message	UH1519	Secondary	MED	\$ 150	
SA117	Styler Street	Leichhardt	Regional Road	safety issue	poor lighting	-33.882679	151.166391	1	install new lighting	UH1520	Secondary	MED	\$ 10,000	
SA118	White Creek	Leichhardt	Local Road	safety issue	missing lighting	-33.88008	151.167394	1	install new lighting	UH1521	Secondary	MED	\$ 10,000	
SA119	William Street	Leichhardt	Local Road	safety issue	poor drainage - severe ponding	-33.877272	151.157464	1	refer to maintenance	UH1522	Secondary	MED	\$ 0	

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
SA120	William Street	Leichhardt	Local Road	safety issue	poor sight lines to approaching traffic - build out kerb	-33.877653	151.151728	1		install kerb extension - pair	UH1523	Secondary	MED	\$ 20,000
SA124	Toothill Street	Lewisham	Regional Road	safety issue	vehicle obscured pedestrians	-33.899396	151.146385	1		install keep clear pavement marking	UH1524	Secondary	MED	\$ 2,500
SA129	Crove Street	Lividell	Local Road	safety issue	poor sight lines	-33.869475	151.153374	1		provide warning signage	UH1525	Secondary	MED	\$ 500
SA134	Calvert Street	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.911657	151.155344	1		install raised pedestrian crossing	UH1526	Secondary	MED	\$ 50,000
SA137	Gladstone Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.911409	151.157934	1		install raised continuous footpath treatment	UH1527	Secondary	MED	\$ 30,000
SA143	Marrickville Road	Marrickville	Regional Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.911666	151.159153	1		install raised pedestrian crossing	UH1528	Secondary	MED	\$ 50,000
SA144	Meeks Road	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.912544	151.161085	1		install raised continuous footpath treatment	UH1529	Secondary	MED	\$ 30,000
SA145	Meeks Road	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.912826	151.160942	1		install raised continuous footpath treatment	UH1530	Secondary	MED	\$ 30,000
SA146	River Canoe Club	Marrickville	Local Road	safety issue	cross pedestrian, bicycle traffic over shared path near gate	-33.923564	151.155555	1		install warning line marking and signage	UH1531	Secondary	MED	\$ 1,500
SA147	Sydenham Road	Marrickville	State Road	safety issue	opportunity to provide signalled intersection	-33.910569	151.163949	1		further investigation required - signals	UH1532	Secondary	MED	\$ 20,000
SA15	Chester Street	Annandale	Local Road	safety issue	steep crossfall	-33.856674	151.174996	1		re-construct footpath pavement	UH1533	Secondary	MED	\$ 200
SA150	Byrnes Street	Marrickville	Local Road	safety issue	vehicles approach crossing at speed	-33.913703	151.155431	1		install new speed cushions	UH1534	Secondary	MED	\$ 3,000
SA151	Byrnes Street	Marrickville	Local Road	safety issue	poor lighting	-33.913716	151.15543	1		install new lighting	UH1535	Secondary	MED	\$ 10,000
SA152	Ilwera Road	Marrickville	Local Road	safety issue	deep tree pit	-33.909703	151.157245	1		top up tree pit	UH1536	Secondary	MED	\$ 150
SA160	Marrickville Road	Marrickville	Regional Road	safety issue	corner obscures pedestrians	-33.912956	151.161507	1		install pavement warning message	UH1537	Secondary	MED	\$ 150
SA161	Marrickville Road	Marrickville	Regional Road	safety issue	poor lighting	-33.910058	151.1554	1		install new lighting	UH1538	Secondary	MED	\$ 10,000
SA162	Marrickville Road	Marrickville	Regional Road	safety issue	vehicles approach crossing at speed	-33.910087	151.155431	1		install raised pedestrian crossing	UH1539	Secondary	MED	\$ 50,000
SA163	Marrickville Road	Marrickville	Regional Road	safety issue	footlights orientated incorrectly	-33.910111	151.155483	1		adjust foot light orientation	UH1540	Secondary	MED	\$ 1,000
SA164	Marrickville Road	Marrickville	Regional Road	safety issue	tree obstructs footlight	-33.911866	151.159233	1		refer to maintenance	UH1541	Secondary	MED	\$ -
SA165	Marrickville Road	Marrickville	Regional Road	safety issue	vehicles approach crossing at speed	-33.911897	151.159225	1		install raised pedestrian crossing	UH1542	Secondary	MED	\$ 50,000
SA166	Marrickville Road	Marrickville	Regional Road	safety issue	roadside furniture obstructs sightlines	-33.911851	151.159203	1		re-construct pedestrian crossing	UH1543	Secondary	MED	\$ 5,000
SA167	O'Hara Park	Marrickville	Local Road	safety issue	missing lighting	-33.913806	151.155857	1		install new lighting	UH1544	Secondary	MED	\$ 10,000
SA183	Edinburgh Road	Newtown	Local Road	safety issue	shared path signage required	-33.807916	151.174484	1		install new shared path signage	UH1545	Secondary	MED	\$ 350
SA187	Liberty Street	Newtown	Regional Road	safety issue	shared path signage conflict	-33.894968	151.171625	1		review and replace shared path signage	UH1546	Secondary	MED	\$ 500
SA188	Liberty Street	Newtown	Regional Road	safety issue	bicycle pavement marking with no shared path signage	-33.895275	151.171576	1		install new shared path signage	UH1547	Secondary	MED	\$ 350
SA206	York Crescent	Petersham	Local Road	safety issue	missing lighting	-33.893744	151.15863	1		install new lighting	UH1548	Secondary	MED	\$ 10,000
SA207	Denson Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.86543	151.167687	1		install raised continuous footpath treatment	UH1549	Secondary	MED	\$ 30,000
SA21	Rose Street	Annandale	Local Road	safety issue	poor lighting	-33.877376	151.176113	1		install new lighting	UH1550	Secondary	MED	\$ 10,000
SA210	Manning Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.865783	151.166826	1		install raised continuous footpath treatment	UH1551	Secondary	MED	\$ 30,000
SA220	Beattie Street	Rozelle	Local Road	safety issue	corner obscures pedestrians	-33.860678	151.172292	1		install pavement warning message	UH1552	Secondary	MED	\$ 150
SA222	Terry Street	Rozelle	Local Road	safety issue	refuge island provides no protection from traffic	-33.860954	151.169516	1		install new refuge island	UH1553	Secondary	MED	\$ 15,000
SA223	Terry Street	Rozelle	Local Road	safety issue	refuge island provides no protection for pedestrians	-33.860678	151.169594	1		install new refuge island	UH1554	Secondary	MED	\$ 15,000
SA224	Bedwin Road	St Peters	Regional Road	safety issue	steep crossfall	-33.909131	151.175137	1		re-construct footpath pavement	UH1555	Secondary	MED	\$ 200
SA232	Merchant Street	Stammore	Local Road	safety issue	poor drainage - severe ponding	-33.895972	151.167462	1		refer to maintenance	UH1556	Secondary	MED	\$ -
SA234	Salisbury Road	Stammore	Regional Road	safety issue	poor drainage - severe ponding	-33.891476	151.166591	1		refer to maintenance	UH1557	Secondary	MED	\$ -
SA235	Lincoln Lane	Stammore	Local Road	safety issue	poor drainage - severe ponding	-33.891435	151.170716	1		refer to maintenance	UH1558	Secondary	MED	\$ -
SA25	Knox Street	Ashfield	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.895314	151.122749	1		install raised pedestrian crossing	UH1559	Secondary	MED	\$ 50,000
SA252	Junction Road	Summer Hill	Local Road	safety issue	corner obscures pedestrians	-33.895391	151.137156	1		install pavement warning message	UH1560	Secondary	MED	\$ 150
SA254	Prospect Road	Summer Hill	Local Road	safety issue	road hump used as crossing	-33.900063	151.13201	1		install pedestrian crossing	UH1561	Secondary	MED	\$ 750
SA256	Prospect Road	Summer Hill	Local Road	safety issue	narrow refuge island	-33.89157	151.132434	1		install new refuge island	UH1562	Secondary	MED	\$ 15,000
SA27	Elizabeth Street	Ashfield	Regional Road	safety issue	corner obscures pedestrians	-33.88638	151.125389	1		install pavement warning message	UH1563	Secondary	MED	\$ 150
SA40	Marham Avenue	Ashfield	Local Road	safety issue	bollards of low contrasting colour	-33.887492	151.123242	1		repaint bollards	UH1564	Secondary	MED	\$ 150
SA42	Victoria Street	Ashfield	Local Road	safety issue	steep crossfall	-33.903218	151.129144	1		re-construct footpath pavement	UH1565	Secondary	MED	\$ 200
SA43	Beattie Street	Balmann	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.857598	151.181049	1		install raised pedestrian crossing	UH1566	Secondary	MED	\$ 50,000
SA45	Trafalgar Street	Annandale	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.881984	151.172128	1		install raised continuous footpath treatment	UH1567	Secondary	MED	\$ 30,000
SA51	King Street	Balmann	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.855953	151.175052	1		install raised continuous footpath treatment	UH1568	Secondary	MED	\$ 30,000
SA54	Young Street	Balmann	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.855972	151.174068	1		install raised continuous footpath treatment	UH1569	Secondary	MED	\$ 30,000
SA55	Young Street	Balmann	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.856066	151.174121	1		install raised continuous footpath treatment	UH1570	Secondary	MED	\$ 30,000
SA56	Clasp Street	Balmann	Local Road	safety issue	vehicles obscure pedestrians	-33.854031	151.174480	1		install kerb extension	UH1571	Secondary	MED	\$ 10,000
SA57	Terry Street	Balmann	Local Road	safety issue	corner obscures pedestrians	-33.856842	151.171205	1		install pavement warning message	UH1572	Secondary	MED	\$ 150
SA6	Trafalgar Street	Annandale	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.881874	151.172171	1		install raised continuous footpath treatment	UH1573	Secondary	MED	\$ 30,000
SA63	Salisbury Road	Camperdown	Regional Road	safety issue	vehicles approach crossing at speed	-33.891774	151.174494	1		install raised pedestrian crossing	UH1574	Secondary	MED	\$ 50,000
SA64	Salisbury Road	Camperdown	Regional Road	safety issue	poor visibility to approaching vehicles	-33.891774	151.174507	1		relocate no stopping sign	UH1575	Secondary	MED	\$ 1,500
SA68	Blackwood Avenue	Dulwich Hill	Local Road	safety issue	potential shared zone	-33.90759	151.140814	1		investigate shared zone implementation	UH1576	Secondary	MED	\$ 15,000
SA78	Constitution Road	Dulwich Hill	Local Road	safety issue	pedestrian desireline	-33.901519	151.137251	1		further investigation required - pedestrian crossing	UH1577	Secondary	MED	\$ 10,000
SA79	New Canterbury Road	Dulwich Hill	State Road	safety issue	narrow pedestrian refuge island across busy road	-33.904038	151.130255	1		consult with City of Canterbury-Bankstown	UH1578	Secondary	MED	\$ -
SA80	New Canterbury Road	Dulwich Hill	Local Road	safety issue	poor drainage	-33.905	151.131775	1		refer to maintenance	UH1579	Secondary	MED	\$ -
SA86	Linton Street	Enmore	Local Road	safety issue	vehicles obscure pedestrians	-33.895399	151.171064	1		install no stopping sign and signpost	UH1580	Secondary	MED	\$ 300
SA87	Phillip Street	Enmore	Local Road	safety issue	poor drainage - severe ponding	-33.896921	151.17332	1		refer to maintenance	UH1581	Secondary	MED	\$ -
SA93	Bland Street	Haberfield	Local Road	safety issue	low visibility to crossing from both approaches	-33.878926	151.13441	1		install raised pedestrian crossing	UH1582	Secondary	MED	\$ 50,000
SA94	Bland Street	Haberfield	Local Road	safety issue	footlights orientated incorrectly	-33.878938	151.13438	1		adjust foot light orientation	UH1583	Secondary	MED	\$ 1,000
SA97	Darley Road	Leichardt	State Road	safety issue	potential pedestrian crossing point	-33.880175	151.147681	1		further investigation required - raised pedestrian crossing	UH1584	Secondary	MED	\$ 15,000
SA98	Foster Street	Leichardt	State Road	safety issue	missing refuge island	-33.884444	151.147681	1		install new refuge island	UH1585	Secondary	MED	\$ 15,000
SA99	Lord Street	Leichardt	Local Road	safety issue	potential pedestrian crossing point	-33.886054	151.147004	1		further investigation required - raised pedestrian crossing	UH1586	Secondary	MED	\$ 15,000
SUBTOTAL														\$ 6,918,650

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
AC12	Birchgrove Oval	Birchgrove	Local Road	access	stairs only access to wharf	-33.848124	151.181953	1		consult with TNSW	B12	Tertiary	LOW		\$ -
AC23	Lilyfield Road	Lilyfield	Local Road	access	stairs only access	-33.872142	151.151073	1		no action	LF76	Tertiary	LOW		\$ 2,500
AC25	Mary Street	Lilyfield	Local Road	access	no ramp between different height footpaths	-33.867576	151.154214	1		install new kerb ramp	LF81	Tertiary	LOW		\$ 2,500
AC28	Premier Street	Marrickville	Local Road	access	stairs only access	-33.917899	151.147691	1		install accessible ramp	MV160	Tertiary	LOW		\$ 10,000
AC29	Premier Street	Marrickville	Local Road	access	stairs only access	-33.918135	151.148047	1		install accessible ramp	MV160	Tertiary	LOW		\$ 10,000
AC3	Pritchard Street	Annandale	Local Road	access	stairs only access	-33.87367	151.170955	1		install accessible ramp	AN123	Tertiary	LOW		\$ 10,000
AC7	Trabular Street	Annandale	Local Road	access	stairs only access	-33.876821	151.174516	1		install accessible ramp	AN102	Tertiary	LOW		\$ 10,000
AC9	Booth Street	Balmian	Local Road	access	stairs only access	-33.860684	151.181955	1		install accessible ramp	BA54	Tertiary	LOW		\$ 10,000
CD1003	Flood Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.885368	151.149224	1		install new kerb ramp - pair	UH1	Tertiary	LOW		\$ 5,000
CD1004	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888977	151.149316	1		install new kerb ramp	UH1	Tertiary	LOW		\$ 2,500
CD1005	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888391	151.149366	1		install new kerb ramp - pair	UH58	Tertiary	LOW		\$ 5,000
CD1008	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878431	151.150193	1		install new kerb ramp - pair	UH3	Tertiary	LOW		\$ 5,000
CD1009	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878674	151.150138	1		install new kerb ramp - pair	UH4	Tertiary	LOW		\$ 5,000
CD1010	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880236	151.150137	1		install new kerb ramp - pair	UH4	Tertiary	LOW		\$ 5,000
CD1011	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.882411	151.15012	1		install new Tactile Ground Surface Indicators	UH6	Tertiary	LOW		\$ 650
CD1014	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879087	151.150019	1		install new kerb ramp - pair	UH4	Tertiary	LOW		\$ 5,000
CD1015	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878445	151.150015	1		install new kerb ramp - pair	UH3	Tertiary	LOW		\$ 5,000
CD1016	Flood Street	Leichhardt	Local Road	crossing deficiency	kerb blister obstructs crossing path	-33.878986	151.150034	1		reconstruct kerb blister	UH3	Tertiary	LOW		\$ 1,500
CD1081	Paramatta Road	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889748	151.149169	1		install new kerb ramp - pair	UH1	Tertiary	LOW		\$ 5,000
CD1135	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.888421	151.150006	1		install new kerb ramp	UH4	Tertiary	LOW		\$ 2,500
CD1141	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.880305	151.150154	1		install new kerb ramp	UH4	Tertiary	LOW		\$ 2,500
CD1163	Eltham Street	Lewisham	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.887729	151.143466	1		further investigation required - pedestrian crossing	OD46	Tertiary	LOW		\$ 10,000
CD1214	Vernon Street	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.899734	151.149986	1		install new Tactile Ground Surface Indicators	LV40	Tertiary	LOW		\$ 650
CD1215	Frazer Street	Lewisham	Regional Road	crossing deficiency	narrow kerb ramp	-33.890362	151.149007	1		install new kerb ramp	LV41	Tertiary	LOW		\$ 2,500
CD1242	Bay Run	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872722	151.151246	1		install new kerb ramp	LF13	Tertiary	LOW		\$ 2,500
CD1253	Frazer Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.869668	151.152608	1		install new kerb ramp - pair	LF43	Tertiary	LOW		\$ 5,000
CD1257	Glover Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.867028	151.155689	1		install new Tactile Ground Surface Indicators	LF61	Tertiary	LOW		\$ 650
CD1258	Grove Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.871096	151.164195	1		install new Tactile Ground Surface Indicators	LF55	Tertiary	LOW		\$ 650
CD1259	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872126	151.164266	1		install new kerb ramp	LF55	Tertiary	LOW		\$ 2,500
CD126	Annandale Street	Annandale	Local Road	crossing deficiency	long crossing	-33.887661	151.166059	1		install kerb extension - pair	AN17	Tertiary	LOW		\$ 20,000
CD1261	Grove Street	Lilyfield	Local Road	crossing deficiency	long crossing	-33.872038	151.164405	1		install kerb extension - pair	LF55	Tertiary	LOW		\$ 20,000
CD1262	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.871943	151.164402	1		install new kerb ramp	LF55	Tertiary	LOW		\$ 2,500
CD1263	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.870524	151.163938	1		install new kerb ramp	LF56	Tertiary	LOW		\$ 2,500
CD1264	Grove Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.870426	151.163911	1		install new Tactile Ground Surface Indicators	LF56	Tertiary	LOW		\$ 650
CD1265	Grove Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.870469	151.163173	1		install new Tactile Ground Surface Indicators	LF56	Tertiary	LOW		\$ 650
CD1265	Lilyfield Road	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874184	151.160466	1		install new kerb ramp - pair	LF64	Tertiary	LOW		\$ 5,000
CD1290	Francis Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873282	151.154168	1		install new kerb ramp	LF60	Tertiary	LOW		\$ 2,500
CD1291	Hubert Street	Lilyfield	Local Road	crossing deficiency	steep kerb ramp	-33.872551	151.153080	1		install new kerb ramp - pair	LF61	Tertiary	LOW		\$ 2,500
CD1292	Charles Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872736	151.152332	1		install new kerb ramp	LF61	Tertiary	LOW		\$ 2,500
CD1293	Charles Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872794	151.152322	1		install new kerb ramp	LF61	Tertiary	LOW		\$ 2,500
CD1294	Charles Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872675	151.152134	1		install new kerb ramp	LF61	Tertiary	LOW		\$ 2,500
CD1295	Lilyfield Road	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872528	151.151237	1		install new kerb ramp	LF61	Tertiary	LOW		\$ 2,500
CD1296	Lilyfield Road	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872423	151.151827	1		install new kerb ramp - pair	LF61	Tertiary	LOW		\$ 5,000
CD1301	Mary Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.886065	151.154361	1		install new Tactile Ground Surface Indicators	LF84	Tertiary	LOW		\$ 650
CD1302	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.869867	151.154422	1		install new kerb ramp - pair	LF84	Tertiary	LOW		\$ 5,000
CD1303	Mary Street	Lilyfield	Local Road	crossing deficiency	missing crossing point	-33.872703	151.155312	1		install new kerb ramp - pair	LF78	Tertiary	LOW		\$ 5,000
CD1304	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872686	151.155203	1		install new kerb ramp - pair	LF78	Tertiary	LOW		\$ 5,000
CD1305	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870602	151.154588	1		install new kerb ramp - pair	LF85	Tertiary	LOW		\$ 5,000
CD1306	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870336	151.154343	1		install new kerb ramp - pair	LF84	Tertiary	LOW		\$ 5,000
CD1307	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868452	151.153429	1		install new kerb ramp	LF43	Tertiary	LOW		\$ 2,500
CD1308	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.867003	151.15391	1		install new kerb ramp	LF81	Tertiary	LOW		\$ 2,500
CD1309	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868004	151.153784	1		install new kerb ramp	LF81	Tertiary	LOW		\$ 2,500
CD1310	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.867707	151.154236	1		install new kerb ramp	LF81	Tertiary	LOW		\$ 2,500
CD1312	Mary Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.872836	151.155338	1		install new kerb ramp - pair	LF78	Tertiary	LOW		\$ 5,000
CD1313	Mary Street	Lilyfield	Local Road	crossing deficiency	missing refuge island	-33.872757	151.155208	1		install new refuge island	LF78	Tertiary	LOW		\$ 15,000
CD1319	Piper Street	Lilyfield	Local Road	crossing deficiency	missing crossing point	-33.871471	151.158468	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1320	Piper Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.877369	151.168288	1		install new kerb ramp	LF96	Tertiary	LOW		\$ 2,500
CD1321	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877104	151.167611	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1322	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877059	151.167444	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1323	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877022	151.167264	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1324	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876819	151.166469	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1327	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876754	151.165935	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1328	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876449	151.166789	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1329	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877153	151.167561	1		install new kerb ramp - pair	LF96	Tertiary	LOW		\$ 5,000
CD1330	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876172	151.163454	1		install new kerb ramp - pair	LF92	Tertiary	LOW		\$ 5,000
CD1331	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876168	151.163725	1		install new kerb ramp - pair	LF92	Tertiary	LOW		\$ 5,000
CD1332	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875973	151.162912	1		install new kerb ramp - pair	LF91	Tertiary	LOW		\$ 5,000
CD1333	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875753	151.161954	1		install new kerb ramp - pair	LF90	Tertiary	LOW		\$ 5,000
CD1337	Carly Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.918466	151.151636	1		install new kerb ramp	MV167	Tertiary	LOW		\$ 2,500
CD1362	Albermarle Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.911299	151.145914	1		install new kerb ramp	MV167	Tertiary	LOW		\$ 2,500
CD1363	Albermarle Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.911747	151.145523	1		install new Tactile Ground Surface Indicators - pair	MV13	Tertiary	LOW		\$ 1,300
CD1364	Albermarle Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.912178	151.146172	1		install new Tactile Ground Surface Indicators - pair	MV12	Tertiary	LOW		\$ 1,300
CD1365	Albermarle Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91267	151.146988	1		install new kerb ramp - pair	MV12	Tertiary	LOW		\$ 5,000
CD1383	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91998	151.155163	1		install new kerb ramp - pair	MV169	Tertiary	LOW		\$ 5,000
CD1384	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918431	151.156208	1		install new kerb ramp - pair	MV28	Tertiary	LOW		\$ 5,000
CD1385	Carrington Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.919789	151.15515	1		re-construct refuge island	MV25	Tertiary	LOW		\$ 15,000
CD1389	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918817	151.155227	1		install new kerb ramp - pair	MV25	Tertiary	LOW		\$ 5,000
CD1390	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919066	151.15584	1		install new kerb ramp - pair	MV27	Tertiary	LOW		\$ 5,000
CD1391	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918732	151.157722	1		install new kerb ramp - pair	MV28	Tertiary	LOW		\$ 5,000
CD1392	Carrington Road	Marrickville	Local Road	crossing deficiency	long crossing	-33.916708	151.157615	1		install kerb extension - pair	MV28	Tertiary	LOW		\$ 20,000
CD1393	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.917516	151.157196	1		install new kerb ramp - pair	MV23	Tertiary	LOW		\$ 5,000
CD1428	Fitzroy Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.909098	151.168995	1		install new kerb ramp	MV70	Tertiary	LOW		\$ 2,500
CD1427	Fitzroy Street	Marrickville	Local Road	crossing deficiency	raised kerb ramp tip	-33.908423	151.165845	1		install new kerb ramp	MV69	Tertiary	LOW		\$ 2,500
CD1428	Fitzroy Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.908444	151.165799	1		install new kerb ramp	MV73	Tertiary	LOW		\$ 2,500
CD1429	Fitzroy Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.908539	151.166614	1		install new kerb ramp - pair</					

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
CD1566	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.90111	151.16749	1		install new Tactile Ground Surface Indicators	MV167	Tertiary	CW	\$ 650
CD1567	Newington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90026	151.16646	1		install new kerb ramp	MV156	Tertiary	CW	\$ 2,500
CD1568	Newington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90034	151.16531	1		install new kerb ramp	MV155	Tertiary	CW	\$ 2,500
CD1569	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.90003	151.16482	1		install new Tactile Ground Surface Indicators	MV154	Tertiary	CW	\$ 650
CD1582	Premier Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.918103	151.148362	1		install new kerb ramp	MV160	Tertiary	CW	\$ 2,500
CD1583	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.91826	151.148261	1		install new Tactile Ground Surface Indicators	MV160	Tertiary	CW	\$ 650
CD1584	Premier Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.918175	151.148119	1		install new kerb ramp	MV160	Tertiary	CW	\$ 2,500
CD1585	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.918292	151.148352	1		install new Tactile Ground Surface Indicators	MV160	Tertiary	CW	\$ 650
CD1586	Premier Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.918039	151.148194	1		install new kerb ramp	MV160	Tertiary	CW	\$ 2,500
CD1582	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.918134	151.152442	1		install new Tactile Ground Surface Indicators - pair	MV167	Tertiary	CW	\$ 1,300
CD1593	Renwick Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.918656	151.155074	1		re-construct refuge island	MV169	Tertiary	CW	\$ 15,000
CD1594	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.918516	151.15274	1		install new Tactile Ground Surface Indicators - pair	MV167	Tertiary	CW	\$ 1,300
CD1595	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.918681	151.152294	1		install new Tactile Ground Surface Indicators - pair	MV167	Tertiary	CW	\$ 1,300
CD1599	Richardson Crescent	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.920513	151.154936	1		install new kerb ramp - pair	MV173	Tertiary	CW	\$ 6,000
CD16	Nelson Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877341	151.175815	1		install new Tactile Ground Surface Indicators	AN64	Tertiary	CW	\$ 650
CD1600	Richardson Crescent	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.921969	151.156433	1		install new kerb ramp - pair	MV174	Tertiary	CW	\$ 5,000
CD1603	Riverside Crescent	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.919055	151.142559	1		install new Tactile Ground Surface Indicators	MV178	Tertiary	CW	\$ 650
CD1604	Riverside Crescent	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914366	151.142635	1		install new kerb ramp	MV178	Tertiary	CW	\$ 2,500
CD1605	Riverside Crescent	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914095	151.139227	1		install new kerb ramp - pair	MV177	Tertiary	CW	\$ 5,000
CD1606	Riverside Crescent	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.914568	151.14027	1		install new Tactile Ground Surface Indicators	MV180	Tertiary	CW	\$ 650
CD1607	Shirlow Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.911221	151.167891	1		install new kerb ramp	MV184	Tertiary	CW	\$ 2,500
CD1608	Shirlow Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.91161	151.167402	1		install new kerb ramp	MV183	Tertiary	CW	\$ 2,500
CD1609	Shirlow Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.911676	151.16753	1		install new Tactile Ground Surface Indicators	MV183	Tertiary	CW	\$ 650
CD1611	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887037	151.166474	1		install new kerb ramp	AN17	Tertiary	CW	\$ 2,500
CD1622	Ilwara Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907656	151.159155	1		install new kerb ramp	MV87	Tertiary	CW	\$ 2,500
CD1623	Ilwara Road	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.907523	151.159163	1		install new kerb ramp	MV82	Tertiary	CW	\$ 2,500
CD1624	Ilwara Road	Marrickville	Local Road	crossing deficiency	traffic post narrow kerb ramp	-33.907566	151.158801	1		consult with TfNSW	MV81	Tertiary	CW	\$ 650
CD1646	Fitzroy Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.910356	151.163594	1		install new Tactile Ground Surface Indicators	MV72	Tertiary	CW	\$ 650
CD1647	Fitzroy Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.910919	151.164137	1		install new kerb ramp	MV72	Tertiary	CW	\$ 2,500
CD1648	Yule Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.901833	151.1491	1		install new kerb ramp - pair	DH119	Tertiary	CW	\$ 5,000
CD1667	Porter Avenue	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.901094	151.149012	1		install new Tactile Ground Surface Indicators	DH118	Tertiary	CW	\$ 650
CD1668	Porter Avenue	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.90216	151.149023	1		install new kerb ramp	DH118	Tertiary	CW	\$ 2,500
CD1669	Pile Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.903699	151.148938	1		install new kerb ramp - pair	DH120	Tertiary	CW	\$ 5,000
CD1670	Pile Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.903732	151.148928	1		re-construct refuge island	DH120	Tertiary	CW	\$ 15,000
CD1671	Woodcourt Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.905866	151.148936	1		install new kerb ramp - pair	MV235	Tertiary	CW	\$ 5,000
CD1672	Woodcourt Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.905844	151.148845	1		install new kerb ramp - pair	MV235	Tertiary	CW	\$ 5,000
CD1683	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.917485	151.15316	1		install new Tactile Ground Surface Indicators - pair	MV241	Tertiary	CW	\$ 1,300
CD1684	Warren Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.918912	151.155112	1		install new kerb ramp	MV21	Tertiary	CW	\$ 2,500
CD1685	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.917496	151.152903	1		install new Tactile Ground Surface Indicators - pair	MV241	Tertiary	CW	\$ 1,300
CD17	Nelson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.877352	151.17583	1		install new kerb ramp	AN64	Tertiary	CW	\$ 2,500
CD172	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.886669	151.16649	1		install new Tactile Ground Surface Indicators	AN17	Tertiary	CW	\$ 650
CD1769	Brighton Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882457	151.163353	1		install new kerb ramp - pair	PF6	Tertiary	CW	\$ 2,500
CD18	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877286	151.175847	1		install new kerb ramp	AN64	Tertiary	CW	\$ 2,500
CD185	Bland Street	Ashfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.882457	151.175847	1		further investigation required - pedestrian crossing	AF24	Tertiary	CW	\$ 10,000
CD187	Hardy Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.900463	151.172012	1		install spitfire/refuge island	RC31	Tertiary	CW	\$ 10,000
CD1878	Denison Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.888787	151.169352	1		install new kerb ramp - pair	RC31	Tertiary	CW	\$ 5,000
CD1879	Denison Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.888997	151.169264	1		install new kerb ramp - pair	RC31	Tertiary	CW	\$ 5,000
CD188	Hardy Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.900438	151.172052	1		install spitfire/refuge island	AF80	Tertiary	CW	\$ 10,000
CD1880	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886447	151.169315	1		install new kerb ramp - pair	RC28	Tertiary	CW	\$ 2,500
CD1881	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886953	151.169477	1		install new kerb ramp - pair	RC28	Tertiary	CW	\$ 5,000
CD1882	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889725	151.169707	1		install new kerb ramp	RC28	Tertiary	CW	\$ 2,500
CD1883	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870191	151.170356	1		install new kerb ramp - pair	RC28	Tertiary	CW	\$ 5,000
CD1884	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870023	151.170037	1		install new kerb ramp - pair	RC28	Tertiary	CW	\$ 5,000
CD1885	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.869046	151.169192	1		install new kerb ramp - pair	RC31	Tertiary	CW	\$ 5,000
CD1886	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868436	151.169162	1		install new kerb ramp	RC31	Tertiary	CW	\$ 2,500
CD1880	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.870121	151.17002	1		install new kerb ramp	RC28	Tertiary	CW	\$ 2,500
CD1881	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866272	151.170672	1		install new kerb ramp - pair	RC34	Tertiary	CW	\$ 5,000
CD1895	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866624	151.170647	1		install new kerb ramp - pair	RC34	Tertiary	CW	\$ 5,000
CD1886	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866145	151.170539	1		install new kerb ramp - pair	RC34	Tertiary	CW	\$ 5,000
CD1897	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.86598	151.17103	1		install new kerb ramp - pair	RC34	Tertiary	CW	\$ 5,000
CD190	Holden Street	Ashfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.896852	151.125086	1		further investigation required - pedestrian crossing, consult with City of Canterbury-Bankstown	AF83	Tertiary	CW	\$ -
CD1911	Gordon Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88662	151.172848	1		install new kerb ramp - pair	RC37	Tertiary	CW	\$ 5,000
CD1925	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882764	151.164537	1		install new kerb ramp - pair	RC50	Tertiary	CW	\$ 2,500
CD1926	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.862462	151.163904	1		install new kerb ramp	RC50	Tertiary	CW	\$ 2,500
CD1927	Manning Street	Rozelle	Local Road	crossing deficiency	long crossing	-33.862429	151.16376	1		install kerb extension	RC50	Tertiary	CW	\$ 10,000
CD1928	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.862663	151.16464	1		install new kerb ramp	RC52	Tertiary	CW	\$ 2,500
CD1936	Robert Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.865597	151.17706	1		install new kerb ramp - pair	RC55	Tertiary	CW	\$ 5,000
CD1937	Parsons Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865052	151.176816	1		install new kerb ramp - pair	RC56	Tertiary	CW	\$ 5,000
CD1941	Robert Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.865893	151.1773	1		install new kerb ramp - pair	RC58	Tertiary	CW	\$ 5,000
CD1942	Robert Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.863569	151.169527	1		install new kerb ramp - pair	RC58	Tertiary	CW	\$ 5,000
CD1944	Terry Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860559	151.168306	1		install new kerb ramp	RC62	Tertiary	CW	\$ 2,500
CD196	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879715	151.130159	1		install new kerb ramp - pair	AF5	Tertiary	CW	\$ 5,000
CD197	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880165	151.129321	1		install new kerb ramp - pair	AF6	Tertiary	CW	\$ 5,000
CD198	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880457	151.128594	1		install new kerb ramp - pair	AF3	Tertiary	CW	\$ 5,000
CD199	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.881447	151.128593	1		install new Tactile Ground Surface Indicators - pair	AF1	Tertiary	CW	\$ 1,300
CD200	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.881717	151.126338	1		install new Tactile Ground Surface Indicators	AF8	Tertiary	CW	\$ 650
CD2007	May Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912578	151.171197	1		install new kerb ramp	PF8	Tertiary	CW	\$ 2,500
CD2009	Macaulay Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88848	151.17112	1		install new kerb ramp	SM4	Tertiary	CW	\$ 2,500
CD2001	Alt Street	Ashfield	Local Road	crossing deficiency	misaligned refuge island	-33.881736	151.126319	1		re-construct refuge island	AF8	Tertiary	CW	\$ 15,000
CD2010	Crunkank Street	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.888088	151.171296	1		install new kerb ramp	SM4	Tertiary	CW	\$ 2,500
CD2001	Corvina Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888524	151.171551	1		install new kerb ramp	SM5	Tertiary	CW	\$ 2,500
CD2012	Crunkank Street	Stammore	Local Road	crossing deficiency	missing crossing point	-33.88424	151.172532	1		install new kerb ramp - pair	SM7	Tertiary	CW	\$ 5,000
CD2033	Northumberland Avenue	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891562	151.16806	1		install new kerb ramp	SM23	Tertiary	CW	\$ 2,500
CD2034	Northumberland Avenue	Stammore	Local Road	crossing deficiency	misaligned refuge island	-33.890736	151.167816	1		install new refuge island	SM23	Tertiary	CW	\$ 15,000
CD2035	Northumberland Avenue	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889879	151.167777	1		install new kerb ramp	SM24	Tertiary	CW	\$ 2,500
CD2036	Northumberland Avenue	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888032	151.16761	1		install new kerb ramp	SM22	Tertiary	CW	\$ 2,500
CD2037	Northumberland Avenue	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.888135	151.167711	1		install new kerb ramp	SM22	Tertiary	CW	\$ 2,500
CD2038	Northumberland Avenue	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.890599	151.16808	1						

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
CD208	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882197	151.125194	1		install new kerb ramp - pair	AF8	Tertiary	CW	\$ 5,000
CD2082	Groveonor Crescent	Summer Hill	Local Road	crossing deficiency	misaligned refuge island	-33.891312	151.142371	1		re-construct refuge island	SH25	Tertiary	CW	\$ 15,000
CD208	Hurlstone Avenue	Summer Hill	Local Road	crossing deficiency	long crossing point	-33.898338	151.133753	1		install kerb extension / refuge island	SH60	Tertiary	CW	\$ 10,000
CD209	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.881897	151.126347	1		install new Tactile Ground Surface Indicators	AF8	Tertiary	CW	\$ 650
CD210	Alt Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.881222	151.127239	1		install new kerb ramp - pair	AF2	Tertiary	CW	\$ 5,000
CD211	Alt Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.881202	151.127194	1		install new kerb ramp - pair	AF2	Tertiary	CW	\$ 5,000
CD2112	Henson Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898338	151.134444	1		install new kerb ramp - pair	SH60	Tertiary	CW	\$ 5,000
CD2113	Henson Street	Summer Hill	Local Road	crossing deficiency	long crossing point	-33.898455	151.13442	1		install kerb extension / refuge island	SH60	Tertiary	CW	\$ 10,000
CD2114	Hurlstone Avenue	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898935	151.133691	1		install new kerb ramp - pair	SH60	Tertiary	CW	\$ 5,000
CD2127	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897831	151.132322	1		install new kerb ramp - pair	SH72	Tertiary	CW	\$ 5,000
CD213	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898163	151.125564	1		install new kerb ramp - pair	AF12	Tertiary	CW	\$ 5,000
CD214	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.897628	151.125182	1		install new kerb ramp	AF12	Tertiary	CW	\$ 2,500
CD215	Armstrong Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.897539	151.125131	1		install new kerb ramp	AF13	Tertiary	CW	\$ 2,500
CD216	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896022	151.126539	1		install new kerb ramp - pair	AF14	Tertiary	CW	\$ 5,000
CD217	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900294	151.127152	1		install new kerb ramp - pair	AF11	Tertiary	CW	\$ 5,000
CD220	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881791	151.129102	1		install new kerb ramp	AF26	Tertiary	CW	\$ 2,500
CD221	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881942	151.129108	1		install new kerb ramp	AF26	Tertiary	CW	\$ 2,500
CD222	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882871	151.127302	1		install new kerb ramp - pair	AF24	Tertiary	CW	\$ 5,000
CD223	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882942	151.127167	1		install new kerb ramp - pair	AF20	Tertiary	CW	\$ 5,000
CD224	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882605	151.127209	1		install new kerb ramp - pair	AF24	Tertiary	CW	\$ 5,000
CD225	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882922	151.127155	1		install new kerb ramp - pair	AF20	Tertiary	CW	\$ 5,000
CD232	Church Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878029	151.124835	1		install new kerb ramp - pair	AF42	Tertiary	CW	\$ 5,000
CD233	Church Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877287	151.124425	1		install new kerb ramp - pair	AF41	Tertiary	CW	\$ 5,000
CD234	Church Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tsgl - pair	-33.878007	151.124955	1		install new Tactile Ground Surface Indicators - pair	AF42	Tertiary	CW	\$ 1,300
CD236	Church Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.877976	151.124855	1		install new kerb ramp - pair	AF42	Tertiary	CW	\$ 5,000
CD237	Church Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.878069	151.124907	1		install new kerb ramp - pair	AF42	Tertiary	CW	\$ 5,000
CD238	Cissoid Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tsgl - pair	-33.895801	151.131819	1		install new Tactile Ground Surface Indicators - pair	AF46	Tertiary	CW	\$ 1,300
CD240	Cissoid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895958	151.131184	1		install new kerb ramp	AF46	Tertiary	CW	\$ 5,000
CD249	Cissoid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895601	151.126299	1		install new kerb ramp	AF47	Tertiary	CW	\$ 2,500
CD250	Cissoid Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895586	151.125194	1		install new kerb ramp - pair	AF89	Tertiary	CW	\$ 5,000
CD302	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901668	151.120339	1		install new kerb ramp - pair	AF1	Tertiary	CW	\$ 5,000
CD303	Hardy Street	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.902895	151.125609	1		install new kerb ramp	AF79	Tertiary	CW	\$ 2,500
CD304	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90288	151.125449	1		install new kerb ramp	AF79	Tertiary	CW	\$ 2,500
CD306	Hardy Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.900532	151.12706	1		install new kerb ramp	AF80	Tertiary	CW	\$ 2,500
CD307	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900532	151.127095	1		install new kerb ramp	AF80	Tertiary	CW	\$ 2,500
CD307	Piper Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.877576	151.169227	1		install new kerb ramp	AN88	Tertiary	CW	\$ 2,500
CD42	Pritchard Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.878229	151.170896	1		install new kerb ramp - pair	AN123	Tertiary	CW	\$ 5,000
CD424	Beattie Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858811	151.175531	1		install new kerb ramp	BA1	Tertiary	CW	\$ 5,000
CD425	Beattie Street	Balmain	Local Road	crossing deficiency	long crossing point	-33.858726	151.175531	1		install kerb extension	BA1	Tertiary	CW	\$ 10,000
CD426	Beattie Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.858804	151.175589	1		install new kerb ramp - pair	BA1	Tertiary	CW	\$ 5,000
CD486	Hyam Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860664	151.160916	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD487	Hyam Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860655	151.160732	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD490	Hyam Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860685	151.160968	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD491	Hyam Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861172	151.160925	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD513	Palmer Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860709	151.161279	1		install new kerb ramp - pair	BA54	Tertiary	CW	\$ 5,000
CD514	Palmer Street	Balmain	Local Road	crossing deficiency	narrow refuge island	-33.860687	151.161205	1		install new refuge island	BA42	Tertiary	CW	\$ 15,000
CD521	Palmer Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.860638	151.161235	1		install new kerb ramp - pair, new refuge island	BA54	Tertiary	CW	\$ 7,000
CD542	Worley Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860181	151.179425	1		install new kerb ramp - pair	BA75	Tertiary	CW	\$ 5,000
CD543	Worley Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.860336	151.179299	1		install new kerb ramp - pair	BA75	Tertiary	CW	\$ 5,000
CD544	Worley Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.860527	151.179015	1		install new kerb ramp - pair	BA75	Tertiary	CW	\$ 5,000
CD554	Birchgrove Road	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852209	151.17895	1		install new kerb ramp	BI3	Tertiary	CW	\$ 2,500
CD555	Cove Street	Birchgrove	Local Road	crossing deficiency	missing crossing point	-33.852065	151.178828	1		install new kerb ramp - pair	BI3	Tertiary	CW	\$ 5,000
CD556	Cove Street	Birchgrove	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.851002	151.178926	1		install new kerb ramp - pair	BI10	Tertiary	CW	\$ 5,000
CD557	Louisa Road	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.850081	151.179657	1		install new kerb ramp - pair	BI10	Tertiary	CW	\$ 5,000
CD561	Rowntree Street	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.851472	151.184228	1		install new kerb ramp	BI16	Tertiary	CW	\$ 2,500
CD562	Rowntree Street	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852202	151.182531	1		install new kerb ramp	BI17	Tertiary	CW	\$ 2,500
CD563	Rowntree Street	Birchgrove	Local Road	crossing deficiency	missing kerb ramp	-33.852398	151.182533	1		install new kerb ramp	BI17	Tertiary	CW	\$ 2,500
CD568	Rowntree Street	Birchgrove	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.853435	151.180566	1		install new Tactile Ground Surface Indicators	BI15	Tertiary	CW	\$ 650
CD570	Rowntree Street	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852228	151.182613	1		install new kerb ramp	BI17	Tertiary	CW	\$ 2,500
CD578	Kingston Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.893917	151.172067	1		install new kerb ramp	CA22	Tertiary	CW	\$ 2,500
CD579	Kingston Road	Camperdown	Regional Road	crossing deficiency	raised kerb ramp lip	-33.893119	151.172306	1		install new kerb ramp	CA21	Tertiary	CW	\$ 2,500
CD580	Kingston Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.892539	151.172424	1		install new kerb ramp	CA21	Tertiary	CW	\$ 2,500
CD581	Kingston Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.892638	151.172446	1		install new kerb ramp	CA21	Tertiary	CW	\$ 2,500
CD60	Trafalgar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875711	151.175005	1		install new kerb ramp	AN102	Tertiary	CW	\$ 2,500
CD636	Carahston Street	Croydon Park	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.893746	151.146719	1		install new Tactile Ground Surface Indicators	CP4	Tertiary	CW	\$ 650
CD641	Carahston Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891781	151.145428	1		install new kerb ramp	DH13	Tertiary	CW	\$ 5,000
CD647	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900943	151.134714	1		install new kerb ramp	DH13	Tertiary	CW	\$ 2,500
CD649	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901002	151.13488	1		install new kerb ramp	DH14	Tertiary	CW	\$ 2,500
CD650	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901403	151.134803	1		install new kerb ramp - pair	DH14	Tertiary	CW	\$ 5,000
CD651	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901051	151.134998	1		install new kerb ramp	DH13	Tertiary	CW	\$ 5,000
CD652	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901143	151.133606	1		install new kerb ramp - pair	DH13	Tertiary	CW	\$ 5,000
CD653	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901169	151.133558	1		install new kerb ramp - pair	DH13	Tertiary	CW	\$ 5,000
CD655	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901062	151.133621	1		install new kerb ramp - pair	DH13	Tertiary	CW	\$ 5,000
CD661	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910546	151.144987	1		install new kerb ramp - pair	DH7	Tertiary	CW	\$ 5,000
CD662	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910811	151.144903	1		install new kerb ramp - pair	DH7	Tertiary	CW	\$ 5,000
CD663	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910664	151.145399	1		install new kerb ramp - pair	DH7	Tertiary	CW	\$ 5,000
CD668	Warrall Road	Regional Road	Regional Road	crossing deficiency	steep kerb ramp	-33.901102	151.144953	1		install new kerb ramp - pair	DH19	Tertiary	CW	\$ 5,000
CD686	Frazer Street	Dulwich Hill	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.900914	151.144682	1		install new kerb ramp	HS3	Tertiary	CW	\$ 2,500
CD687	Gould Avenue	Dulwich Hill	Local Road	crossing deficiency	steep kerb ramp	-33.900797	151.143637	1		install new kerb ramp - pair	DH35	Tertiary	CW	\$ 5,000
CD695	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909103	151.137948	1		install new kerb ramp - pair	SH59	Tertiary	CW	\$ 5,000
CD745	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898177	151.135	1		install new kerb ramp - pair	SH59	Tertiary	CW	\$ 5,000
CD746	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	long crossing	-33.898206	151.134948	1		install kerb extension - pair	SH59	Tertiary	CW	\$ 20,000
CD747	Aberglelie Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898474	151.134137	1		install new kerb ramp - pair	SH60	Tertiary	CW	\$ 5,000
CD761	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909033	151.137699	1		install new kerb ramp - pair	DH111	Tertiary	CW	\$ 5,000
CD764	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.908404	151.137649	1		install new kerb ramp - pair	DH111	Tertiary	CW	\$ 5,000
CD771	Herbert Street	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.902916	151.148757	1		re-construct refuge island	DH120	Tertiary	CW	\$ 15,000
CD786	Wiston Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897069	151.141882	1		install new kerb ramp - pair	DH1	Tertiary	CW	\$ 5,000
CD81														

P4909 Inner West PAMP Detailed Works Program All Treatments 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD907	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873527	151.137471	1	1	install new kerb ramp - pair	HA109	Tertiary	CW	\$	5,000
CD908	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873554	151.138024	1	1	install new kerb ramp - pair	HA109	Tertiary	CW	\$	5,000
CD909	Waratan Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.873592	151.138055	1	1	install kerb extension - pair	HA109	Tertiary	CW	\$	20,000
CD915	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875555	151.144272	1	1	install new kerb ramp - pair	HA104	Tertiary	CW	\$	5,000
CD916	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877377	151.14468	1	1	install new kerb ramp	HA102	Tertiary	CW	\$	2,500
CD917	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878055	151.145539	1	1	install new kerb ramp - pair	HA102	Tertiary	CW	\$	5,000
CD918	Waratan Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.878386	151.145523	1	1	install kerb extension - pair	HA103	Tertiary	CW	\$	20,000
CD919	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876432	151.144467	1	1	install new kerb ramp - pair	HA103	Tertiary	CW	\$	5,000
CD920	Waratan Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.876428	151.144437	1	1	install kerb extension - pair	HA104	Tertiary	CW	\$	20,000
CD921	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876053	151.143458	1	1	install new kerb ramp - pair	HA104	Tertiary	CW	\$	5,000
CD973	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885493	151.152321	1	1	install new kerb ramp - pair	UH57	Tertiary	CW	\$	5,000
CD975	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886139	151.152476	1	1	install new kerb ramp	UH56	Tertiary	CW	\$	2,500
CD977	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.883226	151.152078	1	1	install new Tactile Ground Surface Indicators	UH45	Tertiary	CW	\$	650
CD978	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.882773	151.152094	1	1	install new Tactile Ground Surface Indicators	UH45	Tertiary	CW	\$	650
CD979	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88212	151.152106	1	1	install new Tactile Ground Surface Indicators	UH45	Tertiary	CW	\$	650
CD981	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881286	151.152101	1	1	install new kerb ramp	UH51	Tertiary	CW	\$	2,500
CD986	Elswick Street	Leichhardt	Local Road	crossing deficiency	steep kerb ramp	-33.882428	151.151885	1	1	install new kerb ramp - pair	UH45	Tertiary	CW	\$	5,000
CD987	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.880898	151.152555	1	1	install new kerb ramp	UH54	Tertiary	CW	\$	2,500
CD988	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.886972	151.152581	1	1	install new Tactile Ground Surface Indicators	UH55	Tertiary	CW	\$	650
CD989	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.886166	151.152389	1	1	install new Tactile Ground Surface Indicators	UH111	Tertiary	CW	\$	650
CN1	Pritchard Street	Annandale	Local Road	connectivity	poor connectivity over bayview cre	-33.972127	151.172909	1	1	install new kerb ramp - pair	AN18	Secondary	CW	\$	5,000
CN10	Bedford Crescent	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.910023	151.139994	1	1	no action	DH24	Secondary	CW	\$	-
CN11	Blackwood Lane	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.907255	151.140385	1	1	no action	DH5	Secondary	CW	\$	-
CN12	Constitution Road	Dulwich Hill	Local Road	connectivity	potential shared zone	-33.901473	151.137106	1	1	investigate shared zone implementation	DH16	Secondary	CW	\$	15,000
CN13	Ewart Street	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.910153	151.13764	1	1	no action	DH110	Tertiary	CW	\$	-
CN14	Hercules Street	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.908558	151.139152	1	1	no action	DH53	Secondary	CW	\$	-
CN15	Old Canterbury Road	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.904119	151.139299	1	1	no action	DH53	Primary	CW	\$	-
CN16	Terry Road	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.8999	151.138617	1	1	no action	DH53	Secondary	CW	\$	-
CN17	Prospect Street	Leichhardt	Local Road	connectivity	potential shared zone	-33.884498	151.159615	1	1	investigate shared zone implementation	UH146	Secondary	CW	\$	15,000
CN18	Myrie Street	Leichhardt	Local Road	connectivity	potential shared zone	-33.883116	151.151657	1	1	investigate shared zone implementation	UH111	Tertiary	CW	\$	15,000
CN19	White Creek	Leichhardt	Local Road	connectivity	missing footpath connectivity	-33.882068	151.158312	1	1	no action	UH105	Secondary	CW	\$	-
CN2	Tralalgar Street	Annandale	Local Road	connectivity	missing footpath connectivity	-33.876721	151.174546	1	1	install new kerb ramp - pair	AN102	Tertiary	CW	\$	5,000
CN20	White Creek	Leichhardt	Local Road	connectivity	missing footpath connectivity	-33.886776	151.163253	1	1	no action	UH157	Secondary	CW	\$	-
CN21	Old Canterbury Road	Lewisham	State Road	connectivity	pedestrian desire line	-33.894716	151.145231	1	1	further investigation required - pedestrian refuge or crossing (signal)	LW19	Primary	CW	\$	15,000
CN22	Hudson Street	Lewisham	Local Road	connectivity	inaccessible link	-33.894072	151.143215	1	1	no action	UW1	Secondary	CW	\$	-
CN23	Hudson Street	Lewisham	Local Road	connectivity	potential shared zone	-33.894051	151.144448	1	1	investigate shared zone implementation	LW5	Primary	CW	\$	15,000
CN24	Malhouse Way	Lewisham	Local Road	connectivity	inaccessible link	-33.892746	151.143981	1	1	no action	LW2	Secondary	CW	\$	-
CN25	River Censor Club	Marrickville	Local Road	connectivity	limited access between car park and path, opportunity to upgrade gate and fencing to provide access	-33.892538	151.153538	1	1	consult with Concordia Club (landowner)	UW45	Secondary	CW	\$	-
CN26	Fraser Street	Marrickville	Regional Road	connectivity	missing crossing point	-33.901178	151.151174	1	1	install new kerb ramp - pair, new refuge island	MV77	Secondary	CW	\$	7,000
CN27	Shinlow Street	Marrickville	Local Road	connectivity	missing footpath connectivity	-33.90998	151.169597	1	1	further investigation required - footpath	MV207	Tertiary	CW	\$	5,000
CN28	Victoria Road	Marrickville	Local Road	connectivity	missing crossing point	-33.90567	151.169553	1	1	further investigation required - crossing point	MV211	Secondary	CW	\$	5,000
CN29	Station Street	Newtown	Local Road	connectivity	potential shared zone	-33.913988	151.153319	1	1	investigate shared zone implementation	MV189	Primary	CW	\$	15,000
CN30	Whites Creek Lane	Annandale	Local Road	connectivity	potential shared zone	-33.883492	151.165393	1	1	investigate shared zone implementation	UH162	Secondary	CW	\$	15,000
CN31	Mary Street	St Peters	Local Road	connectivity	missing footpath connectivity	-33.91314	151.174246	1	1	re-align kerb and footpath	SP186	Tertiary	CW	\$	7,500
CN32	Hattie Avenue	Summer Hill	Local Road	connectivity	potential shared zone	-33.920394	151.137389	1	1	investigate shared zone implementation	UH189	Primary	CW	\$	15,000
CN33	Griffiths Street	Tempe	Local Road	connectivity	path terminates	-33.895058	151.142517	1	1	no action	SH17	Secondary	CW	\$	-
CN34	View Street	Tempe	Local Road	connectivity	footpath terminates	-33.925278	151.156364	1	1	install new kerb ramp - pair	TE32	Secondary	CW	\$	5,000
CN4	Whites Creek Lane	Annandale	Local Road	connectivity	potential shared zone	-33.826968	151.157967	1	1	install new kerb ramp - pair	TE34	Primary	CW	\$	5,000
CN5	Elizabeth Street	Ashfield	Local Road	connectivity	missing footpath connectivity	-33.855056	151.163303	1	1	investigate shared zone implementation	UH159	Secondary	CW	\$	15,000
CN6	Beattie Street	Balmann	Local Road	connectivity	missing kerb ramp	-33.853598	151.119215	1	1	no action	CR20	Secondary	CW	\$	-
CN7	Jane Street	Balmann	Local Road	connectivity	missing footpath connectivity	-33.85774	151.180943	1	1	install new kerb ramp	BA8	Secondary	CW	\$	2,500
CN8	Thames Street	Balmann	Local Road	connectivity	footpath leads to road and driveway	-33.858146	151.184442	1	1	install new kerb ramp	BA44	Primary	CW	\$	2,500
CN9	Rowntree Street	Birchgrove	Local Road	connectivity	poor kerb ramp alignment	-33.855063	151.185892	1	1	review and implement shared zone	BA72	Secondary	CW	\$	40,000
CN10	Pymont Bridge Road	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.85227	151.18265	1	1	install new kerb ramp - pair	BI17	Tertiary	CW	\$	5,000
IC101	Knox Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.888462	151.175339	1	1	re-construct footpath pavement	AN61	Secondary	CW	\$	200
IC102	Liverpool Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.885555	151.12305	1	1	re-construct footpath pavement	AP36	Secondary	CW	\$	200
IC103	Milton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.889394	151.132364	1	1	re-construct footpath pavement	SH28	Secondary	CW	\$	200
IC104	Milton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.894004	151.119156	1	1	re-construct footpath pavement	AF141	Secondary	CW	\$	200
IC105	Milton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.894065	151.118582	1	1	re-construct footpath pavement	AF141	Secondary	CW	\$	200
IC11	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.894973	151.119457	1	1	re-construct footpath pavement	AF142	Secondary	CW	\$	200
IC110	Orpington Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.886002	151.175123	1	1	re-construct footpath pavement	AN90	Secondary	CW	\$	200
IC111	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884715	151.133984	1	1	re-construct footpath pavement	AF137	Secondary	CW	\$	200
IC112	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894978	151.120048	1	1	re-construct footpath pavement	AF142	Secondary	CW	\$	200
IC113	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.895144	151.122933	1	1	re-construct footpath pavement	AF139	Secondary	CW	\$	200
IC114	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894911	151.120822	1	1	re-construct footpath pavement	AF143	Secondary	CW	\$	200
IC115	Paramatta Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.894962	151.120159	1	1	re-construct footpath pavement	AF143	Secondary	CW	\$	200
IC116	Paramatta Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.88019	151.131729	1	1	re-construct footpath pavement	HA69	Secondary	CW	\$	200
IC117	Paramatta Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.878404	151.130515	1	1	re-construct footpath pavement	HA68	Secondary	CW	\$	200
IC118	Primer Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894967	151.119758	1	1	re-construct footpath pavement	AF142	Secondary	CW	\$	200
IC119	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.891575	151.127839	1	1	re-construct footpath pavement	AF143	Secondary	CW	\$	200
IC120	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.892261	151.127785	1	1	re-construct footpath pavement	AF149	Secondary	CW	\$	200
IC121	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.892643	151.127751	1	1	re-construct footpath pavement	AF149	Secondary	CW	\$	200
IC122	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894407	151.127638	1	1	re-construct footpath pavement	AF149	Secondary	CW	\$	200
IC123	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.895027	151.129933	1	1	re-construct footpath pavement	AF159	Secondary	CW	\$	200
IC124	Buchanan Street	Balmann	Local Road	infrastructure condition	uneven pavement surface	-33.863147	151.180997	1	1	re-construct footpath pavement	BA18	Tertiary	CW	\$	200
IC125	Buchanan Street	Balmann	Local Road	infrastructure condition	uneven pavement surface	-33.862534	151.180347	1	1	re-construct footpath pavement	BA18	Tertiary	CW	\$	200
IC126	Buchanan Street	Balmann	Local Road	infrastructure condition	uneven pavement surface	-33.862707	151.180294	1	1	re-construct footpath pavement	BA18	Tertiary	CW	\$	200
IC127	Buchanan Street	Balmann	Local Road	infrastructure condition	raised pavement tip	-33.862896	151.180159	1	1	repair pavement panel	BA18	Tertiary	CW	\$	200
IC128	Buchanan Street	Balmann	Local Road	infrastructure condition	uneven pavement surface	-33.863539	151.180493	1	1	re-construct footpath pavement	BA17	Tertiary	CW	\$	200
IC129	Hyam Street	Balmann	Local Road	infrastructure condition	uneven pavement surface	-33.860622	151.180499	1	1	re-construct footpath pavement	BA42	Tertiary	CW	\$	200
IC13	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.886071	151.17496	1	1	re-construct footpath pavement	AN90	Secondary	CW	\$	200
IC130	Hyam Street	Balmann	Local Road	infrastructure condition	raised pavement tip	-33.861575	151.180139	1	1	repair pavement panel	BA43	Secondary	CW	\$	200
IC131	Hyam Street	Balmann	Local Road	infrastructure condition	raised pavement tip	-33.860854	151.181107	1	1	repair pavement panel	BA42	Tertiary	CW	\$	200
IC132	Jane Street	Balmann	Local Road	infrastructure condition	raised pavement tip	-33.859728	151.184177	1	1	repair pavement panel	BA45	Secondary	CW	\$	200
IC134	Montague Street	Balmann	Regional Road	infrastructure condition	uneven pavement surface	-33.858554	151.177511	1	1	re-construct footpath pavement	BA48	Secondary	CW	\$	200
IC135	Palmer Street	Balmann	Local Road	infrastructure condition	raised pavement tip	-33.860594	151.181076	1	1	repair pavement panel	BA55	Secondary	CW	\$	200
IC136	Palmer Street	Balmann	Local Road	infrastructure condition	uneven pavement surface	-33.858813	151.18048								

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
IC145	Rowley Street	Camperdown	Local Road	infrastructure condition	raised pavement tip	-33.893262	151.172128	1		repair pavement panel	CA22	Tertiary	LOW	\$ 200
IC146	Croydon Road	Croydon	Local Road	infrastructure condition	uneven pavement surface	-33.880102	151.120202	1		re-construct footpath pavement	CR3	Secondary	LOW	\$ 200
IC147	Panramatta Road	Croydon	State Road	infrastructure condition	uneven pavement surface	-33.872536	151.153155	1		re-construct footpath pavement	CR30	Secondary	LOW	\$ 200
IC148	Panramatta Road	Croydon	State Road	infrastructure condition	uneven pavement surface	-33.871481	151.122472	1		re-construct footpath pavement	CR27	Secondary	LOW	\$ 200
IC149	Blackwood Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.908915	151.140695	1		re-construct footpath pavement	DH4	Secondary	LOW	\$ 200
IC150	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.884554	151.171124	1		repair pavement panel	AN109	Secondary	LOW	\$ 200
IC151	Blackwood Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.908881	151.140914	1		re-construct footpath pavement	DH4	Secondary	LOW	\$ 200
IC152	Challis Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.910233	151.144798	1		re-construct footpath pavement	DH8	Secondary	LOW	\$ 200
IC153	Challis Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.910446	151.145296	1		re-construct footpath pavement	DH8	Secondary	LOW	\$ 200
IC154	Consett Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.910065	151.144843	1		re-construct footpath pavement	DH8	Secondary	LOW	\$ 200
IC155	Consett Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905795	151.138105	1		re-construct footpath pavement	DH9	Secondary	LOW	\$ 200
IC156	Constitution Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905883	151.138515	1		re-construct footpath pavement	DH9	Secondary	LOW	\$ 200
IC157	Constitution Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.903692	151.140775	1		re-construct footpath pavement	DH18	Secondary	LOW	\$ 200
IC16	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.901355	151.136930	1		re-construct footpath pavement	DH15	Secondary	LOW	\$ 200
IC161	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.882628	151.1719	1		repair pavement panel	AN108	Secondary	LOW	\$ 200
IC162	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909683	151.136692	1		re-construct footpath pavement	DH33	Secondary	LOW	\$ 200
IC163	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909608	151.136772	1		re-construct footpath pavement	DH32	Secondary	LOW	\$ 200
IC164	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909616	151.137230	1		re-construct footpath pavement	DH32	Secondary	LOW	\$ 200
IC165	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90966	151.137396	1		re-construct footpath pavement	DH32	Secondary	LOW	\$ 200
IC166	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909733	151.137515	1		re-construct footpath pavement	DH32	Secondary	LOW	\$ 200
IC167	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90966	151.137397	1		re-construct footpath pavement	DH32	Secondary	LOW	\$ 200
IC168	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90967	151.13705	1		re-construct footpath pavement	DH32	Secondary	LOW	\$ 200
IC169	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909797	151.136192	1		re-construct footpath pavement	DH33	Secondary	LOW	\$ 200
IC17	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.909623	151.135701	1		re-construct footpath pavement	DH28	Secondary	LOW	\$ 200
IC170	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.88162	151.172315	1		repair pavement panel	AN105	Secondary	LOW	\$ 200
IC171	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909003	151.13552	1		re-construct footpath pavement	DH28	Secondary	LOW	\$ 200
IC172	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.91405	151.138478	1		re-construct footpath pavement	DH30	Secondary	LOW	\$ 200
IC174	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.911422	151.139631	1		re-construct footpath pavement	DH30	Secondary	LOW	\$ 200
IC175	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.910111	151.147558	1		re-construct footpath pavement	DH36	Tertiary	LOW	\$ 200
IC176	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.909028	151.146794	1		re-construct footpath pavement	DH35	Tertiary	LOW	\$ 200
IC177	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.909115	151.146185	1		re-construct footpath pavement	DH35	Tertiary	LOW	\$ 200
IC178	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90876	151.145604	1		re-construct footpath pavement	DH34	Secondary	LOW	\$ 200
IC179	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898195	151.137649	1		re-construct footpath pavement	DH63	Secondary	LOW	\$ 200
IC18	Trafalgar Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.898265	151.137786	1		re-construct footpath pavement	DH63	Secondary	LOW	\$ 200
IC180	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.891558	151.172259	1		re-construct footpath pavement	DH68	Secondary	LOW	\$ 200
IC181	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.897286	151.136735	1		re-construct footpath pavement	DH62	Secondary	LOW	\$ 200
IC182	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.897889	151.137298	1		re-construct footpath pavement	DH62	Secondary	LOW	\$ 200
IC183	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.89712	151.136815	1		re-construct footpath pavement	DH25	Secondary	LOW	\$ 200
IC184	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.90668	151.139018	1		re-construct footpath pavement	DH65	Secondary	LOW	\$ 200
IC185	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.907027	151.138988	1		repair pavement panel	DH65	Secondary	LOW	\$ 200
IC186	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90664	151.138815	1		re-construct footpath pavement	DH63	Secondary	LOW	\$ 200
IC187	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90681	151.139298	1		re-construct footpath pavement	DH68	Secondary	LOW	\$ 200
IC188	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.900676	151.138947	1		re-construct footpath pavement	DH68	Secondary	LOW	\$ 200
IC189	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90527	151.139044	1		re-construct footpath pavement	DH68	Secondary	LOW	\$ 200
IC19	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.90801	151.139379	1		re-construct footpath pavement	DH68	Secondary	LOW	\$ 200
IC190	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.897786	151.172629	1		repair pavement panel	AN108	Secondary	LOW	\$ 200
IC191	Marionville Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.900996	151.139755	1		re-construct footpath pavement	DH68	Secondary	LOW	\$ 200
IC193	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905952	151.145327	1		install new utility cover	DH77	Secondary	LOW	\$ 2,000
IC196	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	poorly defined kerb ramp	-33.90481	151.137779	1		install new kerb ramp	DH70	Secondary	LOW	\$ 2,500
IC199	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90096	151.141538	1		re-construct footpath pavement	DH104	Secondary	LOW	\$ 200
IC20	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.901504	151.141534	1		re-construct footpath pavement	DH104	Secondary	LOW	\$ 200
IC200	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.881460	151.17238	1		repair pavement panel	AN105	Secondary	LOW	\$ 200
IC201	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901337	151.142066	1		re-construct footpath pavement	DH104	Secondary	LOW	\$ 200
IC202	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901883	151.143021	1		re-construct footpath pavement	DH101	Secondary	LOW	\$ 200
IC203	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902134	151.143397	1		re-construct footpath pavement	DH105	Secondary	LOW	\$ 200
IC204	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902414	151.143651	1		re-construct footpath pavement	DH101	Secondary	LOW	\$ 200
IC205	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902146	151.143526	1		re-construct footpath pavement	DH105	Secondary	LOW	\$ 200
IC206	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901846	151.143034	1		re-construct footpath pavement	DH101	Secondary	LOW	\$ 200
IC207	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901736	151.142851	1		re-construct footpath pavement	DH101	Secondary	LOW	\$ 200
IC208	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901571	151.142499	1		re-construct footpath pavement	DH101	Secondary	LOW	\$ 200
IC209	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90107	151.141722	1		re-construct footpath pavement	DH104	Secondary	LOW	\$ 200
IC21	Trafalgar Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.900644	151.140782	1		re-construct footpath pavement	DH103	Secondary	LOW	\$ 200
IC210	Riverside Crescent	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.89638	151.172612	1		re-construct footpath pavement	AN109	Secondary	LOW	\$ 200
IC211	Tennysen Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.911989	151.138515	1		re-construct footpath pavement	MV236	Secondary	LOW	\$ 200
IC212	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.911069	151.136777	1		re-construct footpath pavement	DH38	Secondary	LOW	\$ 200
IC213	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.908807	151.137658	1		re-construct footpath pavement	DH11	Tertiary	LOW	\$ 200
IC214	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90941	151.138031	1		re-construct footpath pavement	DH52	Secondary	LOW	\$ 200
IC215	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909504	151.137962	1		re-construct footpath pavement	DH39	Secondary	LOW	\$ 200
IC216	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.907076	151.137672	1		repair pavement panel	DH114	Secondary	LOW	\$ 200
IC217	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.907557	151.137812	1		repair pavement panel	DH113	Tertiary	LOW	\$ 200
IC218	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.908372	151.137563	1		repair pavement panel	DH111	Tertiary	LOW	\$ 200
IC219	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.908429	151.137498	1		repair pavement panel	DH114	Secondary	LOW	\$ 200
IC22	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.907557	151.137812	1		repair pavement panel	AN105	Secondary	LOW	\$ 200
IC220	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.880371	151.172854	1		repair pavement panel	DH114	Secondary	LOW	\$ 200
IC221	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.901169	151.137982	1		repair pavement panel	DH114	Secondary	LOW	\$ 200
IC222	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.900336	151.138018	1		repair pavement panel	DH112	Secondary	LOW	\$ 200
IC223	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905362	151.137849	1		re-construct footpath pavement	DH12	Secondary	LOW	\$ 200
IC224	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905767	151.138039	1		re-construct footpath pavement	DH12	Secondary	LOW	\$ 200
IC225	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905621	151.138098	1		re-construct footpath pavement	DH9	Secondary	LOW	\$ 200
IC226	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905625	151.138028	1		re-construct footpath pavement	DH112	Secondary	LOW	\$ 200
IC227	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905163	151.137979	1		re-construct footpath pavement	DH112	Secondary	LOW	\$ 200
IC228	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.906477	151.145903	1		re-construct footpath pavement	DH121	Secondary	LOW	\$ 200
IC229	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.905026	151.147532	1		re-construct footpath pavement	DH123	Tertiary	LOW	\$ 200
IC23	Hutchinson Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.87759	151.174015	1		repair pavement panel	AN103	Secondary	LOW	\$ 200
IC230	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.904229	151.146266	1		re-construct footpath pavement	MV234	Secondary	LOW	\$ 200
IC235	Marionville Golf Club	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.912124	151.138583	1		re-construct footpath pavement	DH106	Tertiary	LOW	\$ 200
IC236	Marionville Golf Club	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.913366	151.137498	1		re-construct footpath pavement	DH106	Tertiary	LOW	\$ 200
IC237	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.912957	151.139847	1		re-construct footpath pavement	MV236	Secondary	LOW	\$ 200
IC238	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.912546	151.1392	1		re-construct footpath pavement	MV236	Secondary	LOW	\$ 200
IC239	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.912439	151.1394	1		re-construct footpath pavement	MV237	Secondary	LOW	\$ 200
IC24	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-								

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
C244	Alt Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.878685	151.132113	1	1	re-construct footpath pavement	HA2	Secondary	LOW	LOW	\$ 200
C245	Bay Run	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.871593	151.148349	1	1	re-construct footpath pavement	HA10	Secondary	LOW	LOW	\$ 200
C246	Bay Run	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.871192	151.148701	1	1	re-construct footpath pavement	HA10	Secondary	LOW	LOW	\$ 200
C247	Bland Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.878494	151.133356	1	1	re-construct footpath pavement	HA16	Secondary	LOW	LOW	\$ 200
C248	Boomerang Street	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.870762	151.145227	1	1	repair pavement panel	HA22	Secondary	LOW	LOW	\$ 200
C249	Boomerang Street	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.871493	151.146636	1	1	repair pavement panel	HA23	Secondary	LOW	LOW	\$ 200
C25	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.877488	151.17422	1	1	repair pavement panel	AN103	Secondary	LOW	LOW	\$ 200
C250	Boomerang Street	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.874147	151.142839	1	1	repair pavement panel	HA27	Secondary	LOW	LOW	\$ 200
C251	Dalhousie Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.882979	151.136883	1	1	re-construct footpath pavement	HA39	Secondary	LOW	LOW	\$ 200
C252	Denman Avenue	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.878462	151.135217	1	1	repair pavement panel	HA40	Secondary	LOW	LOW	\$ 200
C253	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.880266	151.135457	1	1	re-construct footpath pavement	HA43	Secondary	LOW	LOW	\$ 200
C254	Denman Avenue	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.880273	151.135543	1	1	repair pavement panel	HA43	Secondary	LOW	LOW	\$ 200
C255	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.880352	151.13563	1	1	re-construct footpath pavement	HA43	Secondary	LOW	LOW	\$ 200
C256	Denman Avenue	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.881059	151.136636	1	1	repair pavement panel	HA41	Secondary	LOW	LOW	\$ 200
C257	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.881689	151.136846	1	1	re-construct footpath pavement	HA41	Secondary	LOW	LOW	\$ 200
C258	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.881729	151.137117	1	1	re-construct footpath pavement	HA41	Secondary	LOW	LOW	\$ 200
C259	Parramatta Road	Haberfield	State Road	infrastructure condition	uneven pavement surface	-33.887013	151.142519	1	1	re-construct footpath pavement	HA78	Secondary	LOW	LOW	\$ 200
C26	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.875971	151.174774	1	1	repair pavement panel	AN102	Tertiary	LOW	LOW	\$ 200
C260	Parramatta Road	Haberfield	State Road	infrastructure condition	uneven pavement surface	-33.874501	151.128004	1	1	re-construct footpath pavement	HA80	Secondary	LOW	LOW	\$ 200
C261	Ramsey Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.884442	151.142595	1	1	re-construct footpath pavement	HA91	Secondary	LOW	LOW	\$ 200
C262	Ramsey Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.874586	151.144224	1	1	re-construct footpath pavement	HA97	Secondary	LOW	LOW	\$ 200
C263	Warant Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.877133	151.145712	1	1	re-construct footpath pavement	HA102	Tertiary	LOW	LOW	\$ 200
C264	Warant Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.877289	151.1461	1	1	re-construct footpath pavement	HA102	Tertiary	LOW	LOW	\$ 200
C265	Hardy Street	Hurlstone Park	Local Road	infrastructure condition	raised pavement tip	-33.905366	151.126119	1	1	repair pavement panel	HP2	Secondary	LOW	LOW	\$ 200
C266	Hardy Street	Hurlstone Park	Local Road	infrastructure condition	raised pavement tip	-33.9041	151.124983	1	1	repair pavement panel	HP1	Secondary	LOW	LOW	\$ 200
C268	Darley Road	Leichhardt	State Road	infrastructure condition	raised pavement tip	-33.877639	151.148796	1	1	repair pavement panel	LH38	Secondary	LOW	LOW	\$ 200
C269	Alley Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.880359	151.147759	1	1	re-construct footpath pavement	LH2	Secondary	LOW	LOW	\$ 200
C27	Nelson Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.878676	151.174734	1	1	re-construct footpath pavement	AN69	Secondary	LOW	LOW	\$ 200
C272	Flood Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.877968	151.150199	1	1	re-construct footpath pavement	LH63	Tertiary	LOW	LOW	\$ 200
C273	Flood Street	Leichhardt	Local Road	infrastructure condition	raised pavement tip	-33.878309	151.150183	1	1	repair pavement panel	LH63	Tertiary	LOW	LOW	\$ 200
C274	Flood Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.879207	151.150195	1	1	re-construct footpath pavement	LH63	Tertiary	LOW	LOW	\$ 200
C275	Flood Street	Leichhardt	Local Road	infrastructure condition	raised pavement tip	-33.884894	151.150049	1	1	repair pavement panel	LH62	Secondary	LOW	LOW	\$ 200
C279	Marion Street	Leichhardt	Regional Road	infrastructure condition	uneven pavement surface	-33.884197	151.151554	1	1	re-construct footpath pavement	LH97	Secondary	LOW	LOW	\$ 200
C28	Nelson Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.877125	151.176094	1	1	repair pavement panel	AN66	Secondary	LOW	LOW	\$ 200
C281	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.886927	151.148312	1	1	re-construct footpath pavement	AN68	Secondary	LOW	LOW	\$ 200
C285	Tebbutt Street	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.886668	151.146981	1	1	re-construct footpath pavement	LH155	Secondary	LOW	LOW	\$ 200
C286	William Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.877642	151.152683	1	1	re-construct footpath pavement	LH174	Secondary	LOW	LOW	\$ 200
C287	William Street	Leichhardt	Local Road	infrastructure condition	raised pavement tip	-33.877647	151.152683	1	1	repair pavement panel	LH156	Secondary	LOW	LOW	\$ 200
C288	William Street	Leichhardt	Local Road	infrastructure condition	raised pavement tip	-33.877533	151.154347	1	1	repair pavement panel	LH168	Secondary	LOW	LOW	\$ 200
C291	Old Canterbury Road	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.895165	151.143491	1	1	re-construct footpath pavement	LW20	Secondary	LOW	LOW	\$ 200
C292	Parramatta Road	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.889953	151.148613	1	1	re-construct footpath pavement	LH134	Secondary	LOW	LOW	\$ 200
C296	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.872108	151.151512	1	1	re-construct footpath pavement	L12	Secondary	LOW	LOW	\$ 200
C297	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.867821	151.152079	1	1	re-construct footpath pavement	L25	Secondary	LOW	LOW	\$ 200
C298	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.867116	151.152618	1	1	re-construct footpath pavement	L24	Secondary	LOW	LOW	\$ 200
C299	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.868118	151.155479	1	1	re-construct footpath pavement	L25	Secondary	LOW	LOW	\$ 200
C300	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.871678	151.169116	1	1	re-construct footpath pavement	L775	Secondary	LOW	LOW	\$ 200
C301	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.872954	151.165581	1	1	re-construct footpath pavement	L771	Secondary	LOW	LOW	\$ 200
C302	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.87373	151.164623	1	1	re-construct footpath pavement	L768	Secondary	LOW	LOW	\$ 200
C303	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.873439	151.164074	1	1	re-construct footpath pavement	L768	Secondary	LOW	LOW	\$ 200
C304	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.873577	151.163525	1	1	re-construct footpath pavement	L768	Secondary	LOW	LOW	\$ 200
C305	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.874294	151.160758	1	1	re-construct footpath pavement	L769	Secondary	LOW	LOW	\$ 200
C306	Lilyfield Road	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.874358	151.1598	1	1	re-construct footpath pavement	L764	Tertiary	LOW	LOW	\$ 200
C307	Lilyfield Road	Lilyfield	Local Road	infrastructure condition	raised pavement tip	-33.873172	151.154358	1	1	repair pavement panel	L763	Secondary	LOW	LOW	\$ 200
C308	Lilyfield Road	Lilyfield	Local Road	infrastructure condition	raised pavement tip	-33.87395	151.167137	1	1	repair pavement panel	L766	Secondary	LOW	LOW	\$ 200
C309	Riley Street	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.867911	151.154067	1	1	re-construct footpath pavement	L761	Tertiary	LOW	LOW	\$ 200
C310	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914136	151.143639	1	1	re-construct footpath pavement	MV16	Secondary	LOW	LOW	\$ 200
C311	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91432	151.143534	1	1	re-construct footpath pavement	MV16	Secondary	LOW	LOW	\$ 200
C312	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914347	151.143775	1	1	re-construct footpath pavement	MV16	Secondary	LOW	LOW	\$ 200
C313	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914117	151.143838	1	1	re-construct footpath pavement	MV15	Secondary	LOW	LOW	\$ 200
C314	Byrnes Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913779	151.155462	1	1	re-construct footpath pavement	MV188	Secondary	LOW	LOW	\$ 200
C315	Calvert Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911788	151.155566	1	1	re-construct footpath pavement	MV20	Secondary	LOW	LOW	\$ 200
C316	Carrington Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918844	151.156192	1	1	re-construct footpath pavement	MV27	Tertiary	LOW	LOW	\$ 200
C317	Carrington Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918146	151.156198	1	1	re-construct footpath pavement	MV28	Tertiary	LOW	LOW	\$ 200
C318	Carrington Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.917574	151.157004	1	1	re-construct footpath pavement	MV23	Tertiary	LOW	LOW	\$ 200
C32	Parramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.887819	151.169057	1	1	re-construct footpath pavement	AN79	Secondary	LOW	LOW	\$ 200
C325	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914166	151.142172	1	1	re-construct footpath pavement	MV88	Secondary	LOW	LOW	\$ 200
C326	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914225	151.142955	1	1	re-construct footpath pavement	MV88	Secondary	LOW	LOW	\$ 200
C327	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91383	151.142127	1	1	re-construct footpath pavement	MV85	Secondary	LOW	LOW	\$ 200
C328	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91366	151.141939	1	1	re-construct footpath pavement	MV85	Secondary	LOW	LOW	\$ 200
C330	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907527	151.165098	1	1	re-construct footpath pavement	MV70	Tertiary	LOW	LOW	\$ 200
C331	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907572	151.16804	1	1	re-construct footpath pavement	MV70	Tertiary	LOW	LOW	\$ 200
C332	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907701	151.16769	1	1	re-construct footpath pavement	MV71	Tertiary	LOW	LOW	\$ 200
C333	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.908165	151.167388	1	1	re-construct footpath pavement	MV71	Tertiary	LOW	LOW	\$ 200
C334	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911045	151.164243	1	1	re-construct footpath pavement	MV202	Secondary	LOW	LOW	\$ 200
C335	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.90786	151.167496	1	1	re-construct footpath pavement	MV71	Tertiary	LOW	LOW	\$ 200
C336	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907164	151.168267	1	1	re-construct footpath pavement	MV70	Tertiary	LOW	LOW	\$ 200
C337	Frazer Street	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.901273	151.152307	1	1	re-construct footpath pavement	MV6	Secondary	LOW	LOW	\$ 200
C338	Frazer Street	Marrickville	Regional Road	infrastructure condition	damaged kerb ramp	-33.901189	151.150702	1	1	install new kerb ramp	MV76	Secondary	LOW	2,500	\$ 2,500
C339	Frazer Street	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.901148	151.152558	1	1	re-construct footpath pavement	MV75	Secondary	LOW	LOW	\$ 200
C34	Victoria Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.904903	151.128939	1	1	re-construct footpath pavement	AF159	Secondary	LOW	LOW	\$ 200
C340	Illawarra Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909921	151.157573	1	1	re-construct footpath pavement	MV81	Secondary	LOW	LOW	\$ 200
C341	Illawarra Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909092	151.157821	1	1	re-construct footpath pavement	MV81	Secondary	LOW	LOW	\$ 200
C342	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.918212	151.146827	1	1	re-construct footpath pavement	MV100	Secondary	LOW	LOW	\$ 200
C343	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.913167	151.14409	1	1	re-construct footpath pavement	MV80	Secondary	LOW	LOW	\$ 200
C344	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.920657	151.144234	1	1	re-construct footpath pavement	MV80	Secondary	LOW	LOW	\$ 200
C348	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.903745	151.153108	1	1	re-construct footpath pavement	MV110	Secondary	LOW	LOW	\$ 200
C349	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911391	151.148918	1	1	re-construct footpath pavement	MV106	Secondary	LOW		



Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
C357	Livingstone Road	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.91248	-151.147629	1	-	re-construct topsoil pavement	CV19	Secondary	LOW	S	200
C358	Livingstone Road	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.91187	-151.148346	1	-	re-construct topsoil pavement	CV22	Secondary	LOW	S	200
C359	Livingstone Road	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.911572	-151.148593	1	-	re-construct topsoil pavement	CV22	Secondary	LOW	S	200
C36	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.88017	-151.129602	1	-	repair pavement panel	AF166	Secondary	LOW	S	200
C362	Livingstone Road	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.90704	-151.151748	1	-	re-construct topsoil pavement	CV22	Secondary	LOW	S	200
C367	Lewellyn Street	Manicville	Regional Road	infrastructure condition	uneven pavement surface	-33.904071	-151.171122	1	-	re-construct topsoil pavement	CV225	Secondary	LOW	S	200
C368	Lewellyn Street	Manicville	Regional Road	infrastructure condition	uneven pavement surface	-33.904027	-151.171015	1	-	re-construct topsoil pavement	CV226	Secondary	LOW	S	200
C37	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.88039	-151.129571	1	-	repair pavement panel	AF167	Secondary	LOW	S	200
C371	Myrtle Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.915458	-151.157292	1	-	re-construct topsoil pavement	CV146	Tertiary	LOW	S	200
C372	Premier Street	Manicville	Local Road	infrastructure condition	raised pavement lip	-33.920737	-151.153043	1	-	repair pavement panel	CV159	Secondary	LOW	S	200
C373	Premier Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.920544	-151.152679	1	-	re-construct topsoil pavement	CV161	Secondary	LOW	S	200
C374	Premier Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.919945	-151.151656	1	-	re-construct topsoil pavement	CV161	Secondary	LOW	S	200
C375	Premier Street	Manicville	Local Road	infrastructure condition	raised pavement lip	-33.919425	-151.150648	1	-	repair pavement panel	CV163	Secondary	LOW	S	200
C376	Premier Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.918839	-151.149624	1	-	re-construct topsoil pavement	CV168	Tertiary	LOW	S	200
C377	Premier Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.918615	-151.148926	1	-	re-construct topsoil pavement	CV168	Tertiary	LOW	S	200
C378	Premier Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.918644	-151.148271	1	-	re-construct topsoil pavement	CV168	Tertiary	LOW	S	200
C379	Premier Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.918414	-151.146852	1	-	re-construct topsoil pavement	CV160	Tertiary	LOW	S	200
C38	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.897089	-151.129756	1	-	re-construct topsoil pavement	AF166	Secondary	LOW	S	200
C381	Renwick Street	Manicville	Local Road	infrastructure condition	raised pavement lip	-33.919431	-151.154693	1	-	repair pavement panel	CV169	Tertiary	LOW	S	200
C382	Renwick Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.919658	-151.154756	1	-	re-construct topsoil pavement	CV169	Tertiary	LOW	S	200
C383	Renwick Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.919451	-151.154452	1	-	re-construct topsoil pavement	CV169	Tertiary	LOW	S	200
C384	Renwick Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.918971	-151.153752	1	-	re-construct topsoil pavement	CV172	Tertiary	LOW	S	200
C385	Renwick Street	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.9186	-151.153227	1	-	re-construct topsoil pavement	CV172	Tertiary	LOW	S	200
C386	Richardson Crescent	Manicville	Regional Road	infrastructure condition	uneven pavement surface	-33.922139	-151.156581	1	-	re-construct topsoil pavement	CV175	Secondary	LOW	S	200
C387	Richardson Crescent	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.920799	-151.155942	1	-	re-construct topsoil pavement	CV173	Tertiary	LOW	S	200
C388	Richardson Crescent	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.914943	-151.141807	1	-	re-construct topsoil pavement	CV179	Tertiary	LOW	S	200
C389	Riverside Crescent	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.914859	-151.140669	1	-	re-construct topsoil pavement	CV180	Tertiary	LOW	S	200
C39	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.898121	-151.129566	1	-	repair pavement panel	AF167	Secondary	LOW	S	200
C390	Riverside Crescent	Manicville	Local Road	infrastructure condition	uneven pavement surface	-33.914501	-151.13651	1	-	re-construct topsoil pavement	CV177	Tertiary	LOW	S	200
C391	Riverside Crescent	Manicville	Local Road	infrastructure condition											

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
IC47	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.900491	151.129551	1	1	re-construct footpath pavement	AF169	Secondary	LOW	\$ 200
IC470	Palace Street	Petersham	Local Road	infrastructure condition	uneven pavement surface	-33.889442	151.154448	1	1	re-construct footpath pavement	PE40	Secondary	LOW	\$ 200
IC473	Denison Street	Rozelle	Local Road	infrastructure condition	raised pavement tip	-33.869471	151.169343	1	1	repair pavement panel	RO28	Secondary	LOW	\$ 200
IC474	Denison Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.869494	151.169409	1	1	re-construct footpath pavement	RO28	Tertiary	LOW	\$ 200
IC475	Denison Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.869621	151.169665	1	1	re-construct footpath pavement	RO28	Tertiary	LOW	\$ 200
IC476	Denison Street	Rozelle	Local Road	infrastructure condition	raised pavement tip	-33.869676	151.169735	1	1	repair pavement panel	RO28	Tertiary	LOW	\$ 200
IC477	James Craig Road	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.870037	151.172591	1	1	re-construct footpath pavement	RO44	Secondary	LOW	\$ 200
IC478	Lilyfield Road	Rozelle	Regional Road	infrastructure condition	uneven pavement surface	-33.868791	151.173596	1	1	re-construct footpath pavement	RO42	Secondary	LOW	\$ 200
IC479	Manning Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.86558	151.169663	1	1	re-construct footpath pavement	RO52	Secondary	LOW	\$ 200
IC48	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.900537	151.129332	1	1	repair pavement panel	AF169	Secondary	LOW	\$ 200
IC480	Robert Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.865842	151.177476	1	1	re-construct footpath pavement	RO58	Tertiary	LOW	\$ 200
IC481	Robert Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.865439	151.178104	1	1	re-construct footpath pavement	RO61	Tertiary	LOW	\$ 200
IC482	Terry Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.86028	151.170471	1	1	re-construct footpath pavement	RO63	Secondary	LOW	\$ 200
IC483	Terry Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.859119	151.17078	1	1	re-construct footpath pavement	RO69	Secondary	LOW	\$ 200
IC484	Terry Street	Rozelle	Local Road	infrastructure condition	damaged kerb ramp	-33.858737	151.171139	1	1	install new kerb ramp	RO64	Secondary	LOW	\$ 2,500
IC485	Terry Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.859603	151.170783	1	1	re-construct footpath pavement	RO69	Secondary	LOW	\$ 200
IC486	The Crescent	Rozelle	State Road	infrastructure condition	uneven pavement surface	-33.869787	151.175162	1	1	no action	RO42	Secondary	LOW	\$ -
IC487	Victoria Road	Rozelle	State Road	infrastructure condition	uneven pavement surface	-33.868998	151.176183	1	1	re-construct footpath pavement	RO75	Secondary	LOW	\$ 200
IC488	Victoria Road	Rozelle	State Road	infrastructure condition	uneven pavement surface	-33.86722	151.17533	1	1	re-construct footpath pavement	RO70	Secondary	LOW	\$ 200
IC489	Victoria Road	Rozelle	State Road	infrastructure condition	uneven pavement surface	-33.866281	151.174601	1	1	re-construct footpath pavement	RO74	Secondary	LOW	\$ 200
IC49	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.901631	151.129451	1	1	re-construct footpath pavement	AF170	Secondary	LOW	\$ 200
IC490	Bedwin Road	St Peters	Regional Road	infrastructure condition	uneven pavement surface	-33.900609	151.175616	1	1	re-construct footpath pavement	MF18	Secondary	LOW	\$ 200
IC491	Bedwin Road	St Peters	Regional Road	infrastructure condition	uneven pavement surface	-33.900592	151.175224	1	1	re-construct footpath pavement	MF18	Secondary	LOW	\$ 200
IC492	Church Street	St Peters	Local Road	infrastructure condition	uneven pavement surface	-33.912979	151.177633	1	1	re-construct footpath pavement	SP7	Secondary	LOW	\$ 200
IC493	Edith Street	St Peters	Local Road	infrastructure condition	uneven pavement surface	-33.912383	151.173286	1	1	re-construct footpath pavement	SP35	Tertiary	LOW	\$ 200
IC494	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.916854	151.172236	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200
IC495	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.916453	151.169899	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200
IC496	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.916453	151.169899	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200
IC497	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.916765	151.172728	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200
IC50	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.901178	151.129294	1	1	repair pavement panel	AF169	Secondary	LOW	\$ 200
IC503	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.915266	151.176719	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200
IC506	Railway Avenue	Stammore	Local Road	infrastructure condition	uneven pavement surface	-33.894394	151.169932	1	1	re-construct footpath pavement	SM38	Tertiary	LOW	\$ 200
IC507	Carlton Crescent	Summer Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.897777	151.131969	1	1	re-construct footpath pavement	SH8	Secondary	LOW	\$ 200
IC508	Grosvener Crescent	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.899329	151.133027	1	1	re-construct footpath pavement	SH28	Secondary	LOW	\$ 200
IC509	Henson Street	Summer Hill	Local Road	infrastructure condition	raised pavement tip	-33.897201	151.134566	1	1	repair pavement panel	SH10	Secondary	LOW	\$ 200
IC51	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.902275	151.126391	1	1	repair pavement panel	AF170	Secondary	LOW	\$ 200
IC510	Henson Street	Summer Hill	Local Road	infrastructure condition	raised pavement tip	-33.897136	151.134459	1	1	repair pavement panel	SH35	Secondary	LOW	\$ 200
IC511	Henson Street	Summer Hill	Local Road	infrastructure condition	raised pavement tip	-33.898479	151.134451	1	1	repair pavement panel	SH35	Secondary	LOW	\$ 200
IC512	Herbert Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.896277	151.134181	1	1	re-construct footpath pavement	SH37	Secondary	LOW	\$ 200
IC513	James Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.897356	151.135608	1	1	re-construct footpath pavement	SH38	Secondary	LOW	\$ 200
IC514	Junction Road	Summer Hill	Local Road	infrastructure condition	raised pavement tip	-33.895271	151.137019	1	1	repair pavement panel	SH39	Secondary	LOW	\$ 200
IC515	Junction Road	Summer Hill	Local Road	infrastructure condition	raised pavement tip	-33.891631	151.129492	1	1	repair pavement panel	SH41	Secondary	LOW	\$ 200
IC516	Prospect Road	Summer Hill	Local Road	infrastructure condition	raised pavement tip	-33.89692	151.132313	1	1	repair pavement panel	SH71	Tertiary	LOW	\$ 200
IC517	Prospect Road	Summer Hill	Local Road	infrastructure condition	raised pavement tip	-33.897331	151.132235	1	1	repair pavement panel	SH72	Tertiary	LOW	\$ 200
IC518	Prospect Road	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898205	151.132133	1	1	re-construct footpath pavement	SH73	Secondary	LOW	\$ 200
IC519	Prospect Road	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898999	151.132006	1	1	re-construct footpath pavement	SH74	Secondary	LOW	\$ 200
IC52	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.902211	151.1292	1	1	re-construct footpath pavement	AF170	Secondary	LOW	\$ 200
IC521	Smith Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.891645	151.135966	1	1	install new utility cover	SH62	Secondary	LOW	\$ 2,000
IC522	Burnow Avenue	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.915047	151.160471	1	1	re-construct footpath pavement	SY2	Secondary	LOW	\$ 200
IC523	Burnow Avenue	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.914656	151.160703	1	1	re-construct footpath pavement	SY1	Secondary	LOW	\$ 200
IC524	George Street	Sydenham	Local Road	infrastructure condition	raised pavement tip	-33.914793	151.161747	1	1	repair pavement panel	SY3	Secondary	LOW	\$ 200
IC525	George Street	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.914539	151.162134	1	1	re-construct footpath pavement	SY1	Secondary	LOW	\$ 200
IC526	Princes Highway	Sydenham	State Road	infrastructure condition	uneven pavement surface	-33.918661	151.169633	1	1	re-construct footpath pavement	SP27	Secondary	LOW	\$ 200
IC527	Princes Highway	Sydenham	State Road	infrastructure condition	uneven pavement surface	-33.919422	151.168835	1	1	re-construct footpath pavement	SP28	Secondary	LOW	\$ 200
IC528	Princes Highway	Sydenham	State Road	infrastructure condition	uneven pavement surface	-33.919445	151.168235	1	1	re-construct footpath pavement	SP28	Secondary	LOW	\$ 200
IC53	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.902698	151.129815	1	1	re-construct footpath pavement	AF164	Secondary	LOW	\$ 200
IC530	Griffiths Street	Tempe	Local Road	infrastructure condition	raised pavement tip	-33.924977	151.156729	1	1	repair pavement panel	TE32	Secondary	LOW	\$ 200
IC531	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.920666	151.16703	1	1	re-construct footpath pavement	TE7	Secondary	LOW	\$ 200
IC532	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.920729	151.166849	1	1	re-construct footpath pavement	TE7	Secondary	LOW	\$ 200
IC533	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.921289	151.164896	1	1	re-construct footpath pavement	TE9	Secondary	LOW	\$ 200
IC535	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.927701	151.167903	1	1	re-construct footpath pavement	TE30	Secondary	LOW	\$ 200
IC54	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.902437	151.129203	1	1	repair pavement panel	AF170	Secondary	LOW	\$ 200
IC55	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.902599	151.129186	1	1	re-construct footpath pavement	AF170	Secondary	LOW	\$ 200
IC56	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.902785	151.129187	1	1	repair pavement panel	AF164	Secondary	LOW	\$ 200
IC57	Alt Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894137	151.123853	1	1	re-construct footpath pavement	AF7	Secondary	LOW	\$ 200
IC58	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.886074	151.175097	1	1	re-construct footpath pavement	AN93	Secondary	LOW	\$ 200
IC59	Armstrong Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.897925	151.125413	1	1	repair pavement panel	AF12	Tertiary	LOW	\$ 200
IC62	Armstrong Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.898283	151.125551	1	1	re-construct footpath pavement	AF13	Tertiary	LOW	\$ 200
IC63	Armstrong Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.899669	151.126994	1	1	re-construct footpath pavement	AF11	Tertiary	LOW	\$ 200
IC64	Armstrong Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.899669	151.126994	1	1	repair pavement panel	AF11	Tertiary	LOW	\$ 200
IC66	Charlotte Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.883483	151.127508	1	1	re-construct footpath pavement	AF36	Tertiary	LOW	\$ 200
IC67	Charlotte Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.883116	151.127265	1	1	re-construct footpath pavement	AF36	Tertiary	LOW	\$ 200
IC68	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.878728	151.128211	1	1	re-construct footpath pavement	AF43	Secondary	LOW	\$ 200
IC69	Church Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.878341	151.129038	1	1	repair pavement panel	AF43	Secondary	LOW	\$ 200
IC7	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.88547	151.17603	1	1	re-construct footpath pavement	AN91	Secondary	LOW	\$ 200
IC70	Church Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.87877	151.124071	1	1	repair pavement panel	AF41	Tertiary	LOW	\$ 200
IC71	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.87707	151.124297	1	1	re-construct footpath pavement	AF43	Secondary	LOW	\$ 200
IC72	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.878658	151.125437	1	1	re-construct footpath pavement	AF43	Secondary	LOW	\$ 200
IC73	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.880921	151.126892	1	1	re-construct footpath pavement	AF45	Tertiary	LOW	\$ 200
IC74	Cassold Street	Ashfield	Local Road	infrastructure condition	raised pavement tip	-33.899517	151.128631	1	1	repair pavement panel	AF48	Tertiary	LOW	\$ 200
IC76	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.888433	151.129426	1	1	re-construct footpath pavement	AF63	Secondary	LOW	\$ 200
IC79	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.888327	151.129404	1	1	re-construct footpath pavement	AF63	Secondary	LOW	\$ 200
IC8	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.885703	151.176569	1	1	re-construct footpath pavement	AN91	Secondary	LOW	\$ 200
IC89	Frederick Street	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.882474	151.171299	1	1	re-construct footpath pavement	AN92	Secondary	LOW	\$ 200
IC9	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.885755	151.17548	1	1	re-construct footpath pavement	AN91	Secondary	LOW	\$ 200
IC90	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.882929	151.12097	1	1	re-construct footpath pavement	AF74	Secondary	LOW	\$ 200
IC91	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.884359	151.120325	1	1	re-construct footpath pavement	AF75	Secondary	LOW	\$ 200
IC93	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.877205	151.128676	1	1	re-construct footpath pavement	AF68	Secondary	LOW	\$ 200
IC95	Milton Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.910161	151.170999	1	1	re-construct footpath pavement	AF115	Secondary	LOW	\$ 200
IC99	Milton Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.909065	151.172585	1	1	re-construct footpath pavement	AF115	Secondary	LOW	\$ 200
MP15	Challis Avenue	Dulwich Hill	Local Road	missing footpath	missing footpath	-33.910957	151.145213	1	1	install new footpath	DF7	Tertiary	LOW	\$ 7,000
MP17	Challis Avenue</													

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
MP33	Frazer Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.869215	151.15265	287	install new footpath	LF43	Tertiary	CNW	\$	57,400
MP35	Myrtle Street	Marrickville	Local Road	missing footpath	missing footpath	-33.915227	151.156789	49	install new footpath	MV146	Tertiary	CNW	\$	9,800
MP38	Premier Street	Marrickville	Local Road	missing footpath	missing footpath	-33.918026	151.148074	20	install new footpath	MV160	Tertiary	CNW	\$	4,000
MP45	Robert Street	Rozelle	Local Road	missing footpath	missing footpath	-33.86538	151.178607	291	install new footpath	RO61	Tertiary	CNW	\$	58,200
MP46	Denison Street	Rozelle	Local Road	missing footpath	missing footpath	-33.869111	151.170122	116	install new footpath	RO28	Tertiary	CNW	\$	23,200
NP12	Booth Street	Balmain	Regional Road	narrow footpath	narrow footpath	-33.866543	151.16189	110	widen footpath	BA14	Secondary	CNW	\$	23,600
NP13	Hym Street	Balmain	Local Road	narrow footpath	narrow footpath	-33.861451	151.160362	236	widen footpath	BA45	Secondary	CNW	\$	47,200
NP15	Buchanan Street	Balmain	Local Road	narrow footpath	narrow footpath	-33.863164	151.160334	165	widen footpath	BA18	Tertiary	CNW	\$	33,000
NP16	Paramatta Road	Croydon	State Road	narrow footpath	narrow footpath	-33.871747	151.123853	38	widen footpath	CR29	Secondary	CNW	\$	7,600
NP17	Paramatta Road	Croydon	State Road	narrow footpath	narrow footpath	-33.873061	151.12589	1	widen footpath	CR31	Secondary	CNW	\$	600
NP18	Piggott Street	Dulwich Hill	Local Road	narrow footpath	narrow footpath	-33.902035	151.143263	7	widen footpath	DH105	Secondary	CNW	\$	1,400
NP2	Gordon Street	Annandale	State Road	narrow footpath	narrow footpath	-33.866536	151.174172	161	investigate shared zone implementation	AN39	Secondary	CNW	\$	15,000
NP20	Wheaton Street	Dulwich Hill	Local Road	narrow footpath	narrow footpath	-33.908459	151.13994	1	widen footpath	DH44	Secondary	CNW	\$	1,400
NP21	Constitution Road	Dulwich Hill	Local Road	narrow footpath	narrow footpath	-33.902529	151.137952	1	widen footpath	DH17	Secondary	CNW	\$	3,000
NP23	Elswick Street	Leichhardt	Local Road	narrow footpath	narrow footpath	-33.886627	151.153008	5	widen footpath	LH53	Secondary	CNW	\$	1,000
NP24	Mackenzie Street	Leichhardt	Local Road	narrow footpath	narrow footpath	-33.883812	151.161297	136	widen footpath	LH60	Secondary	CNW	\$	27,200
NP25	Malyavey Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.870469	151.152025	66	widen footpath	LF11	Secondary	CNW	\$	13,000
NP26	Perry Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.872801	151.155287	1	widen footpath	LF78	Tertiary	CNW	\$	1,600
NP27	Glover Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.871799	151.167355	37	widen footpath	LF51	Secondary	CNW	\$	7,400
NP28	Lilyfield Road	Lilyfield	Regional Road	narrow footpath	narrow footpath	-33.870438	151.170706	22	widen footpath	RC46	Secondary	CNW	\$	4,400
NP29	Balmain Road	Lilyfield	State Road	narrow footpath	narrow footpath	-33.869426	151.162638	174	widen footpath	LF2	Secondary	CNW	\$	34,800
NP3	Victoria Street	Ashfield	Local Road	narrow footpath	narrow footpath	-33.899365	151.126602	304	widen footpath	AF168	Secondary	CNW	\$	60,800
NP30	Grove Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.872636	151.164594	128	widen footpath	LF54	Secondary	CNW	\$	25,600
NP31	Piper Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.875959	151.162517	292	widen footpath	LF93	Secondary	CNW	\$	58,400
NP32	Premier Street	Marrickville	Local Road	narrow footpath	narrow footpath	-33.921151	151.153555	78	widen footpath	MV159	Secondary	CNW	\$	15,600
NP33	Warren Road	Marrickville	Local Road	narrow footpath	narrow footpath	-33.918252	151.154425	4	widen footpath	MV250	Tertiary	CNW	\$	800
NP34	Dymes Street	Marrickville	Local Road	narrow footpath	narrow footpath	-33.913723	151.15532	16	widen footpath	MV20	Secondary	CNW	\$	3,600
NP35	Wardell Road	Marrickville	Regional Road	narrow footpath	narrow footpath	-33.913444	151.13744	89	widen footpath	MV233	Secondary	CNW	\$	13,800
NP36	Bedwin Road	Marrickville	Regional Road	narrow footpath	narrow footpath	-33.908891	151.147679	92	widen footpath	MV18	Secondary	CNW	\$	18,400
NP37	Bedwin Road	Marrickville	Regional Road	narrow footpath	narrow footpath	-33.908878	151.176019	91	widen footpath	MV18	Secondary	CNW	\$	18,200
NP38	Sydney Steel Road	Marrickville	Local Road	narrow footpath	narrow footpath	-33.905140	151.170581	221	widen footpath	MV205	Secondary	CNW	\$	44,200
NP39	Sydney Steel Road	Marrickville	Local Road	narrow footpath	narrow footpath	-33.903935	151.17068	224	widen footpath	MV205	Secondary	CNW	\$	44,800
NP4	Clasoid Street	Ashfield	Local Road	narrow footpath	narrow footpath	-33.895725	151.130002	428	widen footpath	AF50	Secondary	CNW	\$	85,800
NP40	Shirrow Street	Marrickville	Local Road	narrow footpath	narrow footpath	-33.911237	151.167889	12	widen footpath	MV108	Tertiary	CNW	\$	2,400
NP41	Victoria Road	Marrickville	State Road	narrow footpath	narrow footpath	-33.914237	151.156801	34	widen footpath	MV228	Secondary	CNW	\$	6,800
NP42	Liberty Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.895627	151.171336	7	widen footpath	NE43	Secondary	CNW	\$	1,400
NP43	Lennox Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.895197	151.169592	5	widen footpath	NE41	Secondary	CNW	\$	1,000
NP47	Bailey Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.899365	151.172727	207	investigate shared zone implementation	NE63	Secondary	CNW	\$	15,000
NP49	Manning Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.865134	151.166133	211	widen footpath	RO52	Secondary	CNW	\$	42,200
NP5	Prospect Road	Ashfield	Local Road	narrow footpath	narrow footpath	-33.896916	151.132331	222	widen footpath	SH72	Tertiary	CNW	\$	44,400
NP50	Manning Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.865962	151.166025	205	widen footpath	RO52	Secondary	CNW	\$	41,800
NP51	Robert Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.864342	151.168406	108	widen footpath	RO59	Tertiary	CNW	\$	21,200
NP52	Robert Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.865522	151.178037	171	widen footpath	RO61	Tertiary	CNW	\$	34,200
NP53	Robert Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.865642	151.175583	18	widen footpath	RO57	Secondary	CNW	\$	3,600
NP54	Victoria Road	Rozelle	State Road	narrow footpath	narrow footpath	-33.866866	151.175107	44	widen footpath	RO66	Secondary	CNW	\$	8,800
NP55	Denison Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.869537	151.169558	15	widen footpath	RO28	Tertiary	CNW	\$	3,000
NP57	St Peters Street	St Peters	Local Road	narrow footpath	narrow footpath	-33.912305	151.177196	158	widen footpath	SP30	Secondary	CNW	\$	31,600
NP58	St Peters Street	St Peters	Local Road	narrow footpath	narrow footpath	-33.912551	151.177261	158	widen footpath	SP30	Secondary	CNW	\$	31,600
NP59	Henson Street	Summer Hill	Local Road	narrow footpath	narrow footpath	-33.894458	151.13466	471	widen footpath	SH18	Secondary	CNW	\$	95,200
NP60	Nowanra Street	Summer Hill	Local Road	narrow footpath	narrow footpath	-33.893384	151.138813	204	widen footpath	SH52	Secondary	CNW	\$	40,800
NP61	James Street	Summer Hill	Local Road	narrow footpath	narrow footpath	-33.897399	151.135239	127	widen footpath	SH38	Secondary	CNW	\$	25,400
NP62	Elizabeth Street	Summer Hill	Regional Road	narrow footpath	narrow footpath	-33.899179	151.131784	108	widen footpath	AG61	Secondary	CNW	\$	21,600
OB1	Annandale Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886254	151.166705	1	refer to maintenance	AN1	Secondary	CNW	\$	-
OB10	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878171	151.175391	1	notify business/property owner	AN87	Secondary	CNW	\$	-
OB100	Holten Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897375	151.165201	1	notify business/property owner	AF31	Tertiary	CNW	\$	-
OB1000	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.911005	151.161333	1	notify business/property owner	MV212	Secondary	CNW	\$	-
OB1001	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.911551	151.160824	1	notify business/property owner	MV220	Primary	CNW	\$	-
OB1002	Victoria Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914405	151.16836	1	refer to maintenance	MV227	Primary	CNW	\$	-
OB1003	Victoria Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914823	151.157831	1	notify business/property owner	MV209	Secondary	CNW	\$	-
OB1004	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.9078	151.163607	1	refer to maintenance	MV217	Secondary	CNW	\$	-
OB1005	Wardell Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.906886	151.145621	1	notify business/property owner	MV240	Secondary	CNW	\$	-
OB1006	Warren Road	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.914436	151.147653	1	no action	MV244	Secondary	CNW	\$	-
OB1007	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.916583	151.151522	1	refer to maintenance	MV248	Secondary	CNW	\$	-
OB1008	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.917158	151.152546	1	notify business/property owner	MV249	Secondary	CNW	\$	-
OB1009	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.917744	151.153603	1	refer to maintenance	MV241	Tertiary	CNW	\$	-
OB101	Holten Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895712	151.126079	1	notify business/property owner	AF38	Tertiary	CNW	\$	-
OB1011	Albermarle Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.896291	151.173952	1	notify business/property owner	NE1	Secondary	CNW	\$	-
OB1012	Albermarle Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.896004	151.174488	1	refer to maintenance	NE1	Secondary	CNW	\$	-
OB1013	Albermarle Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895962	151.174871	1	no action	NE1	Secondary	CNW	\$	-
OB1014	Albermarle Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89591	151.175279	1	refer to maintenance	NE1	Secondary	CNW	\$	-
OB1014	Albermarle Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895859	151.175375	1	refer to maintenance	NE4	Secondary	CNW	\$	-
OB1015	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation - property	-33.903236	151.177883	1	notify business/property owner	NE10	Primary	CNW	\$	-
OB1016	Alice Street	Newtown	Regional Road	obstruction	bus shelter narrows footpath	-33.903465	151.177846	1	relocate and remove bus shelter	NE10	Primary	CNW	\$	5,000
OB1017	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.90442	151.175209	1	notify business/property owner	NE7	Secondary	CNW	\$	-
OB1018	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.904716	151.173974	1	notify business/property owner	NE7	Secondary	CNW	\$	-
OB1019	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.904719	151.173896	1	notify business/property owner	NE8	Secondary	CNW	\$	-
OB102	Holten Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893827	151.152159	1	notify business/property owner	NE8	Secondary	CNW	\$	-
OB1020	Alice Street	Newtown	Regional Road	obstruction	concrete pillar narrows footpath	-33.904731	151.173484	1	no action	NE6	Secondary	CNW	\$	-
OB1021	Bailey Street	Newtown	Local Road	obstruction	bins narrows footpath	-33.899605	151.173732	1	no action	NE9	Secondary	CNW	\$	-
OB1022	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897661	151.176334	1	no action	NE15	Primary	CNW	\$	-
OB1023	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897584	151.177674	1	no action	NE15	Primary	CNW	\$	-
OB1024	Bedford Street	Newtown	Local Road	obstruction	concrete footing narrows footpath	-33.897602	151.177553	1	install contrasting threshold	NE15	Primary	CNW	\$	5,000
OB1025	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897553	151.176771	1	no action	NE20	Secondary	CNW	\$	-
OB1026	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897442	151.176184	1	no action	NE20	Secondary	CNW	\$	-
OB1027	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897398	151.175939	1	no action	NE20	Secondary	CNW	\$	-
OB1028	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897216	151.17547	1	no action	NE19	Secondary	CNW	\$	-
OB1029	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897179	151.175312	1	no action	NE19	Secondary	CNW	\$	-
OB103	Liverpool Road	Ashfield	State Road	obstruction	double pole signpost narrows footpath	-33.899098	151.131028	1	review and relocate double pole signpost	AF98	Primary	CNW	\$	500
OB1030	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.89712	151.175174	1	no action	NE19	Secondary	CNW	\$	-
OB1031	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.896573	151.174071	1	no action	NE18	Secondary	CNW	\$	-
OB1032	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.896524	151.173971	1	no action	NE18	Secondary	CNW	\$	-
OB1033	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.89659	151.173171	1	no action	NE17	Secondary	CNW	\$	-
OB1034	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-								

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB1037	Bedford Street	Newtown	Local Road	obstruction	power pole narrows footpath	-33.895299	151.17176	1		no action	NE16	Secondary	CW	\$	-
OB1038	Edgeware Road	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.904263	151.17234	1		notify business/property owner	NE23	Primary	CW	\$	-
OB1039	Edgeware Road	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.906901	151.174292	1		notify business/property owner	NE32	Primary	CW	\$	-
OB104	Liverpool Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.887616	151.121471	1		notify business/property owner	AF106	Primary	CW	\$	-
OB1040	Edgeware Road	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.907411	151.174611	1		notify business/property owner	NE21	Primary	CW	\$	-
OB1041	Edgeware Road	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.90616	151.173749	1		notify business/property owner	NE31	Primary	CW	\$	-
OB1042	Enmore Road	Newtown	State Road	obstruction	store stand narrows footpath	-33.888111	151.177685	1		notify business/property owner	NE34	Primary	CW	\$	-
OB1043	King Street	Newtown	Local Road	obstruction	storefront narrows footpath - property	-33.904764	151.180484	1		notify business/property owner	NE56	Primary	CW	\$	-
OB1044	Lennox Street	Newtown	Local Road	obstruction	power pole narrows footpath	-33.895206	151.18091	1		no action	NE41	Secondary	CW	\$	-
OB1045	Lennox Street	Newtown	Local Road	obstruction	empty pit narrows footpath	-33.895191	151.180457	1		install new footpath	NE41	Secondary	CW	\$	200
OB1046	Lennox Street	Newtown	Local Road	obstruction	overhanging vegetation - property	-33.895758	151.176799	1		notify business/property owner	NE42	Secondary	CW	\$	-
OB1047	Lord Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.907477	151.178559	1		no action	NE28	Primary	CW	\$	-
OB1048	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.898797	151.176582	1		notify business/property owner	NE58	Secondary	CW	\$	-
OB1049	Station Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.898909	151.176625	1		no action	NE58	Secondary	CW	\$	-
OB105	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation	-33.894628	151.11885	1		refer to maintenance	AF141	Secondary	CW	\$	-
OB1050	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899305	151.176773	1		refer to maintenance	NE58	Secondary	CW	\$	-
OB1051	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899438	151.176874	1		refer to maintenance	NE59	Secondary	CW	\$	-
OB1052	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899583	151.176915	1		refer to maintenance	NE59	Secondary	CW	\$	-
OB1053	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899723	151.176936	1		refer to maintenance	NE59	Secondary	CW	\$	-
OB1054	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.899714	151.176986	1		notify business/property owner	NE59	Secondary	CW	\$	-
OB1055	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899792	151.177037	1		refer to maintenance	NE59	Secondary	CW	\$	-
OB1056	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.899626	151.176819	1		notify business/property owner	NE59	Secondary	CW	\$	-
OB1057	Wells Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.905451	151.179712	1		no action	NE60	Secondary	CW	\$	-
OB1058	Wells Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.905764	151.178773	1		no action	NE65	Secondary	CW	\$	-
OB1059	Wells Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.906307	151.177031	1		no action	NE63	Secondary	CW	\$	-
OB106	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.894117	151.117845	1		notify business/property owner	AF140	Secondary	CW	\$	-
OB1060	Wells Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.9067	151.17575	1		notify business/property owner	NE62	Secondary	CW	\$	-
OB1061	Wells Street	Newtown	Local Road	obstruction	signpost narrows footpath	-33.906626	151.176842	1		relocate signpost	NE61	Secondary	CW	\$	300
OB1062	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892422	151.15684	1		notify business/property owner	PE11	Secondary	CW	\$	-
OB1063	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892534	151.152327	1		refer to maintenance	PE7	Tertiary	CW	\$	-
OB1064	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89256	151.152496	1		refer to maintenance	PE7	Tertiary	CW	\$	-
OB1065	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892694	151.15202	1		refer to maintenance	PE7	Tertiary	CW	\$	-
OB1066	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892889	151.151465	1		notify business/property owner	PE7	Tertiary	CW	\$	-
OB1067	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.893042	151.150965	1		refer to maintenance	PE5	Secondary	CW	\$	-
OB1068	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath	-33.900356	151.153173	1		notify business/property owner	PE26	Secondary	CW	\$	-
OB1069	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.900082	151.153422	1		notify business/property owner	PE26	Secondary	CW	\$	-
OB107	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.894484	151.118235	1		notify business/property owner	AF141	Secondary	CW	\$	-
OB1070	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.897068	151.153801	1		notify business/property owner	PE24	Secondary	CW	\$	-
OB1071	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.898348	151.153514	1		notify business/property owner	PE24	Secondary	CW	\$	-
OB1072	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.899184	151.153495	1		notify business/property owner	PE25	Primary	CW	\$	-
OB1073	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.89994	151.153574	1		notify business/property owner	PE26	Secondary	CW	\$	-
OB1074	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation - property	-33.898741	151.153588	1		notify business/property owner	PE26	Secondary	CW	\$	-
OB1075	New Canterbury Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.899524	151.155314	1		notify business/property owner	PE30	Primary	CW	\$	-
OB1076	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890254	151.154289	1		notify business/property owner	PE41	Primary	CW	\$	-
OB1077	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890345	151.154438	1		notify business/property owner	PE41	Primary	CW	\$	-
OB1078	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation - property	-33.89024	151.154447	1		notify business/property owner	PE41	Primary	CW	\$	-
OB1079	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.898662	151.154448	1		notify business/property owner	PE41	Primary	CW	\$	-
OB108	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.894762	151.118842	1		notify business/property owner	AF141	Secondary	CW	\$	-
OB1080	Terminus Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89415	151.152036	1		notify business/property owner	PE48	Primary	CW	\$	-
OB1081	Terminus Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893439	151.154922	1		notify business/property owner	PE59	Primary	CW	\$	-
OB1082	Terminus Street	Petersham	Local Road	obstruction	tree narrows footpath	-33.893527	151.156148	1		no action	PE58	Primary	CW	\$	-
OB1083	Terminus Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891493	151.156735	1		notify business/property owner	PE64	Secondary	CW	\$	-
OB1084	Triffalgat Street	Petersham	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.894838	151.15185	1		notify business/property owner	PE64	Secondary	CW	\$	-
OB1085	West Street	Petersham	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.893343	151.150341	1		notify business/property owner	PE65	Primary	CW	\$	-
OB1086	York Crescent	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893485	151.150018	1		notify business/property owner	PE21	Secondary	CW	\$	-
OB1087	York Crescent	Petersham	Local Road	obstruction	overhanging vegetation	-33.893735	151.150018	1		refer to maintenance	PE21	Secondary	CW	\$	-
OB1088	York Crescent	Petersham	Local Road	obstruction	damaged fence narrows footpath	-33.893824	151.158753	1		notify property owner	SM15	Secondary	CW	\$	-
OB1089	Anzac Bridge	Rozelle	State Road	obstruction	light post narrows footpath	-33.888003	151.182286	1		relocate light post	RO8	Secondary	CW	\$	10,000
OB109	Milton Street	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.894801	151.118991	1		no action	AF141	Secondary	CW	\$	-
OB1090	Anzac Bridge	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.888175	151.181154	1		refer to maintenance	RO7	Secondary	CW	\$	-
OB1091	Darling Street	Rozelle	Regional Road	obstruction	bus shelter narrows footpath	-33.863341	151.170331	1		relocate or remove bus shelter	RO24	Primary	CW	\$	5,000
OB1092	Darling Street	Rozelle	Regional Road	obstruction	storefront narrows footpath - property	-33.86272	151.170818	1		notify business/property owner	RO18	Primary	CW	\$	-
OB1093	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869165	151.169108	1		notify business/property owner	RO31	Tertiary	CW	\$	-
OB1094	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869115	151.169117	1		notify business/property owner	RO31	Tertiary	CW	\$	-
OB1095	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.867834	151.168842	1		notify business/property owner	RO30	Secondary	CW	\$	-
OB1096	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.867264	151.168548	1		notify business/property owner	RO33	Secondary	CW	\$	-
OB1097	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.866692	151.168222	1		notify business/property owner	RO29	Secondary	CW	\$	-
OB1098	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation - property	-33.866295	151.168088	1		notify business/property owner	RO29	Secondary	CW	\$	-
OB1099	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87025	151.170424	1		notify business/property owner	RO28	Tertiary	CW	\$	-
OB11	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883984	151.172807	1		notify business/property owner	AN71	Primary	CW	\$	-
OB110	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.894973	151.119202	1		notify business/property owner	AF142	Secondary	CW	\$	-
OB1100	Denison Street	Rozelle	Local Road	obstruction	vehicle narrows footpath	-33.869566	151.169575	6		install new wheel stops	RO28	Tertiary	CW	\$	9,000
OB1101	Denison Street	Rozelle	Local Road	obstruction	vehicle narrows footpath	-33.869551	151.169736	2		install new wheel stops	RO28	Tertiary	CW	\$	33,000
OB1102	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.865705	151.171801	1		refer to maintenance	RO36	Primary	CW	\$	-
OB1103	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.865882	151.171464	1		notify business/property owner	RO36	Primary	CW	\$	-
OB1104	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.86663	151.169957	1		notify business/property owner	RO35	Secondary	CW	\$	-
OB1105	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.867314	151.169144	1		notify business/property owner	RO35	Secondary	CW	\$	-
OB1106	Evans Street	Rozelle	Local Road	obstruction	tree narrows footpath	-33.867269	151.169179	1		no action	RO35	Secondary	CW	\$	-
OB1107	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.866936	151.169518	1		notify business/property owner	RO35	Secondary	CW	\$	-
OB1108	Evans Street	Rozelle	Local Road	obstruction	tree narrows footpath	-33.866971	151.169588	1		no action	RO35	Secondary	CW	\$	-
OB1109	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.865704	151.171534	1		refer to maintenance	RO36	Primary	CW	\$	-
OB111	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.890877	151.12653	1		notify business/property owner	AF121	Primary	CW	\$	-
OB1110	Gordon Street	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868427	151.172835	1		notify business/property owner	RO40	Secondary	CW	\$	-
OB1111	James Craig Road	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.87032	151.175247	1		no action	RO44	Secondary	CW	\$	-
OB1112	James Craig Road	Rozelle	Local Road	obstruction	vehicles narrows footpath	-33.870094	151.175291	1		no action	RO44	Secondary	CW	\$	-
OB1113	Lyfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868614	151.172596	1		notify business/property owner	RO41	Secondary	CW	\$	-
OB1114	Lyfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868635	151.175438	1		notify business/property owner	RO41	Secondary	CW	\$	-
OB1115	Lyfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868328	151.175364	1		notify business/property owner	RO44	Secondary	CW	\$	-
OB1116	Lyfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.868535	151.174467	1		refer to maintenance	RO42	Secondary	CW	\$	-
OB1117	Lyfield Road	Rozelle	Regional Road	obstruction											

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB1122	Manning Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.86267	151.164305	1		refer to maintenance	R050	Tertiary	LOW	\$	-
OB1123	Manning Street	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.86492	151.169975	1		no action	R049	Secondary	LOW	\$	-
OB1124	Manning Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.86504	151.166525	1		notify business/property owner	R052	Secondary	LOW	\$	-
OB1125	Mullens Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.86304	151.176465	1		notify business/property owner	R053	Secondary	LOW	\$	-
OB1126	Mullens Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.865494	151.177023	1		notify business/property owner	R055	Tertiary	LOW	\$	-
OB1127	Mullens Street	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.865619	151.176980	1		notify business/property owner	R056	Tertiary	LOW	\$	-
OB1128	Robert Street	Rozelle	Regional Road	obstruction	power pole narrows footpath	-33.86526	151.176553	1		no action	R057	Secondary	LOW	\$	-
OB1129	Robert Street	Rozelle	Local Road	obstruction	vehicles and signpost narrows footpath	-33.865619	151.17796	1		relocate signpost	R061	Tertiary	LOW	\$	300
OB113	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.890113	151.124261	1		notify business/property owner	AF120	Primary	LOW	\$	-
OB1130	Robert Street	Rozelle	Local Road	obstruction	damaged signpost narrows footpath	-33.865815	151.17732	1		install new signpost	R058	Tertiary	LOW	\$	250
OB1131	Robert Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.86408	151.1804	1		refer to maintenance	R059	Tertiary	LOW	\$	-
OB1132	Robert Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.864136	151.180326	1		refer to maintenance	R059	Tertiary	LOW	\$	-
OB1133	Robert Street	Rozelle	Local Road	obstruction	vehicle narrows footpath	-33.865011	151.178991	1		no action	R061	Tertiary	LOW	\$	-
OB1134	Robert Street	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.865306	151.178573	1		no action	R061	Tertiary	LOW	\$	-
OB1135	Robert Street	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.865493	151.177902	1		no action	R058	Tertiary	LOW	\$	-
OB1136	Terry Street	Rozelle	Local Road	obstruction	concrete pillar narrows footpath	-33.86045	151.168899	1		no action	R068	Secondary	LOW	\$	-
OB1137	Terry Street	Rozelle	Local Road	obstruction	electricity box narrows footpath	-33.860716	151.169340	1		no action	R068	Secondary	LOW	\$	-
OB1138	The Crescent	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.869623	151.175255	1		refer to maintenance	R044	Secondary	LOW	\$	-
OB1139	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.860064	151.164791	1		refer to maintenance	R084	Secondary	LOW	\$	-
OB114	Norton Street	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.869634	151.123812	1		no action	AF120	Primary	LOW	\$	-
OB1140	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.869009	151.176207	1		refer to maintenance	R074	Secondary	LOW	\$	-
OB1141	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.866175	151.173975	1		refer to maintenance	R073	Secondary	LOW	\$	-
OB1142	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.86713	151.175253	1		relocate signpost	R070	Secondary	LOW	\$	300
OB1143	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.869065	151.174565	1		relocate signpost	R057	Secondary	LOW	\$	300
OB1144	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.867299	151.175741	1		relocate signpost	R070	Secondary	LOW	\$	300
OB1145	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.86736	151.175753	1		relocate signpost	R070	Secondary	LOW	\$	300
OB1146	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.867444	151.175894	1		refer to maintenance	R070	Secondary	LOW	\$	-
OB1147	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.867573	151.176024	1		notify business/property owner	R070	Secondary	LOW	\$	-
OB1148	Victoria Road	Rozelle	State Road	obstruction	light post narrows footpath	-33.867585	151.176033	1		relocate light post	R070	Secondary	LOW	\$	10,000
OB1149	Campbell Street	St Peters	Regional Road	obstruction	vehicle narrows footpath	-33.912441	151.17639	1		no action	SP2	Secondary	LOW	\$	-
OB115	Norton Street	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.869745	151.123137	1		no action	AF120	Primary	LOW	\$	-
OB1150	Church Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912216	151.178483	1		refer to maintenance	SP6	Secondary	LOW	\$	-
OB1151	Church Street	St Peters	Local Road	obstruction	electricity box narrows footpath	-33.912271	151.178413	1		no action	SP6	Secondary	LOW	\$	-
OB1152	Church Street	St Peters	Local Road	obstruction	power pole narrows footpath	-33.912421	151.178455	1		no action	SP6	Secondary	LOW	\$	-
OB1153	Church Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.912441	151.17839	1		notify business/property owner	SP6	Secondary	LOW	\$	-
OB1154	Church Street	St Peters	Local Road	obstruction	power pole narrows footpath	-33.912685	151.177889	1		no action	SP7	Secondary	LOW	\$	-
OB1155	Church Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913039	151.177724	1		notify business/property owner	SP7	Secondary	LOW	\$	-
OB1156	Church Street	St Peters	Local Road	obstruction	power pole narrows footpath	-33.913116	151.177736	1		no action	SP7	Secondary	LOW	\$	-
OB1157	Church Street	St Peters	Local Road	obstruction	electricity box narrows footpath	-33.913377	151.177539	1		no action	SP7	Secondary	LOW	\$	-
OB1158	Edith Street	St Peters	Local Road	obstruction	vehicle narrows footpath	-33.912538	151.173465	1		no action	SP35	Tertiary	LOW	\$	-
OB1159	Edith Street	St Peters	Local Road	obstruction	bar narrows footpath	-33.912603	151.173622	1		no action	SP35	Tertiary	LOW	\$	-
OB116	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.898442	151.12321	1		notify business/property owner	AF119	Primary	LOW	\$	-
OB1160	Edith Street	St Peters	Local Road	obstruction	overhanging vegetation - property	-33.914377	151.175295	1		notify business/property owner	SP21	Primary	LOW	\$	-
OB1161	Edith Street	St Peters	Local Road	obstruction	tree narrows footpath	-33.914657	151.175568	1		no action	SP21	Primary	LOW	\$	-
OB1162	Edith Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914665	151.175558	1		notify business/property owner	SP21	Primary	LOW	\$	-
OB1163	King Street	St Peters	State Road	obstruction	signpost narrows footpath	-33.907704	151.181318	1		relocate signpost	SP11	Primary	LOW	\$	300
OB1164	Princes Highway	St Peters	State Road	obstruction	overhanging vegetation narrows footpath	-33.917724	151.171543	1		refer to maintenance	SP8	Secondary	LOW	\$	-
OB1165	Princes Highway	St Peters	State Road	obstruction	double pole signpost narrows footpath	-33.914468	151.177285	1		review and relocate double pole signpost	SP18	Primary	LOW	\$	500
OB1166	Princes Highway	St Peters	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.917323	151.178012	1		notify business/property owner	SP18	Primary	LOW	\$	-
OB1167	Princes Highway	St Peters	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.911839	151.178742	1		notify business/property owner	SP15	Secondary	LOW	\$	-
OB1168	St Peters Street	St Peters	Local Road	obstruction	trees narrows footpath	-33.911931	151.177513	1		no action	SP31	Primary	LOW	\$	-
OB1169	St Peters Street	St Peters	Local Road	obstruction	overhanging vegetation - property	-33.912075	151.177491	1		notify business/property owner	SP31	Primary	LOW	\$	-
OB117	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.898477	151.12283	1		notify business/property owner	AF119	Primary	LOW	\$	-
OB1170	St Peters Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912302	151.177289	1		refer to maintenance	SP30	Secondary	LOW	\$	-
OB1171	St Peters Street	St Peters	Local Road	obstruction	overhanging vegetation - property	-33.914575	151.177664	1		notify business/property owner	SP30	Secondary	LOW	\$	-
OB1172	St Peters Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912768	151.17695	1		refer to maintenance	SP30	Secondary	LOW	\$	-
OB1173	Unwins Bridge Road	St Peters	Regional Road	obstruction	overhanging vegetation - property	-33.910458	151.175154	1		notify business/property owner	SP32	Secondary	LOW	\$	-
OB1174	Unwins Bridge Road	St Peters	Regional Road	obstruction	bins narrows footpath	-33.910466	151.175178	1		no action	SP32	Secondary	LOW	\$	-
OB1175	Aubrey Street	Stammore	Local Road	obstruction	overgrown vegetation	-33.895387	151.15147	1		refer to maintenance	SM14	Primary	LOW	\$	-
OB1176	Perceval Road	Stammore	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890427	151.165292	1		notify business/property owner	SM29	Primary	LOW	\$	-
OB1177	Carlton Crescent	Summer Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.89789	151.131668	1		notify business/property owner	SH8	Secondary	LOW	\$	-
OB1178	Carlton Crescent	Summer Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.89866	151.13269	1		notify business/property owner	SH8	Secondary	LOW	\$	-
OB1179	Carlton Crescent	Summer Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.890194	151.137799	1		notify business/property owner	SH14	Primary	LOW	\$	-
OB118	Norton Street	Ashfield	Regional Road	obstruction	signpost narrows footpath	-33.890277	151.124681	1		relocate signpost	AF117	Primary	LOW	\$	300
OB1180	Cissoid Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89585	151.132162	1		notify business/property owner	AF46	Tertiary	LOW	\$	-
OB1181	Cissoid Street	Summer Hill	Local Road	obstruction	signpost narrows footpath	-33.895881	151.132265	1		relocate signpost	AF46	Tertiary	LOW	\$	-
OB1182	Grosvener Crescent	Summer Hill	Local Road	obstruction	signpost narrows footpath	-33.890614	151.140383	1		relocate signpost	SH22	Secondary	LOW	\$	300
OB1183	Grosvener Crescent	Summer Hill	Local Road	obstruction	signpost narrows footpath	-33.890958	151.138438	1		relocate signpost	SH20	Primary	LOW	\$	300
OB1184	Grosvener Crescent	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.898997	151.136595	1		refer to maintenance	SH20	Primary	LOW	\$	-
OB1185	Grosvener Crescent	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.898440	151.134094	1		notify business/property owner	SH20	Primary	LOW	\$	-
OB1186	Hardie Avenue	Summer Hill	Local Road	obstruction	signpost narrows footpath	-33.891454	151.137235	1		relocate signpost	SH34	Primary	LOW	\$	300
OB1187	Henson Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89641	151.134536	1		notify business/property owner	SH35	Secondary	LOW	\$	-
OB1188	Henson Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.896975	151.134589	1		refer to maintenance	SH35	Secondary	LOW	\$	-
OB1189	Herbert Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.896396	151.134414	1		refer to maintenance	SH37	Secondary	LOW	\$	-
OB119	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.891536	151.131496	1		notify business/property owner	AF118	Primary	LOW	\$	-
OB1190	Herbert Street	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.896362	151.133802	1		notify business/property owner	SH37	Secondary	LOW	\$	-
OB1191	Herbert Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89633	151.133212	1		refer to maintenance	SH37	Secondary	LOW	\$	-
OB1192	Herbert Street	Summer Hill	Local Road	obstruction	tree narrows footpath	-33.896316	151.13286	1		no action	SH37	Secondary	LOW	\$	-
OB1193	James Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897406	151.135959	1		notify business/property owner	SH38	Secondary	LOW	\$	-
OB1194	James Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897379	151.134777	1		refer to maintenance	SH38	Secondary	LOW	\$	-
OB1195	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895019	151.133776	1		notify business/property owner	SH41	Secondary	LOW	\$	-
OB1196	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895033	151.134017	1		notify business/property owner	SH41	Secondary	LOW	\$	-
OB1197	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895404	151.136291	1		refer to maintenance	SH44	Primary	LOW	\$	-
OB1198	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895484	151.136097	1		notify business/property owner	SH44	Primary	LOW	\$	-
OB1199	Junction Road	Summer Hill	Local Road	obstruction	concrete pillar narrows footpath	-33.895484	151.137717	1		no action	SH44	Primary	LOW	\$	-
OB12	Bignell Lane	Annandale	Local Road	obstruction	vehicles narrows footpath	-33.895816	151.176276	1		no action	AN19	Secondary	LOW	\$	-
OB120	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.904589	151.138513	1		notify business/property owner	AF130	Primary	LOW	\$	-
OB1200	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895394	151.136947	1		refer to maintenance	SH39	Secondary	LOW	\$	-
OB1201	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895162	151.134446	1		notify business/property owner	SH41	Secondary	LOW	\$	-
OB1202	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895072	151.132938	1		notify business/property owner	SH40	Secondary	LOW	\$	-

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB1208	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.895636	151.138407	1		notify business/property owner	SH56	Primary	LOW	\$	-
OB1209	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation - property	-33.895307	151.132899	1		notify business/property owner	SH61	Secondary	LOW	\$	-
OB1210	Old Canterbury Road	Ashfield	State Road	obstruction	overhanging vegetation	-33.903103	151.128889	1		refer to maintenance	AF129	Primary	LOW	\$	-
OB1210	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation - property	-33.88725	151.133994	1		notify business/property owner	SH60	Tertiary	LOW	\$	-
OB1211	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath	-33.88613	151.134177	1		refer to maintenance	SH60	Tertiary	LOW	\$	-
OB1212	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation	-33.8981	151.134903	1		refer to maintenance	SH59	Tertiary	LOW	\$	-
OB1213	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.897786	151.135339	1		notify business/property owner	SH59	Tertiary	LOW	\$	-
OB1214	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891528	151.132467	1		notify business/property owner	SH65	Secondary	LOW	\$	-
OB1215	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.891034	151.132349	1		notify business/property owner	SH65	Secondary	LOW	\$	-
OB1216	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892004	151.132327	1		notify business/property owner	SH64	Secondary	LOW	\$	-
OB1217	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890225	151.13239	1		notify business/property owner	SH64	Secondary	LOW	\$	-
OB1218	Prospect Road	Summer Hill	Local Road	obstruction	double pole signpost narrows footpath	-33.89578	151.13235	1		review and relocate double pole signpost	SH70	Secondary	LOW	\$	500
OB1219	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.896962	151.132344	1		notify business/property owner	SH70	Secondary	LOW	\$	-
OB122	Orpington Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.885536	151.11952	1		notify business/property owner	AF136	Secondary	LOW	\$	-
OB1220	Prospect Road	Summer Hill	Local Road	obstruction	double pole signpost narrows footpath	-33.894341	151.132353	1		review and relocate double pole signpost	SH69	Secondary	LOW	\$	500
OB1221	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892446	151.132176	1		notify business/property owner	SH66	Secondary	LOW	\$	-
OB1222	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893074	151.132456	1		notify business/property owner	SH67	Secondary	LOW	\$	-
OB1223	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895082	151.132458	1		notify business/property owner	SH70	Secondary	LOW	\$	-
OB1224	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.895917	151.132485	1		notify business/property owner	SH71	Tertiary	LOW	\$	-
OB1225	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89746	151.1323	1		notify business/property owner	SH72	Tertiary	LOW	\$	-
OB1226	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.896394	151.132324	1		notify business/property owner	SH71	Tertiary	LOW	\$	-
OB1227	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.898381	151.132188	1		refer to maintenance	SH73	Secondary	LOW	\$	-
OB1228	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.900752	151.131985	1		refer to maintenance	AF128	Primary	LOW	\$	-
OB1229	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.892913	151.141463	1		notify business/property owner	SH88	Secondary	LOW	\$	-
OB123	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.887778	151.128204	1		notify business/property owner	AF62	Primary	LOW	\$	-
OB1230	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892567	151.143629	1		refer to maintenance	SH89	Secondary	LOW	\$	-
OB1231	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89275	151.143383	1		refer to maintenance	SH88	Secondary	LOW	\$	-
OB1232	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892687	151.141399	1		notify business/property owner	SH88	Secondary	LOW	\$	-
OB1233	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892655	151.141207	1		refer to maintenance	SH88	Secondary	LOW	\$	-
OB1234	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892655	151.139973	1		notify business/property owner	SH87	Secondary	LOW	\$	-
OB1235	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892628	151.139823	1		notify business/property owner	SH86	Secondary	LOW	\$	-
OB1236	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891626	151.135691	1		notify business/property owner	SH82	Secondary	LOW	\$	-
OB1237	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891682	151.133357	1		notify business/property owner	SH80	Secondary	LOW	\$	-
OB1238	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.891717	151.133095	1		refer to maintenance	SH80	Secondary	LOW	\$	-
OB1239	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.891658	151.132517	1		notify business/property owner	SH80	Secondary	LOW	\$	-
OB124	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.884865	151.11944	1		notify business/property owner	AF142	Secondary	LOW	\$	-
OB1240	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.891625	151.132896	1		refer to maintenance	SH80	Secondary	LOW	\$	-
OB1241	George Street	Sydenham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914028	151.137336	1		refer to maintenance	SH80	Secondary	LOW	\$	-
OB1242	George Street	Sydenham	Local Road	obstruction	overhanging vegetation	-33.915137	151.167812	1		refer to maintenance	SV3	Secondary	LOW	\$	-
OB1243	George Street	Sydenham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.915055	151.1677	1		notify business/property owner	SV3	Secondary	LOW	\$	-
OB1244	George Street	Sydenham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914663	151.167527	1		notify business/property owner	SV3	Secondary	LOW	\$	-
OB1245	Rayway Road	Sydenham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.917987	151.167852	1		notify business/property owner	SV3	Primary	LOW	\$	-
OB1246	Rayway Road	Sydenham	State Road	obstruction	traffic post narrows footpath	-33.917816	151.167888	1		widen footpath	SV8	Primary	LOW	\$	200
OB1247	Griffiths Street	Tempe	Local Road	obstruction	signpost narrows footpath	-33.925114	151.156541	1		relocate signpost	TE32	Secondary	LOW	\$	300
OB1248	Griffiths Street	Tempe	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.924809	151.156734	1		notify business/property owner	TE31	Secondary	LOW	\$	-
OB1249	Griffiths Street	Tempe	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.925297	151.156471	1		notify business/property owner	TE32	Secondary	LOW	\$	-
OB125	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894981	151.119999	1		notify business/property owner	AF142	Secondary	LOW	\$	-
OB1250	Griffiths Street	Tempe	Local Road	obstruction	tree narrows footpath	-33.925553	151.15624	1		no action	TE32	Secondary	LOW	\$	-
OB1251	Griffiths Street	Tempe	Local Road	obstruction	tree narrows footpath	-33.925648	151.156208	1		no action	TE32	Secondary	LOW	\$	-
OB1252	Princes Highway	Tempe	State Road	obstruction	power pole narrows footpath	-33.920611	151.167822	1		no action	SP29	Secondary	LOW	\$	-
OB1253	Princes Highway	Tempe	State Road	obstruction	overhanging vegetation narrows footpath	-33.927547	151.158559	1		refer to maintenance	TE30	Secondary	LOW	\$	-
OB1254	Princes Highway	Tempe	State Road	obstruction	power pole narrows footpath	-33.927121	151.158336	1		no action	TE34	Primary	LOW	\$	-
OB1255	Richardson Crescent	Tempe	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.922736	151.156358	1		refer to maintenance	MV175	Secondary	LOW	\$	-
OB1256	Richardson Crescent	Tempe	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.922736	151.156468	1		refer to maintenance	MV175	Secondary	LOW	\$	-
OB1257	Union Street	Tempe	Local Road	obstruction	vehicles narrows footpath	-33.922166	151.161165	1		no action	TE18	Secondary	LOW	\$	-
OB1258	Urwins Bridge Road	Tempe	Regional Road	obstruction	double pole signpost narrows footpath	-33.921341	151.155586	1		review and relocate double pole signpost	TE22	Secondary	LOW	\$	500
OB1259	Urwins Bridge Road	Tempe	Regional Road	obstruction	double pole signpost narrows footpath	-33.919024	151.162882	1		review and relocate double pole signpost	TE27	Secondary	LOW	\$	500
OB126	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895137	151.122247	1		notify business/property owner	AF139	Secondary	LOW	\$	-
OB1260	View Street	Tempe	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.92869	151.15839	1		notify business/property owner	TE34	Primary	LOW	\$	-
OB1261	View Street	Tempe	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.926598	151.158006	1		notify business/property owner	TE34	Primary	LOW	\$	-
OB127	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895134	151.122195	1		notify business/property owner	AF139	Secondary	LOW	\$	-
OB128	Palace Street	Ashfield	Local Road	obstruction	bench narrows footpath	-33.895169	151.122516	1		relocate or remove bench	AF139	Secondary	LOW	\$	400
OB129	Palace Street	Ashfield	Local Road	obstruction	bus stop pole narrows footpath	-33.895146	151.122592	1		relocate bus stop pole	AF139	Secondary	LOW	\$	400
OB13	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.8831	151.173334	1		notify business/property owner	AN72	Primary	LOW	\$	-
OB130	Palace Street	Ashfield	Local Road	obstruction	power pole narrows footpath	-33.895133	151.122703	1		no action	AF139	Secondary	LOW	\$	-
OB131	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.895129	151.12382	1		notify business/property owner	AF144	Secondary	LOW	\$	-
OB132	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895026	151.124001	1		notify business/property owner	AF144	Secondary	LOW	\$	-
OB133	Palace Street	Ashfield	Local Road	obstruction	signpost narrows footpath	-33.894922	151.123098	1		relocate signpost	AF139	Secondary	LOW	\$	300
OB134	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894448	151.120891	1		notify business/property owner	AF143	Secondary	LOW	\$	-
OB135	Paramatta Road	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87905	151.130693	1		notify business/property owner	SH68	Secondary	LOW	\$	-
OB136	Queen Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892166	151.127958	1		notify business/property owner	AF149	Secondary	LOW	\$	-
OB137	Queen Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.89144	151.127822	1		notify business/property owner	AF154	Secondary	LOW	\$	-
OB138	Queen Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893307	151.127734	1		notify business/property owner	AF153	Secondary	LOW	\$	-
OB139	Thomas Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.88709	151.120086	1		notify business/property owner	AF156	Secondary	LOW	\$	-
OB14	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.883419	151.173205	1		notify business/property owner	AN72	Primary	LOW	\$	-
OB140	Thomas Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.887152	151.120132	1		notify business/property owner	AF156	Secondary	LOW	\$	-
OB141	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892441	151.130109	1		notify business/property owner	AF162	Secondary	LOW	\$	-
OB142	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895342	151.129945	1		refer to maintenance	AF159	Secondary	LOW	\$	-
OB143	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89545	151.129935	1		refer to maintenance	AF159	Secondary	LOW	\$	-
OB144	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89545	151.129935	1		refer to maintenance	AF159	Secondary	LOW	\$	-
OB145	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894504	151.129805	1		notify business/property owner	AF163	Secondary	LOW	\$	-
OB146	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893403	151.129939	1		notify business/property owner	AF163	Secondary	LOW	\$	-
OB147	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893206	151.129898	1		notify business/property owner	AF162	Secondary	LOW	\$	-
OB148	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892735	151.129631	1		notify business/property owner	AF162	Secondary	LOW	\$	-
OB149	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.897991	151.129577	1		notify business/property owner	AF166	Secondary	LOW	\$	-
OB15	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883878	151.173057	1		notify business/property owner	AN71	Primary	LOW	\$	-
OB150	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.899187	151.129427	1		notify business/property owner	AF168	Secondary	LOW	\$	-
OB151	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.901045	151.129351	1		notify business/property owner	AF169	Secondary	LOW	\$	-
OB152	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.901359	151.129287	1		notify business/property owner	AF169	Secondary	LOW	\$	

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB159	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.879458	151.130654	1		notify business/property owner	AF6	Secondary	CW	\$	-
OB16	Piper Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.877905	151.169783	1		notify business/property owner	AN89	Secondary	CW	\$	-
OB160	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.878563	151.130451	1		notify business/property owner	AF5	Tertiary	CW	\$	-
OB161	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.883119	151.12455	1		notify business/property owner	AF9	Secondary	CW	\$	-
OB162	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.883949	151.123992	1		notify business/property owner	AF7	Secondary	CW	\$	-
OB163	Alt Street	Ashfield	Local Road	obstruction	double pole signpost narrowes footpath	-33.884068	151.123332	1		review and relocate double pole signpost	AF10	Primary	CW	\$	500
OB164	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.884635	151.123530	1		notify business/property owner	AF10	Primary	CW	\$	-
OB165	Alt Street	Ashfield	Local Road	obstruction	double pole signpost narrowes footpath - property	-33.882039	151.124803	1		review and relocate double pole signpost	AF9	Secondary	CW	\$	500
OB166	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.881961	151.125973	1		notify business/property owner	AF8	Tertiary	CW	\$	-
OB167	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.882007	151.125903	1		notify business/property owner	AF9	Secondary	CW	\$	-
OB168	Armstrong Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.880601	151.125377	1		refer to maintenance	AF12	Tertiary	CW	\$	-
OB169	Armstrong Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.899605	151.12685	1		refer to maintenance	AF11	Tertiary	CW	\$	-
OB17	Pritchard Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.874028	151.170323	1		refer to maintenance	AN122	Secondary	CW	\$	-
OB170	Armstrong Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.889448	151.126589	1		notify business/property owner	AF14	Tertiary	CW	\$	-
OB171	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.881233	151.13054	1		notify business/property owner	AF27	Tertiary	CW	\$	-
OB172	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.88089	151.131251	1		notify business/property owner	AF28	Tertiary	CW	\$	-
OB173	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.882153	151.130731	1		notify business/property owner	AF28	Tertiary	CW	\$	-
OB174	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.88276	151.127508	1		notify business/property owner	AF24	Tertiary	CW	\$	-
OB175	Bland Street	Ashfield	Local Road	obstruction	signpost narrowes footpath	-33.884362	151.126219	1		relocate signpost	AF19	Secondary	CW	\$	300
OB176	Bland Street	Ashfield	Local Road	obstruction	signpost narrowes footpath	-33.885005	151.125801	1		relocate signpost	AF18	Secondary	CW	\$	300
OB177	Bland Street	Ashfield	Local Road	obstruction	signpost narrowes footpath	-33.88576	151.125241	1		relocate signpost	AF17	Primary	CW	\$	300
OB178	Brown Street	Ashfield	Local Road	obstruction	power pole narrowes footpath	-33.887025	151.125954	1		further investigation required - footpath	AF31	Primary	CW	\$	5,000
OB179	Brown Street	Ashfield	Local Road	obstruction	power pole narrowes footpath	-33.887963	151.125738	1		no action	AF31	Primary	CW	\$	-
OB18	Rose Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.877362	151.176368	1		refer to maintenance	AN65	Secondary	CW	\$	-
OB180	Brown Street	Ashfield	Local Road	obstruction	bike locker narrowes footpath	-33.887927	151.125951	1		relocate or remove bike locker	AF31	Primary	CW	\$	400
OB181	Charlotte Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.88458	151.127399	1		refer to maintenance	AF38	Secondary	CW	\$	-
OB182	Charlotte Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.884021	151.127163	1		refer to maintenance	AF38	Secondary	CW	\$	-
OB183	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation	-33.879524	151.12615	1		refer to maintenance	AF40	Tertiary	CW	\$	-
OB184	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.879833	151.126069	1		refer to maintenance	AF40	Tertiary	CW	\$	-
OB185	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation	-33.87979	151.126044	1		refer to maintenance	AF40	Tertiary	CW	\$	-
OB186	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.879538	151.126195	1		refer to maintenance	AF44	Secondary	CW	\$	-
OB187	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.879307	151.125763	1		refer to maintenance	AF44	Secondary	CW	\$	-
OB188	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.879148	151.125699	1		notify business/property owner	AF44	Secondary	CW	\$	-
OB189	Church Street	Ashfield	Local Road	obstruction	tree narrowes footpath	-33.877573	151.124722	1		no action	AF42	Tertiary	CW	\$	-
OB19	The Crescent	Annandale	State Road	obstruction	Bus shelter narrowes footpath	-33.874521	151.174881	1		relocate or remove bus shelter	AN68	Primary	CW	\$	5,000
OB190	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.85798	151.180021	1		refer to maintenance	BA3	Secondary	CW	\$	-
OB191	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.8586	151.178007	1		notify business/property owner	BA7	Secondary	CW	\$	-
OB192	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation	-33.858828	151.17801	1		refer to maintenance	BA1	Tertiary	CW	\$	-
OB193	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.85879	151.178072	1		refer to maintenance	BA1	Tertiary	CW	\$	-
OB194	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.858753	151.178402	1		notify business/property owner	BA1	Tertiary	CW	\$	-
OB195	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.859352	151.174328	1		notify business/property owner	BA5	Secondary	CW	\$	-
OB196	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.859425	151.174385	1		notify business/property owner	BA5	Secondary	CW	\$	-
OB197	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.859498	151.174101	1		notify business/property owner	BA5	Secondary	CW	\$	-
OB198	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.859527	151.174025	1		refer to maintenance	BA5	Secondary	CW	\$	-
OB199	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation - property	-33.85962	151.176301	1		notify business/property owner	BA6	Secondary	CW	\$	-
OB2	Chester Street	Annandale	Local Road	obstruction	tree narrowes footpath	-33.884191	151.173054	1		no action	AN31	Primary	CW	\$	-
OB20	View Street	Annandale	Local Road	obstruction	vehicles narrow crossing path	-33.873939	151.174763	1		install no stopping sign and signpost	AN68	Primary	CW	\$	300
OB200	Beattie Street	Balmann	Local Road	obstruction	overhanging vegetation - property	-33.859848	151.175347	1		notify business/property owner	BA6	Secondary	CW	\$	-
OB201	Booth Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.860745	151.182057	1		refer to maintenance	BA14	Tertiary	CW	\$	-
OB202	Booth Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.860645	151.182027	1		notify business/property owner	BA14	Secondary	CW	\$	-
OB203	Booth Street	Balmann	Local Road	obstruction	overhanging vegetation - property	-33.860257	151.181931	1		notify business/property owner	BA14	Secondary	CW	\$	-
OB204	Booth Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.8597	151.182188	1		notify business/property owner	BA15	Primary	CW	\$	-
OB205	Booth Street	Balmann	Local Road	obstruction	overhanging vegetation - property	-33.860149	151.181805	1		notify business/property owner	BA14	Secondary	CW	\$	-
OB206	Booth Street	Balmann	Local Road	obstruction	overhanging vegetation - property	-33.859872	151.181915	1		notify business/property owner	BA16	Primary	CW	\$	-
OB207	Bradford Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.860407	151.182123	1		refer to maintenance	BA14	Secondary	CW	\$	-
OB208	Buchanan Street	Balmann	Local Road	obstruction	overhanging vegetation	-33.863492	151.180226	1		refer to maintenance	BA17	Tertiary	CW	\$	-
OB209	Buchanan Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.862401	151.18017	1		notify business/property owner	BA61	Secondary	CW	\$	-
OB21	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.882383	151.171912	1		notify business/property owner	AN108	Secondary	CW	\$	-
OB210	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.862602	151.180394	1		no action	BA18	Tertiary	CW	\$	-
OB211	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.862552	151.180318	1		no action	BA18	Tertiary	CW	\$	-
OB212	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.862736	151.180254	1		no action	BA18	Tertiary	CW	\$	-
OB213	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.86262	151.180234	1		no action	BA18	Tertiary	CW	\$	-
OB214	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.862091	151.18026	1		no action	BA18	Tertiary	CW	\$	-
OB215	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.863073	151.180265	1		no action	BA18	Tertiary	CW	\$	-
OB216	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.863122	151.180288	1		no action	BA18	Tertiary	CW	\$	-
OB217	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.863203	151.180313	1		no action	BA17	Tertiary	CW	\$	-
OB218	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.863446	151.180494	1		no action	BA17	Tertiary	CW	\$	-
OB219	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.863563	151.18048	1		no action	BA17	Tertiary	CW	\$	-
OB22	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.882257	151.172072	1		notify business/property owner	AN108	Secondary	CW	\$	-
OB220	Buchanan Street	Balmann	Local Road	obstruction	tree narrowes footpath	-33.862598	151.180559	1		no action	BA17	Tertiary	CW	\$	-
OB221	Buchanan Street	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.863801	151.180566	1		refer to maintenance	BA17	Tertiary	CW	\$	-
OB222	Curtis Road	Balmann	Local Road	obstruction	tree narrowes footpath	-33.857678	151.183552	1		no action	BA20	Primary	CW	\$	-
OB223	Curtis Road	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.857619	151.183547	1		notify business/property owner	BA20	Primary	CW	\$	-
OB224	Curtis Road	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.857039	151.183111	1		notify business/property owner	BA21	Secondary	CW	\$	-
OB225	Curtis Road	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.856607	151.181794	1		notify business/property owner	BA22	Secondary	CW	\$	-
OB226	Curtis Road	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.856021	151.181022	1		notify business/property owner	BA22	Secondary	CW	\$	-
OB227	Curtis Road	Balmann	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.856164	151.178863	1		notify business/property owner	BA19	Secondary	CW	\$	-
OB228	Curtis Road	Balmann	Local Road	obstruction	storefront narrowes footpath - property	-33.855607	151.180757	1		notify business/property owner	BA23	Secondary	CW	\$	-
OB229	Darling Street	Balmann	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.856053	151.173766	1		notify business/property owner	BA35	Secondary	CW	\$	-
OB3	Bignell Lane	Annandale	Local Road	obstruction	vehicles narrow footpath	-33.886427	151.174837	1		no action	AN63	Secondary	CW	\$	-
OB30	Darling Street	Balmann	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.855898	151.174539	1		notify business/property owner	BA34	Primary	CW	\$	-
OB31	Darling Street	Balmann	Regional Road	obstruction	bench narrowes footpath	-33.855889	151.175219	1		relocate or remove bench	BA34	Primary	CW	\$	400
OB32	Darling Street	Balmann	Regional Road	obstruction	overhanging vegetation narrowes footpath	-33.856381	151.177432	1		refer to maintenance	BA32	Primary	CW	\$	-
OB33	Darling Street	Balmann	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.856038	151.175387	1		notify business/property owner	BA34	Primary	CW	\$	-
OB34	Darling Street	Balmann	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.856038	151.174411	1		notify business/property owner	BA34	Primary	CW	\$	-
OB35	Darling Street	Balmann	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.856281	151.173774	1		notify business/property owner	BA35	Secondary	CW	\$	-
OB36	Darling Street	Balmann	Regional Road	obstruction	bus shelter narrowes footpath	-33.856281	151.1738	1		relocate or remove bus shelter	BA35	Secondary	CW	\$	5,000
OB37	Darling Street	Balmann	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.8571	151.172542	1		notify business/property owner	BA36	Secondary	CW	\$	-
OB38	Darling Street	Balmann	Regional Road	obstruction	storefront narrowes footpath - property	-33.856734	151.178378	1		notify business/property owner	BA31	Primary	CW	\$	-
OB39	Darling Street	Balmann	Local Road	obstruction	signage narrowes footpath - property	-33.857674	151.182078	1		notify business owner	BA25	Primary	CW	\$	-
OB4	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property										

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB244	Darling Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.857622	151.18131	1		refer to maintenance	BA29	Primary	LOW	\$	-
OB245	Darling Street	Balmain	Local Road	obstruction	storefront - property narrows footpath	-33.857754	151.182033	1		notify business owner	BA29	Primary	LOW	\$	-
OB246	Darvall Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.858554	151.182539	1		notify business/property owner	BA39	Primary	LOW	\$	-
OB247	Darvall Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.858604	151.183265	1		notify business/property owner	BA39	Primary	LOW	\$	-
OB248	Darvall Street	Balmain	Local Road	obstruction	trees narrows footpath	-33.858646	151.183562	1		no action	BA39	Primary	LOW	\$	-
OB249	Eaton Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.858509	151.183775	1		notify business/property owner	BA40	Primary	LOW	\$	-
OB250	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.862532	151.171842	1		notify business/property owner	AN108	Secondary	LOW	\$	-
OB251	Hyam Street	Balmain	Local Road	obstruction	bollards narrows footpath	-33.86119	151.180869	1		relocate or remove bollard	BA42	Tertiary	LOW	\$	2,500
OB252	Jane Street	Balmain	Local Road	obstruction	light post narrows footpath	-33.861518	151.180392	1		relocate light post	BA43	Secondary	LOW	\$	10,000
OB253	Jane Street	Balmain	Local Road	obstruction	power pole narrows footpath	-33.859767	151.184435	1		no action	BA45	Secondary	LOW	\$	-
OB254	Jane Street	Balmain	Local Road	obstruction	power pole narrows footpath	-33.859488	151.184388	1		no action	BA45	Secondary	LOW	\$	-
OB255	Jane Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.858888	151.184363	1		no action	BA44	Primary	LOW	\$	-
OB256	Macquarie Terrace	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.858824	151.184496	1		notify business/property owner	BA44	Primary	LOW	\$	-
OB257	Macquarie Terrace	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.854196	151.176007	1		notify business/property owner	BA46	Primary	LOW	\$	-
OB258	Montague Street	Balmain	Local Road	obstruction	power pole narrows footpath	-33.854185	151.177899	1		no action	BA46	Primary	LOW	\$	-
OB259	Mulens Street	Balmain	Regional Road	obstruction	bike rack narrows footpath	-33.857093	151.177837	1		relocate or remove bike rack	BA47	Secondary	LOW	\$	250
OB260	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.859401	151.177340	1		refer to maintenance	BA49	Secondary	LOW	\$	-
OB261	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.862895	151.177891	1		notify business/property owner	AN108	Secondary	LOW	\$	-
OB262	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.859698	151.17736	1		refer to maintenance	BA49	Secondary	LOW	\$	-
OB263	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.860569	151.177259	1		refer to maintenance	BA50	Primary	LOW	\$	-
OB264	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.860525	151.177281	1		refer to maintenance	BA50	Primary	LOW	\$	-
OB265	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.860606	151.177168	1		notify business/property owner	BA50	Primary	LOW	\$	-
OB266	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.860645	151.177103	1		refer to maintenance	BA50	Primary	LOW	\$	-
OB267	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation - property	-33.861091	151.176408	1		notify business/property owner	BA51	Primary	LOW	\$	-
OB268	Mulens Street	Balmain	Regional Road	obstruction	bin narrows footpath - council	-33.861324	151.176759	1		further investigation required - bins	BA51	Primary	LOW	\$	-
OB269	Mulens Street	Balmain	Regional Road	obstruction	bus shelter and signpost narrows footpath	-33.862772	151.176459	1		relocate or remove bus shelter and signposts	BA52	Secondary	LOW	\$	5,500
OB270	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.862227	151.176430	1		notify business/property owner	BA52	Secondary	LOW	\$	-
OB271	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.862266	151.176429	1		notify business/property owner	BA52	Secondary	LOW	\$	-
OB272	Palmer Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.884687	151.170836	1		notify business/property owner	AN109	Secondary	LOW	\$	-
OB273	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.860674	151.181477	1		notify business/property owner	BA54	Tertiary	LOW	\$	-
OB274	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.860666	151.181441	1		notify business/property owner	BA54	Tertiary	LOW	\$	-
OB275	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation	-33.86047	151.18113	1		refer to maintenance	BA55	Secondary	LOW	\$	-
OB276	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860366	151.181014	1		refer to maintenance	BA55	Secondary	LOW	\$	-
OB277	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - council and property	-33.86046	151.180881	1		refer to maintenance	BA55	Secondary	LOW	\$	-
OB278	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation	-33.858866	151.180286	1		refer to maintenance	BA55	Secondary	LOW	\$	-
OB279	Palmer Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.858311	151.180461	1		no action	BA53	Secondary	LOW	\$	-
OB280	Palmer Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.859697	151.180589	1		no action	BA56	Secondary	LOW	\$	-
OB281	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.859266	151.18041	1		refer to maintenance	BA56	Secondary	LOW	\$	-
OB282	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.858747	151.17992	1		refer to maintenance	BA57	Secondary	LOW	\$	-
OB283	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.884083	151.171242	1		notify business/property owner	AN32	Secondary	LOW	\$	-
OB284	Thames Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.859784	151.171193	1		no action	BA59	Secondary	LOW	\$	-
OB285	Thames Street	Balmain	Local Road	obstruction	power pole narrows footpath	-33.858513	151.184879	1		no action	BA71	Secondary	LOW	\$	-
OB286	Worley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.861001	151.178463	1		refer to maintenance	BA76	Secondary	LOW	\$	-
OB287	Worley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860916	151.17859	1		refer to maintenance	BA76	Secondary	LOW	\$	-
OB288	Worley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860711	151.178851	1		refer to maintenance	BA76	Secondary	LOW	\$	-
OB289	Worley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.860263	151.179647	1		no action	BA75	Tertiary	LOW	\$	-
OB290	Worley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860307	151.179276	1		refer to maintenance	BA75	Tertiary	LOW	\$	-
OB291	Worley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.86054	151.178755	1		no action	BA76	Secondary	LOW	\$	-
OB292	Worley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.86038	151.178346	1		no action	BA76	Secondary	LOW	\$	-
OB293	Worley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.861146	151.177878	1		no action	BA59	Secondary	LOW	\$	-
OB294	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.859697	151.180589	1		no action	BA56	Secondary	LOW	\$	-
OB295	Worley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.861274	151.177571	1		no action	BA58	Secondary	LOW	\$	-
OB296	Darling Street	Balmain East	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.857963	151.189563	1		notify business/property owner	BA24	Secondary	LOW	\$	-
OB297	Darling Street	Balmain East	Local Road	obstruction	tree narrows footpath - property	-33.857817	151.192097	1		notify property owner	BE3	Primary	LOW	\$	-
OB298	Louisa Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.858009	151.17914	1		no action	B10	Tertiary	LOW	\$	-
OB299	Louisa Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.857199	151.179437	1		no action	B10	Tertiary	LOW	\$	-
OB300	Louisa Road	Birchgrove	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.850044	151.179542	1		notify business/property owner	B10	Tertiary	LOW	\$	-
OB301	Louisa Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.84848	151.180075	1		no action	B11	Tertiary	LOW	\$	-
OB302	Louisa Road	Birchgrove	Local Road	obstruction	Electricity box narrows footpath	-33.849252	151.180176	1		no action	B11	Tertiary	LOW	\$	-
OB303	Louisa Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.848318	151.181108	1		no action	B12	Tertiary	LOW	\$	-
OB304	Louisa Road	Birchgrove	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.848249	151.181281	1		notify business/property owner	B12	Tertiary	LOW	\$	-
OB305	Chester Street	Annandale	Local Road	obstruction	signpost narrows footpath	-33.884265	151.173386	1		relocate signpost	AN31	Primary	LOW	\$	300
OB306	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.884406	151.171105	1		refer to maintenance	AN109	Secondary	LOW	\$	-
OB307	Louisa Road	Birchgrove	Local Road	obstruction	bollards narrows footpath	-33.848039	151.181983	1		relocate or remove bollard	B16	Tertiary	LOW	\$	2,500
OB308	Louisa Road	Birchgrove	Local Road	obstruction	bollard narrows footpath	-33.847977	151.182213	1		repair bollard	B16	Tertiary	LOW	\$	2,500
OB309	Louisa Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.847919	151.182383	1		no action	B17	Tertiary	LOW	\$	-
OB310	Louisa Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.847487	151.184121	1		no action	B13	Tertiary	LOW	\$	-
OB311	Louisa Road	Birchgrove	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.847119	151.184903	1		notify business/property owner	B14	Secondary	LOW	\$	-
OB312	Louisa Road	Birchgrove	Local Road	obstruction	bollard narrows footpath	-33.846821	151.185425	1		relocate or remove bollard	B17	Secondary	LOW	\$	2,500
OB313	Louisa Road	Birchgrove	Local Road	obstruction	pot plants narrows footpath - property	-33.847018	151.182412	1		notify property owner	B17	Secondary	LOW	\$	-
OB314	Louisa Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.849227	151.180192	1		no action	B19	Tertiary	LOW	\$	-
OB315	Romtree Street	Birchgrove	Local Road	obstruction	vehicles narrows footpath	-33.851585	151.183928	1		no action	B16	Tertiary	LOW	\$	-
OB316	Romtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.851713	151.183934	1		no action	B16	Tertiary	LOW	\$	-
OB317	Trafalgar Street	Annandale	Local Road	obstruction	vehicle narrows footpath	-33.884467	151.171069	1		no action	AN109	Secondary	LOW	\$	-
OB318	Romtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.851783	151.183462	1		no action	B16	Tertiary	LOW	\$	-
OB319	Romtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.85182	151.183392	1		no action	B16	Tertiary	LOW	\$	-
OB320	Romtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.851817	151.18339	1		no action	B16	Tertiary	LOW	\$	-
OB321	Romtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.851984	151.183116	1		no action	B17	Tertiary	LOW	\$	-
OB322	Romtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.852174	151.182928	1		no action	B17	Tertiary	LOW	\$	-
OB323	Australia Street	Camperdown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.852047	151.176708	1		notify business/property owner	C48	Primary	LOW	\$	-
OB324	Church Street	Croydon	Local Road	obstruction	vehicles narrows footpath	-33.889571	151.173279	1		no action	CAT8	Secondary	LOW	\$	-
OB325	Church Street	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.875764	151.122047	1		refer to maintenance	CR1	Secondary	LOW	\$	-
OB326	Church Street	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.875861	151.122596	1		refer to maintenance	CR1	Secondary	LOW	\$	-
OB327	Church Street	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.876371	151.123449	1		refer to maintenance	CR2	Secondary	LOW	\$	-
OB328	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation	-33.886961	151.169917	1		refer to maintenance	AN111	Secondary	LOW	\$	-
OB329	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87351	151.125615	1		notify business/property owner	CR4	Secondary	LOW	\$	-
OB330	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.873656	151.125614	1		refer to maintenance	CR4	Secondary	LOW	\$	-
OB331	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation	-33.88137	151.119460	1		refer to maintenance	CR15	Secondary	LOW	\$	-
OB332	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880472	151.119915	1		refer to maintenance	CR3	Secondary	LOW	\$	-
OB333	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879432	151.120637	1		notify business/property owner	CR4	Secondary	LOW	\$	-
OB334	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath - property	-3									

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment	Cost
OB33	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.8816	151.1722	1		refer to maintenance	AN105	Secondary	CW	\$ -
OB330	Paramatta Road	Croydon	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.87198	151.12358	1		notify business/property owner	CR28	Secondary	CW	\$ -
OB331	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.8938	151.11517	1		notify business/property owner	CP4	Tertiary	CW	\$ -
OB332	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.89328	151.11604	1		notify business/property owner	CP3	Secondary	CW	\$ -
OB333	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.893472	151.116167	1		notify business/property owner	CP2	Secondary	CW	\$ -
OB334	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.89437	151.115241	1		notify business/property owner	CP1	Secondary	CW	\$ -
OB335	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.89338	151.114554	1		notify business/property owner	CP5	Secondary	CW	\$ -
OB336	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.901019	151.134118	1		notify business/property owner	DH13	Tertiary	CW	\$ -
OB337	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900974	151.134399	1		notify business/property owner	DH13	Tertiary	CW	\$ -
OB338	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900919	151.135037	1		notify business/property owner	DH14	Tertiary	CW	\$ -
OB339	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900826	151.135734	1		notify business/property owner	DH14	Tertiary	CW	\$ -
OB34	Booth Street	Annandale	Regional Road	obstruction	storefront narrowes footpath - property	-33.88278	151.173173	1		notify business/property owner	AN26	Primary	CW	\$ -
OB340	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.901117	151.134249	1		notify business/property owner	DH13	Tertiary	CW	\$ -
OB341	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.901162	151.133737	1		notify business/property owner	DH13	Tertiary	CW	\$ -
OB342	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.901003	151.133019	1		notify business/property owner	DH12	Secondary	CW	\$ -
OB343	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.909796	151.139996	1		refer to maintenance	DH3	Secondary	CW	\$ -
OB344	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.910559	151.140044	1		refer to maintenance	DH2	Secondary	CW	\$ -
OB345	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.910483	151.140664	1		refer to maintenance	DH2	Secondary	CW	\$ -
OB346	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.910309	151.140333	1		refer to maintenance	DH3	Secondary	CW	\$ -
OB347	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.907034	151.140604	1		notify business/property owner	DH4	Secondary	CW	\$ -
OB348	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.907146	151.140513	1		notify business/property owner	DH4	Secondary	CW	\$ -
OB349	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.907189	151.140569	1		notify business/property owner	DH4	Secondary	CW	\$ -
OB35	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.880147	151.172815	1		notify business/property owner	AN106	Secondary	CW	\$ -
OB350	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.907066	151.140571	1		notify business/property owner	DH4	Secondary	CW	\$ -
OB351	Challis Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.910532	151.14552	1		notify business/property owner	DH7	Tertiary	CW	\$ -
OB352	Challis Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.9104	151.14526	1		notify business/property owner	DH8	Secondary	CW	\$ -
OB353	Consett Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.908145	151.138629	1		notify business/property owner	DH9	Secondary	CW	\$ -
OB354	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902526	151.138629	1		refer to maintenance	DH17	Secondary	CW	\$ -
OB355	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902537	151.138329	1		notify business/property owner	DH17	Secondary	CW	\$ -
OB356	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902626	151.139536	1		notify business/property owner	DH10	Primary	CW	\$ -
OB357	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.903112	151.140405	1		notify business/property owner	DH10	Secondary	CW	\$ -
OB358	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.902994	151.139616	1		refer to maintenance	DH10	Primary	CW	\$ -
OB359	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.902994	151.139113	1		refer to maintenance	DH10	Primary	CW	\$ -
OB36	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.87973	151.173083	1		notify business/property owner	AN100	Secondary	CW	\$ -
OB360	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902536	151.139092	1		refer to maintenance	DH10	Primary	CW	\$ -
OB361	Davis Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.896289	151.140375	1		refer to maintenance	DH16	Secondary	CW	\$ -
OB362	Davis Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.899137	151.140208	1		refer to maintenance	DH16	Secondary	CW	\$ -
OB363	Denison Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902572	151.139531	1		refer to maintenance	DH23	Primary	CW	\$ -
OB364	Denison Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902445	151.139586	1		notify business/property owner	DH23	Primary	CW	\$ -
OB365	Denison Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902225	151.139872	1		notify business/property owner	DH23	Primary	CW	\$ -
OB366	Denison Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902035	151.140059	1		refer to maintenance	DH22	Primary	CW	\$ -
OB367	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902477	151.141028	1		notify business/property owner	DH25	Primary	CW	\$ -
OB368	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902979	151.142138	1		notify business/property owner	DH26	Primary	CW	\$ -
OB369	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.902937	151.141481	1		refer to maintenance	DH26	Primary	CW	\$ -
OB37	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.880181	151.172954	1		refer to maintenance	AN106	Secondary	CW	\$ -
OB370	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902205	151.14072	1		notify business/property owner	DH25	Primary	CW	\$ -
OB371	Ewart Street	Dulwich Hill	Local Road	obstruction	power pole narrowes footpath	-33.906959	151.137106	1		no action	DH32	Secondary	CW	\$ -
OB372	Ewart Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.909751	151.137028	1		notify business/property owner	DH32	Secondary	CW	\$ -
OB373	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.90096	151.147307	1		notify business/property owner	DH35	Tertiary	CW	\$ -
OB374	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.900899	151.146341	1		notify business/property owner	DH35	Tertiary	CW	\$ -
OB375	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900907	151.146155	1		notify business/property owner	DH35	Tertiary	CW	\$ -
OB376	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.900908	151.146923	1		notify business/property owner	DH35	Tertiary	CW	\$ -
OB377	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.900839	151.147446	1		notify business/property owner	DH36	Tertiary	CW	\$ -
OB378	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.901334	151.139437	1		refer to maintenance	DH61	Secondary	CW	\$ -
OB379	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.901449	151.139307	1		refer to maintenance	DH61	Secondary	CW	\$ -
OB38	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.874489	151.173154	1		notify business/property owner	AN100	Secondary	CW	\$ -
OB380	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.901571	151.139266	1		refer to maintenance	DH61	Secondary	CW	\$ -
OB381	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.901665	151.139176	1		refer to maintenance	DH61	Secondary	CW	\$ -
OB382	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.901951	151.138994	1		refer to maintenance	DH60	Secondary	CW	\$ -
OB383	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.902276	151.138771	1		refer to maintenance	DH60	Secondary	CW	\$ -
OB384	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.902086	151.138987	1		refer to maintenance	DH60	Secondary	CW	\$ -
OB385	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.901751	151.139186	1		notify business/property owner	DH60	Secondary	CW	\$ -
OB386	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.901324	151.139548	1		refer to maintenance	DH61	Secondary	CW	\$ -
OB387	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.90118	151.139728	1		refer to maintenance	DH61	Secondary	CW	\$ -
OB388	Hampstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.898528	151.138012	1		notify business/property owner	DH63	Secondary	CW	\$ -
OB389	Hampstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.898663	151.138324	1		notify business/property owner	DH63	Secondary	CW	\$ -
OB39	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.879351	151.173263	1		refer to maintenance	AN100	Secondary	CW	\$ -
OB390	Hampstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.898572	151.138218	1		notify business/property owner	DH63	Secondary	CW	\$ -
OB391	Hampstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.897781	151.137026	1		notify business/property owner	DH62	Secondary	CW	\$ -
OB392	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902721	151.139671	1		notify business/property owner	DH65	Secondary	CW	\$ -
OB393	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902685	151.138903	1		notify business/property owner	DH65	Secondary	CW	\$ -
OB394	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902628	151.138956	1		notify business/property owner	DH65	Secondary	CW	\$ -
OB395	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902683	151.139421	1		notify business/property owner	DH65	Secondary	CW	\$ -
OB396	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.905198	151.139581	1		notify business/property owner	DH64	Secondary	CW	\$ -
OB397	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.905188	151.139581	1		notify business/property owner	DH64	Secondary	CW	\$ -
OB398	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.905052	151.140047	1		notify business/property owner	DH64	Secondary	CW	\$ -
OB399	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.905051	151.139871	1		refer to maintenance	DH65	Secondary	CW	\$ -
OB4	Hutchinson Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.875067	151.169835	1		refer to maintenance	AN120	Secondary	CW	\$ -
OB40	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.879625	151.173083	1		notify business/property owner	AN100	Secondary	CW	\$ -
OB400	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.906822	151.139035	1		notify business/property owner	DH65	Secondary	CW	\$ -
OB401	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.906892	151.138999	1		refer to maintenance	DH65	Secondary	CW	\$ -
OB402	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.906846	151.138969	1		notify business/property owner	DH53	Secondary	CW	\$ -
OB403	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.90674	151.138674	1		notify business/property owner	DH53	Secondary	CW	\$ -
OB404	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.90738	151.138642	1		notify business/property owner	DH68	Secondary	CW	\$ -
OB405	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.900628	151.139362	1		refer to maintenance	DH68	Secondary	CW	\$ -
OB406	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900713	151.139082	1		notify business/property owner	DH68	Secondary	CW	\$ -
OB407	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900462	151.138935	1		notify business/property owner	DH67	Secondary	CW	\$ -
OB408	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900128	151.139169	1		notify business/property owner	DH67	Secondary	CW	\$ -
OB409	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.900391	151.139164	1		refer to maintenance	DH67	Secondary	CW	\$ -
OB41	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.879304	151.173255	1		notify business/property owner	AN100	Secondary	CW	\$ -
OB410	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.900929	151.138949	1		refer to maintenance	DH68	Secondary	CW	\$ -
OB411	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.901237	151.14							

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB415	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.90448	151.141069	1		notify business/property owner	DH74	Secondary	CW	\$	-
OB416	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.90694	151.141315	1		refer to maintenance	DH73	Secondary	CW	\$	-
OB417	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.90665	151.141331	1		notify business/property owner	DH73	Secondary	CW	\$	-
OB418	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.90574	151.140836	1		notify business/property owner	DH72	Secondary	CW	\$	-
OB419	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.90509	151.140686	1		notify business/property owner	DH72	Secondary	CW	\$	-
OB42	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.87658	151.175575	1		refer to maintenance	AN104	Secondary	CW	\$	-
OB420	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.90536	151.140594	1		notify business/property owner	DH72	Secondary	CW	\$	-
OB421	Marickville Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.906119	151.145234	1		notify business/property owner	DH77	Secondary	CW	\$	-
OB422	Marickville Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.90558	151.144933	1		notify business/property owner	DH79	Primary	CW	\$	-
OB423	Ness Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.910741	151.136836	1		refer to maintenance	DH80	Tertiary	CW	\$	-
OB424	Ness Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.910281	151.137432	1		notify business/property owner	DH110	Tertiary	CW	\$	-
OB425	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.901522	151.144786	1		notify business/property owner	DH93	Primary	CW	\$	-
OB426	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.905127	151.137975	1		notify business/property owner	DH112	Secondary	CW	\$	-
OB427	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.905789	151.136194	1		notify business/property owner	DH86	Primary	CW	\$	-
OB428	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.905644	151.134237	1		notify business/property owner	DH88	Secondary	CW	\$	-
OB429	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath	-33.905742	151.134575	1		refer to maintenance	DH87	Primary	CW	\$	-
OB43	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.876323	151.178602	1		notify business/property owner	AN104	Secondary	CW	\$	-
OB430	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath	-33.905592	151.136317	1		refer to maintenance	DH86	Primary	CW	\$	-
OB431	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath	-33.905389	151.136789	1		refer to maintenance	DH85	Primary	CW	\$	-
OB432	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.902536	151.144056	1		notify business/property owner	DH85	Primary	CW	\$	-
OB433	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.901232	151.14466	1		notify business/property owner	DH83	Primary	CW	\$	-
OB434	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.895865	151.138104	1		notify business/property owner	SH56	Primary	CW	\$	-
OB435	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.896212	151.135955	1		notify business/property owner	SH57	Secondary	CW	\$	-
OB436	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.897482	151.135994	1		notify business/property owner	SH58	Secondary	CW	\$	-
OB437	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.898264	151.134852	1		notify business/property owner	SH59	Tertiary	CW	\$	-
OB438	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.898551	151.134269	1		notify business/property owner	SH60	Tertiary	CW	\$	-
OB439	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902021	151.131030	1		notify business/property owner	AF127	Secondary	CW	\$	-
OB44	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.876559	151.173739	1		refer to maintenance	AN104	Secondary	CW	\$	-
OB440	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902136	151.130946	1		notify business/property owner	AF127	Secondary	CW	\$	-
OB441	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900936	151.141305	1		notify business/property owner	DH104	Secondary	CW	\$	-
OB442	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.901001	151.142517	1		notify business/property owner	DH103	Secondary	CW	\$	-
OB443	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902059	151.14321	1		notify business/property owner	DH105	Secondary	CW	\$	-
OB444	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902218	151.14363	1		notify business/property owner	DH105	Secondary	CW	\$	-
OB445	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.900345	151.140276	1		refer to maintenance	DH103	Secondary	CW	\$	-
OB446	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.900725	151.140529	1		notify business/property owner	DH103	Secondary	CW	\$	-
OB447	Riverside Crescent	Dulwich Hill	Local Road	obstruction	bollards narrowes footpath	-33.912687	151.138235	1		relocate or remove bollard	MV236	Secondary	CW	\$	2,500
OB448	Tennyson Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.910599	151.135849	1		notify business/property owner	DH38	Secondary	CW	\$	-
OB449	Tennyson Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.911127	151.136782	1		notify business/property owner	DH38	Secondary	CW	\$	-
OB45	Booth Street	Annandale	Regional Road	obstruction	power pole narrowes footpath	-33.885038	151.175966	1		further investigation required - footpath	AN28	Secondary	CW	\$	5,000
OB450	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.909036	151.137904	1		notify business/property owner	DH111	Tertiary	CW	\$	-
OB451	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.908677	151.137694	1		notify business/property owner	DH111	Tertiary	CW	\$	-
OB452	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.908602	151.137580	1		notify business/property owner	DH111	Tertiary	CW	\$	-
OB453	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.909026	151.137723	1		refer to maintenance	DH111	Tertiary	CW	\$	-
OB454	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.909265	151.13806	1		refer to maintenance	DH52	Secondary	CW	\$	-
OB455	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.907446	151.137694	1		notify business/property owner	DH113	Tertiary	CW	\$	-
OB456	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.90749	151.137618	1		refer to maintenance	DH113	Tertiary	CW	\$	-
OB457	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.907822	151.137787	1		refer to maintenance	DH113	Tertiary	CW	\$	-
OB458	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.908346	151.137552	1		refer to maintenance	DH111	Tertiary	CW	\$	-
OB459	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.908226	151.137741	1		notify business/property owner	DH113	Tertiary	CW	\$	-
OB46	Trafalgar Street	Annandale	Local Road	obstruction	signpost narrowes footpath	-33.876815	151.174432	1		relocate signpost	AN102	Tertiary	CW	\$	300
OB460	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.908321	151.137741	1		refer to maintenance	DH113	Tertiary	CW	\$	-
OB461	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.905224	151.133	1		notify business/property owner	DH114	Secondary	CW	\$	-
OB462	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.906599	151.137999	1		refer to maintenance	DH112	Secondary	CW	\$	-
OB463	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.899519	151.138021	1		notify business/property owner	DH115	Secondary	CW	\$	-
OB464	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.899766	151.138480	1		refer to maintenance	DH115	Secondary	CW	\$	-
OB465	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.899542	151.137924	1		notify business/property owner	DH115	Secondary	CW	\$	-
OB466	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.899492	151.137812	1		refer to maintenance	DH115	Secondary	CW	\$	-
OB467	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.909172	151.143132	1		notify business/property owner	DH128	Primary	CW	\$	-
OB468	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.909072	151.142339	1		notify business/property owner	DH125	Primary	CW	\$	-
OB469	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.910379	151.141969	1		notify business/property owner	DH125	Primary	CW	\$	-
OB47	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.876428	151.174609	1		notify business/property owner	AN102	Tertiary	CW	\$	-
OB470	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.910627	151.141459	1		notify business/property owner	DH124	Primary	CW	\$	-
OB471	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.898058	151.139175	1		refer to maintenance	DH117	Secondary	CW	\$	-
OB472	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.898161	151.140256	1		refer to maintenance	DH44	Secondary	CW	\$	-
OB473	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.898051	151.140418	1		notify business/property owner	DH44	Secondary	CW	\$	-
OB474	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.897246	151.141445	1		notify business/property owner	DH47	Secondary	CW	\$	-
OB475	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.897024	151.141727	1		refer to maintenance	DH46	Tertiary	CW	\$	-
OB476	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.896284	151.141677	1		notify business/property owner	DH45	Secondary	CW	\$	-
OB477	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.896813	151.141696	1		refer to maintenance	DH46	Tertiary	CW	\$	-
OB478	Williams Parade	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.902551	151.137307	1		refer to maintenance	DH127	Secondary	CW	\$	-
OB479	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.900097	151.171436	1		notify business/property owner	EN1	Primary	CW	\$	-
OB48	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.876736	151.174608	1		notify business/property owner	AN102	Tertiary	CW	\$	-
OB480	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.901264	151.171598	1		notify business/property owner	EN2	Primary	CW	\$	-
OB481	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.90189	151.171733	1		notify business/property owner	EN3	Primary	CW	\$	-
OB482	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.902492	151.171977	1		notify business/property owner	EN4	Secondary	CW	\$	-
OB483	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.903255	151.172332	1		notify business/property owner	EN5	Secondary	CW	\$	-
OB484	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation narrowes footpath - property	-33.903631	151.172517	1		notify business/property owner	EN5	Secondary	CW	\$	-
OB485	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.90368	151.172572	1		notify business/property owner	EN5	Secondary	CW	\$	-
OB486	Liberty Street	Enmore	Regional Road	obstruction	empty tree pit narrowes footpath	-33.896103	151.171028	1		widen footpath	EN11	Secondary	CW	\$	200
OB487	Al Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.878119	151.132924	1		refer to maintenance	HA4	Tertiary	CW	\$	-
OB488	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.87923	151.134032	1		refer to maintenance	HA20	Secondary	CW	\$	-
OB489	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.879566	151.133518	1		notify business/property owner	HA19	Secondary	CW	\$	-
OB49	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.876519	151.174685	1		refer to maintenance	AN102	Tertiary	CW	\$	-
OB490	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.882343	151.1321	1		refer to maintenance	HA18	Secondary	CW	\$	-
OB491	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath	-33.880178	151.132265	1		refer to maintenance	AF29	Secondary	CW	\$	-
OB492	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.878669	151.133041	1		notify business/property owner	HA18	Secondary	CW	\$	-
OB493	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.870749	151.145211	1		notify business/property owner	HA22	Secondary	CW	\$	-
OB494	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.870955	151.144683	1		notify business/property owner	HA22	Secondary	CW	\$	-
OB495	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation narrowes footpath - property	-33.871173	151.144848	1		notify business/property owner</					

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment	Cost
OB500	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874657	151.14276	1		notify business/property owner	HA27	Secondary	CW	\$ -
OB501	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874813	151.142683	1		notify business/property owner	HA25	Secondary	CW	\$ -
OB502	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.875434	151.142138	1		notify business/property owner	HA106	Secondary	CW	\$ -
OB503	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.875188	151.142223	1		refer to maintenance	HA25	Secondary	CW	\$ -
OB504	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.874997	151.142302	1		refer to maintenance	HA25	Secondary	CW	\$ -
OB505	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.874844	151.142391	1		refer to maintenance	HA25	Secondary	CW	\$ -
OB506	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874743	151.142697	1		notify business/property owner	HA27	Secondary	CW	\$ -
OB507	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.874219	151.142795	1		refer to maintenance	HA27	Secondary	CW	\$ -
OB508	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874033	151.142856	1		notify business/property owner	HA27	Secondary	CW	\$ -
OB509	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.873368	151.142899	1		refer to maintenance	HA27	Secondary	CW	\$ -
OB51	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation	-33.876148	151.17484	1		refer to maintenance	AN102	Tertiary	CW	\$ -
OB510	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.873733	151.142937	1		notify business/property owner	HA27	Secondary	CW	\$ -
OB511	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.872979	151.143343	1		refer to maintenance	HA28	Secondary	CW	\$ -
OB512	Dalhousie Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.877879	151.140612	1		notify business/property owner	HA32	Primary	CW	\$ -
OB513	Dalhousie Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.88176	151.137997	1		notify business/property owner	HA36	Primary	CW	\$ -
OB514	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.88026	151.135637	1		refer to maintenance	HA43	Secondary	CW	\$ -
OB515	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.880445	151.135501	1		refer to maintenance	HA43	Secondary	CW	\$ -
OB516	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.880711	151.135633	1		refer to maintenance	HA42	Secondary	CW	\$ -
OB517	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881297	151.136463	1		notify business/property owner	HA42	Secondary	CW	\$ -
OB518	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.881442	151.136613	1		notify business/property owner	HA41	Secondary	CW	\$ -
OB519	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881574	151.136759	1		notify business/property owner	HA41	Secondary	CW	\$ -
OB52	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.876227	151.174812	1		notify business/property owner	AN102	Tertiary	CW	\$ -
OB520	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881582	151.136779	1		refer to maintenance	HA41	Secondary	CW	\$ -
OB521	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.881732	151.136933	1		refer to maintenance	HA41	Secondary	CW	\$ -
OB522	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881802	151.136983	1		notify business/property owner	HA41	Secondary	CW	\$ -
OB523	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881801	151.137028	1		refer to maintenance	HA41	Secondary	CW	\$ -
OB524	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881864	151.137099	1		notify business/property owner	HA41	Secondary	CW	\$ -
OB525	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.882001	151.137226	1		notify business/property owner	HA41	Secondary	CW	\$ -
OB526	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881947	151.137393	1		notify business/property owner	HA41	Secondary	CW	\$ -
OB527	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881965	151.137396	1		notify business/property owner	HA41	Secondary	CW	\$ -
OB528	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.881968	151.137412	1		refer to maintenance	HA41	Secondary	CW	\$ -
OB529	Denman Avenue	Haberfield	Local Road	obstruction	signpost narrow footpath	-33.881511	151.136915	1		relocate signpost	HA41	Secondary	CW	\$ 300
OB53	White Creek	Annandale	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.879823	151.167572	1		notify business/property owner	AN113	Secondary	CW	\$ -
OB530	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881467	151.136889	1		refer to maintenance	HA41	Secondary	CW	\$ -
OB531	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881366	151.136764	1		refer to maintenance	HA41	Secondary	CW	\$ -
OB532	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.885754	151.144225	1		notify business/property owner	HA56	Secondary	CW	\$ -
OB533	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.884933	151.144124	1		notify business/property owner	HA56	Secondary	CW	\$ -
OB534	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation	-33.885125	151.143895	1		notify business/property owner	HA56	Secondary	CW	\$ -
OB535	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.88696	151.144136	1		refer to maintenance	HA56	Secondary	CW	\$ -
OB536	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.885667	151.144075	1		refer to maintenance	HA56	Secondary	CW	\$ -
OB537	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.886645	151.143987	1		refer to maintenance	HA56	Secondary	CW	\$ -
OB538	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.878515	151.145895	1		refer to maintenance	HA56	Secondary	CW	\$ -
OB539	Marion Street	Haberfield	Regional Road	obstruction	overhanging vegetation	-33.884069	151.144637	1		refer to maintenance	HA54	Primary	CW	\$ -
OB54	Booth Street	Annandale	Regional Road	obstruction	power pole narrow footpath	-33.884448	151.175797	1		no action	AN28	Secondary	CW	\$ -
OB540	Mortley Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.872074	151.143117	1		notify business/property owner	HA53	Secondary	CW	\$ -
OB541	Mortley Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.870926	151.141981	1		refer to maintenance	HA62	Secondary	CW	\$ -
OB542	Paramatta Road	Haberfield	State Road	obstruction	signposts narrow footpath	-33.874686	151.128185	1		relocate signpost	HA60	Secondary	CW	\$ 300
OB543	Paramatta Road	Haberfield	State Road	obstruction	light post narrow footpath	-33.876595	151.129648	1		relocate light post	HA62	Secondary	CW	\$ 10,000
OB544	Paramatta Road	Haberfield	State Road	obstruction	overhanging vegetation narrow footpath - property	-33.883203	151.143174	1		notify business/property owner	HA62	Secondary	CW	\$ -
OB545	Ramsey Street	Haberfield	Regional Road	obstruction	overhanging vegetation narrow footpath - property	-33.882598	151.140458	1		notify business/property owner	HA66	Secondary	CW	\$ -
OB546	Ramsey Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.885171	151.142567	1		notify business/property owner	HA61	Secondary	CW	\$ -
OB547	Ramsey Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.884963	151.142622	1		refer to maintenance	HA61	Secondary	CW	\$ -
OB548	Ramsey Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.885094	151.142673	1		notify business/property owner	HA61	Secondary	CW	\$ -
OB549	Ramsey Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.885094	151.142673	1		notify business/property owner	HA61	Secondary	CW	\$ -
OB55	Booth Street	Annandale	Regional Road	obstruction	power pole narrow footpath	-33.883891	151.175627	1		no action	AN27	Primary	CW	\$ -
OB550	Slaine Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.886794	151.14285	1		notify business/property owner	HA66	Tertiary	CW	\$ -
OB551	Slaine Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.887105	151.142444	1		notify business/property owner	HA100	Secondary	CW	\$ -
OB552	Ramsey Street	Haberfield	State Road	obstruction	overhanging vegetation narrow footpath - property	-33.874052	151.133594	1		notify business/property owner	HA68	Secondary	CW	\$ -
OB553	Ramsey Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.873768	151.133432	1		notify business/property owner	HA68	Secondary	CW	\$ -
OB554	Ramsey Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.873593	151.133433	1		notify business/property owner	HA68	Secondary	CW	\$ -
OB555	Ramsey Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.87391	151.133711	1		notify business/property owner	HA68	Secondary	CW	\$ -
OB556	Ramsey Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.874891	151.134403	1		notify business/property owner	HA67	Secondary	CW	\$ -
OB557	Ramsey Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.874763	151.134107	1		notify business/property owner	HA67	Secondary	CW	\$ -
OB558	Ramsey Street	Haberfield	State Road	obstruction	overhanging vegetation narrow footpath - property	-33.87461	151.134051	1		notify business/property owner	HA67	Secondary	CW	\$ -
OB559	Slaine Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.884428	151.142978	1		notify business/property owner	HA69	Tertiary	CW	\$ -
OB56	Booth Street	Annandale	Regional Road	obstruction	power pole narrow footpath	-33.883893	151.175488	1		no action	AN27	Primary	CW	\$ -
OB560	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.874407	151.139529	1		refer to maintenance	HA108	Secondary	CW	\$ -
OB561	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.873891	151.13827	1		notify business/property owner	HA101	Secondary	CW	\$ -
OB562	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.873639	151.137769	1		notify business/property owner	HA109	Tertiary	CW	\$ -
OB563	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.873631	151.137769	1		notify business/property owner	HA109	Tertiary	CW	\$ -
OB564	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.873708	151.137496	1		notify business/property owner	HA109	Tertiary	CW	\$ -
OB565	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.873942	151.137881	1		notify business/property owner	HA109	Tertiary	CW	\$ -
OB566	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.874158	151.138929	1		refer to maintenance	HA101	Secondary	CW	\$ -
OB567	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.875895	151.142658	1		notify business/property owner	HA105	Secondary	CW	\$ -
OB568	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.875827	151.142729	1		refer to maintenance	HA105	Secondary	CW	\$ -
OB569	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.876677	151.144619	1		notify business/property owner	HA103	Tertiary	CW	\$ -
OB57	Chester Street	Annandale	Local Road	obstruction	vehicles narrow footpath	-33.884732	151.174107	1		no action	AN30	Secondary	CW	\$ -
OB570	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.876621	151.144972	1		refer to maintenance	HA103	Tertiary	CW	\$ -
OB571	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.874784	151.140947	1		notify business/property owner	HA107	Secondary	CW	\$ -
OB572	Waratan Street	Haberfield	Local Road	obstruction	overhanging vegetation narrow footpath	-33.874666	151.140772	1		notify business/property owner	HA107	Secondary	CW	\$ -
OB573	Hardy Street	Hurlstone Park	Local Road	obstruction	overhanging vegetation narrow footpath	-33.90623	151.123674	1		refer to maintenance	HP2	Secondary	CW	\$ -
OB574	Hardy Street	Hurlstone Park	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.906074	151.123796	1		notify business/property owner	HP2	Secondary	CW	\$ -
OB575	Hardy Street	Hurlstone Park	Local Road	obstruction	overhanging vegetation narrow footpath	-33.905756	151.123994	1		refer to maintenance	HP2	Secondary	CW	\$ -
OB576	Hardy Street	Hurlstone Park	Local Road	obstruction	overhanging vegetation narrow footpath	-33.904457	151.124146	1		refer to maintenance	HP1	Secondary	CW	\$ -
OB577	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.880299	151.143663	1		notify business/property owner	UH2	Secondary	CW	\$ -
OB578	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrow footpath	-33.880389	151.146957	1		refer to maintenance	UH2	Secondary	CW	\$ -
OB579	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.880401	151.152731	1		notify business/property owner	UH6	Tertiary	CW	\$ -
OB58	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.903204	151.125202	1		notify business/property owner	AF82	Secondary	CW	\$ -
OB580	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrow footpath - property	-33.880334	151.153228	1		notify business/property owner	UH6	Tertiary	CW	\$ -
OB581	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrow footpath	-33.880319	151.153504	1		refer to maintenance	UH7	Secondary	CW	\$ -
OB582	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrow footpath	-33.879869	151.153129	1		refer to maintenance	UH1	Secondary	CW	\$ -
OB583	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrow footpath	-33.879869	151.15334	1		refer to maintenance	UH1	Secondary	CW	\$ -
OB584	Balmoral Road	Leichhardt	Regional Road	obstruction	overhanging vegetation narrow footpath - property	-33.880023	151.156923	1		notify business/property owner	UH11	Primary	CW	\$ -
OB585	Balmoral Road	Leichhardt	Regional Road											

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB587	Balmain Road	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.88322	151.15067	1		notify business/property owner	LH17	Primary	LOW	\$	-
OB588	James Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87592	151.15531	1		refer to maintenance	LH114	Primary	LOW	\$	-
OB589	James Street	Leichhardt	State Road	obstruction	signpost narrows footpath	-33.87579	151.15518	1		relocate signpost	L138	Secondary	LOW	\$	300
OB59	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.90418	151.12479	1		refer to maintenance	HP1	Secondary	LOW	\$	-
OB590	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87503	151.15394	1		refer to maintenance	LH32	Secondary	LOW	\$	-
OB591	James Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87524	151.15485	1		refer to maintenance	LH31	Secondary	LOW	\$	-
OB592	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.87521	151.15263	1		notify business/property owner	LH33	Secondary	LOW	\$	-
OB593	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87556	151.152381	1		refer to maintenance	LH34	Secondary	LOW	\$	-
OB594	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87505	151.15228	1		refer to maintenance	LH34	Secondary	LOW	\$	-
OB595	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.87545	151.15147	1		notify business/property owner	LH35	Secondary	LOW	\$	-
OB596	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.87681	151.14963	1		notify business/property owner	LH37	Secondary	LOW	\$	-
OB597	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87744	151.14954	1		refer to maintenance	LH38	Secondary	LOW	\$	-
OB598	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.87778	151.14873	1		notify business/property owner	LH39	Secondary	LOW	\$	-
OB599	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.87745	151.148474	1		notify business/property owner	LH39	Secondary	LOW	\$	-
OB6	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87859	151.174572	1		notify business/property owner	AN69	Secondary	LOW	\$	-
OB60	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.90465	151.124507	1		refer to maintenance	HP1	Secondary	LOW	\$	-
OB600	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87681	151.14836	1		refer to maintenance	LH40	Secondary	LOW	\$	-
OB601	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.87908	151.147841	1		refer to maintenance	LH40	Secondary	LOW	\$	-
OB602	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.879407	151.14779	1		notify business/property owner	LH30	Secondary	LOW	\$	-
OB603	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.88023	151.147697	1		notify business/property owner	LH69	Secondary	LOW	\$	-
OB604	Darley Road	Leichhardt	State Road	obstruction	bollard narrows footpath	-33.88027	151.147521	1		relocate bollard	LH30	Secondary	LOW	\$	2,500
OB605	Derbyshire Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.88067	151.158717	1		refer to maintenance	LH44	Primary	LOW	\$	-
OB606	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.88248	151.152092	1		notify business/property owner	LH45	Tertiary	LOW	\$	-
OB607	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.887138	151.152817	1		notify business/property owner	LH54	Tertiary	LOW	\$	-
OB608	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.888367	151.153054	1		refer to maintenance	LH53	Secondary	LOW	\$	-
OB609	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881798	151.152865	1		notify business/property owner	LH51	Tertiary	LOW	\$	-
OB61	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.90514	151.123244	1		refer to maintenance	HP1	Secondary	LOW	\$	-
OB610	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.881056	151.151924	1		notify business/property owner	LH59	Tertiary	LOW	\$	-
OB611	Elswick Street	Leichhardt	Local Road	obstruction	structure narrows footpath	-33.886675	151.153029	1		re-align kerb and footpath	LH53	Secondary	LOW	\$	7,500
OB612	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881928	151.151914	1		refer to maintenance	LH51	Tertiary	LOW	\$	-
OB613	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.883415	151.151917	1		refer to maintenance	LH54	Tertiary	LOW	\$	-
OB614	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.887978	151.152806	1		notify business/property owner	LH54	Tertiary	LOW	\$	-
OB615	Elswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.886896	151.152519	1		refer to maintenance	LH55	Tertiary	LOW	\$	-
OB616	Elswick Street	Leichhardt	Local Road	obstruction	vehicle narrows footpath	-33.886813	151.152257	1		no action	LH56	Tertiary	LOW	\$	-
OB617	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.878546	151.151898	1		refer to maintenance	LH48	Secondary	LOW	\$	-
OB618	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.878121	151.151962	1		refer to maintenance	LH47	Secondary	LOW	\$	-
OB619	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.887789	151.149421	1		notify business/property owner	LH58	Tertiary	LOW	\$	-
OB62	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905727	151.123843	1		notify business/property owner	LH57	Secondary	LOW	\$	-
OB620	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.888197	151.14948	1		refer to maintenance	LH58	Tertiary	LOW	\$	-
OB621	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.887659	151.149593	1		refer to maintenance	LH60	Secondary	LOW	\$	-
OB622	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886771	151.149724	1		refer to maintenance	LH59	Secondary	LOW	\$	-
OB623	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886482	151.149852	1		refer to maintenance	LH59	Secondary	LOW	\$	-
OB624	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.886159	151.149838	1		notify business/property owner	LH59	Secondary	LOW	\$	-
OB625	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878341	151.150194	1		notify business/property owner	LH63	Tertiary	LOW	\$	-
OB626	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878681	151.150194	1		notify business/property owner	LH63	Tertiary	LOW	\$	-
OB627	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878843	151.150185	1		notify business/property owner	LH63	Tertiary	LOW	\$	-
OB628	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879173	151.150173	1		notify business/property owner	LH64	Tertiary	LOW	\$	-
OB629	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879658	151.150119	1		notify business/property owner	LH64	Tertiary	LOW	\$	-
OB63	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905848	151.123744	1		refer to maintenance	LH59	Secondary	LOW	\$	-
OB630	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.879968	151.150116	1		notify business/property owner	LH64	Tertiary	LOW	\$	-
OB631	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880046	151.150147	1		notify business/property owner	LH65	Tertiary	LOW	\$	-
OB632	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.881269	151.150129	1		refer to maintenance	LH65	Tertiary	LOW	\$	-
OB633	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881698	151.150105	1		refer to maintenance	LH66	Tertiary	LOW	\$	-
OB634	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881799	151.150131	1		refer to maintenance	LH66	Tertiary	LOW	\$	-
OB635	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.882603	151.150111	1		notify business/property owner	LH66	Tertiary	LOW	\$	-
OB636	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.882799	151.150029	1		refer to maintenance	LH66	Tertiary	LOW	\$	-
OB637	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.8832	151.150095	1		notify business/property owner	LH67	Secondary	LOW	\$	-
OB638	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.885225	151.15009	1		refer to maintenance	LH62	Secondary	LOW	\$	-
OB639	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.88444	151.150042	1		refer to maintenance	LH62	Secondary	LOW	\$	-
OB64	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877407	151.124356	1		refer to maintenance	AF41	Tertiary	LOW	\$	-
OB640	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.883612	151.149928	1		refer to maintenance	LH67	Secondary	LOW	\$	-
OB641	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883284	151.149934	1		notify business/property owner	LH67	Secondary	LOW	\$	-
OB642	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.883453	151.149929	1		refer to maintenance	LH67	Secondary	LOW	\$	-
OB643	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.882763	151.149954	1		notify business/property owner	LH67	Tertiary	LOW	\$	-
OB644	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.882268	151.149935	1		refer to maintenance	LH66	Tertiary	LOW	\$	-
OB645	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882249	151.149932	1		notify business/property owner	LH66	Tertiary	LOW	\$	-
OB646	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.881921	151.149959	1		notify business/property owner	LH66	Tertiary	LOW	\$	-
OB647	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.881504	151.149961	1		notify business/property owner	LH65	Tertiary	LOW	\$	-
OB648	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878248	151.149916	1		notify business/property owner	LH64	Tertiary	LOW	\$	-
OB649	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.878662	151.14991	1		notify business/property owner	LH63	Tertiary	LOW	\$	-
OB65	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877201	151.124231	1		notify business/property owner	AF41	Tertiary	LOW	\$	-
OB650	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878192	151.149992	1		notify business/property owner	LH63	Tertiary	LOW	\$	-
OB651	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.877823	151.150017	1		notify business/property owner	LH63	Tertiary	LOW	\$	-
OB652	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877793	151.150019	1		refer to maintenance	LH63	Tertiary	LOW	\$	-
OB653	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation - property	-33.880847	151.147545	1		notify business/property owner	LH69	Secondary	LOW	\$	-
OB654	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.881122	151.147545	1		notify business/property owner	LH69	Secondary	LOW	\$	-
OB655	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.882046	151.147542	1		notify business/property owner	HP2	Secondary	LOW	\$	-
OB656	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.882409	151.147543	1		refer to maintenance	LH70	Secondary	LOW	\$	-
OB657	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.885053	151.147575	1		notify business/property owner	LH68	Primary	LOW	\$	-
OB658	Greenway	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886156	151.144726	1		refer to maintenance	LH71	Tertiary	LOW	\$	-
OB659	Hawthorne Light Rail Station	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.87956	151.147088	1		refer to maintenance	LH79	Secondary	LOW	\$	-
OB66	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87746	151.12478	1		notify business/property owner	AF42	Tertiary	LOW	\$	-
OB660	Hawthorne Light Rail Station	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880024	151.146971	1		refer to maintenance	LH81	Secondary	LOW	\$	-
OB661	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.885529	151.146929	1		refer to maintenance	LH89	Primary	LOW	\$	-
OB662	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886289	151.145601	1		refer to maintenance	LH86	Secondary	LOW	\$	-
OB663	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.885835	151.14812	1		notify business/property owner	LH88	Secondary	LOW	\$	-
OB664	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886088	151.148117	1		refer to maintenance	LH89	Secondary	LOW	\$	-
OB665	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.886194	151.145909	1		notify business/property owner	LH86	Secondary	LOW	\$	-
OB666	Mackenzie Street	Leichhardt	Local Road	obstruction	signpost narrows footpath	-33.883719	151.161297	1		relocate signpost	LH90	Secondary	LOW	\$	300
OB667	Mackenzie Street	Leichhardt	Local Road												

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB672	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation - property	-33.884134	151.152196	-	-	notify business/property owner	LH86	Secondary	LOW	S	-
OB674	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation - property	-33.884107	151.149487	-	-	notify business/property owner	LH87	Secondary	LOW	S	-
OB674	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation - property	-33.884182	151.144844	-	-	notify business/property owner	HA61	Primary	LOW	S	-
OB675	Marion Street	Leichhardt	Regional Road	obstruction	signpost narrows footpath	-33.884235	151.144712	-	-	relocate signpost	HA61	Primary	LOW	S	-
OB676	Marion Street	Leichhardt	Regional Road	obstruction	bus shelter narrows footpath	-33.884085	151.147167	-	-	upgrade or remove bus shelter	LH83	Primary	LOW	S	300
OB677	Moore Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.879652	151.161396	-	-	notify business/property owner	LH104	Secondary	LOW	S	-
OB678	Norton Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.886902	151.157415	-	-	refer to maintenance	LH115	Primary	LOW	S	-
OB679	Norton Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.886506	151.157361	-	-	refer to maintenance	LH116	Secondary	LOW	S	-
OB679	Norton Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.886718	151.157291	-	-	refer to maintenance	HA47	Primary	LOW	S	-
OB680	Norton Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.885421	151.157185	-	-	refer to maintenance	LH117	Primary	LOW	S	-
OB681	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880649	151.156594	-	-	refer to maintenance	LH122	Primary	LOW	S	-
OB682	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.876722	151.156432	-	-	refer to maintenance	LH123	Primary	LOW	S	-
OB683	Norton Street	Leichhardt	Local Road	obstruction	damaged bollard narrows footpath	-33.877289	151.156345	-	-	repair bollard	LH170	Secondary	LOW	S	2,500
OB684	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.876061	151.156248	-	-	refer to maintenance	LH127	Primary	LOW	S	-
OB685	Norton Street	Leichhardt	Local Road	obstruction	bus shelter and signpost narrows footpath	-33.879626	151.156172	-	-	relocate signpost	LH127	Primary	LOW	S	-
OB686	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879727	151.155828	-	-	notify business/property owner	LH127	Primary	LOW	S	-
OB687	Parramatta Road	Leichhardt	State Road	obstruction	double pole signpost narrows footpath	-33.889362	151.150095	-	-	review and relocate double pole signpost	LH136	Primary	LOW	S	500
OB688	Styies Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882655	151.166402	-	-	notify business/property owner	AN33	Secondary	LOW	S	-
OB689	Styies Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883083	151.166348	-	-	notify business/property owner	LH129	Secondary	LOW	S	-
OB690	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.88043	151.126552	-	-	refer to maintenance	AF49	Tertiary	LOW	S	-
OB690	Styies Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883067	151.163769	-	-	notify business/property owner	LH148	Secondary	LOW	S	-
OB691	Styies Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882965	151.164459	-	-	notify business/property owner	LH148	Secondary	LOW	S	-
OB692	Styies Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.883731	151.165346	-	-	refer to maintenance	AN33	Secondary	LOW	S	-
OB693	Styies Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883026	151.164084	-	-	notify business/property owner	LH148	Secondary	LOW	S	-
OB694	Styies Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882997	151.164361	-	-	no action	LH148	Secondary	LOW	S	-
OB695	Styies Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882688	151.166106	-	-	no action	LH150	Secondary	LOW	S	-
OB696	Styies Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882911	151.165884	-	-	no action	LH150	Secondary	LOW	S	-
OB697	Styies Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882777	151.165151	-	-	no action	LH150	Secondary	LOW	S	-
OB698	Styies Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.88261	151.165194	-	-	no action	LH151	Secondary	LOW	S	-
OB699	Styies Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882819	151.165204	-	-	notify business/property owner	LH151	Secondary	LOW	S	-
OB7	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879637	151.174748	-	-	refer to maintenance	AN69	Secondary	LOW	S	-
OB70	Cissold Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895814	151.130461	-	-	notify business/property owner	AF51	Secondary	LOW	S	-
OB701	Styies Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.883022	151.164475	-	-	no action	LH148	Secondary	LOW	S	-
OB702	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.891918	151.144901	-	-	notify business/property owner	LH152	Primary	LOW	S	-
OB702	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.88902	151.147055	-	-	notify business/property owner	LH155	Secondary	LOW	S	-
OB703	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.887936	151.147312	-	-	notify business/property owner	LH154	Secondary	LOW	S	-
OB704	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.887711	151.147368	-	-	notify business/property owner	LH154	Secondary	LOW	S	-
OB705	White Creek	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885274	151.164763	-	-	notify business/property owner	LH160	Secondary	LOW	S	-
OB706	White Creek	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885079	151.164802	-	-	notify business/property owner	LH160	Secondary	LOW	S	-
OB707	White Creek	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885883	151.164761	-	-	notify business/property owner	LH159	Secondary	LOW	S	-
OB708	White Creek Lane	Leichhardt	Local Road	obstruction	vehicles narrows footpath	-33.884633	151.165131	-	-	no action	LH166	Secondary	LOW	S	-
OB709	White Creek Lane	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881351	151.166567	-	-	notify business/property owner	LH166	Secondary	LOW	S	-
OB71	Cissold Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89559	151.127182	-	-	notify business/property owner	AF48	Secondary	LOW	S	-
OB710	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877384	151.157389	-	-	refer to maintenance	LH175	Secondary	LOW	S	-
OB711	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877334	151.157543	-	-	refer to maintenance	LH170	Secondary	LOW	S	-
OB712	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877334	151.157647	-	-	refer to maintenance	LH169	Secondary	LOW	S	-
OB713	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.87734	151.157752	-	-	refer to maintenance	LH169	Secondary	LOW	S	-
OB714	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877342	151.157813	-	-	refer to maintenance	LH169	Secondary	LOW	S	-
OB715	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877344	151.157932	-	-	refer to maintenance	LH169	Secondary	LOW	S	-
OB716	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877231	151.156235	-	-	refer to maintenance	LH169	Secondary	LOW	S	-
OB717	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877246	151.15719	-	-	refer to maintenance	LH169	Secondary	LOW	S	-
OB718	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877289	151.157255	-	-	notify business/property owner	LH174	Secondary	LOW	S	-
OB719	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877766	151.152476	-	-	notify business/property owner	LH167	Secondary	LOW	S	-
OB72	Cissold Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895631	151.126774	-	-	notify business/property owner	AF49	Secondary	LOW	S	-
OB720	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877666	151.152334	-	-	notify business/property owner	LH174	Secondary	LOW	S	-
OB721	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877692	151.152172	-	-	notify business/property owner	LH173	Secondary	LOW	S	-
OB722	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877716	151.151058	-	-	notify business/property owner	LH173	Secondary	LOW	S	-
OB723	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877911	151.150969	-	-	refer to maintenance	LH173	Secondary	LOW	S	-
OB724	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877627	151.149519	-	-	refer to maintenance	LH172	Secondary	LOW	S	-
OB725	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877501	151.14962	-	-	refer to maintenance	LH172	Secondary	LOW	S	-
OB726	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87739	151.14952	-	-	notify business/property owner	LH172	Secondary	LOW	S	-
OB727	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.87731	151.149584	-	-	refer to maintenance	LH172	Secondary	LOW	S	-
OB728	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877411	151.149639	-	-	notify business/property owner	LH172	Secondary	LOW	S	-
OB729	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877551	151.150066	-	-	refer to maintenance	LH172	Secondary	LOW	S	-
OB73	Cissold Street	Ashfield	Local Road	obstruction	signposts narrows footpath	-33.895662	151.126064	-	-	relocate signpost	AF50	Secondary	LOW	S	300
OB730	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.877629	151.150156	-	-	notify business/property owner	LH173	Secondary	LOW	S	-
OB731	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877789	151.151267	-	-	refer to maintenance	LH173	Secondary	LOW	S	-
OB732	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877733	151.151597	-	-	refer to maintenance	LH173	Secondary	LOW	S	-
OB733	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877329	151.150737	-	-	refer to maintenance	LH175	Secondary	LOW	S	-
OB734	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877305	151.150688	-	-	refer to maintenance	LH175	Secondary	LOW	S	-
OB735	Carrington Road	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.891402	151.147883	-	-	refer to maintenance	LW28	Secondary	LOW	S	-
OB736	Carrington Street	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890828	151.147699	-	-	notify business/property owner	LW28	Secondary	LOW	S	-
OB737	Reggie Street	Lewisham	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.892689	151.148964	-	-	notify business/property owner	LW28	Secondary	LOW	S	-
OB738	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath	-33.897065	151.147734	-	-	refer to maintenance	LW13	Primary	LOW	S	-
OB739	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation - property	-33.897363	151.147625	-	-	notify business/property owner	LW13	Primary	LOW	S	-
OB740	New Canterbury Road	Lewisham	State Road	obstruction	signposts narrows footpath	-33.898704	151.129564	-	-	relocate signpost	AF54	Secondary	LOW	S	300
OB740	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation - property	-33.897677	151.147168	-	-	notify business/property owner	LW13	Primary	LOW	S	-
OB741	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath	-33.898369	151.146304	-	-	refer to maintenance	LW15	Primary	LOW	S	-
OB742	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.898915	151.145611	-	-	notify business/property owner	LW16	Primary	LOW	S	-
OB743	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath	-33.899125	151.145392	-	-	refer to maintenance	LW16	Primary	LOW	S	-
OB744	Wardell Road	Lewisham	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.898564	151.145418	-	-	refer to maintenance	LW39	Secondary	LOW	S	-
OB746	Thomas Street	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891968	151.147687	-	-	notify business/property owner	LW33	Primary	LOW	S	-
OB747	Thomas Street	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.893233	151.148029	-	-	refer to maintenance	LW35	Primary	LOW	S	-
OB748	Tootill Street	Lewisham	Regional Road	obstruction	double pole signpost narrows footpath	-33.89702	151.146533	-	-	review and relocate double pole signpost	LW35	Secondary	LOW	S	500
OB748	Tootill Street	Lewisham	Regional Road	obstruction	signposts narrows footpath	-33.897168	151.146693	-	-	relocate signpost	LW35	Secondary	LOW	S	300
OB749	Tootill Street	Lewisham	Regional Road	obstruction	double pole signpost narrows footpath	-33.897148	151.146712	-	-	review and relocate double pole signpost	LW35	Secondary	LOW	S	500
OB75	Old Canterbury Road	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895882	151.129213	-	-	notify business/property owner	AF59	Secondary	LOW	S	-
OB750	Old Canterbury Road	Lewisham	State Road	obstruction	power pole narrows footpath	-33.89309	151.145886	-	-	no action	LW18	Secondary	LOW	S	-
OB751	Trafalgar Street	Lewisham	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.892952	151.145657	-	-	refer to maintenance	LW22	Primary	LOW	S	-
OB752	Railway Terrace	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.893866	151.145338	-	-	notify business/property owner	LW24	Primary	LOW	S	-
OB753	Balmoral Road	Lewisham	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.876889	151.160788	-	-	refer to maintenance	LW15	Secondary	LOW	S	-
OB754	Balmoral Road	Lewisham	Regional Road	obstruction	power pole narrows footpath	-33.876182	151.160735</								

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB758	Balmain Road	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.870271	151.161744	1		notify business/property owner	LF8	Secondary	LOW	\$	-
OB759	Balmain Road	Lilyfield	State Road	obstruction	power pole narrows footpath	-33.869514	151.162951	1		no action	LF2	Secondary	LOW	\$	-
OB76	Clissold Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869548	151.126958	1		notify business/property owner	AF48	Secondary	LOW	\$	-
OB760	Balmain Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873334	151.160227	1		refer to maintenance	LF9	Secondary	LOW	\$	-
OB761	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.872332	151.161135	1		refer to maintenance	LF13	Tertiary	LOW	\$	-
OB762	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872263	151.161253	1		notify business/property owner	LF13	Tertiary	LOW	\$	-
OB763	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.872338	151.161435	1		refer to maintenance	LF13	Secondary	LOW	\$	-
OB764	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.86724	151.152262	1		refer to maintenance	LF24	Secondary	LOW	\$	-
OB765	Catherine Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87051	151.164842	1		notify business/property owner	LF40	Primary	LOW	\$	-
OB766	City West Link Bridge	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.874587	151.154895	1		refer to maintenance	LF58	Secondary	LOW	\$	-
OB767	Darley Road	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.875382	151.152646	1		notify business/property owner	UH33	Secondary	LOW	\$	-
OB768	Glover Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869779	151.156685	1		notify business/property owner	LF50	Secondary	LOW	\$	-
OB769	Glover Street	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.869878	151.156606	1		notify business/property owner	LF50	Secondary	LOW	\$	-
OB77	Clissold Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.869558	151.127214	1		notify business/property owner	AF48	Secondary	LOW	\$	-
OB770	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.871561	151.16408	1		refer to maintenance	LF55	Tertiary	LOW	\$	-
OB771	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872152	151.16432	1		notify business/property owner	LF55	Tertiary	LOW	\$	-
OB772	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872322	151.164373	1		notify business/property owner	LF54	Secondary	LOW	\$	-
OB773	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872779	151.164541	1		notify business/property owner	LF54	Secondary	LOW	\$	-
OB774	Grove Street	Lilyfield	Local Road	obstruction	signpost narrows footpath	-33.869619	151.163504	1		relocate signpost	LF53	Secondary	LOW	\$	300
OB775	Grove Street	Lilyfield	Local Road	obstruction	signpost narrows footpath	-33.869213	151.163257	1		relocate signpost	LF53	Secondary	LOW	\$	300
OB776	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869636	151.163536	1		notify business/property owner	LF53	Secondary	LOW	\$	-
OB777	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.870233	151.163608	1		refer to maintenance	LF56	Tertiary	LOW	\$	-
OB778	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.871071	151.163917	1		refer to maintenance	LF56	Tertiary	LOW	\$	-
OB779	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.874012	151.155168	1		notify business/property owner	LF58	Secondary	LOW	\$	-
OB78	Clissold Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869558	151.128896	1		notify business/property owner	AF50	Secondary	LOW	\$	-
OB780	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.873775	151.155137	1		notify business/property owner	LF58	Secondary	LOW	\$	-
OB781	James Street	Lilyfield	State Road	obstruction	overhanging vegetation - property	-33.87388	151.155144	1		notify business/property owner	LF58	Secondary	LOW	\$	-
OB782	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.874194	151.155258	1		notify business/property owner	LF58	Secondary	LOW	\$	-
OB783	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.874441	151.155054	1		notify business/property owner	LF59	Secondary	LOW	\$	-
OB784	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.874189	151.155028	1		notify business/property owner	LF58	Secondary	LOW	\$	-
OB785	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.874027	151.155057	1		refer to maintenance	LF58	Secondary	LOW	\$	-
OB786	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.873879	151.154994	1		refer to maintenance	LF58	Secondary	LOW	\$	-
OB787	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.873584	151.154951	1		notify business/property owner	LF58	Secondary	LOW	\$	-
OB788	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.872046	151.163203	1		notify business/property owner	LF74	Secondary	LOW	\$	-
OB789	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873187	151.162501	1		refer to maintenance	LF74	Secondary	LOW	\$	-
OB79	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.868029	151.128896	1		notify business/property owner	AF62	Primary	LOW	\$	-
OB790	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873136	151.163595	1		refer to maintenance	LF71	Secondary	LOW	\$	-
OB791	Lilyfield Road	Lilyfield	Regional Road	obstruction	power pole narrows footpath	-33.872745	151.163117	1		no action	LF73	Secondary	LOW	\$	-
OB792	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.872652	151.167475	1		refer to maintenance	LF73	Secondary	LOW	\$	-
OB793	Lilyfield Road	Lilyfield	Regional Road	obstruction	double pole signpost narrows footpath	-33.871098	151.16877	1		relocate signpost	LF75	Secondary	LOW	\$	300
OB794	Lilyfield Road	Lilyfield	Regional Road	obstruction	power pole narrows path	-33.871775	151.16922	1		no action	LF75	Secondary	LOW	\$	-
OB795	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873421	151.163703	1		refer to maintenance	LF68	Secondary	LOW	\$	-
OB796	Lilyfield Road	Lilyfield	Regional Road	obstruction	signposts narrows footpath	-33.873217	151.164338	1		relocate signpost	LF68	Secondary	LOW	\$	300
OB797	Lilyfield Road	Lilyfield	Regional Road	obstruction	double pole signpost narrows footpath	-33.873055	151.163396	1		review and relocate double pole signpost	LF68	Secondary	LOW	\$	500
OB798	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.87329	151.162934	1		refer to maintenance	LF70	Secondary	LOW	\$	-
OB799	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873597	151.162346	1		refer to maintenance	LF70	Secondary	LOW	\$	-
OB8	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878903	151.175089	1		notify business/property owner	AN68	Secondary	LOW	\$	-
OB80	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.867721	151.126962	1		notify business/property owner	AF52	Primary	LOW	\$	-
OB800	Lilyfield Road	Lilyfield	Regional Road	obstruction	power pole narrows footpath	-33.873414	151.162121	1		refer to maintenance	LF64	Tertiary	LOW	\$	-
OB801	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.874315	151.160396	1		notify business/property owner	LF64	Tertiary	LOW	\$	-
OB802	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.874273	151.15797	1		notify business/property owner	LF67	Secondary	LOW	\$	-
OB803	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.874397	151.158322	1		notify business/property owner	LF67	Secondary	LOW	\$	-
OB804	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.874195	151.157562	1		refer to maintenance	LF66	Secondary	LOW	\$	-
OB805	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873881	151.156454	1		notify business/property owner	LF65	Secondary	LOW	\$	-
OB806	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873539	151.156337	1		notify business/property owner	LF65	Secondary	LOW	\$	-
OB807	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.874469	151.154889	1		notify business/property owner	LF63	Secondary	LOW	\$	-
OB808	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873181	151.153884	1		notify business/property owner	LF60	Tertiary	LOW	\$	-
OB809	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.873135	151.153755	1		refer to maintenance	LF60	Tertiary	LOW	\$	-
OB81	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.86839	151.129217	1		notify business/property owner	AF63	Secondary	LOW	\$	-
OB810	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.872746	151.152398	1		notify business/property owner	LF61	Tertiary	LOW	\$	-
OB811	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.872322	151.151512	1		refer to maintenance	LF13	Tertiary	LOW	\$	-
OB812	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.873253	151.154655	1		refer to maintenance	LF63	Secondary	LOW	\$	-
OB813	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.873565	151.155699	1		notify business/property owner	LF65	Secondary	LOW	\$	-
OB814	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873889	151.156934	1		notify business/property owner	LF66	Secondary	LOW	\$	-
OB815	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation	-33.873998	151.157295	1		refer to maintenance	LF66	Secondary	LOW	\$	-
OB816	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation	-33.8743	151.158447	1		refer to maintenance	LF67	Secondary	LOW	\$	-
OB817	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation	-33.8743	151.158545	1		refer to maintenance	LF67	Secondary	LOW	\$	-
OB818	Mary Street	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.870898	151.154604	1		notify business/property owner	LF85	Tertiary	LOW	\$	-
OB819	Mary Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.872722	151.155718	1		notify business/property owner	LF79	Secondary	LOW	\$	-
OB82	Elizabeth Street	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.873842	151.129241	1		refer to maintenance	AF63	Secondary	LOW	\$	-
OB820	Perry Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.872327	151.155654	1		refer to maintenance	LF87	Secondary	LOW	\$	-
OB821	Piper Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876763	151.155991	1		notify business/property owner	LF95	Tertiary	LOW	\$	-
OB822	Piper Street	Lilyfield	Local Road	obstruction	power pole narrows footpath	-33.876763	151.157182	1		no action	LF95	Tertiary	LOW	\$	-
OB823	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918358	151.154686	1		refer to maintenance	MV250	Tertiary	LOW	\$	-
OB824	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.918475	151.154905	1		notify business/property owner	MV247	Tertiary	LOW	\$	-
OB825	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918735	151.154928	1		refer to maintenance	MV247	Tertiary	LOW	\$	-
OB826	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918278	151.154346	1		notify business/property owner	MV250	Tertiary	LOW	\$	-
OB827	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.91814	151.1541	1		notify business/property owner	MV250	Tertiary	LOW	\$	-
OB828	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918054	151.154007	1		notify business/property owner	MV250	Tertiary	LOW	\$	-
OB829	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.916709	151.153153	1		refer to maintenance	MV248	Secondary	LOW	\$	-
OB83	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.888726	151.129849	1		notify business/property owner	AF63	Secondary	LOW	\$	-
OB830	Warren Road	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.914731	151.148018	1		no action	MV244	Secondary	LOW	\$	-
OB831	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914038	151.146978	1		notify business/property owner	MV243	Secondary	LOW	\$	-
OB832	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.91398	151.146752	1		notify business/property owner	MV243	Secondary	LOW	\$	-
OB833	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911539	151.145537	1		refer to maintenance	MV13	Tertiary	LOW	\$	-
OB834	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.911508	151.145188	1		notify business/property owner	MV13	Tertiary	LOW	\$	-
OB835	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911571	151.145329	1		refer to maintenance	MV13	Tertiary	LOW	\$	-
OB836	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.912495	151.146797	1		refer to maintenance	MV12	Tertiary	LOW	\$	-
OB837	Beauchamp Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914656	151.143099	1		refer to maintenance	MV16	Secondary	LOW	\$	-
OB838	Beauchamp Street	Marrickville	Local Road	obstruction</											

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
OB843	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913369	151.158205	1		notify business/property owner	MV22	Secondary	CW	\$	-
OB844	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.91349	151.158476	1		notify business/property owner	MV22	Secondary	CW	\$	-
OB845	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.913547	151.158594	1		refer to maintenance	MV22	Secondary	CW	\$	-
OB846	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913007	151.15781	1		notify business/property owner	MV19	Secondary	CW	\$	-
OB847	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912872	151.157536	1		refer to maintenance	MV19	Secondary	CW	\$	-
OB848	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.912276	151.15643	1		notify business/property owner	MV21	Secondary	CW	\$	-
OB849	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.911941	151.155923	1		notify business/property owner	MV20	Secondary	CW	\$	-
OB85	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.888888	151.13069	1		notify business/property owner	AF64	Secondary	CW	\$	-
OB850	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.911844	151.155746	1		notify business/property owner	MV20	Secondary	CW	\$	-
OB851	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911709	151.155533	1		refer to maintenance	MV20	Secondary	CW	\$	-
OB852	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.912146	151.156149	1		notify business/property owner	MV20	Secondary	CW	\$	-
OB853	Carrington Road	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.916391	151.158055	1		notify business/property owner	MV26	Tertiary	CW	\$	-
OB854	Chapel Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905851	151.162287	1		notify business/property owner	MV31	Secondary	CW	\$	-
OB855	Chapel Street	Marrickville	Local Road	obstruction	double pole signpost narrows footpath	-33.905048	151.162876	1		review and relocate double pole signpost	MV32	Secondary	CW	\$	500
OB856	Edgeware Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.905259	151.173349	1		notify business/property owner	NE24	Primary	CW	\$	-
OB857	Edinburgh Road	Marrickville	Local Road	obstruction	tree narrows footpath	-33.907881	151.170541	1		no action	MV58	Secondary	CW	\$	-
OB858	Edinburgh Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908046	151.170639	1		notify business/property owner	MV57	Secondary	CW	\$	-
OB859	Edinburgh Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907463	151.169585	1		notify business/property owner	MV57	Secondary	CW	\$	-
OB86	Elizabeth Street	Ashfield	Regional Road	obstruction	signpost narrows footpath	-33.889164	151.131611	1		relocate signpost	AF61	Secondary	CW	\$	300
OB860	Edinburgh Road	Marrickville	Local Road	obstruction	bollards narrows footpath	-33.90706	151.169123	1		widen footpath	MV56	Tertiary	CW	\$	200
OB861	Edinburgh Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905777	151.167442	1		refer to maintenance	MV54	Tertiary	CW	\$	-
OB862	Elizabeth Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.909007	151.162856	1		notify business/property owner	MV210	Secondary	CW	\$	-
OB863	Ewart Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.912294	151.140312	1		notify business/property owner	MV68	Primary	CW	\$	-
OB864	Ewart Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914043	151.142158	1		notify business/property owner	MV68	Secondary	CW	\$	-
OB865	Ewart Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914248	151.142406	1		notify business/property owner	MV68	Secondary	CW	\$	-
OB866	Fitzroy Street	Marrickville	Local Road	obstruction	power pole narrows footpath	-33.908195	151.167324	1		no action	MV71	Tertiary	CW	\$	-
OB867	Fitzroy Street	Marrickville	Local Road	obstruction	power pole narrows footpath	-33.90857	151.165729	1		no action	MV69	Tertiary	CW	\$	-
OB868	Fitzroy Street	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.911921	151.165911	1		no action	MV204	Secondary	CW	\$	-
OB869	Fitzroy Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.909096	151.168475	1		notify business/property owner	MV70	Tertiary	CW	\$	-
OB87	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.888224	151.129167	1		notify business/property owner	AF63	Secondary	CW	\$	-
OB870	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901293	151.152078	1		refer to maintenance	MV75	Secondary	CW	\$	-
OB871	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901188	151.150575	1		notify business/property owner	MV76	Secondary	CW	\$	-
OB872	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901119	151.149385	1		notify business/property owner	FE20	Secondary	CW	\$	-
OB873	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901098	151.149359	1		notify business/property owner	FE20	Secondary	CW	\$	-
OB874	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.901033	151.150025	1		refer to maintenance	MV76	Secondary	CW	\$	-
OB875	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.901033	151.150025	1		refer to maintenance	MV76	Secondary	CW	\$	-
OB876	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.901051	151.150767	1		refer to maintenance	MV76	Secondary	CW	\$	-
OB877	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901063	151.151321	1		refer to maintenance	MV75	Secondary	CW	\$	-
OB878	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901189	151.153019	1		notify business/property owner	MV75	Secondary	CW	\$	-
OB879	Hawthurst Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.905598	151.153888	1		refer to maintenance	MV78	Secondary	CW	\$	-
OB88	Frederick Street	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.862457	151.162489	1		notify business/property owner	AF74	Secondary	CW	\$	-
OB880	Hawthurst Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905103	151.155460	1		notify business/property owner	MV29	Secondary	CW	\$	-
OB881	Hawthurst Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.904655	151.156262	1		refer to maintenance	MV29	Secondary	CW	\$	-
OB882	Hawthurst Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905392	151.155274	1		refer to maintenance	MV29	Secondary	CW	\$	-
OB883	Hawthurst Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905774	151.149881	1		notify business/property owner	MV78	Secondary	CW	\$	-
OB884	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907348	151.159417	1		notify business/property owner	MV82	Tertiary	CW	\$	-
OB885	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906955	151.159774	1		notify business/property owner	MV82	Tertiary	CW	\$	-
OB886	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906966	151.159597	1		notify business/property owner	MV82	Tertiary	CW	\$	-
OB887	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906887	151.159662	1		notify business/property owner	MV82	Tertiary	CW	\$	-
OB888	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906011	151.160423	1		notify business/property owner	MV84	Secondary	CW	\$	-
OB889	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905914	151.160508	1		notify business/property owner	MV84	Secondary	CW	\$	-
OB89	Frederick Street	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.860331	151.152189	1		notify business/property owner	AF71	Primary	CW	\$	-
OB890	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.904599	151.161714	1		refer to maintenance	MV79	Secondary	CW	\$	-
OB891	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.904566	151.161568	1		notify business/property owner	MV79	Secondary	CW	\$	-
OB892	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.904464	151.161846	1		notify business/property owner	MV79	Secondary	CW	\$	-
OB893	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.903943	151.162445	1		notify business/property owner	MV86	Tertiary	CW	\$	-
OB894	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.903184	151.162686	1		refer to maintenance	MV86	Tertiary	CW	\$	-
OB895	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902905	151.162882	1		refer to maintenance	MV85	Secondary	CW	\$	-
OB896	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902751	151.162976	1		refer to maintenance	MV85	Secondary	CW	\$	-
OB897	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902736	151.163059	1		refer to maintenance	MV85	Secondary	CW	\$	-
OB898	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.902851	151.158432	1		notify business/property owner	MV87	Tertiary	CW	\$	-
OB899	Ilwara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908509	151.158371	1		notify business/property owner	MV81	Secondary	CW	\$	-
OB9	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87628	151.175276	1		notify business/property owner	AN67	Secondary	CW	\$	-
OB90	Frederick Street	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.87717	151.12922	1		refer to maintenance	AF68	Secondary	CW	\$	-
OB900	Ilwara Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.916736	151.149111	1		notify business/property owner	MV97	Primary	CW	\$	-
OB901	Ilwara Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.919828	151.145448	1		refer to maintenance	MV101	Secondary	CW	\$	-
OB902	Ilwara Road	Marrickville	Regional Road	obstruction	signpost narrows footpath	-33.920616	151.144739	1		relocate signpost	MV102	Secondary	CW	\$	300
OB903	Ilwara Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.919951	151.144795	1		notify business/property owner	MV102	Secondary	CW	\$	-
OB904	Ilwara Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.917379	151.148605	1		notify business/property owner	MV98	Primary	CW	\$	-
OB905	Ilwara Road	Marrickville	Regional Road	obstruction	signpost narrows footpath	-33.917674	151.143691	1		relocate signpost	MV101	Secondary	CW	\$	300
OB906	Kaye Avenue	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911376	151.144374	1		refer to maintenance	MV105	Tertiary	CW	\$	-
OB907	Livingsstone Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.901722	151.153469	1		refer to maintenance	PE27	Primary	CW	\$	-
OB908	Livingsstone Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.89556	151.153222	1		refer to maintenance	MV78	Secondary	CW	\$	-
OB909	Livingsstone Road	Marrickville	Local Road	obstruction	overhanging vegetation	-33.907298	151.152861	1		refer to maintenance	MV115	Secondary	CW	\$	-
OB91	Thomas Street	Ashfield	Regional Road	obstruction	signposts narrows footpath	-33.886592	151.118838	1		relocate signpost	AF157	Secondary	CW	\$	300
OB910	Livingsstone Road	Marrickville	Local Road	obstruction	overhanging vegetation	-33.907169	151.152747	1		refer to maintenance	MV115	Secondary	CW	\$	-
OB911	Livingsstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.908866	151.152797	1		refer to maintenance	MV114	Tertiary	CW	\$	-
OB912	Livingsstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.911332	151.148692	1		notify business/property owner	MV106	Secondary	CW	\$	-
OB913	Livingsstone Road	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.912215	151.147886	1		notify business/property owner	MV116	Secondary	CW	\$	-
OB914	Livingsstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.910566	151.150372	1		notify business/property owner	MV121	Primary	CW	\$	-
OB915	Livingsstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.910395	151.150604	1		notify business/property owner	MV120	Primary	CW	\$	-
OB916	Llewellyn Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.904144	151.171443	1		notify business/property owner	MV125	Secondary	CW	\$	-
OB917	Llewellyn Street	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.904168	151.170888	1		refer to maintenance	MV126	Secondary	CW	\$	-
OB918	Marrickville Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907448	151.148091	1		notify business/property owner	MV143	Tertiary	CW	\$	-
OB919	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.907268	151.147581	1		notify business/property owner	MV142	Secondary	CW	\$	-
OB92	Milton Street	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.890428	151.170881	1		notify business/property owner	AF114	Primary	CW	\$	-
OB920	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.907614	151.148334	1		notify business/property owner	MV143	Tertiary	CW	\$	-
OB921	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.907563	151.149052	1		notify business/property owner	MV144	Secondary	CW	\$	-
OB922	Marrickville Road	Marrickville	State Road	obstruction	overhanging vegetation - property	-33.908167									

**P4909 Inner West PAMP
Detailed Works Program
All Treatments
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CB929	Myrie Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.915879	151.15766	1	-	refer to maintenance	MMV47	Tertiary	LOW	\$	-
CB930	Newington Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.909284	151.171221	1	-	notify business/property owner	AF113	Primary	LOW	\$	-
CB931	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.921083	151.153565	1	-	refer to maintenance	MMV59	Secondary	LOW	\$	-
CB932	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.919357	151.150519	1	-	refer to maintenance	MMV63	Secondary	LOW	\$	-
CB933	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.919115	151.150137	1	-	notify business/property owner	MMV63	Secondary	LOW	\$	-
CB934	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.918897	151.149773	1	-	notify business/property owner	MMV58	Tertiary	LOW	\$	-
CB935	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.918701	151.149438	1	-	refer to maintenance	MMV58	Tertiary	LOW	\$	-
CB936	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.919459	151.148584	1	-	refer to maintenance	MMV58	Tertiary	LOW	\$	-
CB937	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.918403	151.14863	1	-	notify business/property owner	MMV58	Tertiary	LOW	\$	-
CB938	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.917973	151.147696	1	-	refer to maintenance	MMV60	Tertiary	LOW	\$	-
CB939	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.918463	151.153104	1	-	refer to maintenance	MMV67	Tertiary	LOW	\$	-
CB940	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880002	151.117274	1	-	notify business/property owner	AF112	Primary	LOW	\$	-
CB941	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.919227	151.154084	1	-	notify business/property owner	MMV69	Tertiary	LOW	\$	-
CB942	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918635	151.152008	1	-	refer to maintenance	MMV67	Tertiary	LOW	\$	-
CB943	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.919435	151.152008	1	-	refer to maintenance	MMV67	Tertiary	LOW	\$	-
CB944	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.917583	151.15105	1	-	notify business/property owner	MMV70	Secondary	LOW	\$	-
CB945	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.917477	151.150891	1	-	notify business/property owner	MMV70	Secondary	LOW	\$	-
CB946	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.916963	151.149773	1	-	refer to maintenance	MMV70	Secondary	LOW	\$	-
CB947	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.916918	151.149864	1	-	notify business/property owner	MMV68	Secondary	LOW	\$	-
CB948	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.916769	151.149747	1	-	refer to maintenance	MMV68	Secondary	LOW	\$	-
CB949	Richardson Crescent	Marrickville	Regional Road	obstruction	power pole narrows footpath	-33.921154	151.155624	1	-	no action	MMV73	Tertiary	LOW	\$	-
CB950	Richardson Crescent	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.921979	151.156755	1	-	refer to maintenance	TE14	Secondary	LOW	\$	-
CB951	Milton Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.889577	151.117315	1	-	refer to maintenance	AF113	Primary	LOW	\$	-
CB952	Richardson Crescent	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.921886	151.158533	1	-	refer to maintenance	MMV73	Tertiary	LOW	\$	-
CB953	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921659	151.15629	1	-	refer to maintenance	MMV74	Tertiary	LOW	\$	-
CB954	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921506	151.156106	1	-	refer to maintenance	MMV74	Tertiary	LOW	\$	-
CB955	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921377	151.155953	1	-	refer to maintenance	MMV74	Tertiary	LOW	\$	-
CB956	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921263	151.155897	1	-	refer to maintenance	MMV74	Tertiary	LOW	\$	-
CB957	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921061	151.155735	1	-	refer to maintenance	MMV73	Tertiary	LOW	\$	-
CB958	Richardson Crescent	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.920418	151.155122	1	-	refer to maintenance	MMV73	Tertiary	LOW	\$	-
CB959	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.921382	151.156174	1	-	refer to maintenance	MMV73	Secondary	LOW	\$	-
CB960	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.922291	151.1563	1	-	no action	MMV75	Secondary	LOW	\$	-
CB961	Milton Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.914661	151.142222	1	-	notify business/property owner	MMV78	Tertiary	LOW	\$	-
CB962	Riverside Crescent	Marrickville	Local Road	obstruction	overgrown vegetation narrows footpath	-33.889636	151.117333	1	-	refer to maintenance	AF113	Primary	LOW	\$	-
CB963	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914865	151.144075	1	-	notify business/property owner	MMV78	Secondary	LOW	\$	-
CB964	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914839	151.140297	1	-	notify business/property owner	MMV80	Tertiary	LOW	\$	-
CB965	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.915006	151.141185	1	-	refer to maintenance	MMV79	Tertiary	LOW	\$	-
CB966	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.915033	151.141389	1	-	refer to maintenance	MMV79	Tertiary	LOW	\$	-
CB967	Shirrow Street	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.912358	151.166367	1	-	no action	MMV85	Secondary	LOW	\$	-
CB968	Shirrow Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.911818	151.167053	1	-	notify business/property owner	MMV83	Tertiary	LOW	\$	-
CB969	Shirrow Street	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.911527	151.167444	1	-	no action	MMV83	Tertiary	LOW	\$	-
CB970	Shirrow Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.911702	151.167247	1	-	notify business/property owner	MMV83	Tertiary	LOW	\$	-
CB971	Shirrow Street	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.907642	151.174176	1	-	no action	NE21	Primary	LOW	\$	-
CB972	Shirrow Street	Marrickville	Local Road	obstruction	concrete structure obstructs crossing	-33.907786	151.171847	1	-	consult with Marrickville Metro	MMV80	Primary	LOW	\$	-
CB973	Shirrow Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891699	151.1524	1	-	notify business/property owner	AF86	Primary	LOW	\$	-
CB974	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.914187	151.153996	1	-	notify business/property owner	MMV86	Secondary	LOW	\$	-
CB975	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914456	151.154904	1	-	refer to maintenance	MMV88	Secondary	LOW	\$	-
CB976	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914533	151.154443	1	-	notify business/property owner	MMV88	Secondary	LOW	\$	-
CB977	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914619	151.155771	1	-	notify business/property owner	MMV87	Secondary	LOW	\$	-
CB978	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.9147	151.155961	1	-	notify business/property owner	MMV87	Secondary	LOW	\$	-
CB979	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.906891	151.160504	1	-	refer to maintenance	MMV92	Secondary	LOW	\$	-
CB980	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.907234	151.160567	1	-	refer to maintenance	MMV92	Secondary	LOW	\$	-
CB981	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.90903	151.160538	1	-	notify business/property owner	MMV92	Secondary	LOW	\$	-
CB982	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.908511	151.159968	1	-	refer to maintenance	MMV93	Secondary	LOW	\$	-
CB983	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.908672	151.159968	1	-	refer to maintenance	MMV93	Secondary	LOW	\$	-
CB984	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.908259	151.152936	1	-	notify business/property owner	AF86	Primary	LOW	\$	-
CB985	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.90685	151.158349	1	-	notify business/property owner	MMV96	Primary	LOW	\$	-
CB986	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.905486	151.157294	1	-	notify business/property owner	MMV97	Primary	LOW	\$	-
CB987	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.905487	151.15637	1	-	notify business/property owner	MMV97	Primary	LOW	\$	-
CB988	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.903658	151.155567	1	-	notify business/property owner	MMV90	Primary	LOW	\$	-
CB989	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.902602	151.154497	1	-	refer to maintenance	MMV99	Primary	LOW	\$	-
CB990	Sydenham Road	Marrickville	State Road	obstruction	light pole narrows footpath	-33.90261	151.154334	1	-	install light pole	MMV99	Primary	LOW	\$	10,000
CB991	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.902192	151.154013	1	-	notify business/property owner	MMV94	Primary	LOW	\$	-
CB992	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.912235	151.165501	1	-	refer to maintenance	MMV204	Secondary	LOW	\$	-
CB993	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.910337	151.162897	1	-	refer to maintenance	MMV200	Primary	LOW	\$	-
CB994	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.909724	151.162443	1	-	refer to maintenance	MMV200	Primary	LOW	\$	-
CB995	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.89726	151.129035	1	-	refer to maintenance	AF83	Tertiary	LOW	\$	-
CB996	Sydney Steel St	Marrickville	Local Road	obstruction	vehicles narrows footpath	-33.906861	151.169678	1	-	no action	MMV207	Tertiary	LOW	\$	-
CB997	Sydney Steel St	Marrickville	Local Road	obstruction	tree narrows footpath	-33.906821	151.16969	1	-	no action	MMV207	Tertiary	LOW	\$	-
CB998	Sydney Steel St	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.909077	151.170993	1	-	notify business/property owner	MMV205	Secondary	LOW	\$	-
CB999	Victoria Road	Marrickville	Regional Road	obstruction	vehicle narrows footpath	-33.905588	151.166792	1	-	no action	MMV213	Primary	LOW	\$	-
CB1000	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.906388	151.165065	1	-	notify business/property owner	MMV215	Secondary	LOW	\$	-
CB1001	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.906514	151.164888	1	-	refer to maintenance	MMV215	Secondary	LOW	\$	-
CB1002	Victoria Road	Marrickville	Regional Road	obstruction	vehicle narrows footpath	-33.908604	151.163157	1	-	no action	MMV210	Secondary	LOW	\$	-
CB1003	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.910322	151.161599	1	-	refer to maintenance	MMV219	Primary	LOW	\$	-
CB1004	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.909629	151.161481	1	-	refer to maintenance	MMV219	Primary	LOW	\$	-
CB1005	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.909672	151.162099	1	-	notify business/property owner	MMV219	Primary	LOW	\$	-
SA106	Allen Street	Leichhardt	Local Road	safety issue	vehicles approach crossing point at speed	-33.88033	152.151119	1	-	install kerb extension	LH6	Tertiary	LOW	\$	10,000
SA107	Allen Street	Leichhardt	Local Road	safety issue	vehicles approach at speed - insufficient deflection	-33.880362	152.151124	1	-	install new refuge island	LH6	Tertiary	LOW	\$	15,000
SA108	Allen Street	Leichhardt	Local Road	safety issue	vehicles exit roundabout at speed	-33.880388	152.151948	1	-	install kerb extension	LH5	Tertiary	LOW	\$	10,000
SA109	Allen Street	Leichhardt	Local Road	safety issue	vehicles approach at speed - insufficient deflection	-33.880364	152.151146	1	-	install new refuge island	LH5	Tertiary	LOW	\$	15,000
SA110	Allen Street	Leichhardt	Local Road	safety issue	damaged fence obstructs footpath	-33.880869	152.153201	1	-	replace property owner	MMV73	Tertiary	LOW	\$	-
SA170	Sydney Steel St	Marrickville	Local Road	safety issue	construction site with no gate control	-33.910106	151.169686	1	-	notify business owner	MMV207	Tertiary	LOW	\$	-
SA248	Greenway	Summer Hill	Local Road	safety issue	trip hazard - empty bollard floating	-33.891472	151.144249	1	-	repair bollard	SH52	Tertiary	LOW	\$	2,500
SA249	Greenway	Summer Hill	Local Road	safety issue	missing lighting	-33.891456	151.14406	1	-	install new lighting	SH52	Tertiary	LOW	\$	10,000
SA250	Prospect Road	Summer Hill	Local Road	safety issue	missing pedestrian barriers	-33.894046	151.132174	1	-	install landscape barriers	SH71	Tertiary	LOW	\$	750
SA253	Att Street	Ashfield	Local Road	safety issue	poor sight lines between pedestrians and approaching vehicles	-33.880715	151.128337	1	-	relocate no stopping signage	AF3	Tertiary	LOW	\$	300
SUBTOTAL															\$ 3,236,400
TOTAL															\$ 18,070,000

**P4909 Inner West PAMP
Detailed Works Program
Connectivity
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CN1	Pritchard Street	Annandale	Local Road	connectivity	poor connectivity over bayview cres	-33.872127	151.172909	1	1	install new kerb ramp - pair	AN18	Secondary	LOW	\$ 5,000
CN10	Bedford Crescent	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.910023	151.139994	1	1	no action	DH24	Secondary	LOW	\$ -
CN11	Blackwood Lane	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.907325	151.140385	1	1	no action	DH5	Secondary	LOW	\$ -
CN12	Constitution Road	Dulwich Hill	Local Road	connectivity	potential shared zone	-33.901478	151.137108	1	1	investigate shared zone implementation	DH16	Secondary	LOW	\$ 15,000
CN13	Ewart Street	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.910153	151.13764	1	1	no action	DH110	Tertiary	LOW	\$ -
CN14	Heracles Street	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.908658	151.139152	1	1	no action	DH53	Secondary	LOW	\$ -
CN15	Old Canterbury Road	Dulwich Hill	State Road	connectivity	inaccessible link	-33.904419	151.139299	1	1	no action	DH83	Primary	LOW	\$ -
CN16	Terry Road	Dulwich Hill	Local Road	connectivity	inaccessible link	-33.8999	151.138617	1	1	no action	DH67	Secondary	LOW	\$ -
CN17	Prospect Street	Leichhardt	Local Road	connectivity	potential shared zone	-33.884498	151.159615	1	1	investigate shared zone implementation	LH146	Secondary	LOW	\$ 15,000
CN18	Myrtle Street	Leichhardt	Local Road	connectivity	potential shared zone	-33.885316	151.151657	1	1	investigate shared zone implementation	LH111	Tertiary	LOW	\$ 15,000
CN19	White Creek	Leichhardt	Local Road	connectivity	missing footpath connectivity	-33.885268	151.166312	1	1	no action	LH165	Secondary	LOW	\$ -
CN2	Traralgar Street	Annandale	Local Road	connectivity	missing footpath connectivity	-33.876721	151.174546	1	1	install new kerb ramp - pair	AN102	Tertiary	LOW	\$ 5,000
CN20	White Creek	Leichhardt	Local Road	connectivity	missing footpath connectivity	-33.886776	151.163253	1	1	no action	LH157	Secondary	LOW	\$ -
CN21	Old Canterbury Road	Lewisham	State Road	connectivity	pedestrian desire line	-33.884196	151.145231	1	1	further investigation required - pedestrian refuge or crossing (signal)	LW19	Primary	LOW	\$ 15,000
CN22	Hudson Street	Lewisham	Local Road	connectivity	inaccessible link	-33.894072	151.143215	1	1	no action	LW1	Secondary	LOW	\$ -
CN23	Hudson Street	Lewisham	Local Road	connectivity	potential shared zone	-33.894051	151.144448	1	1	investigate shared zone implementation	LW5	Primary	LOW	\$ 15,000
CN24	Mathouse Way	Lewisham	Local Road	connectivity	inaccessible link	-33.892746	151.143981	1	1	no action	LW2	Secondary	LOW	\$ -
CN25	River Canoe Club	Marrickville	Local Road	connectivity	limited access between car park and path. opportunity to upgrade gate and fencing to provide access	-33.923452	151.155358	1	1	consult with Concordia Club (landowner)	MV45	Secondary	LOW	\$ -
CN26	Frazer Street	Marrickville	Regional Road	connectivity	missing crossing point	-33.901178	151.151174	1	1	install new kerb ramp - pair, new refuge island	MV77	Secondary	LOW	\$ 7,000
CN27	Shirrow Street	Marrickville	Local Road	connectivity	missing footpath connectivity	-33.90998	151.169597	1	1	further investigation required - footpath	MV207	Tertiary	LOW	\$ 5,000
CN28	Victoria Road	Marrickville	Local Road	connectivity	missing crossing point	-33.905567	151.169563	1	1	further investigation required - crossing point	MV211	Secondary	LOW	\$ 5,000
CN29	Station Street	Newtown	Local Road	connectivity	potential shared zone	-33.913998	151.153319	1	1	investigate shared zone implementation	MV189	Primary	LOW	\$ 15,000
CN3	Whites Creek Lane	Annandale	Local Road	connectivity	potential shared zone	-33.883492	151.165393	1	1	investigate shared zone implementation	LH162	Secondary	LOW	\$ 15,000
CN30	Mary Street	St Peters	Local Road	connectivity	missing footpath connectivity	-33.91314	151.172456	1	1	re-align kerb and footpath	SP36	Tertiary	LOW	\$ 7,500
CN31	Hardie Avenue	Summer Hill	Local Road	connectivity	potential shared zone	-33.890894	151.13789	1	1	investigate shared zone implementation	SH33	Primary	LOW	\$ 15,000
CN32	Old Canterbury Road	Summer Hill	State Road	connectivity	inaccessible link	-33.895058	151.142517	1	1	no action	SH17	Secondary	LOW	\$ -
CN33	Griffiths Street	Tempe	Local Road	connectivity	path terminates	-33.925278	151.156364	1	1	install new kerb ramp - pair	TE32	Secondary	LOW	\$ 5,000
CN34	View Street	Tempe	Local Road	connectivity	footpath terminates	-33.926898	151.157967	1	1	install new kerb ramp - pair	TE34	Primary	LOW	\$ 5,000
CN4	Whites Creek Lane	Annandale	Local Road	connectivity	potential shared zone	-33.885886	151.165393	1	1	investigate shared zone implementation	LH159	Secondary	LOW	\$ 15,000
CN5	Elizabeth Street	Aufild	Local Road	connectivity	missing footpath connectivity	-33.883598	151.119215	1	1	no action	CP20	Secondary	LOW	\$ -
CN6	Beattie Street	Balmain	Local Road	connectivity	missing kerb ramp	-33.85774	151.180943	1	1	install new kerb ramp	BA8	Secondary	LOW	\$ 2,500
CN7	Jane Street	Balmain	Local Road	connectivity	missing footpath connectivity	-33.858546	151.184442	1	1	install new kerb ramp	BA44	Primary	LOW	\$ 2,500
CN8	Thames Street	Balmain	Local Road	connectivity	footpath leads to road and driveway	-33.855053	151.185892	1	1	review and implement shared zone	BA72	Secondary	LOW	\$ 40,000
CN9	Rowntree Street	Birchgrove	Local Road	connectivity	poor kerb ramp alignment	-33.85227	151.18265	1	1	install new kerb ramp - pair	BIT7	Tertiary	LOW	\$ 5,000
													SUBTOTAL	\$ 229,500
													TOTAL	\$ 229,500

P4909 Inner West PAMP Detailed Works Program Crossing Deficiencies 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1007	Flood Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.88569	151.148749	1		install new kerb ramp	UH89	Primary	HIGH	\$ 2,500
CD1018	Foster Lane	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88531	151.147687	1		install new Tactile Ground Surface Indicators	UH88	Primary	HIGH	\$ 650
CD1021	Lovis Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889074	151.14756	1		install new kerb ramp	UH53	Primary	HIGH	\$ 2,500
CD1032	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883573	151.158599	1		install new kerb ramp - pair	UH102	Primary	HIGH	\$ 5,000
CD1033	Renwick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.883871	151.158191	1		install new kerb ramp	UH101	Primary	HIGH	\$ 2,500
CD1034	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88359	151.153892	1		install new kerb ramp	UH100	Primary	HIGH	\$ 2,500
CD104	Annandale Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.88082	151.169319	1		install new kerb ramp	AN28	Primary	HIGH	\$ 2,500
CD1041	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884156	151.14997	1		install new kerb ramp	UH95	Primary	HIGH	\$ 2,500
CD1042	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88413	151.148755	1		install new kerb ramp - pair	UH95	Primary	HIGH	\$ 5,000
CD1043	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884145	151.147654	1		install new kerb ramp	UH94	Primary	HIGH	\$ 2,500
CD1044	Marion Street	Leichhardt	Regional Road	crossing deficiency	narrow kerb ramp	-33.884211	151.147573	1		install new kerb ramp	UH72	Primary	HIGH	\$ 2,500
CD1047	Moore Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.879309	151.164158	1		install new kerb ramp	UH108	Primary	HIGH	\$ 2,500
CD1052	Catherine Lane	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.87916	151.163203	1		install new kerb ramp - pair	UH107	Primary	HIGH	\$ 5,000
CD1058	Norton Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883596	151.157089	1		install new kerb ramp - pair	UH128	Primary	HIGH	\$ 5,000
CD1059	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883771	151.157157	1		install new kerb ramp - pair	UH103	Primary	HIGH	\$ 5,000
CD1060	Norton Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883712	151.157096	1		install new kerb ramp - pair	UH119	Primary	HIGH	\$ 5,000
CD1061	Marion Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.883749	151.157010	1		install new kerb ramp - pair	UH101	Primary	HIGH	\$ 5,000
CD1062	Norton Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.883857	151.157030	1		install new kerb ramp	UH128	Primary	HIGH	\$ 2,500
CD1063	Norton Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.882004	151.156809	1		install new Tactile Ground Surface Indicators	UH121	Primary	HIGH	\$ 650
CD1064	Norton Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88088	151.156716	1		install new Tactile Ground Surface Indicators	UH122	Primary	HIGH	\$ 650
CD1067	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88786	151.161367	1		install new kerb ramp	UH146	Primary	HIGH	\$ 2,500
CD1068	Tebbutt Street	Leichhardt	State Road	crossing deficiency	misaligned kerb ramp	-33.88083	151.146581	1		install new kerb ramp	UH132	Primary	HIGH	\$ 2,500
CD1069	Paramatta Road	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889945	151.14671	1		install new kerb ramp - pair	UH156	Primary	HIGH	\$ 5,000
CD1070	Peterham Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888162	151.157724	1		install new kerb ramp - pair	UH142	Primary	HIGH	\$ 5,000
CD1072	Hay Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.887746	151.16008	1		install new kerb ramp - pair	UH143	Primary	HIGH	\$ 5,000
CD1073	Balmian Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887782	151.159289	1		install new kerb ramp - pair	UH18	Primary	HIGH	\$ 5,000
CD1074	Paramatta Road	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887777	151.159687	1		install new kerb ramp - pair	UH12	Primary	HIGH	\$ 5,000
CD1075	Norton Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880506	151.157645	1		install new kerb ramp - pair	UH115	Primary	HIGH	\$ 5,000
CD1076	Paramatta Road	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888163	151.157514	1		install new kerb ramp - pair	UH141	Primary	HIGH	\$ 5,000
CD1077	Renwick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888312	151.156818	1		install new kerb ramp - pair	UH141	Primary	HIGH	\$ 5,000
CD1078	Rich Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888061	151.155317	1		install new kerb ramp - pair	UH138	Primary	HIGH	\$ 5,000
CD1079	Elswick Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.888991	151.153145	1		install new kerb ramp - pair	UH138	Primary	HIGH	\$ 5,000
CD1080	National Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889379	151.150996	1		install new kerb ramp - pair	UH136	Primary	HIGH	\$ 5,000
CD1083	Upward Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889977	151.147478	1		install new kerb ramp - pair	UH133	Primary	HIGH	\$ 5,000
CD1084	Tebbutt Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88912	151.148912	1		install new kerb ramp - pair	UH133	Primary	HIGH	\$ 5,000
CD1089	Renwick Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.887972	151.156707	1		install new kerb ramp - pair	UH141	Primary	HIGH	\$ 5,000
CD1089	Keogwort Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889687	151.14736	1		install new kerb ramp	UH153	Primary	HIGH	\$ 2,500
CD110	Annandale Street	Leichhardt	Local Road	crossing deficiency	misaligned refuge island	-33.878113	151.170589	1		re-construct refuge island	AN8	Primary	HIGH	\$ 15,000
CD111	Annandale Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879453	151.169885	1		install new kerb ramp	AN9	Primary	HIGH	\$ 2,500
CD1114	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877203	151.159987	1		install new kerb ramp - pair	UH13	Primary	HIGH	\$ 5,000
CD112	Annandale Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878653	151.170209	1		install new Tactile Ground Surface Indicators	AN8	Primary	HIGH	\$ 650
CD113	Annandale Street	Leichhardt	Local Road	crossing deficiency	misaligned refuge island	-33.87716	151.170589	1		re-construct refuge island	AN8	Primary	HIGH	\$ 15,000
CD114	Annandale Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878116	151.170589	1		install new kerb ramp - pair	AN8	Primary	HIGH	\$ 5,000
CD1142	Moore Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.878239	151.159898	1		install new kerb ramp	UH13	Primary	HIGH	\$ 2,500
CD1144	Arundel Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.879103	151.159489	1		install new kerb ramp	UH12	Primary	HIGH	\$ 2,500
CD1145	Balmian Road	Leichhardt	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.879732	151.159209	1		install new Tactile Ground Surface Indicators - pair	UH11	Primary	HIGH	\$ 1,300
CD1146	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881095	151.158923	1		install new kerb ramp	UH10	Primary	HIGH	\$ 2,500
CD1147	Hill Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.879797	151.159312	1		install new kerb ramp - pair	UH11	Primary	HIGH	\$ 5,000
CD1148	Balmian Road	Leichhardt	Regional Road	crossing deficiency	driveway as kerb ramp	-33.881722	151.158818	1		further investigation required - kerb ramp	UH11	Primary	HIGH	\$ 5,000
CD1149	Balmian Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.882683	151.158965	1		install new kerb ramp	UH21	Primary	HIGH	\$ 5,000
CD1150	Balmian Road	Leichhardt	Regional Road	crossing deficiency	missing kerb ramp	-33.882684	151.158914	1		install new kerb ramp	UH21	Primary	HIGH	\$ 2,500
CD1151	Wetherhill Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882738	151.15889	1		install new kerb ramp	UH17	Primary	HIGH	\$ 2,500
CD1152	Wetherhill Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.882693	151.158984	1		install new kerb ramp	UH21	Primary	HIGH	\$ 2,500
CD1153	Balmian Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88378	151.159008	1		install new kerb ramp - pair	UH9	Primary	HIGH	\$ 5,000
CD1164	McDonald Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.885079	151.159123	1		install new kerb ramp	UH20	Primary	HIGH	\$ 2,500
CD1165	McDonald Street	Leichhardt	Local Road	crossing deficiency	steep kerb ramp	-33.885087	151.159139	1		install new kerb ramp - pair	UH20	Primary	HIGH	\$ 2,500
CD1167	Dof Lane	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.887436	151.159195	1		install new kerb ramp	UH18	Primary	HIGH	\$ 2,500
CD1168	Dof Lane	Leichhardt	Local Road	crossing deficiency	driveway as kerb ramp	-33.887352	151.159173	1		no action	UH18	Primary	HIGH	\$ 2,500
CD1169	Balmian Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887031	151.159216	1		install new kerb ramp - pair	UH18	Primary	HIGH	\$ 5,000
CD1165	Hudson Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89402	151.143995	1		install new kerb ramp	LW5	Primary	HIGH	\$ 2,500
CD1166	Hudson Street	Lewisham	Local Road	crossing deficiency	missing kerb ramp	-33.894029	151.143928	1		install new kerb ramp	LW5	Primary	HIGH	\$ 2,500
CD1167	Hudson Street	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893715	151.143903	1		install new Tactile Ground Surface Indicators	LW5	Primary	HIGH	\$ 650
CD1168	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.896448	151.14509	1		install new kerb ramp	UH11	Primary	HIGH	\$ 2,500
CD1174	Hunter Street	Lewisham	Local Road	crossing deficiency	missing kerb ramp	-33.894468	151.148709	1		install new kerb ramp	LW7	Primary	HIGH	\$ 2,500
CD1175	New Canterbury Road	Lewisham	State Road	crossing deficiency	misaligned kerb ramp	-33.897633	151.147028	1		install new kerb ramp	LW14	Primary	HIGH	\$ 2,500
CD1176	New Canterbury Road	Lewisham	State Road	crossing deficiency	misaligned kerb ramp	-33.89816	151.14923	1		install new kerb ramp	LW13	Primary	HIGH	\$ 2,500
CD1177	Wardell Road	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.899923	151.149333	1		install new kerb ramp - pair	LW38	Primary	HIGH	\$ 5,000
CD1178	New Canterbury Road	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896847	151.149351	1		install new kerb ramp	LW11	Primary	HIGH	\$ 2,500
CD1179	Morton Avenue	Lewisham	Local Road	crossing deficiency	misaligned refuge island	-33.899533	151.145029	1		re-construct refuge island	LW17	Primary	HIGH	\$ 15,000
CD1180	Wardell Road	Lewisham	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.896966	151.149209	1		install new Tactile Ground Surface Indicators	LW23	Primary	HIGH	\$ 650
CD1183	Hunt Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894163	151.145168	1		install new kerb ramp - pair	LW19	Primary	HIGH	\$ 5,000
CD1184	Tootill Street	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.894884	151.144606	1		install new kerb ramp	LW19	Primary	HIGH	\$ 2,500
CD1185	Old Canterbury Road	Lewisham	Local Road	crossing deficiency	missing kerb ramp	-33.895819	151.145438	1		install new kerb ramp	LW8	Primary	HIGH	\$ 2,500
CD1190	Old Canterbury Road	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889598	151.144979	1		install new kerb ramp - pair	UH132	Primary	HIGH	\$ 5,000
CD1191	Carlington Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890158	151.147484	1		install new kerb ramp - pair	UH133	Primary	HIGH	\$ 5,000
CD1193	Rayway Terrace	Lewisham	State Road	crossing deficiency	narrow pedestrian waiting area	-33.894031	151.149796	1		consult with TNSW	LW23	Primary	HIGH	\$ 5,000
CD1195	Thomas Street	Lewisham	Local Road	crossing deficiency	missing crossing point	-33.891676	151.147995	1		install new kerb ramp - pair	LW23	Primary	HIGH	\$ 5,000
CD1197	Tootill Street	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.895564	151.145063	1		install new kerb ramp	LW26	Primary	HIGH	\$ 2,500
CD1198	Tootill Street	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.895527	151.145114	1		install new kerb ramp	LW36	Primary	HIGH	\$ 2,500
CD1203	Tootill Street	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.897685	151.147138	1		install new kerb ramp	LW31	Primary	HIGH	\$ 2,500
CD1204	Tootill Street	Lewisham	Regional Road	crossing deficiency	narrow kerb ramp	-33.897594	151.147172	1		install new kerb ramp	LW13	Primary	HIGH	\$ 2,500
CD1207	Victoria Street	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.893673	151.147728	1		install new Tactile Ground Surface Indicators - pair	LW24	Primary	HIGH	\$ 1,300
CD1208	Old Canterbury Road	Lewisham	State Road	crossing deficiency	narrow kerb ramp	-33.892977	151.145948	1		install new kerb ramp	LW28	Primary	HIGH	\$ 2,500
CD1209	Longford Street	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.892912	151.145877	1		install new kerb ramp	LW23	Primary	HIGH	\$ 2,500
CD121	Annandale Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880639	151.160358	1		install new kerb ramp - pair	AN25	Primary	HIGH	\$ 5,000
CD1213	Rayway Terrace	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.894031	151.149812	1		install new kerb ramp	PE65	Primary	HIGH	\$ 2,500
CD1216	West Street	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894023	151.149859	1		install new kerb ramp - pair	PE65	Primary	H	

P4909 Inner West PAMP Detailed Works Program Crossing Deficiencies 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1231	Balmian Road	Lilyfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871563	151.158717	1		install new kerb ramp - pair	LF6	Primary	HIGH	\$ 5,000
CD1232	Wharf Road	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.871482	151.158991	1		install new kerb ramp	LF8	Primary	HIGH	\$ 2,500
CD1233	NSW Ambulance Centre	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.871772	151.160505	1		install new Tactile Ground Surface Indicators	LF6	Primary	HIGH	\$ 650
CD1238	Edward Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872692	151.160034	1		install new kerb ramp	LF10	Primary	HIGH	\$ 2,500
CD1240	Point Street	Lilyfield	Local Road	crossing deficiency	raised kerb ramp lip	-33.871968	151.159995	1		install new kerb ramp	LF10	Primary	HIGH	\$ 2,500
CD1241	Balmian Road	Lilyfield	Regional Road	crossing deficiency	missing crossing point	-33.872477	151.159942	1		install new kerb ramp - pair	LF10	Primary	HIGH	\$ 5,000
CD1247	City West Link Bridge	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.874637	151.156111	1		install new kerb ramp	LH114	Primary	HIGH	\$ 2,500
CD1248	Norton Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.874933	151.156117	1		install new kerb ramp	LH114	Primary	HIGH	\$ 5,000
CD1249	City West Link Bridge	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.874903	151.155871	1		install new kerb ramp	LH114	Primary	HIGH	\$ 2,500
CD1252	Laches Street	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.876336	151.163203	1		install new kerb ramp	LH114	Primary	HIGH	\$ 2,500
CD129	Nelson Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.88233	151.173585	1		install new kerb ramp - pair	AN65	Primary	HIGH	\$ 5,000
CD130	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.880939	151.169351	1		re-construct refuge island	AN25	Primary	HIGH	\$ 15,000
CD1315	Norton Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875159	151.155995	1		install new kerb ramp	LH114	Primary	HIGH	\$ 2,500
CD1316	Norton Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875126	151.155991	1		install new kerb ramp	LH114	Primary	HIGH	\$ 2,500
CD1317	Emmerick Street	Lilyfield	Local Road	crossing deficiency	long crossing	-33.872096	151.157377	1		install kerb extension - pair	LF8	Primary	HIGH	\$ 20,000
CD1326	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876487	151.164887	1		install new kerb ramp - pair	LF40	Primary	HIGH	\$ 5,000
CD1365	Addison Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.89221	151.163512	1		install new kerb ramp	MV8	Primary	HIGH	\$ 2,500
CD1373	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913721	151.158851	1		install new Tactile Ground Surface Indicators - pair	MV226	Primary	HIGH	\$ 1,300
CD14	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882003	151.173778	1		install new kerb ramp	AN65	Primary	HIGH	\$ 2,500
CD1400	Dudley Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.911448	151.142222	1		install new kerb ramp	MV46	Primary	HIGH	\$ 2,500
CD1403	Edgeware Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.905569	151.174944	1		install new Tactile Ground Surface Indicators	MV47	Primary	HIGH	\$ 650
CD1404	Edinburgh Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905669	151.167114	1		install new kerb ramp	MV213	Primary	HIGH	\$ 2,500
CD1407	Llewellyn Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903409	151.168844	1		install new kerb ramp - pair	MV61	Primary	HIGH	\$ 5,000
CD1408	Enmore Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903162	151.168952	1		install new kerb ramp	MV62	Primary	HIGH	\$ 2,500
CD1409	Cowper Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.902992	151.16888	1		install new kerb ramp	MV62	Primary	HIGH	\$ 2,500
CD141	Bridge Road	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887646	151.171471	1		install new kerb ramp - pair	AN81	Primary	HIGH	\$ 5,000
CD1410	Scudler Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.902513	151.168988	1		install new kerb ramp	MV62	Primary	HIGH	\$ 2,500
CD1413	Enmore Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.905567	151.167394	1		install new kerb ramp	MV213	Primary	HIGH	\$ 2,500
CD1416	Ewart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912116	151.140145	1		install new kerb ramp - pair	MV66	Primary	HIGH	\$ 5,000
CD1417	Ewart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912824	151.140813	1		install new kerb ramp - pair	MV67	Primary	HIGH	\$ 5,000
CD1422	Ewart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.912817	151.141089	1		install new Tactile Ground Surface Indicators - pair	MV61	Primary	HIGH	\$ 1,300
CD1423	Ewart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912382	151.140564	1		install new kerb ramp - pair	MV66	Primary	HIGH	\$ 5,000
CD1424	Wardell Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912065	151.140174	1		install new kerb ramp - pair	MV238	Primary	HIGH	\$ 5,000
CD1449	Illawarra Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910171	151.156633	1		install new Tactile Ground Surface Indicators - pair	MV86	Primary	HIGH	\$ 1,300
CD1451	Schwelet Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914327	151.153771	1		install new kerb ramp	MV69	Primary	HIGH	\$ 2,500
CD1457	Wharf Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.921478	151.143377	1		install new kerb ramp - pair	MV103	Primary	HIGH	\$ 5,000
CD1458	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.921636	151.143277	1		install new kerb ramp	MV103	Primary	HIGH	\$ 2,500
CD1459	Wharf Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.921636	151.143277	1		install new Tactile Ground Surface Indicators - pair	MV103	Primary	HIGH	\$ 1,300
CD146	Chester Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884328	151.17328	1		install new kerb ramp - pair	AN31	Primary	HIGH	\$ 5,000
CD1462	Carv Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.917233	151.148749	1		install new kerb ramp - pair	MV98	Primary	HIGH	\$ 5,000
CD1463	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912677	151.145494	1		install new kerb ramp - pair	MV90	Primary	HIGH	\$ 5,000
CD1464	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912446	151.154119	1		install new kerb ramp - pair	MV90	Primary	HIGH	\$ 5,000
CD1465	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.911826	151.154946	1		install new kerb ramp	MV90	Primary	HIGH	\$ 2,500
CD1467	Illawarra Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910886	151.156113	1		install new Tactile Ground Surface Indicators - pair	MV89	Primary	HIGH	\$ 1,300
CD1468	Byrnes Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912864	151.153798	1		install new kerb ramp - pair	MV91	Primary	HIGH	\$ 5,000
CD1469	Byrnes Street	Marrickville	Local Road	crossing deficiency	uneven crossing surface	-33.912999	151.153624	1		install new pavement surface	MV91	Primary	HIGH	\$ 300
CD147	Chester Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.88427	151.173314	1		install new Tactile Ground Surface Indicators - pair	AN31	Primary	HIGH	\$ 1,300
CD1470	Illawarra Road	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.911641	151.155249	1		install new kerb ramp - pair	MV90	Primary	HIGH	\$ 5,000
CD1472	Livstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.901474	151.153484	1		install new kerb ramp	PE27	Primary	HIGH	\$ 2,500
CD1473	Livstone Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.901463	151.153491	1		install new kerb ramp	PE27	Primary	HIGH	\$ 2,500
CD1478	Livstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.908666	151.152513	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1479	Livstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.908781	151.152487	1		install new kerb ramp - pair	MV138	Primary	HIGH	\$ 5,000
CD1480	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.908449	151.152436	1		install new Tactile Ground Surface Indicators - pair	MV107	Primary	HIGH	\$ 1,300
CD1486	Livstone Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.901646	151.153367	1		install new kerb ramp	MV108	Primary	HIGH	\$ 2,500
CD1487	Fraser Street	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.90154	151.163318	1		install new kerb ramp	MV108	Primary	HIGH	\$ 2,500
CD1491	Livstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910766	151.149772	1		install new Tactile Ground Surface Indicators - pair	MV121	Primary	HIGH	\$ 1,300
CD1501	Livstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.910797	151.149835	1		install new kerb ramp	MV121	Primary	HIGH	\$ 2,500
CD1502	Livstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.910535	151.150489	1		install new kerb ramp	MV120	Primary	HIGH	\$ 2,500
CD1504	Livstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.910443	151.150542	1		install new kerb ramp	MV120	Primary	HIGH	\$ 2,500
CD1511	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.908781	151.152458	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1512	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.908675	151.152381	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1516	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.908576	151.152369	1		install new kerb ramp	MV107	Primary	HIGH	\$ 2,500
CD1517	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.914417	151.163315	1		install new Tactile Ground Surface Indicators - pair	MV100	Primary	HIGH	\$ 1,300
CD1518	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.913516	151.162154	1		install new kerb ramp	MV129	Primary	HIGH	\$ 2,500
CD1519	Sydney Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913449	151.161923	1		install new kerb ramp - pair	MV129	Primary	HIGH	\$ 5,000
CD1527	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.909709	151.154418	1		install new kerb ramp - pair	MV137	Primary	HIGH	\$ 5,000
CD1528	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.909574	151.154322	1		install new kerb ramp	MV139	Primary	HIGH	\$ 2,500
CD1529	Fletcher Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.909672	151.154235	1		install new Tactile Ground Surface Indicators	MV139	Primary	HIGH	\$ 650
CD1530	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.908646	151.152695	1		install new kerb ramp	MV138	Primary	HIGH	\$ 2,500
CD1531	Marrickville Road	Marrickville	Regional Road	crossing deficiency	major driveway crossing missing tgi - pair	-33.909568	151.152042	1		install new Tactile Ground Surface Indicators	MV139	Primary	HIGH	\$ 650
CD1532	Petersham Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909566	151.154329	1		install new kerb ramp - pair	MV139	Primary	HIGH	\$ 5,000
CD1533	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.909735	151.154445	1		install new kerb ramp	MV137	Primary	HIGH	\$ 2,500
CD1534	Moswell Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.909764	151.154932	1		install new Tactile Ground Surface Indicators - pair	MV137	Primary	HIGH	\$ 1,300
CD1544	Marrickville Road	Marrickville	Regional Road	crossing deficiency	narrow refuge island	-33.91226	151.160239	1		install new corner refuge island	MV220	Primary	HIGH	\$ 10,000
CD1545	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.912263	151.160284	1		install new kerb ramp	MV220	Primary	HIGH	\$ 2,500
CD1546	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.913403	151.161993	1		re-construct refuge island	MV129	Primary	HIGH	\$ 15,000
CD1547	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.913823	151.162016	1		install new kerb ramp - pair	MV49	Primary	HIGH	\$ 5,000
CD1548	Railway Parade	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.915071	151.164587	1		install new kerb ramp - pair	MV131	Primary	HIGH	\$ 5,000
CD1549	Marrickville Road	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.911608	151.155263	1		install new kerb ramp - pair	MV90	Primary	HIGH	\$ 5,000
CD1560	Sydney Street	Marrickville	Local Road	crossing deficiency	long crossing	-33.913464	151.162145	1		remove when land use changes	MV129	Primary	HIGH	\$ 5,000
CD1561	Sydney Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.910543	151.156339	1		install new kerb ramp	MV89	Primary	HIGH	\$ 2,500
CD1562	Marrickville Road	Marrickville	Regional Road	crossing deficiency	missing kerb ramp	-33.908587	151.152398	1		install new kerb ramp	MV107	Primary	HIGH	\$ 2,500
CD1564	Murray Street	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.908661	151.173276	1		install new kerb ramp - pair	MV47	Primary	HIGH	\$ 5,000
CD1567	Murray Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.910715	151.172967	1		install new Tactile Ground Surface Indicators	MV49	Primary	HIGH	\$ 650
CD1568	Murray Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.907596	151.172591	1		install new kerb ramp - pair	MV49	Primary	HIGH	\$ 5,000
CD1588	Railway Parade	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.913888	151.165531	1		install new kerb ramp	MV165	Primary	HIGH	\$ 2,500
CD1610	Smidmore													

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1631	Petersham Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.903365	151.155103	1		install new Tactile Ground Surface Indicators	MV190	Primary	HIGH	\$ 650
CD1632	Bereton Avenue	Marrickville	Local Road	crossing deficiency	long crossing point	-33.902453	151.154247	1		install kerb extension - pair	MV199	Primary	HIGH	\$ 20,000
CD1633	Bereton Avenue	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.902363	151.154108	1		install new kerb ramp	MV199	Primary	HIGH	\$ 2,500
CD1637	Sydenham Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913383	151.158823	1		install new Tactile Ground Surface Indicators - pair	MV165	Primary	HIGH	\$ 1,300
CD1638	Sydenham Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.912702	151.160851	1		install new kerb ramp - pair	MV203	Primary	HIGH	\$ 5,000
CD1639	Buckley Street	Marrickville	State Road	crossing deficiency	unsafe crossing point	-33.915353	151.165875	1		further investigation required - pedestrian crossing	MV203	Primary	HIGH	\$ 5,000
CD1644	Meeks Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.910448	151.163397	1		install new kerb ramp - pair	MV200	Primary	HIGH	\$ 5,000
CD1650	Empire Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.905695	151.173189	1		install new Tactile Ground Surface Indicators	MV47	Primary	HIGH	\$ 10,000
CD1654	Sydenham Road	Marrickville	State Road	crossing deficiency	poor kerb ramp alignment	-33.90976	151.162221	1		install new kerb ramp	MV200	Primary	HIGH	\$ 2,500
CD1655	Sydenham Road	Marrickville	State Road	crossing deficiency	missing kerb ramp	-33.909761	151.162137	1		install new kerb ramp	MV219	Primary	HIGH	\$ 2,500
CD1656	Victoria Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913068	151.159302	1		install new Tactile Ground Surface Indicators - pair	MV225	Primary	HIGH	\$ 1,300
CD1657	Victoria Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912699	151.159768	1		install new kerb ramp - pair	MV225	Primary	HIGH	\$ 5,000
CD1658	Victoria Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.912698	151.159884	1		install new Tactile Ground Surface Indicators - pair	MV225	Primary	HIGH	\$ 1,300
CD1660	Victoria Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91432	151.158344	1		install new kerb ramp - pair	MV227	Primary	HIGH	\$ 5,000
CD1662	Warburton Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914195	151.152302	1		install new kerb ramp - pair	MV230	Primary	HIGH	\$ 5,000
CD1663	Warburton Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913899	151.151797	1		install new Tactile Ground Surface Indicators	MV230	Primary	HIGH	\$ 650
CD1665	Warburton Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.913843	151.152227	1		install new Tactile Ground Surface Indicators - pair	MV230	Primary	HIGH	\$ 1,300
CD1675	Dudley Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.911263	151.141334	1		install new kerb ramp	MV46	Primary	HIGH	\$ 2,500
CD1679	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915842	151.150094	1		install new kerb ramp - pair	MV242	Primary	HIGH	\$ 5,000
CD1680	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915827	151.150269	1		install new kerb ramp - pair	MV95	Primary	HIGH	\$ 5,000
CD1681	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.916337	151.151041	1		install new Tactile Ground Surface Indicators - pair	MV246	Primary	HIGH	\$ 1,300
CD1687	Illawarra Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915865	151.150235	1		install new kerb ramp - pair	MV246	Primary	HIGH	\$ 5,000
CD1688	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915934	151.150334	1		install new kerb ramp - pair	MV246	Primary	HIGH	\$ 5,000
CD1692	Enmore Road	Newtown	State Road	crossing deficiency	narrow kerb ramp - pair	-33.89787	151.178382	1		install new kerb ramp - pair	NE33	Primary	HIGH	\$ 5,000
CD1693	King Street	Newtown	State Road	crossing deficiency	narrow kerb ramp - pair	-33.897973	151.178511	1		consult with City of Sydney and TNSW	NE47	Primary	HIGH	\$ 5,000
CD1712	Alice Street	Newtown	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.904867	151.173115	1		install new kerb ramp	NE23	Primary	HIGH	\$ 2,500
CD1713	Australia Street	Newtown	Local Road	crossing deficiency	missing kerb ramp - pair	-33.897184	151.178577	1		install new kerb ramp - pair	NE12	Primary	HIGH	\$ 5,000
CD1714	Australia Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896719	151.178627	1		install new kerb ramp	NE15	Primary	HIGH	\$ 2,500
CD1715	Bedford Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.897515	151.178004	1		install new kerb ramp	NE16	Primary	HIGH	\$ 2,500
CD1722	Smidmore Street	Newtown	Local Road	crossing deficiency	steep kerb ramp	-33.907498	151.174494	1		install new kerb ramp - pair	NE21	Primary	HIGH	\$ 5,000
CD1723	Edgeware Road	Newtown	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.904876	151.173294	1		install new kerb ramp	NE22	Primary	HIGH	\$ 2,500
CD1724	Edgeware Road	Newtown	Regional Road	crossing deficiency	steep kerb ramp	-33.905094	151.173292	1		install new kerb ramp - pair	NE24	Primary	HIGH	\$ 5,000
CD1725	Enmore Road	Newtown	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898487	151.178463	1		install new kerb ramp - pair	NE35	Primary	HIGH	\$ 5,000
CD1726	Station Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898554	151.178408	1		install new kerb ramp - pair	NE35	Primary	HIGH	\$ 5,000
CD1727	Enmore Road	Newtown	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898527	151.178507	1		install new kerb ramp - pair	NE37	Primary	HIGH	\$ 5,000
CD1730	Philip Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.898794	151.173933	1		install new kerb ramp	NE37	Primary	HIGH	\$ 2,500
CD1731	Enmore Road	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.897706	151.178399	1		install new kerb ramp	NE33	Primary	HIGH	\$ 2,500
CD1733	Holt Street	Newtown	Local Road	crossing deficiency	missing kerb ramp - pair	-33.900155	151.176218	1		install new kerb ramp - pair	NE33	Primary	HIGH	\$ 2,500
CD1735	King Street	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.902783	151.179892	1		install new kerb ramp	NE52	Primary	HIGH	\$ 2,500
CD1736	King Street	Newtown	State Road	crossing deficiency	misaligned kerb ramp	-33.898832	151.177837	1		install new kerb ramp	NE48	Primary	HIGH	\$ 2,500
CD1737	King Street	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.906953	151.161328	1		install new kerb ramp	NE22	Primary	HIGH	\$ 2,500
CD1738	King Street	Newtown	State Road	crossing deficiency	poor kerb ramp alignment	-33.905915	151.161098	1		install new kerb ramp	NE57	Primary	HIGH	\$ 2,500
CD1739	Darley Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90583	151.180978	1		install new kerb ramp	NE56	Primary	HIGH	\$ 2,500
CD1740	Walls Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905177	151.180891	1		install new kerb ramp - pair	NE56	Primary	HIGH	\$ 5,000
CD1741	Holmeswood Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903862	151.179591	1		install new kerb ramp	NE53	Primary	HIGH	\$ 2,500
CD1742	King Street	Newtown	State Road	crossing deficiency	missing crossing point	-33.902984	151.179507	1		consult with City of Sydney	NE53	Primary	HIGH	\$ 2,500
CD1747	Lord Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907599	151.177876	1		install new kerb ramp	NE28	Primary	HIGH	\$ 2,500
CD1748	Lord Street	Newtown	Local Road	crossing deficiency	at grade crossing missing tgi	-33.906855	151.180796	1		install new Tactile Ground Surface Indicators	NE22	Primary	HIGH	\$ 650
CD1749	Lord Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.906782	151.180811	1		install new kerb ramp	NE22	Primary	HIGH	\$ 2,500
CD175	Rose Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876314	151.172976	1		install new kerb ramp - pair	AN46	Primary	HIGH	\$ 5,000
CD176	Rose Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.876346	151.172989	1		install new Tactile Ground Surface Indicators	AN46	Primary	HIGH	\$ 650
CD1765	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894872	151.154182	1		install new kerb ramp	PE45	Primary	HIGH	\$ 2,500
CD1766	Audley Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895301	151.154311	1		install new kerb ramp	PE46	Primary	HIGH	\$ 2,500
CD177	Piper Street North	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878378	151.172188	1		install new kerb ramp	AN48	Primary	HIGH	\$ 2,500
CD1772	Crystal Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88405	151.157288	1		install new kerb ramp	PE60	Primary	HIGH	\$ 2,500
CD1778	Erskine Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88925	151.158265	1		install new kerb ramp	PE17	Primary	HIGH	\$ 2,500
CD1779	Queen Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888306	151.15893	1		install new kerb ramp	PE12	Primary	HIGH	\$ 2,500
CD178	Piper Street South	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.878765	151.172075	1		install new kerb ramp	AN49	Primary	HIGH	\$ 2,500
CD1780	Margaret Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889077	151.158727	1		install new kerb ramp	PE17	Primary	HIGH	\$ 2,500
CD1781	Corriva Road	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890675	151.158576	1		install new kerb ramp	PE16	Primary	HIGH	\$ 2,500
CD1786	McRae Street	Petersham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.900593	151.153534	1		install new Tactile Ground Surface Indicators	PE27	Primary	HIGH	\$ 650
CD179	Johnson Street	Annandale	State Road	crossing deficiency	narrow kerb ramp	-33.87825	151.172238	1		install new kerb ramp	AN48	Primary	HIGH	\$ 2,500
CD1790	Morgan Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.89847	151.153443	1		install new kerb ramp	PE25	Primary	HIGH	\$ 2,500
CD1791	McRae Street	Petersham	Local Road	crossing deficiency	long crossing point	-33.90062	151.153533	1		install kerb extension / refuge island	PE27	Primary	HIGH	\$ 10,000
CD1792	West Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898689	151.151364	1		install new kerb ramp - pair	PE28	Primary	HIGH	\$ 5,000
CD1793	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896181	151.154171	1		install new kerb ramp	PE28	Primary	HIGH	\$ 2,500
CD1794	Audley Street	Petersham	Local Road	crossing deficiency	narrow kerb ramp	-33.896182	151.154180	1		install new kerb ramp	PE38	Primary	HIGH	\$ 2,500
CD1795	New Canterbury Road	Petersham	State Road	crossing deficiency	narrow kerb ramp	-33.896209	151.154193	1		install new kerb ramp	PE31	Primary	HIGH	\$ 2,500
CD1796	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896214	151.154103	1		install new kerb ramp	PE32	Primary	HIGH	\$ 2,500
CD1797	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896246	151.154205	1		install new kerb ramp - pair	PE34	Primary	HIGH	\$ 5,000
CD1798	Gordon Street	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896582	151.152424	1		install new kerb ramp	PE34	Primary	HIGH	\$ 2,500
CD1799	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896593	151.152438	1		install new kerb ramp - pair	PE34	Primary	HIGH	\$ 5,000
CD1800	New Canterbury Road	Petersham	State Road	crossing deficiency	missing kerb ramp	-33.897007	151.154487	1		install new kerb ramp	PE35	Primary	HIGH	\$ 2,500
CD1801	Livingstone Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896617	151.152519	1		install new kerb ramp - pair	PE23	Primary	HIGH	\$ 5,000
CD1802	New Canterbury Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.896586	151.152572	1		install new kerb ramp	PE23	Primary	HIGH	\$ 2,500
CD1803	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896624	151.154182	1		install new kerb ramp - pair	PE31	Primary	HIGH	\$ 5,000
CD1810	Johnson Street	Annandale	State Road	crossing deficiency	poor kerb ramp alignment	-33.881386	151.170828	1		install new kerb ramp	PE41	Primary	HIGH	\$ 2,500
CD1813	Palace Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.892797	151.154338	1		install new kerb ramp	PE43	Primary	HIGH	\$ 5,000
CD1814	Palace Street	Petersham	Local Road	crossing deficiency	missing kerb ramp	-33.892894	151.154334	1		install new kerb ramp	PE43	Primary	HIGH	\$ 2,500
CD1815	Palace Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893154	151.154189	1		install new kerb ramp	PE43	Primary	HIGH	\$ 2,500
CD1816	Palace Street	Petersham	Local Road	crossing deficiency	missing crossing point	-33.893393	151.154129	1		install new kerb ramp - pair	PE44	Primary	HIGH	\$ 2,500
CD1819	Palace Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896671	151.154338	1		install new kerb ramp	PE41	Primary	HIGH	\$ 2,500
CD182	Johnson Street	Annandale	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883544	151.169774	1		install new kerb ramp - pair	AN53	Primary	HIGH	\$ 5,000
CD1822	Palace Street	Petersham	Local Road	crossing deficiency	missing crossing point	-33.896706	151.154338	1		install new kerb ramp - pair	PE41	Primary	HIGH	\$ 2,500
CD1823	Crystal Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888042	151.158933	1		install new kerb ramp - pair	UH142	Primary	HIGH	\$ 5,000
CD1827	Andrea Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.889467	151.151486	1		install new kerb ramp - pair	UH136	Primary	HIGH	\$ 5,000
CD1828	Railway Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898879	151.159879	1		install new kerb ramp - pair	UH40	Primary	HIGH	\$ 5,000
CD														

P4909 Inner West PAMP Detailed Works Program Crossing Deficiencies 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD1851	Trafalgar Street	Petersham	Regional Road	crossing deficiency	poor crossing alignment	-33.894612	151.154081	1		re-align crossing and refuge island	PE62	Primary	HIGH	\$ 6,000
CD1855	West Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.893272	151.150491	1		install new kerb ramp	PE65	Primary	HIGH	\$ 2,500
CD1856	West Street	Petersham	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.892387	151.148872	1		install new Tactile Ground Surface Indicators	UW42	Primary	HIGH	\$ 650
CD1857	West Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.893281	151.150413	1		install new kerb ramp	PE65	Primary	HIGH	\$ 2,500
CD1861	Ellen Street	Rozelle	Local Road	crossing deficiency	narrow kerb ramp	-33.864973	151.171357	1		install new kerb ramp	RO76	Primary	HIGH	\$ 2,500
CD1863	Daring Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.863956	151.170142	1		install new kerb ramp	RO24	Primary	HIGH	\$ 2,500
CD1864	Daring Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.863122	151.170490	1		install new Tactile Ground Surface Indicators	RO24	Primary	HIGH	\$ 650
CD1865	Daring Street	Rozelle	Regional Road	crossing deficiency	misaligned kerb ramps	-33.861614	151.17138	1		install new kerb ramp	RO22	Primary	HIGH	\$ 2,500
CD1866	Daring Street	Rozelle	Regional Road	crossing deficiency	missing crossing point	-33.860605	151.171763	1		install new kerb ramp - pair	RO21	Primary	HIGH	\$ 5,000
CD1867	Norman Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859975	151.171782	1		install new kerb ramp	RO21	Primary	HIGH	\$ 2,500
CD1868	Daring Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.858868	151.172067	1		install new Tactile Ground Surface Indicators	RO19	Primary	HIGH	\$ 650
CD1870	Nelson Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.861812	151.171307	1		install new kerb ramp	RO23	Primary	HIGH	\$ 2,500
CD1871	National Street	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgi	-33.863114	151.170907	1		install new Tactile Ground Surface Indicators	RO24	Primary	HIGH	\$ 650
CD1872	Victoria Road	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.863807	151.170271	1		install new kerb ramp	RO24	Primary	HIGH	\$ 2,500
CD1873	Waterloo Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.864519	151.169	1		install new kerb ramp	RO26	Primary	HIGH	\$ 2,500
CD1874	Daring Street	Rozelle	State Road	crossing deficiency	at grade crossing missing tgi	-33.865388	151.167519	1		install new Tactile Ground Surface Indicators	RO27	Primary	HIGH	\$ 650
CD1875	Daring Street	Rozelle	State Road	crossing deficiency	at grade crossing missing tgi	-33.865591	151.167162	1		install new Tactile Ground Surface Indicators	RO27	Primary	HIGH	\$ 650
CD189	Hercules Street	Ashfield	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.888783	151.124952	1		install new kerb ramp - pair	AF21	Primary	HIGH	\$ 5,000
CD191	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884265	151.172826	1		install new kerb ramp - pair	AN71	Primary	HIGH	\$ 5,000
CD192	Liverpool Road	Ashfield	State Road	crossing deficiency	narrow kerb ramp - pair	-33.888853	151.124948	1		install new kerb ramp - pair	AF103	Primary	HIGH	\$ 5,000
CD192	Liverpool Road	Ashfield	State Road	crossing deficiency	narrow kerb ramp - pair	-33.888787	151.124953	1		relocate crossing - signals	AF104	Primary	HIGH	\$ 20,000
CD1961	Victoria Road	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.863712	151.170109	1		install new kerb ramp	RO24	Primary	HIGH	\$ 2,500
CD1963	Victoria Road	Rozelle	State Road	crossing deficiency	at grade crossing missing tgi	-33.863649	151.169553	1		install new Tactile Ground Surface Indicators	RO78	Primary	HIGH	\$ 650
CD1964	Wellington Street	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.86279	151.168724	1		install new kerb ramp - pair	RO80	Primary	HIGH	\$ 5,000
CD1965	Victoria Road	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.862898	151.168732	1		install new kerb ramp	RO80	Primary	HIGH	\$ 2,500
CD1967	Victoria Road	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.866004	151.172879	1		install new kerb ramp	RO72	Primary	HIGH	\$ 2,500
CD1961	Mackenzie Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865966	151.172993	1		install new kerb ramp - pair	RO72	Primary	HIGH	\$ 5,000
CD1962	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865219	151.172383	1		install new kerb ramp - pair	SP16	Primary	HIGH	\$ 5,000
CD1963	Ellen Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.864843	151.171605	1		install new kerb ramp - pair	RO76	Primary	HIGH	\$ 5,000
CD1964	Prosper Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.864578	151.171276	1		install new kerb ramp - pair	RO76	Primary	HIGH	\$ 5,000
CD1965	Willemoet Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.864773	151.171071	1		install new kerb ramp	RO76	Primary	HIGH	\$ 2,500
CD1969	Wise Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.860495	151.170842	1		install new kerb ramp	RO67	Primary	HIGH	\$ 2,500
CD1970	Wise Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.860584	151.171016	1		install new kerb ramp - pair	RO67	Primary	HIGH	\$ 5,000
CD1972	Campbell Street	St Peters	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.912005	151.176202	1		install new kerb ramp	SP16	Primary	HIGH	\$ 2,500
CD1976	Edith Street	St Peters	Local Road	crossing deficiency	missing kerb ramp	-33.914608	151.174713	1		install new kerb ramp - pair	SP17	Primary	HIGH	\$ 2,500
CD1977	Goodsell Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907901	151.161247	1		install new kerb ramp - pair	SP11	Primary	HIGH	\$ 5,000
CD1978	King Street	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907699	151.161387	1		consult with City of Sydney	SP10	Primary	HIGH	\$ 2,500
CD1979	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment	-33.912891	151.176219	1		install new kerb ramp	SP24	Primary	HIGH	\$ 2,500
CD1980	Grove Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.916225	151.173136	1		install new kerb ramp - pair	SP24	Primary	HIGH	\$ 5,000
CD1992	Short Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.910697	151.180107	1		install new kerb ramp	SP9	Primary	HIGH	\$ 2,500
CD1993	May Street	St Peters	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90681	151.161007	1		install new kerb ramp - pair	SP12	Primary	HIGH	\$ 5,000
CD1994	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912653	151.176294	1		install new kerb ramp - pair	SP16	Primary	HIGH	\$ 5,000
CD1995	Victoria Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913249	151.178006	1		install new kerb ramp - pair	SP17	Primary	HIGH	\$ 5,000
CD1996	Bishop Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913795	151.17635	1		install new kerb ramp - pair	SP18	Primary	HIGH	\$ 5,000
CD1997	Edith Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.914687	151.175744	1		install new kerb ramp - pair	SP21	Primary	HIGH	\$ 5,000
CD1998	Silver Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.914811	151.176419	1		install new kerb ramp - pair	SP20	Primary	HIGH	\$ 5,000
CD1999	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914151	151.177405	1		install new kerb ramp - pair	SP19	Primary	HIGH	\$ 5,000
CD200	Nelson Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884121	151.172888	1		install new Tactile Ground Surface Indicators	AN31	Primary	HIGH	\$ 650
CD2000	Victoria Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913279	151.178444	1		install new kerb ramp - pair	SP16	Primary	HIGH	\$ 5,000
CD2001	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912485	151.179035	1		install new kerb ramp - pair	SP16	Primary	HIGH	\$ 5,000
CD2002	Princes Highway	St Peters	State Road	crossing deficiency	missing kerb ramp	-33.908808	151.181159	1		install new kerb ramp	SP12	Primary	HIGH	\$ 2,500
CD2003	Princes Highway	St Peters	State Road	crossing deficiency	misaligned kerb ramp	-33.908812	151.181207	1		consult with City of Sydney	SP12	Primary	HIGH	\$ 2,500
CD2013	Douglas Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894079	151.164246	1		install new kerb ramp	SM34	Primary	HIGH	\$ 2,500
CD2014	Douglas Street	Stammore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.894068	151.164151	1		install new kerb ramp	SM34	Primary	HIGH	\$ 2,500
CD2016	Brace Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893651	151.16142	1		install new kerb ramp - pair	SM12	Primary	HIGH	\$ 5,000
CD2017	Brace Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893427	151.161527	1		install new kerb ramp	SM12	Primary	HIGH	\$ 2,500
CD2018	Brace Lane East	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.8936	151.162057	1		install new kerb ramp	SM12	Primary	HIGH	\$ 2,500
CD2019	Gordon Crescent	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.89423	151.162936	1		install new kerb ramp	SM18	Primary	HIGH	\$ 2,500
CD2022	Holt Street	Stammore	Local Road	crossing deficiency	at grade crossing missing tgi	-33.896307	151.163972	1		install new Tactile Ground Surface Indicators	SM35	Primary	HIGH	\$ 650
CD2023	Holt Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896008	151.163939	1		install new kerb ramp	SM35	Primary	HIGH	\$ 2,500
CD2024	Holt Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.895829	151.163787	1		install new kerb ramp	SM35	Primary	HIGH	\$ 2,500
CD2025	Holt Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895868	151.163746	1		install new kerb ramp	SM35	Primary	HIGH	\$ 2,500
CD2029	Paramatta Road	Stammore	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89806	151.161447	1		install new kerb ramp - pair	U146	Primary	HIGH	\$ 5,000
CD2040	Canon Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888329	151.162998	1		install new kerb ramp - pair	AN73	Primary	HIGH	\$ 5,000
CD2043	Perivall Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893991	151.164141	1		install new kerb ramp	SM41	Primary	HIGH	\$ 2,500
CD2044	Perivall Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893329	151.164248	1		install new kerb ramp	SM43	Primary	HIGH	\$ 2,500
CD2045	Perivall Road	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.890778	151.165047	1		re-construct refuge island	SM30	Primary	HIGH	\$ 15,000
CD2046	Perivall Road	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.890632	151.165033	1		install new kerb ramp	SM29	Primary	HIGH	\$ 2,500
CD2047	Perivall Road	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.890538	151.165144	1		install new kerb ramp	SM29	Primary	HIGH	\$ 2,500
CD2049	Perivall Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893281	151.164446	1		install new kerb ramp	SM44	Primary	HIGH	\$ 2,500
CD2055	Railway Avenue	Stammore	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893737	151.166522	1		install new Tactile Ground Surface Indicators	SM36	Primary	HIGH	\$ 650
CD2056	Railway Avenue	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.893804	151.166567	1		install new kerb ramp	SM36	Primary	HIGH	\$ 2,500
CD2057	Salisbury Road	Stammore	Regional Road	crossing deficiency	misaligned kerb ramp	-33.892894	151.166713	1		install new kerb ramp	SM43	Primary	HIGH	\$ 2,500
CD2058	Myrtle Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89298	151.16615	1		install new kerb ramp	SM42	Primary	HIGH	\$ 2,500
CD2059	Myrtle Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.892474	151.166318	1		install new kerb ramp	SM47	Primary	HIGH	\$ 2,500
CD2060	Myrtle Lane	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.892689	151.167277	1		install new kerb ramp	SM46	Primary	HIGH	\$ 2,500
CD2061	Salisbury Road	Stammore	Regional Road	crossing deficiency	misaligned kerb ramp	-33.891757	151.168003	1		install new kerb ramp	SM46	Primary	HIGH	\$ 2,500
CD2064	Salisbury Road	Stammore	Regional Road	crossing deficiency	narrow refuge island	-33.891809	151.168042	1		install new refuge island	SM46	Primary	HIGH	\$ 15,000
CD2067	Stammore Road	Stammore	State Road	crossing deficiency	steep kerb ramp	-33.895481	151.163203	1		install new kerb ramp - pair	SM49	Primary	HIGH	\$ 5,000
CD2068	Middleton Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89632	151.161508	1		install new kerb ramp	SM50	Primary	HIGH	\$ 2,500
CD2069	Middleton Street	Stammore	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.896281	151.161646	1		install new kerb ramp - pair	SM50	Primary	HIGH	\$ 5,000
CD2070	Trafalgar Street	Stammore	Regional Road	crossing deficiency	narrow pedestrian waiting area	-33.894444	151.16438	1		install kerb extension	SM34	Primary	HIGH	\$ 10,000
CD2074	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890405	151.13843	1		install new kerb ramp - pair	SH14	Primary	HIGH	\$ 5,000
CD2075	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	raised kerb ramp up	-33.890544	151.138527	1		install new kerb ramp	SH48	Primary	HIGH	\$ 2,500
CD2076	Lackley Street	Summer Hill	Local Road	crossing deficiency	raised kerb ramp up	-33.890579	151.13851	1		install new kerb ramp	SH49	Primary	HIGH	\$ 2,500
CD2084	Hardie Avenue	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890669	151.138279	1		install new kerb ramp	SH33	Primary	HIGH	\$ 2,500
CD2091	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895553	151.138468	1		install new kerb ramp	SH5	Primary	HIGH	\$ 2,500
CD21	Paramatta Road	Annandale	State Road	crossing deficiency	poor kerb ramp alignment - pair	-								

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD2118	Edward Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895401	151.141637	1		install new kerb ramp - pair	DH100	Primary	HIGH	\$ 5,000
CD212	Alt Street	Ashfield	Local Road	crossing deficiency	narrow refuge island	-33.885511	151.123005	1		install new refuge island	AF54	Primary	HIGH	\$ 15,000
CD2120	Stoane Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887665	151.141694	1		install new kerb ramp - pair	SH77	Primary	HIGH	\$ 5,000
CD2121	Dover Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889506	151.144304	1		install new kerb ramp - pair	HA65	Primary	HIGH	\$ 5,000
CD2130	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.800762	151.132035	1		install new kerb ramp - pair	AF126	Primary	HIGH	\$ 5,000
CD2131	Stoane Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890626	151.135224	1		install new kerb ramp - pair	SH78	Primary	HIGH	\$ 5,000
CD2132	Stoane Street	Summer Hill	Local Road	crossing deficiency	long crossing	-33.88956	151.139503	1		install kerb blisters, built outs	SH78	Primary	HIGH	\$ 10,000
CD2134	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891658	151.137215	1		install new kerb ramp - pair	SH84	Primary	HIGH	\$ 5,000
CD2135	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890441	151.138491	1		install new kerb ramp	SH49	Primary	HIGH	\$ 2,500
CD2151	Smith Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tsgl - pair	-33.8917	151.137074	1		install new Tactile Ground Surface Indicators - pair	SH84	Primary	HIGH	\$ 1,300
CD2152	Smith Street	Summer Hill	Local Road	crossing deficiency	missing crossing point	-33.891783	151.138114	1		install new kerb ramp - pair	SH49	Primary	HIGH	\$ 5,000
CD2153	Unwins Bridge Road	Sydenham	Regional Road	crossing deficiency	missing kerb ramp	-33.916462	151.166629	1		install new kerb ramp	SV7	Primary	HIGH	\$ 2,500
CD2165	Burrows Avenue	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.916252	151.166163	1		install new kerb ramp - pair	SV5	Primary	HIGH	\$ 5,000
CD2167	Burrows Avenue	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915203	151.166124	1		install new kerb ramp - pair	SV5	Primary	HIGH	\$ 5,000
CD2168	Gieson Avenue	Sydenham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915176	151.166105	1		install new kerb ramp - pair	SV5	Primary	HIGH	\$ 5,000
CD2164	Relly Lane	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918362	151.170215	1		install new kerb ramp - pair	SP28	Primary	HIGH	\$ 5,000
CD2168	Rowe Lane	Sydenham	Local Road	crossing deficiency	steep kerb ramp	-33.916798	151.166665	1		install new kerb ramp - pair	SV7	Primary	HIGH	\$ 5,000
CD2169	Unwins Bridge Road	Sydenham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.916422	151.166363	1		install new kerb ramp	SV13	Primary	HIGH	\$ 2,500
CD2170	Cook Street	Tempe	Local Road	crossing deficiency	missing kerb ramp	-33.926554	151.158169	1		install new kerb ramp	TE34	Primary	HIGH	\$ 2,500
CD2171	Cook Street	Tempe	Local Road	crossing deficiency	missing kerb ramp - pair	-33.926535	151.158134	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2179	Union Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924111	151.162336	1		install new kerb ramp	TE12	Primary	HIGH	\$ 2,500
CD2179	Wentworth Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924775	151.160733	1		install new kerb ramp	TE6	Primary	HIGH	\$ 2,500
CD218	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891828	151.125347	1		install new kerb ramp - pair	AF86	Primary	HIGH	\$ 5,000
CD2180	Veneworth Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924664	151.160776	1		install new kerb ramp	TE6	Primary	HIGH	\$ 2,500
CD2181	Fanning Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924497	151.161301	1		install new kerb ramp	TE13	Primary	HIGH	\$ 2,500
CD2189	Brooklyn Street	Tempe	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.922749	151.163038	1		install new kerb ramp - pair	TE5	Primary	HIGH	\$ 5,000
CD219	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891767	151.125387	1		install new kerb ramp - pair	AF86	Primary	HIGH	\$ 5,000
CD2191	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment	-33.923446	151.162307	1		install new kerb ramp	TE12	Primary	HIGH	\$ 2,500
CD2192	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment	-33.924214	151.161524	1		install new kerb ramp	TE13	Primary	HIGH	\$ 2,500
CD2193	Barden Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.923994	151.161711	1		install new kerb ramp	TE13	Primary	HIGH	\$ 2,500
CD2194	Smith Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.923424	151.162487	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2197	Bay Street	Tempe	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.926789	151.158887	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2198	Holbeach Avenue	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.92696	151.158771	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2199	Bay Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.926816	151.158605	1		install new kerb ramp - pair	TE34	Primary	HIGH	\$ 5,000
CD2208	View Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.926819	151.158135	1		install new kerb ramp	TE34	Primary	HIGH	\$ 2,500
CD226	Brown Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.887628	151.125022	1		further investigation required - refuge	AF22	Primary	HIGH	\$ 10,000
CD228	Cavill Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887074	151.121993	1		install new kerb ramp	AF33	Primary	HIGH	\$ 2,500
CD229	Cavill Avenue	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.887123	151.121984	1		install new kerb ramp - pair	AF33	Primary	HIGH	\$ 5,000
CD230	Cavill Avenue	Ashfield	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.887113	151.12196	1		install new Tactile Ground Surface Indicators	AF33	Primary	HIGH	\$ 650
CD231	Charlotts Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885202	151.12897	1		install new kerb ramp - pair	AF36	Primary	HIGH	\$ 5,000
CD251	Granger Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88707	151.126729	1		install new kerb ramp - pair	AF52	Primary	HIGH	\$ 5,000
CD252	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88676	151.125812	1		install new kerb ramp	AF39	Primary	HIGH	\$ 2,500
CD253	Charlotts Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88668	151.12586	1		install new kerb ramp	AF17	Primary	HIGH	\$ 2,500
CD254	Bland Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.886798	151.12486	1		install new kerb ramp	AF17	Primary	HIGH	\$ 2,500
CD255	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886319	151.124889	1		install new kerb ramp - pair	AF39	Primary	HIGH	\$ 5,000
CD256	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.886205	151.124785	1		install new kerb ramp - pair	AF60	Primary	HIGH	\$ 5,000
CD257	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	crossing within roundabout	-33.885362	151.123111	1		install new kerb ramp - pair	AF10	Primary	HIGH	\$ 5,000
CD258	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.885507	151.123212	1		install new kerb ramp - pair	AF33	Primary	HIGH	\$ 5,000
CD259	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.885424	151.122982	1		install new kerb ramp - pair	AF34	Primary	HIGH	\$ 5,000
CD261	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88632	151.12481	1		install new kerb ramp - pair	AF16	Primary	HIGH	\$ 5,000
CD262	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886223	151.124914	1		install new kerb ramp	AF17	Primary	HIGH	\$ 2,500
CD263	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing refuge island	-33.885458	151.123144	1		install new refuge island	AF33	Primary	HIGH	\$ 15,000
CD264	Alt Street	Ashfield	Local Road	crossing deficiency	missing refuge island	-33.885395	151.12313	1		install new refuge island	AF10	Primary	HIGH	\$ 15,000
CD265	Elizabeth Street	Ashfield	Regional Road	crossing deficiency	missing refuge island	-33.885388	151.122983	1		install new refuge island	AF54	Primary	HIGH	\$ 15,000
CD267	Beatrice Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887248	151.11943	1		install new kerb ramp	AF67	Primary	HIGH	\$ 2,500
CD268	Frederick Street	Ashfield	State Road	crossing deficiency	missing kerb ramp - pair	-33.885375	151.119191	1		install new kerb ramp - pair, new refuge island	AF77	Primary	HIGH	\$ 7,000
CD269	Henry Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tsgl	-33.877949	151.127512	1		install new Tactile Ground Surface Indicators	AF69	Primary	HIGH	\$ 650
CD271	Frederick Street	Ashfield	State Road	crossing deficiency	at grade crossing missing tsgl	-33.878923	151.12544	1		install new Tactile Ground Surface Indicators	AF69	Primary	HIGH	\$ 650
CD272	John Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.879662	151.123535	1		install new kerb ramp - pair	AF70	Primary	HIGH	\$ 5,000
CD273	Hedger Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880591	151.122653	1		install new kerb ramp - pair	AF72	Primary	HIGH	\$ 5,000
CD274	Mackay Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.883177	151.120843	1		install new kerb ramp - pair	AF66	Primary	HIGH	\$ 5,000
CD275	Pound Lane	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883562	151.120337	1		install new kerb ramp - pair	AF66	Primary	HIGH	\$ 5,000
CD276	Pound Lane	Ashfield	Local Road	crossing deficiency	shallow kerb ramp - pair	-33.883603	151.120469	1		install new Tactile Ground Surface Indicators	AF66	Primary	HIGH	\$ 650
CD28	Gordon Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887243	151.174443	1		install new kerb ramp - pair	AN85	Primary	HIGH	\$ 5,000
CD281	Eccles Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883549	151.120722	1		install new kerb ramp - pair	AF66	Primary	HIGH	\$ 5,000
CD285	Henry Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.877963	151.127589	1		install new kerb ramp - pair	AF69	Primary	HIGH	\$ 5,000
CD286	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877571	151.128553	1		install new kerb ramp - pair	AF69	Primary	HIGH	\$ 5,000
CD29	Matheson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887403	151.173284	1		install new kerb ramp - pair	AN83	Primary	HIGH	\$ 5,000
CD291	Henry Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877533	151.127623	1		install new kerb ramp	AF69	Primary	HIGH	\$ 2,500
CD292	Norton Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88001	151.127135	1		install new kerb ramp - pair	AF14	Primary	HIGH	\$ 5,000
CD296	Milton Road	Ashfield	State Road	crossing deficiency	improve pedestrian access by providing additional crossing	-33.89009	151.117204	1		consult with TfNSW	AF114	Primary	HIGH	\$ -
CD297	Milton Road	Ashfield	State Road	crossing deficiency	missing kerb ramp	-33.889966	151.117263	1		install new kerb ramp	AF114	Primary	HIGH	\$ 2,500
CD298	Norton Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889876	151.117287	1		install new kerb ramp - pair	AF14	Primary	HIGH	\$ 5,000
CD299	Somerville Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890549	151.11725	1		install new kerb ramp - pair	AF114	Primary	HIGH	\$ 5,000
CD30	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887533	151.171287	1		install new kerb ramp - pair	AN81	Primary	HIGH	\$ 5,000
CD308	Holden Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890453	151.125483	1		install new kerb ramp - pair	AF84	Primary	HIGH	\$ 5,000
CD309	Holden Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891772	151.125416	1		install new kerb ramp - pair	AF84	Primary	HIGH	\$ 2,500
CD310	Holden Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891037	151.125394	1		install new kerb ramp	AF85	Primary	HIGH	\$ 2,500
CD311	Holden Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89182	151.125416	1		install new kerb ramp - pair	AF86	Primary	HIGH	\$ 5,000
CD315	Hugh Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889369	151.122518	1		install new kerb ramp - pair	AF19	Primary	HIGH	\$ 5,000
CD316	Liverpool Road	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889505	151.125957	1		install new kerb ramp	AF30	Primary	HIGH	\$ 2,500
CD317	Frederick Street	Ashfield	State Road	crossing deficiency	misaligned kerb ramp	-33.88436	151.117633	1		install new kerb ramp	AF107	Primary	HIGH	\$ 2,500
CD318	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.88853	151.117439	1		install new kerb ramp	AF112	Primary	HIGH	\$ 2,500
CD319	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.88425	151.117459	1		install new kerb ramp	AF114	Primary	HIGH	\$ 2,500
CD320	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.88482	151.117379	1		install new kerb ramp	AF91	Primary	HIGH	\$ 2,500
CD321	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889165	151.124942	1		install new kerb ramp - pair	SH45	Primary	HIGH	\$ 5,000
CD322	Pembroke Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888407	151.124239	1		install new kerb ramp - pair	AF95	Primary	HIGH	\$ 5,000
CD323	Liverpool Road	Ashfield	State Road	crossing deficiency	misaligned kerb ramp	-33.88406</								

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD332	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890293	151.128312	1		install new kerb ramp - pair	AF100	Primary	HIGH	\$ 5,000
CD333	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890432	151.128239	1		install new kerb ramp - pair	AF150	Primary	HIGH	\$ 5,000
CD334	Liverpool Road	Ashfield	State Road	crossing deficiency	missing kerb ramp	-33.890293	151.128235	1		install new kerb ramp	AF100	Primary	HIGH	\$ 2,500
CD335	Grimmond Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89	151.130359	1		install new kerb ramp - pair	AF95	Primary	HIGH	\$ 5,000
CD336	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889688	151.13068	1		install new kerb ramp - pair	AF96	Primary	HIGH	\$ 5,000
CD338	Carlton Crescent	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889598	151.131630	1		install new kerb ramp - pair	AF97	Primary	HIGH	\$ 5,000
CD340	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890306	151.128181	1		install new kerb ramp - pair	AF150	Primary	HIGH	\$ 5,000
CD342	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.890315	151.128766	1		install new kerb ramp	AF100	Primary	HIGH	\$ 2,500
CD356	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891326	151.128036	1		install new kerb ramp - pair	AF123	Primary	HIGH	\$ 5,000
CD357	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891217	151.12785	1		install new kerb ramp - pair	AF122	Primary	HIGH	\$ 5,000
CD358	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891201	151.127465	1		install new kerb ramp - pair	AF122	Primary	HIGH	\$ 5,000
CD359	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89088	151.126454	1		install new kerb ramp - pair	AF121	Primary	HIGH	\$ 5,000
CD360	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890649	151.125539	1		install new kerb ramp - pair	AF121	Primary	HIGH	\$ 5,000
CD361	A'Beckett Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.889924	151.123786	1		install new kerb ramp	AF120	Primary	HIGH	\$ 2,500
CD362	A'Beckett Avenue	Ashfield	Local Road	crossing deficiency	long crossing	-33.889932	151.123835	1		install kerb extension - pair	AF120	Primary	HIGH	\$ 20,000
CD363	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889355	151.122597	1		install new kerb ramp - pair	AF119	Primary	HIGH	\$ 5,000
CD364	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.889387	151.122789	1		install new kerb ramp	AF119	Primary	HIGH	\$ 2,500
CD365	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890461	151.125456	1		install new kerb ramp - pair	AF117	Primary	HIGH	\$ 5,000
CD366	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890457	151.125573	1		install new kerb ramp - pair	AF121	Primary	HIGH	\$ 5,000
CD367	Norton Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891505	151.13116	1		install new kerb ramp - pair	AF125	Primary	HIGH	\$ 5,000
CD368	Norton Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891404	151.130186	1		install new kerb ramp	AF125	Primary	HIGH	\$ 2,500
CD369	Norton Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891371	151.129966	1		install new kerb ramp - pair	AF124	Primary	HIGH	\$ 5,000
CD370	Hanks Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903895	151.129081	1		install new kerb ramp - pair	AF130	Primary	HIGH	\$ 5,000
CD373	Orangston Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88967	151.128633	1		install new kerb ramp - pair	AF133	Primary	HIGH	\$ 5,000
CD387	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89121	151.128005	1		install new kerb ramp - pair	AF150	Primary	HIGH	\$ 5,000
CD393	Station Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.887407	151.126423	1		install new kerb ramp - pair	AF138	Primary	HIGH	\$ 5,000
CD395	The Esplanade	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.887542	151.124052	1		install new Tactile Ground Surface Indicators	BA2	Primary	HIGH	\$ 650
CD400	Trensever Street	Ashfield	Local Road	long crossing	long crossing	-33.886867	151.137396	1		install kerb extension - pair	AF32	Primary	HIGH	\$ 20,000
CD401	Victoria Street	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.890359	151.129798	1		install new kerb ramp - pair	AF160	Primary	HIGH	\$ 5,000
CD438	Birchgrove Road	Balmmain	Local Road	crossing deficiency	at grade crossing missing tgi	-33.853435	151.177644	1		install new Tactile Ground Surface Indicators	BA46	Primary	HIGH	\$ 650
CD439	Booth Street	Balmmain	Local Road	crossing deficiency	at grade crossing missing tgi	-33.858247	151.182211	1		install new Tactile Ground Surface Indicators	BA15	Primary	HIGH	\$ 650
CD442	Booth Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860049	151.181911	1		install new kerb ramp	BA16	Primary	HIGH	\$ 2,500
CD443	Curtis Road	Balmmain	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.858059	151.183903	1		install new kerb ramp - pair	BA20	Primary	HIGH	\$ 5,000
CD444	Curtis Road	Balmmain	Local Road	crossing deficiency	missing crossing point	-33.857193	151.183296	1		install new kerb ramp - pair	BA20	Primary	HIGH	\$ 5,000
CD459	Curtis Road	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.857111	151.183293	1		install new kerb ramp - pair	BA20	Primary	HIGH	\$ 5,000
CD456	Schultz Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858196	151.172065	1		install new kerb ramp	RO19	Primary	HIGH	\$ 2,500
CD462	Lawson Street	Balmmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.857433	151.172465	1		install new kerb ramp	BA37	Primary	HIGH	\$ 2,500
CD463	High Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858238	151.172130	1		install new kerb ramp	BA20	Primary	HIGH	\$ 2,500
CD464	Darling Street	Balmmain	Local Road	crossing deficiency	long crossing point	-33.858145	151.184697	1		install new refuge island	BA27	Primary	HIGH	\$ 15,000
CD465	Darling Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858191	151.184697	1		install new kerb ramp - pair	BA27	Primary	HIGH	\$ 5,000
CD466	Darling Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858105	151.186146	1		install new kerb ramp - pair	BA26	Primary	HIGH	\$ 5,000
CD467	Darling Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858167	151.187043	1		install new kerb ramp	BA26	Primary	HIGH	\$ 2,500
CD468	Darling Street	Balmmain	Local Road	crossing deficiency	steep kerb ramp	-33.858264	151.186228	1		install new kerb ramp - pair	BA26	Primary	HIGH	\$ 5,000
CD469	Darling Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858294	151.185526	1		install new kerb ramp - pair	BA26	Primary	HIGH	\$ 5,000
CD470	Darling Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857952	151.183786	1		install new kerb ramp	BA26	Primary	HIGH	\$ 2,500
CD471	Lawson Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857407	151.172421	1		install new kerb ramp	BA37	Primary	HIGH	\$ 2,500
CD472	Darvall Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.859646	151.18235	1		install new kerb ramp	BA39	Primary	HIGH	\$ 2,500
CD473	Eaton Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858138	151.183787	1		install new kerb ramp	BA40	Primary	HIGH	\$ 2,500
CD474	Eaton Street	Balmmain	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.858171	151.183783	1		install new Tactile Ground Surface Indicators - pair	BA40	Primary	HIGH	\$ 1,300
CD475	Eaton Street	Balmmain	Local Road	crossing deficiency	missing kerb ramp	-33.858699	151.183605	1		install new kerb ramp	BA40	Primary	HIGH	\$ 5,000
CD476	Eaton Street	Balmmain	Local Road	crossing deficiency	missing kerb ramp - pair	-33.858965	151.183796	1		install new kerb ramp - pair	BA40	Primary	HIGH	\$ 5,000
CD496	Jane Street	Balmmain	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.858178	151.184383	1		install new Tactile Ground Surface Indicators - pair	BA44	Primary	HIGH	\$ 1,300
CD495	Jane Street	Balmmain	Local Road	crossing deficiency	missing kerb ramp	-33.858786	151.184452	1		install new kerb ramp - pair	BA44	Primary	HIGH	\$ 5,000
CD496	Jane Street	Balmmain	Local Road	crossing deficiency	missing kerb ramp	-33.85873	151.184428	1		install new kerb ramp	BA44	Primary	HIGH	\$ 2,500
CD497	Macquarie Terrace	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.853896	151.176969	1		install new kerb ramp - pair	BA46	Primary	HIGH	\$ 5,000
CD498	Macquarie Terrace	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.854036	151.178225	1		install new kerb ramp - pair	BA46	Primary	HIGH	\$ 5,000
CD507	Reynolds Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.861204	151.176843	1		install new kerb ramp	BA60	Primary	HIGH	\$ 2,500
CD508	Reynolds Street	Balmmain	Local Road	crossing deficiency	missing kerb ramp	-33.861277	151.176761	1		install new kerb ramp	BA51	Primary	HIGH	\$ 2,500
CD509	Reynolds Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.861252	151.176693	1		install new kerb ramp	BA51	Primary	HIGH	\$ 2,500
CD525	Robert Street	Balmmain	Local Road	crossing deficiency	missing kerb ramp	-33.861326	151.177112	1		install new kerb ramp	BA60	Primary	HIGH	\$ 2,500
CD526	Rowntree Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854543	151.178599	1		install new kerb ramp	BA46	Primary	HIGH	\$ 2,500
CD535	Wortley Street	Balmmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861451	151.177142	1		install new kerb ramp - pair	BA60	Primary	HIGH	\$ 5,000
CD547	Darling Street	Balmmain East	Local Road	crossing deficiency	steep kerb ramp	-33.857162	151.190509	1		install new kerb ramp - pair	BE2	Primary	HIGH	\$ 2,500
CD548	Darling Street	Balmmain East	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857321	151.193594	1		install new kerb ramp	BE2	Primary	HIGH	\$ 5,000
CD549	Darling Street	Balmmain East	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857214	151.194316	1		install new kerb ramp	BE2	Primary	HIGH	\$ 2,500
CD550	Darling Street East	Balmmain East	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.857127	151.193332	1		install new kerb ramp - pair	BE2	Primary	HIGH	\$ 2,500
CD562	Tooths Place	Camperdown	Local Road	crossing deficiency	misaligned kerb ramp	-33.890895	151.176241	1		install new kerb ramp	CA12	Primary	HIGH	\$ 2,500
CD583	Victory Lane	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887242	151.176675	1		install new kerb ramp	CA11	Primary	HIGH	\$ 2,500
CD584	Cardigan Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887753	151.176653	1		install new kerb ramp - pair	AN83	Primary	HIGH	\$ 5,000
CD585	Paranatta Road	Camperdown	State Road	crossing deficiency	poor kerb ramp alignment	-33.881748	151.173644	1		install new kerb ramp - pair	AN86	Primary	HIGH	\$ 5,000
CD61	View Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873995	151.174686	1		install new kerb ramp	AN86	Primary	HIGH	\$ 2,500
CD616	Holborow Street	Croydon	Local Road	crossing deficiency	long crossing	-33.887267	151.113919	1		install kerb extension - pair	CR23	Primary	HIGH	\$ 20,000
CD615	Highway Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887467	151.114512	1		install new kerb ramp - pair	CR24	Primary	HIGH	\$ 5,000
CD62	The Crescent	Annandale	State Road	crossing deficiency	potential mid block crossing point - kerb extensions	-33.874816	151.174686	1		consult with TfNSW	AN86	Primary	HIGH	\$ 5,000
CD620	Wetherill Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887933	151.113599	1		install new kerb ramp - pair	CR25	Primary	HIGH	\$ 5,000
CD621	Wetherill Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886966	151.115447	1		install new kerb ramp	CR25	Primary	HIGH	\$ 2,500
CD622	Holborow Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887256	151.113953	1		install new kerb ramp	CR23	Primary	HIGH	\$ 2,500
CD623	Greenhills Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886926	151.113256	1		install new kerb ramp	CR23	Primary	HIGH	\$ 2,500
CD63	Booth Street	Annandale	Regional Road	crossing deficiency	missing crossing point	-33.881559	151.172183	1		install new kerb ramp - pair	AN26	Primary	HIGH	\$ 5,000
CD646	Seaview Street	Dulwich Hill	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.90261	151.144895	1		future investigation required - pedestrian crossing	DH94	Primary	HIGH	\$ 10,000
CD670	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.902472	151.138825	1		install new kerb ramp	DH10	Primary	HIGH	\$ 2,500
CD674	Dulwich Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901445	151.14028	1		install new kerb ramp - pair	DH25	Primary	HIGH	\$ 5,000
CD675	Dulwich Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903258	151.142379	1		install new kerb ramp - pair	DH26	Primary	HIGH	\$ 5,000
CD676	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgi	-33.910106	151.137693	1		install new Tactile Ground Surface Indicators	DH26	Primary	HIGH	\$ 650
CD680	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.909632	151.137659	1		install new kerb ramp	DH31	Primary	HIGH	\$ 2,500
CD681	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910649	151.138976	1		install new kerb ramp - pair	DH29	Primary	HIGH	\$ 5,000
CD682	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.911447	151.139395	1		install new kerb ramp	DH31	Primary	HIGH	\$ 2,500
CD684	Ewart Street	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910302	151.138251	1		install new kerb ramp - pair	DH31	Primary	HIGH	\$ 5,000
CD699	Hill													

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD715	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment	-33.903326	151.142456	1		install new kerb ramp	DH97	Primary	HIGH	\$ 2,500
CD716	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment	-33.903394	151.142372	1		install new kerb ramp	DH76	Primary	HIGH	\$ 2,500
CD717	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp construction	-33.903368	151.142329	1		install new kerb ramp	DH67	Primary	HIGH	\$ 2,500
CD718	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.903822	151.141053	1		install new kerb ramp - pair	DH88	Primary	HIGH	\$ 5,000
CD719	Beach Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903825	151.141054	1		install new kerb ramp	DH88	Primary	HIGH	\$ 2,500
CD720	Beach Road	Dulwich Hill	Local Road	crossing deficiency	narrow kerb ramp	-33.903971	151.140956	1		install new kerb ramp	DH88	Primary	HIGH	\$ 2,500
CD721	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.903953	151.140904	1		install new kerb ramp	DH88	Primary	HIGH	\$ 2,500
CD723	Myra Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905858	151.135932	1		install new kerb ramp	DH86	Primary	HIGH	\$ 2,500
CD724	Garnet Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.905868	151.134424	1		install new kerb ramp	DH87	Primary	HIGH	\$ 2,500
CD725	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.905713	151.133338	1		consult with City of Canterbury-Bankstown	DH89	Primary	HIGH	\$ -
CD726	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	missing kerb ramp - pair	-33.905172	151.133277	1		consult with City of Canterbury-Bankstown	DH89	Primary	HIGH	\$ -
CD729	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	missing kerb ramp	-33.905189	151.133352	1		install new kerb ramp	DH89	Primary	HIGH	\$ 2,500
CD730	Union Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905712	151.133586	1		install new kerb ramp	DH87	Primary	HIGH	\$ 2,500
CD731	Denson Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905034	151.137707	1		install new kerb ramp	DH84	Primary	HIGH	\$ 2,500
CD732	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.90382	151.140856	1		install new kerb ramp - pair	DH88	Primary	HIGH	\$ 5,000
CD733	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.903811	151.140842	1		install new kerb ramp	DH88	Primary	HIGH	\$ 2,500
CD734	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	steep kerb ramp	-33.903817	151.140856	1		install new kerb ramp - pair	DH88	Primary	HIGH	\$ 5,000
CD735	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	misaligned kerb ramp	-33.903803	151.141045	1		install new kerb ramp	DH88	Primary	HIGH	\$ 2,500
CD736	Dulwich Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903205	151.142379	1		install new kerb ramp	DH26	Primary	HIGH	\$ 2,500
CD737	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment	-33.903256	151.142454	1		install new kerb ramp	DH86	Primary	HIGH	\$ 2,500
CD738	Lewisham Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902944	151.143205	1		install new kerb ramp - pair	DH86	Primary	HIGH	\$ 5,000
CD739	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	narrow kerb ramp - pair	-33.902682	151.143809	1		install new kerb ramp - pair	DH86	Primary	HIGH	\$ 5,000
CD740	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903274	151.142322	1		install new kerb ramp - pair	DH87	Primary	HIGH	\$ 5,000
CD741	Farmount Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898059	151.137949	1		install new kerb ramp - pair	DH86	Primary	HIGH	\$ 5,000
CD750	Hugh Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901371	151.131607	1		install new kerb ramp - pair	AF126	Primary	HIGH	\$ 5,000
CD751	Elizabeth Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902416	151.130674	1		install new kerb ramp - pair	AF128	Primary	HIGH	\$ 5,000
CD752	Cobar Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903555	151.128719	1		install new kerb ramp - pair	AF129	Primary	HIGH	\$ 5,000
CD753	Cobar Street	Dulwich Hill	Local Road	crossing deficiency	long crossing point	-33.903579	151.128653	1		install kerb extension / refuge island	AF129	Primary	HIGH	\$ 10,000
CD754	Old Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904672	151.128693	1		install new kerb ramp - pair	DH82	Primary	HIGH	\$ 5,000
CD774	Warrell Road	Dulwich Hill	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.911207	151.141173	1		install new kerb ramp - pair	MV84	Primary	HIGH	\$ 5,000
CD776	Koili Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.910229	151.141894	1		install new kerb ramp - pair	DH125	Primary	HIGH	\$ 2,500
CD778	Margaret Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.908917	151.143231	1		install new kerb ramp - pair	DH126	Primary	HIGH	\$ 5,000
CD778	Kays Avenue West	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.909742	151.142499	1		install new kerb ramp	DH126	Primary	HIGH	\$ 2,500
CD779	Wilga Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.910249	151.142053	1		install new kerb ramp	DH125	Primary	HIGH	\$ 2,500
CD786	Lynch Avenue	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.902132	151.171895	1		install new kerb ramp	EN3	Primary	HIGH	\$ 2,500
CD796	Stannmore road	Enmore	State Road	crossing deficiency	misaligned kerb ramp	-33.899521	151.170816	1		install new kerb ramp	EN13	Primary	HIGH	\$ 2,500
CD797	Enmore Road	Enmore	State Road	crossing deficiency	poor kerb ramp alignment	-33.899595	151.170777	1		install new kerb ramp	EN8	Primary	HIGH	\$ 2,500
CD798	Lidett Street	Enmore	Local Road	crossing deficiency	missing kerb ramp	-33.900927	151.170924	1		install new kerb ramp	MV83	Primary	HIGH	\$ 2,500
CD799	Francis Street	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900073	151.170792	1		install new kerb ramp	EN8	Primary	HIGH	\$ 2,500
CD8	Albion Lane	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887416	151.167894	1		install new kerb ramp - pair	AN55	Primary	HIGH	\$ 5,000
CD800	Edgeware Road	Enmore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.899571	151.170962	1		install new kerb ramp	EN8	Primary	HIGH	\$ 2,500
CD801	Enmore Road	Enmore	State Road	crossing deficiency	poor kerb ramp alignment	-33.898457	151.171042	1		install new kerb ramp	EN6	Primary	HIGH	\$ 2,500
CD802	Enmore Road	Enmore	State Road	crossing deficiency	misaligned kerb ramp	-33.899154	151.172025	1		install new kerb ramp	EN7	Primary	HIGH	\$ 2,500
CD803	Enmore Road	Enmore	State Road	crossing deficiency	misaligned kerb ramp	-33.898949	151.172825	1		install new kerb ramp	EN7	Primary	HIGH	\$ 2,500
CD804	Edgeware Road	Enmore	Regional Road	crossing deficiency	at grade crossing missing tpsl	-33.899461	151.171077	1		install new Tactile Ground Surface Indicators	EN6	Primary	HIGH	\$ 650
CD812	Stannmore Road	Enmore	State Road	crossing deficiency	poor kerb ramp alignment	-33.898899	151.169590	1		install new kerb ramp	EN13	Primary	HIGH	\$ 2,500
CD814	Tupper Street	Enmore	Local Road	crossing deficiency	misaligned kerb ramp	-33.898785	151.168952	1		install new kerb ramp	EN14	Primary	HIGH	\$ 2,500
CD816	Marion Street	Haberfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.884155	151.143874	1		further investigation required - pedestrian crossing	H400	Primary	HIGH	\$ 10,000
CD818	Ramsey Street	Haberfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.876466	151.135906	1		further investigation required - pedestrian crossing	H403	Primary	HIGH	\$ 10,000
CD837	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880458	151.138738	1		install new kerb ramp - pair	H400	Primary	HIGH	\$ 5,000
CD838	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88034	151.138895	1		install new kerb ramp - pair	H434	Primary	HIGH	\$ 5,000
CD839	Dalhousie Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.879881	151.139171	1		install new Tactile Ground Surface Indicators - pair	H434	Primary	HIGH	\$ 1,300
CD840	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877708	151.140738	1		install new kerb ramp	H432	Primary	HIGH	\$ 2,500
CD844	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878991	151.140024	1		install new kerb ramp - pair	H432	Primary	HIGH	\$ 5,000
CD845	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880494	151.138889	1		install new kerb ramp - pair	H403	Primary	HIGH	\$ 5,000
CD846	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880522	151.138851	1		install new kerb ramp - pair	H403	Primary	HIGH	\$ 5,000
CD847	Dalhousie Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.880955	151.138589	1		install new Tactile Ground Surface Indicators - pair	H436	Primary	HIGH	\$ 1,300
CD860	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.889395	151.144444	1		install kerb extension	H405	Primary	HIGH	\$ 10,000
CD862	Hawthorne Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884191	151.143972	1		install new kerb ramp - pair	H461	Primary	HIGH	\$ 5,000
CD863	Marion Street	Haberfield	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884468	151.142134	1		install new kerb ramp	H460	Primary	HIGH	\$ 2,500
CD864	Hawthorne Parade	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.88408	151.144179	1		install new kerb ramp	H461	Primary	HIGH	\$ 2,500
CD874	Wattle Street	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877229	151.129953	1		install new kerb ramp - pair	H466	Primary	HIGH	\$ 5,000
CD875	Wattle Street	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877162	151.130019	1		install new kerb ramp - pair	H466	Primary	HIGH	\$ 5,000
CD876	Walker Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.87808	151.130638	1		install new kerb ramp - pair	H467	Primary	HIGH	\$ 5,000
CD880	Ramsey Street	Haberfield	Regional Road	crossing deficiency	missing crossing point	-33.881372	151.139995	1		install new kerb ramp - pair	H465	Primary	HIGH	\$ 5,000
CD881	Kingsford Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.881462	151.13988	1		install new kerb ramp - pair	H465	Primary	HIGH	\$ 5,000
CD884	Yasmar Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878598	151.137229	1		install new kerb ramp - pair	H469	Primary	HIGH	\$ 5,000
CD888	Walker Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876151	151.135282	1		install new kerb ramp - pair	H463	Primary	HIGH	\$ 5,000
CD891	All Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876841	151.135891	1		install new kerb ramp - pair	H468	Primary	HIGH	\$ 5,000
CD892	Enmore Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876251	151.137351	1		install new kerb ramp - pair	H469	Primary	HIGH	\$ 5,000
CD893	Ramsey Street	Haberfield	Regional Road	crossing deficiency	opportunity to raise pedestrian crossing within town centre	-33.878495	151.137248	1		further investigation required - raised pedestrian crossing	H469	Primary	HIGH	\$ 15,000
CD894	Ramsey Street	Haberfield	Regional Road	crossing deficiency	at grade crossing missing tpsl - pair	-33.878554	151.138383	1		install new Tactile Ground Surface Indicators - pair	H460	Primary	HIGH	\$ 1,300
CD91	White Creek Lane	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88169	151.170792	1		install new kerb ramp - pair	AF130	Primary	HIGH	\$ 5,000
CD926	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904554	151.128671	1		consult with City of Canterbury-Bankstown	DH82	Primary	HIGH	\$ 5,000
CD935	Waratan Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.881258	151.15995	1		install new kerb ramp	H110	Primary	HIGH	\$ 2,500
CD940	Moore Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.879231	151.164093	1		install new kerb ramp	H1107	Primary	HIGH	\$ 2,500
CD950	Catherine Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.876234	151.164113	1		install new kerb ramp	H1107	Primary	HIGH	\$ 2,500
CD951	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp construction	-33.87919	151.164283	1		install new kerb ramp	H1108	Primary	HIGH	\$ 2,500
CD955	James Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment	-33.875194	151.165335	1		install new kerb ramp	H1114	Primary	HIGH	\$ 2,500
CD971	Dearyville Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881097	151.158805	1		install new kerb ramp - pair	H144	Primary	HIGH	\$ 5,000
CD999	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878122	151.170555	1		install new kerb ramp - pair	AN8	Primary	HIGH	\$ 5,000
CD991	Elswick Street	Leichhardt	Local Road	crossing deficiency	traffic post narrows kerb ramp	-33.884248	151.149939	1		consult with TfNSW	UH95	Primary	HIGH	\$ -
CD992	Foster Street	Leichhardt	State Road	crossing deficiency	misaligned kerb ramp	-33.88422	151.147642	1		install new kerb ramp	UH94	Primary	HIGH	\$ 2,500
CD993	Marion Street	Leichhardt	Regional Road	crossing deficiency	missing kerb ramp	-33.884195	151.14766	1		install new kerb ramp	UH94	Primary	HIGH	\$ 2,500
													SUBTOTAL	\$ 2,880,150

P4909 Inner West PAMP Detailed Works Program Crossing Deficiencies 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873888	151.172547	1		install new kerb ramp	AN3	Secondary	MED	\$	2,500
CD10	Johnston Street	Annandale	State Road	crossing deficiency	misaligned kerb ramp	-33.885777	151.168895	1		install new kerb ramp	AN42	Secondary	MED	\$	2,500
CD101	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88318	151.168222	1		install new Tactile Ground Surface Indicators	AN14	Secondary	MED	\$	650
CD1000	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88679	151.14976	1		install new kerb ramp - pair	UH5	Secondary	MED	\$	5,000
CD1001	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887674	151.149464	1		install new kerb ramp	UH60	Secondary	MED	\$	2,500
CD1002	Flood Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.886914	151.14898	1		install new kerb ramp	UH135	Secondary	MED	\$	2,500
CD1006	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.886365	151.148957	1		install new Tactile Ground Surface Indicators	UH12	Secondary	MED	\$	650
CD101	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882384	151.168704	1		install new kerb ramp - pair	AN12	Secondary	MED	\$	5,000
CD1012	Flood Street	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.885577	151.149888	1		install new kerb ramp - pair	UH2	Secondary	MED	\$	5,000
CD1013	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.883768	151.14985	1		install new Tactile Ground Surface Indicators - pair	UH7	Secondary	MED	\$	1,300
CD1017	Foster Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment	-33.88593	151.147574	1		install new kerb ramp	UH8	Secondary	MED	\$	2,500
CD1019	Lords Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88607	151.147532	1		install new kerb ramp	UH87	Secondary	MED	\$	2,500
CD102	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.883184	151.168234	1		install new Tactile Ground Surface Indicators	AN14	Secondary	MED	\$	650
CD1020	Foster Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment	-33.885963	151.147706	1		install new kerb ramp	UH8	Secondary	MED	\$	2,500
CD1022	Foster Street	Leichhardt	State Road	crossing deficiency	misaligned kerb ramp	-33.88593	151.147731	1		install new kerb ramp	UH8	Secondary	MED	\$	2,500
CD1023	Lords Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886043	151.14775	1		install new kerb ramp	UH8	Secondary	MED	\$	2,500
CD1024	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.883269	151.161299	1		install new kerb ramp - pair	UH90	Secondary	MED	\$	5,000
CD1025	Leichhardt Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp construction	-33.883182	151.161236	1		install new kerb ramp	UH3	Secondary	MED	\$	2,500
CD1026	Lords Road	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.885962	151.148314	1		install new Tactile Ground Surface Indicators	UH8	Secondary	MED	\$	650
CD1027	Lords Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88607	151.148607	1		install new kerb ramp	UH7	Secondary	MED	\$	2,500
CD1028	Lords Road	Leichhardt	Local Road	crossing deficiency	long driveway crossing point	-33.885762	151.148463	1		no action	UH8	Secondary	MED	\$	-
CD1029	Lords Road	Leichhardt	Local Road	crossing deficiency	long driveway crossing point	-33.885801	151.148442	1		no action	UH8	Secondary	MED	\$	-
CD103	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88314	151.168216	1		install new kerb ramp	AN34	Secondary	MED	\$	2,500
CD1030	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.88445	151.161034	1		install new kerb ramp	UH147	Secondary	MED	\$	2,500
CD1031	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.884417	151.161133	1		install new kerb ramp	UH147	Secondary	MED	\$	2,500
CD1035	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884088	151.152036	1		install new kerb ramp	UH8	Secondary	MED	\$	2,500
CD1036	Erskine Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.884161	151.151589	1		install new kerb ramp - pair	UH46	Secondary	MED	\$	5,000
CD1037	Erskine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.884032	151.151688	1		install new kerb ramp	UH97	Secondary	MED	\$	2,500
CD1038	Marion Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.884079	151.151889	1		install new kerb ramp - pair	UH97	Secondary	MED	\$	5,000
CD1039	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884197	151.151096	1		install new kerb ramp	UH97	Secondary	MED	\$	2,500
CD1040	Marion Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.884143	151.150094	1		install new kerb ramp	UH97	Secondary	MED	\$	2,500
CD1045	Foster Street	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment	-33.88413	151.147534	1		install new kerb ramp	UH71	Secondary	MED	\$	2,500
CD1046	Marion Street	Leichhardt	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.884092	151.145378	1		install new Tactile Ground Surface Indicators	UH92	Secondary	MED	\$	650
CD1048	Catharine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879311	151.164138	1		install new kerb ramp	UH24	Secondary	MED	\$	2,500
CD1049	John Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877769	151.166228	1		install new kerb ramp	UH109	Secondary	MED	\$	2,500
CD105	Booth Street	Annandale	Regional Road	crossing deficiency	narrow kerb ramp	-33.881	151.169297	1		install new kerb ramp	AN11	Secondary	MED	\$	2,500
CD1050	Moore Street	Leichhardt	Regional Road	crossing deficiency	missing crossing point	-33.879754	151.166258	1		install new kerb ramp - pair	UH109	Secondary	MED	\$	5,000
CD1051	Moore Street	Leichhardt	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.878638	151.166257	1		install new Tactile Ground Surface Indicators	UH110	Secondary	MED	\$	650
CD1053	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.878769	151.161921	1		install new kerb ramp	UH104	Secondary	MED	\$	2,500
CD1054	MacKenzie Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.878784	151.161971	1		install new kerb ramp	UH105	Secondary	MED	\$	2,500
CD1055	Alnaworth Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.878655	151.16248	1		install new kerb ramp	UH105	Secondary	MED	\$	2,500
CD1056	White Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878777	151.166846	1		install new kerb ramp	UH110	Secondary	MED	\$	2,500
CD1057	Alnaworth Street	Leichhardt	Local Road	crossing deficiency	steep kerb ramp	-33.878862	151.162513	1		install new kerb ramp - pair	UH105	Secondary	MED	\$	5,000
CD1058	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88096	151.169307	1		install new kerb ramp	AN11	Secondary	MED	\$	2,500
CD1065	Norton Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877223	151.156315	1		install new kerb ramp - pair	UH128	Secondary	MED	\$	5,000
CD1066	Norton Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877151	151.156128	1		install new kerb ramp - pair	UH126	Secondary	MED	\$	5,000
CD107	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88092	151.169327	1		install new kerb ramp	AN10	Secondary	MED	\$	2,500
CD1071	Catharine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887893	151.161242	1		install new kerb ramp - pair	UH144	Secondary	MED	\$	5,000
CD108	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.880449	151.168603	1		install new Tactile Ground Surface Indicators - pair	UH10	Secondary	MED	\$	1,300
CD1082	George Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889058	151.148488	1		install new kerb ramp - pair	UH34	Secondary	MED	\$	5,000
CD1085	Prospect Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.884458	151.160544	1		install new kerb ramp - pair	UH147	Secondary	MED	\$	5,000
CD1086	Prospect Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.884457	151.160535	1		install new kerb ramp	UH147	Secondary	MED	\$	2,500
CD1087	Prospect Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.884416	151.160492	1		install new kerb ramp	UH147	Secondary	MED	\$	2,500
CD1088	Hay Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.884487	151.160488	1		install new kerb ramp	UH147	Secondary	MED	\$	2,500
CD1089	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.880089	151.168751	1		install new Tactile Ground Surface Indicators	AN22	Secondary	MED	\$	1,300
CD1090	John Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882791	151.165407	1		install new kerb ramp - pair	UH150	Secondary	MED	\$	5,000
CD1091	Emma Lane	Leichhardt	Regional Road	crossing deficiency	raised kerb ramp lip	-33.882864	151.164907	1		install new kerb ramp	UH151	Secondary	MED	\$	2,500
CD1092	Styles Street	Leichhardt	Regional Road	crossing deficiency	raised kerb ramp	-33.882868	151.164853	1		install new kerb ramp	UH151	Secondary	MED	\$	2,500
CD1093	Emma Lane	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.882927	151.164416	1		install new kerb ramp - pair	UH148	Secondary	MED	\$	5,000
CD1094	Thorby Avenue	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882977	151.164416	1		install new kerb ramp - pair	UH148	Secondary	MED	\$	5,000
CD1095	Coleridge Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.883269	151.161884	1		install new kerb ramp	UH149	Secondary	MED	\$	2,500
CD1096	Styles Street	Leichhardt	Regional Road	crossing deficiency	missing kerb ramp	-33.883376	151.162024	1		install new kerb ramp	UH149	Secondary	MED	\$	2,500
CD1097	Coleridge Lane	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.883197	151.162313	1		install new kerb ramp - pair	UH149	Secondary	MED	\$	5,000
CD1098	Styles Street	Leichhardt	Regional Road	crossing deficiency	narrow refuge island	-33.882698	151.162034	1		install new refuge island	AN33	Secondary	MED	\$	15,000
CD11	Bignell Lane	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886099	151.176235	1		install new kerb ramp	AN19	Secondary	MED	\$	2,500
CD1100	Keyworth Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88703	151.147386	1		install new kerb ramp - pair	UH154	Secondary	MED	\$	5,000
CD1101	Keyworth Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887094	151.147313	1		install new kerb ramp - pair	UH154	Secondary	MED	\$	5,000
CD1102	Benson Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887924	151.147137	1		install new kerb ramp	UH154	Secondary	MED	\$	2,500
CD1103	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.884052	151.165038	1		install new Tactile Ground Surface Indicators - pair	UH161	Secondary	MED	\$	1,300
CD1104	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.884052	151.165038	1		install new Tactile Ground Surface Indicators - pair	UH161	Secondary	MED	\$	1,300
CD1105	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.885008	151.164792	1		install new Tactile Ground Surface Indicators - pair	UH162	Secondary	MED	\$	1,300
CD1106	White Creek	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.883942	151.165139	1		install new kerb ramp - pair	UH163	Secondary	MED	\$	5,000
CD1107	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.886871	151.164993	1		install new Tactile Ground Surface Indicators - pair	UH164	Secondary	MED	\$	1,300
CD1108	White Creek	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.886365	151.164099	1		install new kerb ramp	UH165	Secondary	MED	\$	2,500
CD1109	White Creek	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.886268	151.164173	1		install new kerb ramp	UH166	Secondary	MED	\$	2,500
CD1110	White Creek	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.886362	151.164105	1		install new Tactile Ground Surface Indicators	UH167	Secondary	MED	\$	650
CD1111	White Creek	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.886362	151.163369	1		install new kerb ramp	UH168	Secondary	MED	\$	2,500
CD1112	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.87734	151.156443	1		install new kerb ramp	UH169	Secondary	MED	\$	2,500
CD1113	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.87749	151.152042	1		install new kerb ramp	UH170	Secondary	MED	\$	2,500
CD1115	William Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877225	151.156285	1		install new Tactile Ground Surface Indicators	UH171	Secondary	MED	\$	650
CD1116	William Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877252	151.157563	1		install new Tactile Ground Surface Indicators	UH172	Secondary	MED	\$	650
CD1117	William Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.877261	151.157481	1		install new kerb ramp	UH173	Secondary	MED	\$	2,500
CD1118	William Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.877764	151.150239	1		re-construct refuge island	UH174	Secondary	MED	\$	15,000
CD1119	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877481	151.149197	1		install new kerb ramp - pair	UH175	Secondary	MED	\$	5,000
CD1120	William Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877603</									

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1131	William Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp - pair	-33.8776	151.152178	1		install new kerb ramp - pair	UH187	Secondary	MED		\$ 5,000
CD1132	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned refuge island	-33.880226	151.149891	1		re-construct refuge island	UH188	Secondary	MED		\$ 15,000
CD1133	Allen Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.882432	151.148791	1		install new Tactile Ground Surface Indicators	UH189	Secondary	MED		\$ 650
CD1134	Allen Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.880415	151.149584	1		install new kerb ramp	UH190	Secondary	MED		\$ 2,500
CD1136	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.880203	151.153377	1		install new kerb ramp - pair	UH191	Secondary	MED		\$ 5,000
CD1137	Allen Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.880069	151.154526	1		install new kerb ramp	UH192	Secondary	MED		\$ 2,500
CD1138	Allen Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.880061	151.154584	1		install new kerb ramp	UH193	Secondary	MED		\$ 2,500
CD1139	Allen Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.880102	151.156007	1		install new kerb ramp	UH194	Secondary	MED		\$ 2,500
CD1140	Allen Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879943	151.155794	1		install new kerb ramp	UH195	Secondary	MED		\$ 2,500
CD1143	Balmn Road	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.878162	151.154668	1		install new kerb ramp	UH196	Secondary	MED		\$ 2,500
CD115	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878108	151.17055	1		install new Tactile Ground Surface Indicators	UH197	Secondary	MED		\$ 650
CD1156	Prospect Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884515	151.159195	1		install new kerb ramp - pair	UH198	Secondary	MED		\$ 5,000
CD116	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878042	151.170576	1		install new Tactile Ground Surface Indicators	UH199	Secondary	MED		\$ 650
CD1160	Style Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp	-33.883185	151.162653	1		install new kerb ramp	UH200	Secondary	MED		\$ 2,500
CD1161	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887213	151.161611	1		install new kerb ramp	UH201	Secondary	MED		\$ 2,500
CD1162	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.887058	151.161662	1		install new Tactile Ground Surface Indicators	UH202	Secondary	MED		\$ 650
CD1164	Carrington Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894468	151.147637	1		install new kerb ramp	UH203	Secondary	MED		\$ 2,500
CD1169	Hunter Street	Lewisham	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.895509	151.149447	1		install new kerb ramp - pair	UH204	Secondary	MED		\$ 5,000
CD117	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879009	151.171669	1		install new kerb ramp	UH205	Secondary	MED		\$ 2,500
CD1170	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895022	151.149439	1		install new kerb ramp	UH206	Secondary	MED		\$ 2,500
CD1171	Hunter Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895244	151.149209	1		install new kerb ramp	UH207	Secondary	MED		\$ 2,500
CD1172	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895096	151.149246	1		install new kerb ramp	UH208	Secondary	MED		\$ 2,500
CD1173	Hunter Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.895193	151.149228	1		install new kerb ramp	UH209	Secondary	MED		\$ 2,500
CD118	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878617	151.171711	1		install new kerb ramp	UH210	Secondary	MED		\$ 2,500
CD1181	Gould Avenue	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.898134	151.149195	1		install new Tactile Ground Surface Indicators	UH211	Secondary	MED		\$ 650
CD1182	Henry Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894035	151.145379	1		install new kerb ramp	UH212	Secondary	MED		\$ 2,500
CD1186	McGill Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895063	151.145783	1		install new kerb ramp	UH213	Secondary	MED		\$ 2,500
CD1187	McGill Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895068	151.145783	1		install new kerb ramp	UH214	Secondary	MED		\$ 2,500
CD1188	Old Canterbury Road	Lewisham	State Road	crossing deficiency	long crossing	-33.895069	151.144053	1		requires further investigation - long crossing	UH215	Secondary	MED		\$ 5,000
CD1189	Old Canterbury Road	Lewisham	State Road	crossing deficiency	missing crossing point	-33.895198	151.144209	1		further investigation required - pedestrian refuge or crossing (signal)	UH216	Secondary	MED		\$ 15,000
CD119	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.878681	151.171708	1		re-construct refuge island	UH217	Secondary	MED		\$ 15,000
CD1192	Paramatta Road	Lewisham	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.895953	151.148906	1		install new kerb ramp - pair	UH218	Secondary	MED		\$ 5,000
CD1194	Smith Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893422	151.14337	1		install new kerb ramp	UH219	Secondary	MED		\$ 2,500
CD1196	Thomas Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.891453	151.147992	1		install new kerb ramp - pair	UH220	Secondary	MED		\$ 5,000
CD1199	Toothill Street	Lewisham	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.896345	151.146714	1		install new Tactile Ground Surface Indicators	UH221	Secondary	MED		\$ 650
CD12	Bignell Lane	Annandale	Local Road	crossing deficiency	poor kerb ramp construction	-33.886159	151.176304	1		install new kerb ramp	UH222	Secondary	MED		\$ 2,500
CD120	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878356	151.172571	1		install new Tactile Ground Surface Indicators	UH223	Secondary	MED		\$ 650
CD1200	Toothill Street	Lewisham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.896917	151.146238	1		install new kerb ramp	UH224	Secondary	MED		\$ 2,500
CD1201	Toothill Street	Lewisham	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.896942	151.146463	1		install new kerb ramp - pair	UH225	Secondary	MED		\$ 5,000
CD1202	Toothill Street	Lewisham	Regional Road	crossing deficiency	misaligned refuge island	-33.896913	151.146431	1		re-construct refuge island	UH226	Secondary	MED		\$ 15,000
CD1205	Toothill Street	Lewisham	Regional Road	crossing deficiency	narrow kerb ramp	-33.897617	151.147062	1		install new kerb ramp	UH227	Secondary	MED		\$ 2,500
CD1206	Toothill Street	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.894914	151.144458	1		install new kerb ramp	UH228	Secondary	MED		\$ 2,500
CD1210	Old Canterbury Road	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893083	151.145792	1		install new kerb ramp - pair	UH229	Secondary	MED		\$ 5,000
CD1211	Longport Street	Lewisham	Regional Road	crossing deficiency	narrow kerb ramp	-33.893093	151.145891	1		install new kerb ramp	UH230	Secondary	MED		\$ 2,500
CD1212	Trillager Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp	-33.892625	151.144983	1		install new kerb ramp	UH231	Secondary	MED		\$ 2,500
CD1219	Charlote Street	Lewisham	Local Road	crossing deficiency	narrow kerb ramp	-33.878622	151.160481	1		install new kerb ramp	UH232	Secondary	MED		\$ 2,500
CD122	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.873485	151.17257	1		install new Tactile Ground Surface Indicators	UH233	Secondary	MED		\$ 650
CD1226	Carrington Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896935	151.162736	1		install new kerb ramp - pair	UH234	Secondary	MED		\$ 5,000
CD1227	The Boulevard	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896961	151.162201	1		install new kerb ramp - pair	UH235	Secondary	MED		\$ 5,000
CD1228	The Boulevard	Lewisham	Local Road	crossing deficiency	long crossing point	-33.870013	151.162216	1		install kerb extension / refuge island	UH236	Secondary	MED		\$ 10,000
CD1229	May Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870741	151.161392	1		install new kerb ramp - pair	UH237	Secondary	MED		\$ 5,000
CD123	Annandale Street	Annandale	Local Road	crossing deficiency	missing crossing point	-33.872587	151.172545	1		install new kerb ramp - pair	UH238	Secondary	MED		\$ 5,000
CD1230	Helene Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871139	151.160592	1		install new kerb ramp - pair	UH239	Secondary	MED		\$ 5,000
CD1234	Glendale Drive	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.870851	151.161068	1		install new Tactile Ground Surface Indicators	UH240	Secondary	MED		\$ 650
CD1235	Glendale Drive	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.870189	151.161625	1		install new Tactile Ground Surface Indicators	UH241	Secondary	MED		\$ 650
CD1236	Balmn Road	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.873733	151.160326	1		install new kerb ramp	UH242	Secondary	MED		\$ 2,500
CD1237	Balmn Road	Lewisham	Regional Road	crossing deficiency	missing kerb ramp	-33.872916	151.160052	1		install new kerb ramp	UH243	Secondary	MED		\$ 2,500
CD1239	Eric Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873186	151.160164	1		install new kerb ramp	UH244	Secondary	MED		\$ 2,500
CD124	Annandale Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.873101	151.172573	1		install new kerb ramp	UH245	Secondary	MED		\$ 2,500
CD1243	Catherine Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878532	151.164883	1		install new kerb ramp - pair	UH246	Secondary	MED		\$ 5,000
CD1244	Catherine Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876473	151.164817	1		install new kerb ramp - pair	UH247	Secondary	MED		\$ 5,000
CD1245	Catherine Street	Lewisham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.874472	151.164691	1		install new kerb ramp	UH248	Secondary	MED		\$ 2,500
CD1246	Church Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876037	151.166780	1		install new kerb ramp - pair	UH249	Secondary	MED		\$ 5,000
CD1248	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880066	151.166082	1		install new kerb ramp - pair	UH250	Secondary	MED		\$ 5,000
CD1250	James Street	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.879032	151.155116	1		install new kerb ramp	UH251	Secondary	MED		\$ 2,500
CD1251	James Street	Lewisham	State Road	crossing deficiency	poor kerb ramp alignment	-33.874741	151.155386	1		install new kerb ramp	UH252	Secondary	MED		\$ 2,500
CD1254	Frazier Street	Lewisham	Local Road	crossing deficiency	missing kerb ramp - pair	-33.870096	151.152039	1		install new kerb ramp - pair	UH253	Secondary	MED		\$ 5,000
CD1255	Glover Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.869673	151.155519	1		install new kerb ramp	UH254	Secondary	MED		\$ 2,500
CD1266	Glover Street	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.869137	151.156221	1		install new Tactile Ground Surface Indicators	UH255	Secondary	MED		\$ 650
CD1260	Grove Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872581	151.154457	1		install new kerb ramp - pair	UH256	Secondary	MED		\$ 5,000
CD1266	Grove Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.869987	151.163655	1		install new kerb ramp	UH257	Secondary	MED		\$ 2,500
CD1267	Grove Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.869554	151.16348	1		install new kerb ramp - pair	UH258	Secondary	MED		\$ 5,000
CD1268	Grove Street	Lewisham	Local Road	crossing deficiency	missing kerb ramp - pair	-33.86944	151.163394	1		install new kerb ramp - pair, and Tactile Ground Surface Indicators	UH259	Secondary	MED		\$ 5,000
CD1269	City West Link Bridge	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.874003	151.154996	1		install new kerb ramp	UH260	Secondary	MED		\$ 2,500
CD127	Annandale Street	Annandale	Local Road	crossing deficiency	driver confusion at unconventional crossing	-33.87583	151.171631	1		further investigation required - pedestrian crossing	UH261	Secondary	MED		\$ 10,000
CD1270	Foucant Lane	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.871651	151.169173	1		install new kerb ramp	UH262	Secondary	MED		\$ 2,500
CD1271	Cecil Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.871677	151.16894	1		install new kerb ramp	UH263	Secondary	MED		\$ 2,500
CD1272	Cecil Lane	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872049	151.168409	1		install new kerb ramp - pair	UH264	Secondary	MED		\$ 5,000
CD1273	Lamb Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872583	151.167237	1		install new kerb ramp - pair	UH265	Secondary	MED		\$ 5,000
CD1274	Lamb Lane	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872728	151.16665	1		install new kerb ramp	UH266	Secondary	MED		\$ 2,500
CD1275	Julian Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.87279	151.166326	1		install new kerb ramp - pair	UH267	Secondary	MED		\$ 5,000
CD1276	Halloran Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873022	151.165352	1		install new kerb ramp - pair	UH268	Secondary	MED		\$ 5,000
CD1277	Grove Street	Lewisham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.873036	151.16479	1		install new kerb ramp - pair	UH269	Secondary	MED		\$ 5,000
CD1278	Catherine Street	Lewisham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.87326	151.16443	1		install new kerb ramp - pair	UH270	Secondary	MED		\$ 5,000
CD1															

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1297	Steward Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873744	151.156417	1		install new kerb ramp	UH282	Secondary	MED	\$	2,500
CD1298	Rayner Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874288	151.158929	1		install new kerb ramp - pair	UH283	Secondary	MED	\$	5,000
CD1299	Lilyfield Road	Lilyfield	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.872254	151.167073	1		install new kerb ramp - pair	UH284	Secondary	MED	\$	5,000
CD13	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886988	151.165603	1		install new kerb ramp	UH285	Secondary	MED	\$	2,500
CD1300	Lilyfield Road	Lilyfield	Regional Road	crossing deficiency	missing crossing point - future park access	-33.872249	151.167967	1		install new kerb ramp - pair, new refuge island	UH286	Secondary	MED	\$	7,000
CD131	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884356	151.167526	1		install new kerb ramp - pair	UH287	Secondary	MED	\$	5,000
CD1311	James Street	Lilyfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.873576	151.162280	1		install new kerb ramp	UH288	Secondary	MED	\$	2,500
CD1314	Perry Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.872496	151.155563	1		install new kerb ramp - pair	UH289	Secondary	MED	\$	5,000
CD1318	Steward Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872402	151.156249	1		install new kerb ramp	UH290	Secondary	MED	\$	2,500
CD132	Booth Street	Annandale	Regional Road	crossing deficiency	missing kerb ramp	-33.886909	151.168008	1		install new kerb ramp	UH291	Secondary	MED	\$	2,500
CD1325	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.876647	151.165703	1		install new kerb ramp	UH292	Secondary	MED	\$	2,500
CD133	Young Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.880653	151.168253	1		install new kerb ramp	UH293	Secondary	MED	\$	2,500
CD1334	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876417	151.161043	1		install new kerb ramp - pair	UH294	Secondary	MED	\$	5,000
CD1335	Addison Road	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.903008	151.165389	1		install new pedestrian refuge	UH295	Secondary	MED	\$	15,000
CD1336	Addison Road	Marrickville	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.899899	151.157739	1		further investigation required - pedestrian crossing	UH296	Secondary	MED	\$	10,000
CD1338	Cary Street	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.919003	151.151776	1		further investigation required - pedestrian crossing	UH297	Secondary	MED	\$	10,000
CD1339	Cook Road	Marrickville	Local Road	crossing deficiency	long crossing	-33.905069	151.166009	1		install kerb bollards built out	UH298	Secondary	MED	\$	10,000
CD134	Young Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.880701	151.168330	1		install new kerb ramp	UH299	Secondary	MED	\$	2,500
CD1340	Hawthurst Street	Marrickville	Local Road	crossing deficiency	long crossing	-33.905714	151.154609	1		install kerb extensions	UH300	Secondary	MED	\$	10,000
CD1341	Livingstone Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.903969	151.153226	1		further investigation required - pedestrian crossing	UH301	Secondary	MED	\$	10,000
CD1342	Livingstone Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.912787	151.147235	1		further investigation required - pedestrian crossing	UH302	Secondary	MED	\$	10,000
CD1343	Livingstone Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.912133	151.147924	1		further investigation required - pedestrian crossing	UH303	Secondary	MED	\$	10,000
CD1344	Thompson Street	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.909005	151.161394	1		further investigation required - pedestrian crossing	UH304	Secondary	MED	\$	10,000
CD1345	Thomley Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp - pair	-33.919773	151.146789	1		install new kerb ramp - pair	UH305	Secondary	MED	\$	10,000
CD1346	Warren Road	Marrickville	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.915051	151.148765	1		further investigation required - pedestrian crossing	UH306	Secondary	MED	\$	10,000
CD1347	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.899919	151.157784	1		install new kerb ramp	UH307	Secondary	MED	\$	2,500
CD1348	Park Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.899866	151.157613	1		install new kerb ramp	UH308	Secondary	MED	\$	2,500
CD1349	Newlie Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.900342	151.158603	1		install new kerb ramp	UH309	Secondary	MED	\$	2,500
CD135	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.880699	151.168321	1		install new kerb ramp	UH310	Secondary	MED	\$	2,500
CD1350	Bright Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900443	151.156928	1		install new kerb ramp	UH311	Secondary	MED	\$	2,500
CD1351	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.901107	151.160811	1		install new kerb ramp	UH312	Secondary	MED	\$	2,500
CD1352	East Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901316	151.161305	1		install new kerb ramp - pair	UH313	Secondary	MED	\$	5,000
CD1353	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.901843	151.162572	1		install new kerb ramp	UH314	Secondary	MED	\$	2,500
CD1354	England Avenue	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.901728	151.162544	1		install new kerb ramp	UH315	Secondary	MED	\$	2,500
CD1356	Shepard Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.902658	151.156427	1		install new kerb ramp	UH316	Secondary	MED	\$	2,500
CD1357	Perry Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902943	151.165391	1		install new kerb ramp - pair	UH317	Secondary	MED	\$	5,000
CD1358	Fotheringham Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.903836	151.167728	1		install new Traffic Ground Surface Indicators	UH318	Secondary	MED	\$	650
CD1359	Addison Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.904043	151.168222	1		install new kerb ramp	UH319	Secondary	MED	\$	2,500
CD136	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.880925	151.169148	1		install new kerb ramp	UH320	Secondary	MED	\$	2,500
CD1360	Fotheringham Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.903843	151.167682	1		install new Traffic Ground Surface Indicators	UH321	Secondary	MED	\$	650
CD1361	Addison Road	Marrickville	Regional Road	crossing deficiency	narrow refuge island	-33.904054	151.168341	1		install new refuge island	UH322	Secondary	MED	\$	15,000
CD1366	Beauchamp Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.914341	151.143041	1		install new Traffic Ground Surface Indicators - pair	UH323	Secondary	MED	\$	1,300
CD1367	Beauchamp Street	Marrickville	Local Road	crossing deficiency	overhanging vegetation narrows kerb ramp	-33.914	151.145104	1		refer to maintenance	UH324	Secondary	MED	\$	-
CD1368	Beauchamp Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.914199	151.144104	1		install new Traffic Ground Surface Indicators - pair	UH325	Secondary	MED	\$	1,300
CD1369	Beauchamp Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.913949	151.146222	1		install new kerb ramp - pair	UH326	Secondary	MED	\$	5,000
CD137	Booth Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885377	151.170071	1		consult with City of Sydney	UH327	Secondary	MED	\$	5,000
CD1370	Calvert Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912466	151.155596	1		install new kerb ramp - pair	UH328	Secondary	MED	\$	5,000
CD1371	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.912746	151.157186	1		install new Traffic Ground Surface Indicators	UH329	Secondary	MED	\$	650
CD1372	Calvert Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912631	151.157280	1		install new kerb ramp	UH330	Secondary	MED	\$	2,500
CD1374	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.913497	151.158675	1		install new Traffic Ground Surface Indicators - pair	UH331	Secondary	MED	\$	1,300
CD1375	Calvert Street	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.912943	151.157586	1		install new kerb ramp - pair	UH332	Secondary	MED	\$	5,000
CD1376	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.91281	151.157389	1		install new Traffic Ground Surface Indicators - pair	UH333	Secondary	MED	\$	1,300
CD1377	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.912504	151.157019	1		install new Traffic Ground Surface Indicators - pair	UH334	Secondary	MED	\$	1,300
CD1378	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.912337	151.156656	1		install new Traffic Ground Surface Indicators - pair	UH335	Secondary	MED	\$	1,300
CD1379	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.912029	151.156243	1		install new Traffic Ground Surface Indicators - pair	UH336	Secondary	MED	\$	1,300
CD138	Guthrie Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884286	151.171767	1		install new kerb ramp - pair	UH337	Secondary	MED	\$	5,000
CD1380	Calvert Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.911798	151.155568	1		install new Traffic Ground Surface Indicators - pair	UH338	Secondary	MED	\$	1,300
CD1381	Calvert Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.911676	151.155346	1		install new kerb ramp - pair	UH339	Secondary	MED	\$	5,000
CD1382	Calvert Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912008	151.155915	1		install new kerb ramp - pair	UH340	Secondary	MED	\$	5,000
CD1386	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920494	151.154511	1		install new kerb ramp - pair	UH341	Secondary	MED	\$	5,000
CD1387	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.920582	151.154408	1		install new kerb ramp	UH342	Secondary	MED	\$	2,500
CD1388	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.921255	151.154021	1		install new kerb ramp	UH343	Secondary	MED	\$	2,500
CD139	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp construction	-33.883177	151.168322	1		install new kerb ramp	UH344	Secondary	MED	\$	2,500
CD1394	Chapel Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.9051	151.161694	1		install new Traffic Ground Surface Indicators	UH345	Secondary	MED	\$	650
CD1395	Chapel Street	Marrickville	Local Road	crossing deficiency	narrow kerb ramp	-33.905514	151.162409	1		install new kerb ramp	UH346	Secondary	MED	\$	2,500
CD1396	Chapel Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.905586	151.162319	1		install new kerb ramp	UH347	Secondary	MED	\$	2,500
CD1397	Chapel Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905528	151.162361	1		install new kerb ramp	UH348	Secondary	MED	\$	2,500
CD1398	Chapel Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905982	151.162946	1		install new kerb ramp - pair	UH349	Secondary	MED	\$	5,000
CD1399	Chapel Street	Marrickville	Local Road	crossing deficiency	raised kerb ramp lip - pair	-33.906008	151.162996	1		install new kerb ramp - pair	UH350	Secondary	MED	\$	5,000
CD140	Booth Street	Annandale	Regional Road	crossing deficiency	potential build-out to improve crossing and slow vehicles	-33.880576	151.168182	1		install kerb extension - pair	UH351	Secondary	MED	\$	20,000
CD1401	Dudley Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.911446	151.143019	1		install new kerb ramp	UH352	Secondary	MED	\$	2,500
CD1402	Llewellyn Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.905052	151.173209	1		install new kerb ramp	UH353	Secondary	MED	\$	2,500
CD1405	Edinburgh Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.908913	151.172288	1		install new Traffic Ground Surface Indicators	UH354	Secondary	MED	\$	650
CD1406	Edinburgh Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907978	151.170625	1		install new kerb ramp	UH355	Secondary	MED	\$	2,500
CD1411	Enmore Road	Marrickville	Regional Road	crossing deficiency	narrow pedestrian waiting area	-33.904014	151.168283	1		install new refuge island	UH356	Secondary	MED	\$	15,000
CD1412	Enmore Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.904169	151.168399	1		install new kerb ramp	UH357	Secondary	MED	\$	2,500
CD1414	Ewart Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.911066	151.139953	1		install new kerb ramp	UH358	Secondary	MED	\$	2,500
CD1415	Wardell Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912068	151.139988	1		install new kerb ramp - pair	UH359	Secondary	MED	\$	5,000
CD1418	Ewart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.914589	151.142749	1		install new Traffic Ground Surface Indicators	UH360	Secondary	MED	\$	650
CD1419	Ewart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.914525	151.142926	1		install new Traffic Ground Surface Indicators	UH361	Secondary	MED	\$	650
CD142	Catherine Street	Annandale	Local Road	crossing deficiency	poor kerb ramp construction	-33.879198	151.164111	1		install new kerb ramp	UH362	Secondary	MED	\$	2,500
CD1420	Ewart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.913973	151.142361	1		install new Traffic Ground Surface Indicators - pair	UH363	Secondary	MED	\$	1,300
CD1421	Ewart Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.913564	151.141629	1		install new Traffic Ground Surface Indicators - pair	UH364	Secondary	MED	\$	1,300
CD1425	Ewart Street	Marrickville	Local Road	crossing deficiency	narrow kerb ramp	-33.911955	151.146019	1							

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1441	Hawthurst Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.90562	151.154795	1		install new kerb ramp - pair	UH377	Secondary	MED	\$	5,000
CD1442	Sydenham Road	Marrickville	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90717	151.159198	1		install new kerb ramp - pair	UH378	Secondary	MED	\$	5,000
CD1444	Ilwara Road	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.90526	151.16032	1		install new kerb ramp - pair	UH379	Secondary	MED	\$	5,000
CD1445	Ilwara Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.90514	151.160245	1		install new kerb ramp	UH380	Secondary	MED	\$	2,500
CD1446	Ilwara Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.90508	151.161281	1		install new Tactile Ground Surface Indicators	UH381	Secondary	MED	\$	650
CD1447	Ilwara Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.904516	151.161589	1		install new Tactile Ground Surface Indicators	UH382	Secondary	MED	\$	650
CD1448	Ilwara Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.904161	151.161843	1		install new Tactile Ground Surface Indicators	UH383	Secondary	MED	\$	650
CD145	Chester Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.885071	151.174498	1		install new kerb ramp	UH384	Secondary	MED	\$	2,500
CD1450	Ilwara Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.909136	151.15765	1		install new Tactile Ground Surface Indicators - pair	UH385	Secondary	MED	\$	1,300
CD1452	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.916528	151.149462	1		install new kerb ramp - pair	UH386	Secondary	MED	\$	5,000
CD1453	Hill Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918828	151.145787	1		install new kerb ramp - pair	UH387	Secondary	MED	\$	5,000
CD1454	Cahill Place	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919109	151.145367	1		install new kerb ramp - pair	UH388	Secondary	MED	\$	5,000
CD1455	Wallace Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919799	151.14467	1		install new kerb ramp - pair	UH389	Secondary	MED	\$	5,000
CD1456	Ilwara Road	Marrickville	Regional Road	crossing deficiency	misaligned refuge island	-33.919716	151.144871	1		re-construct refuge island	UH390	Secondary	MED	\$	15,000
CD1460	Thornley Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919111	151.145595	1		install new kerb ramp - pair	UH391	Secondary	MED	\$	5,000
CD1461	Warne Place	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.918673	151.14626	1		install new kerb ramp - pair	UH392	Secondary	MED	\$	5,000
CD1466	Ilwara Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.910468	151.150330	1		install new kerb ramp - pair	UH393	Secondary	MED	\$	5,000
CD1474	Livingstone Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.904991	151.153053	1		install new kerb ramp	UH394	Secondary	MED	\$	2,500
CD1475	Livingstone Road	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.90597	151.153224	1		install new kerb ramp - pair	UH395	Secondary	MED	\$	5,000
CD1476	Livingstone Road	Marrickville	Local Road	crossing deficiency	steep roadway crossing point	-33.906766	151.153206	1		no action	UH396	Secondary	MED	\$	1,300
CD1477	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.907862	151.152781	1		install new Tactile Ground Surface Indicators - pair	UH397	Secondary	MED	\$	1,300
CD148	Colins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88401	151.171111	1		install new Tactile Ground Surface Indicators	UH398	Secondary	MED	\$	650
CD1481	Livingstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907317	151.152702	1		install new kerb ramp	UH399	Secondary	MED	\$	2,500
CD1482	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.908315	151.152936	1		install new Tactile Ground Surface Indicators - pair	UH400	Secondary	MED	\$	1,300
CD1483	Livingstone Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.905148	151.153067	1		re-construct refuge island	UH401	Secondary	MED	\$	15,000
CD1484	Livingstone Road	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.905061	151.153081	1		install new kerb ramp - pair	UH402	Secondary	MED	\$	5,000
CD1485	Livingstone Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.904161	151.153102	1		re-construct refuge island	UH403	Secondary	MED	\$	15,000
CD1488	Livingstone Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.901237	151.153329	1		install new kerb ramp	UH404	Secondary	MED	\$	2,500
CD1489	Livingstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913859	151.146392	1		install new kerb ramp - pair	UH405	Secondary	MED	\$	5,000
CD149	Colins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.88413	151.171282	1		install new Tactile Ground Surface Indicators - pair	UH406	Secondary	MED	\$	1,300
CD1490	Livingstone Road	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.913723	151.146397	1		install new kerb ramp - pair	UH407	Secondary	MED	\$	2,500
CD1492	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911171	151.148871	1		install new Tactile Ground Surface Indicators - pair	UH408	Secondary	MED	\$	1,300
CD1493	Livingstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.911449	151.14858	1		install new kerb ramp - pair	UH409	Secondary	MED	\$	5,000
CD1494	Livingstone Road	Marrickville	Local Road	crossing deficiency	long crossing	-33.911434	151.148496	1		install kerb extension - pair	UH410	Secondary	MED	\$	20,000
CD1495	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.912101	151.147692	1		install new Tactile Ground Surface Indicators - pair	UH411	Secondary	MED	\$	1,300
CD1496	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.912783	151.147314	1		install new Tactile Ground Surface Indicators	UH412	Secondary	MED	\$	650
CD1498	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.912573	151.147554	1		install new Tactile Ground Surface Indicators	UH413	Secondary	MED	\$	650
CD1499	Livingstone Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.912523	151.148027	1		install new Tactile Ground Surface Indicators	UH414	Secondary	MED	\$	650
CD15	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882174	151.174863	1		install new kerb ramp	UH415	Secondary	MED	\$	2,500
CD150	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887013	151.166589	1		install new kerb ramp - pair	UH416	Secondary	MED	\$	5,000
CD1500	Livingstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.91212	151.148114	1		install new kerb ramp	UH417	Secondary	MED	\$	2,500
CD1503	Livingstone Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.908566	151.152295	1		install new kerb ramp - pair	UH418	Secondary	MED	\$	5,000
CD1505	Shelby Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.904743	151.172467	1		install new Tactile Ground Surface Indicators - pair	UH419	Secondary	MED	\$	1,300
CD1506	Lynch Lane	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.904668	151.172613	1		install new kerb ramp	UH420	Secondary	MED	\$	2,500
CD1507	O'Connor Lane	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.904174	151.171588	1		install new Tactile Ground Surface Indicators - pair	UH421	Secondary	MED	\$	1,300
CD1508	Jewell Street	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.904395	151.1719	1		install new kerb ramp	UH422	Secondary	MED	\$	2,500
CD1509	Jewell Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904349	151.171909	1		install new kerb ramp - pair	UH423	Secondary	MED	\$	5,000
CD151	Colins Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.883934	151.170422	1		install new kerb ramp	UH424	Secondary	MED	\$	2,500
CD1510	Jewell Street	Marrickville	Regional Road	crossing deficiency	misaligned refuge island	-33.904124	151.170625	1		re-construct refuge island	UH425	Secondary	MED	\$	15,000
CD1513	Harvey Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.907124	151.147089	1		install new kerb ramp	UH426	Secondary	MED	\$	2,500
CD1514	Wardell Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.906875	151.145946	1		install new kerb ramp	UH427	Secondary	MED	\$	2,500
CD1515	Avonlea Street	Marrickville	Local Road	crossing deficiency	raised kerb ramp lip	-33.908334	151.15071	1		install new kerb ramp	UH428	Secondary	MED	\$	2,500
CD152	Colins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884531	151.172549	1		install new Tactile Ground Surface Indicators	UH429	Secondary	MED	\$	650
CD1520	Victoria Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912408	151.160148	1		install new kerb ramp	UH430	Secondary	MED	\$	2,500
CD1521	Marrickville Road	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.912331	151.159594	1		install new kerb ramp - pair	UH431	Secondary	MED	\$	5,000
CD1522	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.912396	151.159677	1		install new kerb ramp	UH432	Secondary	MED	\$	2,500
CD1523	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.911061	151.157625	1		install new kerb ramp	UH433	Secondary	MED	\$	2,500
CD1524	Ilwara Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.910503	151.156558	1		install new kerb ramp - pair	UH434	Secondary	MED	\$	5,000
CD1525	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.910559	151.156485	1		install new kerb ramp	UH435	Secondary	MED	\$	2,500
CD1526	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910048	151.155426	1		install new Tactile Ground Surface Indicators - pair	UH436	Secondary	MED	\$	1,300
CD153	Colins Street	Annandale	Local Road	crossing deficiency	driveway as kerb ramp	-33.884612	151.172615	1		no action	UH437	Secondary	MED	\$	-
CD1535	Depot Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910711	151.155476	1		install new Tactile Ground Surface Indicators - pair	UH438	Secondary	MED	\$	1,300
CD1536	Marrickville Road	Marrickville	Regional Road	crossing deficiency	shallow kerb ramp	-33.910534	151.156276	1		install new kerb ramp	UH439	Secondary	MED	\$	2,500
CD1537	Silver Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911176	151.157155	1		install new Tactile Ground Surface Indicators - pair	UH440	Secondary	MED	\$	1,300
CD1538	Garner Avenue	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910946	151.157295	1		install new Tactile Ground Surface Indicators - pair	UH441	Secondary	MED	\$	1,300
CD1539	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911175	151.158132	1		install new Tactile Ground Surface Indicators - pair	UH442	Secondary	MED	\$	1,300
CD154	Colins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884642	151.172494	1		install new Tactile Ground Surface Indicators	UH443	Secondary	MED	\$	650
CD1540	Marrickville Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911288	151.158301	1		install new Tactile Ground Surface Indicators - pair	UH444	Secondary	MED	\$	1,300
CD1541	Marrickville Road	Marrickville	Regional Road	crossing deficiency	misaligned kerb ramp	-33.912173	151.160052	1		install new kerb ramp	UH445	Secondary	MED	\$	2,500
CD1542	Marrickville Road	Marrickville	Regional Road	crossing deficiency	narrow refuge island	-33.912167	151.160017	1		install new corner refuge island	UH446	Secondary	MED	\$	2,500
CD1543	Victoria Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.912378	151.160167	1		install new kerb ramp	UH447	Secondary	MED	\$	2,500
CD155	Colins Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884653	151.172488	1		install new Tactile Ground Surface Indicators	UH448	Secondary	MED	\$	650
CD1553	Victoria Road	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.912363	151.159718	1		install new kerb ramp	UH449	Secondary	MED	\$	2,500
CD1555	Murray Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.906463	151.173099	1		install new Tactile Ground Surface Indicators	UH450	Secondary	MED	\$	650
CD1556	Murray Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.906802	151.172899	1		install new Tactile Ground Surface Indicators	UH451	Secondary	MED	\$	650
CD156	Colins Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.884662	151.17257	1		install new kerb ramp	UH452	Secondary	MED	\$	2,500
CD1562	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.901722	151.159192	1		install new Tactile Ground Surface Indicators	UH453	Secondary	MED	\$	650
CD1563	Newington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901629	151.168763	1		install new kerb ramp	UH454	Secondary	MED	\$	2,500
CD157	Colins Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882505	151.166587	1		install new kerb ramp	UH455	Secondary	MED	\$	2,500
CD1570	Newington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.909764	151.163626	1		install new kerb ramp	UH456	Secondary	MED	\$	2,500
CD1571	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.898155	151.159024	1		install new Tactile Ground Surface Indicators - pair	UH457	Secondary	MED	\$	650
CD1572	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.898276	151.159071	1		install new Tactile Ground Surface Indicators - pair	UH458	Secondary	MED	\$	650
CD1573	Premier Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.921265	151.153885	1		install new kerb ramp	UH459	Secondary	MED	\$	2,500
CD1574	Premier Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.921018	151.153171	1		install new Tactile Ground					

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1590	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.918051	151.15221	1		install new Tactile Ground Surface Indicators - pair	UH472	Secondary	MED	\$	1,300
CD1591	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.91802	151.15223	1		install new Tactile Ground Surface Indicators - pair	UH473	Secondary	MED	\$	1,300
CD1596	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.917918	151.151701	1		install new Tactile Ground Surface Indicators - pair	UH474	Secondary	MED	\$	1,300
CD1597	Renwick Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.916542	151.149507	1		install new kerb ramp - pair	UH475	Secondary	MED	\$	5,000
CD1598	Richardson Crescent	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.922128	151.155436	1		install new kerb ramp - pair	UH476	Secondary	MED	\$	5,000
CD1601	Collins Street	Annandale	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.88004	151.165311	1		install new kerb ramp	UH477	Secondary	MED	\$	2,500
CD1602	Richardson Crescent	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.923555	151.155980	1		install new kerb ramp	UH478	Secondary	MED	\$	2,500
CD1602	Richardson Crescent	Marrickville	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.923518	151.156104	1		install new kerb ramp - pair	UH479	Secondary	MED	\$	5,000
CD1611	Smidmore Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp - pair	-33.907754	151.171415	1		install new kerb ramp - pair	UH480	Secondary	MED	\$	5,000
CD1613	Station Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914447	151.155203	1		install new kerb ramp - pair	UH481	Secondary	MED	\$	5,000
CD1614	Sydenham Road	Marrickville	State Road	crossing deficiency	misaligned kerb ramp	-33.909586	151.162174	1		install new kerb ramp	UH482	Secondary	MED	\$	2,500
CD1617	Farr Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.908804	151.160814	1		install new kerb ramp	UH483	Secondary	MED	\$	2,500
CD1618	Frampton Avenue	Marrickville	Local Road	crossing deficiency	sleep kerb ramp	-33.909246	151.161319	1		install new kerb ramp - pair	UH484	Secondary	MED	\$	5,000
CD1619	Edward Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.908431	151.160197	1		install new kerb ramp	UH485	Secondary	MED	\$	2,500
CD162	Collins Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.882854	151.167326	1		install new kerb ramp	UH486	Secondary	MED	\$	2,500
CD1620	Gorman Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.908181	151.159779	1		install new kerb ramp	UH487	Secondary	MED	\$	2,500
CD1621	Ileawera Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907578	151.159214	1		install new kerb ramp	UH488	Secondary	MED	\$	2,500
CD1625	Despoites Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.907124	151.158590	1		re-construct refuge island	UH489	Secondary	MED	\$	15,000
CD163	Collins Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.882811	151.167121	1		install new kerb ramp	UH490	Secondary	MED	\$	2,500
CD1634	Calogian Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.911421	151.164611	1		install new Tactile Ground Surface Indicators - pair	UH491	Secondary	MED	\$	1,300
CD1635	Stones Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.911937	151.165330	1		install new Tactile Ground Surface Indicators - pair	UH492	Secondary	MED	\$	1,300
CD1636	Shilow Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.912485	151.166024	1		install new Tactile Ground Surface Indicators	UH493	Secondary	MED	\$	650
CD164	Young Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.882821	151.167196	1		re-construct refuge island	UH494	Secondary	MED	\$	15,000
CD1640	Sydenham Road	Marrickville	State Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.912233	151.165552	1		install new Tactile Ground Surface Indicators - pair	UH495	Secondary	MED	\$	1,300
CD1641	Sydenham Road	Marrickville	State Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.911805	151.164957	1		install new Tactile Ground Surface Indicators - pair	UH496	Secondary	MED	\$	1,300
CD1642	Sydney Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.911229	151.164271	1		install new kerb ramp	UH497	Secondary	MED	\$	2,500
CD1643	Vincent Street	Marrickville	Local Road	crossing deficiency	sleep kerb ramp	-33.910651	151.163438	1		install new kerb ramp	UH498	Secondary	MED	\$	2,500
CD1645	Fareham Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.91037	151.16344	1		install new Tactile Ground Surface Indicators - pair	UH499	Secondary	MED	\$	1,300
CD1648	Sydney Street St	Marrickville	Local Road	crossing deficiency	poor kerb ramp construction	-33.908667	151.171404	1		install new kerb ramp	UH500	Secondary	MED	\$	2,500
CD1649	Victoria Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment, does not follow desire line	-33.905432	151.169251	1		no action	UH501	Secondary	MED	\$	2,500
CD165	Collins Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.882765	151.167196	1		install new kerb ramp	UH502	Secondary	MED	\$	2,500
CD1651	Cook Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.905811	151.166231	1		re-construct refuge island	UH503	Secondary	MED	\$	15,000
CD1652	Smith Street	Marrickville	Local Road	crossing deficiency	long crossing point	-33.905848	151.165795	1		install new refuge island	UH504	Secondary	MED	\$	15,000
CD1653	Chapel Street	Marrickville	Local Road	crossing deficiency	sleep kerb ramp	-33.906816	151.164431	1		install new kerb ramp - pair	UH505	Secondary	MED	\$	5,000
CD1659	Victoria Road	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.914802	151.155428	1		install new kerb ramp - pair	UH506	Secondary	MED	\$	5,000
CD166	Hutchinson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.875005	151.169881	1		install new kerb ramp	UH507	Secondary	MED	\$	2,500
CD1661	Victoria Road	Marrickville	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.912192	151.160089	1		install new Tactile Ground Surface Indicators	UH508	Secondary	MED	\$	650
CD1664	Warburton Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.913768	151.169251	1		install new kerb ramp	UH509	Secondary	MED	\$	2,500
CD167	Hutchinson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875024	151.16991	1		install new kerb ramp	UH510	Secondary	MED	\$	2,500
CD1673	Pine Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.907676	151.144781	1		re-construct refuge island	UH511	Secondary	MED	\$	15,000
CD1674	Wardell Road	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.906229	151.144207	1		install new kerb ramp - pair	UH512	Secondary	MED	\$	5,000
CD1676	Renswick Crescent	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.91304	151.138544	1		re-construct refuge island	UH513	Secondary	MED	\$	15,000
CD1677	Wardell Road	Marrickville	Regional Road	crossing deficiency	missing crossing point	-33.91342	151.137788	1		install new kerb ramp - pair	UH514	Secondary	MED	\$	5,000
CD1678	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914796	151.148406	1		install new kerb ramp	UH515	Secondary	MED	\$	2,500
CD168	Hutchinson Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.87624	151.169912	1		install new kerb ramp	UH516	Secondary	MED	\$	2,500
CD1682	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.917045	151.152302	1		install new Tactile Ground Surface Indicators - pair	UH517	Secondary	MED	\$	1,300
CD1686	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.917167	151.152413	1		install new Tactile Ground Surface Indicators - pair	UH518	Secondary	MED	\$	1,300
CD1689	Warren Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.915533	151.149162	1		install new kerb ramp - pair	UH519	Secondary	MED	\$	5,000
CD169	Hutchinson Street	Annandale	Local Road	crossing deficiency	sleep kerb ramp	-33.875196	151.170437	1		install new kerb ramp - pair	UH520	Secondary	MED	\$	5,000
CD1690	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913841	151.14653	1		install new kerb ramp - pair	UH521	Secondary	MED	\$	5,000
CD1691	Warren Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91419	151.147391	1		install new kerb ramp - pair	UH522	Secondary	MED	\$	5,000
CD1694	Albermarle Street	Newtown	Regional Road	crossing deficiency	missing kerb ramp	-33.895917	151.174988	1		install new kerb ramp - pair	UH523	Secondary	MED	\$	5,000
CD1695	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895919	151.174958	1		install new kerb ramp	UH524	Secondary	MED	\$	2,500
CD1696	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895963	151.174984	1		install new kerb ramp	UH525	Secondary	MED	\$	2,500
CD1697	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.8959	151.17503	1		install new kerb ramp	UH526	Secondary	MED	\$	2,500
CD1698	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp - pair	-33.895984	151.175733	1		install new kerb ramp - pair	UH527	Secondary	MED	\$	5,000
CD1699	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895917	151.176303	1		install new kerb ramp	UH528	Secondary	MED	\$	2,500
CD170	Hutchinson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.875367	151.170671	1		install new kerb ramp - pair	UH529	Secondary	MED	\$	5,000
CD1700	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895566	151.176339	1		install new kerb ramp	UH530	Secondary	MED	\$	2,500
CD1701	Albermarle Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.89555	151.176378	1		install new kerb ramp	UH531	Secondary	MED	\$	2,500
CD1702	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895496	151.176366	1		install new kerb ramp	UH532	Secondary	MED	\$	2,500
CD1703	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895319	151.176972	1		install new kerb ramp	UH533	Secondary	MED	\$	2,500
CD1704	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895268	151.177025	1		install new kerb ramp	UH534	Secondary	MED	\$	2,500
CD1705	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895367	151.176989	1		install new kerb ramp	UH535	Secondary	MED	\$	2,500
CD1706	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895346	151.177048	1		install new kerb ramp	UH536	Secondary	MED	\$	2,500
CD1707	Albermarle Street	Newtown	Local Road	crossing deficiency	missing kerb ramp	-33.895297	151.177037	1		install new kerb ramp	UH537	Secondary	MED	\$	2,500
CD1708	Albermarle Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895117	151.177062	1		install new kerb ramp	UH538	Secondary	MED	\$	2,500
CD1709	Albermarle Street	Newtown	Regional Road	crossing deficiency	driveway as kerb ramp	-33.904092	151.175913	1		no action	UH539	Secondary	MED	\$	-
CD171	Hutchinson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.875367	151.170684	1		install new kerb ramp - pair	UH540	Secondary	MED	\$	5,000
CD1710	Albermarle Street	Newtown	Local Road	crossing deficiency	driveway as kerb ramp	-33.904094	151.175963	1		no action	UH541	Secondary	MED	\$	650
CD1711	Clara Street	Newtown	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.904005	151.175822	1		install new Tactile Ground Surface Indicators	UH542	Secondary	MED	\$	650
CD1716	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897555	151.177141	1		install new kerb ramp - pair	UH543	Secondary	MED	\$	5,000
CD1717	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.896881	151.176938	1		install new kerb ramp	UH544	Secondary	MED	\$	2,500
CD1718	Bedford Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.896276	151.173784	1		install new kerb ramp - pair	UH545	Secondary	MED	\$	5,000
CD1719	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896204	151.173576	1		install new kerb ramp - pair	UH546	Secondary	MED	\$	5,000
CD1720	Bedford Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895305	151.17372	1		install new kerb ramp	UH547	Secondary	MED	\$	2,500
CD1721	Edgeware Road	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907866	151.174811	1		install new kerb ramp	UH548	Secondary	MED	\$	2,500
CD1728	Enmore Road	Newtown	State Road	crossing deficiency	misaligned kerb ramp	-33.896871	151.174031	1		install new kerb ramp	UH549	Secondary	MED	\$	2,500
CD1729	Phillip Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.898719	151.173892	1		install new kerb ramp	UH550	Secondary	MED	\$	2,500
CD173	Hutchinson Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.875346	151.170738	1		install new kerb ramp	UH551	Secondary	MED	\$	2,500
CD1732	Station Street	Newtown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897244	151.175832	1		install new kerb ramp - pair	UH552	Secondary	MED	\$	5,000
CD1734	Albermarle Street	Newtown	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.902894	151.179366	1		install new kerb ramp	UH553	Secondary	MED	\$	2,500
CD174	Kentville Avenue	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873735	151.174157	1		install new kerb ramp	UH554	Secondary	MED	\$	2,500
CD1743	Sandbrook Lane	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.894411	151.171971	1		install new kerb ramp	UH555	Secondary	MED		

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1758	Wells Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.908202	151.177328	1		install new kerb ramp	UH567	Secondary	MED	\$	2,500
CD1759	Walls Street	Newtown	Local Road	crossing deficiency	misaligned kerb ramp	-33.90476	151.174455	1		install new kerb ramp	UH568	Secondary	MED	\$	2,500
CD1760	Palace Street	Petersham	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.892217	151.154253	1		further investigation required - pedestrian crossing	UH569	Secondary	MED	\$	10,000
CD1761	Coronation Avenue	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895997	151.155881	1		install new kerb ramp	UH570	Secondary	MED	\$	2,500
CD1762	Audley Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.894777	151.154484	1		install new kerb ramp - pair	UH571	Secondary	MED	\$	5,000
CD1763	Audley Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89448	151.154552	1		install new kerb ramp	UH572	Secondary	MED	\$	2,500
CD1764	Shaw Street	Petersham	Regional Road	crossing deficiency	steep kerb ramp	-33.895523	151.155501	1		install new kerb ramp - pair	UH573	Secondary	MED	\$	5,000
CD1767	Brighton Street	Petersham	Local Road	crossing deficiency	missing kerb ramp	-33.892211	151.154886	1		install new kerb ramp	UH574	Secondary	MED	\$	2,500
CD1768	Brighton Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.892187	151.15614	1		install new kerb ramp	UH575	Secondary	MED	\$	2,500
CD1770	Brighton Street	Petersham	Local Road	crossing deficiency	misaligned refuge island	-33.893037	151.150439	1		re-construct refuge island	UH576	Secondary	MED	\$	15,000
CD1771	Brighton Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893238	151.150431	1		install new kerb ramp	UH577	Secondary	MED	\$	2,500
CD1773	Crystal Street	Petersham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.894099	151.157447	1		install new kerb ramp	UH578	Secondary	MED	\$	2,500
CD1774	Crystal Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.893026	151.157534	1		install new kerb ramp	UH579	Secondary	MED	\$	2,500
CD1775	Douglas Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.892593	151.157595	1		install new kerb ramp	UH580	Secondary	MED	\$	2,500
CD1776	Brighton Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89231	151.1579	1		install new kerb ramp	UH581	Secondary	MED	\$	2,500
CD1777	Croydon Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891117	151.158341	1		install new kerb ramp	UH582	Secondary	MED	\$	2,500
CD1782	Westbourne Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891803	151.15829	1		install new kerb ramp	UH583	Secondary	MED	\$	2,500
CD1783	Frazer Street	Petersham	Regional Road	crossing deficiency	missing kerb ramp	-33.900943	151.149176	1		install new kerb ramp	UH584	Secondary	MED	\$	2,500
CD1784	Jarvie Avenue	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.900085	151.149583	1		install new Tactile Ground Surface Indicators - pair	UH585	Secondary	MED	\$	1,300
CD1785	Frazer Street	Petersham	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.901185	151.153311	1		install new Tactile Ground Surface Indicators	UH586	Secondary	MED	\$	650
CD1787	Livingstone Road	Petersham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.896027	151.153445	1		install new kerb ramp	UH587	Secondary	MED	\$	2,500
CD1788	Addison Road	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.899416	151.153636	1		install new kerb ramp	UH588	Secondary	MED	\$	2,500
CD1789	Rosford Avenue	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.897479	151.153493	1		install new Tactile Ground Surface Indicators - pair	UH589	Secondary	MED	\$	1,300
CD1789	Piper Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878533	151.171983	1		install new kerb ramp - pair	UH590	Secondary	MED	\$	5,000
CD1804	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.898501	151.160045	1		install new Tactile Ground Surface Indicators	UH591	Secondary	MED	\$	650
CD1805	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.898421	151.160478	1		install new Tactile Ground Surface Indicators	UH592	Secondary	MED	\$	650
CD1806	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.898366	151.159974	1		install new Tactile Ground Surface Indicators	UH593	Secondary	MED	\$	650
CD1807	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.898196	151.159642	1		install new Tactile Ground Surface Indicators	UH594	Secondary	MED	\$	650
CD1808	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.898016	151.158311	1		install new Tactile Ground Surface Indicators	UH595	Secondary	MED	\$	650
CD1809	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.897997	151.158358	1		install new Tactile Ground Surface Indicators	UH596	Secondary	MED	\$	650
CD1810	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.897958	151.158323	1		install new Tactile Ground Surface Indicators	UH597	Secondary	MED	\$	650
CD1811	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.897995	151.158241	1		install new Tactile Ground Surface Indicators	UH598	Secondary	MED	\$	650
CD1812	Newington Road	Petersham	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.897866	151.157472	1		install new Tactile Ground Surface Indicators	UH599	Secondary	MED	\$	650
CD1817	Palace Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.892104	151.154319	1		install new kerb ramp	UH600	Secondary	MED	\$	2,500
CD1818	Palace Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89036	151.154429	1		install new kerb ramp - pair	UH601	Secondary	MED	\$	5,000
CD1820	Palace Street	Petersham	Local Road	crossing deficiency	missing crossing point	-33.891236	151.154323	1		install new kerb ramp - pair	UH602	Secondary	MED	\$	2,500
CD1821	Palace Street	Petersham	Local Road	crossing deficiency	missing crossing point	-33.892213	151.154399	1		install new kerb ramp - pair	UH603	Secondary	MED	\$	5,000
CD1824	West Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.898933	151.149138	1		install new kerb ramp	UH604	Secondary	MED	\$	2,500
CD1825	Paramatta Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889933	151.149158	1		install new kerb ramp - pair	UH605	Secondary	MED	\$	5,000
CD1826	Park Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889629	151.149494	1		install new kerb ramp - pair	UH606	Secondary	MED	\$	5,000
CD1831	Hardy Street	Ashbury	Local Road	crossing deficiency	misaligned kerb ramp	-33.930345	151.162521	1		install new kerb ramp	UH607	Secondary	MED	\$	2,500
CD1830	Philo Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887863	151.160259	1		install new kerb ramp - pair	UH608	Secondary	MED	\$	5,000
CD1831	Paramatta Road	Petersham	State Road	crossing deficiency	poor kerb ramp alignment	-33.887971	151.161197	1		install new kerb ramp	UH609	Secondary	MED	\$	2,500
CD1832	Rayway Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893105	151.155924	1		install new kerb ramp	UH610	Secondary	MED	\$	2,500
CD1833	Rayway Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892369	151.156168	1		install new kerb ramp - pair	UH611	Secondary	MED	\$	5,000
CD1834	Rayway Street	Petersham	Local Road	crossing deficiency	missing kerb ramp - pair	-33.892297	151.155997	1		install new kerb ramp - pair	UH612	Secondary	MED	\$	5,000
CD1835	Rayway Street	Petersham	Local Road	crossing deficiency	crossing within roundabout	-33.892246	151.156176	1		install new kerb ramp and reconstruct refuge island	UH613	Secondary	MED	\$	5,000
CD1836	Chester Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894133	151.156633	1		install new kerb ramp	UH614	Secondary	MED	\$	2,500
CD1837	Oxford Street	Petersham	Local Road	crossing deficiency	misaligned kerb ramp	-33.893779	151.155996	1		install new kerb ramp	UH615	Secondary	MED	\$	2,500
CD1838	Chester Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894421	151.156527	1		install new kerb ramp	UH616	Secondary	MED	\$	2,500
CD1839	Crystal Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.895005	151.156845	1		install new kerb ramp	UH617	Secondary	MED	\$	2,500
CD184	Hardy Street	Ashbury	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906324	151.123342	1		install new kerb ramp	UH618	Secondary	MED	\$	2,500
CD1841	Shaw Street	Petersham	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895781	151.156894	1		install new kerb ramp - pair	UH619	Secondary	MED	\$	5,000
CD1845	Terminus Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893447	151.155858	1		install new kerb ramp	UH620	Secondary	MED	\$	2,500
CD1847	Terminus Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893415	151.157058	1		install new kerb ramp - pair	UH621	Secondary	MED	\$	5,000
CD1848	Trillalgar Street	Petersham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.894031	151.157139	1		install new kerb ramp	UH622	Secondary	MED	\$	2,500
CD1852	Wardell Road	Petersham	Regional Road	crossing deficiency	missing kerb ramp	-33.900952	151.149216	1		install new kerb ramp	UH623	Secondary	MED	\$	2,500
CD1853	Wardell Road	Petersham	Regional Road	crossing deficiency	misaligned kerb ramp	-33.90096	151.149125	1		install new kerb ramp	UH624	Secondary	MED	\$	2,500
CD1854	Morgan Street	Petersham	Local Road	crossing deficiency	misaligned refuge island	-33.898719	151.149241	1		re-construct refuge island	UH625	Secondary	MED	\$	15,000
CD1858	West Street	Petersham	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.89074	151.149006	1		install new Tactile Ground Surface Indicators	UH626	Secondary	MED	\$	650
CD1859	Station Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890643	151.149052	1		install new kerb ramp	UH627	Secondary	MED	\$	2,500
CD186	Carlton Crescent	Ashfield	Regional Road	crossing deficiency	missing crossing point	-33.892442	151.143786	1		modify splitter island	UH628	Secondary	MED	\$	10,000
CD1860	York Crescent	Petersham	Local Road	crossing deficiency	missing kerb ramp	-33.893722	151.158509	1		install new kerb ramp	UH629	Secondary	MED	\$	2,500
CD1862	Beattie Street	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.860575	151.172306	1		install new Tactile Ground Surface Indicators	UH630	Secondary	MED	\$	650
CD1869	Beattie Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860732	151.171928	1		install new kerb ramp	UH631	Secondary	MED	\$	2,500
CD1876	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.868344	151.169217	1		install new kerb ramp - pair	UH632	Secondary	MED	\$	5,000
CD1877	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868314	151.169182	1		install new kerb ramp	UH633	Secondary	MED	\$	2,500
CD1887	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866197	151.168037	1		install new kerb ramp	UH634	Secondary	MED	\$	2,500
CD1888	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865765	151.167898	1		install new kerb ramp - pair	UH635	Secondary	MED	\$	5,000
CD1889	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865842	151.167898	1		install new kerb ramp - pair	UH636	Secondary	MED	\$	5,000
CD1892	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866998	151.169666	1		install new kerb ramp	UH637	Secondary	MED	\$	2,500
CD1893	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.867843	151.168794	1		install new kerb ramp - pair	UH638	Secondary	MED	\$	5,000
CD1894	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.867107	151.169273	1		install new kerb ramp	UH639	Secondary	MED	\$	2,500
CD1898	Gordon Street	Rozelle	State Road	crossing deficiency	poor kerb ramp alignment	-33.866045	151.17295	1		install new kerb ramp	UH640	Secondary	MED	\$	2,500
CD1899	Alfred Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.867861	151.172761	1		install new kerb ramp	UH641	Secondary	MED	\$	2,500
CD1900	Gordon Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.867723	151.172764	1		install new kerb ramp	UH642	Secondary	MED	\$	2,500
CD1901	Gordon Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.867438	151.172728	1		install new Tactile Ground Surface Indicators	UH643	Secondary	MED	\$	650
CD1902	Gordon Street	Rozelle	Regional Road	crossing deficiency	misaligned kerb ramp	-33.867075	151.172776	1		install new kerb ramp	UH644	Secondary	MED	\$	2,500
CD1903	Dunk Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866994	151.17278	1		install new kerb ramp - pair	UH645	Secondary	MED	\$	5,000
CD1904	Gordon Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.866842	151.172881	1		install new Tactile Ground Surface Indicators	UH646	Secondary	MED	\$	650
CD1905	Prince Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866495	151.172873	1		install new kerb ramp	UH647	Secondary	MED	\$	2,500
CD1906	Gordon Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.866475	151.173002	1		install new Tactile Ground Surface Indicators	UH648	Secondary	MED	\$	650
CD1907	Dunk Street	Rozelle	Local Road	crossing deficiency	misaligned kerb ramp	-33.866852	151.172909	1		install new kerb ramp	UH649	Secondary	MED	\$	2,500
CD1908	Homesy Street	Rozelle	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.867716	151.172817	1		install new Tactile Ground Surface Indicators	UH650	Secondary	MED	\$	650
CD1909	Gordon Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgsi</										

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD1921	Livfield Road	Rozelle	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.869686	151.170823	1		install new kerb ramp - pair	UH662	Secondary	MED	\$	5,000
CD1922	Livfield Road	Rozelle	Regional Road	crossing deficiency	missing crossing point - future park access	-33.869695	151.171029	1		install new kerb ramp - pair, new refuge island	UH663	Secondary	MED	\$	7,000
CD1923	Livfield Road	Rozelle	Regional Road	crossing deficiency	missing kerb ramp - pair	-33.870848	151.170227	1		install new kerb ramp - pair	UH664	Secondary	MED	\$	5,000
CD1924	Livfield Road	Rozelle	Regional Road	crossing deficiency	missing crossing point - future park access	-33.870985	151.170104	1		install new kerb ramp - pair, new refuge island	UH665	Secondary	MED	\$	7,000
CD1929	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.863646	151.165320	1		install new kerb ramp - pair	UH666	Secondary	MED	\$	5,000
CD1931	Norton Street	Ashfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.891284	151.127951	1		further investigation required - pedestrian crossing	UH667	Secondary	MED	\$	10,000
CD1930	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.864216	151.165602	1		install new kerb ramp	UH668	Secondary	MED	\$	2,500
CD1931	Manning Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.865215	151.166302	1		install new kerb ramp	UH669	Secondary	MED	\$	2,500
CD1932	Mullens Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.853846	151.176639	1		install new Tactile Ground Surface Indicators - pair	UH670	Secondary	MED	\$	1,300
CD1933	Mullens Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.864031	151.176778	1		install new kerb ramp	UH671	Secondary	MED	\$	2,500
CD1934	Manfield street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.86416	151.176741	1		install new kerb ramp	UH672	Secondary	MED	\$	2,500
CD1935	Mullens Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp - pair	-33.863082	151.176432	1		install new kerb ramp - pair	UH673	Secondary	MED	\$	5,000
CD1938	Mullens Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi - pair	-33.863454	151.176531	1		install new Tactile Ground Surface Indicators - pair	UH674	Secondary	MED	\$	1,300
CD1939	Robert Street	Rozelle	Regional Road	crossing deficiency	narrow kerb ramp - pair	-33.866163	151.176516	1		install new kerb ramp - pair	UH675	Secondary	MED	\$	5,000
CD194	Norton Street	Ashfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.891444	151.130048	1		further investigation required - pedestrian crossing	UH676	Secondary	MED	\$	10,000
CD1940	Cruscent Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866634	151.175495	1		install new kerb ramp - pair	UH677	Secondary	MED	\$	5,000
CD1943	Terry Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861841	151.166463	1		install new kerb ramp - pair	UH678	Secondary	MED	\$	5,000
CD1945	Terry Street	Rozelle	Local Road	crossing deficiency	narrow refuge island	-33.86069	151.169973	1		install new refuge island	UH679	Secondary	MED	\$	15,000
CD1946	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.860664	151.169994	1		install new kerb ramp	UH680	Secondary	MED	\$	2,500
CD1947	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp - pair	-33.860355	151.170337	1		install new kerb ramp - pair	UH681	Secondary	MED	\$	5,000
CD1948	Terry Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858863	151.171122	1		install new kerb ramp	UH682	Secondary	MED	\$	2,500
CD1949	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp	-33.85877	151.171152	1		install new kerb ramp	UH683	Secondary	MED	\$	2,500
CD195	Queen Street	Ashfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.892005	151.127878	1		further investigation required - pedestrian crossing	UH684	Secondary	MED	\$	10,000
CD1960	Terry Street	Rozelle	Local Road	crossing deficiency	missing kerb ramp - pair	-33.860453	151.170346	1		install new kerb ramp - pair	UH685	Secondary	MED	\$	5,000
CD1962	Robert Street	Rozelle	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.866745	151.175269	1		install new Tactile Ground Surface Indicators	UH686	Secondary	MED	\$	650
CD1966	Crystal Lane	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.862043	151.167416	1		install new kerb ramp - pair	UH687	Secondary	MED	\$	5,000
CD1968	Manley Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.866143	151.173754	1		install new kerb ramp	UH688	Secondary	MED	\$	2,500
CD1969	Harley Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865737	151.173263	1		install new kerb ramp - pair	UH689	Secondary	MED	\$	5,000
CD1960	Robert Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.866964	151.175467	1		install new kerb ramp	UH690	Secondary	MED	\$	5,000
CD1966	Loughlin Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866075	151.174188	1		install new kerb ramp - pair	UH691	Secondary	MED	\$	2,500
CD1967	Livfield Road	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.868327	151.176717	1		install new kerb ramp	UH692	Secondary	MED	\$	5,000
CD1968	Victoria Road	Rozelle	State Road	crossing deficiency	missing crossing point	-33.867011	151.175164	1		install new kerb ramp - pair	UH693	Secondary	MED	\$	5,000
CD1971	Campbell Street	St Peters	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.911797	151.177657	1		install new kerb ramp	UH694	Secondary	MED	\$	2,500
CD1973	Church Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912762	151.178077	1		install new kerb ramp	UH695	Secondary	MED	\$	2,500
CD1974	Church Street	St Peters	Local Road	crossing deficiency	missing crossing point	-33.913402	151.177459	1		install new kerb ramp - pair	UH696	Secondary	MED	\$	5,000
CD1975	Church Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91216	151.177576	1		install new kerb ramp - pair	UH697	Secondary	MED	\$	2,500
CD1981	Sutherland Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.916819	151.172659	1		install new kerb ramp - pair	UH698	Secondary	MED	\$	5,000
CD1982	Frederica Street	St Peters	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.916819	151.172033	1		install new kerb ramp - pair	UH699	Secondary	MED	\$	5,000
CD1983	Talbot Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919638	151.168754	1		install new kerb ramp - pair	UH700	Secondary	MED	\$	5,000
CD1984	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919235	151.16939	1		install new kerb ramp - pair	UH701	Secondary	MED	\$	5,000
CD1985	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919066	151.170921	1		install new kerb ramp - pair	UH702	Secondary	MED	\$	5,000
CD1986	Princes Highway	St Peters	State Road	crossing deficiency	missing kerb ramp - pair	-33.917498	151.171195	1		install new kerb ramp - pair	UH703	Secondary	MED	\$	5,000
CD1987	Princes Highway	St Peters	State Road	crossing deficiency	missing crossing point	-33.915677	151.174383	1		install new kerb ramp - pair	UH704	Secondary	MED	\$	5,000
CD1988	Canal Road	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915624	151.174663	1		install new kerb ramp - pair	UH705	Secondary	MED	\$	5,000
CD1989	Princes Highway	St Peters	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91554	151.174815	1		install new kerb ramp - pair	UH706	Secondary	MED	\$	5,000
CD1990	Mary Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915454	151.174502	1		install new kerb ramp - pair	UH707	Secondary	MED	\$	5,000
CD1991	Alfred Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915771	151.173918	1		install new kerb ramp - pair	UH708	Secondary	MED	\$	5,000
CD2	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88697	151.166512	1		install new Tactile Ground Surface Indicators	UH709	Secondary	MED	\$	650
CD2004	St Peter Street	St Peters	Local Road	crossing deficiency	missing crossing point	-33.912884	151.176709	1		install new kerb ramp - pair	UH710	Secondary	MED	\$	5,000
CD2005	Sutherland Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914086	151.169965	1		install new kerb ramp	UH711	Secondary	MED	\$	2,500
CD2006	Grove Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.913505	151.170742	1		install new kerb ramp	UH712	Secondary	MED	\$	2,500
CD2008	Salisbury Lane	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90905	151.170547	1		install new kerb ramp	UH713	Secondary	MED	\$	2,500
CD2015	Stanley Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893142	151.15942	1		install new kerb ramp	UH714	Secondary	MED	\$	2,500
CD202	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879412	151.131048	1		install new kerb ramp - pair	UH715	Secondary	MED	\$	5,000
CD2020	Gordon Crescent	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894369	151.161218	1		install new kerb ramp - pair	UH716	Secondary	MED	\$	5,000
CD2021	Gordon Crescent	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893378	151.15943	1		install new kerb ramp	UH717	Secondary	MED	\$	2,500
CD2026	Harlow Road	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.896372	151.170757	1		install new kerb ramp	UH718	Secondary	MED	\$	2,500
CD2027	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp - pair	-33.897108	151.166898	1		install new kerb ramp - pair	UH719	Secondary	MED	\$	5,000
CD2028	Merchant Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.897108	151.166772	1		install new kerb ramp	UH720	Secondary	MED	\$	2,500
CD2029	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.896971	151.16663	1		install new kerb ramp	UH721	Secondary	MED	\$	2,500
CD203	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.883402	151.124342	1		install new Tactile Ground Surface Indicators - pair	UH722	Secondary	MED	\$	1,300
CD2030	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.897548	151.166705	1		install new kerb ramp	UH723	Secondary	MED	\$	2,500
CD2031	Merchant Street	Stammore	Local Road	crossing deficiency	raised kerb ramp lip	-33.896077	151.167443	1		install new kerb ramp	UH724	Secondary	MED	\$	2,500
CD2032	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.897299	151.166573	1		install new kerb ramp	UH725	Secondary	MED	\$	2,500
CD204	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.882725	151.124037	1		install new Tactile Ground Surface Indicators - pair	UH726	Secondary	MED	\$	1,300
CD2041	Paranatta Road	Stammore	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888186	151.165018	1		install new kerb ramp - pair	UH727	Secondary	MED	\$	5,000
CD2042	Bridge Road	Stammore	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887727	151.171551	1		install new kerb ramp - pair	UH728	Secondary	MED	\$	5,000
CD205	Alt Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.882622	151.124953	1		install new kerb ramp - pair	UH729	Secondary	MED	\$	5,000
CD2054	Rayway Avenue	Stammore	Local Road	crossing deficiency	misaligned refuge island	-33.893778	151.167464	1		re-construct refuge island	UH730	Secondary	MED	\$	15,000
CD206	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.89263	151.125018	1		install new Tactile Ground Surface Indicators - pair	UH731	Secondary	MED	\$	650
CD2062	Durham Street	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891683	151.168495	1		install new kerb ramp	UH732	Secondary	MED	\$	2,500
CD2063	Salisbury Road	Stammore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.891245	151.170413	1		install new kerb ramp	UH733	Secondary	MED	\$	2,500
CD2065	Merchant Street	Stammore	Local Road	crossing deficiency	missing kerb ramp	-33.897556	151.166947	1		install new kerb ramp	UH734	Secondary	MED	\$	2,500
CD2066	Stammore Road	Stammore	State Road	crossing deficiency	misaligned kerb ramp	-33.897611	151.16634	1		install new kerb ramp	UH735	Secondary	MED	\$	2,500
CD2071	Drynan Street	Summer Hill	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.893565	151.132904	1		further investigation required - pedestrian crossing	UH736	Secondary	MED	\$	10,000
CD2072	Smith Street	Summer Hill	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.892707	151.141805	1		further investigation required - pedestrian crossing	UH737	Secondary	MED	\$	10,000
CD2073	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898763	151.131495	1		install new kerb ramp - pair	UH738	Secondary	MED	\$	5,000
CD2077	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	raised kerb ramp lip - pair	-33.891733	151.142156	1		install new kerb ramp - pair	UH739	Secondary	MED	\$	5,000
CD2078	Carlton Crescent	Summer Hill	Regional Road	crossing deficiency	missing crossing point	-33.892465	151.14378	1		install new kerb ramp - pair	UH740	Secondary	MED	\$	5,000
CD2080	Poor Mill Way Hill	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgi	-33.892014	151.142347	1		install new Tactile Ground Surface Indicators	UH741	Secondary	MED	\$	5,000
CD2081	French Lane	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89746	151.144604	1		install new kerb ramp - pair	UH742	Secondary	MED	\$	5,000
CD2083	Grosvener Crescent	Summer Hill	Local Road	crossing deficiency	missing crossing point	-33.892461	151.144	1		install new kerb ramp - pair	UH743	Secondary	MED	\$	5,000
CD2085	Henson Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896381	151.134978	1		install new kerb ramp - pair	UH744	Secondary	MED	\$	5,000
CD2086	Herbert Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.896337	151.134492	1		install new kerb ramp - pair	UH745	Secondary	MED	\$	5,000
CD															

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD2100	Junction Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895341	151.136659	1		install new kerb ramp - pair	UH757	Secondary	MED	\$ 5,000
CD2102	Oaklands Avenue	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888194	151.135129	1		install new kerb ramp - pair	UH758	Secondary	MED	\$ 5,000
CD2103	Kensington Road	Summer Hill	Local Road	crossing deficiency	long crossing	-33.898852	151.137615	1		install kerb risers/flush outs	UH759	Secondary	MED	\$ 10,000
CD2104	Grosvener Crescent	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884119	151.132474	1		install new kerb ramp - pair	UH760	Secondary	MED	\$ 5,000
CD2106	Nowarie Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882396	151.138806	1		install new kerb ramp - pair	UH761	Secondary	MED	\$ 5,000
CD2107	Nowarie Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.88426	151.138754	1		install new Tactile Ground Surface Indicators - pair	UH762	Secondary	MED	\$ 1,300
CD2108	Nowarie Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885477	151.138597	1		install new kerb ramp - pair	UH763	Secondary	MED	\$ 5,000
CD2109	Nowarie Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.8835	151.138692	1		install new kerb ramp - pair	UH764	Secondary	MED	\$ 5,000
CD2119	Paramatta Road	Summer Hill	State Road	crossing deficiency	missing kerb ramp	-33.887654	151.141804	1		install new kerb ramp	UH765	Secondary	MED	\$ 2,500
CD2122	Prospect Road	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.894463	151.132263	1		install new Tactile Ground Surface Indicators - pair	UH766	Secondary	MED	\$ 1,300
CD2123	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88963	151.132295	1		install new kerb ramp - pair	UH767	Secondary	MED	\$ 5,000
CD2124	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89353	151.132342	1		install new kerb ramp	UH768	Secondary	MED	\$ 2,500
CD2125	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89345	151.132477	1		install new kerb ramp - pair	UH769	Secondary	MED	\$ 5,000
CD2126	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898764	151.132216	1		install new kerb ramp - pair	UH770	Secondary	MED	\$ 5,000
CD2128	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896284	151.132403	1		install new kerb ramp - pair	UH771	Secondary	MED	\$ 5,000
CD2129	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897966	151.132522	1		install new kerb ramp - pair	UH772	Secondary	MED	\$ 5,000
CD2133	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp	-33.891694	151.134315	1		install new kerb ramp	UH773	Secondary	MED	\$ 2,500
CD2136	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.891818	151.138099	1		install new kerb ramp - pair	UH774	Secondary	MED	\$ 5,000
CD2137	Smith Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.892043	151.138786	1		install new Tactile Ground Surface Indicators - pair	UH775	Secondary	MED	\$ 1,300
CD2138	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892384	151.140438	1		install new kerb ramp - pair	UH776	Secondary	MED	\$ 5,000
CD2139	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892614	151.141703	1		install new kerb ramp - pair	UH777	Secondary	MED	\$ 5,000
CD2140	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.892496	151.143564	1		install new kerb ramp - pair	UH778	Secondary	MED	\$ 5,000
CD2141	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892822	151.14172	1		install new kerb ramp - pair	UH779	Secondary	MED	\$ 5,000
CD2142	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892952	151.140356	1		install new kerb ramp - pair	UH780	Secondary	MED	\$ 5,000
CD2143	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892374	151.139908	1		install new kerb ramp - pair	UH781	Secondary	MED	\$ 5,000
CD2144	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892089	151.138984	1		install new kerb ramp - pair	UH782	Secondary	MED	\$ 5,000
CD2145	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.891423	151.134807	1		install new kerb ramp - pair	UH783	Secondary	MED	\$ 5,000
CD2146	Smith Street	Summer Hill	Local Road	crossing deficiency	missing kerb ramp - pair	-33.891707	151.135505	1		install new kerb ramp - pair	UH784	Secondary	MED	\$ 5,000
CD2147	Smith Street	Summer Hill	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.8917	151.13323	1		install new Tactile Ground Surface Indicators - pair	UH785	Secondary	MED	\$ 1,300
CD2148	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89178	151.132522	1		install new kerb ramp - pair	UH786	Secondary	MED	\$ 5,000
CD2149	Smith Street	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891666	151.133624	1		install new kerb ramp - pair	UH787	Secondary	MED	\$ 5,000
CD2150	Smith Street	Summer Hill	Local Road	crossing deficiency	long crossing	-33.892086	151.138857	1		install kerb extension	UH788	Secondary	MED	\$ 10,000
CD2154	Burrows Avenue	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915074	151.166403	1		install new kerb ramp - pair	UH789	Secondary	MED	\$ 5,000
CD2156	George Street	Sydenham	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.914601	151.167272	1		install new Tactile Ground Surface Indicators - pair	UH790	Secondary	MED	\$ 1,300
CD2159	Burrows Avenue	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.915007	151.166175	1		install new kerb ramp	UH791	Secondary	MED	\$ 2,500
CD2160	Belmore Street	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment	-33.920181	151.16792	1		install new kerb ramp	UH792	Secondary	MED	\$ 2,500
CD2161	Park Road	Sydenham	Local Road	crossing deficiency	misaligned kerb ramp	-33.919654	151.16881	1		install new kerb ramp	UH793	Secondary	MED	\$ 2,500
CD2162	Yelverton Street	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91740	151.17340	1		install new kerb ramp - pair	UH794	Secondary	MED	\$ 5,000
CD2163	George Street	Sydenham	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.918021	151.170721	1		install new kerb ramp - pair	UH795	Secondary	MED	\$ 5,000
CD2165	Railway Road	Sydenham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919086	151.169292	1		install new kerb ramp - pair	UH796	Secondary	MED	\$ 5,000
CD2166	Railway Road	Sydenham	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919104	151.169186	1		install new kerb ramp - pair	UH797	Secondary	MED	\$ 5,000
CD2167	Belmore Street	Sydenham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920186	151.16791	1		install new kerb ramp - pair	UH798	Secondary	MED	\$ 5,000
CD2172	Gannon Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.924783	151.159867	1		install new kerb ramp - pair	UH799	Secondary	MED	\$ 5,000
CD2173	Gannon Street	Tempe	Local Road	crossing deficiency	misaligned kerb ramp	-33.923643	151.157903	1		install new kerb ramp	UH800	Secondary	MED	\$ 2,500
CD2174	Gannon Street	Tempe	Local Road	crossing deficiency	steep kerb ramp	-33.92326	151.157321	1		install new kerb ramp - pair	UH801	Secondary	MED	\$ 5,000
CD2175	Griffiths Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.924748	151.156844	1		install new kerb ramp	UH802	Secondary	MED	\$ 2,500
CD2176	Griffiths Street	Tempe	Local Road	crossing deficiency	at grade crossing missing tgi	-33.924132	151.156971	1		install new Tactile Ground Surface Indicators	UH803	Secondary	MED	\$ 650
CD2177	Gannon Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.925033	151.160396	1		install new kerb ramp	UH804	Secondary	MED	\$ 2,500
CD2182	Samuel Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.92094	151.165621	1		install new kerb ramp	UH805	Secondary	MED	\$ 2,500
CD2183	Terry Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.920473	151.167509	1		install new kerb ramp	UH806	Secondary	MED	\$ 2,500
CD2184	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920502	151.16772	1		install new kerb ramp - pair	UH807	Secondary	MED	\$ 5,000
CD2185	Terry Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920456	151.167503	1		install new kerb ramp - pair	UH808	Secondary	MED	\$ 5,000
CD2186	Terry Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920534	151.16733	1		install new kerb ramp - pair	UH809	Secondary	MED	\$ 5,000
CD2187	Lymerston Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.921107	151.165531	1		install new kerb ramp - pair	UH810	Secondary	MED	\$ 5,000
CD2188	Foran Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.922104	151.16389	1		install new kerb ramp - pair	UH811	Secondary	MED	\$ 5,000
CD2190	Princes Highway	Tempe	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.923038	151.162371	1		install new kerb ramp - pair	UH812	Secondary	MED	\$ 5,000
CD2195	Bellevue Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.920626	151.167628	1		install new kerb ramp - pair	UH813	Secondary	MED	\$ 5,000
CD2196	Station Street West	Tempe	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.925848	151.159681	1		install new kerb ramp - pair	UH814	Secondary	MED	\$ 5,000
CD22	Pymont Bridge Road	Annandale	State Road	crossing deficiency	missing kerb ramp	-33.887368	151.173594	1		install new kerb ramp	UH815	Secondary	MED	\$ 2,500
CD2200	Station Street West	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.925714	151.159408	1		install new kerb ramp - pair	UH816	Secondary	MED	\$ 5,000
CD2201	Hart Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.925374	151.160182	1		install new kerb ramp - pair	UH817	Secondary	MED	\$ 5,000
CD2202	Unwinds Bridge Road	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.922385	151.157902	1		install new kerb ramp - pair	UH818	Secondary	MED	\$ 5,000
CD2203	Richardson Crescent	Tempe	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.922288	151.158309	1		install new kerb ramp - pair	UH819	Secondary	MED	\$ 5,000
CD2204	Union Street	Tempe	Local Road	crossing deficiency	at grade crossing missing tgi	-33.92163	151.160547	1		install new Tactile Ground Surface Indicators	UH820	Secondary	MED	\$ 650
CD2205	Union Street	Tempe	Local Road	crossing deficiency	poor kerb ramp alignment	-33.921885	151.160889	1		install new kerb ramp	UH821	Secondary	MED	\$ 2,500
CD2206	Union Street	Tempe	Local Road	crossing deficiency	at grade crossing missing tgi	-33.921161	151.15998	1		install new Tactile Ground Surface Indicators	UH822	Secondary	MED	\$ 650
CD2207	Unwinds Bridge Road	Tempe	Regional Road	crossing deficiency	misaligned kerb ramp	-33.920345	151.160554	1		install new kerb ramp	UH823	Secondary	MED	\$ 2,500
CD2227	Carlton Crescent	Ashfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.896997	151.131654	1		install new kerb ramp - pair	UH824	Secondary	MED	\$ 5,000
CD23	Pymont Bridge Road	Annandale	State Road	crossing deficiency	missing kerb ramp - pair	-33.887265	151.173594	1		install new kerb ramp - pair	UH825	Secondary	MED	\$ 5,000
CD235	Church Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.878461	151.126867	1		install new Tactile Ground Surface Indicators - pair	UH826	Secondary	MED	\$ 5,000
CD236	Cissold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895787	151.13099	1		install new kerb ramp - pair	UH827	Secondary	MED	\$ 5,000
CD24	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp construction	-33.884754	151.167648	1		install new kerb ramp	UH828	Secondary	MED	\$ 2,500
CD241	Cissold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.89586	151.13098	1		install new kerb ramp	UH829	Secondary	MED	\$ 5,000
CD242	Cissold Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.895544	151.130406	1		install new Tactile Ground Surface Indicators - pair	UH830	Secondary	MED	\$ 1,300
CD243	Cissold Street	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.895727	151.12978	1		install new kerb ramp	UH831	Secondary	MED	\$ 2,500
CD244	Cissold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895571	151.127487	1		install new kerb ramp - pair	UH832	Secondary	MED	\$ 5,000
CD245	Cissold Street	Ashfield	Local Road	crossing deficiency	misaligned refuge island	-33.89563	151.127616	1		install new kerb ramp	UH833	Secondary	MED	\$ 15,000
CD246	Cissold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895601	151.127633	1		install new kerb ramp - pair	UH834	Secondary	MED	\$ 5,000
CD247	Cissold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895554	151.128633	1		install new kerb ramp - pair	UH835	Secondary	MED	\$ 5,000
CD248	Cissold Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.89576	151.128673	1		install new Tactile Ground Surface Indicators	UH836	Secondary	MED	\$ 650
CD25	Johnston Street	Annandale	State Road	crossing deficiency	poor kerb ramp alignment	-33.887841	151.167985	1		install new kerb ramp	UH837	Secondary	MED	\$ 2,500
CD26	Paramatta Road	Annandale	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88812	151.164827	1		install new kerb ramp - pair	UH838	Secondary	MED	\$ 5,000
CD260	Benalla Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884641	151.121621	1		install new kerb ramp - pair	UH839	Secondary	MED	\$ 5,000
CD266	Thomas Street	Ashfield	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.88656	151.118653	1		install new kerb ramp - pair	UH840	Secondary	MED	\$ 5,000
CD27	Paramatta Road	Annandale	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886641	151.176398	1		install new kerb ramp - pair	UH841	Secondary	MED	\$ 5,000
CD270	Church Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878889	151.125555	1		install new kerb ramp - pair	UH842	Secondary	MED	\$ 5,000
CD277	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.884023	151.							

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD289	Frederick Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877101	151.12965	1		install new kerb ramp - pair	UH852	Secondary	MED	\$ 5,000
CD290	Henry Lane	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877005	151.129274	1		install new kerb ramp - pair	UH853	Secondary	MED	\$ 5,000
CD292	Thomas Street	Ashfield	Local Road	crossing deficiency	narrow kerb ramp	-33.88555	151.11852	1		install new kerb ramp	UH854	Secondary	MED	\$ 2,500
CD293	Albert Parade	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.882199	151.121631	1		install new kerb ramp - pair	UH855	Secondary	MED	\$ 5,000
CD294	Georges River Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893236	151.116927	1		install new kerb ramp - pair	UH856	Secondary	MED	\$ 5,000
CD3	Calina Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893622	151.169756	1		install new kerb ramp - pair	UH857	Secondary	MED	\$ 5,000
CD300	Blackwood Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893244	151.117155	1		install new kerb ramp - pair	UH858	Secondary	MED	\$ 5,000
CD301	Watson Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893406	151.116773	1		install new kerb ramp - pair	UH859	Secondary	MED	\$ 5,000
CD305	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903047	151.125991	1		install new kerb ramp	UH860	Secondary	MED	\$ 2,500
CD311	Trafalgar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887693	151.169716	1		install new kerb ramp - pair	UH861	Secondary	MED	\$ 5,000
CD312	Holden Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893709	151.125363	1		install new Tactile Ground Surface Indicators	UH862	Secondary	MED	\$ 650
CD313	Holden Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.89455	151.12516	1		install new Tactile Ground Surface Indicators - pair	UH863	Secondary	MED	\$ 1,300
CD314	Holden Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89413	151.125188	1		install new kerb ramp - pair	UH864	Secondary	MED	\$ 5,000
CD32	Perivale Road	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888091	151.164842	1		install new kerb ramp - pair	UH865	Secondary	MED	\$ 5,000
CD327	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886159	151.138667	1		install new kerb ramp - pair	UH866	Secondary	MED	\$ 5,000
CD33	Piper Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877515	151.168629	1		install new Tactile Ground Surface Indicators	UH867	Secondary	MED	\$ 650
CD337	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.889369	151.130209	1		install new kerb ramp	UH868	Secondary	MED	\$ 2,500
CD338	Liverpool Road	Ashfield	State Road	crossing deficiency	missing kerb ramp	-33.889337	151.1322	1		install new kerb ramp	UH869	Secondary	MED	\$ 2,500
CD34	Piper Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.877438	151.168645	1		install new kerb ramp	UH870	Secondary	MED	\$ 2,500
CD341	Liverpool Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887478	151.121167	1		install new kerb ramp - pair	UH871	Secondary	MED	\$ 5,000
CD343	Marham Place	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88745	151.123253	1		install new kerb ramp	UH872	Secondary	MED	\$ 2,500
CD344	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891611	151.117025	1		install new kerb ramp - pair	UH873	Secondary	MED	\$ 5,000
CD345	Milton Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891433	151.11702	1		install new kerb ramp - pair	UH874	Secondary	MED	\$ 5,000
CD346	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891055	151.11728	1		install new kerb ramp - pair	UH875	Secondary	MED	\$ 5,000
CD347	Milton Street	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891627	151.117176	1		install new kerb ramp - pair	UH876	Secondary	MED	\$ 5,000
CD348	Palace Lane	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.894331	151.118216	1		install new Tactile Ground Surface Indicators - pair	UH877	Secondary	MED	\$ 1,300
CD349	Park Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893968	151.117417	1		install new kerb ramp	UH878	Secondary	MED	\$ 2,500
CD35	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885997	151.165526	1		install new kerb ramp - pair	UH879	Secondary	MED	\$ 5,000
CD350	Dougan Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894072	151.117391	1		install new kerb ramp	UH880	Secondary	MED	\$ 2,500
CD351	Milton Street	Ashfield	Regional Road	crossing deficiency	missing crossing point	-33.894072	151.117628	1		install new kerb ramp - pair	UH881	Secondary	MED	\$ 5,000
CD352	Dougan Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.89406	151.11745	1		install new Tactile Ground Surface Indicators	UH882	Secondary	MED	\$ 650
CD353	Viabley Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894544	151.118445	1		install new kerb ramp - pair	UH883	Secondary	MED	\$ 5,000
CD354	Milton Street	Ashfield	Regional Road	crossing deficiency	missing crossing point	-33.894862	151.118283	1		install new kerb ramp - pair	UH884	Secondary	MED	\$ 5,000
CD355	Arthur Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891533	151.117028	1		install new kerb ramp - pair	UH885	Secondary	MED	\$ 5,000
CD36	Piper Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877452	151.168691	1		install new Tactile Ground Surface Indicators	UH886	Secondary	MED	\$ 650
CD371	Orpington Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884446	151.134738	1		install new kerb ramp - pair	UH887	Secondary	MED	\$ 5,000
CD372	Orpington Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885439	151.132245	1		install new kerb ramp - pair	UH888	Secondary	MED	\$ 5,000
CD374	Orpington Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88494	151.133126	1		install new kerb ramp - pair	UH889	Secondary	MED	\$ 5,000
CD375	Orpington Street	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.884454	151.134666	1		install new kerb ramp	UH890	Secondary	MED	\$ 2,500
CD376	Palace Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.884888	151.122279	1		install new kerb ramp	UH891	Secondary	MED	\$ 2,500
CD377	Palace Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.884444	151.120729	1		install raised continuous footpath and tgi	UH892	Secondary	MED	\$ 30,000
CD378	Paranatta Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.884816	151.135449	1		install new kerb ramp	UH893	Secondary	MED	\$ 2,500
CD379	Paranatta Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment	-33.884816	151.135449	1		install new kerb ramp	UH894	Secondary	MED	\$ 2,500
CD38	Piper Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.87736	151.169715	1		install new Tactile Ground Surface Indicators	UH895	Secondary	MED	\$ 650
CD380	Earle Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.876887	151.129117	1		install new kerb ramp	UH896	Secondary	MED	\$ 2,500
CD381	Page Avenue	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875644	151.128572	1		install new kerb ramp - pair	UH897	Secondary	MED	\$ 5,000
CD382	Paranatta Road	Ashfield	Local Road	crossing deficiency	long driveway crossing point	-33.874946	151.128058	1		install new Tactile Ground Surface Indicators	UH898	Secondary	MED	\$ 650
CD383	Paranatta Road	Ashfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886033	151.138642	1		install new kerb ramp - pair	UH899	Secondary	MED	\$ 5,000
CD384	Premier Street	Ashfield	Local Road	crossing deficiency	long crossing	-33.894038	151.119392	1		install kerb extension - pair	UH900	Secondary	MED	\$ 20,000
CD385	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893327	151.127898	1		install new kerb ramp	UH901	Secondary	MED	\$ 5,000
CD386	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892037	151.127972	1		install new kerb ramp - pair	UH902	Secondary	MED	\$ 5,000
CD388	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891824	151.127821	1		install new kerb ramp - pair	UH903	Secondary	MED	\$ 5,000
CD389	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892834	151.12776	1		install new kerb ramp - pair	UH904	Secondary	MED	\$ 5,000
CD39	Piper Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.87753	151.168767	1		install new kerb ramp - pair	UH905	Secondary	MED	\$ 5,000
CD390	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893553	151.12769	1		install new kerb ramp - pair	UH906	Secondary	MED	\$ 5,000
CD391	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894093	151.127458	1		install new kerb ramp - pair	UH907	Secondary	MED	\$ 5,000
CD392	Queen Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895718	151.127635	1		install new kerb ramp - pair	UH908	Secondary	MED	\$ 5,000
CD394	The Esplanade	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.887604	151.123888	1		install new kerb ramp	UH909	Secondary	MED	\$ 2,500
CD396	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886529	151.118683	1		install new kerb ramp	UH910	Secondary	MED	\$ 2,500
CD397	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886406	151.118019	1		install new kerb ramp - pair	UH911	Secondary	MED	\$ 5,000
CD398	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887106	151.120368	1		install new kerb ramp - pair	UH912	Secondary	MED	\$ 5,000
CD399	Thomas Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887507	151.121338	1		install new kerb ramp - pair	UH913	Secondary	MED	\$ 5,000
CD4	Colina Street	Annandale	Regional Road	crossing deficiency	misaligned kerb ramp	-33.83808	151.168656	1		install new kerb ramp	UH914	Secondary	MED	\$ 2,500
CD40	Pritchard Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.872122	151.173016	1		install new kerb ramp	UH915	Secondary	MED	\$ 5,000
CD402	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892076	151.129946	1		install new kerb ramp - pair	UH916	Secondary	MED	\$ 5,000
CD403	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891317	151.130115	1		install new kerb ramp	UH917	Secondary	MED	\$ 2,500
CD404	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893239	151.130058	1		install new kerb ramp	UH918	Secondary	MED	\$ 2,500
CD405	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895694	151.129928	1		install new kerb ramp - pair	UH919	Secondary	MED	\$ 5,000
CD406	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895647	151.129761	1		install new kerb ramp - pair	UH920	Secondary	MED	\$ 5,000
CD407	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.894725	151.129715	1		install new Tactile Ground Surface Indicators - pair	UH921	Secondary	MED	\$ 1,300
CD408	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893345	151.129901	1		install new kerb ramp	UH922	Secondary	MED	\$ 2,500
CD409	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.89891	151.129677	1		install new Tactile Ground Surface Indicators - pair	UH923	Secondary	MED	\$ 1,300
CD41	Pritchard Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.873864	151.174298	1		install new kerb ramp	UH924	Secondary	MED	\$ 2,500
CD410	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897776	151.129517	1		install new kerb ramp - pair	UH925	Secondary	MED	\$ 5,000
CD411	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.897847	151.129622	1		install new kerb ramp - pair	UH926	Secondary	MED	\$ 5,000
CD412	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.897858	151.129667	1		install new kerb ramp	UH927	Secondary	MED	\$ 2,500
CD413	Victoria Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.898498	151.129475	1		install new kerb ramp	UH928	Secondary	MED	\$ 5,000
CD414	Victoria Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.899477	151.12943	1		install new kerb ramp	UH929	Secondary	MED	\$ 2,500
CD415	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.898691	151.129556	1		install new kerb ramp - pair	UH930	Secondary	MED	\$ 5,000
CD416	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.900869	151.129438	1		install new Tactile Ground Surface Indicators	UH931	Secondary	MED	\$ 650
CD417	Victoria Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.900807	151.129355	1		install new Tactile Ground Surface Indicators - pair	UH932	Secondary	MED	\$ 1,300
CD418	Victoria Street	Ashfield	Local Road	crossing deficiency	raised kerb ramp lip	-33.900923	151.129328	1		install new kerb ramp	UH933	Secondary	MED	\$ 2,500
CD419	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.901701	151.129439	1		install new kerb ramp - pair	UH934	Secondary	MED	\$ 5,000
CD420	Victoria Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.903443	151.129214	1		install new kerb ramp - pair	UH935	Secondary	MED	\$ 5,000
CD421	Beattie Street	Balmann	Local Road	crossing deficiency	missing kerb ramp - pair	-33.858665	151.177582	1		install new kerb ramp - pair	UH936	Secondary	MED	\$ 5,000
CD422	Beattie Street	Balmann	Local Road	crossing deficiency	missing kerb ramp - pair	-33.858752	151.177628	1		install new kerb ramp - pair	UH937	Secondary	MED	\$ 5,000
CD423	Beattie Street	Balmann	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857169	151.169933	1						

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD434	Birchgrove Road	Balmain	Local Road	crossing deficiency	missing crossing point	-33.854946	151.175135	1		install new kerb ramp - pair	UH467	Secondary	MED	\$ 5,000
CD435	Birchgrove Road	Balmain	Local Road	crossing deficiency	missing crossing point	-33.854832	151.175188	1		install new kerb ramp - pair	UH468	Secondary	MED	\$ 5,000
CD436	Birchgrove Road	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.853832	151.176763	1		install new kerb ramp	UH469	Secondary	MED	\$ 2,500
CD437	Birchgrove Road	Balmain	Local Road	crossing deficiency	at grade crossing missing tgi	-33.853523	151.17735	1		install new Tactile Ground Surface Indicators	UH500	Secondary	MED	\$ 650
CD440	Pymont Bridge Road	Annandale	State Road	crossing deficiency	at grade crossing missing tgi	-33.886301	151.174784	1		install new Tactile Ground Surface Indicators	UH501	Secondary	MED	\$ 650
CD441	Booth Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.861102	151.182127	1		install new kerb ramp	UH502	Secondary	MED	\$ 2,500
CD442	Booth Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860346	151.181861	1		install new kerb ramp	UH503	Secondary	MED	\$ 2,500
CD445	Curtis Road	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.857084	151.18317	1		install new kerb ramp	UH504	Secondary	MED	\$ 2,500
CD446	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856809	151.182538	1		install new kerb ramp	UH505	Secondary	MED	\$ 2,500
CD447	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856941	151.181	1		install new kerb ramp	UH506	Secondary	MED	\$ 2,500
CD448	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855487	151.180642	1		install new kerb ramp	UH507	Secondary	MED	\$ 2,500
CD449	Curtis Road	Balmain	Local Road	crossing deficiency	raised kerb ramp lip	-33.854832	151.179203	1		install new kerb ramp	UH508	Secondary	MED	\$ 2,500
CD450	Gordon Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.856653	151.174291	1		install new kerb ramp - pair	UH509	Secondary	MED	\$ 5,000
CD450	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854754	151.179224	1		install new kerb ramp	UH510	Secondary	MED	\$ 2,500
CD451	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855018	151.179919	1		install new kerb ramp	UH511	Secondary	MED	\$ 2,500
CD452	Curtis Road	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.855236	151.180902	1		install new kerb ramp	UH512	Secondary	MED	\$ 2,500
CD453	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.851768	151.180907	1		install new kerb ramp	UH513	Secondary	MED	\$ 2,500
CD454	Curtis Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856814	151.18216	1		install new kerb ramp	UH514	Secondary	MED	\$ 2,500
CD457	Elliott Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856533	151.17266	1		install new kerb ramp	UH515	Secondary	MED	\$ 2,500
CD458	Darling Street	Balmain	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.856533	151.178018	1		install new kerb ramp - pair	UH516	Secondary	MED	\$ 5,000
CD459	Rowntree Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856467	151.178058	1		install new kerb ramp	UH517	Secondary	MED	\$ 2,500
CD460	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884669	151.167662	1		install new kerb ramp - pair	UH518	Secondary	MED	\$ 5,000
CD460	Darling Street	Balmain	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.856676	151.17286	1		install new Tactile Ground Surface Indicators	UH519	Secondary	MED	\$ 650
CD461	Elliott Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.856567	151.17227	1		install new kerb ramp - pair	UH520	Secondary	MED	\$ 5,000
CD47	Pymont Bridge Road	Annandale	State Road	crossing deficiency	missing kerb ramp - pair	-33.886806	151.17403	1		install new kerb ramp - pair	UH521	Secondary	MED	\$ 5,000
CD477	Elliott Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.856548	151.171365	1		install new kerb ramp - pair	UH522	Secondary	MED	\$ 5,000
CD478	Glassop Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.856542	151.17231	1		install new kerb ramp - pair	UH523	Secondary	MED	\$ 5,000
CD479	Glassop Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.855092	151.173067	1		install new kerb ramp - pair	UH524	Secondary	MED	\$ 5,000
CD480	Gordon Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.886668	151.174228	1		install new kerb ramp - pair	UH525	Secondary	MED	\$ 5,000
CD480	Glassop Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tgi	-33.851157	151.173172	1		install new Tactile Ground Surface Indicators	UH526	Secondary	MED	\$ 650
CD481	Kessop Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.854054	151.173804	1		install new kerb ramp	UH527	Secondary	MED	\$ 2,500
CD482	Glassop Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.853966	151.175431	1		install new kerb ramp	UH528	Secondary	MED	\$ 2,500
CD483	Glassop Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.854033	151.175476	1		install new kerb ramp - pair	UH529	Secondary	MED	\$ 5,000
CD484	Glassop Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854104	151.176105	1		install new kerb ramp	UH530	Secondary	MED	\$ 2,500
CD485	Glassop Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.854038	151.176140	1		install new kerb ramp	UH531	Secondary	MED	\$ 2,500
CD488	Hyam Street	Balmain	Local Road	crossing deficiency	narrow refuge island	-33.862022	151.179689	1		re-construct refuge island	UH532	Secondary	MED	\$ 15,000
CD489	Hyam Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861929	151.179708	1		install new kerb ramp - pair	UH533	Secondary	MED	\$ 5,000
CD490	Chester Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.885968	151.175138	1		install new kerb ramp	UH534	Secondary	MED	\$ 2,500
CD492	Hyam Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.861579	151.180288	1		install new kerb ramp - pair	UH535	Secondary	MED	\$ 5,000
CD493	Jane Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.85937	151.184494	1		install new Tactile Ground Surface Indicators - pair	UH536	Secondary	MED	\$ 1,300
CD496	Little Llewellyn Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858325	151.177675	1		install new kerb ramp	UH537	Secondary	MED	\$ 2,500
CD5	Johnston Street	Annandale	State Road	crossing deficiency	misaligned kerb ramp - pair	-33.856537	151.168661	1		install new kerb ramp - pair	UH538	Secondary	MED	\$ 5,000
CD500	Rowntree Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.872041	151.17222	1		install new kerb ramp	UH539	Secondary	MED	\$ 2,500
CD500	Montague Street	Balmain	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.85742	151.177855	1		install new kerb ramp - pair	UH540	Secondary	MED	\$ 5,000
CD501	Llewellyn Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857147	151.177838	1		install new kerb ramp	UH541	Secondary	MED	\$ 2,500
CD502	Llewellyn Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.85735	151.177725	1		install new kerb ramp - pair	UH542	Secondary	MED	\$ 5,000
CD503	Little Beattie Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.854777	151.177552	1		install new kerb ramp	UH543	Secondary	MED	\$ 2,500
CD504	Little Beattie Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.859521	151.177543	1		install new kerb ramp	UH544	Secondary	MED	\$ 2,500
CD505	Mulena Street	Balmain	Regional Road	crossing deficiency	at grade crossing missing tgi	-33.859019	151.176509	1		install new Tactile Ground Surface Indicators	UH545	Secondary	MED	\$ 650
CD506	Ennis Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.859992	151.177334	1		install new kerb ramp - pair	UH546	Secondary	MED	\$ 5,000
CD507	Rowntree Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872041	151.172179	1		install new kerb ramp	UH547	Secondary	MED	\$ 2,500
CD510	Mulena Street	Balmain	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.862463	151.176427	1		install new kerb ramp - pair	UH548	Secondary	MED	\$ 5,000
CD511	Henry Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tgi	-33.862057	151.1763	1		install new Tactile Ground Surface Indicators	UH549	Secondary	MED	\$ 650
CD512	Stewards Street	Balmain	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.859656	151.177439	1		install new kerb ramp - pair	UH550	Secondary	MED	\$ 5,000
CD516	Palmer Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.859023	151.180002	1		install new Tactile Ground Surface Indicators - pair	UH551	Secondary	MED	\$ 1,300
CD518	Palmer Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856828	151.180633	1		install new kerb ramp	UH552	Secondary	MED	\$ 2,500
CD517	Palmer Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857994	151.180777	1		install new kerb ramp	UH553	Secondary	MED	\$ 2,500
CD518	Palmer Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858629	151.179686	1		install new kerb ramp	UH554	Secondary	MED	\$ 2,500
CD519	Palmer Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.858139	151.17994	1		install new Tactile Ground Surface Indicators - pair	UH555	Secondary	MED	\$ 1,300
CD520	Palmer Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.872073	151.172003	1		install new kerb ramp	UH556	Secondary	MED	\$ 2,500
CD522	Rowntree Street	Balmain	Local Road	crossing deficiency	narrow refuge island	-33.858708	151.179872	1		install new kerb ramp - pair	UH557	Secondary	MED	\$ 5,000
CD523	Rowntree Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.862166	151.179727	1		install new kerb ramp	UH558	Secondary	MED	\$ 15,000
CD524	Robert Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.862278	151.179690	1		install new kerb ramp	UH559	Secondary	MED	\$ 2,500
CD524	Robert Street	Balmain	Local Road	crossing deficiency	missing crossing point	-33.861409	151.177409	1		install new kerb ramp - pair	UH560	Secondary	MED	\$ 5,000
CD527	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858177	151.171165	1		install new kerb ramp	UH561	Secondary	MED	\$ 2,500
CD528	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857763	151.171032	1		install new kerb ramp	UH562	Secondary	MED	\$ 2,500
CD529	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857264	151.171203	1		install new kerb ramp	UH563	Secondary	MED	\$ 2,500
CD530	Rowntree Street	Annandale	Local Road	crossing deficiency	long crossing point	-33.87502	151.169887	1		install kerb extension / refuge island	UH564	Secondary	MED	\$ 10,000
CD530	Terry Street	Balmain	Local Road	crossing deficiency	at grade crossing missing tgi	-33.858642	151.17123	1		install new Tactile Ground Surface Indicators	UH565	Secondary	MED	\$ 650
CD531	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.858642	151.17123	1		install new kerb ramp - pair	UH566	Secondary	MED	\$ 2,500
CD532	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.856527	151.171211	1		install new kerb ramp	UH567	Secondary	MED	\$ 2,500
CD533	Terry Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.856441	151.17123	1		install new kerb ramp - pair	UH568	Secondary	MED	\$ 5,000
CD534	Thames Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.855448	151.180238	1		install new kerb ramp	UH569	Secondary	MED	\$ 2,500
CD536	Wortley Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861472	151.177496	1		install new kerb ramp - pair	UH570	Secondary	MED	\$ 5,000
CD537	Wortley Street	Balmain	Local Road	crossing deficiency	raised kerb ramp lip	-33.861195	151.178053	1		install new kerb ramp	UH571	Secondary	MED	\$ 2,500
CD538	Wortley Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.861171	151.178159	1		install new kerb ramp	UH572	Secondary	MED	\$ 2,500
CD538	Wortley Street	Balmain	Local Road	crossing deficiency	missing kerb ramp	-33.861103	151.178239	1		install new kerb ramp	UH573	Secondary	MED	\$ 2,500
CD540	Rowe Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.877506	151.176318	1		install new Tactile Ground Surface Indicators	UH574	Secondary	MED	\$ 650
CD540	Wortley Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.859825	151.180566	1		install new kerb ramp	UH575	Secondary	MED	\$ 2,500
CD541	Wortley Street	Balmain	Local Road	crossing deficiency	misaligned kerb ramp	-33.859897	151.18023	1		install new kerb ramp	UH576	Secondary	MED	\$ 2,500
CD545	Wortley Street	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860793	151.178616	1		install new kerb ramp - pair	UH577	Secondary	MED	\$ 5,000
CD546	Darling Street	Balmain East	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858064	151.188655	1		install new kerb ramp	UH578	Secondary	MED	\$ 2,500
CD550	Rowe Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.877386	151.175914	1		install new Tactile Ground Surface Indicators - pair	UH579	Secondary	MED	\$ 1,300
CD551	Birchgrove Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.857386	151.178603	1		install new kerb ramp	UH580	Secondary	MED	\$ 2,500
CD552	Birchgrove Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852633	151.179075	1		install new kerb ramp	UH581	Secondary	MED	\$ 2,500
CD553	Birchgrove Road	Balmain	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852513	151.179083	1		install new kerb ramp	UH582	Secondary	MED	\$ 2,500
CD558	Louisa Road	Birchgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.846819	151.185449	1		install new kerb ramp	UH583	Secondary	MED	\$ 2,500
CD559	Louisa Road	Birchgrove	Local Road	crossing deficiency	missing kerb ramp - pair	-33.846834	151.185549	1		install new kerb ramp - pair	UH58			

P4909 Inner West PAMP Detailed Works Program Crossing Deficiencies 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Treatment	Cost
CD57	Annandale Street	Annandale	Local Road	crossing deficiency	missing crossing point	-33.884651	151.167623	1		install new kerb ramp - pair	LH1042	Secondary	MED	\$	5,000
CD571	Australia Street	Camperdown	Local Road	crossing deficiency	misaligned kerb ramp	-33.893259	151.178873	1		install new kerb ramp	LH1043	Secondary	MED	\$	2,500
CD572	Australia Street	Camperdown	Local Road	crossing deficiency	misaligned kerb ramp	-33.893394	151.176702	1		install new kerb ramp	LH1044	Secondary	MED	\$	2,500
CD573	Australia Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.890438	151.175753	1		install new kerb ramp	LH1045	Secondary	MED	\$	2,500
CD574	Australia Street	Camperdown	Local Road	crossing deficiency	at grade crossing missing tgi	-33.887614	151.174473	1		install new Tactile Ground Surface Indicators	LH1046	Secondary	MED	\$	650
CD575	Derby Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889533	151.174715	1		install new kerb ramp - pair	LH1047	Secondary	MED	\$	5,000
CD576	Derby Street	Camperdown	Local Road	crossing deficiency	missing kerb ramp	-33.889806	151.174582	1		install new kerb ramp	LH1048	Secondary	MED	\$	2,500
CD577	Australia Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887399	151.174346	1		install new kerb ramp - pair	LH1049	Secondary	MED	\$	5,000
CD58	William Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.876294	151.175539	1		install new kerb ramp	LH1050	Secondary	MED	\$	2,500
CD586	Salisbury Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.891852	151.176338	1		install new kerb ramp	LH1051	Secondary	MED	\$	2,500
CD587	Roberts Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891352	151.17797	1		install new kerb ramp - pair	LH1052	Secondary	MED	\$	5,000
CD588	Hopetown Street	Camperdown	Local Road	crossing deficiency	misaligned kerb ramp	-33.89163	151.177091	1		install new kerb ramp	LH1053	Secondary	MED	\$	2,500
CD589	Denison Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891979	151.175472	1		install new kerb ramp - pair	LH1054	Secondary	MED	\$	5,000
CD59	The Crescent	Annandale	State Road	crossing deficiency	missing kerb ramp	-33.876527	151.174683	1		install new kerb ramp	LH1055	Secondary	MED	\$	2,500
CD590	Denison Street	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.891984	151.175489	1		install new kerb ramp - pair	LH1056	Secondary	MED	\$	5,000
CD591	Kington Lane	Camperdown	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891658	151.173178	1		install new kerb ramp	LH1057	Secondary	MED	\$	2,500
CD592	Church Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.876277	151.118565	1		install new kerb ramp	LH1058	Secondary	MED	\$	2,500
CD593	Church Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875917	151.123032	1		install new kerb ramp - pair	LH1059	Secondary	MED	\$	5,000
CD594	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874867	151.124141	1		install new kerb ramp - pair	LH1060	Secondary	MED	\$	5,000
CD595	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873979	151.125053	1		install new kerb ramp	LH1061	Secondary	MED	\$	2,500
CD596	Croydon Road	Croydon	Local Road	crossing deficiency	at grade crossing missing tgi	-33.873537	151.125053	1		install new Tactile Ground Surface Indicators	LH1062	Secondary	MED	\$	650
CD597	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873067	151.126035	1		install new kerb ramp - pair	LH1063	Secondary	MED	\$	5,000
CD598	Croydon Road	Croydon	Local Road	crossing deficiency	at grade crossing missing tgi	-33.873394	151.125776	1		install new Tactile Ground Surface Indicators	LH1064	Secondary	MED	\$	650
CD599	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874373	151.124742	1		install new kerb ramp - pair	LH1065	Secondary	MED	\$	5,000
CD6	Reserve Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885097	151.168967	1		install new kerb ramp - pair	LH1066	Secondary	MED	\$	5,000
CD600	Croydon Road	Croydon	Local Road	crossing deficiency	at grade crossing missing tgi	-33.874706	151.12443	1		install new Tactile Ground Surface Indicators	LH1067	Secondary	MED	\$	650
CD601	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.874658	151.124440	1		install new kerb ramp	LH1068	Secondary	MED	\$	2,500
CD602	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875054	151.126885	1		install new kerb ramp - pair	LH1069	Secondary	MED	\$	5,000
CD603	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880177	151.120274	1		install new kerb ramp - pair	LH1070	Secondary	MED	\$	5,000
CD604	Croydon Road	Croydon	Local Road	crossing deficiency	raised kerb ramp lip - pair	-33.882628	151.118358	1		install new kerb ramp	LH1071	Secondary	MED	\$	5,000
CD605	Croydon Road	Croydon	Local Road	crossing deficiency	at grade crossing missing tgi	-33.881197	151.119332	1		install new Tactile Ground Surface Indicators	LH1072	Secondary	MED	\$	650
CD606	Croydon Road	Croydon	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88105	151.119566	1		install new Tactile Ground Surface Indicators	LH1073	Secondary	MED	\$	650
CD607	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879743	151.120495	1		install new kerb ramp - pair	LH1074	Secondary	MED	\$	5,000
CD608	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878624	151.121204	1		install new kerb ramp - pair	LH1075	Secondary	MED	\$	5,000
CD609	Edwin Street	Croydon	Local Road	crossing deficiency	missing kerb ramp - pair	-33.881546	151.118245	1		install new kerb ramp - pair	LH1076	Secondary	MED	\$	5,000
CD610	Edwin Street	Croydon	Local Road	crossing deficiency	missing kerb ramp	-33.881518	151.118159	1		install new kerb ramp	LH1077	Secondary	MED	\$	2,500
CD611	Edwin Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881531	151.11814	1		install new kerb ramp	LH1078	Secondary	MED	\$	2,500
CD612	Edwin Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881493	151.118139	1		install new kerb ramp	LH1079	Secondary	MED	\$	2,500
CD613	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883169	151.118271	1		install new kerb ramp - pair	LH1080	Secondary	MED	\$	5,000
CD614	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88313	151.118118	1		install new kerb ramp	LH1081	Secondary	MED	\$	2,500
CD615	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.883001	151.117958	1		install new kerb ramp - pair	LH1082	Secondary	MED	\$	5,000
CD616	Elizabeth Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.882637	151.117617	1		install new kerb ramp	LH1083	Secondary	MED	\$	2,500
CD617	Edwin Street North	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882501	151.117318	1		install new kerb ramp - pair	LH1084	Secondary	MED	\$	5,000
CD624	Paramatta Road	Croydon	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874098	151.127288	1		install new kerb ramp - pair	LH1085	Secondary	MED	\$	5,000
CD625	Croydon Road	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873145	151.126138	1		install new kerb ramp - pair	LH1086	Secondary	MED	\$	5,000
CD626	Scott Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871672	151.123587	1		install new kerb ramp - pair	LH1087	Secondary	MED	\$	5,000
CD627	Paramatta Road	Croydon	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.871341	151.121954	1		consult with City of Canada Bay	LH1088	Secondary	MED	\$	-
CD628	Paramatta Road	Croydon	State Road	crossing deficiency	missing kerb ramp	-33.873779	151.126963	1		install new kerb ramp	LH1089	Secondary	MED	\$	2,500
CD629	Scott Street	Croydon	Local Road	crossing deficiency	misaligned refuge island	-33.874678	151.123609	1		install new kerb ramp - pair	LH1090	Secondary	MED	\$	5,000
CD630	Thomas Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886013	151.117194	1		install new kerb ramp	LH1091	Secondary	MED	\$	2,500
CD631	Thomas Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88559	151.116971	1		install new kerb ramp	LH1092	Secondary	MED	\$	2,500
CD632	Thomas Street	Croydon	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885465	151.116157	1		install new kerb ramp - pair	LH1093	Secondary	MED	\$	5,000
CD633	Thomas Street	Croydon	Local Road	crossing deficiency	misaligned kerb ramp	-33.885043	151.115332	1		install new kerb ramp	LH1094	Secondary	MED	\$	2,500
CD634	Thomas Street	Croydon	Local Road	crossing deficiency	missing crossing point	-33.884883	151.115221	1		install new kerb ramp - pair	LH1095	Secondary	MED	\$	5,000
CD635	Pittley Lane	Croydon	Local Road	crossing deficiency	missing kerb ramp	-33.884453	151.11467	1		install new kerb ramp	LH1096	Secondary	MED	\$	2,500
CD637	Cornwell Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893539	151.155454	1		install new kerb ramp - pair	LH1097	Secondary	MED	\$	5,000
CD638	Leopold Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893766	151.154885	1		install new kerb ramp - pair	LH1098	Secondary	MED	\$	5,000
CD639	Forbes Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893997	151.144223	1		install new kerb ramp - pair	LH1099	Secondary	MED	\$	5,000
CD64	Tralflaga Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.889066	151.170216	1		install new kerb ramp	LH1100	Secondary	MED	\$	5,000
CD640	Georges River Drive	Croydon Park	State Road	crossing deficiency	misaligned kerb ramp	-33.894079	151.113756	1		install new kerb ramp	LH1101	Secondary	MED	\$	2,500
CD641	Hay Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894205	151.113118	1		install new kerb ramp - pair	LH1102	Secondary	MED	\$	5,000
CD642	Georges River Drive	Croydon Park	State Road	crossing deficiency	improve pedestrian access by providing additional crossing	-33.894013	151.113512	1		consult with TfNSW	LH1103	Secondary	MED	\$	5,000
CD643	Holborn Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.893865	151.113611	1		install new kerb ramp - pair	LH1104	Secondary	MED	\$	5,000
CD645	Greenhills Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment	-33.894254	151.112533	1		install new kerb ramp	LH1105	Secondary	MED	\$	2,500
CD648	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.900752	151.136071	1		install new kerb ramp	LH1106	Secondary	MED	\$	2,500
CD65	Tralflaga Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.906258	151.170059	1		install new Tactile Ground Surface Indicators - pair	LH1107	Secondary	MED	\$	1,300
CD654	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900891	151.132205	1		install new kerb ramp - pair	LH1108	Secondary	MED	\$	5,000
CD656	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.900747	151.13612	1		install new refuge island	LH1109	Secondary	MED	\$	15,000
CD657	Bedford Crescent	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.910735	151.141349	1		install new kerb ramp - pair	LH1110	Secondary	MED	\$	5,000
CD658	Bedford Crescent	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.910181	151.141192	1		install new Tactile Ground Surface Indicators - pair	LH1111	Secondary	MED	\$	1,300
CD659	Blackwood Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906841	151.141068	1		install new kerb ramp - pair	LH1112	Secondary	MED	\$	5,000
CD66	Tralflaga Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.88646	151.168886	1		install new Tactile Ground Surface Indicators	LH1113	Secondary	MED	\$	650
CD660	Blackwood Lane	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907146	151.14145	1		install new Tactile Ground Surface Indicators	LH1114	Secondary	MED	\$	650
CD664	Consett Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905711	151.138043	1		install new kerb ramp - pair	LH1115	Secondary	MED	\$	5,000
CD665	Consett Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.905089	151.138883	1		install new kerb ramp	LH1116	Secondary	MED	\$	2,500
CD666	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900977	151.136327	1		install new kerb ramp - pair	LH1117	Secondary	MED	\$	5,000
CD667	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902636	151.137629	1		install new kerb ramp - pair	LH1118	Secondary	MED	\$	5,000
CD668	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903744	151.14087	1		install new kerb ramp - pair	LH1119	Secondary	MED	\$	5,000
CD669	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903624	151.140794	1		install new kerb ramp - pair	LH1120	Secondary	MED	\$	5,000
CD67	Tralflaga Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.884183	151.171239	1		install new kerb ramp	LH1121	Secondary	MED	\$	2,500
CD671	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.902099	151.137705	1		install new kerb ramp - pair	LH1122	Secondary	MED	\$	5,000
CD672	Davis Street	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.894333	151.140569	1		install new kerb ramp	LH1123	Secondary	MED	\$	2,500
CD673	Denison Road	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.900776	151.141118	1		install new Tactile Ground Surface Indicators - pair	LH1124	Secondary	MED	\$	1,300
CD676	Ewart Lane	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgi	-33.910593	151.139634	1							

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD694	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.907281	151.138225	1		install new Tactile Ground Surface Indicators - pair	UH1137	Secondary	MED	\$ 1,300
CD696	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.904986	151.140219	1		install new Tactile Ground Surface Indicators - pair	UH1138	Secondary	MED	\$ 1,300
CD697	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.904978	151.140428	1		install new Tactile Ground Surface Indicators - pair	UH1139	Secondary	MED	\$ 1,300
CD698	Hill Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.901498	151.14052	1		install new Tactile Ground Surface Indicators	UH1140	Secondary	MED	\$ 650
CD7	Johnston Street	Annandale	State Road	crossing deficiency	narrow kerb ramp	-33.885616	151.168727	1		install new kerb ramp	UH1141	Secondary	MED	\$ 2,500
CD70	Tratlar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886763	151.168840	1		install new kerb ramp	UH1142	Secondary	MED	\$ 2,500
CD700	Keith Lane	Dulwich Hill	Local Road	crossing deficiency	missing kerb ramp	-33.909062	151.140229	1		install new kerb ramp	UH1143	Secondary	MED	\$ 2,500
CD701	Keith Lane	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.909677	151.139896	1		install new Tactile Ground Surface Indicators	UH1144	Secondary	MED	\$ 650
CD702	Kintore Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905979	151.141114	1		install new kerb ramp - pair	UH1145	Secondary	MED	\$ 5,000
CD703	Kintore Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.907165	151.141907	1		install new Tactile Ground Surface Indicators - pair	UH1146	Secondary	MED	\$ 1,300
CD704	Kintore Street	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.907116	151.141873	1		re-construct refuge island	UH1147	Secondary	MED	\$ 15,000
CD706	Marrickville Road	Dulwich Hill	Regional Road	crossing deficiency	misaligned kerb ramp	-33.906633	151.145777	1		install new kerb ramp	UH1148	Secondary	MED	\$ 2,500
CD707	Canbury Grove	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.906062	151.145189	1		install new kerb ramp	UH1149	Secondary	MED	\$ 2,500
CD71	Tratlar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886755	151.170025	1		install new kerb ramp - pair	UH1150	Secondary	MED	\$ 5,000
CD711	Frazer Street	Dulwich Hill	Regional Road	crossing deficiency	misaligned kerb ramp	-33.900795	151.144609	1		install new kerb ramp	UH1151	Secondary	MED	\$ 2,500
CD712	New Canterbury Road	Dulwich Hill	State Road	crossing deficiency	poor kerb ramp alignment	-33.900636	151.144911	1		install new kerb ramp	UH1152	Secondary	MED	\$ 2,500
CD72	Tratlar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879251	151.173331	1		install new kerb ramp - pair	UH1153	Secondary	MED	\$ 5,000
CD722	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.905111	151.138059	1		install new kerb ramp	UH1154	Secondary	MED	\$ 2,500
CD727	Ross Street	Dulwich Hill	Local Road	crossing deficiency	raised kerb ramp lip	-33.904974	151.131752	1		install new kerb ramp	UH1155	Secondary	MED	\$ 2,500
CD728	Ross Street	Dulwich Hill	Local Road	crossing deficiency	raised kerb ramp lip	-33.90497	151.131901	1		install new kerb ramp	UH1156	Secondary	MED	\$ 2,500
CD73	Tratlar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.879097	151.173472	1		install new kerb ramp	UH1157	Secondary	MED	\$ 2,500
CD74	Tratlar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.87909	151.173452	1		install new kerb ramp	UH1158	Secondary	MED	\$ 2,500
CD742	Rosendale Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895668	151.137297	1		install new kerb ramp - pair	UH1159	Secondary	MED	\$ 5,000
CD743	Hampstead Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897116	151.136907	1		install new kerb ramp - pair	UH1160	Secondary	MED	\$ 5,000
CD744	Maddock Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897613	151.135803	1		install new kerb ramp - pair	UH1161	Secondary	MED	\$ 5,000
CD748	Dixon Avenue	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894883	151.13343	1		install new kerb ramp - pair	UH1162	Secondary	MED	\$ 5,000
CD749	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900723	151.132295	1		install new kerb ramp - pair	UH1163	Secondary	MED	\$ 5,000
CD75	Tratlar Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.87911	151.173499	1		install new Tactile Ground Surface Indicators	UH1164	Secondary	MED	\$ 650
CD755	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.900807	151.141186	1		install new Tactile Ground Surface Indicators - pair	UH1165	Secondary	MED	\$ 1,300
CD756	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.900849	151.141115	1		install new Tactile Ground Surface Indicators - pair	UH1166	Secondary	MED	\$ 1,300
CD757	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901077	151.142652	1		install new kerb ramp - pair	UH1167	Secondary	MED	\$ 5,000
CD758	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901066	151.142753	1		install new kerb ramp - pair	UH1168	Secondary	MED	\$ 5,000
CD759	Piggott Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.900765	151.141123	1		install new Tactile Ground Surface Indicators - pair	UH1169	Secondary	MED	\$ 1,300
CD76	Tratlar Street	Annandale	Local Road	crossing deficiency	missing crossing point	-33.878994	151.173511	1		install new kerb ramp - pair	UH1170	Secondary	MED	\$ 5,000
CD760	Tennison Street	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.911033	151.138907	1		install new kerb ramp - pair	UH1171	Secondary	MED	\$ 5,000
CD762	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90943	151.13809	1		install new kerb ramp - pair	UH1172	Secondary	MED	\$ 5,000
CD763	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.907186	151.137834	1		install new Tactile Ground Surface Indicators - pair	UH1173	Secondary	MED	\$ 1,300
CD765	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90571	151.138060	1		install new kerb ramp	UH1174	Secondary	MED	\$ 2,500
CD766	Terrace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.905055	151.138063	1		install new kerb ramp	UH1175	Secondary	MED	\$ 2,500
CD767	Terry Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.894115	151.137879	1		install new kerb ramp - pair	UH1176	Secondary	MED	\$ 5,000
CD768	Barnsbury Grove	Dulwich Hill	Local Road	crossing deficiency	sleep kerb ramp	-33.906159	151.146317	1		install new kerb ramp - pair	UH1177	Secondary	MED	\$ 5,000
CD769	Wardell Road	Dulwich Hill	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.903322	151.146594	1		install new kerb ramp	UH1178	Secondary	MED	\$ 2,500
CD77	Tratlar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.878816	151.174413	1		install new kerb ramp - pair	UH1179	Secondary	MED	\$ 2,500
CD770	Wardell Road	Dulwich Hill	Regional Road	crossing deficiency	misaligned refuge island	-33.903771	151.146893	1		re-construct refuge island	UH1180	Secondary	MED	\$ 15,000
CD772	Beach Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907764	151.14433	1		install new kerb ramp - pair	UH1181	Secondary	MED	\$ 5,000
CD773	Margaret Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.908802	151.143358	1		install new kerb ramp - pair	UH1182	Secondary	MED	\$ 5,000
CD777	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.909036	151.143228	1		no action	UH1183	Secondary	MED	\$ -
CD78	Tratlar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.877222	151.174338	1		install new kerb ramp	UH1184	Secondary	MED	\$ 2,500
CD780	Rosendale Crescent	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.913114	151.138129	1		install new kerb ramp - pair	UH1185	Secondary	MED	\$ 5,000
CD781	Pile Street	Dulwich Hill	Local Road	crossing deficiency	missing kerb ramp	-33.903833	151.148696	1		install new kerb ramp	UH1186	Secondary	MED	\$ 2,500
CD782	Weston Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898197	151.139296	1		install new kerb ramp - pair	UH1187	Secondary	MED	\$ 5,000
CD783	Weston Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898835	151.139355	1		install new kerb ramp - pair	UH1188	Secondary	MED	\$ 5,000
CD784	Weston Street	Dulwich Hill	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.89593	151.141712	1		install new Tactile Ground Surface Indicators	UH1189	Secondary	MED	\$ 650
CD785	Weston Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895535	151.141753	1		install new kerb ramp - pair	UH1190	Secondary	MED	\$ 5,000
CD787	Williams Parade	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.902338	151.137393	1		re-construct refuge island	UH1191	Secondary	MED	\$ 15,000
CD788	Windor Road	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.888326	151.138344	1		install new kerb ramp - pair	UH1192	Secondary	MED	\$ 5,000
CD789	Windor Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898363	151.138976	1		install new kerb ramp - pair	UH1193	Secondary	MED	\$ 5,000
CD79	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.884692	151.167525	1		install new Tactile Ground Surface Indicators	UH1194	Secondary	MED	\$ 650
CD790	Windor Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.898208	151.139189	1		install new kerb ramp	UH1195	Secondary	MED	\$ 2,500
CD791	Windor Road	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.89812	151.139288	1		install new kerb ramp - pair	UH1196	Secondary	MED	\$ 5,000
CD792	Windor Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898243	151.139042	1		install new kerb ramp - pair	UH1197	Secondary	MED	\$ 5,000
CD793	Camden Street	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.903962	151.172898	1		install new kerb ramp	UH1198	Secondary	MED	\$ 2,500
CD794	Sanah Street	Enmore	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.902519	151.172237	1		install new Tactile Ground Surface Indicators	UH1199	Secondary	MED	\$ 650
CD80	Tratlar Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.878683	151.174469	1		install new kerb ramp	UH1200	Secondary	MED	\$ 2,500
CD805	Liberty Street	Enmore	Regional Road	crossing deficiency	misaligned kerb ramp	-33.895253	151.171009	1		install new kerb ramp	UH1201	Secondary	MED	\$ 2,500
CD806	Liberty Street	Enmore	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.896488	151.170629	1		install new kerb ramp - pair	UH1202	Secondary	MED	\$ 5,000
CD807	Cavendish Street	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.898268	151.169705	1		install new kerb ramp	UH1203	Secondary	MED	\$ 2,500
CD808	Liberty Street	Enmore	Regional Road	crossing deficiency	missing refuge island	-33.895593	151.171335	1		install new refuge island	UH1204	Secondary	MED	\$ 15,000
CD809	Llewellyn Street	Enmore	Regional Road	crossing deficiency	at grade crossing missing tgsi	-33.904826	151.173084	1		install new Tactile Ground Surface Indicators	UH1205	Secondary	MED	\$ 650
CD811	Philo Street	Enmore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.898344	151.173291	1		install new kerb ramp	UH1206	Secondary	MED	\$ 2,500
CD813	Liberty Street	Enmore	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.898865	151.169567	1		install new kerb ramp	UH1207	Secondary	MED	\$ 2,500
CD815	Dalhousie Street	Haberfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.882353	151.137157	1		further investigation required - pedestrian crossing	UH1208	Secondary	MED	\$ 10,000
CD817	Ramsay Street	Haberfield	Regional Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.882618	151.140592	1		further investigation required - pedestrian crossing	UH1209	Secondary	MED	\$ 10,000
CD82	Tratlar Street	Annandale	Local Road	crossing deficiency	misaligned refuge island	-33.878599	151.174449	1		re-construct refuge island	UH1210	Secondary	MED	\$ 15,000
CD820	Alt Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.879245	151.131218	1		install new kerb ramp - pair	UH1211	Secondary	MED	\$ 5,000
CD822	Alt Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.878536	151.135886	1		install kerb extension - pair	UH1212	Secondary	MED	\$ 20,000
CD824	Alt Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878466	151.131338	1		install new kerb ramp - pair	UH1213	Secondary	MED	\$ 5,000
CD825	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88035	151.132108	1		install new kerb ramp - pair	UH1214	Secondary	MED	\$ 5,000
CD826	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878733	151.134616	1		install new kerb ramp - pair	UH1215	Secondary	MED	\$ 5,000
CD827	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878763	151.134648	1		install new kerb ramp - pair	UH1216	Secondary	MED	\$ 5,000
CD828	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878869	151.134657	1		install new kerb ramp - pair	UH1217	Secondary	MED	\$ 5,000
CD829	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880429	151.132164	1		install new kerb ramp - pair	UH1218	Secondary	MED	\$ 5,000
CD830	Bland Street	Haberfield	Local Road	crossing deficiency	misaligned refuge island	-33.878777	151.134679	1		re-construct refuge island	UH1219	Secondary	MED	\$ 15,000
CD831	Boomerang Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878822	151.145187	1		install new kerb ramp	UH1220	Secondary	MED	\$ 2,500
CD832	Boomerang Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.879009	151.145099	1		install new Tactile Ground Surface Indicators	UH1221	Secondary	MED	\$ 650
CD833	Boomerang Street	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.878269								

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD85	White Creek	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.883921	151.165206	1		install new kerb ramp - pair	UH1232	Secondary	MED	\$ 5,000
CD850	Dalhousie Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882105	151.137289	1		install new kerb ramp - pair	UH1233	Secondary	MED	\$ 5,000
CD851	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882653	151.135642	1		install new kerb ramp - pair	UH1234	Secondary	MED	\$ 5,000
CD852	Denman Avenue	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.879711	151.135313	1		install new kerb ramp	UH1235	Secondary	MED	\$ 2,500
CD853	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880847	151.135955	1		install new kerb ramp - pair	UH1236	Secondary	MED	\$ 5,000
CD854	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.880965	151.135959	1		install new kerb ramp	UH1237	Secondary	MED	\$ 2,500
CD855	Denman Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.881024	151.136460	1		install new kerb ramp - pair	UH1238	Secondary	MED	\$ 5,000
CD856	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.884907	151.143935	1		install new kerb ramp	UH1239	Secondary	MED	\$ 2,500
CD857	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.885357	151.144051	1		install new Tactile Ground Surface Indicators	UH1240	Secondary	MED	\$ 650
CD858	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	missing kerb ramp	-33.887768	151.143776	1		install new kerb ramp	UH1241	Secondary	MED	\$ 2,500
CD859	Hawthorn Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887561	151.143839	1		install new kerb ramp	UH1242	Secondary	MED	\$ 2,500
CD86	White Creek	Annandale	Local Road	crossing deficiency	narrow kerb ramp	-33.886397	151.164142	1		install new kerb ramp	UH1243	Secondary	MED	\$ 2,500
CD861	Hawthorne Parade	Haberfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.886186	151.14418	1		install new kerb ramp - pair	UH1244	Secondary	MED	\$ 5,000
CD865	Mortley Avenue	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.871977	151.14307	1		install new Tactile Ground Surface Indicators - pair	UH1245	Secondary	MED	\$ 1,300
CD866	Mortley Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870918	151.141838	1		install new kerb ramp - pair	UH1246	Secondary	MED	\$ 5,000
CD867	Mortley Avenue	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.871036	151.141754	1		install new Tactile Ground Surface Indicators	UH1247	Secondary	MED	\$ 650
CD868	Mortley Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870869	151.141935	1		install new kerb ramp - pair	UH1248	Secondary	MED	\$ 5,000
CD869	Mortley Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872594	151.14382	1		install new kerb ramp - pair	UH1249	Secondary	MED	\$ 5,000
CD87	White Creek	Annandale	Local Road	crossing deficiency	missing crossing point	-33.887191	151.162936	1		install new kerb ramp - pair	UH1250	Secondary	MED	\$ 5,000
CD870	Paramatta Road	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884557	151.135639	1		install new kerb ramp - pair	UH1251	Secondary	MED	\$ 5,000
CD871	Paramatta Road	Haberfield	State Road	crossing deficiency	missing crossing point	-33.880379	151.13227	1		install new kerb ramp - pair	UH1252	Secondary	MED	\$ 5,000
CD872	Dobroyd Parade	Haberfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.874427	151.127948	1		install new kerb ramp - pair	UH1253	Secondary	MED	\$ 5,000
CD873	Walesley Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875385	151.128735	1		install new kerb ramp - pair	UH1254	Secondary	MED	\$ 5,000
CD877	Rogers Avenue	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88391	151.134655	1		install new kerb ramp - pair	UH1255	Secondary	MED	\$ 5,000
CD878	Sloane Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887407	151.141907	1		install new kerb ramp - pair	UH1256	Secondary	MED	\$ 5,000
CD879	Paramatta Road	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.887486	151.141723	1		install new kerb ramp - pair	UH1257	Secondary	MED	\$ 5,000
CD88	White Creek	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.887118	151.162943	1		install new Tactile Ground Surface Indicators	UH1258	Secondary	MED	\$ 650
CD882	Connor Street	Haberfield	Local Road	crossing deficiency	missing crossing point	-33.882154	151.140388	1		install new kerb ramp - pair	UH1259	Secondary	MED	\$ 5,000
CD883	Connor Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882424	151.140348	1		install new kerb ramp - pair	UH1260	Secondary	MED	\$ 5,000
CD885	Bland Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877766	151.135654	1		install new kerb ramp	UH1261	Secondary	MED	\$ 2,500
CD886	Bland Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.877711	151.135654	1		install kerb extension - pair	UH1262	Secondary	MED	\$ 20,000
CD887	Alt Street	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.876901	151.135559	1		install new kerb ramp	UH1263	Secondary	MED	\$ 2,500
CD889	Ramsay Street	Haberfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875302	151.13467	1		install new kerb ramp - pair	UH1264	Secondary	MED	\$ 5,000
CD889	White Creek	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.887734	151.162881	1		install new kerb ramp	UH1265	Secondary	MED	\$ 2,500
CD890	Ramsay Street	Haberfield	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.87531	151.134659	1		install new kerb ramp - pair	UH1266	Secondary	MED	\$ 5,000
CD895	Ramsay Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.884764	151.142287	1		install new kerb ramp	UH1267	Secondary	MED	\$ 2,500
CD896	Ramsay Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885157	151.14271	1		install new kerb ramp - pair	UH1268	Secondary	MED	\$ 5,000
CD898	Northcote Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874125	151.133880	1		install new kerb ramp - pair	UH1269	Secondary	MED	\$ 5,000
CD9	Johnston Street	Annandale	State Road	crossing deficiency	poor kerb ramp alignment	-33.883695	151.169881	1		install new kerb ramp	UH1270	Secondary	MED	\$ 2,500
CD90	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.884711	151.167543	1		install new Tactile Ground Surface Indicators	UH1271	Secondary	MED	\$ 650
CD900	Walesley Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873301	151.132689	1		install new kerb ramp - pair	UH1272	Secondary	MED	\$ 5,000
CD901	Ramsay Street	Haberfield	State Road	crossing deficiency	missing crossing point	-33.874732	151.133219	1		further investigation required - pedestrian refuge or crossing (signal)	UH1273	Secondary	MED	\$ 15,000
CD902	Dobroyd Parade	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873328	151.133192	1		install new kerb ramp - pair	UH1274	Secondary	MED	\$ 5,000
CD903	Ramsay Street	Haberfield	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875011	151.134294	1		install new kerb ramp - pair	UH1275	Secondary	MED	\$ 5,000
CD904	Ramsay Street	Haberfield	State Road	crossing deficiency	traffic post narrows kerb ramp	-33.874554	151.134273	1		consult with TfNSW	UH1276	Secondary	MED	\$ 5,000
CD905	Sloane Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.886844	151.142449	1		install new kerb ramp - pair	UH1277	Secondary	MED	\$ 5,000
CD906	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874494	151.139733	1		install new kerb ramp - pair	UH1278	Secondary	MED	\$ 5,000
CD910	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874776	151.139969	1		install new kerb ramp - pair	UH1279	Secondary	MED	\$ 5,000
CD911	Waratan Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.874454	151.140182	1		install new Tactile Ground Surface Indicators	UH1280	Secondary	MED	\$ 650
CD912	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875231	151.141112	1		install new kerb ramp	UH1281	Secondary	MED	\$ 2,500
CD913	Waratan Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.875259	151.141185	1		install kerb extension - pair	UH1282	Secondary	MED	\$ 20,000
CD914	Waratan Street	Haberfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.875265	151.141233	1		install new Tactile Ground Surface Indicators	UH1283	Secondary	MED	\$ 650
CD92	Widson Street	Annandale	Local Road	crossing deficiency	raised kerb ramp lip	-33.878958	151.168177	1		install new kerb ramp	UH1284	Secondary	MED	\$ 2,500
CD922	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90481	151.123518	1		install new kerb ramp - pair	UH1285	Secondary	MED	\$ 5,000
CD923	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905919	151.12388	1		install new kerb ramp - pair	UH1286	Secondary	MED	\$ 5,000
CD924	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905197	151.12432	1		install new kerb ramp - pair	UH1287	Secondary	MED	\$ 5,000
CD925	Hardy Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.903876	151.125114	1		install new kerb ramp - pair	UH1288	Secondary	MED	\$ 5,000
CD927	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.905125	151.127203	1		consult with City of Canterbury-Bankstown	UH1289	Secondary	MED	\$ -
CD928	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906368	151.127448	1		consult with City of Canterbury-Bankstown	UH1290	Secondary	MED	\$ -
CD929	Princess Street	Hurlstone Park	Local Road	crossing deficiency	missing kerb ramp - pair	-33.907545	151.12588	1		consult with City of Canterbury-Bankstown	UH1291	Secondary	MED	\$ -
CD93	Widson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878923	151.168207	1		install new kerb ramp	UH1292	Secondary	MED	\$ 2,500
CD930	Warkin Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906669	151.12662	1		install new kerb ramp - pair	UH1293	Secondary	MED	\$ 5,000
CD931	Queen Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.906248	151.127094	1		install new kerb ramp - pair	UH1294	Secondary	MED	\$ 5,000
CD932	New Canterbury Road	Hurlstone Park	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.90482	151.128402	1		consult with City of Canterbury-Bankstown	UH1295	Secondary	MED	\$ -
CD933	Griffiths Street	Hurlstone Park	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.904866	151.128443	1		install new kerb ramp - pair	UH1296	Secondary	MED	\$ 5,000
CD934	Loft Street	Hurlstone Park	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.886186	151.14418	1		install new kerb ramp - pair	UH1297	Secondary	MED	\$ 5,000
CD936	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886033	151.161891	1		install new kerb ramp	UH1298	Secondary	MED	\$ 2,500
CD937	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.886194	151.161818	1		install new Tactile Ground Surface Indicators - pair	UH1299	Secondary	MED	\$ 1,300
CD938	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884513	151.162455	1		install new kerb ramp - pair	UH1300	Secondary	MED	\$ 5,000
CD939	Styler Street	Leichhardt	Regional Road	crossing deficiency	misaligned kerb ramp - pair	-33.883161	151.162774	1		install new kerb ramp - pair	UH1301	Secondary	MED	\$ 5,000
CD94	Young Street	Annandale	Local Road	crossing deficiency	driveway as kerb ramp	-33.87538	151.170617	1		no action	UH1302	Secondary	MED	\$ -
CD940	Catherine Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.883207	151.162799	1		install new kerb ramp - pair	UH1303	Secondary	MED	\$ 5,000
CD941	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.883169	151.162821	1		install new kerb ramp	UH1304	Secondary	MED	\$ 2,500
CD942	Catherine Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88313	151.162793	1		install new kerb ramp - pair	UH1305	Secondary	MED	\$ 5,000
CD943	Styler Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.88314	151.162853	1		install new kerb ramp - pair	UH1306	Secondary	MED	\$ 5,000
CD944	Catherine Street	Leichhardt	Regional Road	crossing deficiency	poor kerb ramp alignment	-33.883114	151.162828	1		install new kerb ramp	UH1307	Secondary	MED	\$ 2,500
CD945	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.880721	151.163893	1		install new Tactile Ground Surface Indicators	UH1308	Secondary	MED	\$ 650
CD946	Catherine Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.880794	151.163585	1		install new kerb ramp - pair	UH1309	Secondary	MED	\$ 5,000
CD947	Catherine Street	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.880607	151.163817	1		install new kerb ramp - pair	UH1310	Secondary	MED	\$ 5,000
CD948	Catherine Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.879284	151.164092	1		install new kerb ramp	UH1311	Secondary	MED	\$ 2,500
CD95	Young Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876127	151.170253	1		install new kerb ramp - pair	UH1312	Secondary	MED	\$ 5,000
CD952	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.880857	151.163611	1		install new Tactile Ground Surface Indicators - pair	UH1313	Secondary	MED	\$ 1,300
CD953	Catherine Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.880841	151.163527	1		install new Tactile Ground Surface Indicators - pair	UH1314	Secondary	MED	\$ 1,300
CD954	Catherine Street	Leichhardt	Local Road	crossing deficiency	uneven crossing surface	-33.880837	151.163541	1		install new pavement surface	UH1315	Secondary	MED	\$ 300
CD956	Francis Lane	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875454	151.154816	1		install new kerb ramp	UH1316	Secondary	MED	\$ 2,500
CD957	Francis Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.875426	151.15439	1		install new kerb ramp	UH1317	Secondary	MED	\$ 2,500
CD958	Darby Road	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.875378	151.153783	1		install new				

P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD966	William Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp	-33.877231	151.148316	1		install new kerb ramp	LH1327	Secondary	MED	\$ 2,500
CD967	Alford Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp construction	-33.878339	151.148209	1		install new kerb ramp	LH1328	Secondary	MED	\$ 2,500
CD968	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.877303	151.158188	1		install new kerb ramp - pair	LH1329	Secondary	MED	\$ 5,000
CD969	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.878224	151.158317	1		install new Tactile Ground Surface Indicators - pair	LH1330	Secondary	MED	\$ 1,300
CD97	Young Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.876904	151.169904	1		install new kerb ramp	LH1331	Secondary	MED	\$ 2,500
CD970	Derbyshire Road	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.878953	151.159496	1		install new kerb ramp	LH1332	Secondary	MED	\$ 2,500
CD972	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.88479	151.152173	1		install new Tactile Ground Surface Indicators	LH1333	Secondary	MED	\$ 650
CD974	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.883194	151.152099	1		install new Tactile Ground Surface Indicators	LH1334	Secondary	MED	\$ 650
CD975	Elswick Street	Leichhardt	Local Road	crossing deficiency	misaligned refuge island	-33.883134	151.152045	1		re-construct refuge island	LH1335	Secondary	MED	\$ 15,000
CD98	Annandale Street	Annandale	Local Road	crossing deficiency	missing refuge island	-33.88112	151.168448	1		install new refuge island	LH1336	Secondary	MED	\$ 15,000
CD980	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.888259	151.152931	1		install new Tactile Ground Surface Indicators	LH1337	Secondary	MED	\$ 650
CD982	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.888261	151.153025	1		install new Tactile Ground Surface Indicators	LH1338	Secondary	MED	\$ 650
CD983	Elswick Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.888325	151.153072	1		install new kerb ramp	LH1339	Secondary	MED	\$ 2,500
CD984	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888991	151.153021	1		install new kerb ramp	LH1340	Secondary	MED	\$ 2,500
CD985	Elswick Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.888562	151.152956	1		install new kerb ramp	LH1341	Secondary	MED	\$ 2,500
CD990	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.884224	151.151176	1		install new kerb ramp - pair	LH1342	Secondary	MED	\$ 5,000
CD994	Elswick Street	Leichhardt	Local Road	crossing deficiency	missing kerb ramp	-33.877587	151.151639	1		install new kerb ramp	LH1343	Secondary	MED	\$ 2,500
CD995	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877546	151.151747	1		install new kerb ramp	LH1344	Secondary	MED	\$ 2,500
CD996	Flood Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.879698	151.151967	1		install new kerb ramp	LH1345	Secondary	MED	\$ 2,500
CD997	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.878293	151.151965	1		install new Tactile Ground Surface Indicators	LH1346	Secondary	MED	\$ 650
CD998	Flood Street	Leichhardt	Local Road	crossing deficiency	missing crossing point	-33.877591	151.151639	1		install new kerb ramp - pair	LH1347	Secondary	MED	\$ 5,000
CD999	Flood Street	Leichhardt	Local Road	crossing deficiency	narrow kerb ramp - pair	-33.885818	151.149859	1		no action	LH1348	Secondary	MED	\$ -
													SUBTOTAL	\$ 4,743,000

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
CD1003	Flood Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.889368	151.149224	1		install new kerb ramp - pair	LH61	Tertiary	CW	\$ 5,000
CD1004	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888877	151.149316	1		install new kerb ramp	LH61	Tertiary	CW	\$ 2,500
CD1005	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888391	151.149386	1		install new kerb ramp - pair	LH68	Tertiary	CW	\$ 5,000
CD1008	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878431	151.150183	1		install new kerb ramp - pair	LH63	Tertiary	CW	\$ 5,000
CD1009	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878674	151.150138	1		install new kerb ramp - pair	LH64	Tertiary	CW	\$ 5,000
CD1010	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888236	151.150137	1		install new kerb ramp - pair	LH64	Tertiary	CW	\$ 5,000
CD1011	Flood Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tgi	-33.888411	151.150112	1		install new Tactile Ground Surface Indicators	LH68	Tertiary	CW	\$ 650
CD1014	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879087	151.150019	1		install new kerb ramp - pair	LH64	Tertiary	CW	\$ 5,000
CD1015	Flood Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878445	151.150015	1		install new kerb ramp - pair	LH63	Tertiary	CW	\$ 5,000
CD1016	Flood Street	Leichhardt	Local Road	crossing deficiency	kerb blaster obstructs crossing path	-33.878666	151.150034	1		reconstruct kerb blaster	LH63	Tertiary	CW	\$ 1,500
CD1081	Parramatta Road	Leichhardt	State Road	crossing deficiency	poor kerb ramp alignment - pair	-33.889748	151.149169	1		install new kerb ramp - pair	LH61	Tertiary	CW	\$ 5,000
CD1135	Alan Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.880421	151.150006	1		install new kerb ramp	LH4	Tertiary	CW	\$ 2,500
CD1141	Alan Street	Leichhardt	Local Road	crossing deficiency	misaligned kerb ramp	-33.880356	151.150104	1		install new kerb ramp	LH4	Tertiary	CW	\$ 2,500
CD1163	Elfrim Street	Lewisham	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.897729	151.143456	1		further investigation required - pedestrian crossing	QH46	Tertiary	CW	\$ 10,000
CD1214	Vernon Street	Lewisham	Local Road	crossing deficiency	at grade crossing missing tgi	-33.899734	151.148998	1		install new Tactile Ground Surface Indicators	LW40	Tertiary	CW	\$ 650
CD1215	Fraser Street	Lewisham	Regional Road	crossing deficiency	narrow kerb ramp	-33.90092	151.149007	1		install new kerb ramp	LW41	Tertiary	CW	\$ 2,500
CD1242	Bay Run	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872722	151.151246	1		install new kerb ramp	L13	Tertiary	CW	\$ 2,500
CD1253	Fraser Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.869666	151.152606	1		install new kerb ramp - pair	LF43	Tertiary	CW	\$ 5,000
CD1257	Glover Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.867928	151.155669	1		install new Tactile Ground Surface Indicators	LF80	Tertiary	CW	\$ 650
CD1268	Grove Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.871696	151.164195	1		install new Tactile Ground Surface Indicators	LF55	Tertiary	CW	\$ 650
CD1269	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872126	151.164296	1		install new kerb ramp	LF55	Tertiary	CW	\$ 2,500
CD126	Annandale Street	Annandale	Local Road	crossing deficiency	long crossing	-33.887961	151.166059	1		install kerb extension - pair	AN17	Tertiary	CW	\$ 20,000
CD1261	Grove Street	Lilyfield	Local Road	crossing deficiency	long crossing	-33.872038	151.164405	1		install kerb extension - pair	LF55	Tertiary	CW	\$ 20,000
CD1262	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.871043	151.164402	1		install new kerb ramp	LF55	Tertiary	CW	\$ 2,500
CD1263	Grove Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.870524	151.163936	1		install new kerb ramp	LF56	Tertiary	CW	\$ 2,500
CD1264	Grove Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.870426	151.163911	1		install new Tactile Ground Surface Indicators	LF56	Tertiary	CW	\$ 650
CD1265	Grove Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.870469	151.163773	1		install new Tactile Ground Surface Indicators	LF56	Tertiary	CW	\$ 650
CD1285	Lilyfield Road	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.874194	151.160446	1		install new kerb ramp - pair	LF4	Tertiary	CW	\$ 5,000
CD1290	Francis Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.873262	151.154168	1		install new kerb ramp	LF60	Tertiary	CW	\$ 2,500
CD1291	Hubert Street	Lilyfield	Local Road	crossing deficiency	steep kerb ramp	-33.872951	151.153096	1		install new kerb ramp - pair	LF62	Tertiary	CW	\$ 5,000
CD1292	Charles Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.872738	151.152337	1		install new kerb ramp	LF61	Tertiary	CW	\$ 2,500
CD1293	Charles Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872794	151.152322	1		install new kerb ramp	LF61	Tertiary	CW	\$ 2,500
CD1294	Charles Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872675	151.152134	1		install new kerb ramp	LF61	Tertiary	CW	\$ 2,500
CD1295	Lilyfield Road	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.872529	151.151237	1		install new kerb ramp	LF57	Tertiary	CW	\$ 2,500
CD1296	Lilyfield Road	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872423	151.151237	1		install new kerb ramp - pair	LF57	Tertiary	CW	\$ 5,000
CD1301	Mary Street	Lilyfield	Local Road	crossing deficiency	at grade crossing missing tgi	-33.86965	151.154361	1		install new Tactile Ground Surface Indicators	LF84	Tertiary	CW	\$ 650
CD1302	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.869967	151.154422	1		install new kerb ramp - pair	LF84	Tertiary	CW	\$ 5,000
CD1303	Mary Street	Lilyfield	Local Road	crossing deficiency	missing crossing	-33.872703	151.155312	1		install new kerb ramp - pair	LF78	Tertiary	CW	\$ 5,000
CD1304	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.872686	151.155203	1		install new kerb ramp - pair	LF78	Tertiary	CW	\$ 5,000
CD1305	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870802	151.154588	1		install new kerb ramp - pair	LF85	Tertiary	CW	\$ 5,000
CD1306	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870336	151.154343	1		install new kerb ramp - pair	LF84	Tertiary	CW	\$ 5,000
CD1307	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868492	151.153429	1		install new kerb ramp	LF84	Tertiary	CW	\$ 2,500
CD1308	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.867903	151.15391	1		install new kerb ramp	LF81	Tertiary	CW	\$ 2,500
CD1309	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868004	151.153764	1		install new kerb ramp	LF81	Tertiary	CW	\$ 2,500
CD1310	Mary Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.867107	151.154236	1		install new kerb ramp	LF81	Tertiary	CW	\$ 2,500
CD1312	Mary Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.872836	151.155338	1		install new kerb ramp - pair	LF78	Tertiary	CW	\$ 5,000
CD1313	Mary Street	Lilyfield	Local Road	crossing deficiency	missing refuge island	-33.872757	151.155208	1		install new refuge island	LF78	Tertiary	CW	\$ 15,000
CD1319	Piper Street	Lilyfield	Local Road	crossing deficiency	missing crossing point	-33.87741	151.168486	1		install new kerb ramp - pair	LF96	Tertiary	CW	\$ 5,000
CD1320	Piper Street	Lilyfield	Local Road	crossing deficiency	missing kerb ramp	-33.877369	151.168288	1		install new kerb ramp	LF96	Tertiary	CW	\$ 2,500
CD1321	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877104	151.167611	1		install new kerb ramp - pair	LF96	Tertiary	CW	\$ 5,000
CD1322	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877059	151.167444	1		install new kerb ramp - pair	LF96	Tertiary	CW	\$ 5,000
CD1323	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877023	151.167284	1		install new kerb ramp - pair	LF95	Tertiary	CW	\$ 5,000
CD1324	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876819	151.166469	1		install new kerb ramp - pair	LF95	Tertiary	CW	\$ 5,000
CD1327	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876754	151.165935	1		install new kerb ramp - pair	LF95	Tertiary	CW	\$ 5,000
CD1328	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.876949	151.165799	1		install new kerb ramp	LF95	Tertiary	CW	\$ 2,500
CD1329	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.877153	151.167651	1		install new kerb ramp - pair	LF95	Tertiary	CW	\$ 5,000
CD1330	Piper Street	Lilyfield	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.876172	151.163454	1		install new kerb ramp - pair	LF92	Tertiary	CW	\$ 5,000
CD1331	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876168	151.163735	1		install new kerb ramp - pair	LF92	Tertiary	CW	\$ 5,000
CD1332	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876973	151.162912	1		install new kerb ramp - pair	LF91	Tertiary	CW	\$ 5,000
CD1333	Piper Street	Lilyfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.875753	151.161954	1		install new kerb ramp - pair	LF90	Tertiary	CW	\$ 5,000
CD1337	Cary Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.918046	151.151836	1		install new kerb ramp	MF167	Tertiary	CW	\$ 2,500
CD1362	Alberrmarie Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.911269	151.14509	1		install new kerb ramp	MF13	Tertiary	CW	\$ 2,500
CD1363	Alberrmarie Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.911747	151.145202	1		install new Tactile Ground Surface Indicators - pair	MF13	Tertiary	CW	\$ 1,300
CD1364	Alberrmarie Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.912178	151.146172	1		install new Tactile Ground Surface Indicators - pair	MF12	Tertiary	CW	\$ 1,300
CD1365	Alberrmarie Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.912807	151.146989	1		install new kerb ramp - pair	MF12	Tertiary	CW	\$ 5,000
CD1383	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91968	151.155183	1		install new kerb ramp - pair	MF169	Tertiary	CW	\$ 5,000
CD1384	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.918431	151.156206	1		install new kerb ramp - pair	MF28	Tertiary	CW	\$ 5,000
CD1385	Carrington Road	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.919799	151.15515	1		re-construct refuge island	MF25	Tertiary	CW	\$ 15,000
CD1389	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.919817	151.155297	1		install new kerb ramp	MF25	Tertiary	CW	\$ 2,500
CD1390	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.919096	151.155934	1		install new kerb ramp - pair	MF27	Tertiary	CW	\$ 5,000
CD1391	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.916732	151.157722	1		install new kerb ramp - pair	MF26	Tertiary	CW	\$ 5,000
CD1392	Carrington Road	Marrickville	Local Road	crossing deficiency	long crossing	-33.916708	151.157615	1		install kerb extension - pair	MF26	Tertiary	CW	\$ 20,000
CD1393	Carrington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.917116	151.157136	1		install new kerb ramp - pair	MF23	Tertiary	CW	\$ 5,000
CD1426	Fitzroy Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.906998	151.166895	1		install new kerb ramp	MF70	Tertiary	CW	\$ 2,500
CD1427	Fitzroy Street	Marrickville	Local Road	crossing deficiency	raised kerb ramp lip	-33.909423	151.165845	1		install new kerb ramp	MF69	Tertiary	CW	\$ 2,500
CD1428	Fitzroy Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.909644	151.165799	1		install new kerb ramp	MF69	Tertiary	CW	\$ 2,500
CD1429	Fitzroy Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.908538	151.166614	1		install new kerb ramp - pair	MF73	Tertiary	CW	\$ 5,000
CD1430	Fitzroy Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.908579	151.166596	1		install new kerb ramp - pair	MF73	Tertiary	CW	\$ 5,000
CD1431	Fitzroy Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.907471	151.167934	1		install new Tactile Ground Surface Indicators	MF70	Tertiary	CW	\$ 650
CD1443	Sydenham Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.907561	151.159125	1		install new kerb ramp - pair	MF67	Tertiary	CW	\$ 5,000
CD1471	Kenwick Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.918399	151.152972	1		install new kerb ramp	MF167	Tertiary	CW	\$ 2,500
CD1497	Alberrmarie Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.912783	151.147172	1		re-construct refuge island	MF12	Tertiary	CW	\$ 15,000
CD1569	Myrtle Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.915765	151.157753	1		install new kerb ramp - pair	MF147	Tertiary	CW	\$ 5,000
CD1590	Myrtle Street	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.91514	151.155486	1		install new kerb ramp - pair	MF146	Tertiary	CW	\$ 5,000
CD1561	Myrtle Street	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.915151	151.155653	1		install new kerb ramp - pair	MF146	Tertiary	CW	\$ 5,000
CD1564	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.901345	151.167999	1		install new Tactile Ground Surface Indicators	MF157	Tertiary	CW	\$ 650
CD1565	Newington Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901118	151.168117	1		install new kerb ramp	MF157	Tertiary	CW	\$ 2,500
CD1566	Newington Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgi	-33.90111	151.1674							

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
CD1586	Premier Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.918039	151.148194	1		install new kerb ramp	MV160	Tertiary	CW	\$ 2,500
CD1592	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.918134	151.152442	1		install new Tactile Ground Surface Indicators - pair	MV167	Tertiary	CW	\$ 1,300
CD1593	Renwick Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.918566	151.155074	1		re-construct refuge island	MV169	Tertiary	CW	\$ 15,000
CD1594	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.918516	151.15274	1		install new Tactile Ground Surface Indicators - pair	MV167	Tertiary	CW	\$ 1,300
CD1595	Renwick Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.918261	151.162294	1		install new Tactile Ground Surface Indicators - pair	MV167	Tertiary	CW	\$ 1,300
CD1599	Richardson Crescent	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.920313	151.164908	1		install new kerb ramp - pair	MV173	Tertiary	CW	\$ 5,000
CD16	Nelson Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.977341	151.179815	1		install new Tactile Ground Surface Indicators	AN64	Tertiary	CW	\$ 650
CD1600	Richardson Crescent	Marrickville	Local Road	crossing deficiency	missing crossing point	-33.921969	151.165343	1		install new kerb ramp - pair	MV174	Tertiary	CW	\$ 5,000
CD1603	Riverside Crescent	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.919505	151.142558	1		install new Tactile Ground Surface Indicators	MV178	Tertiary	CW	\$ 650
CD1604	Riverside Crescent	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.914498	151.142635	1		install new kerb ramp	MV178	Tertiary	CW	\$ 2,500
CD1605	Riverside Crescent	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.914095	151.139227	1		install new kerb ramp - pair	MV177	Tertiary	CW	\$ 5,000
CD1606	Riverside Crescent	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.914899	151.140227	1		install new Tactile Ground Surface Indicators	MV180	Tertiary	CW	\$ 650
CD1607	Shirlow Street	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.911122	151.167891	1		install new kerb ramp	MV184	Tertiary	CW	\$ 2,500
CD1608	Shirlow Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.911161	151.167402	1		install new kerb ramp	MV183	Tertiary	CW	\$ 2,500
CD1609	Shirlow Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.911676	151.16733	1		install new Tactile Ground Surface Indicators	MV183	Tertiary	CW	\$ 650
CD161	Annandale Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.887037	151.166474	1		install new kerb ramp	AN17	Tertiary	CW	\$ 2,500
CD162	Ilwara Road	Marrickville	Local Road	crossing deficiency	poor kerb ramp alignment	-33.907064	151.159195	1		install new kerb ramp	MV87	Tertiary	CW	\$ 2,500
CD1623	Ilwara Road	Marrickville	Local Road	crossing deficiency	missing kerb ramp	-33.907523	151.159163	1		install new kerb ramp	MV82	Tertiary	CW	\$ 2,500
CD1624	Ilwara Road	Marrickville	Local Road	crossing deficiency	traffic post narrows kerb ramp	-33.907586	151.159091	1		consult with TNSW	MV87	Tertiary	CW	\$ -
CD1646	Fitzroy Street	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.910656	151.163994	1		install new Tactile Ground Surface Indicators	MV72	Tertiary	CW	\$ 650
CD1647	Fitzroy Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.910919	151.164137	1		install new kerb ramp	MV72	Tertiary	CW	\$ 2,500
CD1666	Yule Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.901833	151.1491	1		install new kerb ramp - pair	DH119	Tertiary	CW	\$ 5,000
CD1667	Porter Avenue	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.901994	151.149072	1		install new Tactile Ground Surface Indicators	DH118	Tertiary	CW	\$ 650
CD1668	Porter Avenue	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.902116	151.149023	1		install new kerb ramp	DH118	Tertiary	CW	\$ 2,500
CD1669	Pile Street	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.903699	151.148938	1		install new kerb ramp - pair	DH120	Tertiary	CW	\$ 5,000
CD1670	Pile Street	Marrickville	Local Road	crossing deficiency	misaligned refuge island	-33.903732	151.148928	1		re-construct refuge island	DH120	Tertiary	CW	\$ 15,000
CD1671	Woodcourt Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.905861	151.146936	1		install new kerb ramp - pair	MV235	Tertiary	CW	\$ 5,000
CD1672	Woodcourt Street	Marrickville	Local Road	crossing deficiency	steep kerb ramp	-33.905944	151.146645	1		install new kerb ramp - pair	MV235	Tertiary	CW	\$ 5,000
CD1683	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.917485	151.15316	1		install new Tactile Ground Surface Indicators - pair	MV241	Tertiary	CW	\$ 1,300
CD1684	Warren Road	Marrickville	Local Road	crossing deficiency	misaligned kerb ramp	-33.918912	151.155712	1		install new kerb ramp	MV27	Tertiary	CW	\$ 2,500
CD1685	Warren Road	Marrickville	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.917486	151.152953	1		install new Tactile Ground Surface Indicators - pair	MV241	Tertiary	CW	\$ 1,300
CD17	Nelson Street	Annandale	Local Road	crossing deficiency	missing kerb ramp	-33.877352	151.17583	1		install new kerb ramp	AN64	Tertiary	CW	\$ 2,500
CD172	Annandale Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.886989	151.16649	1		install new Tactile Ground Surface Indicators	AN17	Tertiary	CW	\$ 650
CD1769	Brighton Street	Petersham	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.892257	151.153353	1		install new kerb ramp - pair	PE6	Tertiary	CW	\$ 5,000
CD18	Nelson Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.877358	151.17584	1		install new kerb ramp - pair	AN64	Tertiary	CW	\$ 2,500
CD185	Bland Street	Ashfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.862598	151.127725	1		further investigation required - pedestrian crossing	AF24	Tertiary	CW	\$ 10,000
CD187	Hardy Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.900463	151.120792	1		install splitter/refuge island	AF80	Tertiary	CW	\$ 10,000
CD1878	Denison Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.868787	151.169332	1		install new kerb ramp - pair	RC031	Tertiary	CW	\$ 5,000
CD1879	Denison Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.868997	151.169294	1		install new kerb ramp - pair	RC031	Tertiary	CW	\$ 5,000
CD188	Hardy Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.900439	151.120792	1		install splitter/refuge island	AF80	Tertiary	CW	\$ 10,000
CD1880	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.869547	151.169315	1		install new kerb ramp	RC028	Tertiary	CW	\$ 2,500
CD1881	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.86953	151.169417	1		install new kerb ramp - pair	RC028	Tertiary	CW	\$ 5,000
CD1882	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.869725	151.169707	1		install new kerb ramp	RC028	Tertiary	CW	\$ 2,500
CD1883	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.870191	151.170355	1		install new kerb ramp - pair	RC028	Tertiary	CW	\$ 5,000
CD1884	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.870023	151.170037	1		install new kerb ramp - pair	RC028	Tertiary	CW	\$ 5,000
CD1885	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.869046	151.169192	1		install new kerb ramp - pair	RC031	Tertiary	CW	\$ 5,000
CD1886	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.868436	151.169162	1		install new kerb ramp	RC031	Tertiary	CW	\$ 2,500
CD1890	Denison Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.870121	151.17042	1		install new kerb ramp	RC028	Tertiary	CW	\$ 2,500
CD1891	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.868272	151.170812	1		install new kerb ramp - pair	RC034	Tertiary	CW	\$ 5,000
CD1895	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.866624	151.170047	1		install new kerb ramp - pair	RC034	Tertiary	CW	\$ 5,000
CD1896	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865345	151.170539	1		install new kerb ramp - pair	RC034	Tertiary	CW	\$ 5,000
CD1897	Evans Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.86598	151.171153	1		install new kerb ramp - pair	RC034	Tertiary	CW	\$ 5,000
CD190	Holden Street	Ashfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.898952	151.125096	1		further investigation required - pedestrian crossing, consult with City of Canterbury-Bankstown	AF83	Tertiary	CW	\$ 5,000
CD1911	Gordon Street	Rozelle	Regional Road	crossing deficiency	poor kerb ramp alignment - pair	-33.86862	151.172848	1		install new kerb ramp - pair	RC037	Tertiary	CW	\$ 5,000
CD1925	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.862764	151.164537	1		install new kerb ramp - pair	RC050	Tertiary	CW	\$ 5,000
CD1926	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.862402	151.163594	1		install new kerb ramp	RC050	Tertiary	CW	\$ 2,500
CD1927	Manning Street	Rozelle	Local Road	crossing deficiency	long crossing	-33.862429	151.16376	1		install kerb extension	RC050	Tertiary	CW	\$ 10,000
CD1928	Manning Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.862863	151.1645	1		install new kerb ramp	RC050	Tertiary	CW	\$ 2,500
CD1936	Robert Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.865597	151.17138	1		install new kerb ramp - pair	RC055	Tertiary	CW	\$ 5,000
CD1937	Parsons Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.865052	151.176916	1		install new kerb ramp - pair	RC055	Tertiary	CW	\$ 5,000
CD1941	Robert Street	Rozelle	Local Road	crossing deficiency	missing crossing point	-33.865893	151.1773	1		install new kerb ramp - pair	RC058	Tertiary	CW	\$ 5,000
CD1942	Robert Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.863959	151.180527	1		install new kerb ramp - pair	RC059	Tertiary	CW	\$ 5,000
CD1944	Terry Street	Rozelle	Local Road	crossing deficiency	poor kerb ramp alignment	-33.860559	151.163536	1		install new kerb ramp	RC62	Tertiary	CW	\$ 2,500
CD196	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.879715	151.130159	1		install new kerb ramp - pair	AF5	Tertiary	CW	\$ 5,000
CD197	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880155	151.129251	1		install new kerb ramp - pair	AF4	Tertiary	CW	\$ 5,000
CD198	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.880457	151.128593	1		install new kerb ramp - pair	AF3	Tertiary	CW	\$ 5,000
CD199	Alt Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgsi - pair	-33.881447	151.126593	1		install new Tactile Ground Surface Indicators - pair	AF1	Tertiary	CW	\$ 1,300
CD200	Alt Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881717	151.126338	1		install new Tactile Ground Surface Indicators	AF8	Tertiary	CW	\$ 650
CD2007	Mary Street	St Peters	Local Road	crossing deficiency	poor kerb ramp alignment	-33.912576	151.171197	1		install new kerb ramp	SP38	Tertiary	CW	\$ 2,500
CD2009	Macaulay Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.88948	151.17112	1		install new kerb ramp	SM4	Tertiary	CW	\$ 5,000
CD2010	Crunkshank Street	Ashfield	Local Road	crossing deficiency	misaligned refuge island	-33.881736	151.126319	1		re-construct refuge island	AF8	Tertiary	CW	\$ 15,000
CD2011	Crunkshank Street	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.889288	151.172399	1		install new kerb ramp	SM4	Tertiary	CW	\$ 2,500
CD2011	Conna Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888524	151.165821	1		install new kerb ramp	SM6	Tertiary	CW	\$ 2,500
CD2012	Crunkshank Street	Stammore	Local Road	crossing deficiency	missing crossing point	-33.889424	151.172532	1		install new kerb ramp - pair	SM7	Tertiary	CW	\$ 5,000
CD2033	Northumberland Avenue	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.891582	151.18806	1		install new kerb ramp	SM23	Tertiary	CW	\$ 2,500
CD2034	Northumberland Avenue	Stammore	Local Road	crossing deficiency	misaligned refuge island	-33.890738	151.167876	1		install new refuge island	SM23	Tertiary	CW	\$ 15,000
CD2035	Northumberland Avenue	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888976	151.16777	1		install new kerb ramp	SM23	Tertiary	CW	\$ 2,500
CD2036	Northumberland Avenue	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment	-33.888032	151.16761	1		install new kerb ramp	SM22	Tertiary	CW	\$ 5,000
CD2037	Northumberland Avenue	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.888335	151.167771	1		install new kerb ramp	SM22	Tertiary	CW	\$ 2,500
CD2038	Northumberland Avenue	Stammore	Local Road	crossing deficiency	misaligned kerb ramp	-33.890599	151.168028	1		install new kerb ramp	SM24	Tertiary	CW	\$ 2,500
CD2048	Perivola Road	Stammore	Local Road	crossing deficiency	narrow refuge island	-33.888944	151.164933	1		re-construct refuge island	SM27	Tertiary	CW	\$ 15,000
CD2050	Perivola Road	Stammore	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.888196	151.164875	1		install new kerb ramp - pair	SM27	Tertiary	CW	\$ 5,000
CD2051	Railway Avenue	Stammore	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.894505	151.17012	1		install new Tactile Ground Surface Indicators	SM38	Tertiary	CW	\$ 650
CD2052	Railway Avenue	Stammore	Local Road	crossing deficiency	at grade crossing missing tgsi	-33.894236	151.169231	1		install new Tactile Ground Surface Indicators	SM39	Tertiary	CW	\$ 5,000
CD2053	Railway Avenue	Stammore	Local Road	crossing deficiency	misaligned refuge island	-33.89369	151.168306	1		re-construct refuge island	SM39	Tertiary	CW	\$ 15,000
CD207	Alt Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.881629	151.126308	1		install new kerb ramp	AF8	Tertiary	CW	\$ 2,500
CD2078	Crescent Street	Summer Hill	Local Road	crossing deficiency	misaligned kerb ramp	-33.899923	151.132382	1		install new kerb ramp	AF48	Tertiary	CW	\$ 2,500
CD208														

**P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Priority	Cost
CD2114	Hurlstone Avenue	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898935	151.133691	1		install new kerb ramp - pair	SH60	Tertiary	CW	\$ 5,000
CD2127	Prospect Road	Summer Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897931	151.132282	1		install new kerb ramp - pair	SH72	Tertiary	CW	\$ 5,000
CD213	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898163	151.125554	1		install new kerb ramp - pair	AF12	Tertiary	CW	\$ 5,000
CD214	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.897528	151.125182	1		install new kerb ramp	AF12	Tertiary	CW	\$ 2,500
CD215	Armstrong Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp	-33.897539	151.125131	1		install new kerb ramp	AF83	Tertiary	CW	\$ 2,500
CD216	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898002	151.125539	1		install new kerb ramp - pair	AF14	Tertiary	CW	\$ 5,000
CD217	Armstrong Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.900294	151.127152	1		install new kerb ramp - pair	AF11	Tertiary	CW	\$ 5,000
CD220	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881791	151.129102	1		install new kerb ramp	AF26	Tertiary	CW	\$ 2,500
CD221	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881942	151.129188	1		install new kerb ramp	AF26	Tertiary	CW	\$ 2,500
CD222	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882871	151.127302	1		install new kerb ramp - pair	AF24	Tertiary	CW	\$ 5,000
CD223	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882942	151.127157	1		install new kerb ramp - pair	AF20	Tertiary	CW	\$ 5,000
CD224	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882805	151.127209	1		install new kerb ramp - pair	AF24	Tertiary	CW	\$ 5,000
CD225	Bland Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.882922	151.127125	1		install new kerb ramp - pair	AF20	Tertiary	CW	\$ 5,000
CD232	Church Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.878029	151.124835	1		install new kerb ramp - pair	AF42	Tertiary	CW	\$ 5,000
CD233	Church Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.877287	151.124425	1		install new kerb ramp - pair	AF41	Tertiary	CW	\$ 5,000
CD234	Church Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.878007	151.124905	1		install new Tactile Ground Surface Indicators - pair	AF42	Tertiary	CW	\$ 1,300
CD236	Church Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.877974	151.124895	1		install new kerb ramp - pair	AF42	Tertiary	CW	\$ 5,000
CD237	Church Street	Ashfield	Local Road	crossing deficiency	missing kerb ramp - pair	-33.878069	151.124907	1		install new kerb ramp - pair	AF42	Tertiary	CW	\$ 5,000
CD238	Clasold Street	Ashfield	Local Road	crossing deficiency	at grade crossing missing tgi - pair	-33.895901	151.131818	1		install new Tactile Ground Surface Indicators - pair	AF46	Tertiary	CW	\$ 1,300
CD240	Clasold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895658	151.131184	1		install new kerb ramp	AF46	Tertiary	CW	\$ 2,500
CD248	Clasold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.895901	151.130290	1		install new kerb ramp	AF47	Tertiary	CW	\$ 2,500
CD250	Clasold Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.895686	151.125194	1		install new kerb ramp - pair	AF89	Tertiary	CW	\$ 5,000
CD302	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901568	151.126369	1		install new kerb ramp - pair	AF81	Tertiary	CW	\$ 5,000
CD303	Hardy Street	Ashfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.902865	151.126569	1		install new kerb ramp	AF78	Tertiary	CW	\$ 2,500
CD304	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.90288	151.125449	1		install new kerb ramp	AF79	Tertiary	CW	\$ 2,500
CD306	Hardy Street	Ashfield	Local Road	crossing deficiency	missing crossing point	-33.900532	151.12700	1		install new kerb ramp	AF80	Tertiary	CW	\$ 2,500
CD307	Hardy Street	Ashfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900632	151.127095	1		install new kerb ramp	AF80	Tertiary	CW	\$ 2,500
CD37	Piper Street	Annandale	Local Road	crossing deficiency	misaligned kerb ramp	-33.877576	151.169227	1		install new kerb ramp	AN68	Tertiary	CW	\$ 2,500
CD42	Pritchard Street	Annandale	Local Road	crossing deficiency	missing kerb ramp - pair	-33.873629	151.170966	1		install new kerb ramp - pair	AN123	Tertiary	CW	\$ 5,000
CD424	Beattie Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment	-33.858811	151.175794	1		install new kerb ramp	BA1	Tertiary	CW	\$ 2,500
CD426	Beattie Street	Balmoral	Local Road	crossing deficiency	long crossing	-33.858726	151.175831	1		install kerb extension	BA1	Tertiary	CW	\$ 10,000
CD426	Beattie Street	Balmoral	Local Road	crossing deficiency	missing crossing point	-33.858804	151.175589	1		install new kerb ramp - pair	BA1	Tertiary	CW	\$ 5,000
CD486	Hyam Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860964	151.180916	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD487	Hyam Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860955	151.180732	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD489	Hyam Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860965	151.180968	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD491	Hyam Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.861172	151.180925	1		install new kerb ramp - pair	BA42	Tertiary	CW	\$ 5,000
CD513	Palmer Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860709	151.181279	1		install new kerb ramp - pair	BA54	Tertiary	CW	\$ 5,000
CD514	Palmer Street	Balmoral	Local Road	crossing deficiency	narrow refuge	-33.860887	151.181205	1		install new refuge island	BA54	Tertiary	CW	\$ 15,000
CD521	Palmer Street	Balmoral	Local Road	crossing deficiency	missing crossing point	-33.860638	151.181279	1		install new kerb ramp - pair, new refuge island	BA54	Tertiary	CW	\$ 7,000
CD542	Worley Street	Balmoral	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.860181	151.179425	1		install new kerb ramp - pair	BA75	Tertiary	CW	\$ 5,000
CD543	Worley Street	Balmoral	Local Road	crossing deficiency	missing crossing point	-33.860336	151.179599	1		install new kerb ramp - pair	BA75	Tertiary	CW	\$ 5,000
CD544	Worley Street	Balmoral	Local Road	crossing deficiency	missing crossing point	-33.860527	151.179615	1		install new kerb ramp - pair	BA75	Tertiary	CW	\$ 5,000
CD554	Birdgrove Road	Birdgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852209	151.17985	1		install new kerb ramp	B13	Tertiary	CW	\$ 2,500
CD555	Cove Street	Birdgrove	Local Road	crossing deficiency	missing crossing point	-33.852085	151.179826	1		install new kerb ramp - pair	B15	Tertiary	CW	\$ 5,000
CD556	Cove Street	Birdgrove	Local Road	crossing deficiency	misaligned kerb ramp - pair	-33.851062	151.178238	1		install new kerb ramp - pair	B17	Tertiary	CW	\$ 5,000
CD557	Louisa Road	Birdgrove	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.850081	151.179557	1		install new kerb ramp - pair	B10	Tertiary	CW	\$ 5,000
CD561	Rowntree Street	Birdgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.851472	151.184228	1		install new kerb ramp	B16	Tertiary	CW	\$ 2,500
CD562	Rowntree Street	Birdgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852022	151.182531	1		install new kerb ramp	B17	Tertiary	CW	\$ 2,500
CD563	Rowntree Street	Birdgrove	Local Road	crossing deficiency	missing kerb ramp	-33.852036	151.182533	1		install new kerb ramp	B17	Tertiary	CW	\$ 2,500
CD568	Rowntree Street	Birdgrove	Local Road	crossing deficiency	at grade crossing missing tgi	-33.853435	151.180656	1		install new Tactile Ground Surface Indicators	B15	Tertiary	CW	\$ 650
CD570	Rowntree Street	Birdgrove	Local Road	crossing deficiency	poor kerb ramp alignment	-33.852226	151.182613	1		install new kerb ramp	B17	Tertiary	CW	\$ 2,500
CD573	Kingston Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.893817	151.172937	1		install new kerb ramp	CA22	Tertiary	CW	\$ 2,500
CD579	Kingston Road	Camperdown	Regional Road	crossing deficiency	raised kerb ramp	-33.893119	151.172306	1		install new kerb ramp	CA21	Tertiary	CW	\$ 2,500
CD580	Kingston Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.892539	151.172424	1		install new kerb ramp	CA21	Tertiary	CW	\$ 2,500
CD581	Kingston Road	Camperdown	Regional Road	crossing deficiency	misaligned kerb ramp	-33.892536	151.172340	1		install new kerb ramp	CA21	Tertiary	CW	\$ 2,500
CD58	Trillalgar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.875711	151.175260	1		install new kerb ramp	AN102	Tertiary	CW	\$ 2,500
CD636	Canalshon Street	Croydon Park	Local Road	crossing deficiency	at grade crossing missing tgi	-33.893746	151.114679	1		install new Tactile Ground Surface Indicators	CP4	Tertiary	CW	\$ 650
CD644	Canalshon Street	Croydon Park	Local Road	crossing deficiency	poor kerb ramp alignment	-33.893738	151.114548	1		install new kerb ramp	CP4	Tertiary	CW	\$ 2,500
CD647	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900943	151.134714	1		install new kerb ramp	DH13	Tertiary	CW	\$ 2,500
CD649	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901002	151.13486	1		install new kerb ramp	DH14	Tertiary	CW	\$ 2,500
CD650	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901043	151.134803	1		install new kerb ramp - pair	DH14	Tertiary	CW	\$ 5,000
CD651	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.901051	151.134698	1		install new kerb ramp	DH13	Tertiary	CW	\$ 2,500
CD652	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901143	151.133688	1		install new kerb ramp - pair	DH13	Tertiary	CW	\$ 5,000
CD653	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901169	151.133568	1		install new kerb ramp - pair	DH13	Tertiary	CW	\$ 5,000
CD655	Arlington Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.901092	151.133491	1		install new kerb ramp - pair	DH13	Tertiary	CW	\$ 5,000
CD661	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910846	151.144997	1		install new kerb ramp - pair	DH11	Tertiary	CW	\$ 5,000
CD662	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910811	151.144903	1		install new kerb ramp - pair	DH7	Tertiary	CW	\$ 5,000
CD663	Challis Avenue	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.910664	151.145399	1		install new kerb ramp - pair	DH7	Tertiary	CW	\$ 5,000
CD665	Warfield Road	Dulwich Hill	Regional Road	crossing deficiency	steep kerb ramp	-33.901102	151.144953	1		install new kerb ramp - pair	DH19	Tertiary	CW	\$ 5,000
CD686	Fraser Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment	-33.900944	151.144682	1		install new kerb ramp	DH35	Tertiary	CW	\$ 5,000
CD687	Gould Avenue	Dulwich Hill	Local Road	crossing deficiency	steep kerb ramp	-33.900797	151.146387	1		install new kerb ramp - pair	DH35	Tertiary	CW	\$ 5,000
CD695	Hercules Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909103	151.137948	1		install new kerb ramp - pair	DH111	Tertiary	CW	\$ 5,000
CD745	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.898177	151.1346	1		install new kerb ramp - pair	SH59	Tertiary	CW	\$ 5,000
CD746	Constitution Road	Dulwich Hill	Local Road	crossing deficiency	long crossing	-33.898206	151.134946	1		install kerb extension - pair	SH59	Tertiary	CW	\$ 20,000
CD747	Aberglie Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.89874	151.134137	1		install new kerb ramp - pair	SH60	Tertiary	CW	\$ 5,000
CD761	Terace Road	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.909033	151.137696	1		install new kerb ramp - pair	DH111	Tertiary	CW	\$ 5,000
CD764	Terace Road	Dulwich Hill	Local Road	crossing deficiency	missing crossing point	-33.908404	151.137649	1		install new kerb ramp - pair	DH11	Tertiary	CW	\$ 5,000
CD771	Herbert Street	Dulwich Hill	Local Road	crossing deficiency	misaligned refuge island	-33.902916	151.148757	1		re-construct refuge island	DH20	Tertiary	CW	\$ 15,000
CD786	Weston Street	Dulwich Hill	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.897005	151.141682	1		install new kerb ramp - pair	DH46	Tertiary	CW	\$ 5,000
CD81	Trillalgar Street	Annandale	Local Road	crossing deficiency	poor kerb ramp alignment	-33.87667	151.174933	1		install new kerb ramp	AN102	Tertiary	CW	\$ 2,500
CD810	Newington Road	Enmore	Local Road	crossing deficiency	at grade crossing missing tgi	-33.900668	151.166882	1		install new Tactile Ground Surface Indicators	MV156	Tertiary	CW	\$ 650
CD819	Sloane Street	Haberfield	Local Road	crossing deficiency	opportunity to provide pedestrian crossing	-33.886228	151.143364	1		further investigation required - pedestrian crossing	HA99	Tertiary	CW	\$ 10,000
CD821	All Street	Haberfield	Local Road	crossing deficiency	misaligned kerb ramp	-33.87789	151.134012	1		install new kerb ramp	HA4	Tertiary	CW	\$ 2,500
CD823	Alt Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.87784	151.13389	1		install new kerb ramp - pair	HA4	Tertiary	CW	\$ 5,000
CD83	Trillalgar Street	Annandale	Local Road	crossing deficiency	at grade crossing missing tgi	-33.878609	151.174503	1		install new Tactile Ground Surface Indicators	AN102	Tertiary	CW	\$ 650
CD897	Ramsey Street	Haberfield	Local Road	crossing deficiency	missing kerb ramp	-33.886155	151.143485	1		install new kerb ramp	HA99	Tertiary	CW	\$ 2,500
CD986	Lynd Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886269	151.143445	1		install new kerb ramp	HA109	Tertiary	CW	\$ 5,000
CD997	Waratan Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.873527	151.137471	1		install new kerb ramp - pair	HA109	Tertiary	CW	\$ 5,000
CD998	Waratan Street													

P4909 Inner West PAMP
Detailed Works Program
Crossing Deficiencies
6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
CD920	Waratah Street	Haberfield	Local Road	crossing deficiency	long crossing	-33.876428	151.144437	1		install kerb extension - pair	HA104	Tertiary	LOW	\$ 20,000
CD921	Waratah Street	Haberfield	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.876053	151.143496	1		install new kerb ramp - pair	HA104	Tertiary	LOW	\$ 5,000
CD973	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment - pair	-33.885493	151.152321	1		install new kerb ramp - pair	LH57	Tertiary	LOW	\$ 5,000
CD976	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886139	151.152476	1		install new kerb ramp	LH56	Tertiary	LOW	\$ 2,500
CD977	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.883026	151.152078	1		install new Tactile Ground Surface Indicators	LH45	Tertiary	LOW	\$ 650
CD978	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.882273	151.152094	1		install new Tactile Ground Surface Indicators	LH45	Tertiary	LOW	\$ 650
CD979	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.885112	151.152100	1		install new Tactile Ground Surface Indicators	LH45	Tertiary	LOW	\$ 650
CD981	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.881286	151.152101	1		install new kerb ramp	LH51	Tertiary	LOW	\$ 2,500
CD986	Elswick Street	Leichhardt	Local Road	crossing deficiency	steep kerb ramp	-33.882426	151.151885	1		install new kerb ramp - pair	LH45	Tertiary	LOW	\$ 5,000
CD987	Elswick Street	Leichhardt	Local Road	crossing deficiency	poor kerb ramp alignment	-33.886068	151.152955	1		install new kerb ramp	LH54	Tertiary	LOW	\$ 2,500
CD988	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.886972	151.152581	1		install new Tactile Ground Surface Indicators	LH55	Tertiary	LOW	\$ 650
CD989	Elswick Street	Leichhardt	Local Road	crossing deficiency	at grade crossing missing tpsi	-33.886166	151.152389	1		install new Tactile Ground Surface Indicators	LH111	Tertiary	LOW	\$ 650
													SUBTOTAL	\$ 1,322,850
													TOTAL	\$ 6,616,100

**P4909 Inner West PAMP
Detailed Works Program
Infrastructure Condition
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
IC1	Booth Street	Annandale	Regional Road	infrastructure condition	uneven pavement surface	-33.883688	151.175605	1	1	re-construct footpath pavement	AN27	Primary	MED	\$ 200
IC100	Knox Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.886284	151.12627	1	1	re-construct footpath pavement	AF119	Primary	MED	\$ 200
IC106	Norton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.889719	151.123695	1	1	re-construct footpath pavement	AF120	Primary	MED	\$ 200
IC107	Norton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.891219	151.127881	1	1	re-construct footpath pavement	AF122	Primary	MED	\$ 200
IC108	Norton Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.891512	151.130531	1	1	re-construct footpath pavement	AF125	Primary	MED	\$ 200
IC109	Old Canterbury Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.90406	151.12899	1	1	re-construct footpath pavement	AF130	Primary	MED	\$ 200
IC117	Parramatta Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.877694	151.130217	1	1	re-construct footpath pavement	H467	Primary	MED	\$ 200
IC12	Booth Street	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.883483	151.175456	1	1	re-construct footpath pavement	AN27	Primary	MED	\$ 200
IC133	Jane Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.858625	151.184373	1	1	re-construct footpath pavement	BA44	Primary	MED	\$ 200
IC140	Robert Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.861392	151.177245	1	1	re-construct footpath pavement	BA60	Primary	MED	\$ 200
IC158	Denison Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901631	151.140312	1	1	re-construct footpath pavement	DH22	Primary	MED	\$ 200
IC159	Dulwich Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902876	151.141907	1	1	re-construct footpath pavement	DH26	Primary	MED	\$ 200
IC160	Dulwich Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902449	151.141171	1	1	re-construct footpath pavement	DH25	Primary	MED	\$ 200
IC173	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.91058	151.13868	1	1	re-construct footpath pavement	DH31	Primary	MED	\$ 200
IC192	New Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.90443	151.138616	1	1	re-construct footpath pavement	DH63	Primary	MED	\$ 200
IC194	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.900027	151.132851	1	1	re-construct footpath pavement	SH62	Primary	MED	\$ 200
IC195	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	raised pavement lip	-33.900488	151.13246	1	1	repair pavement panel	SH62	Primary	MED	\$ 200
IC196	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.902725	151.13045	1	1	re-construct footpath pavement	AF128	Primary	MED	\$ 200
IC197	Old Canterbury Road	Dulwich Hill	State Road	infrastructure condition	uneven pavement surface	-33.902864	151.130361	1	1	re-construct footpath pavement	AF128	Primary	MED	\$ 200
IC2	Parramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.887372	151.173527	1	1	re-construct footpath pavement	AN63	Primary	MED	\$ 200
IC227	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905087	151.137955	1	1	re-construct footpath pavement	DH84	Primary	MED	\$ 200
IC231	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.902682	151.143025	1	1	re-construct footpath pavement	DH126	Primary	MED	\$ 200
IC232	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.90423	151.142896	1	1	re-construct footpath pavement	DH126	Primary	MED	\$ 200
IC233	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.908889	151.142396	1	1	re-construct footpath pavement	DH125	Primary	MED	\$ 200
IC234	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.910539	151.141747	1	1	re-construct footpath pavement	DH125	Primary	MED	\$ 200
IC267	New Canterbury Road	State Road	infrastructure condition	damaged refuge island	consult with City of Canterbury-Bankstown	-33.905105	151.13258	1	1	consult with City of Canterbury-Bankstown	DH125	Primary	MED	\$ 200
IC270	Derbyshire Road	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.880827	151.158775	1	1	re-construct footpath pavement	LH44	Primary	MED	\$ 200
IC271	Derbyshire Road	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.880931	151.158734	1	1	re-construct footpath pavement	LH44	Primary	MED	\$ 200
IC276	Foster Street	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.88428	151.147536	1	1	re-construct footpath pavement	LH72	Primary	MED	\$ 200
IC277	Lords Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.885916	151.149450	1	1	re-construct footpath pavement	LH89	Primary	MED	\$ 200
IC278	Marion Street	Leichhardt	Regional Road	infrastructure condition	raised pavement lip	-33.88396	151.155479	1	1	repair pavement panel	LH91	Primary	MED	\$ 200
IC280	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.888554	151.154056	1	1	re-construct footpath pavement	LH138	Primary	MED	\$ 200
IC282	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.88988	151.154646	1	1	re-construct footpath pavement	LH132	Primary	MED	\$ 200
IC283	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.88946	151.146235	1	1	re-construct footpath pavement	LH132	Primary	MED	\$ 200
IC284	Renwick Lane	Leichhardt	Local Road	infrastructure condition	faded traffic control marking	-33.887689	151.157481	1	1	repair pavement marking	LH131	Primary	MED	\$ 200
IC289	New Canterbury Road	Lewisham	State Road	infrastructure condition	damaged sign	-33.880689	151.146528	1	1	install new Traffic Ground Surface Indicators	LW14	Primary	MED	\$ 650
IC29	Nelson Street	Lewisham	Local Road	infrastructure condition	raised pavement lip	-33.882789	151.146814	1	1	repair pavement panel	AN72	Primary	MED	\$ 200
IC290	Old Canterbury Road	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.894548	151.144849	1	1	re-construct footpath pavement	LW19	Primary	MED	\$ 200
IC293	Railway Terrace	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.894131	151.149956	1	1	re-construct footpath pavement	PE48	Primary	MED	\$ 200
IC294	Thomas Street	Lewisham	Local Road	infrastructure condition	uneven pavement surface	-33.893336	151.148369	1	1	re-construct footpath pavement	LW34	Primary	MED	\$ 200
IC295	Orange Grove Plaza	Lewisham	Local Road	infrastructure condition	refer to maintenance	-33.891404	151.169832	1	1	refer to maintenance	LFS	Primary	MED	\$ 200
IC3	Parramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.887526	151.172122	1	1	re-construct footpath pavement	AN62	Primary	MED	\$ 200
IC30	Nelson Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.882916	151.173451	1	1	re-construct footpath pavement	AN72	Primary	MED	\$ 200
IC31	Nelson Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.883288	151.173528	1	1	re-construct footpath pavement	AN72	Primary	MED	\$ 200
IC319	Dudley Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911434	151.142486	1	1	re-construct footpath pavement	MV46	Primary	MED	\$ 200
IC320	Dudley Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911575	151.142003	1	1	re-construct footpath pavement	MV46	Primary	MED	\$ 200
IC321	Edgeware Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.905298	151.173344	1	1	re-construct footpath pavement	NE24	Primary	MED	\$ 200
IC322	Ermore Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.905672	151.167576	1	1	re-construct footpath pavement	MV213	Primary	MED	\$ 200
IC323	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.912504	151.140639	1	1	re-construct footpath pavement	MV66	Primary	MED	\$ 200
IC324	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.912712	151.140716	1	1	re-construct footpath pavement	MV66	Primary	MED	\$ 200
IC329	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913238	151.141458	1	1	re-construct footpath pavement	MV67	Primary	MED	\$ 200
IC33	Queen Street	Ashfield	Local Road	infrastructure condition	repaint dragons teeth	-33.891031	151.127971	1	1	refer to maintenance	AF150	Primary	MED	\$ 200
IC345	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.913604	151.153266	1	1	re-construct footpath pavement	MV92	Primary	MED	\$ 200
IC346	Illawarra Road	Marrickville	Regional Road	infrastructure condition	trip hazard - raised manhole cover	-33.914079	151.152853	1	1	repair pit cover	MV92	Primary	MED	\$ 2,000
IC347	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.913452	151.153249	1	1	re-construct footpath pavement	MV92	Primary	MED	\$ 200
IC360	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.910748	151.149689	1	1	re-construct footpath pavement	MV121	Primary	MED	\$ 200
IC361	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91069	151.150155	1	1	re-construct footpath pavement	MV121	Primary	MED	\$ 200
IC363	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909265	151.151944	1	1	re-construct footpath pavement	MV118	Primary	MED	\$ 200
IC364	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.908988	151.152164	1	1	re-construct footpath pavement	MV118	Primary	MED	\$ 200
IC365	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.908325	151.151667	1	1	re-construct footpath pavement	MV118	Primary	MED	\$ 200
IC366	Livingstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.910312	151.150797	1	1	re-construct footpath pavement	MV120	Primary	MED	\$ 200
IC369	Marrickville Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.913887	151.162515	1	1	re-construct footpath pavement	MV129	Primary	MED	\$ 200
IC370	Marrickville Road	Marrickville	Regional Road	infrastructure condition	sunken pits	-33.913563	151.162295	1	1	install new utility cover	MV129	Primary	MED	\$ 2,000
IC380	Railway Parade	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913726	151.166874	1	1	re-construct footpath pavement	MV166	Primary	MED	\$ 200
IC4	Parramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.88759	151.17136	1	1	re-construct footpath pavement	AN61	Primary	MED	\$ 200
IC404	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.912847	151.166448	1	1	re-construct footpath pavement	MV203	Primary	MED	\$ 200
IC405	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.912882	151.166486	1	1	re-construct footpath pavement	MV203	Primary	MED	\$ 200
IC406	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.913001	151.166661	1	1	re-construct footpath pavement	MV203	Primary	MED	\$ 200
IC407	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.913077	151.166766	1	1	re-construct footpath pavement	MV165	Primary	MED	\$ 200
IC411	Sydenham Road	Marrickville	State Road	infrastructure condition	damaged pit cover	-33.909591	151.162361	1	1	install new pit cover	MV200	Primary	MED	\$ 250
IC423	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.905748	151.171096	1	1	re-construct footpath pavement	MV222	Primary	MED	\$ 200
IC425	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.905756	151.171132	1	1	re-construct footpath pavement	MV222	Primary	MED	\$ 200
IC427	Victoria Road	Marrickville	Regional Road	infrastructure condition	sunken pit	-33.911635	151.160771	1	1	install new utility cover	MV220	Primary	MED	\$ 2,000
IC428	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913531	151.159018	1	1	re-construct footpath pavement	MV226	Primary	MED	\$ 200
IC429	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913269	151.159181	1	1	re-construct footpath pavement	MV226	Primary	MED	\$ 200
IC430	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.912824	151.159727	1	1	re-construct footpath pavement	MV225	Primary	MED	\$ 200
IC431	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913132	151.159562	1	1	re-construct footpath pavement	MV225	Primary	MED	\$ 200
IC452	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.915236	151.148276	1	1	re-construct footpath pavement	MV242	Primary	MED	\$ 200
IC453	Warren Road	Marrickville	Local Road	infrastructure condition	raised pavement lip	-33.915316	151.148415	1	1	repair pavement panel	MV242	Primary	MED	\$ 200
IC454	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.916256	151.150776	1	1	re-construct footpath pavement	MV246	Primary	MED	\$ 200
IC461	Bedford Street	Newtown	Local Road	infrastructure condition	cyclist sign faded and covered with stickers	-33.897476	151.178888	1	1	refer to maintenance	NE15	Primary	MED	\$ 200
IC462	Edgeware Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.904618	151.173213	1	1	re-construct footpath pavement	LH145	Primary	MED	\$ 200
IC463	Simmons Street	Newtown	Local Road	infrastructure condition	faded traffic control marking	-33.898874	151.173582	1	1	repair inemarking	NE37	Primary	MED	\$ 500
IC464	Holt Street	Newtown	Local Road	infrastructure condition	uneven pavement surface	-33.90021	151.177432	1	1	re-construct footpath pavement	NE38	Primary	MED	\$ 200
IC468	New Canterbury Road	Petersham	State Road	infrastructure condition	uneven pavement surface	-33.896717	151.152029	1	1	re-construct footpath pavement	PE34	Primary	MED	\$ 200
IC471	Terminus Street	Petersham	Local Road	infrastructure condition	raised pavement lip	-33.90352	151.15634	1	1	repair pavement panel	LW38	Primary	MED	\$ 200
IC472	Wardell Road	Petersham	Regional Road	infrastructure condition	uneven pavement surface	-33.897133	151.149416	1	1	re-construct footpath pavement	LW38	Primary	MED	\$ 200
IC498	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.91613	151.173422	1	1	re-construct footpath pavement	SP24	Primary	MED	\$ 200
IC499	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.910843	151.180192	1						

**P4909 Inner West PAMP
Detailed Works Program
Infrastructure Condition
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
IC504	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.91487	151.176133	1	1	re-construct footpath pavement	SP20	Primary	MED	\$ 200
IC505	Audley Street	Stannmore	Local Road	infrastructure condition	uneven pavement surface	-33.895143	151.161807	1	1	re-construct footpath pavement	SM14	Primary	MED	\$ 200
IC520	Smith Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.89172	151.137041	1	1	re-construct footpath pavement	SH84	Primary	MED	\$ 200
IC529	Railway Parade	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.874874	151.16525	1	1	re-construct footpath pavement	MM/166	Primary	MED	\$ 200
IC534	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.923804	151.163283	1	1	re-construct footpath pavement	TE5	Primary	MED	\$ 200
IC536	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.926027	151.159052	1	1	re-construct footpath pavement	TE34	Primary	MED	\$ 200
IC58	Alt Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884607	151.123521	1	1	re-construct footpath pavement	AF10	Primary	MED	\$ 200
IC59	Alt Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.885251	151.123249	1	1	re-construct footpath pavement	AF10	Primary	MED	\$ 200
IC60	Alt Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884614	151.123684	1	1	re-construct footpath pavement	AF10	Primary	MED	\$ 200
IC65	Charlotte Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.886364	151.126066	1	1	re-construct footpath pavement	AF39	Primary	MED	\$ 200
IC75	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.887487	151.127378	1	1	re-construct footpath pavement	AF52	Primary	MED	\$ 200
IC76	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	raised pavement lip	-33.887753	151.127987	1	1	repair pavement panel	AF52	Primary	MED	\$ 200
IC77	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.888124	151.128806	1	1	re-construct footpath pavement	AF52	Primary	MED	\$ 200
IC80	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.88953	151.123287	1	1	re-construct footpath pavement	AF53	Primary	MED	\$ 200
IC81	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.885744	151.126869	1	1	re-construct footpath pavement	AF53	Primary	MED	\$ 200
IC82	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.878426	151.126481	1	1	re-construct footpath pavement	AF69	Primary	MED	\$ 200
IC83	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.878666	151.126041	1	1	re-construct footpath pavement	AF69	Primary	MED	\$ 200
IC84	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.879014	151.126246	1	1	re-construct footpath pavement	AF69	Primary	MED	\$ 200
IC85	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.879505	151.126207	1	1	re-construct footpath pavement	AF70	Primary	MED	\$ 200
IC86	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.879739	151.12382	1	1	re-construct footpath pavement	AF70	Primary	MED	\$ 200
IC87	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.880883	151.122364	1	1	re-construct footpath pavement	AF72	Primary	MED	\$ 200
IC88	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.880883	151.122364	1	1	re-construct footpath pavement	AF72	Primary	MED	\$ 200
IC92	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.880541	151.12298	1	1	re-construct footpath pavement	AF71	Primary	MED	\$ 200
IC94	Frederick Street	Ashfield	State Road	infrastructure condition	poor barrier condition	-33.885216	151.119696	1	1	repair barrier	AF76	Primary	MED	\$ 750
IC96	Milton Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.88998	151.117413	1	1	re-construct footpath pavement	AF112	Primary	MED	\$ 200
IC97	Milton Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.889708	151.117296	1	1	re-construct footpath pavement	AF113	Primary	MED	\$ 200
IC98	Milton Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.890292	151.117268	1	1	re-construct footpath pavement	AF114	Primary	MED	\$ 200
SUBTOTAL														\$ 29,950
IC10	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.885862	151.175338	1	1	re-construct footpath pavement	AN61	Secondary	LOW	\$ 200
IC101	Knox Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.888555	151.12304	1	1	re-construct footpath pavement	AF90	Secondary	LOW	\$ 200
IC102	Liverpool Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.889394	151.132364	1	1	re-construct footpath pavement	SH28	Secondary	LOW	\$ 200
IC103	Milton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.894804	151.119156	1	1	re-construct footpath pavement	AF141	Secondary	LOW	\$ 200
IC104	Milton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.89485	151.118552	1	1	re-construct footpath pavement	AF141	Secondary	LOW	\$ 200
IC105	Milton Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.894973	151.119457	1	1	re-construct footpath pavement	AF142	Secondary	LOW	\$ 200
IC11	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.886002	151.175123	1	1	re-construct footpath pavement	AN60	Secondary	LOW	\$ 200
IC110	Oprington Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884715	151.133884	1	1	re-construct footpath pavement	AF137	Secondary	LOW	\$ 200
IC111	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884998	151.120947	1	1	re-construct footpath pavement	AF142	Secondary	LOW	\$ 200
IC112	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.895144	151.12293	1	1	re-construct footpath pavement	AF139	Secondary	LOW	\$ 200
IC113	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894911	151.120822	1	1	re-construct footpath pavement	AF143	Secondary	LOW	\$ 200
IC114	Palace Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894892	151.120159	1	1	re-construct footpath pavement	AF142	Secondary	LOW	\$ 200
IC115	Paramatta Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.88018	151.131728	1	1	re-construct footpath pavement	HA69	Secondary	LOW	\$ 200
IC116	Paramatta Road	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.878404	151.130515	1	1	re-construct footpath pavement	HA68	Secondary	LOW	\$ 200
IC118	Premier Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894967	151.119758	1	1	re-construct footpath pavement	AF142	Secondary	LOW	\$ 200
IC119	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.891578	151.127939	1	1	re-construct footpath pavement	AF154	Secondary	LOW	\$ 200
IC120	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.892281	151.127765	1	1	re-construct footpath pavement	AF149	Secondary	LOW	\$ 200
IC121	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.892643	151.127761	1	1	re-construct footpath pavement	AF149	Secondary	LOW	\$ 200
IC122	Queen Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894407	151.127639	1	1	re-construct footpath pavement	AF152	Secondary	LOW	\$ 200
IC123	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.895027	151.129933	1	1	re-construct footpath pavement	AF159	Secondary	LOW	\$ 200
IC124	Buchanan Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.863147	151.180097	1	1	re-construct footpath pavement	BA19	Tertiary	LOW	\$ 200
IC125	Buchanan Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.862534	151.180347	1	1	re-construct footpath pavement	BA18	Tertiary	LOW	\$ 200
IC126	Buchanan Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.862707	151.180294	1	1	re-construct footpath pavement	BA18	Tertiary	LOW	\$ 200
IC127	Buchanan Street	Balmain	Local Road	infrastructure condition	raised pavement lip	-33.862886	151.180159	1	1	repair pavement panel	BA18	Tertiary	LOW	\$ 200
IC128	Buchanan Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.863539	151.180493	1	1	re-construct footpath pavement	BA17	Tertiary	LOW	\$ 200
IC129	Hyam Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.860922	151.180949	1	1	re-construct footpath pavement	BA42	Tertiary	LOW	\$ 200
IC13	Pymont Bridge Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.886071	151.17496	1	1	re-construct footpath pavement	AN60	Secondary	LOW	\$ 200
IC130	Hyam Street	Balmain	Local Road	infrastructure condition	raised pavement lip	-33.861575	151.180139	1	1	repair pavement panel	BA43	Secondary	LOW	\$ 200
IC131	Hyam Street	Balmain	Local Road	infrastructure condition	raised pavement lip	-33.860854	151.181107	1	1	repair pavement panel	BA42	Tertiary	LOW	\$ 200
IC132	Jane Street	Balmain	Local Road	infrastructure condition	raised pavement lip	-33.859278	151.184477	1	1	repair pavement panel	BA45	Secondary	LOW	\$ 200
IC134	Montague Street	Balmain	Regional Road	infrastructure condition	uneven pavement surface	-33.858554	151.177511	1	1	re-construct footpath pavement	BA48	Secondary	LOW	\$ 200
IC135	Palmer Street	Balmain	Local Road	infrastructure condition	raised pavement lip	-33.860594	151.181076	1	1	repair pavement panel	BA5	Secondary	LOW	\$ 200
IC136	Palmer Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.858913	151.180466	1	1	re-construct footpath pavement	BA57	Secondary	LOW	\$ 200
IC137	Palmer Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.859602	151.180569	1	1	re-construct footpath pavement	BA56	Secondary	LOW	\$ 200
IC138	Palmer Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.859336	151.180626	1	1	re-construct footpath pavement	BA58	Secondary	LOW	\$ 200
IC139	Palmer Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.857883	151.180763	1	1	re-construct footpath pavement	BA58	Secondary	LOW	\$ 200
IC14	Trafalgar Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.883548	151.171334	1	1	re-construct footpath pavement	AN107	Secondary	LOW	\$ 200
IC141	Thames Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.856619	151.183771	1	1	re-construct footpath pavement	BA70	Secondary	LOW	\$ 200
IC142	Wortley Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.859926	151.178944	1	1	re-construct footpath pavement	BA14	Secondary	LOW	\$ 200
IC143	Wortley Street	Balmain	Local Road	infrastructure condition	uneven pavement surface	-33.861077	151.178034	1	1	re-construct footpath pavement	BA59	Secondary	LOW	\$ 200
IC144	Louisa Road	Birchgrove	Local Road	infrastructure condition	uneven pavement surface	-33.846819	151.185658	1	1	re-construct footpath pavement	B17	Secondary	LOW	\$ 200
IC145	Rowley Street	Camperdown	Local Road	infrastructure condition	raised pavement lip	-33.853262	151.172126	1	1	repair pavement panel	CA22	Tertiary	LOW	\$ 200
IC146	Croydon Road	Croydon	Local Road	infrastructure condition	uneven pavement surface	-33.881002	151.122002	1	1	re-construct footpath pavement	CR3	Secondary	LOW	\$ 200
IC147	Paramatta Road	Croydon	State Road	infrastructure condition	uneven pavement surface	-33.872536	151.125155	1	1	re-construct footpath pavement	CR30	Secondary	LOW	\$ 200
IC148	Paramatta Road	Croydon	State Road	infrastructure condition	uneven pavement surface	-33.871461	151.122472	1	1	re-construct footpath pavement	CR27	Secondary	LOW	\$ 200
IC149	Blackwood Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.906915	151.140695	1	1	re-construct footpath pavement	DH1	Secondary	LOW	\$ 200
IC15	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement lip	-33.884354	151.171124	1	1	repair pavement panel	AN109	Secondary	LOW	\$ 200
IC150	Blackwood Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.906881	151.140914	1	1	re-construct footpath pavement	DH4	Secondary	LOW	\$ 200
IC151	Challis Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.910233	151.144798	1	1	re-construct footpath pavement	DH8	Secondary	LOW	\$ 200
IC152	Challis Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.910446	151.145296	1	1	re-construct footpath pavement	DH8	Secondary	LOW	\$ 200
IC153	Challis Avenue	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.910085	151.144943	1	1	re-construct footpath pavement	DH8	Secondary	LOW	\$ 200
IC154	Consett Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905795	151.138105	1	1	re-				

P4909 Inner West PAMP Detailed Works Program Infrastructure Condition 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
IC17	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.88162	151.172315	1		repair pavement panel	AN105	Secondary	DW	\$ 200
IC170	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909903	151.13652	1		re-construct footpath pavement	DH28	Secondary	DW	\$ 200
IC171	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.911405	151.139478	1		re-construct footpath pavement	DH30	Secondary	DW	\$ 200
IC172	Ewart Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.911422	151.139631	1		re-construct footpath pavement	DH30	Secondary	DW	\$ 200
IC174	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.901011	151.147558	1		re-construct footpath pavement	DH36	Tertiary	DW	\$ 200
IC175	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.900928	151.146784	1		re-construct footpath pavement	DH35	Tertiary	DW	\$ 200
IC176	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.900915	151.146185	1		re-construct footpath pavement	DH35	Tertiary	DW	\$ 200
IC177	Frazer Street	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.900878	151.145804	1		re-construct footpath pavement	DH34	Secondary	DW	\$ 200
IC178	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898195	151.137649	1		re-construct footpath pavement	DH63	Secondary	DW	\$ 200
IC179	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898285	151.137756	1		re-construct footpath pavement	DH63	Secondary	DW	\$ 200
IC18	Trafalgar Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.881538	151.172252	1		re-construct footpath pavement	AN105	Secondary	DW	\$ 200
IC180	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.897286	151.136735	1		re-construct footpath pavement	DH62	Secondary	DW	\$ 200
IC181	Hampstead Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.897889	151.137298	1		re-construct footpath pavement	DH62	Secondary	DW	\$ 200
IC182	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90512	151.136887	1		re-construct footpath pavement	DH64	Secondary	DW	\$ 200
IC183	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.906660	151.136918	1		re-construct footpath pavement	DH65	Secondary	DW	\$ 200
IC184	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.907027	151.138888	1		repair pavement panel	DH65	Secondary	DW	\$ 200
IC185	Hercules Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90684	151.138815	1		re-construct footpath pavement	DH63	Secondary	DW	\$ 200
IC186	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.900881	151.136296	1		re-construct footpath pavement	DH68	Secondary	DW	\$ 200
IC187	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.900816	151.138497	1		re-construct footpath pavement	DH68	Secondary	DW	\$ 200
IC188	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.900527	151.139044	1		re-construct footpath pavement	DH68	Secondary	DW	\$ 200
IC189	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.900801	151.139379	1		re-construct footpath pavement	DH68	Secondary	DW	\$ 200
IC19	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.880786	151.172629	1		repair pavement panel	AN106	Secondary	DW	\$ 200
IC190	Hill Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.900996	151.138755	1		re-construct footpath pavement	DH68	Secondary	DW	\$ 200
IC191	Marrickville Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.905952	151.145327	1		install new utility cover	DH77	Secondary	DW	\$ 2,000
IC193	Rosa Street	Dulwich Hill	Local Road	infrastructure condition	poorly defined kerb ramp	-33.904981	151.131779	1		install new kerb ramp	DH90	Secondary	DW	\$ 2,500
IC198	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.903096	151.141538	1		re-construct footpath pavement	DH104	Secondary	DW	\$ 200
IC199	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901054	151.141534	1		re-construct footpath pavement	DH104	Secondary	DW	\$ 200
IC20	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.881049	151.17258	1		repair pavement panel	AN105	Secondary	DW	\$ 200
IC200	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901337	151.142666	1		re-construct footpath pavement	DH104	Secondary	DW	\$ 200
IC201	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901863	151.143021	1		re-construct footpath pavement	DH101	Secondary	DW	\$ 200
IC202	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902134	151.143397	1		re-construct footpath pavement	DH105	Secondary	DW	\$ 200
IC203	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902414	151.143861	1		re-construct footpath pavement	DH105	Secondary	DW	\$ 200
IC204	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.902146	151.143526	1		re-construct footpath pavement	DH105	Secondary	DW	\$ 200
IC205	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901846	151.143034	1		re-construct footpath pavement	DH101	Secondary	DW	\$ 200
IC206	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901736	151.142851	1		re-construct footpath pavement	DH101	Secondary	DW	\$ 200
IC207	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901571	151.142499	1		re-construct footpath pavement	DH101	Secondary	DW	\$ 200
IC208	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901071	151.141722	1		re-construct footpath pavement	DH104	Secondary	DW	\$ 200
IC209	Piggott Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.900644	151.140782	1		re-construct footpath pavement	DH103	Secondary	DW	\$ 200
IC21	Trafalgar Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.880638	151.172612	1		re-construct footpath pavement	AN106	Secondary	DW	\$ 200
IC210	Riverside Crescent	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.911889	151.138515	1		re-construct footpath pavement	MV236	Secondary	DW	\$ 200
IC211	Ternyoun Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.901088	151.136177	1		re-construct footpath pavement	DH38	Secondary	DW	\$ 200
IC212	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.908807	151.137684	1		re-construct footpath pavement	DH111	Tertiary	DW	\$ 200
IC213	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.90941	151.138031	1		re-construct footpath pavement	DH82	Secondary	DW	\$ 200
IC214	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.909504	151.137962	1		re-construct footpath pavement	DH39	Secondary	DW	\$ 200
IC215	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.907076	151.137624	1		repair pavement panel	DH114	Secondary	DW	\$ 200
IC216	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.908036	151.13765	1		repair pavement panel	DH113	Tertiary	DW	\$ 200
IC217	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.907557	151.137612	1		repair pavement panel	DH113	Tertiary	DW	\$ 200
IC218	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.908572	151.137663	1		repair pavement panel	DH111	Tertiary	DW	\$ 200
IC219	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.906426	151.137984	1		repair pavement panel	DH114	Secondary	DW	\$ 200
IC22	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.880371	151.172864	1		repair pavement panel	AN106	Secondary	DW	\$ 200
IC220	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.906169	151.137962	1		repair pavement panel	DH114	Secondary	DW	\$ 200
IC221	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.906038	151.138018	1		repair pavement panel	DH12	Secondary	DW	\$ 200
IC222	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905382	151.137948	1		re-construct footpath pavement	DH112	Secondary	DW	\$ 200
IC223	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905767	151.138039	1		re-construct footpath pavement	DH112	Secondary	DW	\$ 200
IC224	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	raised pavement tip	-33.905621	151.138098	1		repair pavement panel	DH9	Secondary	DW	\$ 200
IC225	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905625	151.13808	1		re-construct footpath pavement	DH12	Secondary	DW	\$ 200
IC226	Terrace Road	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.905163	151.137979	1		re-construct footpath pavement	DH112	Secondary	DW	\$ 200
IC228	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.906477	151.145903	1		re-construct footpath pavement	DH121	Secondary	DW	\$ 200
IC229	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.905026	151.147532	1		re-construct footpath pavement	DH123	Tertiary	DW	\$ 200
IC23	Hutchinson Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.875297	151.170524	1		repair pavement panel	AN121	Secondary	DW	\$ 200
IC230	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.904229	151.148266	1		re-construct footpath pavement	MV234	Secondary	DW	\$ 200
IC235	Marrickville Golf Club	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.913364	151.137584	1		re-construct footpath pavement	DH106	Tertiary	DW	\$ 200
IC236	Marrickville Golf Club	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.913266	151.137494	1		re-construct footpath pavement	DH106	Tertiary	DW	\$ 200
IC237	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.912657	151.138122	1		re-construct footpath pavement	MV236	Secondary	DW	\$ 200
IC238	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.912546	151.1382	1		re-construct footpath pavement	MV236	Secondary	DW	\$ 200
IC239	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.912439	151.1394	1		re-construct footpath pavement	MV237	Secondary	DW	\$ 200
IC24	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.87758	151.174015	1		repair pavement panel	AN103	Secondary	DW	\$ 200
IC240	Wardell Road	Dulwich Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.91214	151.139853	1		re-construct footpath pavement	MV237	Secondary	DW	\$ 200
IC241	Weston Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898569	151.139698	1		re-construct footpath pavement	DH117	Secondary	DW	\$ 200
IC242	Weston Street	Dulwich Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898568	151.139613	1		re-construct footpath pavement	DH117	Secondary	DW	\$ 200
IC243	Alt Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.878247	151.133947	1		re-construct footpath pavement	HA2	Tertiary	DW	\$ 200
IC244	Alt Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.878685	151.132113	1		re-construct footpath pavement	HA2	Secondary	DW	\$ 200
IC245	Bay Run	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.871593	151.149349	1		re-construct footpath pavement	HA10	Secondary	DW	\$ 200
IC246	Bay Run	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.87192	151.149701	1		re-construct footpath pavement	HA10	Secondary	DW	\$ 200
IC247	Blind Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.873464	151.133396	1		re-construct footpath pavement	HA19	Secondary	DW	\$ 200
IC248	Boomerang Street	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.870762	151.145227	1		repair pavement panel	HA22	Secondary	DW	\$ 200
IC249	Boomerang Street	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.871493	151.144638	1		repair pavement panel	HA23	Secondary	DW	\$ 200
IC25	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.877488	151.17422	1		repair pavement panel	AN103	Secondary	DW	\$ 200
IC250	Boomerang Street	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.871417	151.142638	1		repair pavement panel	HA27	Secondary	DW	\$ 200
IC251	Dalhousie Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.882979	151.136883	1		re-construct footpath pavement	HA39	Secondary	DW	\$ 200
IC252	Denman Avenue	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.879482	151.136221	1		repair pavement panel	HA40	Secondary	DW	\$ 200
IC253	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.880286	151.135457	1		re-construct footpath pavement	HA43	Secondary	DW	\$ 200
IC254	Denman Avenue	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.880273	151.135543	1		repair pavement panel	HA43	Secondary	DW	\$ 200
IC255	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.880352	151.13563	1		re-construct footpath pavement	HA43	Secondary	DW	\$ 200
IC256	Denman Avenue	Haberfield	Local Road	infrastructure condition	raised pavement tip	-33.881659	151.136836	1		repair pavement panel	HA41	Secondary	DW	\$ 200
IC257	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.881688	151.136846	1		re-construct footpath pavement	HA41	Secondary	DW	\$ 200
IC258	Denman Avenue	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.881729	151.137117	1		re-construct footpath pavement	HA41	Secondary	DW	\$ 200
IC259	Paramatta Road	Haberfield	State Road	infrastructure condition	uneven pavement surface	-33.887803	151.142519	1		re-construct footpath pavement	HA78	Secondary	DW	\$ 200
IC26	Trafalgar Street	Annandale	Local Road	infrastructure condition	raised pavement tip	-33.875971	151.174774	1		repair pavement panel	AN102	Tertiary	DW	\$ 200
IC260	Paramatta Road	Haberfield	State Road	infrastructure condition	uneven pavement surface	-33.874501	151.128004	1		re-construct footpath pavement	HA78	Secondary	DW	\$ 200
IC261	Ramsay Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.884942								

P4909 Inner West PAMP Detailed Works Program Infrastructure Condition 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
C264	Warrah Street	Haberfield	Local Road	infrastructure condition	uneven pavement surface	-33.877289	151.1461	1	1	re-construct footpath pavement	HA102	Tertiary	LOW	\$ 200
C265	Hardy Street	Hurstville Park	Local Road	infrastructure condition	raised pavement tp	-33.906386	151.123618	1	1	repair pavement panel	HP2	Secondary	LOW	\$ 200
C266	Hardy Street	Hurstville Park	Local Road	infrastructure condition	raised pavement tp	-33.9041	151.126963	1	1	repair pavement panel	HP1	Secondary	LOW	\$ 200
C268	Derley Road	Leichhardt	State Road	infrastructure condition	raised pavement tp	-33.876339	151.148758	1	1	repair pavement panel	LH38	Secondary	LOW	\$ 200
C269	Allen Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.880309	151.147758	1	1	re-construct footpath pavement	LH2	Secondary	LOW	\$ 200
C27	Nelson Street	Annandale	Local Road	infrastructure condition	uneven pavement surface	-33.879676	151.174724	1	1	re-construct footpath pavement	AN69	Secondary	LOW	\$ 200
C272	Flood Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.877888	151.150199	1	1	re-construct footpath pavement	LH63	Tertiary	LOW	\$ 200
C273	Flood Street	Leichhardt	Local Road	infrastructure condition	raised pavement tp	-33.878309	151.150183	1	1	repair pavement panel	LH63	Tertiary	LOW	\$ 200
C274	Flood Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.879207	151.150165	1	1	re-construct footpath pavement	LH64	Tertiary	LOW	\$ 200
C275	Flood Street	Leichhardt	Local Road	infrastructure condition	raised pavement tp	-33.884894	151.150049	1	1	repair pavement panel	LH62	Secondary	LOW	\$ 200
C279	Manion Street	Leichhardt	Regional Road	infrastructure condition	uneven pavement surface	-33.884197	151.151554	1	1	re-construct footpath pavement	LH97	Secondary	LOW	\$ 200
C28	Nelson Street	Annandale	Local Road	infrastructure condition	raised pavement tp	-33.877125	151.176064	1	1	repair pavement panel	AN66	Secondary	LOW	\$ 200
C281	Parramatta Road	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.889997	151.148312	1	1	re-construct footpath pavement	LH134	Secondary	LOW	\$ 200
C285	Tabbutt Street	Leichhardt	State Road	infrastructure condition	uneven pavement surface	-33.886668	151.146661	1	1	re-construct footpath pavement	LH155	Secondary	LOW	\$ 200
C286	William Street	Leichhardt	Local Road	infrastructure condition	uneven pavement surface	-33.877462	151.152963	1	1	re-construct footpath pavement	LH174	Secondary	LOW	\$ 200
C287	William Street	Leichhardt	Local Road	infrastructure condition	raised pavement tp	-33.877467	151.153994	1	1	repair pavement panel	LH168	Secondary	LOW	\$ 200
C288	William Street	Leichhardt	Local Road	infrastructure condition	raised pavement tp	-33.877533	151.154347	1	1	repair pavement panel	LH168	Secondary	LOW	\$ 200
C291	Old Canterbury Road	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.895165	151.143491	1	1	re-construct footpath pavement	LW20	Secondary	LOW	\$ 200
C292	Parramatta Road	Lewisham	State Road	infrastructure condition	uneven pavement surface	-33.889653	151.148919	1	1	re-construct footpath pavement	LH134	Secondary	LOW	\$ 200
C296	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.872109	151.151512	1	1	re-construct footpath pavement	LF12	Secondary	LOW	\$ 200
C297	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.867821	151.152079	1	1	re-construct footpath pavement	LF25	Secondary	LOW	\$ 200
C298	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.867119	151.152818	1	1	re-construct footpath pavement	LF24	Secondary	LOW	\$ 200
C299	Bay Run	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.866018	151.155475	1	1	re-construct footpath pavement	LF20	Secondary	LOW	\$ 200
C300	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.871678	151.169116	1	1	re-construct footpath pavement	LF75	Secondary	LOW	\$ 200
C301	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.872954	151.165581	1	1	re-construct footpath pavement	LF71	Secondary	LOW	\$ 200
C302	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.8733	151.164623	1	1	re-construct footpath pavement	LF71	Secondary	LOW	\$ 200
C303	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.873439	151.164074	1	1	re-construct footpath pavement	LF68	Secondary	LOW	\$ 200
C304	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.873577	151.163525	1	1	re-construct footpath pavement	LF68	Secondary	LOW	\$ 200
C305	Lilyfield Road	Lilyfield	Regional Road	infrastructure condition	uneven pavement surface	-33.874294	151.160758	1	1	re-construct footpath pavement	LF69	Secondary	LOW	\$ 200
C306	Lilyfield Road	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.874356	151.1598	1	1	re-construct footpath pavement	LF64	Tertiary	LOW	\$ 200
C307	Lilyfield Road	Lilyfield	Local Road	infrastructure condition	raised pavement tp	-33.873172	151.154358	1	1	repair pavement panel	LF63	Secondary	LOW	\$ 200
C308	Lilyfield Road	Lilyfield	Local Road	infrastructure condition	raised pavement tp	-33.87396	151.157137	1	1	repair pavement panel	LF66	Secondary	LOW	\$ 200
C309	Mary Street	Lilyfield	Local Road	infrastructure condition	uneven pavement surface	-33.867911	151.154067	1	1	re-construct footpath pavement	LF81	Tertiary	LOW	\$ 200
C310	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914136	151.143638	1	1	re-construct footpath pavement	MV16	Secondary	LOW	\$ 200
C311	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91432	151.143534	1	1	re-construct footpath pavement	MV16	Secondary	LOW	\$ 200
C312	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914347	151.143775	1	1	re-construct footpath pavement	MV16	Secondary	LOW	\$ 200
C313	Beauchamp Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914347	151.144068	1	1	re-construct footpath pavement	MV16	Secondary	LOW	\$ 200
C314	Byrnes Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913779	151.155462	1	1	re-construct footpath pavement	MV188	Secondary	LOW	\$ 200
C315	Calvert Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911788	151.155566	1	1	re-construct footpath pavement	MV20	Secondary	LOW	\$ 200
C316	Carrington Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918544	151.156192	1	1	re-construct footpath pavement	MV27	Tertiary	LOW	\$ 200
C317	Carrington Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918146	151.15658	1	1	re-construct footpath pavement	MV28	Tertiary	LOW	\$ 200
C318	Carrington Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.917574	151.157004	1	1	re-construct footpath pavement	MV23	Tertiary	LOW	\$ 200
C32	Parramatta Road	Annandale	State Road	infrastructure condition	uneven pavement surface	-33.887819	151.169057	1	1	re-construct footpath pavement	AN79	Secondary	LOW	\$ 200
C325	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914366	151.14272	1	1	re-construct footpath pavement	MV68	Secondary	LOW	\$ 200
C326	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914225	151.142596	1	1	re-construct footpath pavement	MV68	Secondary	LOW	\$ 200
C327	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91383	151.142127	1	1	re-construct footpath pavement	MV65	Secondary	LOW	\$ 200
C328	Ewart Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91366	151.141939	1	1	re-construct footpath pavement	MV65	Secondary	LOW	\$ 200
C330	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907627	151.168266	1	1	re-construct footpath pavement	MV70	Tertiary	LOW	\$ 200
C331	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907572	151.16804	1	1	re-construct footpath pavement	MV70	Tertiary	LOW	\$ 200
C332	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907701	151.16789	1	1	re-construct footpath pavement	MV71	Tertiary	LOW	\$ 200
C333	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.908156	151.167356	1	1	re-construct footpath pavement	MV71	Tertiary	LOW	\$ 200
C334	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911045	151.166243	1	1	re-construct footpath pavement	MV202	Secondary	LOW	\$ 200
C335	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.90766	151.167456	1	1	re-construct footpath pavement	MV71	Tertiary	LOW	\$ 200
C336	Fitzroy Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907164	151.166287	1	1	re-construct footpath pavement	MV70	Tertiary	LOW	\$ 200
C337	Frazer Street	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.901273	151.152307	1	1	re-construct footpath pavement	MV75	Secondary	LOW	\$ 200
C338	Frazer Street	Marrickville	Regional Road	infrastructure condition	damaged kerb ramp	-33.901188	151.150702	1	1	install new kerb ramp	MV76	Secondary	LOW	\$ 2,500
C339	Frazer Street	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.901148	151.152558	1	1	re-construct footpath pavement	MV75	Secondary	LOW	\$ 200
C34	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.894903	151.129839	1	1	re-construct footpath pavement	AF159	Secondary	LOW	\$ 200
C340	Illawarra Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.906221	151.157573	1	1	re-construct footpath pavement	MV81	Secondary	LOW	\$ 200
C341	Illawarra Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.906902	151.157921	1	1	re-construct footpath pavement	MV81	Secondary	LOW	\$ 200
C342	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.918212	151.146827	1	1	re-construct footpath pavement	MV100	Secondary	LOW	\$ 200
C343	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.920834	151.14406	1	1	re-construct footpath pavement	MV80	Secondary	LOW	\$ 200
C344	Illawarra Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.926587	151.144254	1	1	re-construct footpath pavement	MV80	Secondary	LOW	\$ 200
C348	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.903746	151.153254	1	1	re-construct footpath pavement	MV110	Secondary	LOW	\$ 200
C349	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911291	151.148895	1	1	re-construct footpath pavement	MV106	Secondary	LOW	\$ 200
C35	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.898771	151.129555	1	1	re-construct footpath pavement	AF166	Secondary	LOW	\$ 200
C350	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911536	151.148465	1	1	re-construct footpath pavement	MV122	Secondary	LOW	\$ 200
C351	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.912338	151.147529	1	1	re-construct footpath pavement	MV116	Secondary	LOW	\$ 200
C352	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913167	151.146733	1	1	re-construct footpath pavement	MV117	Secondary	LOW	\$ 200
C353	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913508	151.146458	1	1	re-construct footpath pavement	MV117	Secondary	LOW	\$ 200
C354	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913676	151.146543	1	1	re-construct footpath pavement	MV117	Secondary	LOW	\$ 200
C355	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913275	151.146826	1	1	re-construct footpath pavement	MV117	Secondary	LOW	\$ 200
C356	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91283	151.147217	1	1	re-construct footpath pavement	MV116	Secondary	LOW	\$ 200
C357	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91248	151.147629	1	1	re-construct footpath pavement	MV116	Secondary	LOW	\$ 200
C358	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911787	151.145346	1	1	re-construct footpath pavement	MV122	Secondary	LOW	\$ 200
C359	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911572	151.148593	1	1	re-construct footpath pavement	MV122	Secondary	LOW	\$ 200
C36	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement tp	-33.898017	151.129602	1	1	repair pavement panel	AF166	Secondary	LOW	\$ 200
C362	Livingsstone Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.907194	151.151745	1	1	re-construct footpath pavement	MV119	Secondary	LOW	\$ 200
C367	Llewellyn Street	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.904071	151.171122	1	1	re-construct footpath pavement	MV126	Secondary	LOW	\$ 200
C368	Llewellyn Street	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.904027	151.171015	1	1	re-construct footpath pavement	MV126	Secondary	LOW	\$ 200
C37	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement tp	-33.89809	151.129571	1	1	repair pavement panel	AF167	Secondary	LOW	\$ 200
C371	Myrtle Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.915458	151.157292	1	1	re-construct footpath pavement	MV148	Tertiary	LOW	\$ 200
C372	Premier Street	Marrickville	Local Road	infrastructure condition	raised pavement tp	-33.920737	151.153043	1	1	repair pavement panel	MV159	Secondary	LOW	\$ 200
C373	Premier Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.920544	151.152879	1	1	re-construct footpath pavement	MV161	Secondary	LOW	\$ 200
C374	Premier Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.919946	151.151605	1	1	re-construct footpath pavement	MV162	Secondary	LOW	\$ 200
C375	Premier Street	Marrickville	Local Road	infrastructure condition	raised pavement tp	-33.919425	151.150441	1	1	repair pavement panel	MV163	Secondary	LOW	\$ 200
C376	Premier Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918839	151.149624	1	1	re-construct footpath pavement	MV158	Tertiary	LOW	\$ 200
C377	Premier Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918616	151.148905	1	1	re-construct footpath pavement	MV158	Tertiary	LOW	\$ 200
C378	Premier Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918644	151.148271	1	1	re-construct footpath pavement	MV158	Tertiary	LOW	\$ 200
C379	Premier Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918414	151.14852	1	1	re-construct footpath pavement	MV160	Tertiary	LOW	\$ 200
C38	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.								

**P4909 Inner West PAMP
Detailed Works Program
Infrastructure Condition
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
IC383	Renwick Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.919481	151.154452	1	1	re-construct footpath pavement	MV169	Tertiary	LOW	\$ 200
IC384	Renwick Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918971	151.153572	1	1	re-construct footpath pavement	MV172	Tertiary	LOW	\$ 200
IC385	Renwick Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91788	151.15327	1	1	re-construct footpath pavement	MV172	Tertiary	LOW	\$ 200
IC386	Richardson Crescent	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.922135	151.155651	1	1	re-construct footpath pavement	MV175	Secondary	LOW	\$ 200
IC387	Richardson Crescent	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.920799	151.155462	1	1	re-construct footpath pavement	MV173	Tertiary	LOW	\$ 200
IC388	Riverside Crescent	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914943	151.141807	1	1	re-construct footpath pavement	MV179	Tertiary	LOW	\$ 200
IC389	Riverside Crescent	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914859	151.140669	1	1	re-construct footpath pavement	MV180	Tertiary	LOW	\$ 200
IC39	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.898121	151.129566	1	1	repair pavement panel	AF167	Secondary	LOW	\$ 200
IC390	Riverside Crescent	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914501	151.13951	1	1	re-construct footpath pavement	MV177	Tertiary	LOW	\$ 200
IC391	Riverside Crescent	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.913864	151.139103	1	1	re-construct footpath pavement	MV177	Tertiary	LOW	\$ 200
IC392	Riverside Crescent	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914634	151.14049	1	1	re-construct footpath pavement	MV180	Tertiary	LOW	\$ 200
IC393	Shirlow Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.912172	151.166532	1	1	re-construct footpath pavement	MV185	Secondary	LOW	\$ 200
IC394	Shirlow Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.912064	151.166611	1	1	re-construct footpath pavement	MV185	Secondary	LOW	\$ 200
IC395	Shirlow Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911484	151.167485	1	1	re-construct footpath pavement	MV183	Tertiary	LOW	\$ 200
IC396	Shirlow Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.911158	151.168006	1	1	re-construct footpath pavement	MV184	Tertiary	LOW	\$ 200
IC397	Shirlow Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91238	151.16609	1	1	re-construct footpath pavement	MV185	Secondary	LOW	\$ 200
IC398	Station Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91449	151.155221	1	1	re-construct footpath pavement	MV188	Secondary	LOW	\$ 200
IC399	Station Street	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914673	151.155948	1	1	re-construct footpath pavement	MV187	Secondary	LOW	\$ 200
IC40	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.898323	151.129551	1	1	repair pavement panel	AF167	Secondary	LOW	\$ 200
IC400	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.911674	151.165012	1	1	re-construct footpath pavement	MV204	Secondary	LOW	\$ 200
IC401	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.911852	151.165257	1	1	re-construct footpath pavement	MV204	Secondary	LOW	\$ 200
IC402	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.912133	151.165602	1	1	re-construct footpath pavement	MV204	Secondary	LOW	\$ 200
IC403	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.912286	151.165714	1	1	re-construct footpath pavement	MV204	Secondary	LOW	\$ 200
IC406	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.911548	151.16461	1	1	re-construct footpath pavement	MV202	Secondary	LOW	\$ 200
IC409	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.910833	151.163767	1	1	re-construct footpath pavement	MV201	Secondary	LOW	\$ 200
IC41	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.898235	151.129451	1	1	repair pavement panel	AF168	Secondary	LOW	\$ 200
IC410	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.910777	151.1637	1	1	re-construct footpath pavement	MV201	Secondary	LOW	\$ 200
IC412	Sydenham Road	Marrickville	State Road	infrastructure condition	uneven pavement surface	-33.910253	151.163254	1	1	re-construct footpath pavement	MV201	Secondary	LOW	\$ 200
IC413	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909886	151.169796	1	1	re-construct footpath pavement	MV207	Tertiary	LOW	\$ 200
IC414	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909846	151.170149	1	1	re-construct footpath pavement	MV206	Tertiary	LOW	\$ 200
IC415	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909363	151.170621	1	1	re-construct footpath pavement	MV206	Tertiary	LOW	\$ 200
IC416	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909368	151.17069	1	1	re-construct footpath pavement	MV206	Tertiary	LOW	\$ 200
IC417	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909217	151.170632	1	1	re-construct footpath pavement	MV205	Secondary	LOW	\$ 200
IC418	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909284	151.171233	1	1	re-construct footpath pavement	MV205	Secondary	LOW	\$ 200
IC419	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909308	151.170879	1	1	re-construct footpath pavement	MV205	Secondary	LOW	\$ 200
IC42	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.899546	151.129421	1	1	repair pavement panel	AF168	Secondary	LOW	\$ 200
IC420	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.909971	151.169828	1	1	re-construct footpath pavement	MV207	Tertiary	LOW	\$ 200
IC421	Sydney Steel St	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.910107	151.169423	1	1	re-construct footpath pavement	MV207	Tertiary	LOW	\$ 200
IC422	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.905565	151.167827	1	1	re-construct footpath pavement	MV224	Secondary	LOW	\$ 200
IC424	Victoria Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.906504	151.164632	1	1	re-construct footpath pavement	MV215	Secondary	LOW	\$ 200
IC426	Victoria Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.911222	151.161119	1	1	re-construct footpath pavement	MV212	Secondary	LOW	\$ 200
IC43	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.900012	151.129412	1	1	repair pavement panel	AF168	Secondary	LOW	\$ 200
IC432	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914743	151.156477	1	1	re-construct footpath pavement	MV228	Secondary	LOW	\$ 200
IC433	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914435	151.156652	1	1	re-construct footpath pavement	MV228	Secondary	LOW	\$ 200
IC434	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914284	151.157137	1	1	re-construct footpath pavement	MV228	Secondary	LOW	\$ 200
IC435	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914448	151.157434	1	1	re-construct footpath pavement	MV209	Secondary	LOW	\$ 200
IC436	Victoria Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.914573	151.157668	1	1	re-construct footpath pavement	MV209	Secondary	LOW	\$ 200
IC437	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.901687	151.146097	1	1	re-construct footpath pavement	DH119	Tertiary	LOW	\$ 200
IC438	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.903558	151.148933	1	1	re-construct footpath pavement	DH120	Tertiary	LOW	\$ 200
IC439	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.903938	151.148755	1	1	re-construct footpath pavement	MV234	Secondary	LOW	\$ 200
IC44	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.900194	151.129382	1	1	repair pavement panel	AF168	Secondary	LOW	\$ 200
IC440	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.904317	151.148424	1	1	re-construct footpath pavement	MV234	Secondary	LOW	\$ 200
IC441	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.904429	151.148314	1	1	re-construct footpath pavement	DH122	Secondary	LOW	\$ 200
IC442	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.906038	151.146718	1	1	re-construct footpath pavement	MV235	Tertiary	LOW	\$ 200
IC443	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.907394	151.145164	1	1	re-construct footpath pavement	MV240	Secondary	LOW	\$ 200
IC444	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.907174	151.144652	1	1	re-construct footpath pavement	MV232	Secondary	LOW	\$ 200
IC445	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.907925	151.144383	1	1	re-construct footpath pavement	MV232	Secondary	LOW	\$ 200
IC446	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.908328	151.143953	1	1	re-construct footpath pavement	MV239	Secondary	LOW	\$ 200
IC447	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.912209	151.139698	1	1	re-construct footpath pavement	MV237	Secondary	LOW	\$ 200
IC448	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.912516	151.139491	1	1	re-construct footpath pavement	MV237	Secondary	LOW	\$ 200
IC449	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.91262	151.139291	1	1	re-construct footpath pavement	MV236	Secondary	LOW	\$ 200
IC45	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.900283	151.129369	1	1	re-construct footpath pavement	AF168	Secondary	LOW	\$ 200
IC450	Wardell Road	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.912873	151.138807	1	1	re-construct footpath pavement	MV236	Secondary	LOW	\$ 200
IC451	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.915082	151.148947	1	1	re-construct footpath pavement	MV245	Secondary	LOW	\$ 200
IC455	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.916408	151.151195	1	1	re-construct footpath pavement	MV248	Secondary	LOW	\$ 200
IC456	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91742	151.152982	1	1	re-construct footpath pavement	MV241	Tertiary	LOW	\$ 200
IC457	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.918104	151.154194	1	1	re-construct footpath pavement	MV249	Tertiary	LOW	\$ 200
IC458	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91846	151.154647	1	1	re-construct footpath pavement	MV250	Tertiary	LOW	\$ 200
IC459	Warren Road	Marrickville	Local Road	infrastructure condition	uneven pavement surface	-33.91381	151.146756	1	1	re-construct footpath pavement	MV243	Secondary	LOW	\$ 200
IC46	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.900383	151.129358	1	1	repair pavement panel	AF169	Secondary	LOW	\$ 200
IC460	Alice Street	Marrickville	Regional Road	infrastructure condition	uneven pavement surface	-33.903631	151.171063	1	1	re-construct footpath pavement	MV263	Secondary	LOW	\$ 200
IC465	Philip Street	Newtown	Local Road	infrastructure condition	uneven crossing surface	-33.898292	151.173763	1	1	install new pavement surface	NE46	Secondary	LOW	\$ 300
IC466	Station Street	Newtown	Local Road	infrastructure condition	uneven pavement surface	-33.899886	151.177047	1	1	re-construct footpath pavement	NE59	Secondary	LOW	\$ 200
IC467	Crystal Street	Petersham	Regional Road	infrastructure condition	uneven pavement surface	-33.895453	151.157558	1	1	re-construct footpath pavement	PE13	Secondary	LOW	\$ 200
IC469	Palace Street	Petersham	Local Road	infrastructure condition	raised pavement lip	-33.896991	151.154429	1	1	repair pavement panel	PE12	Secondary	LOW	\$ 200
IC47	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.900491	151.129351	1	1	re-construct footpath pavement	AF169	Secondary	LOW	\$ 200
IC470	Palace Street	Petersham	Local Road	infrastructure condition	uneven pavement surface	-33.899442	151.154448	1	1	re-construct footpath pavement	PE40	Secondary	LOW	\$ 200
IC473	Denison Street	Rozelle	Local Road	infrastructure condition	raised pavement lip	-33.866471	151.166343	1	1	repair pavement panel	RO29	Secondary	LOW	\$ 200
IC474	Denison Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.863464	151.169409	1	1	re-construct footpath pavement	RO28	Tertiary	LOW	\$ 200
IC475	Denison Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.868621	151.166665	1	1	re-construct footpath pavement	RO28	Tertiary	LOW	\$ 200
IC476	Denison Street	Rozelle	Local Road	infrastructure condition	raised pavement lip	-33.868676	151.169735	1	1	repair pavement panel	RO28	Tertiary	LOW	\$ 200
IC477	James Craig Road	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.870037	151.175291	1	1	re-construct footpath pavement	RO44	Secondary	LOW	\$ 200
IC478	Lilyfield Road	Rozelle	Regional Road	infrastructure condition	uneven pavement surface	-33.868791	151.173636	1	1	re-construct footpath pavement	RO42	Secondary	LOW	\$ 200
IC479	Manning Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.86558	151.166663	1	1	re-construct footpath pavement	RO62	Secondary	LOW	\$ 200
IC48	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.900537	151.129332	1	1	repair pavement panel	AF169	Secondary	LOW	\$ 200
IC480	Robert Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.865842	151.171478	1	1	re-construct footpath pavement	RO68	Tertiary	LOW	\$ 200
IC481	Robert Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.865439	151.178104	1	1	re-construct footpath pavement	RO61	Tertiary	LOW	\$ 200
IC482	Terry Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.86026	151.170471	1	1	re-construct footpath pavement	RO63	Secondary	LOW	\$ 200
IC483	Terry Street	Rozelle	Local Road	infrastructure condition	uneven pavement surface	-33.859119	151.17078	1	1	re-construct footpath pavement	RO69	Secondary	LOW	\$ 200
IC484														

**P4909 Inner West PAMP
Detailed Works Program
Infrastructure Condition
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost	
IC488	Victoria Road	Rozelle	State Road	infrastructure condition	uneven pavement surface	-33.86722	151.17533	1	1	re-construct footpath pavement	RO70	Secondary	LOW	\$ 200	
IC489	Victoria Road	Rozelle	State Road	infrastructure condition	uneven pavement surface	-33.866281	151.174601	1	1	re-construct footpath pavement	RO74	Secondary	LOW	\$ 200	
IC490	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.901631	151.129451	1	1	re-construct footpath pavement	AF170	Secondary	LOW	\$ 200	
IC490	Bedwin Road	St Peters	Regional Road	infrastructure condition	uneven pavement surface	-33.909069	151.17516	1	1	re-construct footpath pavement	MM18	Secondary	LOW	\$ 200	
IC491	Bedwin Road	St Peters	Regional Road	infrastructure condition	uneven pavement surface	-33.909052	151.175224	1	1	re-construct footpath pavement	MM18	Secondary	LOW	\$ 200	
IC492	Church Street	St Peters	Local Road	infrastructure condition	uneven pavement surface	-33.912979	151.177833	1	1	re-construct footpath pavement	SPT7	Secondary	LOW	\$ 200	
IC493	Edith Street	St Peters	Local Road	infrastructure condition	uneven pavement surface	-33.912383	151.173286	1	1	re-construct footpath pavement	SP35	Tertiary	LOW	\$ 200	
IC494	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.916854	151.172236	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200	
IC495	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.919463	151.169059	1	1	re-construct footpath pavement	SP28	Secondary	LOW	\$ 200	
IC496	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.916931	151.172492	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200	
IC497	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.916746	151.172726	1	1	re-construct footpath pavement	SP25	Secondary	LOW	\$ 200	
IC500	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.901178	151.129294	1	1	repair pavement panel	AF169	Secondary	LOW	\$ 200	
IC503	Princes Highway	St Peters	State Road	infrastructure condition	uneven pavement surface	-33.915286	151.175019	1	1	re-construct footpath pavement	SP22	Secondary	LOW	\$ 200	
IC506	Railway Avenue	Stammore	Local Road	infrastructure condition	uneven pavement surface	-33.894384	151.169932	1	1	re-construct footpath pavement	SM38	Tertiary	LOW	\$ 200	
IC507	Carlton Crescent	Summer Hill	Regional Road	infrastructure condition	uneven pavement surface	-33.889777	151.131969	1	1	re-construct footpath pavement	SH8	Secondary	LOW	\$ 200	
IC508	Grosvenor Crescent	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.889329	151.133027	1	1	re-construct footpath pavement	SH28	Secondary	LOW	\$ 200	
IC509	Henson Street	Summer Hill	Local Road	infrastructure condition	raised pavement lip	-33.897201	151.134566	1	1	repair pavement panel	SH35	Secondary	LOW	\$ 200	
IC510	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.902275	151.129591	1	1	repair pavement panel	AF170	Secondary	LOW	\$ 200	
IC510	Henson Street	Summer Hill	Local Road	infrastructure condition	raised pavement lip	-33.897136	151.134459	1	1	repair pavement panel	SH35	Secondary	LOW	\$ 200	
IC511	Henson Street	Summer Hill	Local Road	infrastructure condition	raised pavement lip	-33.898479	151.134491	1	1	repair pavement panel	SH35	Secondary	LOW	\$ 200	
IC512	Herbert Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.896277	151.134181	1	1	re-construct footpath pavement	SH37	Secondary	LOW	\$ 200	
IC513	James Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.897356	151.135608	1	1	re-construct footpath pavement	SH38	Secondary	LOW	\$ 200	
IC514	Junction Road	Summer Hill	Local Road	infrastructure condition	raised pavement lip	-33.895271	151.137019	1	1	repair pavement panel	SH39	Secondary	LOW	\$ 200	
IC515	Junction Road	Summer Hill	Local Road	infrastructure condition	raised pavement lip	-33.895166	151.134231	1	1	repair pavement panel	SH41	Secondary	LOW	\$ 200	
IC516	Prospect Road	Summer Hill	Local Road	infrastructure condition	raised pavement lip	-33.89692	151.132313	1	1	repair pavement panel	SH71	Tertiary	LOW	\$ 200	
IC517	Prospect Road	Summer Hill	Local Road	infrastructure condition	raised pavement lip	-33.897331	151.132235	1	1	repair pavement panel	SH72	Tertiary	LOW	\$ 200	
IC518	Prospect Road	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898205	151.132133	1	1	re-construct footpath pavement	SH73	Secondary	LOW	\$ 200	
IC519	Prospect Road	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.898899	151.132096	1	1	re-construct footpath pavement	SH74	Secondary	LOW	\$ 200	
IC52	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.902211	151.1292	1	1	re-construct footpath pavement	AF170	Secondary	LOW	\$ 200	
IC521	Smith Street	Summer Hill	Local Road	infrastructure condition	uneven pavement surface	-33.891845	151.138695	1	1	install new utility cover	SH82	Secondary	LOW	\$ 2,000	
IC522	Burrows Avenue	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.915047	151.166471	1	1	re-construct footpath pavement	SY2	Secondary	LOW	\$ 200	
IC523	Burrows Avenue	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.914656	151.167033	1	1	re-construct footpath pavement	SY1	Secondary	LOW	\$ 200	
IC524	George Street	Sydenham	Local Road	infrastructure condition	raised pavement lip	-33.914793	151.167477	1	1	repair pavement panel	SY3	Secondary	LOW	\$ 200	
IC525	George Street	Sydenham	Local Road	infrastructure condition	uneven pavement surface	-33.914539	151.167214	1	1	re-construct footpath pavement	SY1	Secondary	LOW	\$ 200	
IC526	Princes Highway	Sydenham	State Road	infrastructure condition	uneven pavement surface	-33.918661	151.169832	1	1	re-construct footpath pavement	SP27	Secondary	LOW	\$ 200	
IC527	Princes Highway	Sydenham	State Road	infrastructure condition	uneven pavement surface	-33.919422	151.168835	1	1	re-construct footpath pavement	SP28	Secondary	LOW	\$ 200	
IC528	Princes Highway	Sydenham	State Road	infrastructure condition	uneven pavement surface	-33.919945	151.168235	1	1	re-construct footpath pavement	SP29	Secondary	LOW	\$ 200	
IC53	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.902968	151.129325	1	1	re-construct footpath pavement	AF164	Secondary	LOW	\$ 200	
IC530	Griffiths Street	Tempe	Local Road	infrastructure condition	raised pavement lip	-33.924977	151.156729	1	1	repair pavement panel	TE32	Secondary	LOW	\$ 200	
IC531	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.920966	151.16703	1	1	re-construct footpath pavement	TE7	Secondary	LOW	\$ 200	
IC532	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.920729	151.168849	1	1	re-construct footpath pavement	TE1	Secondary	LOW	\$ 200	
IC533	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.921289	151.164896	1	1	re-construct footpath pavement	TE9	Secondary	LOW	\$ 200	
IC535	Princes Highway	Tempe	State Road	infrastructure condition	uneven pavement surface	-33.927701	151.157903	1	1	re-construct footpath pavement	TE30	Secondary	LOW	\$ 200	
IC54	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.902437	151.129203	1	1	repair pavement panel	AF170	Secondary	LOW	\$ 200	
IC55	Victoria Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.902598	151.129188	1	1	re-construct footpath pavement	AF170	Secondary	LOW	\$ 200	
IC56	Victoria Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.902786	151.129167	1	1	repair pavement panel	AF164	Secondary	LOW	\$ 200	
IC57	All Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.884137	151.123853	1	1	re-construct footpath pavement	AF7	Secondary	LOW	\$ 200	
IC6	Pymont Bridge Road	Ammandale	State Road	infrastructure condition	uneven pavement surface	-33.886074	151.175067	1	1	re-construct footpath pavement	AN80	Secondary	LOW	\$ 200	
IC61	Armstrong Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.897925	151.125413	1	1	repair pavement panel	AF12	Tertiary	LOW	\$ 200	
IC62	Armstrong Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.898283	151.125551	1	1	re-construct footpath pavement	AF13	Tertiary	LOW	\$ 200	
IC63	Armstrong Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.899999	151.126954	1	1	re-construct footpath pavement	AF11	Tertiary	LOW	\$ 200	
IC64	Armstrong Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.8998	151.128815	1	1	repair pavement panel	AF11	Tertiary	LOW	\$ 200	
IC66	Charlotte Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.883483	151.127508	1	1	re-construct footpath pavement	AF36	Tertiary	LOW	\$ 200	
IC67	Charlotte Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.883115	151.127265	1	1	re-construct footpath pavement	AF36	Tertiary	LOW	\$ 200	
IC68	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.878728	151.125311	1	1	re-construct footpath pavement	AF43	Secondary	LOW	\$ 200	
IC69	Church Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.878341	151.129338	1	1	repair pavement panel	AF43	Secondary	LOW	\$ 200	
IC70	Pymont Bridge Road	Ammandale	State Road	infrastructure condition	uneven pavement surface	-33.88547	151.17603	1	1	re-construct footpath pavement	AN91	Secondary	LOW	\$ 200	
IC71	Church Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.87677	151.124071	1	1	repair pavement panel	AF41	Tertiary	LOW	\$ 200	
IC72	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.87707	151.124297	1	1	re-construct footpath pavement	AF41	Tertiary	LOW	\$ 200	
IC72	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.876826	151.125437	1	1	re-construct footpath pavement	AF43	Secondary	LOW	\$ 200	
IC73	Church Street	Ashfield	Local Road	infrastructure condition	uneven pavement surface	-33.880921	151.126892	1	1	re-construct footpath pavement	AF45	Tertiary	LOW	\$ 200	
IC74	Clissold Street	Ashfield	Local Road	infrastructure condition	raised pavement lip	-33.895617	151.126631	1	1	repair pavement panel	AF48	Secondary	LOW	\$ 200	
IC78	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.886433	151.129426	1	1	re-construct footpath pavement	AF63	Secondary	LOW	\$ 200	
IC79	Elizabeth Street	Ashfield	Regional Road	infrastructure condition	uneven pavement surface	-33.886327	151.129404	1	1	re-construct footpath pavement	AF63	Secondary	LOW	\$ 200	
IC8	Pymont Bridge Road	Ammandale	State Road	infrastructure condition	uneven pavement surface	-33.885703	151.175569	1	1	re-construct footpath pavement	AN91	Secondary	LOW	\$ 200	
IC89	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.882474	151.121299	1	1	re-construct footpath pavement	AF74	Secondary	LOW	\$ 200	
IC90	Pymont Bridge Road	Ammandale	State Road	infrastructure condition	uneven pavement surface	-33.886786	151.17548	1	1	re-construct footpath pavement	AN91	Secondary	LOW	\$ 200	
IC90	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.885209	151.12097	1	1	re-construct footpath pavement	AF74	Secondary	LOW	\$ 200	
IC91	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.884359	151.120205	1	1	re-construct footpath pavement	AF75	Secondary	LOW	\$ 200	
IC93	Frederick Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.877206	151.128676	1	1	re-construct footpath pavement	AF68	Secondary	LOW	\$ 200	
IC95	Milton Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.891061	151.117059	1	1	re-construct footpath pavement	AF115	Secondary	LOW	\$ 200	
IC99	Milton Street	Ashfield	State Road	infrastructure condition	uneven pavement surface	-33.890956	151.117255	1	1	re-construct footpath pavement	AF115	Secondary	LOW	\$ 200	
														SUBTOTAL	\$ 93,600
														TOTAL	\$ 123,556

**P4909 Inner West PAMP
Detailed Works Program
Missing Footpaths
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
MP10	Frederick Street	Ashfield	State Road	missing footpath	missing footpath section	-33.877829	151.127969	2	install new footpath		AF69	Primary	HIGH	\$ 400
MP11	Gladstone Street	Balmain	Local Road	missing footpath	missing footpath	-33.887477	151.184061	55	install new footpath		BA41	Primary	HIGH	\$ 11,000
MP14	Iron Cove Creek	Croydon	Local Road	missing footpath	new footpath	-33.873977	151.126936	2785	Undertake masterplan study		NA	Primary	HIGH	\$ 200,000
MP22	Hudson Street	Lewisham	Local Road	missing footpath	missing footpath	-33.883976	151.143764	34	install new footpath		LW5	Primary	HIGH	\$ 6,800
MP23	McGill Street	Lewisham	Local Road	missing footpath	missing footpath	-33.884526	151.143881	114	investigate shared zone implementation		LW5	Primary	HIGH	\$ 15,000
MP37	Ewart Lane	Marrickville	Local Road	missing footpath	missing footpath	-33.91079	151.139553	149	install new footpath		DH51	Primary	HIGH	\$ 29,800
MP41	Victoria Road	Marrickville	State Road	missing footpath	missing footpath	-33.914528	151.158278	54	install new footpath		MV227	Primary	HIGH	\$ 10,800
MP7	Johnsons Creek	Annandale	Local Road	missing footpath	major pedestrian link missing	-33.885979	151.173072	375	further investigation required - pedestrian link (major infrastructure)		AN31	Primary	HIGH	\$ 50,000
														SUBTOTAL \$ 323,800
MP1	Railway Parade	Annandale	Local Road	missing footpath	missing footpath	-33.872089	151.172521	75	install new footpath		AN18	Secondary	MED	\$ 15,000
MP12	Cardigan Lane	Camperdown	Local Road	missing footpath	missing footpath	-33.889988	151.172808	152	investigate shared zone implementation		CA18	Secondary	MED	\$ 15,000
MP13	Church Street	Croydon	Local Road	missing footpath	missing footpath	-33.875618	151.120223	179	install new footpath		CR1	Secondary	MED	\$ 35,800
MP16	Hercules Street	Dulwich Hill	Local Road	missing footpath	missing footpath	-33.90901	151.138479	79	install new footpath		DH52	Secondary	MED	\$ 15,800
MP18	Elswick Street	Leichhardt	Local Road	missing footpath	missing footpath	-33.87763	151.151657	65	install new footpath		LH47	Secondary	MED	\$ 13,000
MP19	Darley Road	Leichhardt	State Road	missing footpath	missing footpath	-33.876768	151.148943	589	install new footpath		LH57	Secondary	MED	\$ 117,800
MP2	Pritchard Street	Annandale	Local Road	missing footpath	missing footpath	-33.872312	151.172766	60	install new footpath		AN18	Secondary	MED	\$ 12,000
MP20	Whites Creek Lane	Leichhardt	Local Road	missing footpath	missing footpath	-33.885639	151.164353	101	install new footpath		LH159	Secondary	MED	\$ 20,200
MP21	Whites Creek Lane	Leichhardt	Local Road	missing footpath	missing footpath	-33.882401	151.166286	57	install new footpath		LH165	Secondary	MED	\$ 11,400
MP25	Maiyawl Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.872116	151.151727	91	install new footpath		LF12	Secondary	MED	\$ 18,200
MP26	Maiyawl Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.872296	151.151955	44	install new footpath		LF12	Secondary	MED	\$ 8,800
MP27	Maiyawl Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.871275	151.151854	112	install new footpath		LF28	Secondary	MED	\$ 22,400
MP28	Maiyawl Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.869276	151.153444	186	install new footpath		LF28	Secondary	MED	\$ 37,200
MP3	Cohen Park	Annandale	Local Road	missing footpath	missing footpath	-33.875723	151.169162	196	install new footpath		AN119	Secondary	MED	\$ 39,200
MP31	Glover Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.867735	151.155751	347	install new footpath		LF49	Secondary	MED	\$ 69,400
MP32	Lilyfield Road	Lilyfield	Regional Road	missing footpath	missing footpath	-33.872812	151.166818	31	install new footpath		LF73	Secondary	MED	\$ 6,200
MP34	Carrington Road	Marrickville	Local Road	missing footpath	missing footpath	-33.92101	151.154265	86	install new footpath		MV24	Secondary	MED	\$ 17,200
MP36	Byrnes Street	Marrickville	Local Road	missing footpath	missing footpath	-33.913724	151.15543	3	install new footpath		MV20	Secondary	MED	\$ 600
MP39	Victoria Road	Marrickville	State Road	missing footpath	missing footpath	-33.914457	151.157086	92	install new footpath		MV228	Secondary	MED	\$ 18,400
MP4	Hudson Street - Piper Street	Annandale	Local Road	missing footpath	missing footpath	-33.87031	151.168789	99	investigate shared zone implementation		AN118	Secondary	MED	\$ 15,000
MP40	Meeks Road	Marrickville	Local Road	missing footpath	missing footpath	-33.914755	151.156052	105	install new footpath		MV209	Secondary	MED	\$ 21,000
MP42	Edgeware Road	Marrickville	Regional Road	missing footpath	missing footpath	-33.908086	151.174658	19	install new footpath		MV17	Secondary	MED	\$ 3,800
MP43	Pearl Lane	Newtown	Local Road	missing footpath	missing footpath	-33.905116	151.177747	183	investigate shared zone implementation		NE64	Secondary	MED	\$ 15,000
MP44	Manning Street	Rozelle	Local Road	missing footpath	missing footpath	-33.863085	151.16485	273	install new footpath		RO51	Secondary	MED	\$ 54,600
MP47	Albion Lane	St Peters	Local Road	missing footpath	missing footpath	-33.913383	151.171561	155	investigate shared zone implementation		SP37	Secondary	MED	\$ 15,000
MP48	James Street	Summer Hill	Local Road	missing footpath	missing footpath	-33.897348	151.135723	8	install new footpath		SH38	Secondary	MED	\$ 1,600
MP49	Smith Street	Summer Hill	Local Road	missing footpath	missing footpath	-33.892694	151.14323	8	install new footpath		SH89	Secondary	MED	\$ 1,600
MP5	Gehrig Lane	Annandale	Local Road	missing footpath	missing footpath	-33.885653	151.174785	89	investigate shared zone implementation		AN38	Secondary	MED	\$ 15,000
MP6	Bignell Lane	Annandale	Local Road	missing footpath	missing footpath	-33.886367	151.175613	151	investigate shared zone implementation		AN19	Secondary	MED	\$ 15,000
MP8	Victoria Street	Ashfield	Local Road	missing footpath	missing footpath	-33.903441	151.129241	32	install new footpath		AF164	Secondary	MED	\$ 6,400
MP9	Palace Street	Ashfield	Local Road	missing footpath	missing footpath	-33.894974	151.122167	169	install new footpath		AF143	Secondary	MED	\$ 33,800
														SUBTOTAL \$ 691,400
MP15	Challis Avenue	Dulwich Hill	Local Road	missing footpath	missing footpath	-33.910857	151.145213	35	install new footpath		DH7	Tertiary	LOW	\$ 7,000
MP17	Challis Avenue	Dulwich Hill	Local Road	missing footpath	missing footpath	-33.9109	151.144876	17	install new footpath		DH7	Tertiary	LOW	\$ 3,400
MP24	Canal Road	Lilyfield	Local Road	missing footpath	missing footpath	-33.87241	151.151096	43	install new footpath		LF13	Tertiary	LOW	\$ 8,600
MP29	Mary Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.86786	151.15504	114	install new footpath		LF80	Tertiary	LOW	\$ 22,800
MP30	Mary Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.867835	151.155396	18	install new footpath		LF80	Tertiary	LOW	\$ 3,600
MP33	Frazer Street	Lilyfield	Local Road	missing footpath	missing footpath	-33.869215	151.15265	287	install new footpath		LF43	Tertiary	LOW	\$ 57,400
MP35	Myrtle Street	Marrickville	Local Road	missing footpath	missing footpath	-33.915227	151.156766	49	install new footpath		MV146	Tertiary	LOW	\$ 9,800
MP38	Premier Street	Marrickville	Local Road	missing footpath	missing footpath	-33.918026	151.148074	20	install new footpath		MV160	Tertiary	LOW	\$ 4,000
MP45	Robert Street	Rozelle	Local Road	missing footpath	missing footpath	-33.86538	151.178607	291	install new footpath		RO61	Tertiary	LOW	\$ 58,200
MP46	Denison Street	Rozelle	Local Road	missing footpath	missing footpath	-33.869911	151.170122	116	install new footpath		RO28	Tertiary	LOW	\$ 23,200
														SUBTOTAL \$ 198,000
														TOTAL \$ 1,213,200

**P4909 Inner West PAMP
Detailed Works Program
Narrow Footpaths
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost	
NP1	Chester Street	Annandale	Local Road	narrow footpath	narrow footpath	-33.884362	151.17364	53	widen footpath		AN31	Primary	MED	\$ 10,600	
NP10	Jane Street	Balmain	Local Road	narrow footpath	narrow footpath	-33.890906	151.184397	167	widen footpath		BA44	Primary	MED	\$ 33,400	
NP11	Jane Street	Balmain	Local Road	narrow footpath	narrow footpath	-33.890901	151.18443	165	widen footpath		BA44	Primary	MED	\$ 33,000	
NP14	Mullens Street	Balmain	Regional Road	narrow footpath	narrow footpath	-33.881438	151.176628	14	widen footpath		BA51	Primary	MED	\$ 2,800	
NP19	Denison Road	Dulwich Hill	Local Road	narrow footpath	narrow footpath	-33.902163	151.139559	7	widen footpath		DH23	Primary	MED	\$ 1,400	
NP22	Parramatta Road	Haberfield	State Road	narrow footpath	narrow footpath	-33.88124	151.132727	210	widen footpath		AF145	Primary	MED	\$ 42,000	
NP44	Wilford Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.88373	151.174777	67	Investigate shared zone implementation		NE38	Primary	MED	\$ 15,000	
NP45	Station Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.899738	151.177022	231	widen footpath		NE38	Primary	MED	\$ 46,200	
NP46	Station Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.899916	151.176999	218	widen footpath		NE38	Primary	MED	\$ 43,600	
NP48	Goddard Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.89341	151.17755	46	Investigate shared zone implementation		NE49	Primary	MED	\$ 15,000	
NP56	Princes Highway	St Peters	State Road	narrow footpath	narrow footpath	-33.914562	151.176896	17	widen footpath		SP19	Primary	MED	\$ 3,400	
NP6	Cavill Avenue	Ashfield	Local Road	narrow footpath	narrow footpath	-33.887172	151.122279	60	widen footpath		AF33	Primary	MED	\$ 12,000	
NP7	Frederick Street	Ashfield	State Road	narrow footpath	narrow footpath in underpass due to fencing	-33.885379	151.119519	25	widen path and relocate fencing		AF76	Primary	MED	\$ 10,000	
NP8	Frederick Street	Ashfield	State Road	narrow footpath	narrow footpath in underpass due to fencing	-33.885328	151.119435	26	widen path and relocate fencing		AF76	Primary	MED	\$ 10,400	
NP9	Eaton Street	Balmain	Local Road	narrow footpath	narrow footpath	-33.886262	151.183702	11	widen footpath		BA40	Primary	MED	\$ 2,200	
														SUBTOTAL	\$ 281,000
NP12	Booth Street	Balmain	Regional Road	narrow footpath	narrow footpath	-33.880543	151.181198	118	widen footpath		BA14	Secondary	LOW	\$ 23,600	
NP13	Hyam Street	Balmain	Local Road	narrow footpath	narrow footpath	-33.881451	151.180362	236	widen footpath		BA43	Secondary	LOW	\$ 47,200	
NP15	Buchanan Street	Balmain	Local Road	narrow footpath	narrow footpath	-33.883164	151.180334	165	widen footpath		BA18	Tertiary	LOW	\$ 33,000	
NP16	Parramatta Road	Croydon	State Road	narrow footpath	narrow footpath	-33.871747	151.123853	38	widen footpath		CR29	Secondary	LOW	\$ 7,600	
NP17	Parramatta Road	Croydon	State Road	narrow footpath	narrow footpath	-33.873056	151.125958	3	widen footpath		CR31	Secondary	LOW	\$ 600	
NP18	Piggott Street	Dulwich Hill	Local Road	narrow footpath	narrow footpath	-33.902035	151.143263	7	widen footpath		DH105	Secondary	LOW	\$ 1,400	
NP2	Gordon Street	Annandale	State Road	narrow footpath	narrow footpath	-33.886536	151.174172	161	Investigate shared zone implementation		AN39	Secondary	LOW	\$ 15,000	
NP20	Weston Street	Dulwich Hill	Local Road	narrow footpath	narrow footpath	-33.888439	151.13994	7	widen footpath		DH44	Secondary	LOW	\$ 1,400	
NP21	Constitution Road	Dulwich Hill	Local Road	narrow footpath	narrow footpath	-33.902529	151.137952	15	widen footpath		DH17	Secondary	LOW	\$ 3,000	
NP23	Elwick Street	Leichhardt	Local Road	narrow footpath	narrow footpath	-33.888627	151.153008	8	widen footpath		LH53	Secondary	LOW	\$ 1,000	
NP24	Mackenzie Street	Leichhardt	Local Road	narrow footpath	narrow footpath	-33.883812	151.161257	136	widen footpath		LH60	Secondary	LOW	\$ 27,200	
NP25	Maliyawul Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.870489	151.152025	65	widen footpath		LF11	Secondary	LOW	\$ 13,000	
NP26	Perry Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.872601	151.155287	8	widen footpath		LF78	Tertiary	LOW	\$ 1,600	
NP27	Glover Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.871739	151.157355	37	widen footpath		LF51	Secondary	LOW	\$ 7,400	
NP28	Lilyfield Road	Lilyfield	Regional Road	narrow footpath	narrow footpath	-33.870438	151.170706	22	widen footpath		RO46	Secondary	LOW	\$ 4,400	
NP29	Balmain Road	Lilyfield	State Road	narrow footpath	narrow footpath	-33.869428	151.162638	174	widen footpath		LF2	Secondary	LOW	\$ 34,800	
NP3	Victoria Street	Ashfield	Local Road	narrow footpath	narrow footpath	-33.889385	151.128602	304	widen footpath		AF168	Secondary	LOW	\$ 60,800	
NP30	Grove Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.872636	151.164594	128	widen footpath		LF54	Secondary	LOW	\$ 25,600	
NP31	Piper Street	Lilyfield	Local Road	narrow footpath	narrow footpath	-33.875999	151.162517	292	widen footpath		LF93	Secondary	LOW	\$ 58,400	
NP32	Premier Street	Marrickville	Local Road	narrow footpath	narrow footpath	-33.921151	151.153555	78	widen footpath		MV159	Secondary	LOW	\$ 15,600	
NP33	Warren Road	Marrickville	Local Road	narrow footpath	narrow footpath	-33.918262	151.154425	4	widen footpath		MV250	Tertiary	LOW	\$ 800	
NP34	Byrnes Street	Marrickville	Local Road	narrow footpath	narrow footpath	-33.913722	151.15532	18	widen footpath		MV20	Secondary	LOW	\$ 3,600	
NP35	Wardell Road	Marrickville	Regional Road	narrow footpath	narrow footpath	-33.913644	151.13744	69	widen footpath		MV233	Secondary	LOW	\$ 13,800	
NP36	Bedwin Road	Marrickville	Regional Road	narrow footpath	narrow footpath	-33.908891	151.174979	92	widen footpath		MV18	Secondary	LOW	\$ 18,400	
NP37	Bedwin Road	Marrickville	Regional Road	narrow footpath	narrow footpath	-33.908879	151.175019	91	widen footpath		MV18	Secondary	LOW	\$ 18,200	
NP38	Sydney Steel Road	Marrickville	Local Road	narrow footpath	narrow footpath	-33.909349	151.170599	221	widen footpath		MV205	Secondary	LOW	\$ 44,200	
NP39	Sydney Steel Road	Marrickville	Local Road	narrow footpath	narrow footpath	-33.909385	151.17068	224	widen footpath		MV205	Secondary	LOW	\$ 44,800	
NP4	Chasold Street	Ashfield	Local Road	narrow footpath	narrow footpath	-33.895725	151.130002	429	widen footpath		AF50	Secondary	LOW	\$ 85,800	
NP40	Shirlow Street	Marrickville	Local Road	narrow footpath	narrow footpath	-33.911237	151.167889	12	widen footpath		MV108	Tertiary	LOW	\$ 2,400	
NP41	Victoria Road	Marrickville	State Road	narrow footpath	narrow footpath	-33.914237	151.156804	34	widen footpath		MV228	Secondary	LOW	\$ 6,800	
NP42	Liberty Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.895627	151.17136	7	widen footpath		NE43	Secondary	LOW	\$ 1,400	
NP43	Lennox Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.895187	151.180592	5	widen footpath		NE41	Secondary	LOW	\$ 1,000	
NP47	Bailey Street	Newtown	Local Road	narrow footpath	narrow footpath	-33.899395	151.177277	207	Investigate shared zone implementation		NE59	Secondary	LOW	\$ 15,000	
NP49	Manning Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.865134	151.166133	211	widen footpath		SH72	Secondary	LOW	\$ 42,200	
NP5	Prospect Road	Ashfield	Local Road	narrow footpath	narrow footpath	-33.896916	151.132231	222	widen footpath		SH72	Tertiary	LOW	\$ 44,400	
NP50	Manning Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.865093	151.166205	209	widen footpath		RO52	Secondary	LOW	\$ 41,800	
NP51	Robert Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.864342	151.160406	106	widen footpath		RO59	Tertiary	LOW	\$ 21,200	
NP52	Robert Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.865522	151.178037	171	widen footpath		RO61	Tertiary	LOW	\$ 34,200	
NP53	Robert Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.866542	151.175683	18	widen footpath		RO57	Secondary	LOW	\$ 3,600	
NP54	Victoria Road	Rozelle	State Road	narrow footpath	narrow footpath	-33.866968	151.175101	44	widen footpath		RO74	Secondary	LOW	\$ 8,800	
NP55	Denison Street	Rozelle	Local Road	narrow footpath	narrow footpath	-33.869537	151.169558	15	widen footpath		RO28	Tertiary	LOW	\$ 3,000	
NP57	St Peters Street	St Peters	Local Road	narrow footpath	narrow footpath	-33.912305	151.177196	158	widen footpath		SP30	Secondary	LOW	\$ 31,600	
NP58	St Peters Street	St Peters	Local Road	narrow footpath	narrow footpath	-33.912351	151.177261	158	widen footpath		SP30	Secondary	LOW	\$ 31,600	
NP59	Henson Street	Summer Hill	Local Road	narrow footpath	narrow footpath	-33.884458	151.134665	476	widen footpath		SH36	Secondary	LOW	\$ 96,200	
NP60	Nowraire Street	Summer Hill	Local Road	narrow footpath	narrow footpath	-33.893384	151.138813	204	widen footpath		SH52	Secondary	LOW	\$ 40,800	
NP61	James Street	Summer Hill	Local Road	narrow footpath	narrow footpath	-33.897399	151.135239	127	widen footpath		SH38	Secondary	LOW	\$ 25,400	
NP62	Elizabeth Street	Summer Hill	Regional Road	narrow footpath	narrow footpath	-33.889179	151.131764	108	widen footpath		AG61	Secondary	LOW	\$ 21,600	
														SUBTOTAL	\$ 1,084,200
														TOTAL	\$ 1,365,200

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB1	Annandale Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886254	151.166705	1		refer to maintenance	AN1	Secondary	LOW	\$ -
OB10	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878177	151.175391	1		notify business/property owner	AN67	Secondary	LOW	\$ -
OB100	Holiden Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897375	151.126021	1		notify business/property owner	AF63	Tertiary	LOW	\$ -
OB100V	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.911026	151.161333	1		notify business/property owner	MV212	Secondary	LOW	\$ -
OB100V	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.911551	151.160824	1		notify business/property owner	MV220	Primary	LOW	\$ -
OB100V	Victoria Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914405	151.158536	1		refer to maintenance	MV227	Primary	LOW	\$ -
OB100V	Victoria Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914623	151.157831	1		notify business/property owner	MV209	Secondary	LOW	\$ -
OB100V	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.9078	151.163607	1		refer to maintenance	MV217	Secondary	LOW	\$ -
OB100V	Wardell Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.906986	151.149621	1		notify business/property owner	MV240	Secondary	LOW	\$ -
OB100V	Warren Road	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.914436	151.147853	1		no action	MV244	Secondary	LOW	\$ -
OB100V	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.916563	151.151522	1		refer to maintenance	MV248	Secondary	LOW	\$ -
OB100V	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.917158	151.152546	1		notify business/property owner	MV249	Secondary	LOW	\$ -
OB100V	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.917744	151.153603	1		refer to maintenance	MV241	Tertiary	LOW	\$ -
OB101	Holiden Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895572	151.125079	1		notify business/property owner	AF69	Tertiary	LOW	\$ -
OB1014	Abbermarke Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.896291	151.173992	1		notify business/property owner	NE1	Secondary	LOW	\$ -
OB1014	Abbermarke Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.896004	151.17488	1		refer to maintenance	NE1	Secondary	LOW	\$ -
OB1014	Abbermarke Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.895962	151.174671	1		no action	NE1	Secondary	LOW	\$ -
OB1014	Abbermarke Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895911	151.175226	1		refer to maintenance	NE4	Secondary	LOW	\$ -
OB1014	Abbermarke Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895559	151.175379	1		refer to maintenance	NE4	Secondary	LOW	\$ -
OB1014	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation - property	-33.903295	151.177893	1		notify business/property owner	NE10	Primary	LOW	\$ -
OB1014	Alice Street	Newtown	Regional Road	obstruction	bus shelter narrows footpath	-33.903486	151.177446	1		relocate or remove bus shelter	NE10	Primary	LOW	\$ 5,000
OB1014	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.904232	151.175209	1		notify business/property owner	NE7	Secondary	LOW	\$ -
OB1014	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.904716	151.173974	1		notify business/property owner	NE6	Secondary	LOW	\$ -
OB1014	Alice Street	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.904719	151.173856	1		notify business/property owner	NE6	Secondary	LOW	\$ -
OB102	Holiden Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893627	151.125158	1		notify business/property owner	AF67	Secondary	LOW	\$ -
OB102	Alice Street	Newtown	Regional Road	obstruction	concrete pillar narrows footpath	-33.904721	151.173484	1		no action	NE6	Secondary	LOW	\$ -
OB102	Bailey Street	Newtown	Local Road	obstruction	bins narrows footpath	-33.899605	151.177372	1		no action	NE59	Secondary	LOW	\$ -
OB102	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897561	151.177834	1		no action	NE15	Primary	LOW	\$ -
OB102	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897584	151.177674	1		no action	NE15	Primary	LOW	\$ -
OB102	Bedford Street	Newtown	Local Road	obstruction	concrete footing narrows footpath	-33.897662	151.177503	1		install contrasting threshold	NE15	Primary	LOW	\$ 5,000
OB102	Bedford Street	Newtown	Local Road	obstruction	trees narrows footpath	-33.897553	151.176771	1		no action	NE20	Secondary	LOW	\$ -
OB102	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897442	151.176194	1		no action	NE20	Secondary	LOW	\$ -
OB102	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897398	151.176936	1		no action	NE20	Secondary	LOW	\$ -
OB102	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897218	151.175447	1		no action	NE19	Secondary	LOW	\$ -
OB102	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897179	151.175317	1		no action	NE19	Secondary	LOW	\$ -
OB103	Liverpool Road	Ashfield	State Road	obstruction	double pole signpost narrows footpath	-33.899908	151.131028	1		review and relocate double pole signpost	AF68	Primary	LOW	\$ 500
OB103	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.897174	151.175317	1		no action	NE19	Secondary	LOW	\$ -
OB103	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.896573	151.174071	1		no action	NE18	Secondary	LOW	\$ -
OB103	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.896521	151.173977	1		no action	NE18	Secondary	LOW	\$ -
OB103	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.89599	151.17317	1		no action	NE17	Secondary	LOW	\$ -
OB103	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.895918	151.173065	1		no action	NE17	Secondary	LOW	\$ -
OB103	Bedford Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.895582	151.172425	1		no action	NE16	Secondary	LOW	\$ -
OB103	Bedford Street	Newtown	Local Road	obstruction	signpost narrows footpath	-33.895359	151.171898	1		relocate signpost	NE16	Secondary	LOW	\$ 300
OB103	Bedford Street	Newtown	Local Road	obstruction	power pole narrows footpath	-33.895289	151.171716	1		no action	NE16	Secondary	LOW	\$ -
OB103	Edgeware Road	Newtown	Regional Road	obstruction	overhanging vegetation - property	-33.894264	151.173411	1		notify business/property owner	NE23	Primary	LOW	\$ -
OB103	Edgeware Road	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.906801	151.174292	1		notify business/property owner	NE32	Primary	LOW	\$ -
OB104	Liverpool Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.887616	151.121471	1		notify business/property owner	AF106	Primary	LOW	\$ -
OB104	Liverpool Road	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.897411	151.174611	1		notify business/property owner	NE21	Primary	LOW	\$ -
OB104	Edgeware Road	Newtown	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.906016	151.173749	1		notify business/property owner	NE31	Primary	LOW	\$ -
OB104	Edgeware Road	Newtown	State Road	obstruction	store stand narrows footpath	-33.888111	151.177685	1		notify business/property owner	NE34	Primary	LOW	\$ -
OB104	King Street	Newtown	Local Road	obstruction	storefront narrows footpath - property	-33.904764	151.180484	1		notify business/property owner	NE55	Primary	LOW	\$ -
OB104	Lennox Street	Newtown	Local Road	obstruction	power pole narrows footpath	-33.895208	151.18061	1		no action	NE41	Secondary	LOW	\$ -
OB104	Lennox Street	Newtown	Local Road	obstruction	empty pit narrows footpath	-33.895191	151.180457	1		install new footpath	NE41	Secondary	LOW	\$ 200
OB104	Lennox Street	Newtown	Local Road	obstruction	overhanging vegetation - property	-33.895788	151.178799	1		notify business/property owner	NE42	Secondary	LOW	\$ -
OB104	Lord Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.907477	151.178559	1		no action	NE28	Primary	LOW	\$ -
OB104	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.898797	151.176582	1		notify business/property owner	NE58	Secondary	LOW	\$ -
OB104	Station Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.898909	151.176625	1		no action	NE58	Secondary	LOW	\$ -
OB105	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation	-33.894628	151.11885	1		refer to maintenance	AF141	Secondary	LOW	\$ -
OB105	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895305	151.176773	1		refer to maintenance	NE58	Secondary	LOW	\$ -
OB105	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.894936	151.176874	1		refer to maintenance	NE59	Secondary	LOW	\$ -
OB105	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895583	151.176915	1		refer to maintenance	NE59	Secondary	LOW	\$ -
OB105	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899723	151.176936	1		refer to maintenance	NE59	Secondary	LOW	\$ -
OB105	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.899714	151.176999	1		notify business/property owner	NE59	Secondary	LOW	\$ -
OB105	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899762	151.177037	1		refer to maintenance	NE59	Secondary	LOW	\$ -
OB105	Station Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.899526	151.176819	1		notify business/property owner	NE59	Secondary	LOW	\$ -
OB105	Wells Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.905451	151.179712	1		no action	NE60	Secondary	LOW	\$ -
OB105	Wells Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.905754	151.179773	1		no action	NE65	Secondary	LOW	\$ -
OB105	Wells Street	Newtown	Local Road	obstruction	tree narrows footpath	-33.906307	151.177031	1		no action	NE63	Secondary	LOW	\$ -
OB106	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.894117	151.117845	1		notify business/property owner	AF140	Secondary	LOW	\$ -
OB106	Wells Street	Newtown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.9087	151.17575	1		notify business/property owner	NE62	Secondary	LOW	\$ -
OB106	Wells Street	Newtown	Local Road	obstruction	signpost narrows footpath	-33.896285	151.175402	1		relocate signpost	NE61	Secondary	LOW	\$ 300
OB106	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892422	151.156884	1		notify business/property owner	PE11	Secondary	LOW	\$ -
OB106	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892534	151.152327	1		refer to maintenance	PE7	Tertiary	LOW	\$ -
OB106	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89255	151.152499	1		refer to maintenance	PE6	Tertiary	LOW	\$ -
OB106	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892694	151.152621	1		refer to maintenance	PE7	Tertiary	LOW	\$ -
OB106	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892889	151.151465	1		notify business/property owner	PE7	Tertiary	LOW	\$ -
OB106	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.893042	151.150965	1		refer to maintenance	PE5	Secondary	LOW	\$ -
OB106	Brighton Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900385	151.153373	1		notify business/property owner	PE19	Secondary	LOW	\$ -
OB106	Brighton Street	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.900082	151.153422	1		notify business/property owner	PE26	Secondary	LOW	\$ -
OB107	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.894484	151.118235	1		notify business/property owner	AF141	Secondary	LOW	\$ -
OB107	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.897868	151.153801	1		notify business/property owner	PE24	Secondary	LOW	\$ -
OB107	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.898348	151.153514	1		notify business/property owner	PE24	Secondary	LOW	\$ -
OB107	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.899184	151.153455	1		notify business/property owner	PE25	Primary	LOW	\$ -
OB107	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.89984	151.153574	1		notify business/property owner	PE26	Secondary	LOW	\$ -
OB107	Livingstone Road	Petersham	State Road	obstruction	overhanging vegetation - property	-33.899741	151.153598	1		notify business/property owner	PE26	Secondary	LOW	\$ -
OB107	New Centenary Road	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.895924	151.155114	1		notify business/property owner	PE40	Primary	LOW	\$ -
OB107	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890254	151.154289	1		notify business/property owner	PE41	Primary	LOW	\$ -
OB107	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890545	151.154438	1		notify business/property owner	PE42	Secondary	LOW	\$ -
OB107	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation - property	-33.89024	151.154447	1		notify business/property owner	PE41	Primary	LOW	\$ -
OB107	Palace Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890862	151.154587	1		notify business/property owner	PE41	Primary	LOW	\$ -
OB108	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.894762	151.118842	1		notify business/property owner	AF141	Secondary	LOW	\$ -
OB108	Railway Terrace	Petersham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.89415	151.150266	1		notify business/property owner	PE48	Primary	LOW	\$ -
OB108	Terminus Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893439								

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB1082	Terminus Street	Petersham	Local Road	obstruction	tree narrow footpath	-33.893527	151.156418	1	1	no action	PE58	Primary	LOW	\$ -
OB1083	Terminus Street	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89349	151.156705	1	1	notify business/property owner	PE58	Primary	LOW	\$ -
OB1084	Refugee Street	Petersham	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.894336	151.155185	1	1	notify business/property owner	PE54	Secondary	LOW	\$ -
OB1085	West Street	Petersham	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.893343	151.153941	1	1	notify business/property owner	PE55	Primary	LOW	\$ -
OB1086	York Crescent	Petersham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893485	151.158018	1	1	notify business/property owner	PE21	Secondary	LOW	\$ -
OB1087	York Crescent	Petersham	Local Road	obstruction	overhanging vegetation	-33.893736	151.158527	1	1	refer to maintenance	PE21	Secondary	LOW	\$ -
OB1088	York Crescent	Petersham	Local Road	obstruction	damaged fence narrows footpath	-33.893824	151.158763	1	1	notify property owner	SM15	Secondary	LOW	\$ -
OB1089	Anzac Bridge	Rozelle	State Road	obstruction	light post narrows footpath	-33.868003	151.182266	1	1	relocate light post	RO8	Secondary	LOW	\$ 10,000
OB1090	Anzac Bridge	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.894901	151.119061	1	1	no action	AF141	Secondary	LOW	\$ -
OB1091	Anzac Bridge	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.868175	151.181154	1	1	refer to maintenance	RO7	Secondary	LOW	\$ -
OB1092	Darling Street	Rozelle	Regional Road	obstruction	bus shelter narrows footpath	-33.861341	151.170331	1	1	relocate or remove bus shelter	RO24	Primary	LOW	\$ 5,000
OB1093	Darling Street	Rozelle	Regional Road	obstruction	storefront narrows footpath - property	-33.86272	151.170818	1	1	notify business/property owner	RO18	Primary	LOW	\$ -
OB1094	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869165	151.169108	1	1	notify business/property owner	RO31	Tertiary	LOW	\$ -
OB1095	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869115	151.16917	1	1	notify business/property owner	RO31	Tertiary	LOW	\$ -
OB1096	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.867394	151.168942	1	1	notify business/property owner	RO30	Secondary	LOW	\$ -
OB1097	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.867264	151.168548	1	1	notify business/property owner	RO33	Secondary	LOW	\$ -
OB1098	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.866662	151.168222	1	1	notify business/property owner	RO29	Secondary	LOW	\$ -
OB1099	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation - property	-33.866295	151.168088	1	1	notify business/property owner	RO29	Secondary	LOW	\$ -
OB1100	Denison Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87025	151.170424	1	1	notify business/property owner	RO28	Tertiary	LOW	\$ -
OB111	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883984	151.172807	1	1	notify business/property owner	AN71	Primary	LOW	\$ -
OB110	Milton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.894973	151.116202	1	1	notify business/property owner	AF142	Secondary	LOW	\$ -
OB1102	Denison Street	Rozelle	Local Road	obstruction	vehicle narrows footpath	-33.869586	151.169575	6	22	install new wheel stops	RO28	Tertiary	LOW	\$ 9,000
OB1103	Denison Street	Rozelle	Local Road	obstruction	vehicle narrows footpath	-33.869551	151.169796	22	22	install new wheel stops	RO28	Tertiary	LOW	\$ 33,000
OB1102	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.865705	151.171801	1	1	refer to maintenance	RO36	Primary	LOW	\$ -
OB1103	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.865882	151.171464	1	1	notify business/property owner	RO36	Primary	LOW	\$ -
OB1104	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.866653	151.16997	1	1	notify business/property owner	RO35	Secondary	LOW	\$ -
OB1105	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.867314	151.169144	1	1	notify business/property owner	RO35	Secondary	LOW	\$ -
OB1106	Evans Street	Rozelle	Local Road	obstruction	tree narrows footpath	-33.867269	151.169179	1	1	no action	RO35	Secondary	LOW	\$ -
OB1107	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.866936	151.169518	1	1	notify business/property owner	RO35	Secondary	LOW	\$ -
OB1108	Evans Street	Rozelle	Local Road	obstruction	tree narrows footpath	-33.866971	151.169586	1	1	no action	RO35	Secondary	LOW	\$ -
OB1109	Evans Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.865704	151.171534	1	1	refer to maintenance	RO36	Primary	LOW	\$ -
OB111	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.890877	151.126553	1	1	notify business/property owner	AF121	Primary	LOW	\$ -
OB111	Belconn Street	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868427	151.172838	1	1	notify business/property owner	RO40	Secondary	LOW	\$ -
OB111	James Craig Road	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.870032	151.175247	1	1	no action	RO44	Secondary	LOW	\$ -
OB111	James Craig Road	Rozelle	Local Road	obstruction	vehicles narrows footpath	-33.870094	151.175291	1	1	no action	RO44	Secondary	LOW	\$ -
OB111	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868614	151.172596	1	1	notify business/property owner	RO41	Secondary	LOW	\$ -
OB111	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868621	151.172596	1	1	notify business/property owner	RO41	Secondary	LOW	\$ -
OB111	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.868328	151.175364	1	1	notify business/property owner	RO44	Secondary	LOW	\$ -
OB111	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.868535	151.174467	1	1	refer to maintenance	RO42	Secondary	LOW	\$ -
OB111	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.870921	151.170159	1	1	refer to maintenance	RO45	Secondary	LOW	\$ -
OB111	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.871061	151.169977	1	1	refer to maintenance	RO45	Secondary	LOW	\$ -
OB111	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.871252	151.169666	1	1	refer to maintenance	RO45	Secondary	LOW	\$ -
OB112	Norton Street	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.890318	151.124906	1	1	no action	AF117	Primary	LOW	\$ -
OB112	Livfield Road	Rozelle	Regional Road	obstruction	power pole narrows path	-33.871568	151.168666	1	1	no action	RO45	Secondary	LOW	\$ -
OB112	Livfield Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.870915	151.170771	1	1	refer to maintenance	LF98	Secondary	LOW	\$ -
OB112	Manning Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.86267	151.164305	1	1	refer to maintenance	RO50	Tertiary	LOW	\$ -
OB112	Manning Street	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.864892	151.165975	1	1	no action	RO49	Secondary	LOW	\$ -
OB112	Manning Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.865844	151.166525	1	1	notify business/property owner	RO52	Secondary	LOW	\$ -
OB112	Mulens Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.865304	151.176495	1	1	notify business/property owner	RO53	Secondary	LOW	\$ -
OB112	Mulens Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.865494	151.177023	1	1	notify business/property owner	RO55	Tertiary	LOW	\$ -
OB112	Mulens Street	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.865819	151.176886	1	1	notify business/property owner	RO58	Tertiary	LOW	\$ -
OB112	Robert Street	Rozelle	Regional Road	obstruction	power pole narrows footpath	-33.866528	151.175993	1	1	no action	RO57	Secondary	LOW	\$ -
OB112	Robert Street	Rozelle	Local Road	obstruction	vehicles and signpost narrows footpath	-33.865519	151.17795	1	1	relocate signpost	RO61	Tertiary	LOW	\$ 300
OB113	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.890113	151.124261	1	1	notify business/property owner	AF120	Primary	LOW	\$ -
OB113	Robert Street	Rozelle	Local Road	obstruction	damaged signpost narrows footpath	-33.865815	151.17752	1	1	install new signpost	RO58	Tertiary	LOW	\$ 250
OB113	Robert Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.864089	151.1804	1	1	refer to maintenance	RO59	Tertiary	LOW	\$ -
OB113	Robert Street	Rozelle	Local Road	obstruction	overhanging vegetation narrows footpath	-33.864136	151.180326	1	1	refer to maintenance	RO59	Tertiary	LOW	\$ -
OB113	Robert Street	Rozelle	Local Road	obstruction	vehicle narrows footpath	-33.865201	151.178691	1	1	no action	RO61	Tertiary	LOW	\$ -
OB113	Robert Street	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.865306	151.178573	1	1	no action	RO61	Tertiary	LOW	\$ -
OB113	Robert Street	Rozelle	Local Road	obstruction	power pole narrows footpath	-33.865493	151.177902	1	1	no action	RO68	Tertiary	LOW	\$ -
OB113	Terry Street	Rozelle	Local Road	obstruction	concrete pillar narrows footpath	-33.860645	151.168899	1	1	no action	RO68	Secondary	LOW	\$ -
OB113	Terry Street	Rozelle	Local Road	obstruction	electricity box narrows footpath	-33.860716	151.169348	1	1	no action	RO68	Secondary	LOW	\$ -
OB113	The Crescent	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.869623	151.173256	1	1	refer to maintenance	RO44	Secondary	LOW	\$ -
OB113	Victoria Road	Rozelle	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.860984	151.175791	1	1	refer to maintenance	RO54	Secondary	LOW	\$ -
OB114	Victoria Road	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.869834	151.123812	1	1	no action	AF120	Primary	LOW	\$ -
OB114	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.869699	151.175057	1	1	refer to maintenance	RO74	Secondary	LOW	\$ -
OB114	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.868175	151.173975	1	1	refer to maintenance	RO74	Secondary	LOW	\$ -
OB114	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.86713	151.175253	1	1	relocate signpost	RO70	Secondary	LOW	\$ 300
OB114	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.866965	151.175495	1	1	relocate signpost	RO67	Secondary	LOW	\$ 300
OB114	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.867299	151.175741	1	1	relocate signpost	RO70	Secondary	LOW	\$ 300
OB114	Victoria Road	Rozelle	State Road	obstruction	signpost narrows footpath	-33.86736	151.175906	1	1	relocate signpost	RO70	Secondary	LOW	\$ 300
OB114	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath	-33.867444	151.175894	1	1	refer to maintenance	RO70	Secondary	LOW	\$ -
OB114	Victoria Road	Rozelle	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.867573	151.176024	1	1	notify business/property owner	RO70	Secondary	LOW	\$ -
OB114	Victoria Road	Rozelle	State Road	obstruction	light post narrows footpath	-33.867585	151.176033	1	1	relocate light post	RO70	Secondary	LOW	\$ 10,000
OB114	Campbell Street	St Peters	Regional Road	obstruction	vehicle narrows footpath	-33.912418	151.175064	1	1	no action	SP2	Secondary	LOW	\$ -
OB115	Norton Street	Ashfield	Regional Road	obstruction	power pole narrows footpath	-33.869745	151.12357	1	1	no action	AF120	Primary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912216	151.178483	1	1	refer to maintenance	SP6	Secondary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	electricity box narrows footpath	-33.912271	151.178413	1	1	no action	SP6	Secondary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	power pole narrows footpath	-33.912421	151.178455	1	1	no action	SP6	Secondary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.912441	151.17838	1	1	notify business/property owner	SP6	Secondary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	power pole narrows footpath	-33.912985	151.177889	1	1	no action	SP7	Secondary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913099	151.177724	1	1	notify business/property owner	SP7	Secondary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	power pole narrows footpath	-33.91316	151.177736	1	1	no action	SP7	Secondary	LOW	\$ -
OB115	Church Street	St Peters	Local Road	obstruction	electricity box narrows footpath	-33.913377	151.177539	1	1	no action	SP7	Secondary	LOW	\$ -
OB115	Edith Street	St Peters	Local Road	obstruction	vehicle narrows footpath	-33.912538	151.173465	1	1	no action	SP35	Tertiary	LOW	\$ -
OB115	Edith Street	St Peters	Local Road	obstruction	lan narrows footpath	-33.912903	151.173822	1	1	no action	SP35	Tertiary	LOW	\$ -
OB116	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.899642	151.12321	1	1	notify business/property owner	AF119	Primary	LOW	\$ -
OB116	Edith Street	St Peters	Local Road	obstruction	overhanging vegetation - property	-33.914377	151.175259	1	1	notify business/property owner	SP21	Primary	LOW	\$ -
OB116	Edith Street	St Peters	Local Road	obstruction	tree narrows footpath	-33.914607	151.175668	1	1	no action	SP21	Primary	LOW	\$ -
OB116	Edith Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914665	151.175668	1	1	notify business/property owner	SP21	Primary	LOW	\$ -
OB116	King Street	St Peters	State Road	obstruction	signpost narrows footpath	-33.907704	151.181318	1	1	relocate signpost	SP11	Primary	LOW	\$ 300

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB1168	Princes Highway	St Peters	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.913733	151.178012	1		notify business/property owner	SP18	Primary	LOW	\$ -
OB1169	Princes Highway	St Peters	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.911839	151.179742	1		notify business/property owner	SP15	Secondary	LOW	\$ -
OB1169a	Peters Street	St Peters	Local Road	obstruction	tree narrows footpath	-33.911931	151.177513	1		no action	SP31	Secondary	LOW	\$ -
OB1169b	Peters Street	St Peters	Local Road	obstruction	overhanging vegetation - property	-33.912075	151.177491	1		notify business/property owner	SP31	Secondary	LOW	\$ -
OB1171	Norton Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.889477	151.12283	1		notify business/property owner	AF119	Primary	LOW	\$ -
OB1170a	St Peters Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912302	151.177289	1		refer to maintenance	SP30	Secondary	LOW	\$ -
OB1171b	St Peters Street	St Peters	Local Road	obstruction	overhanging vegetation - property	-33.912475	151.177064	1		notify business/property owner	SP30	Secondary	LOW	\$ -
OB1172a	St Peters Street	St Peters	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912768	151.17686	1		refer to maintenance	SP30	Secondary	LOW	\$ -
OB1173	Unwins Bridge Road	St Peters	Regional Road	obstruction	overhanging vegetation - property	-33.910458	151.175154	1		notify business/property owner	SP32	Secondary	LOW	\$ -
OB1174	Unwins Bridge Road	St Peters	Regional Road	obstruction	bins narrows footpath	-33.910486	151.175178	1		no action	SP32	Secondary	LOW	\$ -
OB1175	Auburn Street	Stammore	Local Road	obstruction	overgrown vegetation	-33.895287	151.161547	1		refer to maintenance	SM14	Primary	LOW	\$ -
OB1176	Perival Road	Stammore	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890427	151.165282	1		notify business/property owner	SM29	Primary	LOW	\$ -
OB1177	Carlton Crescent	Summer Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.889789	151.131868	1		notify business/property owner	SH8	Secondary	LOW	\$ -
OB1178	Carlton Crescent	Summer Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.889886	151.13269	1		notify business/property owner	SH8	Secondary	LOW	\$ -
OB1179	Carlton Crescent	Summer Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.890184	151.137799	1		notify business/property owner	SH14	Primary	LOW	\$ -
OB118	Norton Street	Ashfield	Regional Road	obstruction	signpost narrows footpath	-33.890277	151.124981	1		relocate signpost	AF117	Primary	LOW	\$ 300
OB118a	Clissold Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89585	151.132192	1		notify business/property owner	AF46	Tertiary	LOW	\$ -
OB118b	Clissold Street	Summer Hill	Local Road	obstruction	signposts narrows footpath	-33.895881	151.132265	1		relocate signpost	AF46	Tertiary	LOW	\$ 300
OB118c	Groenover Crescent	Summer Hill	Local Road	obstruction	signpost narrows footpath	-33.890614	151.140383	1		relocate signpost	SH22	Secondary	LOW	\$ 300
OB118d	Groenover Crescent	Summer Hill	Local Road	obstruction	signpost narrows footpath	-33.889958	151.138438	1		relocate signpost	SH20	Primary	LOW	\$ 300
OB118e	Groenover Crescent	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.889997	151.138556	1		refer to maintenance	SH20	Primary	LOW	\$ -
OB118f	Groenover Crescent	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.889448	151.134094	1		notify business/property owner	SH29	Secondary	LOW	\$ -
OB118g	Hardie Avenue	Summer Hill	Local Road	obstruction	signpost narrows footpath	-33.891454	151.137235	1		relocate signpost	SH34	Primary	LOW	\$ 300
OB118h	Henson Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89641	151.134636	1		notify business/property owner	SH35	Secondary	LOW	\$ -
OB118i	Henson Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.896975	151.134589	1		refer to maintenance	SH35	Secondary	LOW	\$ -
OB118j	Herbert Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.896396	151.134144	1		refer to maintenance	SH37	Secondary	LOW	\$ -
OB119	Norton Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.891536	151.131496	1		notify business/property owner	AF118	Primary	LOW	\$ -
OB119a	Herbert Street	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.896362	151.133802	1		notify business/property owner	SH37	Secondary	LOW	\$ -
OB119b	Herbert Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89633	151.133231	1		refer to maintenance	SH37	Secondary	LOW	\$ -
OB119c	Herbert Street	Summer Hill	Local Road	obstruction	tree narrows footpath	-33.896318	151.13286	1		no action	SH37	Secondary	LOW	\$ -
OB119d	James Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897406	151.135099	1		notify business/property owner	SH38	Secondary	LOW	\$ -
OB119e	James Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.897379	151.134777	1		refer to maintenance	SH38	Secondary	LOW	\$ -
OB119f	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895019	151.133776	1		notify business/property owner	SH41	Secondary	LOW	\$ -
OB119g	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895033	151.134017	1		notify business/property owner	SH41	Secondary	LOW	\$ -
OB119h	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895404	151.136291	1		refer to maintenance	SH44	Primary	LOW	\$ -
OB119i	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895484	151.136097	1		notify business/property owner	SH44	Primary	LOW	\$ -
OB119j	Junction Road	Summer Hill	Local Road	obstruction	concrete pillar narrows footpath	-33.895484	151.137113	1		no action	SH41	Primary	LOW	\$ -
OB12	Bignell Lane	Amundale	Local Road	obstruction	vehicles narrows footpath	-33.886518	151.175276	1		no action	AN19	Secondary	LOW	\$ -
OB120	Old Canterbury Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.904589	151.128531	1		notify business/property owner	AF130	Primary	LOW	\$ -
OB120a	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895394	151.136947	1		refer to maintenance	SH39	Secondary	LOW	\$ -
OB120b	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895162	151.134446	1		notify business/property owner	SH41	Secondary	LOW	\$ -
OB120c	Junction Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895072	151.132938	1		notify business/property owner	SH40	Secondary	LOW	\$ -
OB120d	Liverpool Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.888623	151.134166	1		notify business/property owner	AF95	Primary	LOW	\$ -
OB120e	Nowanra Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893803	151.138676	1		notify business/property owner	SH80	Secondary	LOW	\$ -
OB120f	Nowanra Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894888	151.138665	1		notify business/property owner	SH83	Secondary	LOW	\$ -
OB120g	Nowanra Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894937	151.138693	1		notify business/property owner	SH83	Secondary	LOW	\$ -
OB120h	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.896176	151.137562	1		notify business/property owner	SH86	Primary	LOW	\$ -
OB120i	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.896386	151.138407	1		notify business/property owner	SH86	Primary	LOW	\$ -
OB120j	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation - property	-33.893937	151.133269	1		notify business/property owner	SH81	Secondary	LOW	\$ -
OB121	Old Canterbury Road	Ashfield	State Road	obstruction	overhanging vegetation	-33.903103	151.129889	1		refer to maintenance	AF129	Primary	LOW	\$ -
OB121a	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation - property	-33.898725	151.133994	1		notify business/property owner	SH80	Tertiary	LOW	\$ -
OB121b	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath	-33.898613	151.134177	1		refer to maintenance	SH80	Tertiary	LOW	\$ -
OB121c	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation	-33.8981	151.134903	1		refer to maintenance	SH89	Tertiary	LOW	\$ -
OB121d	Old Canterbury Road	Summer Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.897788	151.135326	1		notify business/property owner	SH89	Tertiary	LOW	\$ -
OB121e	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891528	151.132467	1		notify business/property owner	SH85	Secondary	LOW	\$ -
OB121f	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.891034	151.132449	1		notify business/property owner	SH85	Secondary	LOW	\$ -
OB121g	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890204	151.132287	1		notify business/property owner	SH84	Secondary	LOW	\$ -
OB121h	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890225	151.13239	1		notify business/property owner	SH84	Secondary	LOW	\$ -
OB121i	Prospect Road	Summer Hill	Local Road	obstruction	double pole signpost narrows footpath	-33.89578	151.13235	1		review and relocate double pole signpost	SH70	Secondary	LOW	\$ 500
OB121j	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895662	151.132344	1		notify business/property owner	SH70	Secondary	LOW	\$ -
OB122	Orpington Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.885536	151.131952	1		notify business/property owner	AF136	Secondary	LOW	\$ -
OB122a	Prospect Road	Summer Hill	Local Road	obstruction	double pole signpost narrows footpath	-33.894341	151.132353	1		review and relocate double pole signpost	SH89	Secondary	LOW	\$ 500
OB122b	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892446	151.132376	1		notify business/property owner	SH89	Secondary	LOW	\$ -
OB122c	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893071	151.132456	1		notify business/property owner	SH87	Secondary	LOW	\$ -
OB122d	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895082	151.132458	1		notify business/property owner	SH70	Secondary	LOW	\$ -
OB122e	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.895917	151.132485	1		notify business/property owner	SH71	Tertiary	LOW	\$ -
OB122f	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897466	151.1321	1		notify business/property owner	SH72	Tertiary	LOW	\$ -
OB122g	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.896094	151.132324	1		notify business/property owner	SH71	Tertiary	LOW	\$ -
OB122h	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.898381	151.132188	1		refer to maintenance	SH73	Secondary	LOW	\$ -
OB122i	Prospect Road	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.900762	151.131985	1		refer to maintenance	AF128	Primary	LOW	\$ -
OB122j	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation - property	-33.892613	151.141482	1		notify business/property owner	SH88	Secondary	LOW	\$ -
OB123	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.887778	151.128204	1		notify business/property owner	AF62	Primary	LOW	\$ -
OB123a	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892587	151.143629	1		refer to maintenance	SH89	Secondary	LOW	\$ -
OB123b	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89275	151.143553	1		refer to maintenance	SH89	Secondary	LOW	\$ -
OB123c	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892887	151.141399	1		notify business/property owner	SH88	Secondary	LOW	\$ -
OB123d	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.892655	151.141207	1		refer to maintenance	SH88	Secondary	LOW	\$ -
OB123e	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892398	151.139673	1		notify business/property owner	SH87	Secondary	LOW	\$ -
OB123f	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89228	151.139623	1		notify business/property owner	SH86	Secondary	LOW	\$ -
OB123g	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891628	151.135691	1		notify business/property owner	SH82	Secondary	LOW	\$ -
OB123h	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891682	151.133357	1		notify business/property owner	SH80	Secondary	LOW	\$ -
OB123i	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.891717	151.133095	1		refer to maintenance	SH80	Secondary	LOW	\$ -
OB123j	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891688	151.132517	1		notify business/property owner	SH80	Secondary	LOW	\$ -
OB124	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894885	151.11944	1		notify business/property owner	AF142	Secondary	LOW	\$ -
OB124a	Smith Street	Summer Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.891625	151.132686	1		refer to maintenance	SH80	Secondary	LOW	\$ -
OB124b	George Street	Sydenham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914928	151.167396	1		refer to maintenance	SY3	Secondary	LOW	\$ -
OB124c	George Street	Sydenham	Local Road	obstruction	overhanging vegetation	-33.915137	151.167192	1		refer to maintenance	SY3	Secondary	LOW	\$ -
OB124d	George Street	Sydenham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.915055	151.1677	1		notify business/property owner	SY3	Secondary	LOW	\$ -
OB124e	George Street	Sydenham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914883	151.167527	1		notify business/property owner	SY3	Secondary	LOW	\$ -
OB124f	Georgina Road	Sydenham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.917867	151.167932	1		notify business/property owner	SY8	Primary	LOW	\$ -
OB124g	Georgina Road	Sydenham	State Road	obstruction	traffic post narrows footpath	-33.917816	151.167886	1		no action	SY8	Primary	LOW	\$ 200
OB124h	Griffins Street	Tempe	Local Road	obstruction	signpost narrows footpath	-33.925114	151.156541	1						

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB125	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894981	151.119999	1	1	notify business/property owner	AF142	Secondary	LOW	\$ -
OB125a	Griffins Street	Tempe	Local Road	obstruction	tree narrows footpath	-33.925553	151.15624	1	1	no action	TE32	Secondary	LOW	\$ -
OB125b	Griffins Street	Tempe	Local Road	obstruction	tree narrows footpath	-33.925648	151.156208	1	1	no action	TE32	Secondary	LOW	\$ -
OB125c	Princes Highway	Tempe	State Road	obstruction	power pole narrows footpath	-33.920511	151.167822	1	1	no action	SP29	Secondary	LOW	\$ -
OB125d	Princes Highway	Tempe	State Road	obstruction	overhanging vegetation narrows footpath	-33.927547	151.158059	1	1	refer to maintenance	TE30	Secondary	LOW	\$ -
OB125d	Princes Highway	Tempe	State Road	obstruction	power pole narrows footpath	-33.927121	151.158386	1	1	no action	TE34	Primary	LOW	\$ -
OB125e	Richardson Crescent	Tempe	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.922736	151.155358	1	1	refer to maintenance	MV175	Secondary	LOW	\$ -
OB125e	Richardson Crescent	Tempe	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.92238	151.156466	1	1	refer to maintenance	MV175	Secondary	LOW	\$ -
OB125f	Union Street	Tempe	Local Road	obstruction	vehicles narrows footpath	-33.922195	151.161165	1	1	no action	TE18	Secondary	LOW	\$ -
OB125g	Unwin Bridge Road	Tempe	Regional Road	obstruction	double pole signpost narrows footpath	-33.921341	151.159594	1	1	review and relocate double pole signpost	TE22	Secondary	LOW	\$ 500
OB125h	Unwin Bridge Road	Tempe	Regional Road	obstruction	double pole signpost narrows footpath	-33.919024	151.163982	1	1	review and relocate double pole signpost	TE27	Secondary	LOW	\$ 500
OB126	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895137	151.122247	1	1	notify business/property owner	AF139	Secondary	LOW	\$ -
OB126d	View Street	Tempe	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.92669	151.15808	1	1	notify business/property owner	TE34	Primary	LOW	\$ -
OB126d	View Street	Tempe	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.926658	151.158096	1	1	notify business/property owner	TE34	Primary	LOW	\$ -
OB127	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895134	151.122199	1	1	notify business/property owner	AF139	Secondary	LOW	\$ -
OB128	Palace Street	Ashfield	Local Road	obstruction	bench narrows footpath	-33.895169	151.122516	1	1	relocate or remove bench	AF139	Secondary	LOW	\$ 400
OB129	Palace Street	Ashfield	Local Road	obstruction	bus stop pole narrows footpath	-33.895146	151.122592	1	1	relocate bus stop pole	AF139	Secondary	LOW	\$ 400
OB13	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.8831	151.173334	1	1	notify business/property owner	AN12	Primary	LOW	\$ -
OB130	Palace Street	Ashfield	Local Road	obstruction	power pole narrows footpath	-33.895133	151.122703	1	1	no action	AF139	Secondary	LOW	\$ -
OB131	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.895129	151.12382	1	1	notify business/property owner	AF144	Secondary	LOW	\$ -
OB132	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895026	151.124001	1	1	notify business/property owner	AF144	Secondary	LOW	\$ -
OB133	Palace Street	Ashfield	Local Road	obstruction	signpost narrows footpath	-33.894923	151.123098	1	1	relocate signpost	AF139	Secondary	LOW	\$ 300
OB134	Palace Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894455	151.120881	1	1	notify business/property owner	AF143	Secondary	LOW	\$ -
OB135	Paramatta Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.879095	151.130993	1	1	notify business/property owner	HA68	Secondary	LOW	\$ -
OB136	Queen Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892168	151.127958	1	1	notify business/property owner	AF149	Secondary	LOW	\$ -
OB137	Queen Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.89144	151.12782	1	1	notify business/property owner	AF154	Secondary	LOW	\$ -
OB138	Queen Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893307	151.127704	1	1	notify business/property owner	AF153	Secondary	LOW	\$ -
OB139	Thomas Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.88709	151.120086	1	1	notify business/property owner	AF156	Secondary	LOW	\$ -
OB14	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.883419	151.173205	1	1	notify business/property owner	AN12	Primary	LOW	\$ -
OB140	Thomas Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.887152	151.120132	1	1	notify business/property owner	AF156	Secondary	LOW	\$ -
OB141	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892441	151.130109	1	1	notify business/property owner	AF162	Secondary	LOW	\$ -
OB142	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.895342	151.129945	1	1	refer to maintenance	AF159	Secondary	LOW	\$ -
OB143	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.89545	151.129935	1	1	refer to maintenance	AF159	Secondary	LOW	\$ -
OB144	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89545	151.129935	1	1	refer to maintenance	AF159	Secondary	LOW	\$ -
OB145	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.894504	151.129805	1	1	notify business/property owner	AF163	Secondary	LOW	\$ -
OB146	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893403	151.129939	1	1	notify business/property owner	AF163	Secondary	LOW	\$ -
OB147	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.893268	151.129989	1	1	notify business/property owner	AF163	Secondary	LOW	\$ -
OB148	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892735	151.129931	1	1	notify business/property owner	AF162	Secondary	LOW	\$ -
OB149	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.897991	151.129577	1	1	notify business/property owner	AF166	Secondary	LOW	\$ -
OB15	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883678	151.173037	1	1	notify business/property owner	AN11	Primary	LOW	\$ -
OB150	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.898977	151.129427	1	1	notify business/property owner	AF168	Secondary	LOW	\$ -
OB151	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.901045	151.129351	1	1	notify business/property owner	AF169	Secondary	LOW	\$ -
OB152	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.901359	151.129287	1	1	notify business/property owner	AF169	Secondary	LOW	\$ -
OB153	Victoria Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.901669	151.129276	1	1	notify business/property owner	AF170	Secondary	LOW	\$ -
OB154	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.886074	151.129074	1	1	notify business/property owner	AF1	Tertiary	LOW	\$ -
OB155	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881527	151.128487	1	1	notify business/property owner	AF1	Tertiary	LOW	\$ -
OB156	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881645	151.126458	1	1	notify business/property owner	AF1	Tertiary	LOW	\$ -
OB157	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880722	151.126627	1	1	notify business/property owner	AF4	Tertiary	LOW	\$ -
OB158	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879638	151.130274	1	1	notify business/property owner	AF5	Tertiary	LOW	\$ -
OB159	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879458	151.130554	1	1	notify business/property owner	AF6	Secondary	LOW	\$ -
OB16	Piper Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877905	151.166783	1	1	notify business/property owner	AN89	Secondary	LOW	\$ -
OB160	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879563	151.130451	1	1	notify business/property owner	AF5	Tertiary	LOW	\$ -
OB161	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.883119	151.12455	1	1	notify business/property owner	AF9	Secondary	LOW	\$ -
OB162	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.883949	151.123992	1	1	notify business/property owner	AF7	Secondary	LOW	\$ -
OB163	Alt Street	Ashfield	Local Road	obstruction	double pole signpost narrows footpath	-33.884888	151.123532	1	1	review and relocate double pole signpost	AF10	Primary	LOW	\$ 500
OB164	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.884835	151.123538	1	1	notify business/property owner	AF10	Primary	LOW	\$ -
OB165	Alt Street	Ashfield	Local Road	obstruction	double pole signpost narrows footpath	-33.882939	151.124803	1	1	review and relocate double pole signpost	AF9	Secondary	LOW	\$ 500
OB166	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881961	151.125673	1	1	notify business/property owner	AF8	Tertiary	LOW	\$ -
OB167	Alt Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882307	151.125093	1	1	notify business/property owner	AF8	Secondary	LOW	\$ -
OB168	Armstrong Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.889861	151.125377	1	1	refer to maintenance	AF12	Tertiary	LOW	\$ -
OB169	Armstrong Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899865	151.12685	1	1	refer to maintenance	AF11	Tertiary	LOW	\$ -
OB17	Pritchard Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.874028	151.170323	1	1	refer to maintenance	AN122	Secondary	LOW	\$ -
OB170	Armstrong Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.89948	151.125889	1	1	notify business/property owner	AF14	Tertiary	LOW	\$ -
OB171	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881233	151.13054	1	1	notify business/property owner	AF27	Tertiary	LOW	\$ -
OB172	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.88089	151.131251	1	1	notify business/property owner	AF28	Tertiary	LOW	\$ -
OB173	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882153	151.128731	1	1	notify business/property owner	AF25	Tertiary	LOW	\$ -
OB174	Bland Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882776	151.127598	1	1	notify business/property owner	AF24	Tertiary	LOW	\$ -
OB175	Bland Street	Ashfield	Local Road	obstruction	signpost narrows footpath	-33.884362	151.126219	1	1	relocate signpost	AF19	Secondary	LOW	\$ 300
OB176	Bland Street	Ashfield	Local Road	obstruction	signpost narrows footpath	-33.885005	151.126801	1	1	relocate signpost	AF18	Secondary	LOW	\$ 300
OB177	Bland Street	Ashfield	Local Road	obstruction	signpost narrows footpath	-33.885736	151.125241	1	1	relocate signpost	AF17	Primary	LOW	\$ 300
OB178	Brown Street	Ashfield	Local Road	obstruction	power pole narrows footpath	-33.87625	151.12564	1	1	further investigation required - footpath	AF31	Primary	LOW	\$ 5,000
OB179	Brown Street	Ashfield	Local Road	obstruction	power pole narrows footpath	-33.887963	151.125738	1	1	no action	AF31	Primary	LOW	\$ -
OB18	Rose Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877362	151.170608	1	1	refer to maintenance	AN85	Secondary	LOW	\$ -
OB180	Brown Street	Ashfield	Local Road	obstruction	bike locker narrows footpath	-33.887927	151.125861	1	1	relocate or remove bike locker	AF31	Primary	LOW	\$ 400
OB181	Charlotte Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.89458	151.127299	1	1	refer to maintenance	AF38	Secondary	LOW	\$ -
OB182	Charlotte Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.884921	151.127153	1	1	refer to maintenance	AF38	Secondary	LOW	\$ -
OB183	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation	-33.879924	151.12615	1	1	refer to maintenance	AF40	Tertiary	LOW	\$ -
OB184	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879833	151.126091	1	1	refer to maintenance	AF40	Tertiary	LOW	\$ -
OB185	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation	-33.87979	151.126044	1	1	refer to maintenance	AF40	Tertiary	LOW	\$ -
OB186	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879538	151.125879	1	1	refer to maintenance	AF44	Secondary	LOW	\$ -
OB187	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879367	151.125763	1	1	refer to maintenance	AF44	Secondary	LOW	\$ -
OB188	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879148	151.125656	1	1	notify business/property owner	AF44	Secondary	LOW	\$ -
OB189	Church Street	Ashfield	Local Road	obstruction	tree narrows footpath	-33.877873	151.124722	1	1	no action	AF42	Tertiary	LOW	\$ -
OB19	The Crescent	Annandale	State Road	obstruction	bus shelter narrows footpath	-33.874251	151.174881	1	1	relocate or remove bus shelter	AN88	Primary	LOW	\$ 5,000
OB190	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.85738	151.18021	1	1	refer to maintenance	BA3	Secondary	LOW	\$ -
OB191	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.8588	151.176001	1	1	notify business/property owner	BA3	Secondary	LOW	\$ -
OB192	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.858828	151.17601	1	1	refer to maintenance	BA1	Tertiary	LOW	\$ -
OB193	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.85879	151.175872	1	1	refer to maintenance	BA1	Tertiary	LOW	\$ -
OB194	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.858753	151.175402	1	1	notify business/property owner	BA1	Tertiary	LOW	\$ -
OB195	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.859382	151.174329	1	1	notify business/property owner	BA5	Secondary	LOW	\$ -
OB196	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property									

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB199	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.85892	151.176201	1	1	notify business/property owner	BA6	Secondary	LOW	\$ -
OB2	Chester Street	Amnandale	Local Road	obstruction	trees narrows footpath	-33.884181	151.173054	1	1	no action	AN31	Primary	LOW	\$ -
OB20	View Street	Amnandale	Local Road	obstruction	vehicles narrow crossing path	-33.873928	151.174763	1	1	install no stopping sign and signpost	AN68	Primary	LOW	\$ 300
OB200	Beattie Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.858948	151.175347	1	1	notify business/property owner	BA6	Secondary	LOW	\$ -
OB201	Booth Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880745	151.182057	1	1	refer to maintenance	BA14	Secondary	LOW	\$ -
OB202	Booth Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880645	151.182027	1	1	notify business/property owner	BA14	Secondary	LOW	\$ -
OB203	Booth Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.880257	151.181931	1	1	notify business/property owner	BA14	Secondary	LOW	\$ -
OB204	Booth Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.8597	151.182188	1	1	notify business/property owner	BA16	Primary	LOW	\$ -
OB205	Booth Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.880149	151.181805	1	1	notify business/property owner	BA14	Secondary	LOW	\$ -
OB206	Booth Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.859872	151.181915	1	1	notify business/property owner	BA16	Primary	LOW	\$ -
OB207	Bradford Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880407	151.182123	1	1	refer to maintenance	BA14	Secondary	LOW	\$ -
OB208	Buchanan Street	Balmain	Local Road	obstruction	overhanging vegetation	-33.863492	151.180298	1	1	refer to maintenance	BA17	Tertiary	LOW	\$ -
OB209	Buchanan Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.862401	151.18017	1	1	notify business/property owner	BA61	Secondary	LOW	\$ -
OB21	Trafalgar Street	Amnandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882383	151.171912	1	1	notify business/property owner	AN108	Secondary	LOW	\$ -
OB210	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.862602	151.180294	1	1	no action	BA18	Tertiary	LOW	\$ -
OB211	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.862552	151.180318	1	1	no action	BA18	Tertiary	LOW	\$ -
OB212	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.862736	151.180254	1	1	no action	BA18	Tertiary	LOW	\$ -
OB213	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.862852	151.180234	1	1	no action	BA18	Tertiary	LOW	\$ -
OB214	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.862901	151.180226	1	1	no action	BA18	Tertiary	LOW	\$ -
OB215	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.863073	151.180265	1	1	no action	BA18	Tertiary	LOW	\$ -
OB216	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.863122	151.180288	1	1	no action	BA18	Tertiary	LOW	\$ -
OB217	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.863203	151.180313	1	1	no action	BA17	Tertiary	LOW	\$ -
OB218	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.863446	151.180484	1	1	no action	BA17	Tertiary	LOW	\$ -
OB219	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.863563	151.180488	1	1	no action	BA17	Tertiary	LOW	\$ -
OB22	Trafalgar Street	Amnandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882257	151.172072	1	1	notify business/property owner	AN108	Secondary	LOW	\$ -
OB220	Buchanan Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.863819	151.180568	1	1	no action	BA17	Tertiary	LOW	\$ -
OB221	Buchanan Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.863601	151.180566	1	1	refer to maintenance	BA17	Tertiary	LOW	\$ -
OB222	Curtis Road	Balmain	Local Road	obstruction	tree narrows footpath	-33.857678	151.183552	1	1	no action	BA20	Primary	LOW	\$ -
OB223	Curtis Road	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.857619	151.183547	1	1	notify business/property owner	BA20	Primary	LOW	\$ -
OB224	Curtis Road	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.857638	151.183111	1	1	notify business/property owner	BA21	Secondary	LOW	\$ -
OB225	Curtis Road	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.856607	151.181794	1	1	notify business/property owner	BA22	Secondary	LOW	\$ -
OB226	Curtis Road	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.856021	151.181022	1	1	notify business/property owner	BA22	Secondary	LOW	\$ -
OB227	Curtis Road	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.855184	151.178683	1	1	notify business/property owner	BA19	Secondary	LOW	\$ -
OB228	Curtis Road	Balmain	Local Road	obstruction	storefront narrows footpath - property	-33.855507	151.180757	1	1	notify business/property owner	BA23	Secondary	LOW	\$ -
OB229	Darling Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.856053	151.173766	1	1	notify business/property owner	BA35	Secondary	LOW	\$ -
OB23	Bignell Lane	Amnandale	State Road	obstruction	vehicles narrows footpath	-33.886427	151.174837	1	1	no action	AN63	Secondary	LOW	\$ -
OB230	Darling Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.855888	151.174528	1	1	notify business/property owner	BA34	Primary	LOW	\$ 400
OB231	Darling Street	Balmain	Regional Road	obstruction	bench narrows footpath	-33.855889	151.175219	1	1	relocate or remove bench	BA34	Primary	LOW	\$ -
OB232	Darling Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.856381	151.177432	1	1	refer to maintenance	BA32	Primary	LOW	\$ -
OB233	Darling Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.856038	151.175387	1	1	notify business/property owner	BA34	Primary	LOW	\$ -
OB234	Darling Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.856038	151.174411	1	1	notify business/property owner	BA34	Primary	LOW	\$ -
OB235	Darling Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.856209	151.173774	1	1	notify business/property owner	BA35	Secondary	LOW	\$ -
OB236	Darling Street	Balmain	Regional Road	obstruction	bus shelter narrows footpath	-33.856281	151.1735	1	1	relocate or remove bus shelter	BA35	Secondary	LOW	\$ 5,000
OB237	Darling Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.8571	151.175422	1	1	notify business/property owner	BA36	Secondary	LOW	\$ -
OB238	Darling Street	Balmain	Regional Road	obstruction	storefront narrows footpath - property	-33.856734	151.175378	1	1	notify business/property owner	BA31	Primary	LOW	\$ -
OB239	Darling Street	Balmain	Local Road	obstruction	signage narrows footpath - property	-33.857674	151.182078	1	1	notify business owner	BA29	Primary	LOW	\$ -
OB24	Trafalgar Street	Amnandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882421	151.171988	1	1	notify business/property owner	AN108	Secondary	LOW	\$ -
OB240	Darling Street	Balmain	Local Road	obstruction	footpath leading narrows footpath	-33.857741	151.184533	1	1	notify business/property owner	BA29	Primary	LOW	\$ -
OB241	Darling Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.858166	151.183767	1	1	notify business/property owner	BA27	Primary	LOW	\$ -
OB242	Darling Street	Balmain	Local Road	obstruction	storefront narrows footpath - property	-33.858172	151.186089	1	1	notify business/property owner	BA26	Primary	LOW	\$ -
OB243	Darling Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.858188	151.186623	1	1	notify business/property owner	BA26	Primary	LOW	\$ -
OB244	Darling Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.857623	151.18131	1	1	refer to maintenance	BA29	Primary	LOW	\$ -
OB245	Darling Street	Balmain	Local Road	obstruction	storefront - property narrows footpath	-33.857754	151.182033	1	1	notify business owner	BA29	Primary	LOW	\$ -
OB246	Darval Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.859554	151.182539	1	1	notify business/property owner	BA39	Primary	LOW	\$ -
OB247	Darval Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.859604	151.183265	1	1	notify business/property owner	BA39	Primary	LOW	\$ -
OB248	Darval Street	Balmain	Local Road	obstruction	trees narrows footpath	-33.859546	151.183662	1	1	no action	BA39	Primary	LOW	\$ -
OB249	Eaton Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.858509	151.183775	1	1	notify business/property owner	BA40	Primary	LOW	\$ -
OB25	Trafalgar Street	Amnandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882532	151.171942	1	1	notify business/property owner	AN108	Secondary	LOW	\$ -
OB250	Hyam Street	Balmain	Local Road	obstruction	bollards narrows footpath	-33.86119	151.180859	1	1	relocate or remove bollard	BA42	Tertiary	LOW	\$ 2,500
OB251	Hyam Street	Balmain	Local Road	obstruction	light post narrows footpath	-33.861518	151.180382	1	1	relocate light post	BA43	Secondary	LOW	\$ 10,000
OB252	Jane Street	Balmain	Local Road	obstruction	power pole narrows footpath	-33.859767	151.184435	1	1	no action	BA45	Secondary	LOW	\$ -
OB253	Jane Street	Balmain	Local Road	obstruction	power pole narrows footpath	-33.859488	151.184388	1	1	no action	BA45	Secondary	LOW	\$ -
OB254	Jane Street	Balmain	Local Road	obstruction	power pole narrows footpath	-33.859898	151.184363	1	1	no action	BA44	Primary	LOW	\$ -
OB255	Jane Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.858624	151.184363	1	1	notify business/property owner	BA44	Primary	LOW	\$ -
OB256	Macquarie Terrace	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.854186	151.178007	1	1	notify business/property owner	BA46	Primary	LOW	\$ -
OB257	Macquarie Terrace	Balmain	Local Road	obstruction	power pole narrows footpath	-33.854185	151.177899	1	1	no action	BA46	Primary	LOW	\$ -
OB258	Montague Street	Balmain	Regional Road	obstruction	bike rack narrows footpath	-33.857059	151.177838	1	1	relocate or remove bike rack	BA47	Secondary	LOW	\$ 250
OB259	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.859401	151.177348	1	1	refer to maintenance	BA49	Secondary	LOW	\$ -
OB26	Trafalgar Street	Amnandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882685	151.171891	1	1	notify business/property owner	AN108	Secondary	LOW	\$ -
OB260	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.859688	151.177336	1	1	refer to maintenance	BA49	Secondary	LOW	\$ -
OB261	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.859568	151.177256	1	1	refer to maintenance	BA49	Secondary	LOW	\$ -
OB262	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.860525	151.177281	1	1	refer to maintenance	BA50	Primary	LOW	\$ -
OB263	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.860806	151.177168	1	1	notify business/property owner	BA50	Primary	LOW	\$ -
OB264	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.860845	151.177103	1	1	refer to maintenance	BA50	Primary	LOW	\$ -
OB265	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation - property	-33.861891	151.176498	1	1	notify business/property owner	BA51	Primary	LOW	\$ -
OB266	Mulens Street	Balmain	Regional Road	obstruction	bin narrows footpath - council	-33.861324	151.176759	1	1	further investigation required - bins	BA51	Primary	LOW	\$ -
OB267	Mulens Street	Balmain	Regional Road	obstruction	bus shelter and signpost narrows footpath	-33.862772	151.176459	1	1	relocate or remove bus shelter and signposts	BA52	Secondary	LOW	\$ 5,500
OB268	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.862277	151.176436	1	1	notify business/property owner	BA52	Secondary	LOW	\$ -
OB269	Mulens Street	Balmain	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.862266	151.176429	1	1	notify business/property owner	BA52	Secondary	LOW	\$ -
OB27	Trafalgar Street	Amnandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.884687	151.170836	1	1	notify business/property owner	AN109	Secondary	LOW	\$ -
OB270	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.860674	151.181477	1	1	notify business/property owner	BA54	Tertiary	LOW	\$ -
OB271	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation - property	-33.860686	151.18141	1	1	notify business/property owner	BA54	Tertiary	LOW	\$ -
OB272	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation	-33.86047	151.181133	1	1	refer to maintenance	BA55	Secondary	LOW	\$ -
OB273	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860366	151.181014	1	1	refer to maintenance	BA55	Secondary	LOW	\$ -
OB274	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath - council and property	-33.86046	151.180981	1	1	refer to maintenance	BA55	Secondary	LOW	\$ -
OB275	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation	-33.858866	151.180286	1	1	refer to maintenance	BA57	Secondary	LOW	\$ -
OB276	Palmer Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.858311	151.180461	1	1	no action	BA53	Secondary	LOW	\$ -
OB277	Palmer Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.859597	151.180589	1	1	no action	BA56	Secondary	LOW	\$ -
OB278	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.859086	151.18047	1	1	refer to maintenance	BA57	Secondary	LOW	\$ -
OB279	Palmer Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.858747	151.17992	1	1	refer to maintenance	BA57	Secondary	LOW	\$ -
OB28	Trafalgar Street	Amnandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.884083	151.171242	1	1					

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB282	Wortley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.861001	151.178463	1	1	refer to maintenance	BA76	Secondary	LOW	\$ -
OB283	Wortley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860916	151.17859	1	1	refer to maintenance	BA76	Secondary	LOW	\$ -
OB284	Wortley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860711	151.17859	1	1	refer to maintenance	BA76	Secondary	LOW	\$ -
OB285	Wortley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.860283	151.17847	1	1	no action	BA75	Tertiary	LOW	\$ -
OB286	Wortley Street	Balmain	Local Road	obstruction	overhanging vegetation narrows footpath	-33.860307	151.178276	1	1	refer to maintenance	BA75	Tertiary	LOW	\$ -
OB287	Wortley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.86064	151.178755	1	1	no action	BA76	Secondary	LOW	\$ -
OB288	Wortley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.86088	151.178348	1	1	no action	BA76	Secondary	LOW	\$ -
OB289	Wortley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.861146	151.177978	1	1	no action	BA59	Secondary	LOW	\$ -
OB29	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.867014	151.169746	1	1	notify business/property owner	AN111	Secondary	LOW	\$ -
OB290	Wortley Street	Balmain	Local Road	obstruction	tree narrows footpath	-33.861274	151.177571	1	1	no action	BA59	Secondary	LOW	\$ -
OB291	Darling Street	Balmain East	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.857963	151.188963	1	1	notify business/property owner	BA24	Secondary	LOW	\$ -
OB292	Darling Street	Balmain East	Local Road	obstruction	tree narrows footpath - property	-33.857517	151.192097	1	1	notify property owner	BE3	Primary	LOW	\$ -
OB293	Lousia Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.850609	151.17914	1	1	no action	BI10	Tertiary	LOW	\$ -
OB294	Lousia Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.850189	151.179437	1	1	no action	BI10	Tertiary	LOW	\$ -
OB295	Lousia Road	Birchgrove	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.850044	151.179542	1	1	notify business/property owner	BI10	Tertiary	LOW	\$ -
OB296	Lousia Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.84948	151.180015	1	1	no action	BI11	Tertiary	LOW	\$ -
OB297	Lousia Road	Birchgrove	Local Road	obstruction	electricity box narrows footpath	-33.849252	151.180178	1	1	no action	BI9	Tertiary	LOW	\$ -
OB298	Lousia Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.848318	151.181108	1	1	no action	BI12	Tertiary	LOW	\$ -
OB299	Lousia Road	Birchgrove	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.848249	151.181281	1	1	notify business/property owner	BI12	Tertiary	LOW	\$ -
OB3	Chester Street	Annandale	Local Road	obstruction	signpost narrows footpath	-33.848285	151.173368	1	1	relocate signpost	AN31	Primary	LOW	\$ 300
OB30	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.84406	151.177105	1	1	refer to maintenance	AN109	Secondary	LOW	\$ -
OB301	Lousia Road	Birchgrove	Local Road	obstruction	bollards narrows footpath	-33.848039	151.181963	1	1	relocate or remove bollard	BI6	Tertiary	LOW	\$ 2,500
OB302	Lousia Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.847919	151.182383	1	1	no action	BI6	Tertiary	LOW	\$ -
OB303	Lousia Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.847487	151.184121	1	1	no action	BI13	Tertiary	LOW	\$ -
OB304	Lousia Road	Birchgrove	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.847119	151.184923	1	1	notify business/property owner	BI14	Secondary	LOW	\$ -
OB305	Lousia Road	Birchgrove	Local Road	obstruction	bollard narrows footpath	-33.846821	151.185425	1	1	relocate or remove bollard	BI7	Secondary	LOW	\$ 2,500
OB306	Lousia Road	Birchgrove	Local Road	obstruction	pot plants narrows footpath - property	-33.847918	151.184121	1	1	notify property owner	BI6	Tertiary	LOW	\$ -
OB307	Lousia Road	Birchgrove	Local Road	obstruction	power pole narrows footpath	-33.849227	151.180192	1	1	no action	BI9	Tertiary	LOW	\$ -
OB308	Rowtree Street	Birchgrove	Local Road	obstruction	vehicles narrows footpath	-33.851686	151.183928	1	1	no action	BI16	Tertiary	LOW	\$ -
OB309	Rowtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.851713	151.183604	1	1	no action	BI16	Tertiary	LOW	\$ -
OB31	Trafalgar Street	Annandale	Local Road	obstruction	vehicle narrows footpath	-33.844467	151.177069	1	1	no action	AN109	Secondary	LOW	\$ -
OB310	Rowtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.851783	151.183463	1	1	no action	BI16	Tertiary	LOW	\$ -
OB311	Rowtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.85182	151.183382	1	1	no action	BI16	Tertiary	LOW	\$ -
OB312	Rowtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.85197	151.18326	1	1	no action	BI16	Tertiary	LOW	\$ -
OB313	Rowtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.851984	151.183116	1	1	no action	BI17	Tertiary	LOW	\$ -
OB314	Rowtree Street	Birchgrove	Local Road	obstruction	tree narrows footpath	-33.852174	151.183074	1	1	no action	BI17	Tertiary	LOW	\$ -
OB315	Australia Street	Camperdown	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892947	151.176708	1	1	notify business/property owner	CAB	Secondary	LOW	\$ -
OB316	Horden Place	Camperdown	Local Road	obstruction	vehicles narrows footpath	-33.895671	151.173279	1	1	no action	CA18	Secondary	LOW	\$ -
OB317	Church Street	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.875764	151.122047	1	1	refer to maintenance	CR1	Secondary	LOW	\$ -
OB318	Church Street	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.875461	151.122566	1	1	refer to maintenance	CR1	Secondary	LOW	\$ -
OB319	Church Street	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.876371	151.123549	1	1	refer to maintenance	CR2	Secondary	LOW	\$ -
OB32	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation	-33.869661	151.169917	1	1	refer to maintenance	AN111	Secondary	LOW	\$ -
OB320	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87351	151.128615	1	1	notify business/property owner	CR4	Secondary	LOW	\$ -
OB321	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.873656	151.129474	1	1	refer to maintenance	CR4	Secondary	LOW	\$ -
OB322	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation	-33.88137	151.119466	1	1	refer to maintenance	CR3	Secondary	LOW	\$ -
OB323	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880472	151.119915	1	1	refer to maintenance	CR3	Secondary	LOW	\$ -
OB324	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879432	151.120637	1	1	notify business/property owner	CR14	Secondary	LOW	\$ -
OB325	Croydon Road	Croydon	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879432	151.122331	1	1	notify business/property owner	CR9	Secondary	LOW	\$ -
OB326	Eltonville Parade	Croydon	Local Road	obstruction	tree narrows footpath	-33.88351	151.119242	1	1	no action	CR20	Secondary	LOW	\$ -
OB327	Liverpool Road	Croydon	State Road	obstruction	overhanging vegetation - property	-33.887134	151.113548	1	1	notify business/property owner	CR23	Primary	LOW	\$ -
OB328	Parramatta Road	Croydon	State Road	obstruction	tree narrows footpath	-33.874294	151.127442	1	1	no action	CR33	Secondary	LOW	\$ -
OB329	Parramatta Road	Croydon	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.87175	151.123807	1	1	notify business/property owner	CR29	Secondary	LOW	\$ -
OB33	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881616	151.17222	1	1	refer to maintenance	AN105	Secondary	LOW	\$ -
OB330	Parramatta Road	Croydon	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.871698	151.122688	1	1	notify business/property owner	CR28	Secondary	LOW	\$ -
OB331	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.883618	151.11517	1	1	notify business/property owner	CP4	Tertiary	LOW	\$ -
OB332	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.893328	151.116014	1	1	notify business/property owner	CP9	Secondary	LOW	\$ -
OB333	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.893472	151.116157	1	1	notify business/property owner	CP2	Secondary	LOW	\$ -
OB334	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.89437	151.112541	1	1	notify business/property owner	CP1	Secondary	LOW	\$ -
OB335	Georges River Drive	Croydon Park	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.893838	151.114054	1	1	notify business/property owner	CP5	Secondary	LOW	\$ -
OB336	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.901019	151.134118	1	1	notify business/property owner	DH13	Tertiary	LOW	\$ -
OB337	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900974	151.134399	1	1	notify business/property owner	DH13	Tertiary	LOW	\$ -
OB338	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900969	151.135057	1	1	notify business/property owner	DH14	Tertiary	LOW	\$ -
OB339	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900969	151.135724	1	1	notify business/property owner	DH14	Tertiary	LOW	\$ -
OB34	Booth Street	Annandale	Regional Road	obstruction	storefront narrows footpath - property	-33.882278	151.173173	1	1	notify business/property owner	AN26	Primary	LOW	\$ -
OB340	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.901117	151.134249	1	1	notify business/property owner	DH13	Tertiary	LOW	\$ -
OB341	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.901162	151.133737	1	1	notify business/property owner	DH13	Tertiary	LOW	\$ -
OB342	Arlington Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.901003	151.133019	1	1	notify business/property owner	DH12	Secondary	LOW	\$ -
OB343	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.909796	151.139966	1	1	refer to maintenance	DH3	Secondary	LOW	\$ -
OB344	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.910589	151.140844	1	1	refer to maintenance	DH2	Secondary	LOW	\$ -
OB345	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.910463	151.140864	1	1	refer to maintenance	DH3	Secondary	LOW	\$ -
OB346	Bedford Crescent	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.910309	151.140333	1	1	refer to maintenance	DH3	Secondary	LOW	\$ -
OB347	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907034	151.140604	1	1	notify business/property owner	DH4	Secondary	LOW	\$ -
OB348	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.907146	151.140513	1	1	notify business/property owner	DH4	Secondary	LOW	\$ -
OB349	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907189	151.140569	1	1	notify business/property owner	DH4	Secondary	LOW	\$ -
OB35	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880147	151.172815	1	1	notify business/property owner	AN106	Secondary	LOW	\$ -
OB350	Blackwood Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907096	151.140671	1	1	notify business/property owner	DH4	Secondary	LOW	\$ -
OB351	Challis Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.910532	151.14552	1	1	notify business/property owner	DH7	Tertiary	LOW	\$ -
OB352	Challis Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.9104	151.14526	1	1	notify business/property owner	DH6	Secondary	LOW	\$ -
OB353	Consett Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906145	151.138826	1	1	notify business/property owner	DH9	Secondary	LOW	\$ -
OB354	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902528	151.138084	1	1	refer to maintenance	DH17	Secondary	LOW	\$ -
OB355	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902537	151.138329	1	1	notify business/property owner	DH17	Secondary	LOW	\$ -
OB356	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902526	151.139536	1	1	notify business/property owner	DH10	Primary	LOW	\$ -
OB357	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.903412	151.140455	1	1	notify business/property owner	DH18	Secondary	LOW	\$ -
OB358	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.902994	151.139816	1	1	refer to maintenance	DH10	Primary	LOW	\$ -
OB359	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902994	151.13915	1	1	refer to maintenance	DH10	Primary	LOW	\$ -
OB36	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87973	151.173083	1	1	notify business/property owner	AN100	Secondary	LOW	\$ -
OB360	Constitution Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902535	151.139021	1	1	refer to maintenance	DH10	Primary	LOW	\$ -
OB361	Davia Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.896289	151.140375	1	1	refer to maintenance	DH116	Secondary	LOW	\$ -
OB362	Davia Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899137	151.140208	1	1	refer to maintenance	DH116	Secondary	LOW	\$ -
OB363	Denison Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902572	151.139631	1	1	refer to maintenance	DH23	Primary	LOW	\$ -
OB364	Denison Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902445	151.139696	1	1	notify business/property owner	DH23	Primary	LOW	\$ -
OB365	Denison Road	Dulwich Hill	Local Road											

P4909 Inner West PAMP Detailed Works Program Obstructions 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB366	Denison Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902006	151.140056	1	1	refer to maintenance	DH22	Primary	LOW	\$ -
OB367	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902477	151.141028	1	1	notify business/property owner	DH25	Primary	LOW	\$ -
OB368	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902979	151.142136	1	1	notify business/property owner	DH26	Primary	LOW	\$ -
OB369	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902637	151.141481	1	1	refer to maintenance	DH26	Primary	LOW	\$ -
OB37	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880181	151.172954	1	1	refer to maintenance	AN106	Secondary	LOW	\$ -
OB370	Dulwich Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902205	151.14072	1	1	notify business/property owner	DH25	Primary	LOW	\$ -
OB371	Ewart Street	Dulwich Hill	Local Road	obstruction	power pole narrows footpath	-33.906959	151.137108	1	1	no action	DH32	Secondary	LOW	\$ -
OB372	Ewart Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.909751	151.137208	1	1	notify business/property owner	DH32	Secondary	LOW	\$ -
OB373	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.900995	151.147307	1	1	notify business/property owner	DH36	Tertiary	LOW	\$ -
OB374	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.900899	151.146341	1	1	notify business/property owner	DH35	Tertiary	LOW	\$ -
OB375	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.900907	151.146155	1	1	notify business/property owner	DH35	Tertiary	LOW	\$ -
OB376	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.900808	151.146923	1	1	notify business/property owner	DH35	Tertiary	LOW	\$ -
OB377	Frazer Street	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.900839	151.147446	1	1	notify business/property owner	DH36	Tertiary	LOW	\$ -
OB378	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901334	151.139437	1	1	refer to maintenance	DH61	Secondary	LOW	\$ -
OB379	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901449	151.139307	1	1	refer to maintenance	DH61	Secondary	LOW	\$ -
OB38	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879489	151.173154	1	1	notify business/property owner	AN100	Secondary	LOW	\$ -
OB380	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901571	151.139266	1	1	refer to maintenance	DH61	Secondary	LOW	\$ -
OB381	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901665	151.139170	1	1	refer to maintenance	DH61	Secondary	LOW	\$ -
OB382	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901951	151.138904	1	1	refer to maintenance	DH60	Secondary	LOW	\$ -
OB383	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902278	151.138771	1	1	refer to maintenance	DH60	Secondary	LOW	\$ -
OB384	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902086	151.138987	1	1	refer to maintenance	DH60	Secondary	LOW	\$ -
OB385	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.901751	151.139186	1	1	notify business/property owner	DH60	Secondary	LOW	\$ -
OB386	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901324	151.139548	1	1	refer to maintenance	DH61	Secondary	LOW	\$ -
OB387	Grove Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901118	151.139728	1	1	refer to maintenance	DH61	Secondary	LOW	\$ -
OB388	Hamstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.898528	151.138012	1	1	notify business/property owner	DH63	Secondary	LOW	\$ -
OB389	Hamstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.898655	151.138324	1	1	notify business/property owner	DH63	Secondary	LOW	\$ -
OB39	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879351	151.173263	1	1	refer to maintenance	AN100	Secondary	LOW	\$ -
OB390	Hamstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.898572	151.138218	1	1	notify business/property owner	DH63	Secondary	LOW	\$ -
OB391	Hamstead Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897781	151.137206	1	1	notify business/property owner	DH62	Secondary	LOW	\$ -
OB392	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907421	151.138981	1	1	notify business/property owner	DH65	Secondary	LOW	\$ -
OB393	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906285	151.138903	1	1	notify business/property owner	DH65	Secondary	LOW	\$ -
OB394	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906228	151.138956	1	1	notify business/property owner	DH65	Secondary	LOW	\$ -
OB395	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905388	151.139431	1	1	notify business/property owner	DH66	Secondary	LOW	\$ -
OB396	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905188	151.139581	1	1	notify business/property owner	DH64	Secondary	LOW	\$ -
OB397	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.905188	151.139581	1	1	notify business/property owner	DH64	Secondary	LOW	\$ -
OB398	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905052	151.140047	1	1	notify business/property owner	DH64	Secondary	LOW	\$ -
OB399	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905051	151.139971	1	1	refer to maintenance	DH64	Secondary	LOW	\$ -
OB4	Hutchinson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.875087	151.169935	1	1	refer to maintenance	AN120	Secondary	LOW	\$ -
OB40	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.879926	151.173083	1	1	notify business/property owner	AN100	Secondary	LOW	\$ -
OB400	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.905522	151.139035	1	1	notify business/property owner	DH65	Secondary	LOW	\$ -
OB401	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905862	151.138969	1	1	refer to maintenance	DH65	Secondary	LOW	\$ -
OB402	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905846	151.138966	1	1	notify business/property owner	DH63	Secondary	LOW	\$ -
OB403	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.90874	151.138674	1	1	notify business/property owner	DH63	Secondary	LOW	\$ -
OB404	Hercules Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.90738	151.138642	1	1	notify business/property owner	DH65	Secondary	LOW	\$ -
OB405	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905928	151.139028	1	1	refer to maintenance	DH68	Secondary	LOW	\$ -
OB406	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900713	151.139082	1	1	notify business/property owner	DH68	Secondary	LOW	\$ -
OB407	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900482	151.138935	1	1	notify business/property owner	DH68	Secondary	LOW	\$ -
OB408	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900738	151.139169	1	1	notify business/property owner	DH67	Secondary	LOW	\$ -
OB409	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.900391	151.139164	1	1	refer to maintenance	DH67	Secondary	LOW	\$ -
OB41	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.879304	151.173255	1	1	notify business/property owner	AN100	Secondary	LOW	\$ -
OB410	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.900929	151.139589	1	1	refer to maintenance	DH68	Secondary	LOW	\$ -
OB411	Hill Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901227	151.140095	1	1	refer to maintenance	DH69	Secondary	LOW	\$ -
OB412	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.905186	151.140322	1	1	notify business/property owner	DH72	Secondary	LOW	\$ -
OB413	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905894	151.140717	1	1	notify business/property owner	DH72	Secondary	LOW	\$ -
OB414	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906029	151.140764	1	1	notify business/property owner	DH74	Secondary	LOW	\$ -
OB415	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905498	151.141069	1	1	notify business/property owner	DH74	Secondary	LOW	\$ -
OB416	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.90684	151.141315	1	1	refer to maintenance	DH73	Secondary	LOW	\$ -
OB417	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.90665	151.141331	1	1	notify business/property owner	DH73	Secondary	LOW	\$ -
OB418	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905794	151.140836	1	1	notify business/property owner	DH72	Secondary	LOW	\$ -
OB419	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905606	151.140986	1	1	notify business/property owner	DH72	Secondary	LOW	\$ -
OB42	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.878588	151.173575	1	1	refer to maintenance	AN104	Secondary	LOW	\$ -
OB420	Kintore Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation - property	-33.905336	151.140594	1	1	notify business/property owner	DH72	Secondary	LOW	\$ -
OB421	Marrickville Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.906119	151.140324	1	1	notify business/property owner	DH77	Secondary	LOW	\$ -
OB422	Marrickville Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.9058	151.140633	1	1	notify business/property owner	DH79	Primary	LOW	\$ -
OB423	Ness Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.910741	151.136836	1	1	refer to maintenance	DH80	Tertiary	LOW	\$ -
OB424	Ness Avenue	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.910281	151.137432	1	1	notify business/property owner	DH110	Tertiary	LOW	\$ -
OB425	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.901522	151.144786	1	1	notify business/property owner	DH88	Primary	LOW	\$ -
OB426	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.905127	151.137979	1	1	notify business/property owner	DH112	Secondary	LOW	\$ -
OB427	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.905789	151.136194	1	1	notify business/property owner	DH86	Primary	LOW	\$ -
OB428	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.905644	151.134237	1	1	notify business/property owner	DH88	Secondary	LOW	\$ -
OB429	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath	-33.905742	151.134675	1	1	refer to maintenance	DH87	Primary	LOW	\$ -
OB43	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878323	151.173682	1	1	notify business/property owner	AN104	Secondary	LOW	\$ -
OB430	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath	-33.905592	151.138317	1	1	refer to maintenance	DH86	Primary	LOW	\$ -
OB431	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath	-33.905389	151.136789	1	1	refer to maintenance	DH85	Primary	LOW	\$ -
OB432	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.902636	151.140659	1	1	notify business/property owner	DH86	Primary	LOW	\$ -
OB433	New Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation - property	-33.901232	151.14466	1	1	notify business/property owner	DH83	Primary	LOW	\$ -
OB434	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.895985	151.138104	1	1	notify business/property owner	SH56	Primary	LOW	\$ -
OB435	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.896812	151.138695	1	1	notify business/property owner	SH57	Primary	LOW	\$ -
OB436	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.897452	151.139994	1	1	notify business/property owner	SH58	Secondary	LOW	\$ -
OB437	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.898264	151.134852	1	1	notify business/property owner	SH59	Tertiary	LOW	\$ -
OB438	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.898851	151.134269	1	1	notify business/property owner	SH60	Tertiary	LOW	\$ -
OB439	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.902021	151.131036	1	1	notify business/property owner	SH61	Tertiary	LOW	\$ -
OB44	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.876559	151.173708	1	1	refer to maintenance	AN104	Secondary	LOW	\$ -
OB440	Old Canterbury Road	Dulwich Hill	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.902136	151.130946	1	1	notify business/property owner	AF127	Secondary	LOW	\$ -
OB441	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900938	151.141305	1	1	notify business/property owner	DH104	Secondary	LOW	\$ -
OB442	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.901601	151.142517	1	1	notify business/property owner	DH104	Secondary	LOW	\$ -
OB443	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902059	151.14321	1	1	notify business/property owner	DH105	Secondary	LOW	\$ -
OB444	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902218	151.14363	1	1	notify business/property owner	DH105	Secondary	LOW	\$ -
OB445	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.900345	151.140276	1	1	refer to maintenance	DH103	Secondary	LOW	\$ -
OB446	Piggott Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.900735	151.140959	1	1	notify business/property owner	DH103	Secondary	LOW	\$ -
OB447	Rivendale													

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB45	Booth Street	Annandale	Regional Road	obstruction	power pole narrows footpath	-33.885038	151.175966	1		further investigation required - footpath	AN28	Secondary	LOW	\$ 5,000
OB450	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.909036	151.137904	1		notify business/property owner	DH111	Tertiary	LOW	\$ -
OB451	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908672	151.137994	1		notify business/property owner	DH111	Tertiary	LOW	\$ -
OB452	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908652	151.137586	1		notify business/property owner	DH111	Tertiary	LOW	\$ -
OB453	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.909028	151.137723	1		refer to maintenance	DH111	Tertiary	LOW	\$ -
OB454	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.909265	151.13806	1		refer to maintenance	DH52	Secondary	LOW	\$ -
OB455	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907446	151.137604	1		notify business/property owner	DH113	Tertiary	LOW	\$ -
OB456	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.90749	151.137618	1		refer to maintenance	DH113	Tertiary	LOW	\$ -
OB457	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.907822	151.137787	1		refer to maintenance	DH113	Tertiary	LOW	\$ -
OB458	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation	-33.908346	151.137552	1		refer to maintenance	DH111	Tertiary	LOW	\$ -
OB459	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908228	151.137741	1		notify business/property owner	DH113	Tertiary	LOW	\$ -
OB46	Trafalgar Street	Annandale	Local Road	obstruction	signpost narrows footpath	-33.876815	151.174432	1		relocate signpost	AN102	Tertiary	LOW	\$ 300
OB460	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.908321	151.137741	1		refer to maintenance	DH113	Tertiary	LOW	\$ -
OB461	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908224	151.138	1		notify business/property owner	DH114	Secondary	LOW	\$ -
OB462	Terrace Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.909098	151.137999	1		refer to maintenance	DH112	Secondary	LOW	\$ -
OB463	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.899519	151.138021	1		notify business/property owner	DH115	Secondary	LOW	\$ -
OB464	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899766	151.138498	1		refer to maintenance	DH115	Secondary	LOW	\$ -
OB465	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.899452	151.137924	1		notify business/property owner	DH115	Secondary	LOW	\$ -
OB466	Terry Road	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.899452	151.137812	1		refer to maintenance	DH115	Secondary	LOW	\$ -
OB467	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.909172	151.143132	1		notify business/property owner	DH126	Primary	LOW	\$ -
OB468	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.909972	151.142309	1		notify business/property owner	DH125	Primary	LOW	\$ -
OB469	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.910378	151.141969	1		notify business/property owner	DH125	Primary	LOW	\$ -
OB47	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.876428	151.174609	1		notify business/property owner	AN102	Tertiary	LOW	\$ -
OB470	Wardell Road	Dulwich Hill	Regional Road	obstruction	overhanging vegetation - property	-33.910827	151.141459	1		notify business/property owner	DH124	Primary	LOW	\$ -
OB471	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.898605	151.13975	1		refer to maintenance	DH117	Secondary	LOW	\$ -
OB472	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.898161	151.140266	1		refer to maintenance	DH44	Secondary	LOW	\$ -
OB473	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.898051	151.140418	1		notify business/property owner	DH44	Secondary	LOW	\$ -
OB474	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.897246	151.14145	1		notify business/property owner	DH47	Secondary	LOW	\$ -
OB475	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.897024	151.141727	1		refer to maintenance	DH46	Tertiary	LOW	\$ -
OB476	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.896284	151.141977	1		notify business/property owner	DH45	Secondary	LOW	\$ -
OB477	Weston Street	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.896813	151.141666	1		refer to maintenance	DH46	Tertiary	LOW	\$ -
OB478	Williams Parade	Dulwich Hill	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902655	151.137307	1		refer to maintenance	DH127	Secondary	LOW	\$ -
OB479	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.900097	151.171436	1		notify business/property owner	EN19	Primary	LOW	\$ -
OB48	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876376	151.174609	1		notify business/property owner	AN102	Tertiary	LOW	\$ -
OB480	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.901264	151.171586	1		notify business/property owner	EN2	Primary	LOW	\$ -
OB481	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.90189	151.171733	1		notify business/property owner	EN3	Primary	LOW	\$ -
OB482	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.903462	151.17177	1		notify business/property owner	EN3	Primary	LOW	\$ -
OB483	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.903325	151.172332	1		notify business/property owner	EN5	Secondary	LOW	\$ -
OB484	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.903631	151.172517	1		notify business/property owner	EN5	Secondary	LOW	\$ -
OB485	Edgeware Road	Enmore	Regional Road	obstruction	overhanging vegetation - property	-33.90368	151.172572	1		notify business/property owner	EN5	Secondary	LOW	\$ -
OB486	Liberty Street	Enmore	Regional Road	obstruction	empty tree pit narrows footpath	-33.89103	151.171028	1		widen footpath	EN11	Secondary	LOW	\$ 200
OB487	All Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.878319	151.132924	1		refer to maintenance	HA3	Tertiary	LOW	\$ -
OB488	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.87923	151.134032	1		refer to maintenance	HA20	Secondary	LOW	\$ -
OB489	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879568	151.133516	1		notify business/property owner	HA19	Secondary	LOW	\$ -
OB49	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879719	151.174609	1		refer to maintenance	AN102	Tertiary	LOW	\$ -
OB490	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880243	151.13251	1		refer to maintenance	HA18	Secondary	LOW	\$ -
OB491	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880178	151.132265	1		refer to maintenance	AF29	Secondary	LOW	\$ -
OB492	Bland Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879688	151.133041	1		notify business/property owner	HA18	Secondary	LOW	\$ -
OB493	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.870749	151.140221	1		notify business/property owner	HA22	Secondary	LOW	\$ -
OB494	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.870955	151.144983	1		notify business/property owner	HA22	Secondary	LOW	\$ -
OB495	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.871173	151.144848	1		notify business/property owner	HA22	Secondary	LOW	\$ -
OB496	Boomerang Street	Haberfield	Local Road	obstruction	comms pillar narrows footpath	-33.873621	151.143178	1		no action	HA26	Secondary	LOW	\$ -
OB497	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.87378	151.143145	1		refer to maintenance	HA27	Secondary	LOW	\$ -
OB498	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.873916	151.143097	1		notify business/property owner	HA27	Secondary	LOW	\$ -
OB499	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.874187	151.14301	1		notify business/property owner	HA27	Secondary	LOW	\$ -
OB5	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879897	151.174527	1		refer to maintenance	AN69	Secondary	LOW	\$ -
OB50	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876066	151.17473	1		notify business/property owner	AN102	Tertiary	LOW	\$ -
OB500	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874657	151.14276	1		notify business/property owner	HA27	Secondary	LOW	\$ -
OB501	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874813	151.142863	1		notify business/property owner	HA25	Secondary	LOW	\$ -
OB502	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.875434	151.142108	1		notify business/property owner	HA106	Secondary	LOW	\$ -
OB503	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.875188	151.142223	1		refer to maintenance	HA25	Secondary	LOW	\$ -
OB504	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.874997	151.142302	1		refer to maintenance	HA25	Secondary	LOW	\$ -
OB505	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.874844	151.142391	1		refer to maintenance	HA25	Secondary	LOW	\$ -
OB506	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874473	151.142667	1		notify business/property owner	HA27	Secondary	LOW	\$ -
OB507	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.874219	151.142795	1		refer to maintenance	HA27	Secondary	LOW	\$ -
OB508	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.874033	151.142856	1		notify business/property owner	HA27	Secondary	LOW	\$ -
OB509	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.87388	151.142895	1		refer to maintenance	HA27	Secondary	LOW	\$ -
OB51	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation	-33.876148	151.17484	1		refer to maintenance	AN102	Tertiary	LOW	\$ -
OB510	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.873733	151.142937	1		notify business/property owner	HA27	Secondary	LOW	\$ -
OB511	Boomerang Street	Haberfield	Local Road	obstruction	overhanging vegetation	-33.872979	151.143343	1		refer to maintenance	HA26	Secondary	LOW	\$ -
OB512	Dalhousie Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.871878	151.140612	1		notify business/property owner	HA32	Primary	LOW	\$ -
OB513	Dalhousie Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881778	151.137997	1		notify business/property owner	HA36	Primary	LOW	\$ -
OB514	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.880526	151.136637	1		refer to maintenance	HA43	Secondary	LOW	\$ -
OB515	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.880445	151.136581	1		refer to maintenance	HA43	Secondary	LOW	\$ -
OB516	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.880711	151.136323	1		refer to maintenance	HA42	Secondary	LOW	\$ -
OB517	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881297	151.136463	1		notify business/property owner	HA42	Secondary	LOW	\$ -
OB518	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881442	151.136613	1		notify business/property owner	HA41	Secondary	LOW	\$ -
OB519	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881574	151.136759	1		notify business/property owner	HA41	Secondary	LOW	\$ -
OB52	Trafalgar Street	Annandale	Local Road	obstruction	overhanging vegetation - property	-33.876227	151.174812	1		notify business/property owner	AN102	Tertiary	LOW	\$ -
OB520	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881582	151.136779	1		refer to maintenance	HA41	Secondary	LOW	\$ -
OB521	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881732	151.136933	1		refer to maintenance	HA41	Secondary	LOW	\$ -
OB522	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881863	151.136951	1		notify business/property owner	HA41	Secondary	LOW	\$ -
OB523	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881801	151.137028	1		refer to maintenance	HA41	Secondary	LOW	\$ -
OB524	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881864	151.137059	1		notify business/property owner	HA41	Secondary	LOW	\$ -
OB525	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.882001	151.137228	1		notify business/property owner	HA41	Secondary	LOW	\$ -
OB526	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881947	151.137293	1		notify business/property owner	HA41	Secondary	LOW	\$ -
OB527	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.881965	151.137398	1		notify business/property owner	HA41	Secondary	LOW	\$ -
OB528	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881906	151.13732	1		refer to maintenance	HA41	Secondary	LOW	\$ -
OB529	Denman Avenue	Haberfield	Local Road	obstruction	signpost narrows footpath	-33.881511	151.138812	1		relocate signpost	HA41	Secondary	LOW	\$ 300
OB53	White Creek	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879233	151.167572	1		notify business/property owner	AN113	Secondary	LOW	\$ -
OB530	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881467	151.136889	1		refer to maintenance	HA41	Secondary	LOW	\$ -
OB531	Denman Avenue	Haberfield	Local Road	obstruction	overhanging vegetation	-33.881396	151.136764	1		refer to maintenance				

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB533	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.884933	151.144124	1	1	notify business/property owner	H456	Secondary	LOW	\$ -
OB534	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.885125	151.143966	1	1	notify business/property owner	H456	Secondary	LOW	\$ -
OB535	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886591	151.144136	1	1	refer to maintenance	H455	Secondary	LOW	\$ -
OB536	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.885591	151.144075	1	1	refer to maintenance	H456	Secondary	LOW	\$ -
OB537	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886643	151.143987	1	1	refer to maintenance	H455	Secondary	LOW	\$ -
OB538	Hawthorn Parade	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879915	151.145865	1	1	refer to maintenance	H450	Secondary	LOW	\$ -
OB539	Marion Street	Haberfield	Regional Road	obstruction	overhanging vegetation	-33.884088	151.144637	1	1	refer to maintenance	H454	Primary	LOW	\$ -
OB54	Booth Street	Annandale	Regional Road	obstruction	power pole narrows footpath	-33.884548	151.175797	1	1	no action	AN28	Secondary	LOW	\$ -
OB540	Mortley Avenue	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.872074	151.143117	1	1	notify business/property owner	H463	Secondary	LOW	\$ -
OB541	Mortley Avenue	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.870928	151.141981	1	1	refer to maintenance	H462	Secondary	LOW	\$ -
OB542	Paramatta Road	Haberfield	State Road	obstruction	signpost narrows footpath	-33.874686	151.129185	1	1	relocate signpost	H480	Secondary	LOW	\$ 300
OB543	Paramatta Road	Haberfield	State Road	obstruction	light post narrows footpath	-33.876596	151.129648	1	1	relocate light post	H482	Secondary	LOW	\$ 10,000
OB544	Paramatta Road	Haberfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.883203	151.134174	1	1	notify business/property owner	HA71	Secondary	LOW	\$ -
OB545	Ramsay Street	Haberfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882586	151.140458	1	1	notify business/property owner	HA95	Secondary	LOW	\$ -
OB546	Ramsay Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885171	151.142567	1	1	notify business/property owner	HA91	Secondary	LOW	\$ -
OB547	Ramsay Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.884955	151.142402	1	1	refer to maintenance	HA91	Secondary	LOW	\$ -
OB548	Ramsay Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885084	151.142673	1	1	notify business/property owner	HA91	Secondary	LOW	\$ -
OB549	Ramsay Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885084	151.142673	1	1	notify business/property owner	HA91	Secondary	LOW	\$ -
OB55	Booth Street	Annandale	Regional Road	obstruction	power pole narrows footpath	-33.883991	151.175627	1	1	no action	AN27	Primary	LOW	\$ -
OB550	Stoane Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.886764	151.14285	1	1	notify business/property owner	HA99	Tertiary	LOW	\$ -
OB551	Stoane Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.887105	151.142444	1	1	notify business/property owner	HA100	Secondary	LOW	\$ -
OB552	Ramsay Street	Haberfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.874052	151.133594	1	1	notify business/property owner	HA86	Secondary	LOW	\$ -
OB553	Ramsay Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.873768	151.133432	1	1	notify business/property owner	HA86	Secondary	LOW	\$ -
OB554	Ramsay Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.873593	151.133433	1	1	notify business/property owner	HA86	Secondary	LOW	\$ -
OB555	Ramsay Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.873391	151.133711	1	1	notify business/property owner	HA88	Secondary	LOW	\$ -
OB556	Ramsay Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.874891	151.134003	1	1	notify business/property owner	HA87	Secondary	LOW	\$ -
OB557	Ramsay Street	Haberfield	State Road	obstruction	overhanging vegetation - property	-33.874763	151.134167	1	1	notify business/property owner	HA87	Secondary	LOW	\$ -
OB558	Ramsay Street	Haberfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.874611	151.134051	1	1	notify business/property owner	HA87	Secondary	LOW	\$ -
OB559	Stoane Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.884228	151.142978	1	1	notify business/property owner	HA99	Tertiary	LOW	\$ -
OB56	Booth Street	Annandale	Regional Road	obstruction	power pole narrows footpath	-33.883608	151.175488	1	1	no action	AN27	Primary	LOW	\$ -
OB560	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.874407	151.139529	1	1	refer to maintenance	HA108	Secondary	LOW	\$ -
OB561	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.873891	151.13827	1	1	notify business/property owner	HA101	Secondary	LOW	\$ -
OB562	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.873638	151.137769	1	1	notify business/property owner	HA109	Tertiary	LOW	\$ -
OB563	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.873631	151.137702	1	1	refer to maintenance	HA109	Tertiary	LOW	\$ -
OB564	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.873708	151.137496	1	1	notify business/property owner	HA109	Tertiary	LOW	\$ -
OB565	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation - property	-33.873942	151.137881	1	1	notify business/property owner	HA109	Tertiary	LOW	\$ -
OB566	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.874745	151.138904	1	1	refer to maintenance	HA101	Secondary	LOW	\$ -
OB567	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.875885	151.142558	1	1	notify business/property owner	HA105	Secondary	LOW	\$ -
OB568	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.875827	151.142729	1	1	refer to maintenance	HA105	Secondary	LOW	\$ -
OB569	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876677	151.144619	1	1	notify business/property owner	HA103	Tertiary	LOW	\$ -
OB57	Chester Street	Annandale	Regional Road	obstruction	vehicles narrows footpath	-33.884732	151.174107	1	1	no action	AK30	Secondary	LOW	\$ -
OB570	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.876621	151.144972	1	1	refer to maintenance	HA103	Tertiary	LOW	\$ -
OB571	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.874974	151.140947	1	1	notify business/property owner	HA107	Secondary	LOW	\$ -
OB572	Waratah Street	Haberfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.874986	151.140772	1	1	notify business/property owner	HA107	Secondary	LOW	\$ -
OB573	Hardy Street	Hurstone Park	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905323	151.123874	1	1	refer to maintenance	HP2	Secondary	LOW	\$ -
OB574	Hardy Street	Hurstone Park	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906074	151.123796	1	1	notify business/property owner	HP2	Secondary	LOW	\$ -
OB575	Hardy Street	Hurstone Park	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905796	151.123964	1	1	refer to maintenance	HP2	Secondary	LOW	\$ -
OB576	Hardy Street	Hurstone Park	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905457	151.124148	1	1	refer to maintenance	HP2	Secondary	LOW	\$ -
OB577	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880299	151.148363	1	1	notify business/property owner	LH2	Secondary	LOW	\$ -
OB578	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880389	151.148657	1	1	refer to maintenance	LH2	Secondary	LOW	\$ -
OB579	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880401	151.152791	1	1	notify business/property owner	LH6	Tertiary	LOW	\$ -
OB58	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.903204	151.125302	1	1	notify business/property owner	AF82	Secondary	LOW	\$ -
OB580	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.88034	151.153228	1	1	notify business/property owner	LH6	Tertiary	LOW	\$ -
OB581	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880319	151.153504	1	1	refer to maintenance	LH7	Secondary	LOW	\$ -
OB582	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879989	151.153534	1	1	refer to maintenance	LH1	Secondary	LOW	\$ -
OB583	Allen Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879989	151.153534	1	1	refer to maintenance	LH1	Secondary	LOW	\$ -
OB584	Balmann Road	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.880023	151.159283	1	1	notify business/property owner	LH11	Primary	LOW	\$ -
OB585	Balmann Road	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.880967	151.159029	1	1	notify business/property owner	LH10	Primary	LOW	\$ -
OB586	Balmann Road	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882286	151.158943	1	1	notify business/property owner	LH21	Primary	LOW	\$ -
OB587	Balmann Road	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883322	151.159097	1	1	notify business/property owner	LH17	Primary	LOW	\$ -
OB588	James Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.875082	151.155301	1	1	refer to maintenance	LH14	Primary	LOW	\$ -
OB589	James Street	Leichhardt	State Road	obstruction	signpost narrows footpath	-33.875379	151.155518	1	1	relocate signpost	LF59	Secondary	LOW	\$ 300
OB59	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.904181	151.124779	1	1	refer to maintenance	HP1	Secondary	LOW	\$ -
OB590	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.875503	151.153904	1	1	refer to maintenance	LH32	Secondary	LOW	\$ -
OB591	James Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.875284	151.154855	1	1	refer to maintenance	LH31	Secondary	LOW	\$ -
OB592	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.875521	151.152563	1	1	notify business/property owner	LH33	Secondary	LOW	\$ -
OB593	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.875586	151.152381	1	1	refer to maintenance	LH34	Secondary	LOW	\$ -
OB594	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.875605	151.152286	1	1	refer to maintenance	LH34	Secondary	LOW	\$ -
OB595	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.875745	151.151447	1	1	notify business/property owner	LH35	Secondary	LOW	\$ -
OB596	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.876981	151.148636	1	1	notify business/property owner	LH37	Secondary	LOW	\$ -
OB597	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.877444	151.149554	1	1	refer to maintenance	LH38	Secondary	LOW	\$ -
OB598	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.877778	151.148713	1	1	notify business/property owner	LH39	Secondary	LOW	\$ -
OB599	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.877945	151.148474	1	1	notify business/property owner	LH39	Secondary	LOW	\$ -
OB6	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879859	151.174572	1	1	notify business/property owner	AN69	Secondary	LOW	\$ -
OB60	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.90465	151.124507	1	1	refer to maintenance	HP1	Secondary	LOW	\$ -
OB600	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.878981	151.148096	1	1	refer to maintenance	LH40	Secondary	LOW	\$ -
OB601	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath	-33.879098	151.147441	1	1	refer to maintenance	LH40	Secondary	LOW	\$ -
OB602	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.879407	151.147798	1	1	notify business/property owner	LH30	Secondary	LOW	\$ -
OB603	Darley Road	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.880823	151.147697	1	1	notify business/property owner	LH69	Secondary	LOW	\$ -
OB604	Darley Road	Leichhardt	State Road	obstruction	bollard narrows footpath	-33.880267	151.147521	1	1	relocate bollard	LH30	Secondary	LOW	\$ 2,500
OB605	Darbyshire Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880627	151.158717	1	1	refer to maintenance	LH44	Primary	LOW	\$ -
OB606	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883448	151.153993	1	1	notify business/property owner	LH45	Tertiary	LOW	\$ -
OB607	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.887136	151.152817	1	1	notify business/property owner	LH54	Tertiary	LOW	\$ -
OB608	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.888367	151.153054	1	1	refer to maintenance	LH53	Secondary	LOW	\$ -
OB609	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881788	151.152865	1	1	notify business/property owner	LH51	Tertiary	LOW	\$ -
OB61	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905514	151.123924	1	1	refer to maintenance	LH50	Tertiary	LOW	\$ -
OB610	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.881056	151.151924	1	1	notify business/property owner	LH50	Tertiary	LOW	\$ -
OB611	Eiswick Street	Leichhardt	Local Road	obstruction	structure narrows footpath	-33.888675	151.153029	1	1	re-align kerb and footpath	LH53	Secondary	LOW	\$ 7,500
OB612	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881628	151.151914	1	1	refer to maintenance	LH51	Tertiary	LOW	\$ -
OB613	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.883415	151.151911	1	1	refer to maintenance	LH52	Secondary	LOW	\$ -
OB614	Eiswick Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.887978								

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB617	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879546	151.151958	1		refer to maintenance	LH48	Secondary	LOW	\$ -
OB618	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.878121	151.151962	1		refer to maintenance	LH47	Secondary	LOW	\$ -
OB619	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.887769	151.148421	1		notify business/property owner	LH58	Tertiary	LOW	\$ -
OB62	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.865727	151.123943	1		notify business/property owner	HP2	Secondary	LOW	\$ -
OB620	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.888187	151.14948	1		refer to maintenance	LH58	Tertiary	LOW	\$ -
OB621	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.887659	151.148593	1		refer to maintenance	LH60	Secondary	LOW	\$ -
OB622	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.888771	151.149724	1		refer to maintenance	LH59	Secondary	LOW	\$ -
OB623	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886482	151.148582	1		refer to maintenance	LH59	Secondary	LOW	\$ -
OB624	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.886159	151.148638	1		notify business/property owner	LH59	Secondary	LOW	\$ -
OB625	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878341	151.150194	1		notify business/property owner	LH63	Tertiary	LOW	\$ -
OB626	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876681	151.150194	1		notify business/property owner	LH63	Tertiary	LOW	\$ -
OB627	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878843	151.150185	1		notify business/property owner	LH63	Tertiary	LOW	\$ -
OB628	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879173	151.150173	1		notify business/property owner	LH64	Tertiary	LOW	\$ -
OB629	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879688	151.150178	1		notify business/property owner	LH64	Tertiary	LOW	\$ -
OB63	Hardy Street	Ashbury	Local Road	obstruction	overhanging vegetation narrows footpath	-33.865948	151.123764	1		refer to maintenance	HP2	Secondary	LOW	\$ -
OB630	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.879998	151.150116	1		notify business/property owner	LH64	Tertiary	LOW	\$ -
OB631	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.880946	151.150147	1		notify business/property owner	LH65	Tertiary	LOW	\$ -
OB632	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.881269	151.150129	1		refer to maintenance	LH65	Tertiary	LOW	\$ -
OB633	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881688	151.150105	1		refer to maintenance	LH66	Tertiary	LOW	\$ -
OB634	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.881759	151.150131	1		refer to maintenance	LH66	Tertiary	LOW	\$ -
OB635	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.882603	151.150111	1		notify business/property owner	LH66	Tertiary	LOW	\$ -
OB636	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.882786	151.150096	1		refer to maintenance	LH66	Tertiary	LOW	\$ -
OB637	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.88332	151.150095	1		notify business/property owner	LH67	Secondary	LOW	\$ -
OB638	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.885225	151.15006	1		refer to maintenance	LH62	Secondary	LOW	\$ -
OB639	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.884944	151.150042	1		refer to maintenance	LH62	Secondary	LOW	\$ -
OB64	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877407	151.124366	1		refer to maintenance	AF41	Tertiary	LOW	\$ -
OB640	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.883612	151.149926	1		refer to maintenance	LH67	Secondary	LOW	\$ -
OB641	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883284	151.149934	1		notify business/property owner	LH67	Secondary	LOW	\$ -
OB642	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.883043	151.149928	1		refer to maintenance	LH67	Secondary	LOW	\$ -
OB643	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.882753	151.149954	1		notify business/property owner	LH68	Tertiary	LOW	\$ -
OB644	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.882298	151.149935	1		refer to maintenance	LH66	Tertiary	LOW	\$ -
OB645	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.882249	151.149962	1		notify business/property owner	LH66	Tertiary	LOW	\$ -
OB646	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.881921	151.149956	1		notify business/property owner	LH66	Tertiary	LOW	\$ -
OB647	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.881504	151.149961	1		notify business/property owner	LH65	Tertiary	LOW	\$ -
OB648	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.879248	151.150016	1		notify business/property owner	LH64	Tertiary	LOW	\$ -
OB649	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.879682	151.14999	1		notify business/property owner	LH63	Tertiary	LOW	\$ -
OB65	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877201	151.124321	1		notify business/property owner	AF41	Tertiary	LOW	\$ -
OB650	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.878192	151.149992	1		notify business/property owner	LH63	Tertiary	LOW	\$ -
OB651	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.877823	151.150017	1		notify business/property owner	LH63	Tertiary	LOW	\$ -
OB652	Flood Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877793	151.150019	1		refer to maintenance	LH63	Tertiary	LOW	\$ -
OB653	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation - property	-33.880477	151.147545	1		notify business/property owner	LH69	Secondary	LOW	\$ -
OB654	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.881122	151.147545	1		notify business/property owner	LH69	Secondary	LOW	\$ -
OB655	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.882046	151.147542	1		notify business/property owner	LH70	Secondary	LOW	\$ -
OB656	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.882409	151.147543	1		refer to maintenance	LH70	Secondary	LOW	\$ -
OB657	Foster Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.882553	151.147575	1		notify business/property owner	LH68	Primary	LOW	\$ -
OB658	Greenway	Leichhardt	Local Road	obstruction	overgrown vegetation narrows footpath	-33.886556	151.144726	1		refer to maintenance	LH76	Tertiary	LOW	\$ -
OB659	Hawthorne Light Rail Station	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.87996	151.147088	1		refer to maintenance	LH79	Secondary	LOW	\$ -
OB66	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877446	151.124776	1		notify business/property owner	AF42	Tertiary	LOW	\$ -
OB660	Hawthorne Light Rail Station	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880004	151.146891	1		refer to maintenance	LH81	Secondary	LOW	\$ -
OB661	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.885829	151.14629	1		refer to maintenance	LH89	Primary	LOW	\$ -
OB662	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886289	151.145801	1		refer to maintenance	LH88	Secondary	LOW	\$ -
OB663	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.885835	151.14812	1		notify business/property owner	LH88	Secondary	LOW	\$ -
OB664	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.886008	151.146817	1		refer to maintenance	LH87	Secondary	LOW	\$ -
OB665	Lords Road	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.886184	151.145909	1		notify business/property owner	LH86	Secondary	LOW	\$ -
OB666	Mackenzie Street	Leichhardt	Local Road	obstruction	signpost narrows footpath	-33.883719	151.161297	1		relocate signpost	LH90	Secondary	LOW	\$ 300
OB667	Mackenzie Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.883786	151.161245	1		notify business/property owner	LH90	Secondary	LOW	\$ -
OB668	Marion Street	Leichhardt	Regional Road	obstruction	signpost narrows footpath	-33.883726	151.156638	1		relocate signpost	LH101	Primary	LOW	\$ 300
OB669	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883922	151.155766	1		notify business/property owner	LH91	Primary	LOW	\$ -
OB67	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881156	151.127042	1		notify business/property owner	AF45	Tertiary	LOW	\$ -
OB670	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883987	151.155255	1		notify business/property owner	LH91	Primary	LOW	\$ -
OB671	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883961	151.15488	1		notify business/property owner	LH91	Primary	LOW	\$ -
OB672	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation - property	-33.884134	151.152195	1		notify business/property owner	LH98	Secondary	LOW	\$ -
OB673	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation - property	-33.884107	151.148487	1		notify business/property owner	LH95	Primary	LOW	\$ -
OB674	Marion Street	Leichhardt	Regional Road	obstruction	overhanging vegetation - property	-33.884182	151.144844	1		notify business/property owner	HA81	Primary	LOW	\$ -
OB675	Marion Street	Leichhardt	Regional Road	obstruction	signpost narrows footpath	-33.884235	151.144712	1		relocate signpost	HA61	Primary	LOW	\$ 300
OB676	Marion Street	Leichhardt	Regional Road	obstruction	bus shelter narrows footpath	-33.884085	151.147187	1		relocate or remove bus shelter	LH93	Primary	LOW	\$ 5,000
OB677	Moore Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.878652	151.161396	1		notify business/property owner	LH104	Secondary	LOW	\$ -
OB678	Norton Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.886902	151.157415	1		refer to maintenance	LH115	Primary	LOW	\$ -
OB679	Norton Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.886506	151.157361	1		refer to maintenance	LH116	Secondary	LOW	\$ -
OB68	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880718	151.128737	1		refer to maintenance	AF45	Tertiary	LOW	\$ -
OB680	Norton Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.885421	151.157185	1		refer to maintenance	LH117	Primary	LOW	\$ -
OB681	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.880649	151.156594	1		refer to maintenance	LH122	Primary	LOW	\$ -
OB682	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879572	151.156432	1		refer to maintenance	LH123	Primary	LOW	\$ -
OB683	Norton Street	Leichhardt	Local Road	obstruction	damaged bollard narrows footpath	-33.877289	151.156345	1		repair bollard	LH170	Secondary	LOW	\$ 2,500
OB684	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.876981	151.156248	1		refer to maintenance	LH127	Primary	LOW	\$ -
OB685	Norton Street	Leichhardt	Local Road	obstruction	bus shelter and signpost narrows footpath	-33.875628	151.156172	1		relocate signpost	LH127	Primary	LOW	\$ 300
OB686	Norton Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.875727	151.15558	1		notify business/property owner	LH127	Primary	LOW	\$ -
OB687	Parramatta Road	Leichhardt	Regional Road	obstruction	double pole signpost narrows footpath	-33.885835	151.158905	1		review and relocate double pole signpost	LH136	Secondary	LOW	\$ 500
OB688	Styles Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882655	151.166402	1		notify business/property owner	AN33	Secondary	LOW	\$ -
OB689	Styles Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883093	151.163238	1		notify business/property owner	LH152	Secondary	LOW	\$ -
OB69	Church Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.88043	151.12652	1		refer to maintenance	AF40	Tertiary	LOW	\$ -
OB690	Styles Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883987	151.163766	1		notify business/property owner	LH148	Secondary	LOW	\$ -
OB691	Styles Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882965	151.164459	1		notify business/property owner	LH148	Secondary	LOW	\$ -
OB692	Styles Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.882731	151.166346	1		refer to maintenance	AN33	Secondary	LOW	\$ -
OB693	Styles Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.883026	151.164084	1		notify business/property owner	LH148	Secondary	LOW	\$ -
OB694	Styles Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882997	151.164361	1		no action	LH148	Secondary	LOW	\$ -
OB695	Styles Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882698	151.166106	1		no action	LH150	Secondary	LOW	\$ -
OB696	Styles Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882691	151.165884	1		no action	LH150	Secondary	LOW	\$ -
OB697	Styles Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882777	151.165801	1		no action	LH150	Secondary	LOW	\$ -
OB698	Styles Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882821	151.165801	1		no action	LH151	Secondary	LOW	\$ -
OB699	Styles Street	Leichhardt	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.882819	151.165204	1		notify business/property owner	LH151	Secondary	LOW	\$ -
OB7	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath	-33.879637	151.174748	1		refer to maintenance	AN69	Secondary	LOW	\$ -
OB70	Cissoid Street	Ashfield	Local Road	obstruction	over									

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB700	Stiles Street	Leichhardt	Regional Road	obstruction	power pole narrows footpath	-33.882922	151.164475	1		no action	LH148	Secondary	LOW	\$ -
OB701	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.88018	151.148607	1		notify business/property owner	LH156	Primary	LOW	\$ -
OB702	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.88082	151.147055	1		notify business/property owner	LH155	Secondary	LOW	\$ -
OB703	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.887361	151.147512	1		notify business/property owner	LH154	Secondary	LOW	\$ -
OB704	Tebbutt Street	Leichhardt	State Road	obstruction	overhanging vegetation - property	-33.887791	151.147366	1		notify business/property owner	LH154	Secondary	LOW	\$ -
OB705	White Creek	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885274	151.164763	1		notify business/property owner	LH160	Secondary	LOW	\$ -
OB706	White Creek	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885078	151.164802	1		notify business/property owner	LH160	Secondary	LOW	\$ -
OB707	White Creek	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.885383	151.164761	1		notify business/property owner	LH159	Secondary	LOW	\$ -
OB708	White Creek	Leichhardt	Local Road	obstruction	vehicles narrows footpath	-33.886483	151.163783	1		no action	LH158	Secondary	LOW	\$ -
OB709	White Creek Lane	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.881351	151.166567	1		notify business/property owner	LH166	Secondary	LOW	\$ -
OB71	Cissod Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.88656	151.127192	1		notify business/property owner	AF48	Secondary	LOW	\$ -
OB710	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877364	151.157289	1		refer to maintenance	LH170	Secondary	LOW	\$ -
OB711	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877334	151.157543	1		refer to maintenance	LH170	Secondary	LOW	\$ -
OB712	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877334	151.157647	1		refer to maintenance	LH169	Secondary	LOW	\$ -
OB713	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.87734	151.157762	1		refer to maintenance	LH169	Secondary	LOW	\$ -
OB714	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877342	151.157813	1		refer to maintenance	LH169	Secondary	LOW	\$ -
OB715	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877344	151.157932	1		refer to maintenance	LH169	Secondary	LOW	\$ -
OB716	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877251	151.158235	1		refer to maintenance	LH169	Secondary	LOW	\$ -
OB717	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877246	151.1579	1		refer to maintenance	LH169	Secondary	LOW	\$ -
OB718	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87728	151.157255	1		notify business/property owner	LH170	Secondary	LOW	\$ -
OB719	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87786	151.152476	1		notify business/property owner	LH174	Secondary	LOW	\$ -
OB72	Cissod Street	Ashfield	Local Road	obstruction	overhanging vegetation	-33.886531	151.128274	1		notify business/property owner	AF49	Secondary	LOW	\$ -
OB720	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877666	151.152334	1		notify business/property owner	LH174	Secondary	LOW	\$ -
OB721	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877932	151.151172	1		notify business/property owner	LH173	Secondary	LOW	\$ -
OB722	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877916	151.151058	1		notify business/property owner	LH173	Secondary	LOW	\$ -
OB723	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877911	151.150961	1		refer to maintenance	LH173	Secondary	LOW	\$ -
OB724	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877627	151.149919	1		refer to maintenance	LH172	Secondary	LOW	\$ -
OB725	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877501	151.14862	1		refer to maintenance	LH172	Secondary	LOW	\$ -
OB726	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87739	151.14852	1		notify business/property owner	LH172	Secondary	LOW	\$ -
OB727	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.87731	151.148564	1		refer to maintenance	LH172	Secondary	LOW	\$ -
OB728	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.877411	151.148639	1		notify business/property owner	LH172	Secondary	LOW	\$ -
OB729	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877551	151.150066	1		refer to maintenance	LH172	Secondary	LOW	\$ -
OB73	Cissod Street	Ashfield	Local Road	obstruction	signposts narrows footpath	-33.886682	151.128664	1		relocate signpost	LH176	Secondary	LOW	\$ 300
OB730	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation - property	-33.877628	151.150542	1		notify business/property owner	LH172	Secondary	LOW	\$ -
OB731	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877799	151.151267	1		refer to maintenance	LH173	Secondary	LOW	\$ -
OB732	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation narrows footpath	-33.877733	151.151597	1		refer to maintenance	LH173	Secondary	LOW	\$ -
OB733	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877328	151.150727	1		refer to maintenance	LH173	Secondary	LOW	\$ -
OB734	William Street	Leichhardt	Local Road	obstruction	overhanging vegetation	-33.877305	151.155863	1		refer to maintenance	LH175	Secondary	LOW	\$ -
OB735	Carrington Road	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.891402	151.147883	1		refer to maintenance	LW28	Secondary	LOW	\$ -
OB736	Carrington Street	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.890828	151.147859	1		notify business/property owner	LW28	Secondary	LOW	\$ -
OB737	Fraser Street	Lewisham	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.89068	151.148864	1		notify business/property owner	OB17	Tertiary	LOW	\$ -
OB738	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath	-33.897065	151.147734	1		refer to maintenance	LW13	Primary	LOW	\$ -
OB739	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation - property	-33.897363	151.147525	1		notify business/property owner	LW13	Primary	LOW	\$ -
OB74	Cissod Street	Ashfield	Local Road	obstruction	signposts narrows footpath	-33.885704	151.128664	1		relocate signpost	AF50	Secondary	LOW	\$ 300
OB740	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation - property	-33.897677	151.147168	1		notify business/property owner	LW13	Primary	LOW	\$ -
OB741	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath	-33.898369	151.148304	1		refer to maintenance	LW15	Primary	LOW	\$ -
OB742	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.898915	151.145611	1		notify business/property owner	LW16	Primary	LOW	\$ -
OB743	New Canterbury Road	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath	-33.899125	151.145362	1		refer to maintenance	LW16	Primary	LOW	\$ -
OB744	Wardell Road	Lewisham	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.898564	151.149149	1		refer to maintenance	LW36	Secondary	LOW	\$ -
OB745	Thomas Street	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891968	151.147687	1		notify business/property owner	LW33	Primary	LOW	\$ -
OB746	Thomas Street	Lewisham	Local Road	obstruction	overhanging vegetation narrows footpath	-33.893233	151.148029	1		refer to maintenance	LW34	Primary	LOW	\$ -
OB747	Toothill Street	Lewisham	Regional Road	obstruction	double pole signpost narrows footpath	-33.897043	151.148533	1		review and relocate double pole signpost	LW35	Secondary	LOW	\$ 500
OB748	Toothill Street	Lewisham	Regional Road	obstruction	signposts narrow footpath	-33.897168	151.146693	1		relocate signpost	LW35	Secondary	LOW	\$ 300
OB749	Toothill Street	Lewisham	Regional Road	obstruction	double pole signpost narrows footpath	-33.897148	151.146712	1		review and relocate double pole signpost	LW35	Secondary	LOW	\$ 500
OB75	Cissod Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.886602	151.128213	1		notify business/property owner	AF50	Secondary	LOW	\$ -
OB750	Old Canterbury Road	Lewisham	State Road	obstruction	power pole narrows footpath	-33.89336	151.145886	1		no action	LW18	Secondary	LOW	\$ -
OB751	Trafalgar Street	Lewisham	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.892952	151.145657	1		refer to maintenance	LW22	Primary	LOW	\$ -
OB752	Railway Terrace	Lewisham	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.893696	151.148338	1		notify business/property owner	LW34	Primary	LOW	\$ -
OB753	Balmn Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.876089	151.160799	1		notify business/property owner	LH15	Secondary	LOW	\$ -
OB754	Balmn Road	Lilyfield	Regional Road	obstruction	power pole narrows footpath	-33.876182	151.160735	1		no action	LH15	Secondary	LOW	\$ -
OB755	Balmn Road	Lilyfield	State Road	obstruction	power pole narrows footpath	-33.866251	151.166295	1		no action	LH3	Primary	LOW	\$ -
OB756	Balmn Road	Lilyfield	State Road	obstruction	power pole narrows footpath	-33.870599	151.161142	1		no action	LH7	Secondary	LOW	\$ -
OB757	Balmn Road	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.870543	151.161463	1		notify business/property owner	LH8	Secondary	LOW	\$ -
OB758	Balmn Road	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.870271	151.161744	1		notify business/property owner	LH8	Secondary	LOW	\$ -
OB759	Balmn Road	Lilyfield	State Road	obstruction	power pole narrows footpath	-33.869514	151.162561	1		no action	LH2	Secondary	LOW	\$ -
OB76	Cissod Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895648	151.126698	1		notify business/property owner	AF48	Secondary	LOW	\$ -
OB760	Balmn Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873334	151.160227	1		refer to maintenance	LH16	Secondary	LOW	\$ -
OB761	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.872232	151.151135	1		refer to maintenance	LF13	Tertiary	LOW	\$ -
OB762	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872283	151.151253	1		notify business/property owner	LF13	Tertiary	LOW	\$ -
OB763	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.872039	151.151435	1		refer to maintenance	LF12	Secondary	LOW	\$ -
OB764	Bay Run	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.86724	151.152062	1		refer to maintenance	LF24	Secondary	LOW	\$ -
OB765	Catherine Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876051	151.164842	1		notify business/property owner	LF40	Primary	LOW	\$ -
OB766	City West Link Bridge	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.874587	151.154886	1		refer to maintenance	LF59	Secondary	LOW	\$ -
OB767	Darley Road	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.875382	151.152646	1		notify business/property owner	LH33	Secondary	LOW	\$ -
OB768	Glover Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869779	151.156689	1		notify business/property owner	LF50	Secondary	LOW	\$ -
OB769	Glover Street	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.869878	151.156606	1		notify business/property owner	LF50	Secondary	LOW	\$ -
OB77	Cissod Street	Ashfield	Local Road	obstruction	overhanging vegetation - property	-33.895588	151.127214	1		notify business/property owner	AF48	Secondary	LOW	\$ -
OB770	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.871561	151.164908	1		refer to maintenance	LF55	Tertiary	LOW	\$ -
OB771	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872152	151.164332	1		notify business/property owner	LF55	Tertiary	LOW	\$ -
OB772	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872322	151.164373	1		notify business/property owner	LF54	Secondary	LOW	\$ -
OB773	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872779	151.164541	1		notify business/property owner	LF54	Secondary	LOW	\$ -
OB774	Grove Street	Lilyfield	Local Road	obstruction	signpost narrows footpath	-33.869619	151.163504	1		relocate signpost	LF53	Secondary	LOW	\$ 300
OB775	Grove Street	Lilyfield	Local Road	obstruction	signpost narrows footpath	-33.869213	151.163257	1		relocate signpost	LF53	Secondary	LOW	\$ 300
OB776	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.869936	151.163536	1		notify business/property owner	LF53	Secondary	LOW	\$ -
OB777	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.870233	151.163608	1		refer to maintenance	LF56	Tertiary	LOW	\$ -
OB778	Grove Street	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.871071	151.163917	1		refer to maintenance	LF56	Tertiary	LOW	\$ -
OB779	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.874012	151.155168	1		notify business/property owner	LF58	Secondary	LOW	\$ -
OB78	Cissod Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.895568	151.126896	1		notify business/property owner	AF50	Secondary	LOW	\$ -
OB780	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.873775	151.155137	1		notify business/property owner	LF58	Secondary	LOW	\$ -
OB781	James Street	Lilyfield	State Road	obstruction	overhanging vegetation - property	-33.873788	151.155144	1		notify business/property owner	LF58	Secondary	LOW	\$ -
OB782	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.874194	151.155202	1		refer to maintenance	LF58	Secondary	LOW	\$ -
OB783	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.874441	151.155054	1		notify business/property owner	LF59	Secondary	LOW	\$ -
OB784	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.874189	151.155							

P4909 Inner West PAMP Detailed Works Program Obstructions 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB785	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.874027	151.155007	1	1	refer to maintenance	LF58	Secondary	LOW	\$ -
OB786	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.873879	151.154994	1	1	refer to maintenance	LF58	Secondary	LOW	\$ -
OB787	James Street	Lilyfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.873584	151.154951	1	1	notify business/property owner	LF58	Secondary	LOW	\$ -
OB788	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.872098	151.165203	1	1	notify business/property owner	LF74	Secondary	LOW	\$ -
OB789	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873187	151.165051	1	1	refer to maintenance	LF71	Secondary	LOW	\$ -
OB790	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.880209	151.128866	1	1	notify business/property owner	AF62	Primary	LOW	\$ -
OB791	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873138	151.165365	1	1	refer to maintenance	LF71	Secondary	LOW	\$ -
OB792	Lilyfield Road	Lilyfield	Regional Road	obstruction	power pole narrows footpath	-33.872445	151.167117	1	1	no action	LF73	Secondary	LOW	\$ -
OB793	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.872652	151.167478	1	1	refer to maintenance	LF73	Secondary	LOW	\$ -
OB794	Lilyfield Road	Lilyfield	Regional Road	obstruction	double pole signpost narrows footpath	-33.871988	151.168777	1	1	relocate signpost	LF75	Secondary	LOW	\$ 300
OB795	Lilyfield Road	Lilyfield	Regional Road	obstruction	power pole narrows path	-33.871775	151.169227	1	1	no action	LF75	Secondary	LOW	\$ -
OB796	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873421	151.163703	1	1	refer to maintenance	LF68	Secondary	LOW	\$ -
OB797	Lilyfield Road	Lilyfield	Regional Road	obstruction	signposts narrows footpath	-33.873217	151.164339	1	1	relocate signpost	LF68	Secondary	LOW	\$ 300
OB798	Lilyfield Road	Lilyfield	Regional Road	obstruction	double pole signpost narrows footpath	-33.873605	151.163396	1	1	review and relocate double pole signpost	LF68	Secondary	LOW	\$ 500
OB799	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.872739	151.162934	1	1	refer to maintenance	LF70	Secondary	LOW	\$ -
OB800	Lilyfield Road	Lilyfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.873857	151.162346	1	1	refer to maintenance	LF70	Secondary	LOW	\$ -
OB801	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876903	151.175089	1	1	notify business/property owner	AN68	Secondary	LOW	\$ -
OB802	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.887211	151.126662	1	1	notify business/property owner	AF62	Primary	LOW	\$ -
OB803	Lilyfield Road	Lilyfield	Regional Road	obstruction	power pole narrows footpath	-33.873914	151.162121	1	1	no action	LF70	Secondary	LOW	\$ -
OB804	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.874315	151.160396	1	1	notify business/property owner	LF64	Tertiary	LOW	\$ -
OB805	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.874273	151.157977	1	1	notify business/property owner	LF67	Secondary	LOW	\$ -
OB806	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.874397	151.158322	1	1	notify business/property owner	LF67	Secondary	LOW	\$ -
OB807	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.874185	151.157562	1	1	refer to maintenance	LF66	Secondary	LOW	\$ -
OB808	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873881	151.156454	1	1	notify business/property owner	LF66	Secondary	LOW	\$ -
OB809	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873639	151.156337	1	1	notify business/property owner	LF65	Secondary	LOW	\$ -
OB810	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.873468	151.154889	1	1	notify business/property owner	LF63	Secondary	LOW	\$ -
OB811	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873181	151.153884	1	1	notify business/property owner	LF60	Tertiary	LOW	\$ -
OB812	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.873135	151.153758	1	1	refer to maintenance	LF60	Tertiary	LOW	\$ -
OB813	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.88629	151.126217	1	1	notify business/property owner	AF63	Secondary	LOW	\$ -
OB814	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.872746	151.152368	1	1	notify business/property owner	LF61	Tertiary	LOW	\$ -
OB815	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.872322	151.151512	1	1	refer to maintenance	LF13	Tertiary	LOW	\$ -
OB816	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath	-33.873253	151.154655	1	1	refer to maintenance	LF63	Secondary	LOW	\$ -
OB817	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.873565	151.155698	1	1	notify business/property owner	LF65	Secondary	LOW	\$ -
OB818	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation - property	-33.873889	151.156934	1	1	notify business/property owner	LF66	Secondary	LOW	\$ -
OB819	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation	-33.873998	151.157295	1	1	refer to maintenance	LF66	Secondary	LOW	\$ -
OB820	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation	-33.8743	151.158447	1	1	refer to maintenance	LF67	Secondary	LOW	\$ -
OB821	Lilyfield Road	Lilyfield	Local Road	obstruction	overhanging vegetation	-33.8743	151.158447	1	1	refer to maintenance	LF67	Secondary	LOW	\$ -
OB822	Piper Street	Lilyfield	Local Road	obstruction	overhanging vegetation	-33.8743	151.158447	1	1	refer to maintenance	LF67	Secondary	LOW	\$ -
OB823	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.870898	151.154604	1	1	notify business/property owner	LF85	Tertiary	LOW	\$ -
OB824	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.872722	151.155718	1	1	notify business/property owner	LF79	Secondary	LOW	\$ -
OB825	Warren Road	Marrickville	Local Road	obstruction	power pole narrows footpath	-33.88412	151.125341	1	1	no action	AF63	Secondary	LOW	\$ -
OB826	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.872327	151.156564	1	1	refer to maintenance	LF87	Secondary	LOW	\$ -
OB827	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.876763	151.156991	1	1	notify business/property owner	LF95	Tertiary	LOW	\$ -
OB828	Warren Road	Marrickville	Local Road	obstruction	power pole narrows footpath	-33.875762	151.161782	1	1	no action	LF90	Tertiary	LOW	\$ -
OB829	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918388	151.154696	1	1	refer to maintenance	MV250	Tertiary	LOW	\$ -
OB830	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.918475	151.154747	1	1	notify business/property owner	MV247	Tertiary	LOW	\$ -
OB831	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918735	151.154628	1	1	refer to maintenance	MV247	Tertiary	LOW	\$ -
OB832	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.916279	151.154346	1	1	notify business/property owner	MV250	Tertiary	LOW	\$ -
OB833	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.916114	151.1541	1	1	notify business/property owner	MV250	Tertiary	LOW	\$ -
OB834	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.918064	151.154007	1	1	notify business/property owner	MV250	Tertiary	LOW	\$ -
OB835	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.916709	151.151528	1	1	refer to maintenance	MF248	Secondary	LOW	\$ -
OB836	Warren Road	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.888726	151.125849	1	1	notify business/property owner	AF63	Secondary	LOW	\$ -
OB837	Warren Road	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.914731	151.148016	1	1	no action	MV244	Secondary	LOW	\$ -
OB838	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914028	151.146978	1	1	notify business/property owner	MV243	Secondary	LOW	\$ -
OB839	Warren Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913988	151.146752	1	1	notify business/property owner	MV243	Secondary	LOW	\$ -
OB840	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911539	151.145637	1	1	refer to maintenance	MV13	Tertiary	LOW	\$ -
OB841	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.911536	151.145186	1	1	notify business/property owner	MV13	Tertiary	LOW	\$ -
OB842	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911571	151.145329	1	1	refer to maintenance	MV13	Tertiary	LOW	\$ -
OB843	Albermarle Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.912495	151.146797	1	1	refer to maintenance	MV12	Tertiary	LOW	\$ -
OB844	Beauchamp Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914656	151.143099	1	1	refer to maintenance	MV16	Secondary	LOW	\$ -
OB845	Beauchamp Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913717	151.146164	1	1	notify business/property owner	MV14	Secondary	LOW	\$ -
OB846	Byrnes Street	Marrickville	Local Road	obstruction	power pole narrows footpath	-33.913723	151.155388	1	1	no action	MV188	Secondary	LOW	\$ -
OB847	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.888664	151.130349	1	1	notify business/property owner	AF64	Secondary	LOW	\$ -
OB848	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.912657	151.156981	1	1	notify business/property owner	MV21	Secondary	LOW	\$ -
OB849	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.913012	151.157571	1	1	refer to maintenance	MV19	Secondary	LOW	\$ -
OB850	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913151	151.157843	1	1	notify business/property owner	MV19	Secondary	LOW	\$ -
OB851	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913369	151.158265	1	1	notify business/property owner	MV22	Secondary	LOW	\$ -
OB852	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913488	151.158476	1	1	notify business/property owner	MV22	Secondary	LOW	\$ -
OB853	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.913547	151.158884	1	1	refer to maintenance	MV22	Secondary	LOW	\$ -
OB854	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.913007	151.167811	1	1	notify business/property owner	MV19	Secondary	LOW	\$ -
OB855	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912872	151.157538	1	1	refer to maintenance	MV19	Secondary	LOW	\$ -
OB856	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.912278	151.158453	1	1	notify business/property owner	MV20	Secondary	LOW	\$ -
OB857	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911941	151.158923	1	1	notify business/property owner	MV20	Secondary	LOW	\$ -
OB858	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.888988	151.130359	1	1	notify business/property owner	AF64	Secondary	LOW	\$ -
OB859	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.911844	151.155746	1	1	notify business/property owner	MV20	Secondary	LOW	\$ -
OB860	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911709	151.155633	1	1	refer to maintenance	MV20	Secondary	LOW	\$ -
OB861	Calvert Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.912146	151.156149	1	1	notify business/property owner	MV20	Secondary	LOW	\$ -
OB862	Carrington Road	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.916391	151.158055	1	1	notify business/property owner	MV26	Tertiary	LOW	\$ -
OB863	Chapel Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905581	151.162287	1	1	notify business/property owner	MV31	Tertiary	LOW	\$ -
OB864	Chapel Street	Marrickville	Local Road	obstruction	double pole signpost narrows footpath	-33.905948	151.162876	1	1	review and relocate double pole signpost	MV32	Secondary	LOW	\$ 500
OB865	Edgeware Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.905259	151.173349	1	1	notify business/property owner	NE24	Primary	LOW	\$ -
OB866	Edinburgh Road	Marrickville	Local Road	obstruction	tree narrows footpath	-33.907881	151.170541	1	1	no action	MV58	Secondary	LOW	\$ -
OB867	Edinburgh Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908046	151.170529	1	1	notify business/property owner	MV58	Secondary	LOW	\$ -
OB868	Edinburgh Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907463	151.169685	1	1	notify business/property owner	MV57	Secondary	LOW	\$ -
OB869	Elizabeth Street	Ashfield	Regional Road	obstruction	signpost narrows footpath	-33.889164	151.131511	1	1	relocate signpost	AF61	Secondary	LOW	\$ 300
OB870	Edinburgh Road	Marrickville	Local Road	obstruction	bollards narrows footpath	-33.90706	151.169123	1	1	widen footpath	MV56	Tertiary	LOW	\$ 200
OB871	Edinburgh Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905777	151.167442	1	1	refer to maintenance	MV56	Tertiary	LOW	\$ -
OB872	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation - property	-33.909007	151.162856	1	1	notify business/property owner	MV210	Secondary	LOW	\$ -
OB873	Ewart Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.912294	151.149312	1	1	notify business/property owner	MV66	Primary	LOW	\$ -
OB874	Ewart Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914043	151.142168	1	1	notify business/property owner	MV68	Secondary	LOW	\$ -
OB875	Ewart Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914246	151.142666							

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB869	Fitzroy Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906996	151.168475	1	1	notify business/property owner	MV70	Tertiary	LOW	\$ -
OB87	Elizabeth Street	Ashfield	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.888224	151.129167	1	1	notify business/property owner	AF63	Secondary	LOW	\$ -
OB870	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.901263	151.152976	1	1	refer to maintenance	MV75	Secondary	LOW	\$ -
OB871	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901186	151.155275	1	1	notify business/property owner	MV76	Secondary	LOW	\$ -
OB872	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901119	151.149385	1	1	notify business/property owner	PE20	Secondary	LOW	\$ -
OB873	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901096	151.148359	1	1	notify business/property owner	PE20	Secondary	LOW	\$ -
OB874	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.901033	151.150023	1	1	refer to maintenance	PE20	Secondary	LOW	\$ -
OB875	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.901033	151.150322	1	1	refer to maintenance	MV76	Secondary	LOW	\$ -
OB876	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.901051	151.150767	1	1	refer to maintenance	MV76	Secondary	LOW	\$ -
OB877	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.901063	151.15121	1	1	refer to maintenance	MV77	Secondary	LOW	\$ -
OB878	Frazer Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.901186	151.153019	1	1	notify business/property owner	MV75	Secondary	LOW	\$ -
OB879	Hawkhurst Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.905598	151.153886	1	1	refer to maintenance	MV78	Secondary	LOW	\$ -
OB88	Frederick Street	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.882457	151.121499	1	1	notify business/property owner	AF74	Secondary	LOW	\$ -
OB880	Hawkhurst Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905103	151.155486	1	1	notify business/property owner	MV29	Secondary	LOW	\$ -
OB881	Hawkhurst Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.904656	151.156292	1	1	refer to maintenance	MV29	Secondary	LOW	\$ -
OB882	Hawkhurst Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.905392	151.155274	1	1	refer to maintenance	MV29	Secondary	LOW	\$ -
OB883	Hawkhurst Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905774	151.154681	1	1	notify business/property owner	MV78	Secondary	LOW	\$ -
OB884	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.907348	151.159417	1	1	notify business/property owner	MV82	Tertiary	LOW	\$ -
OB885	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906955	151.159774	1	1	notify business/property owner	MV82	Tertiary	LOW	\$ -
OB886	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906968	151.159597	1	1	notify business/property owner	MV82	Tertiary	LOW	\$ -
OB887	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906887	151.159662	1	1	notify business/property owner	MV82	Tertiary	LOW	\$ -
OB888	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.906011	151.160423	1	1	notify business/property owner	MV84	Secondary	LOW	\$ -
OB889	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.905914	151.160508	1	1	notify business/property owner	MV84	Secondary	LOW	\$ -
OB89	Frederick Street	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.880331	151.123169	1	1	notify business/property owner	AF71	Primary	LOW	\$ -
OB890	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.904599	151.161174	1	1	refer to maintenance	MV79	Secondary	LOW	\$ -
OB891	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.904566	151.161566	1	1	notify business/property owner	MV79	Secondary	LOW	\$ -
OB892	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.904464	151.161846	1	1	notify business/property owner	MV79	Secondary	LOW	\$ -
OB893	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.903943	151.162245	1	1	notify business/property owner	MV86	Tertiary	LOW	\$ -
OB894	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.903184	151.162886	1	1	refer to maintenance	MV86	Tertiary	LOW	\$ -
OB895	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902965	151.163082	1	1	refer to maintenance	MV85	Secondary	LOW	\$ -
OB896	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902751	151.162976	1	1	refer to maintenance	MV85	Secondary	LOW	\$ -
OB897	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.902736	151.163059	1	1	refer to maintenance	MV85	Secondary	LOW	\$ -
OB898	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.902621	151.158432	1	1	notify business/property owner	MV87	Tertiary	LOW	\$ -
OB899	Ilwarrara Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.908506	151.155371	1	1	notify business/property owner	MV81	Secondary	LOW	\$ -
OB9	Nelson Street	Annandale	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.87628	151.175276	1	1	notify business/property owner	AN67	Secondary	LOW	\$ -
OB90	Frederick Street	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath	-33.87717	151.12922	1	1	refer to maintenance	AF68	Secondary	LOW	\$ -
OB901	Ilwarrara Road	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.916728	151.144911	1	1	notify business/property owner	MV101	Primary	LOW	\$ -
OB901	Ilwarrara Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.919026	151.145448	1	1	refer to maintenance	MV101	Secondary	LOW	\$ -
OB902	Ilwarrara Road	Marrickville	Regional Road	obstruction	signpost narrows footpath	-33.920016	151.144739	1	1	relocate signpost	MV102	Secondary	LOW	\$ 300
OB903	Ilwarrara Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.919951	151.144795	1	1	notify business/property owner	MV102	Secondary	LOW	\$ -
OB904	Ilwarrara Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.917379	151.148695	1	1	notify business/property owner	MV98	Primary	LOW	\$ -
OB905	Ilwarrara Road	Marrickville	Regional Road	obstruction	signpost narrows footpath	-33.912874	151.153958	1	1	relocate signpost	MV91	Primary	LOW	\$ 300
OB906	Kays Avenue	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.911376	151.144374	1	1	refer to maintenance	MV105	Tertiary	LOW	\$ -
OB907	Livingstone Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.901172	151.153469	1	1	refer to maintenance	PE27	Primary	LOW	\$ -
OB908	Livingstone Road	Marrickville	State Road	obstruction	overhanging vegetation - local road	-33.90366	151.152976	1	1	refer to maintenance	MV78	Secondary	LOW	\$ -
OB909	Livingstone Road	Marrickville	Local Road	obstruction	overhanging vegetation	-33.907288	151.152861	1	1	refer to maintenance	MV115	Secondary	LOW	\$ -
OB91	Thomas Street	Ashfield	Regional Road	obstruction	signposts narrows footpath	-33.886592	151.118638	1	1	relocate signpost	AF157	Secondary	LOW	\$ 300
OB910	Livingstone Road	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.907168	151.152747	1	1	refer to maintenance	MV115	Secondary	LOW	\$ -
OB911	Livingstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.906865	151.152797	1	1	refer to maintenance	MV114	Secondary	LOW	\$ -
OB912	Livingstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.911332	151.148692	1	1	notify business/property owner	MV106	Secondary	LOW	\$ -
OB913	Livingstone Road	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.912215	151.147886	1	1	notify business/property owner	MV116	Secondary	LOW	\$ -
OB914	Livingstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.910596	151.150372	1	1	notify business/property owner	MV121	Primary	LOW	\$ -
OB915	Livingstone Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.910385	151.150604	1	1	notify business/property owner	MV120	Primary	LOW	\$ -
OB916	Llewellyn Street	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.904144	151.17143	1	1	notify business/property owner	MV125	Secondary	LOW	\$ -
OB917	Llewellyn Street	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.904168	151.170888	1	1	refer to maintenance	MV126	Secondary	LOW	\$ -
OB918	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.907448	151.148095	1	1	notify business/property owner	MV143	Tertiary	LOW	\$ -
OB919	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.907268	151.147581	1	1	notify business/property owner	MV142	Secondary	LOW	\$ -
OB92	Milton Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.890428	151.117081	1	1	notify business/property owner	AF114	Primary	LOW	\$ -
OB920	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.9074	151.148534	1	1	notify business/property owner	MV143	Tertiary	LOW	\$ -
OB921	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.907463	151.148992	1	1	notify business/property owner	MV144	Secondary	LOW	\$ -
OB922	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation - property	-33.908167	151.151072	1	1	notify business/property owner	MV127	Secondary	LOW	\$ -
OB923	Marrickville Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.915134	151.164484	1	1	refer to maintenance	MV131	Primary	LOW	\$ -
OB924	Marrickville Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.914997	151.164296	1	1	refer to maintenance	MV131	Primary	LOW	\$ -
OB925	Marrickville Road	Marrickville	Regional Road	obstruction	vehicle narrows footpath	-33.914179	151.162561	1	1	no action	MV130	Primary	LOW	\$ -
OB926	Marrickville Road	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.908886	151.152626	1	1	refer to maintenance	MV138	Primary	LOW	\$ -
OB927	Marrickville Road	Marrickville	Regional Road	obstruction	bollard narrows footpath	-33.913008	151.161566	1	1	relocate or remove bollard	MV128	Secondary	LOW	\$ 2,500
OB928	Myrtle Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.915683	151.152929	1	1	notify business/property owner	MV147	Tertiary	LOW	\$ -
OB929	Myrtle Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.915879	151.15766	1	1	refer to maintenance	MV147	Tertiary	LOW	\$ -
OB93	Milton Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.889284	151.117227	1	1	notify business/property owner	AF113	Primary	LOW	\$ -
OB930	Newington Road	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.901037	151.167243	1	1	refer to maintenance	MV156	Tertiary	LOW	\$ -
OB931	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.921063	151.153665	1	1	refer to maintenance	MV169	Secondary	LOW	\$ -
OB932	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.919357	151.150519	1	1	refer to maintenance	MV163	Secondary	LOW	\$ -
OB933	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.919115	151.150137	1	1	notify business/property owner	MV163	Secondary	LOW	\$ -
OB934	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.918897	151.149773	1	1	notify business/property owner	MV158	Tertiary	LOW	\$ -
OB935	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.918701	151.149438	1	1	refer to maintenance	MV158	Tertiary	LOW	\$ -
OB936	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918459	151.148984	1	1	refer to maintenance	MV158	Tertiary	LOW	\$ -
OB937	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.918403	151.14883	1	1	notify business/property owner	MV158	Tertiary	LOW	\$ -
OB938	Premier Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.917973	151.147696	1	1	refer to maintenance	MV160	Tertiary	LOW	\$ -
OB939	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation	-33.918543	151.153104	1	1	refer to maintenance	MV167	Tertiary	LOW	\$ -
OB94	Milton Road	Ashfield	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.889002	151.117274	1	1	notify business/property owner	AF112	Primary	LOW	\$ -
OB940	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.91927	151.154084	1	1	notify business/property owner	MV169	Tertiary	LOW	\$ -
OB941	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation - local road	-33.918435	151.153698	1	1	refer to maintenance	MV167	Tertiary	LOW	\$ -
OB942	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.918435	151.152608	1	1	refer to maintenance	MV167	Tertiary	LOW	\$ -
OB943	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.917583	151.15105	1	1	notify business/property owner	MV170	Secondary	LOW	\$ -
OB944	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.917477	151.150891	1	1	notify business/property owner	MV170	Secondary	LOW	\$ -
OB945	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.916983	151.149973	1	1	refer to maintenance	MV168	Secondary	LOW	\$ -
OB946	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.916918	151.149864	1	1	notify business/property owner	MV168	Secondary	LOW	\$ -
OB947	Renwick Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.916769	151.149747	1	1	refer to maintenance	MV168	Secondary	LOW	\$ -
OB948	Richardson Crescent	Marrickville	Local Road	obstruction	power pole narrows footpath	-33.921144	151.156634	1	1	no action	MV173	Tertiary	LOW	\$ -
OB949	Richardson Crescent	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.921979	151.156755	1	1	refer to maintenance	TE14	Secondary	LOW	\$ -
OB95	Milton Road	Ashfield</												

**P4909 Inner West PAMP
Detailed Works Program
Obstructions
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
OB952	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921508	151.156106	1	1	refer to maintenance	MV174	Tertiary	LOW	\$ -
OB953	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921377	151.155953	1	1	refer to maintenance	MV174	Tertiary	LOW	\$ -
OB954	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921263	151.155887	1	1	refer to maintenance	MV174	Tertiary	LOW	\$ -
OB955	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.921081	151.155735	1	1	refer to maintenance	MV173	Tertiary	LOW	\$ -
OB956	Richardson Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.920418	151.155122	1	1	refer to maintenance	MV173	Tertiary	LOW	\$ -
OB957	Richardson Crescent	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.923282	151.156214	1	1	refer to maintenance	MV175	Secondary	LOW	\$ -
OB958	Richardson Crescent	Marrickville	Regional Road	obstruction	power pole narrows footpath	-33.922291	151.1563	1	1	no action	MV175	Secondary	LOW	\$ -
OB959	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914961	151.142222	1	1	notify business/property owner	MV176	Tertiary	LOW	\$ -
OB96	Milton Road	Ashfield	State Road	obstruction	overgrown vegetation narrows footpath	-33.889836	151.117333	1	1	refer to maintenance	AF113	Primary	LOW	\$ -
OB960	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914865	151.140475	1	1	notify business/property owner	MV180	Tertiary	LOW	\$ -
OB961	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914836	151.140297	1	1	notify business/property owner	MV180	Tertiary	LOW	\$ -
OB962	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.915006	151.141165	1	1	refer to maintenance	MV179	Tertiary	LOW	\$ -
OB963	Riverside Crescent	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.915033	151.141389	1	1	refer to maintenance	MV179	Tertiary	LOW	\$ -
OB964	Shirlow Street	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.912388	151.166367	1	1	no action	MV185	Secondary	LOW	\$ -
OB965	Shirlow Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.911818	151.167053	1	1	notify business/property owner	MV183	Tertiary	LOW	\$ -
OB966	Shirlow Street	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.911527	151.167444	1	1	no action	MV183	Tertiary	LOW	\$ -
OB967	Shirlow Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.911702	151.167247	1	1	notify business/property owner	MV183	Tertiary	LOW	\$ -
OB968	Smidmore Street	Marrickville	Local Road	obstruction	vehicle narrows footpath	-33.907642	151.174176	1	1	no action	NE21	Primary	LOW	\$ -
OB969	Smidmore Street	Marrickville	Local Road	obstruction	concrete structure obstructs crossing	-33.907766	151.171847	1	1	consult with Marrickville Metro	MV50	Primary	LOW	\$ -
OB97	Holden Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.891959	151.1254	1	1	notify business/property owner	AF86	Primary	LOW	\$ -
OB970	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.914187	151.153996	1	1	notify business/property owner	MV186	Secondary	LOW	\$ -
OB971	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath	-33.914456	151.154904	1	1	refer to maintenance	MV188	Secondary	LOW	\$ -
OB972	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914533	151.155443	1	1	notify business/property owner	MV188	Secondary	LOW	\$ -
OB973	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.914619	151.155771	1	1	notify business/property owner	MV187	Secondary	LOW	\$ -
OB974	Station Street	Marrickville	Local Road	obstruction	overhanging vegetation - property	-33.9147	151.155966	1	1	notify business/property owner	MV187	Secondary	LOW	\$ -
OB975	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.908591	151.169504	1	1	refer to maintenance	MV192	Secondary	LOW	\$ -
OB976	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.907234	151.158667	1	1	refer to maintenance	MV195	Secondary	LOW	\$ -
OB977	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.90903	151.160938	1	1	notify business/property owner	MV192	Secondary	LOW	\$ -
OB978	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.908311	151.159998	1	1	refer to maintenance	MV193	Secondary	LOW	\$ -
OB979	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath	-33.908272	151.159936	1	1	refer to maintenance	MV193	Secondary	LOW	\$ -
OB98	Holden Street	Ashfield	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.892059	151.125396	1	1	notify business/property owner	AF86	Primary	LOW	\$ -
OB980	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.90685	151.158349	1	1	notify business/property owner	MV196	Primary	LOW	\$ -
OB981	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.905486	151.157294	1	1	notify business/property owner	MV197	Primary	LOW	\$ -
OB982	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.904567	151.15637	1	1	notify business/property owner	MV190	Primary	LOW	\$ -
OB983	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.903658	151.155567	1	1	notify business/property owner	MV190	Primary	LOW	\$ -
OB984	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.902602	151.154487	1	1	refer to maintenance	MV199	Primary	LOW	\$ -
OB985	Sydenham Road	Marrickville	State Road	obstruction	light post narrows footpath	-33.902651	151.154384	1	1	relocate light post	MV169	Primary	LOW	\$ 10,000
OB986	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation narrows footpath - property	-33.902192	151.154013	1	1	notify business/property owner	MV194	Primary	LOW	\$ -
OB987	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.912235	151.165501	1	1	refer to maintenance	MV204	Secondary	LOW	\$ -
OB988	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.910037	151.162667	1	1	refer to maintenance	MV200	Primary	LOW	\$ -
OB989	Sydenham Road	Marrickville	State Road	obstruction	overhanging vegetation	-33.909724	151.162443	1	1	refer to maintenance	MV200	Primary	LOW	\$ -
OB99	Holden Street	Ashfield	Local Road	obstruction	overhanging vegetation	-33.89726	151.125035	1	1	refer to maintenance	AF83	Tertiary	LOW	\$ -
OB990	Sydney Steel St	Marrickville	Local Road	obstruction	vehicles narrows footpath	-33.909861	151.169878	1	1	no action	MV207	Tertiary	LOW	\$ -
OB991	Sydney Steel St	Marrickville	Local Road	obstruction	tree narrows footpath	-33.908621	151.16996	1	1	no action	MV207	Tertiary	LOW	\$ -
OB992	Sydney Steel St	Marrickville	Local Road	obstruction	overhanging vegetation narrows footpath - property	-33.909077	151.170993	1	1	notify business/property owner	MV205	Secondary	LOW	\$ -
OB993	Victoria Road	Marrickville	Regional Road	obstruction	vehicle narrows footpath	-33.90558	151.166792	1	1	no action	MV213	Primary	LOW	\$ -
OB994	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.906036	151.165065	1	1	notify business/property owner	MV215	Secondary	LOW	\$ -
OB995	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath	-33.906514	151.164888	1	1	refer to maintenance	MV215	Secondary	LOW	\$ -
OB996	Victoria Road	Marrickville	Regional Road	obstruction	vehicle narrows footpath	-33.906804	151.163157	1	1	no action	MV210	Secondary	LOW	\$ -
OB997	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.910322	151.161569	1	1	refer to maintenance	MV219	Primary	LOW	\$ -
OB998	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation	-33.909929	151.162148	1	1	refer to maintenance	MV219	Primary	LOW	\$ -
OB999	Victoria Road	Marrickville	Regional Road	obstruction	overhanging vegetation narrows footpath - property	-33.909972	151.162099	1	1	notify business/property owner	MV219	Primary	LOW	\$ -
													SUBTOTAL	\$ 186,100
													TOTAL	\$ 186,100

**P4909 Inner West PAMP
Detailed Works Program
Safety Issues
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
SA102	Allen Street	Leichhardt	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.880031	151.15674	1	1	install raised continuous footpath treatment	LH222	Primary	HIGH	\$ 30,000
SA103	Balmain Road	Leichhardt	Regional Road	safety issue	opportunity to raise pedestrian crossing near school	-33.882073	151.158871	1	1	install raised pedestrian crossing	LH21	Primary	HIGH	\$ 50,000
SA104	Norton Street	Leichhardt	Regional Road	safety issue	potential HPAA	-33.883788	151.151073	1	1	investigate High Pedestrian Activity Area implementation	LH28	Primary	HIGH	\$ 20,000
SA105	Renwick Lane	Leichhardt	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.887881	151.151512	1	1	install raised continuous footpath treatment	LH131	Primary	HIGH	\$ 30,000
SA110	Balmain Road	Leichhardt	Regional Road	safety issue	steep crossfall	-33.878879	151.158911	1	1	re-construct footpath pavement	LH12	Primary	HIGH	\$ 200
SA111	Balmain Road	Leichhardt	Regional Road	safety issue	steep crossfall	-33.879236	151.159445	1	1	further investigation required - crossfall	LH12	Primary	HIGH	\$ -
SA112	Balmain Road	Leichhardt	Regional Road	safety issue	footlights orientated incorrectly	-33.882059	151.158871	1	1	adjust flood light orientation	LH21	Primary	HIGH	\$ 1,000
SA113	Balmain Road	Leichhardt	Regional Road	safety issue	vehicles approach crossing at speed	-33.882059	151.158873	1	1	install raised pedestrian crossing	LH21	Primary	HIGH	\$ 50,000
SA114	Derbyshire Road	Leichhardt	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.879642	151.158578	1	1	install raised pedestrian crossing	LH41	Secondary	HIGH	\$ 50,000
SA115	Flood Street	Leichhardt	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.885805	151.148843	1	1	install raised pedestrian crossing	LH89	Secondary	HIGH	\$ 50,000
SA116	Lords Road	Leichhardt	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.885707	151.148733	1	1	install raised pedestrian crossing	LH89	Primary	HIGH	\$ 50,000
SA12	Traralgon Street	Amandale	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.886017	151.170286	1	1	install raised pedestrian crossing	AN101	Secondary	HIGH	\$ 50,000
SA121	Hobb Street	Lewisham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.89413	151.14716	1	1	install raised continuous footpath treatment	LW25	Primary	HIGH	\$ 30,000
SA122	Hunter Street	Lewisham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.89382	151.148402	1	1	install raised continuous footpath treatment	LW7	Primary	HIGH	\$ 30,000
SA123	Jubilee Lane	Lewisham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.88911	151.147395	1	1	install raised continuous footpath treatment	LW25	Primary	HIGH	\$ 30,000
SA125	Thomas Street	Lewisham	Local Road	safety issue	missing lighting	-33.893268	151.148191	1	1	install new lighting	LW34	Primary	HIGH	\$ 10,000
SA126	Thomas Street	Lewisham	Local Road	safety issue	missing lighting	-33.893341	151.148383	1	1	install new lighting	LW34	Primary	HIGH	\$ 10,000
SA127	Tootill Street	Lewisham	Regional Road	safety issue	opportunity to raise pedestrian crossing near school	-33.895634	151.145199	1	1	install raised pedestrian crossing	LW36	Primary	HIGH	\$ 50,000
SA128	Victoria Street	Lewisham	Local Road	safety issue	potential HPAA	-33.893222	151.147588	1	1	investigate High Pedestrian Activity Area implementation	LW24	Primary	HIGH	\$ 20,000
SA130	Traralgon Street	Amandale	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.884188	151.171128	1	1	install raised pedestrian crossing	AN109	Secondary	HIGH	\$ 50,000
SA133	Perry Street	Lylfield	State Road	safety issue	opportunity to raise pedestrian crossing near school	-33.872037	151.157497	1	1	install raised pedestrian crossing	L788	Primary	HIGH	\$ 50,000
SA131	Arthur Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.913475	151.153168	1	1	install raised continuous footpath treatment	MV92	Primary	HIGH	\$ 30,000
SA132	Blamie Lane	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.91482	151.152535	1	1	install raised continuous footpath treatment	MV93	Primary	HIGH	\$ 30,000
SA133	Buckley Street	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing near public transport station	-33.914591	151.163849	1	1	install raised pedestrian crossing	MV131	Primary	HIGH	\$ 50,000
SA135	Carlingford Road	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.920681	151.154546	1	1	install raised pedestrian crossing	MV24	Secondary	HIGH	\$ 50,000
SA136	Church Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.915294	151.151074	1	1	install raised continuous footpath treatment	MV94	Primary	HIGH	\$ 30,000
SA138	Greenbank Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.914891	151.151923	1	1	install raised continuous footpath treatment	MV94	Primary	HIGH	\$ 30,000
SA139	Grove Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.915178	151.151824	1	1	install raised continuous footpath treatment	MV94	Primary	HIGH	\$ 30,000
SA142	Booth Street	Amandale	Regional Road	safety issue	potential HPAA	-33.881823	151.171774	1	1	investigate High Pedestrian Activity Area implementation	AN20	Primary	HIGH	\$ 20,000
SA143	Ilwarrara Road	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.915018	151.151616	1	1	install raised continuous footpath treatment	MV94	Primary	HIGH	\$ 30,000
SA141	Ilwarrara Road	Marrickville	Regional Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.914423	151.152654	1	1	install raised pedestrian crossing	MV93	Primary	HIGH	\$ 50,000
SA142	Ilwarrara Road	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.905623	151.162258	1	1	install raised pedestrian crossing	MV31	Secondary	HIGH	\$ 50,000
SA148	Truilly Lane	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.911808	151.156694	1	1	install raised continuous footpath treatment	MV98	Primary	HIGH	\$ 30,000
SA140	Warburton Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.914294	151.152623	1	1	install raised continuous footpath treatment	MV230	Primary	HIGH	\$ 30,000
SA153	Ilwarrara Road	Marrickville	Regional Road	safety issue	steep crossfall	-33.913886	151.152911	1	1	re-construct footpath pavement	MV92	Primary	HIGH	\$ 200
SA154	Ilwarrara Road	Marrickville	Regional Road	safety issue	corner obscures pedestrians	-33.911863	151.154956	1	1	install pavement warning message	MV90	Primary	HIGH	\$ 150
SA155	Ilwarrara Road	Marrickville	Regional Road	safety issue	corner obscures pedestrians	-33.911838	151.154956	1	1	install pavement warning message	MV90	Primary	HIGH	\$ 150
SA156	Ilwarrara Road	Marrickville	Regional Road	safety issue	vehicles approach crossing at speed	-33.911635	151.155267	1	1	install raised pedestrian crossing	MV90	Primary	HIGH	\$ 50,000
SA157	Ilwarrara Road	Marrickville	Regional Road	safety issue	missing pedestrian crossing signage	-33.911252	151.155622	1	1	install pedestrian crossing signage	MV98	Primary	HIGH	\$ 200
SA158	Ilwarrara Road	Marrickville	Regional Road	safety issue	potential HPAA	-33.910988	151.155913	1	1	investigate High Pedestrian Activity Area implementation	MV89	Primary	HIGH	\$ 20,000
SA159	Marrickville Road	Marrickville	State Road	safety issue	missing lighting	-33.914814	151.164091	1	1	install new lighting	MV131	Primary	HIGH	\$ 10,000
SA16	Chester Street	Amandale	Local Road	safety issue	steep crossfall	-33.884132	151.172892	1	1	further investigation required - crossfall	AN31	Primary	HIGH	\$ -
SA169	Sydenham Road	Marrickville	State Road	safety issue	substation obstructs pedestrian vehicle sight lines	-33.912566	151.165876	1	1	no action	MV203	Primary	HIGH	\$ -
SA17	Chester Street	Amandale	Local Road	safety issue	steep crossfall	-33.884138	151.172917	1	1	further investigation required - crossfall	AN31	Primary	HIGH	\$ -
SA171	Warford Road	Marrickville	Regional Road	safety issue	poor visibility of pedestrians from workshop, no warning of vehicular crossover	-33.911883	151.142093	1	1	install pavement warning message	MV238	Primary	HIGH	\$ 150
SA172	Schubel Street	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.914308	151.152821	1	1	install raised pedestrian crossing	MV189	Primary	HIGH	\$ 50,000
SA173	Bailey Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.894891	151.176874	1	1	install raised continuous footpath treatment	NE34	Primary	HIGH	\$ 30,000
SA174	Camden Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.891815	151.178556	1	1	install raised continuous footpath treatment	NE61	Primary	HIGH	\$ 30,000
SA175	Emmore Road	Newtown	State Road	safety issue	narrow footpath	-33.897385	151.178252	1	1	further investigation required - path widening	NE33	Primary	HIGH	\$ 30,000
SA176	Goddard Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.892886	151.177757	1	1	install raised continuous footpath treatment	NE49	Primary	HIGH	\$ 30,000
SA177	Holt Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.90011	151.178002	1	1	install raised continuous footpath treatment	NE38	Primary	HIGH	\$ 30,000
SA178	Lennox Street	Newtown	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.895516	151.178576	1	1	install raised pedestrian crossing	NE40	Secondary	HIGH	\$ 50,000
SA179	Marian Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.898978	151.172854	1	1	install raised continuous footpath treatment	EN7	Primary	HIGH	\$ 30,000
SA180	Collins Street	Amandale	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.884096	151.171073	1	1	install raised pedestrian crossing	AN32	Secondary	HIGH	\$ 50,000
SA182	Reiby Street	Newtown	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.898771	151.175237	1	1	install raised continuous footpath treatment	NE38	Primary	HIGH	\$ 30,000
SA181	Wells Street	Newtown	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.89471	151.176441	1	1	install raised pedestrian crossing	NE62	Secondary	HIGH	\$ 30,000
SA182	Edgeware Road	Newtown	Regional Road	safety issue	shared path signage conflict	-33.907574	151.174553	1	1	install shared path signage	NE21	Primary	HIGH	\$ 300
SA184	Emmore Road	Newtown	State Road	safety issue	pole blocks sight lines to high pedestrian traffic area	-33.898584	151.173613	1	1	no action	NE37	Primary	HIGH	\$ -
SA185	Emmore Road	Newtown	State Road	safety issue	pedestrian waiting area too small - narrowed by cafe seating	-33.897602	151.178472	1	1	review footpath trading	NE33	Primary	HIGH	\$ -
SA186	Eliza Street	Newtown	Local Road	safety issue	cars do not give way to pedestrians	-33.897214	151.178098	1	1	install new shared zone signage and delineation	NE12	Primary	HIGH	\$ 500
SA189	Laura Street	Newtown	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.905532	151.175576	1	1	install raised pedestrian crossing	NE62	Secondary	HIGH	\$ 50,000
SA19	Johnston Street	Amandale	State Road	safety issue	poor visibility of waiting pedestrians and crossing	-33.876017	151.17223	1	1	install kerb extension - pair	AN48	Primary	HIGH	\$ 20,000
SA190	Albert Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896168	151.158013	1	1	install raised continuous footpath treatment	PE57	Primary	HIGH	\$ 30,000
SA191	Audley Lane	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896271	151.153658	1	1	install raised continuous footpath treatment	PE38	Primary	HIGH	\$ 30,000
SA192	Balanaming Lane	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896411	151.153006	1	1	install raised continuous footpath treatment	PE33	Primary	HIGH	\$ 30,000
SA193	Church Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.895793	151.157631	1	1	install raised continuous footpath treatment	PE54	Primary	HIGH	\$ 30,000
SA194	Duross Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.897085	151.151391	1	1	install raised continuous footpath treatment	PE38	Primary	HIGH	\$ 30,000
SA195	Fisher Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.8955	151.154189	1	1	install raised continuous footpath treatment	PE38	Primary	HIGH	\$ 30,000
SA196	Hunter Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.897118	151.150675	1	1	install raised continuous footpath treatment	PE35	Primary	HIGH	\$ 30,000
SA197	Maria Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896808	151.152122	1	1	install raised continuous footpath treatment	PE34	Primary	HIGH	\$ 30,000
SA198	Marshall Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.896743	151.150675	1	1	install raised continuous footpath treatment	PE38	Primary	HIGH	\$ 30,000
SA199	Railway Terrace	Petersham	State Road	safety issue	review pedestrian and cyclist safety	-33.894082	151.148859	1	1	further investigation required - safety assessment	PE48	Primary	HIGH	\$ 5,000
SA2	Chester Street	Amandale	State Road	safety issue	vehicle encroachment on pedestrian areas	-33.884154	151.172842	1	1	install kerb blisters/ build outs	AN31	Primary	HIGH	\$ 10,000
SA20	Nelson Street	Amandale	Local Road	safety issue	steep crossfall	-33.863386	151.17322	1	1	re-construct footpath pavement	AN72	Primary	HIGH	\$ 500
SA201	Regent Street	Petersham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.895887	151.155459	1	1	install raised continuous footpath treatment	PE30	Primary	HIGH	\$ 30,000
SA201	West Street	Petersham	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.894885	151.150247	1	1	install raised pedestrian crossing	PE48	Primary	HIGH	\$ 50,000
SA202	West Street	Petersham	Regional Road	safety issue	opportunity to raise pedestrian crossing near school	-33.892415	151.148839	1	1	install raised pedestrian crossing	LW42	Primary	HIGH	\$ 50,000
SA203	Audley Street	Petersham	Local Road	safety issue	potential HPAA	-33.895932	151.156144	1	1	investigate High Pedestrian Activity Area implementation	PE38	Primary	HIGH	\$ 30,000
SA204	Regent Street	Petersham	Local Road	safety issue	vehicles obscures pedestrians	-33.895915	151.155436	1	1	install no stopping sign and signpost	PE30	Primary	HIGH	\$ 300
SA205	Stannmore Road	Petersham	State Road	safety issue	poor drainage - severe ponding	-33.895611	151.156994	1	1	refer to maintenance	PE54	Primary	HIGH	\$ -
SA208	Evans Street	Rozelle	Local Road	safety issue	crossover at the driveway is dangerous with vehicles approaching at speed	-33.865332	151.171842	1	1	install contrasting threshold	RO76	Primary	HIGH	\$ 5,000
SA209	Hamick Lane	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.88428	151.169671	1	1	install raised continuous footpath treatment	LF3	Primary	HIGH	\$ 30,000
SA21	Matilda Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.865959	151.16681	1	1	install raised continuous footpath treatment	LF3	Primary	HIGH	\$ 30,000
SA212	Merton Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.862348	151.171054	1	1	install raised continuous footpath treatment	RO23	Primary	HIGH	\$ 30,000
SA213	Merton Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.862293	151.170901	1	1	install raised continuous footpath treatment	RO18	Primary	HIGH	\$ 30,000
SA214	Nelson Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.861724	151.171136	1	1	install raised continuous footpath treatment	RO23	Primary	HIGH	

P4909 Inner West PAMP Detailed Works Program Safety Issues 6 August 2021

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
SA225	Cavendish Street	Stammore	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.895955	151.163869	1	1	install raised pedestrian crossing	SM35	Primary	HIGH	\$ 50,000
SA226	Holt Street	Stammore	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.895839	151.163846	1	1	install raised pedestrian crossing	SM35	Primary	HIGH	\$ 50,000
SA227	Myrtle Street	Stammore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.892365	151.164546	1	1	install raised continuous footpath treatment	SM31	Primary	HIGH	\$ 30,000
SA228	Myrtle Street	Stammore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.892411	151.164724	1	1	install raised continuous footpath treatment	SM31	Primary	HIGH	\$ 30,000
SA229	Percival Lane East	Stammore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.893176	151.16494	1	1	install raised continuous footpath treatment	SM48	Primary	HIGH	\$ 30,000
SA23	Cavill Avenue	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.887412	151.121736	1	1	install raised continuous footpath treatment	AF106	Primary	HIGH	\$ 30,000
SA230	Percival Lane West	Stammore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.893947	151.163575	1	1	install raised continuous footpath treatment	SM13	Primary	HIGH	\$ 30,000
SA231	Temple Street	Stammore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.893234	151.164252	1	1	install raised continuous footpath treatment	SM32	Primary	HIGH	\$ 30,000
SA233	Percival Road	Stammore	Local Road	safety issue	potential HPAA	-33.892651	151.164569	1	1	investigate High Pedestrian Activity Area implementation	SM32	Primary	HIGH	\$ 20,000
SA236	Aubrey Street	Stammore	Local Road	safety issue	missing lighting	-33.895371	151.161398	1	1	install new lighting	SM50	Primary	HIGH	\$ 10,000
SA237	Holt Street	Stammore	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.894953	151.164314	1	1	install raised pedestrian crossing	SM26	Primary	HIGH	\$ 50,000
SA238	Holt Street	Stammore	Local Road	safety issue	potential HPAA	-33.895192	151.164221	1	1	investigate High Pedestrian Activity Area implementation	SM26	Primary	HIGH	\$ 20,000
SA239	Liberty Street	Stammore	Regional Road	safety issue	opportunity to raise pedestrian crossing near school	-33.89733	151.170384	1	1	install raised pedestrian crossing	EN12	Secondary	HIGH	\$ 50,000
SA24	Fox's La	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.887732	151.126038	1	1	install raised continuous footpath treatment	AF32	Primary	HIGH	\$ 30,000
SA240	Hardie Avenue	Summer Hill	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.88984	151.137299	1	1	install raised pedestrian crossing	SH34	Primary	HIGH	\$ 50,000
SA241	Hardie Avenue	Summer Hill	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.891634	151.137252	1	1	install raised pedestrian crossing	SH34	Primary	HIGH	\$ 50,000
SA242	Hardie Avenue	Summer Hill	Local Road	safety issue	potential HPAA	-33.890812	151.137541	1	1	investigate High Pedestrian Activity Area implementation	SH33	Primary	HIGH	\$ 20,000
SA243	Lackey Street	Summer Hill	Local Road	safety issue	potential HPAA	-33.891196	151.138286	1	1	investigate High Pedestrian Activity Area implementation	SH49	Primary	HIGH	\$ 20,000
SA244	Moondie Street	Summer Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.891714	151.136911	1	1	install raised continuous footpath treatment	SH84	Primary	HIGH	\$ 30,000
SA245	Moondie Street	Summer Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.891881	151.137884	1	1	install raised continuous footpath treatment	SH85	Primary	HIGH	\$ 30,000
SA246	Moondie Street	Summer Hill	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.89001	151.139159	1	1	install raised pedestrian crossing	SH78	Primary	HIGH	\$ 50,000
SA247	Carlton Crescent	Summer Hill	Regional Road	safety issue	steep crossfall	-33.890708	151.138695	1	1	further investigation required - crossfall	SH3	Primary	HIGH	\$ 50,000
SA250	Henson Street	Summer Hill	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.896219	151.134579	1	1	install raised pedestrian crossing	SH36	Secondary	HIGH	\$ 50,000
SA251	Junction Road	Summer Hill	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.895285	151.136501	1	1	install raised pedestrian crossing	SH43	Secondary	HIGH	\$ 50,000
SA253	Lackey Street	Summer Hill	Local Road	safety issue	traction issues when wet	-33.891692	151.138101	1	1	no action	SH49	Primary	HIGH	\$ 30,000
SA257	Railway Road	Sydenham	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.916315	151.16629	1	1	install raised pedestrian crossing	SY6	Primary	HIGH	\$ 50,000
SA258	Railway Road	Sydenham	State Road	safety issue	potential HPAA	-33.914972	151.166932	1	1	investigate High Pedestrian Activity Area implementation	SY6	Primary	HIGH	\$ 20,000
SA259	Wright Street	Sydenham	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.915703	151.166176	1	1	install raised continuous footpath treatment	SY6	Primary	HIGH	\$ 30,000
SA26	Lagap Avenue	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.889188	151.120111	1	1	install raised continuous footpath treatment	AF109	Primary	HIGH	\$ 30,000
SA27	Miller Avenue	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.887673	151.122173	1	1	install raised continuous footpath treatment	AF108	Primary	HIGH	\$ 30,000
SA28	Murrell Street	Ashfield	Local Road	safety issue	opportunity to provide raised pedestrian crossing	-33.889451	151.127634	1	1	further investigation required - raised pedestrian crossing	AF101	Primary	HIGH	\$ 15,000
SA29	Murrell Street	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.889483	151.12762	1	1	further investigation required - traffic calming	AF101	Primary	HIGH	\$ 30,000
SA3	Johnson Lane	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.887149	151.121433	1	1	install raised continuous footpath treatment	AN20	Primary	HIGH	\$ 30,000
SA30	Murrell Street	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.889441	151.127349	1	1	install raised continuous footpath treatment	AF101	Primary	HIGH	\$ 30,000
SA31	Norton Street	Ashfield	Regional Road	safety issue	opportunity to provide traffic calming treatment	-33.890978	151.12687	1	1	further investigation required - traffic calming	AF122	Primary	HIGH	\$ -
SA32	Orchard Crescent	Ashfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.888375	151.126672	1	1	install raised continuous footpath treatment	AF51	Primary	HIGH	\$ 30,000
SA34	Alt Street	Ashfield	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.885812	151.126267	1	1	install raised pedestrian crossing	AF18	Secondary	HIGH	\$ 50,000
SA35	Bland Street	Ashfield	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.885535	151.125367	1	1	install raised pedestrian crossing	AF18	Secondary	HIGH	\$ 50,000
SA36	Brown Street	Ashfield	Local Road	safety issue	potential HPAA	-33.889306	151.126144	1	1	investigate High Pedestrian Activity Area implementation	AF30	Primary	HIGH	\$ 20,000
SA38	Elizabeth Street	Ashfield	Regional Road	safety issue	potential HPAA	-33.88691	151.12628	1	1	investigate High Pedestrian Activity Area implementation	AF58	Primary	HIGH	\$ 20,000
SA39	Frederick Street	Ashfield	Local Road	safety issue	poor drainage	-33.885422	151.119696	1	1	refer to maintenance	AF76	Primary	HIGH	\$ 50,000
SA4	Susan Street	Annandale	Local Road	safety issue	vehicle encroach on pedestrian areas	-33.884388	151.173324	1	1	install kerb blisters/ build outs	AN31	Primary	HIGH	\$ 10,000
SA41	Prospect Road	Ashfield	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.899418	151.132148	1	1	install raised pedestrian crossing	SH74	Secondary	HIGH	\$ 50,000
SA44	Church Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.85687	151.179648	1	1	install raised continuous footpath treatment	BA31	Primary	HIGH	\$ 30,000
SA45	Church Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.856764	151.179714	1	1	install raised continuous footpath treatment	BA31	Primary	HIGH	\$ 30,000
SA46	College Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857065	151.180219	1	1	install raised continuous footpath treatment	BA30	Primary	HIGH	\$ 30,000
SA47	Darling Street	Balmain	Local Road	safety issue	potential HPAA	-33.896479	151.177998	1	1	investigate High Pedestrian Activity Area implementation	BA32	Primary	HIGH	\$ 20,000
SA48	Ford Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857685	151.18022	1	1	install raised continuous footpath treatment	BA29	Primary	HIGH	\$ 30,000
SA49	Hampden Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.858578	151.174846	1	1	install raised continuous footpath treatment	BA34	Primary	HIGH	\$ 30,000
SA50	Jacques Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.856118	151.176179	1	1	install raised continuous footpath treatment	BA33	Primary	HIGH	\$ 30,000
SA52	McDonald Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857421	151.182749	1	1	install raised continuous footpath treatment	BA28	Primary	HIGH	\$ 30,000
SA53	Mort Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857342	151.180692	1	1	install raised continuous footpath treatment	BE2	Primary	HIGH	\$ 30,000
SA58	Darling Street	Balmain East	Local Road	safety issue	potential HPAA	-33.857478	151.192796	1	1	investigate High Pedestrian Activity Area implementation	BE5	Primary	HIGH	\$ 20,000
SA59	Datchett Street	Balmain East	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857705	151.19198	1	1	install raised continuous footpath treatment	BE3	Primary	HIGH	\$ 30,000
SA60	Duke Street	Balmain East	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857476	151.19231	1	1	install raised continuous footpath treatment	BE3	Primary	HIGH	\$ 30,000
SA61	Johnson Street	Balmain East	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857446	151.193897	1	1	install raised continuous footpath treatment	BE2	Primary	HIGH	\$ 30,000
SA62	Union Street	Balmain East	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.857617	151.192615	1	1	install raised continuous footpath treatment	BE5	Primary	HIGH	\$ 30,000
SA65	Elizabeth Street	Croydon	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.882742	151.117276	1	1	install raised pedestrian crossing	CR21	Secondary	HIGH	\$ 50,000
SA66	Teakie Street	Croydon	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.883709	151.133626	1	1	install raised pedestrian crossing	SH88	Secondary	HIGH	\$ 50,000
SA67	Beach Road	Dulwich Hill	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.904813	151.141392	1	1	install raised pedestrian crossing	DH88	Primary	HIGH	\$ 50,000
SA69	Denison Road	Dulwich Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.904398	151.139258	1	1	install raised continuous footpath treatment	DH83	Primary	HIGH	\$ 30,000
SA7	View Street	Annandale	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.8816	151.171503	1	1	install raised continuous footpath treatment	AN20	Primary	HIGH	\$ 30,000
SA70	Fairfow Lane	Dulwich Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.904884	151.144167	1	1	install raised continuous footpath treatment	DH75	Primary	HIGH	\$ 30,000
SA71	Herbert Street	Dulwich Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.902479	151.144265	1	1	install raised continuous footpath treatment	DH84	Primary	HIGH	\$ 30,000
SA72	Kingtore Street	Dulwich Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.904395	151.139556	1	1	install raised continuous footpath treatment	DH89	Primary	HIGH	\$ 30,000
SA73	Lewisham Street	Dulwich Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.902834	151.143172	1	1	install raised continuous footpath treatment	DH86	Primary	HIGH	\$ 30,000
SA74	New Canterbury Road	Dulwich Hill	Local Road	safety issue	potential HPAA	-33.903433	151.142695	1	1	investigate High Pedestrian Activity Area implementation	DH97	Primary	HIGH	\$ 30,000
SA75	Old Canterbury Road	Dulwich Hill	State Road	safety issue	opportunity to upgrade to signalised crossing	-33.900913	151.132005	1	1	further investigation required - signals	AF126	Primary	HIGH	\$ 20,000
SA76	Pilgott Street	Dulwich Hill	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.902495	151.144004	1	1	install raised continuous footpath treatment	DH95	Primary	HIGH	\$ 30,000
SA77	Wardell Road	Dulwich Hill	Regional Road	safety issue	opportunity to raise pedestrian crossing near public transport station	-33.911229	151.141275	1	1	install raised pedestrian crossing	MV46	Primary	HIGH	\$ 50,000
SA8	Wells Street	Annandale	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.882278	151.172149	1	1	install raised continuous footpath treatment	AN28	Primary	HIGH	\$ 30,000
SA81	Cambridge Street	Enmore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.899133	151.171484	1	1	install raised continuous footpath treatment	EN6	Primary	HIGH	\$ 30,000
SA82	Enmore Lane	Enmore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.899699	151.171232	1	1	install raised continuous footpath treatment	EN1	Primary	HIGH	\$ 30,000
SA83	Fotheringham Street	Enmore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.892684	151.170141	1	1	install raised continuous footpath treatment	EN13	Primary	HIGH	\$ 30,000
SA84	London Street	Enmore	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.898945	151.172149	1	1	install raised continuous footpath treatment	EN7	Primary	HIGH	\$ 30,000
SA85	Stammore Road	Enmore	State Road	safety issue	potential HPAA	-33.89943	151.170771	1	1	investigate High Pedestrian Activity Area implementation	EN13	Primary	HIGH	\$ 20,000
SA88	Dickson Street	Haberfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.879863	151.139457	1	1	install raised continuous footpath treatment	HA34	Primary	HIGH	\$ 30,000
SA89	Odlies Avenue	Haberfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.879863	151.137641	1	1	install raised continuous footpath treatment	HA86	Primary	HIGH	\$ 30,000
SA9	Annandale Street	Annandale	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.877992	151.17063	1	1	install raised pedestrian crossing	AN7	Secondary	HIGH	\$ 50,000
SA90	Ramsay Street	Haberfield	Regional Road	safety issue	potential HPAA	-33.880486	151.138652	1	1	investigate High Pedestrian Activity Area implementation	HA93	Primary	HIGH	\$ 20,000
SA91	Rawson Street	Haberfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.879481	151.138173	1	1	install raised continuous footpath treatment	HA86	Primary	HIGH	\$ 30,000
SA92	Wincombe Avenue	Haberfield	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.881343	151.138591	1	1	install raised continuous footpath treatment	HA86	Primary	HIGH	\$ 30,000
SA95	Dalhousie Street	Haberfield	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.87885	151.14	1	1	install raised pedestrian crossing	HA32	Primary	HIGH	\$ 50,000
SA96	Waratah Street	Haberfield	Local Road	safety issue	opportunity to raise pedestrian crossing near school	-33.874858	151.140362	1	1	install raised pedestrian crossing	HA107	Secondary	HIGH	\$ 50,000
													SUBTOTAL	\$ 6,038,350

**P4909 Inner West PAMP
Detailed Works Program
Safety Issues
6 August 2021**

Issue ID	Street	Suburb	Classification	Category	Issue	Latitude	Longitude	Quantity	Length	Recommendation	Segment ID	Segment Hierarchy	Treatment Priority	Cost
SA1	Hutchinson Lane	Annandale	Local Road	safety issue	missing footpaths in laneway	-33.876	151.169650	1	1	review and implement shared zone	AN119	Secondary	MED	\$ 40,000
SA10	Taylor Street	Annandale	Local Road	safety issue	vegetation obscures pedestrians	-33.882991	151.174647	1	1	refer to maintenance	AN58	Secondary	MED	\$ -
SA100	Lord Street	Leichhardt	Local Road	safety issue	fencing requires flare at end	-33.882644	151.144377	1	1	re-construct fence	LH85	Secondary	MED	\$ 150
SA101	Allen Street	Leichhardt	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.879975	151.156416	1	1	install raised continuous footpath treatment	LH8	Secondary	MED	\$ 30,000
SA11	Trafalgar Street	Annandale	Local Road	safety issue	corner obstructs pedestrian	-33.877288	151.174322	1	1	install pavement warning message	AN103	Secondary	MED	\$ 150
SA117	Styler Street	Leichhardt	Regional Road	safety issue	poor lighting	-33.882679	151.166391	1	1	install new lighting	AN33	Secondary	MED	\$ 10,000
SA118	White Creek	Leichhardt	Local Road	safety issue	missing lighting	-33.88308	151.167354	1	1	install new lighting	AN113	Secondary	MED	\$ 10,000
SA119	William Street	Leichhardt	Local Road	safety issue	poor drainage - severe ponding	-33.877272	151.157464	1	1	refer to maintenance	LH170	Secondary	MED	\$ -
SA120	William Street	Leichhardt	Local Road	safety issue	poor sight lines to approaching traffic - build out kerb	-33.877653	151.151728	1	1	install kerb extension - pair	LH173	Secondary	MED	\$ 20,000
SA124	Toothill Street	Lewisham	Regional Road	safety issue	vehicle obscured pedestrians	-33.869360	151.146369	1	1	install keep clear pavement marking	LW35	Secondary	MED	\$ 2,500
SA129	Grove Street	Dryfield	Local Road	safety issue	poor sight lines	-33.869475	151.163374	1	1	provide warning signage	LF53	Secondary	MED	\$ 500
SA134	Calvert Street	Marrickville	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.911657	151.155344	1	1	install raised pedestrian crossing	MV20	Secondary	MED	\$ 60,000
SA137	Gladstone Street	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.911409	151.157934	1	1	install raised continuous footpath treatment	MV135	Secondary	MED	\$ 30,000
SA143	Marrickville Road	Marrickville	Regional Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.911686	151.159153	1	1	install raised pedestrian crossing	MV133	Secondary	MED	\$ 50,000
SA144	Meeks Road	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.912644	151.161095	1	1	install raised continuous footpath treatment	MV128	Secondary	MED	\$ 30,000
SA145	Meeks Road	Marrickville	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.912826	151.160942	1	1	install raised continuous footpath treatment	MV132	Secondary	MED	\$ 30,000
SA146	River Cance Club	Marrickville	Local Road	safety issue	cross pedestrian, bicycle traffic over shared path near gate	-33.923584	151.155555	1	1	install warning line marking and signage	MV45	Secondary	MED	\$ 1,500
SA147	Sydenham Road	Marrickville	State Road	safety issue	opportunity to provide signalised intersection	-33.910959	151.163949	1	1	further investigation required - signals	MV201	Secondary	MED	\$ 20,000
SA15	Chester Street	Annandale	Local Road	safety issue	steep crossfall	-33.885674	151.174996	1	1	re-construct footpath pavement	AN29	Secondary	MED	\$ 200
SA150	Byrnes Street	Marrickville	Local Road	safety issue	vehicles approach crossing at speed	-33.913703	151.155431	1	1	install new speed cushions	MV188	Secondary	MED	\$ 3,000
SA151	Byrnes Street	Marrickville	Local Road	safety issue	poor lighting	-33.913716	151.155431	1	1	install new lighting	MV188	Secondary	MED	\$ 10,000
SA152	Willwara Road	Marrickville	Local Road	safety issue	deep tree pit	-33.909703	151.157245	1	1	top up tree pit	MV91	Secondary	MED	\$ 150
SA160	Marrickville Road	Marrickville	Regional Road	safety issue	corner obscures pedestrians	-33.912956	151.161507	1	1	install pavement warning message	MV128	Secondary	MED	\$ 150
SA161	Marrickville Road	Marrickville	Regional Road	safety issue	poor lighting	-33.910058	151.1554	1	1	install new lighting	MV140	Secondary	MED	\$ 10,000
SA162	Marrickville Road	Marrickville	Regional Road	safety issue	vehicles approach crossing at speed	-33.910087	151.155431	1	1	install raised pedestrian crossing	MV140	Secondary	MED	\$ 50,000
SA163	Marrickville Road	Marrickville	Regional Road	safety issue	footlights orientated incorrectly	-33.910111	151.155431	1	1	adjust flood light orientation	MV140	Secondary	MED	\$ 1,000
SA164	Marrickville Road	Marrickville	Regional Road	safety issue	tree obstructs footlight	-33.911865	151.159233	1	1	refer to maintenance	MV136	Secondary	MED	\$ -
SA165	Marrickville Road	Marrickville	Regional Road	safety issue	vehicles approach crossing at speed	-33.911897	151.159225	1	1	install raised pedestrian crossing	MV136	Secondary	MED	\$ 50,000
SA166	Marrickville Road	Marrickville	Regional Road	safety issue	roadside furniture obstructs sightlines	-33.911851	151.159203	1	1	re-construct pedestrian fencing	MV136	Secondary	MED	\$ 5,000
SA167	Charm Park	Marrickville	Local Road	safety issue	missing lighting	-33.913866	151.156597	1	1	install new lighting	MV187	Secondary	MED	\$ 10,000
SA183	Edinburgh Road	Newtown	Local Road	safety issue	shared path signage required	-33.907916	151.174484	1	1	install new shared path signage	MV17	Secondary	MED	\$ 350
SA187	Liberty Street	Newtown	Regional Road	safety issue	shared path signage conflict	-33.894988	151.171625	1	1	review and replace shared path signage	NE43	Secondary	MED	\$ 500
SA188	Liberty Street	Newtown	Regional Road	safety issue	bicycle pavement marking with no shared path signage	-33.895275	151.171578	1	1	install new shared path signage	NE43	Secondary	MED	\$ 1,000
SA206	York Crescent	Petersham	Local Road	safety issue	missing lighting	-33.852744	151.15853	1	1	install new lighting	PE21	Secondary	MED	\$ 10,000
SA207	Denison Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.86543	151.167687	1	1	install raised continuous footpath treatment	RO32	Secondary	MED	\$ 30,000
SA21	Rose Street	Annandale	Local Road	safety issue	poor lighting	-33.873776	151.176113	1	1	install new lighting	AN95	Secondary	MED	\$ 10,000
SA210	Manning Street	Rozelle	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.865782	151.169122	1	1	install raised continuous footpath treatment	RO32	Secondary	MED	\$ 30,000
SA220	Beattie Street	Rozelle	Local Road	safety issue	corner obscures pedestrians	-33.860579	151.172292	1	1	install pavement warning message	RO17	Secondary	MED	\$ 150
SA222	Terry Street	Rozelle	Local Road	safety issue	refuge island provides no protection from traffic	-33.860804	151.169576	1	1	install new refuge island	RO68	Secondary	MED	\$ 15,000
SA223	Terry Street	Rozelle	Local Road	safety issue	refuge island provides no protection for pedestrians	-33.860678	151.169964	1	1	install new refuge island	RO68	Secondary	MED	\$ 15,000
SA224	Bedford Road	St Peters	Regional Road	safety issue	steep crossfall	-33.891311	151.175137	1	1	re-construct footpath pavement	MV18	Secondary	MED	\$ 200
SA232	Merchant Street	Stammore	Local Road	safety issue	poor drainage - severe ponding	-33.895872	151.167462	1	1	refer to maintenance	SM20	Secondary	MED	\$ -
SA234	Salsbury Road	Stammore	Regional Road	safety issue	poor drainage - severe ponding	-33.891476	151.169591	1	1	refer to maintenance	SM44	Secondary	MED	\$ -
SA235	Lincoln Lane	Stammore	Local Road	safety issue	poor drainage - severe ponding	-33.891435	151.17016	1	1	refer to maintenance	SM44	Secondary	MED	\$ -
SA25	Knox Street	Ashfield	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.893114	151.122749	1	1	install raised pedestrian crossing	AF90	Secondary	MED	\$ 50,000
SA252	Junction Road	Summer Hill	Local Road	safety issue	corner obscures pedestrians	-33.895391	151.137156	1	1	install pavement warning message	SH39	Secondary	MED	\$ 150
SA254	Prospect Road	Summer Hill	Local Road	safety issue	road hump used as crossing	-33.900063	151.13201	1	1	install pedestrian fencing	SH63	Secondary	MED	\$ 750
SA256	Prospect Road	Summer Hill	Local Road	safety issue	narrow refuge island	-33.891167	151.132434	1	1	install new refuge island	SH65	Secondary	MED	\$ 15,000
SA257	Elizabeth Street	Ashfield	Local Road	safety issue	corner obscures pedestrians	-33.88838	151.125389	1	1	install pavement warning message	AF63	Secondary	MED	\$ 150
SA40	Markham Avenue	Ashfield	Local Road	safety issue	bollards of low contrasting colour	-33.887492	151.123242	1	1	repaint bollards	AF110	Secondary	MED	\$ 150
SA42	Victoria Street	Ashfield	Local Road	safety issue	steep crossfall	-33.903218	151.129144	1	1	re-construct footpath pavement	AF164	Secondary	MED	\$ 200
SA43	Beattie Street	Balmain	Local Road	safety issue	opportunity to raise pedestrian crossing within town centre	-33.857588	151.181049	1	1	install raised pedestrian crossing	B42	Secondary	MED	\$ 50,000
SA5	Trafalgar Street	Annandale	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.881894	151.172128	1	1	install raised continuous footpath treatment	AN108	Secondary	MED	\$ 30,000
SA51	King Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.859593	151.175802	1	1	install raised continuous footpath treatment	BA11	Secondary	MED	\$ 30,000
SA54	Young Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.859572	151.174068	1	1	install raised continuous footpath treatment	BA35	Secondary	MED	\$ 30,000
SA55	Young Street	Balmain	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.860686	151.174121	1	1	install raised continuous footpath treatment	BA35	Secondary	MED	\$ 30,000
SA56	Glassop Street	Balmain	Local Road	safety issue	vehicles obscure pedestrians	-33.854031	151.175489	1	1	install kerb extension	BA65	Secondary	MED	\$ 10,000
SA57	Terry Street	Balmain	Local Road	safety issue	corner obscures pedestrians	-33.856842	151.171205	1	1	install pavement warning message	BA69	Secondary	MED	\$ 150
SA5	Trafalgar Street	Annandale	Local Road	safety issue	opportunity to provide raised continuous footpath within town centre	-33.881674	151.172171	1	1	install raised continuous footpath treatment	AN105	Secondary	MED	\$ 30,000
SA63	Salsbury Road	Camperdown	Regional Road	safety issue	vehicles approach crossing at speed	-33.891774	151.174494	1	1	install raised pedestrian crossing	CA27	Secondary	MED	\$ 50,000
SA64	Salsbury Road	Camperdown	Regional Road	safety issue	poor visibility to approaching vehicles	-33.89174	151.174507	1	1	relocate no stopping sign	CA27	Secondary	MED	\$ 1,500
SA68	Blackwood Avenue	Dulwich Hill	Local Road	safety issue	potential shared zone	-33.90759	151.140814	1	1	investigate shared zone implementation	DH4	Secondary	MED	\$ 15,000
SA78	Donibutun Road	Dulwich Hill	Local Road	safety issue	pedestrian desireline	-33.901519	151.137251	1	1	further investigation required - pedestrian crossing	DH16	Secondary	MED	\$ 10,000
SA79	New Canterbury Road	Dulwich Hill	State Road	safety issue	narrow pedestrian refuge island across busy road	-33.904938	151.132633	1	1	consult with City of Canterbury-Bankstown	DH81	Secondary	MED	\$ -
SA80	New Canterbury Road	Dulwich Hill	Local Road	safety issue	poor drainage	-33.905	151.131775	1	1	refer to maintenance	DH90	Secondary	MED	\$ -
SA86	London Street	Enmore	Local Road	safety issue	vehicles obscure pedestrians	-33.896399	151.171064	1	1	install no stopping sign and signpost	EN11	Secondary	MED	\$ 300
SA87	Phillip Street	Enmore	Local Road	safety issue	poor drainage - severe ponding	-33.896196	151.17137	1	1	refer to maintenance	LH6	Secondary	MED	\$ -
SA93	Bland Street	Haslerfield	Local Road	safety issue	low visibility to crossing from both approaches	-33.878926	151.13441	1	1	install raised pedestrian crossing	HA20	Secondary	MED	\$ 50,000
SA94	Bland Street	Haslerfield	Local Road	safety issue	footlights orientated incorrectly	-33.878938	151.13428	1	1	adjust flood light orientation	HA20	Secondary	MED	\$ 1,000
SA97	Darley Road	Leichhardt	State Road	safety issue	potential pedestrian crossing point	-33.880175	151.147661	1	1	further investigation required - raised pedestrian crossing	LH30	Secondary	MED	\$ 15,000
SA98	Porter Street	Leichhardt	State Road	safety issue	missing refuge island	-33.880444	151.147661	1	1	install new refuge island	LH8	Secondary	MED	\$ 15,000
SA99	Lord Street	Leichhardt	Local Road	safety issue	potential pedestrian crossing point	-33.880504	151.147004	1	1	further investigation required - raised pedestrian crossing	LH87	Secondary	MED	\$ 15,000
SA108	Allen Street	Leichhardt	Local Road	safety issue	vehicles approach crossing point at speed	-33.88033	151.152118	1	1	install kerb extension	LH6	Tertiary	LOW	\$ 10,000
SA107	Allen Street	Leichhardt	Local Road	safety issue	vehicles approach at speed - insufficient collection	-33.880362	151.152124	1	1	install new refuge island	LH6	Tertiary	LOW	\$ 10,000
SA108	Allen Street	Leichhardt	Local Road	safety issue	vehicles exit roundabout at speed	-33.880388	151.151968	1	1	install kerb extension	LH5	Tertiary	LOW	\$ 10,000
SA109	Allen Street	Leichhardt	Local Road	safety issue	vehicles approach at speed - insufficient deflection	-33.880364	151.151946	1	1	install new refuge island	LH5	Tertiary	LOW	\$ 15,000
SA168	Richmond Crescent	Marrickville	Local Road	safety issue	damaged fence obstructs footpath	-33.920888	151.158533	1	1	notify property owner	LM73	Tertiary	LOW	\$ -
SA170	Sydney Steel St	Marrickville	Local Road	safety issue	construction site with no gate control	-33.910106	151.169868	1	1	notify business owner	MV207	Tertiary	LOW	\$ -
SA248	Greenway	Summer Hill	Local Road	safety issue	trip hazard - empty bollard footing	-33.891472	151.144049	1	1	repair bollard	SH32	Tertiary	LOW	\$ 2,500
SA249	Greenway	Summer Hill	Local Road	safety issue	missing lighting	-33.891456	151.14406	1	1	install new lighting	SH32	Tertiary	LOW	\$ 10,000
SA255	Prospect Road	Summer Hill	Local Road	safety issue	missing pedestrian barriers	-33.894628	151.132374	1	1	install landscape barriers	SH11	Tertiary	LOW	\$ 1,000
SA33	Alt Street	Ashfield	Local Road	safety issue	poor sight lines between pedestrians and approaching vehicles	-33.890715	151.128337	1	1	relocate no stopping signage	AF3	Tertiary	LOW	\$ 300
													SUBTOTAL	\$ 1,025,200
													TOTAL	\$ 6,127,180